PHASE I ENVIRONMENTAL SITE ASSESSMENT

FOR THE

BUFFALO-AMHERST-TONAWANDA CORRIDOR TRANSIT EXPANSION

CITY OF BUFFALO, TOWNS OF AMHERST AND TONAWANDA

May 17, 2024

PREPARED FOR

WSP USA INC.

50 LAKEFRONT BLVD, SUITE 111 B

BUFFALO, NEW YORK 14202

FOR SUBMISSION TO

NIAGARA FRONTIER TRANSPORTATION AUTHORITY

METROPOLITAN TRANSPORTATION CENTER

181 ELLICOTT STREET

BUFFALO, NEW YORK 14203

Submitted by:

Watts Architects &Engineers

BUFFALO / SYRACUSE / NEW YORK

watts-ae.com

TABLE OF CONTENTS

1.0 INTRODUCTION 1
2.0 SCOPE AND METHODOLOGY 2
2.1 Investigation of Previous Activities and Site Use 3
2.1.1 USGS Topographic Maps 3
2.1.2 Historic Land Use Maps 4
2.1.3 Sanborn Fire Insurance Maps 4
2.1.4 City Directories 4
2.1.5 Aerial Photographs 4
2.2 Review of Government Records and Databases 4
2.3 Field Inspection 6
2.4 Interviews 6
3.0 FINDINGS 7
3.1 University at Buffalo – 3425 Main Street 7
3.2 Subway Restaurant – 3384 Main Street 10
3.3 Walgreens – 3490 Main Street 11
3.4 University Plaza – 3500 Main Street 14
3.5 May Jen Chinese Restaurant – 47 Kenmore Avenue 15
3.6 Vacant Lot – 159 Kenmore Avenue 15
3.7 Storefronts – 240-242 Niagara Falls Boulevard 17
3.8 Sweeney's Garage – 424 Niagara Falls Boulevard 18
3.9 American Auto World – 733 Niagara Falls Boulevard 20
3.10 Empire Auto Electric – 803 Niagara Falls Boulevard 21
3.11 NOCO Express – 820-828 Niagara Falls Boulevard 22
3.12 Sentry North Appliance Service – 845 Niagara Falls Boulevard 23
3.13 Fancy Florist and Storefront – 853 Niagara Falls Boulevard 24
3.14 Corsi A First Klass Collision Center – 874 Niagara Falls Boulevard 25
3.15 Lombardo Corporate Office – 899 Niagara Falls Boulevard 26
3.16 U-Haul – 925 Niagara Falls Boulevard 27
3.17 Sun City Mattress – 926 Niagara Falls Boulevard 28
3.18 Partner's Bar & Pizzeria – 934 Niagara Falls Boulevard 28
3.19 Stanton Optical – 2965 Sheridan Drive 29
3.20 El Palenque Restaurant – 951 Niagara Falls Boulevard 31
3.21 Monro Auto Service and Tire Centers – 2980 Sheridan Drive 32
3.22 Firestone Complete Auto Care – 995 Niagara Falls Boulevard 33
3.23 Pep Boys Auto Parts & Service – 1025 Niagara Falls Boulevard 35
3.24 AudioMotive Creations – 1167 Niagara Falls Boulevard 36
3.25 Boulevard Mall – 1261-1269 Niagara Falls Boulevard 37
3.26 Plaza – 1200 Niagara Falls Boulevard 39
3.27 Goodyear Auto Service – 1280 Niagara Falls Boulevard 40
3.28 Valu Muffler & Brake Auto Center – 1346 Niagara Falls Boulevard 41
3.29 Delta Sonic Car Wash – 1355 Niagara Falls Boulevard 42
3.30 Firestone Complete Auto Care – 3893 Maple Road 44
3.31 Premiere Group – 3900 Maple Road 45

3.32 Sweet Home Middle School – 4150 Maple Road 47
3.33 NOCO Express – 4265 Maple Road 48
3.34 Mobil – 4291 Maple Road..... 49
3.35 Anchor Bar – 4300 Maple Road..... 51
3.36 Ball Pump Station – 1201 Sweet Home Road..... 51
3.37 University of Buffalo – Millersport Highway..... 53
3.38 Office Building – 140 John James Audubon Parkway 55
3.39 Town of Amherst – 350 John James Audubon Parkway..... 56
4.0 CONCLUSIONS AND RECOMMENDATIONS..... 54

LIST OF TABLES

Table 1 – Summary of Recommendations.....57

LIST OF FIGURES (At the end of the report)

Figure 1 – Project Location Map
Figures 2a-2g – Sites of Potential Environmental Concern

LIST OF ATTACHMENTS

Attachment A Sources of Information
Attachment B Site Photographs
Attachment C Environmental Data Resources, Inc. (EDR) Environmental Reports

1.0 INTRODUCTION

Watts Architecture & Engineering (Watts) was retained to perform a Phase I Environmental Site Assessment (Phase I ESA) of the Buffalo-Amherst-Tonawanda Corridor Transit Expansion (the Project) in the municipalities of Buffalo, Tonawanda, and Amherst, in Erie County, NY. This report was prepared for the Niagara Frontier Transportation Authority (NFTA) in technical support of the proposed Project which includes an approximate 7-mile transportation corridor between Metro Rail's University Station, the University at Buffalo (UB) North Campus, and the I-990 interchange with John James Audubon Parkway. The Project limits are shown on **Figure 1**.

This report provides the results of the Phase I ESA for this Project. The purpose of the Phase I ESA is to identify potential areas of contamination that may be excavated or impacted during construction. If warranted, a second phase of the Phase I ESA, known as the Phase II ESA, will be performed during final design. The Phase II ESA is used for soil (or other material) characterization to determine disposal requirements for excavated soil and to identify environmental concerns that could affect the public or worker safety. It is standard engineering practice and sound environmental policy under the state and federal environmental regulations to identify potential areas of contamination to avoid unexpected costs and significant delays late in the development of a project.

Research and reporting for this Phase I ESA was performed in 2019. The document title and minor design references within this Phase I ESA report have been updated since 2019; however, no additional environmental research has been performed since the original Phase I ESA in 2019. See Section 2.0, Scope and Methodology, below for additional information on the research performed in 2019. Based on a review of notable changes along the Project corridor since 2019, it is believed that the environmental concerns identified within this report are still applicable to the current Project. While the names of several businesses identified in this analysis have changed since 2019, the property land uses remain essentially the same and the associated historic environmental concerns are still a consideration for this Project.

2.0 SCOPE AND METHODOLOGY

As NFTA is a New York State transportation agency, this Phase I ESA follows the methodology described in the New York State Department of Transportation's The Environmental Manual Section 4.4.20 as the most appropriate guide for the Phase I ESA process to identify sites of potential environmental concern based on existing and past property uses. The procedures described in The Environmental Manual's overall Environmental Site Assessment process typically follows the steps outlined in the American Society for Testing and Materials' (ASTM) E1527-13: Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process and are consistent with the ASTM's E1528-06, Standard Practice for Limited Environmental Due Diligence; Transaction Screen Process, and E1903-97, Standard Guide for Environmental Site Assessments: Phase II Environmental Site Assessment Process (and all updates), but are adapted to meet the needs of transportation projects more specifically.

NYSDOT guidance differs from the ASTM approaches in five specific ways which are listed below:

1. The standard search distances in ASTM 1527 may be modified and are generally shorter to reflect the linear geometry of NYSDOT's facilities.
2. Soil vapor intrusion (SVI) studies are rarely performed because NYSDOT typically acquires buildings to demolish them to expand transportation networks. SVI studies may be performed if a structure will be subsequently leased, sold, or used for commercial or residential purposes after the project is completed.
3. Formal data validation (an extra QA/QC step in addition to the normal laboratory QA/QC procedures) is rarely required for NYSDOT projects.
4. NYSDOT may opt to perform only limited due diligence and not attempt to qualify for the landowner liability protections available under the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA), especially when acquiring residential rather than commercial real estate. Thus, the procedures described here may more closely resemble a transaction screen process rather than a full Phase I environmental site assessment as described within ASTM 1527.
5. NYSDOT has a process for acquiring real estate that includes final approval from the New York State Office of the Attorney General's (NYSOAG) Bureau of Real Property. For this reason, a search for environmental liens is not part of this Phase I environmental site assessment.

This Phase I ESA consists of collecting information through a record search to investigate previous activities and site uses in the corridor; a review of government databases and records; a review of historical maps, figures, photos and records; a field inspection; and interviews with local government agencies.

2.1 Investigation of Previous Activities and Site Use

A records search is conducted to determine past or current land uses on and in the immediate vicinity of the Project corridor that may be of environmental concern. The following sources were used to evaluate potential environmental concerns on the Project corridor.

2.1.1 USGS Topographic Maps

The USGS Topographic Quadrangle maps were obtained from Environmental Data Resources, Inc. (EDR), an independent research firm. These maps provide a historical reference to land use in addition to showing prominent structures, roadways, bodies of water, and topography.

- Buffalo NE: 2013, 1965, 1950, 1948, and 1946
- Buffalo: 1901 and 1894
- Tonawanda – East: 2013, 1980, 1965, and 1950
- Tonawanda: 1901, 1900, 1899, and 1894
- Niagara: 1913 and 1899

2.1.2 Historic Land Use Maps

The following atlases were reviewed online at Historic Map Works (www.historicmapworks.com) and Warp Maps (www.wardmaps.com) websites:

- 1866 Topographical Atlas of Erie County, NY
- 1880 Illustrated Historical Atlas of Erie County, NY
- 1909 New Century Atlas Erie County, NY
- 1872 Atlas of the City of Buffalo, Erie County, NY

2.1.3 Sanborn Fire Insurance Maps

The Sanborn Fire Insurance Maps were requested from EDR. Coverage with these maps varies by location. These maps provide a historical reference to land use in addition to showing prominent structures and roadways. Watts reviewed the maps for the City of Buffalo, Town of Tonawanda, and Town of Amherst, Erie County, New York for the following years: 1900, 1916, 1928, 1932, 1935, 1950, 1957, 1964, and 1986. The maps were obtained from EDR.

2.1.4 City Directories

Watts reviewed City Directories for the City of Buffalo, Town of Tonawanda, and Town of Amherst, Erie County, New York for the following years: 1963, 1964, 1968, 1973, 1977, 1982, 1983, 1987, 1988, 1992, 1993, 1998, 1999, 2004, 2008, 2014, 2018, and 2019. The city directories were obtained from EDR.

2.1.5 Aerial Photographs

Aerial photographs dated 1927, 1938, 1951, 1958, 1966, 1971, 1978, 1981, 1985, 1995, 2006, 2009, 2013, and 2017 were reviewed in support of this assessment. The aerial photos were obtained from EDR.

2.2 Review of Government Records and Databases

The government records search included a review of federal, state, and local government databases of known or suspected inactive hazardous waste sites; petroleum and chemical bulk storage tank sites; reported spills, including leaking underground storage tanks; and hazardous waste generation sites.

Environmental Data Resources, Inc. (EDR), an independent research firm, was employed to perform a United States Environmental Protection Agency (USEPA) and New York State Department of Environmental Conservation (NYSDEC) database search for the proposed Project corridor.

Per the NYSDOT TEM, for transportation projects, the standard search distances in ASTM may be modified, and are generally shorter to reflect the linear geometry of transportation facilities. The federal and state databases, searched at ½-mile radii from the Project corridor, are summarized below:

- National Priorities List (NPL)
- National Priorities List Delisted (NPLD)
- Comprehensive Environmental Response, Compensation, and Liability Information System (CERCLIS)
- No Further Remedial Action Planned Sites (CERC-NFRAP)
- Corrective Action Sites (RCRA COR)
- Resource Conservation and Recovery Act (RCRA) Treatment, Storage, and Disposal Sites (RCRA TSD)
- Resource Conservation and Recovery Act (RCRA) Large and Small Quantity Generators (RCRA GEN)
- Federal Institutional and Engineering Controls (Fed IC/EC)
- Emergency Response Notification System (ERNS)
- NYSDEC Registry of Inactive Hazardous Waste Disposal Sites (SHWS)
- State/Tribal Solid Waste Landfills (SWL)
- State/Tribal Leaking Underground Storage Tanks (LTANKS)
- State/Tribal Underground Storage Tanks/ Aboveground Storage Tanks (UST/AST)
- State/Tribal Institutional & Engineering Controls (IC/EC)
- State/Tribal Voluntary Cleanup Program (VCP)
- State/Tribal Brownfield (Brownfield)
- Federal Brownfield (Brownfield)
- Hazardous Materials Information Reporting System (HMIRS)
- NYSDEC Spills (SPILLS)
- Non Generator (NON GEN)
- Toxic Chemical Inventory Release System (TRIS)
- Toxic Substances Control Act (TSCA)
- FIFRA/TSCA Tracking Systems (FTTS)
- Integrated Compliance Information System (ICIS)
- PCB Activity Database System (PADS)
- Material Licensing Tracking System (MLTS)
- Radiation Information Database (RADINFO)
- Facility Index System (FINDS)
- RCRA Administrative Action Tracking System (RAATS)
- Risk Management Plan (RMP)
- Hazardous Substance Waste Disposal (HSWDS)
- Hazardous Waste Manifest (Manifest)
- Manufactured Gas Plants (MGP)
- National Pollution Discharge Elimination System (NPDES)
- Tribal Lands (TRIBAL)

- Potentially Responsible Party (PRP)
- Aerometric Information Retrieval System (AIRS)

Watts also reviewed in-house data including NYSDEC, Division of Environmental Remediation, Freedom of Information Law (FOIL) and the NYSDEC Environmental Remediation Databases on their website. Information that did not yield potential contamination concerns for the Project corridor is not presented within this report. If potential contamination concerns were identified, such information is presented, by site, within Section 3.0 Findings.

Additional site information was also obtained through data searches of local agency files. These files were reviewed to determine past environmental problems, engineering studies, utility locations, and property ownership/boundaries. If potential contamination concerns were identified, such information is presented, by site, within Section 3.0 Findings. Watts made the following contacts:

- Town of Amherst for parcel information and hazardous materials information
- City of Buffalo for parcel information and hazardous materials information
- Town of Tonawanda for parcel information and hazardous materials information
- Erie County Department of Environmental and Planning for parcel information

2.3 Field Inspection

The field inspection is a walkover of the Project corridor to observe potential locations of contamination that may be environmental concerns and affect the design or construction of a project. Potential environmental concerns may be identified by: stained or discolored soil or building foundations; distressed, dead, or absence of vegetation; air emissions or odors; discolored or sheened surface water or ground water discharges; evidence of previous fill placement or waste disposal; and evidence of previous fires. Additional concerns may be identified by: evidence of former or existing underground storage tanks; aboveground storage tanks; monitoring wells; pipes or pipelines; 55-gallon drums or other evidence of bulk chemical storage and disposal; old pump islands; possible PCB storage, including transformers and former transformer pads; railroad tracks; sumps or septic systems; and pits, lagoons, or other surface impoundments. A site walkover reconnaissance of the corridor was conducted in March 2019.

2.4 Interviews

Contacts were made with a number of government agencies during the research of the subject property. If potential contamination concerns were identified, such information is presented, by site, within Section 3.0 Findings.

3.0 FINDINGS

A property is included in this section if it showed the potential to be an environmental concern in the general vicinity of the Project corridor during one of the methods of investigation listed in Section 2.0. Available information from researched sources is listed for each property followed by an evaluation of impacts or potential impacts on the Project corridor.

The following properties are considered to be potential environmental concerns with respect to the Project corridor. The Project corridor and the location of each property of potential environmental concern to the proposed Project are shown in Figures 2a-g (found at the end of this report) by designated site number. Many of the sites consist of more than one parcel (based on ownership). The addresses and ownership were identified on the Erie County GIS Parcel Viewer. Photographs of the sites of potential environmental concern can be found in Attachment B.

Each property identified below has been given a Property Risk Rating to assist with identification of sites that may require a Phase II ESA field investigation. The Property Risk Rating is a subjective number based on professional judgement in relation to the currently proposed construction and historic site uses; therefore, ratings may change during final design when the disturbance areas are known. Properties were assigned a rating score from 1 to 3; ratings are as follows:

1. A rating of 1 represents a recommendation for a Phase II ESA if fee acquisition and/or disturbance is proposed to occur on or adjacent to the site in question.
2. A rating of 2 represents a site where contamination may be encountered if disturbance is likely to occur on the site in question. The determination as to whether to perform a Phase II ESA on these sites will be made during final design when soil disturbance limits are known.
3. A rating of 3 represents a site where a Phase II ESA is not recommended at this time. A rating of 3 does not indicate a lack of contamination, it is a subjective determination of a lower risk for project impact. The contractor should be made aware of the concerns at these sites (through this Phase I ESA) so they can be prepared if signs of contamination are observed during construction. This will allow the contractor to make arrangements with a stand-by Environmental Monitor that can be called out to the site, if necessary.

3.1 University at Buffalo – 3425 Main Street

Site Inspection

This site is currently the University of Buffalo South Campus. The site includes numerous buildings, parking lots, and the NFTA University Metro Rail Station. The property is two parcels with the following SBL numbers: 79.10-1-1.111 and 79.10-1-1.112. Refer to Photos #2-3.

Aerial Photos
This site is depicted on the 1927, 1938, 1951, 1958, 1966, 1978, 1985, 1995, 2006, 2009, 2013, and 2017 aerial photos as the University of Buffalo. The number of buildings on the site has increased over the years.

Sanborn Maps
This site is depicted on the 1935, 1950, and 1986 Sanborn Fire Insurance Maps as the University of Buffalo. The number of buildings on the site has increased over the years. On the 1916 and 1900 maps, the site is depicted as the Erie County Poor House.

City Directories
The following business was identified on this site in the city directories:

Address	Use	Years
3435 Main Street	University	1964-2018

RCRA Generator
Two (2) RCRA GEN records were identified for this site. This database identified sites that generates, transports, treats, stores, or disposes of hazardous waste.

- State University of New York at Buffalo South Campus – 3425 Main Street
- State University of New York at Buffalo South Campus – 3435 Main Street

RCRA Non Generator
One (1) NON GEN record was identified for this site. This site was identified as a site that no longer generates, transports, treats, stores, or disposes of hazardous waste.

- State University of New York at Buffalo South Campus – 3435 Main Street

NYSDEC Spill Report Database
Ten (10) Spill records were identified for this site:

- McKay Heating Plant – 3545 Main Street: Spill #0375429 – human error (opened 9/5/2003, closed 12/18/2003). Contractor dropped a transmitter which contained mercury. Spill was cleaned up, closed and met NYSDEC cleanup standards.
- Buffalo College – 3435 Main Street: Spill #1704127 – equipment failure (opened 7/26/2017, closed 7/27/2017). A minor spill of diesel fuel was reported at the site. The spill was cleaned up by the fire department. Spill was cleaned up and closed but did not meet NYSDEC cleanup standards.
- University of Buffalo – 3435 Main Street: Spill #1100485 – other (opened 4/13/2011, closed 5/23/2011). Mercury was found in drain line. Spill was cleaned up, closed and met NYSDEC cleanup standards.

- University of Buffalo – 3435 Main Street: Spill #0711200 – equipment failure (opened 1/23/2008, closed 1/23/2009). Hydraulic oil spilled from a broken lift. Spill was cleaned up, closed and met NYSDEC cleanup standards.
- University of Buffalo – 3435 Main Street: Spill #1207951 – unknown (opened 10/1/2012, closed 4/4/2013). Contamination was found during construction. Contaminated soil was removed. Spill was cleaned up and closed but did not meet NYSDEC cleanup standards.
- University of Buffalo – 3435 Main Street: Spill #0075177 – equipment failure (opened 6/20/2000, closed 10/18/2000). Hydraulic oil spilled onto the lawn from a riding mower. Spill was cleaned up, closed and met NYSDEC cleanup standards.
- University of Buffalo – 3435 Main St: Spill #0913360 – unknown (opened 3/18/2010, closed 3/22/2010). A trailer labeled asbestos appeared to be leaking water. Spill was cleaned up and closed but did not meet NYSDEC cleanup standards.
- UB South Campus – Main Street: Spill #0650660 – equipment failure (opened 7/20/2006, closed 7/21/2006). A hose broke spilling hydraulic oil. Spill was cleaned up, closed and met NYSDEC cleanup standards.
- SUNY at Buffalo – Atchison Hall: Spill #8803631 – other (opened 7/26/1988, closed 10/26/1988). Fire within the chemistry building. Spill was cleaned up, closed and met NYSDEC cleanup standards.
- SUNY at Buffalo – Main Street: Spill #8706241 – human error (opened 10/23/1987, closed 10/23/1987). Containment within building. Spill was cleaned up, closed and met NYSDEC cleanup standards.

Leaking Storage Tanks

Three (3) LTANKS records were identified for this site:

- University of Buffalo – 3435 Main Street: Spill #9004852 – tank test failure (opened 7/31/1990, closed 12/23/1993). A tank was found to be taking on water. Tank and contaminated soil was removed. Spill was cleaned up and closed but did not meet NYSDEC cleanup standards. Since this spill did not meet NYSDEC cleanup standards, UB was contacted (5/15/2024) for details on this spill and their representative indicated that they would look into the matter further and contact retired employees for additional information. The UB representative agreed that this former tank was likely near one of the buildings. Since the buildings are generally far from the proposed excavations for the project, there is no reason to believe that this former tank was close enough to be considered an environmental concern for the proposed project. If additional information indicating a potential project concern is discovered through UB's ongoing research, this report will be updated to reflect the new information.
- University of Buffalo – 3435 Main Street: Spill #9307528 – tank test failure (opened 9/21/1993, closed 11/19/1993). Tank failed its tightness test, was retested and passed. Spill was cleaned up, closed and met NYSDEC cleanup standards.

- SUNY Buffalo – Talbert Hall: Spill #0102018 – tank failure (opened 5/22/2001, closed 2/19/2002). Contamination was found during tank removal. Contaminated soil was removed. Spill was cleaned up, closed and met NYSDEC cleanup standards.

Integrated Compliance Information System
One (1) ICIS record was identified for this site. This record identifies properties that have Federal Administrative and Judicial enforcement actions.

- State University of New York at Buffalo South Campus – 3435 Main Street

Enforcement & Compliance History Online
Two (2) ECHO records were identified for this site. This database identifies properties that have compliance and enforcement actions.

- State University of New York at Buffalo South Campus – 3435 Main Street
- State University Construction Fund – 3435 Main Street

Aerometric Information Retrieval System
One (1) AIRS record was identified for this site. This database identifies sites that are or were point source emissions sources.

- State University of New York at Buffalo South Campus – 3435 Main Street

Hazardous Waste Manifest
One (1) HW Manifest record was identified for this site. This site has or had manifests for hazardous materials that they utilized or stored onsite.

- State University of New York at Buffalo South Campus – 3435 Main Street

Property Risk Rating
This property has been given a Property Risk Rating of 3 since there is a lower likelihood of project impact due to the location of the tanks and historic contamination in relation to the currently proposed construction areas.

3.2 Subway Restaurant – 3384 Main Street

Site Inspection
This site is currently a Subway restaurant. The site includes the building and the associated parking lot. The property is one parcel with the following SBL number: 79.47-3-10. Refer to Photo #1.

Sanborn Maps
This site is depicted on the 1935 and 1950 Sanborn Fire Insurance Maps as a gas station with three tanks.

City Directories
The following businesses were identified on this site in the city directories:

Address	Use	Years
3382 Main Street	Restaurant	1973-2018
3384 Main Street	Store	1964-1968

Historic Auto
One (1) Historic Auto record was identified for this site. This database identifies sites that are considered potential gas stations, filling stations, and/or service stations.

- Keating Gas Station – 3384 Main Street: 1930-1955

Property Risk Rating
This property has been given a Property Risk Rating of 2 since construction is not proposed on or adjacent to this site.

3.3 Walgreens – 3490 Main Street

Site Inspection
This site is currently operated by Walgreens Co., a pharmacy and retail store. The site includes the building and the associated parking lot. The property is one parcel with the following SBL number: 79.39-6-5. Refer to Photo #4.

Aerial Photos
This site is under construction on the 1927 photo with disturbed land. Windermere Boulevard divides the site. There are two small structures on the eastern portion of the site. On the 1938 photo, Windermere Boulevard continues to divide the site. There is now one building on each side of the site. On the 1951, 1958, 1966, 1978, 1985, and 1995 photos, Windermere Boulevard continues to divide the site. There is a large building covering the western side of the site and several smaller buildings are depicted on the eastern side of the site. On the 2006, 2009, 2013, and 2017 photos, the site is similar to the current configuration.

Sanborn Maps
This site is depicted on the 1950 and 1986 Sanborn Fire Insurance Maps as an auto sales and service with three tanks (3484 Main Street); a gas station with three tanks (3488 Main Street) and a gas station with four tanks (3514 Main Street). On the 1935 map, there is only one gas station (3488 Main Street) on the site with three tanks.

City Directories
The following businesses were identified on this site in the city directories:

Address	Use	Years
3484 Main Street	Auto Sales & Service	1964-1992
3488 Main Street	Gas Station	1964-1992
3488 Main Street	Pharmacy	2004-2018
3514 Main Street	Gas Station	1964-1977

RCRA Generator
One (1) RCRA GEN record was identified for this site. This database identified sites that generates, transports, treats, stores, or disposes of hazardous waste.

- Basil Ford – 3484 Main Street

RCRA Non Generator
Two (2) NON GEN records were identified for this site. This site was identified as a site that no longer generates, transports, treats, stores or disposes of hazardous waste.

- 7-Eleven #22491 – 3488 Main Street
- Mobil Oil Corp – 3514 Main Street

Hazardous Waste Manifest
One (1) HW Manifest record was identified for this site. This site has or had manifests for hazardous materials that they utilized or stored onsite.

- Mobil Oil Corp – 3514 Main Street

NYSDEC Bulk Storage Database
Three (3) UST/AST records were listed for this site:

- 7-Eleven #22491 – 3488 Main Street: Three tanks (all closed-removed)
- Basil Ford – 3484 Main Street: Five tanks (1 in service, 4 closed-removed)
- Mobil Oil Corp – 3514 Main Street: Three tanks (all closed prior to 3/1991)

NYSDEC Spill Report Database
Six (6) Spill records were identified for this site:

- Mobil – Main Street and Kenmore Avenue: Spill #8708684 – deliberate (opened 1/12/1988, closed 1/14/1988). NYSDEC received report of waste oil being dumped into sewer. The NYSDEC investigated and no spill was found. The Spill record was closed and met NYSDEC cleanup standards.

- ROW – Main Street and Kenmore Avenue: Spill #0485256 – unknown (opened 1/1/2004, closed 11/3/2005). Contamination was found during road work and removed. Spill was cleaned up and closed but did not meet NYSDEC cleanup standards.
- Basil Ford – Main Street at Windemere Avenue: Spill #9514248 – housekeeping (opened 2/7/1996, closed 2/9/1996). Sheen was found on driveway. Spill was cleaned up, closed and met NYSDEC cleanup standards.
- Former Basil Ford – Main Street at Windemere Avenue: Spill #9514250 – other (opened 2/1/1996, closed 3/21/1996). Contamination was found during tank removal. Spill was cleaned up, closed and met NYSDEC cleanup standards.
- 7-Eleven Store #2249 – 3488 Main Street: Spill #9211094 – equipment failure (opened 12/23/1992, closed 11/3/2000). A submersible pump leaked to the backfill around the pump. Tanks were removed and gasoline sales ended for this site. Spill was cleaned up and closed but did not meet NYSDEC cleanup standards.
- Walgreens Parking Lot – 3488 Main Street: Spill #1601035 – equipment failure (opened 5/1/2016, closed 5/2/2016). A minor spill from a passenger vehicle was cleaned up by the fire department. Spill was cleaned up and closed but did not meet NYSDEC cleanup standards.

Leaking Storage Tanks

Four (4) LTANKS records were identified for this site:

- Mobil Oil Corp – 3514 Main Street: Spill #8908630 – tank failure (opened 11/1/1989, closed 10/30/1990). A site investigation of an old gas station found contamination. Spill was cleaned up, closed and met NYSDEC cleanup standards.
- Southland Corp. 7-Eleven – 3488 Main Street: Spill #8702468 – tank test failure (opened 6/23/1987, closed 8/11/1987). Two tanks failed tightness test. Tanks were retested and problem was identified to be in the lines. Spill was cleaned up, closed and met NYSDEC cleanup standards.
- Basil Ford – 3484 Main Street: Spill #9501367 – tank failure (opened 4/6/1995, closed 11/17/1995). Contamination was found during tank removal. Spill was cleaned up, closed and met NYSDEC cleanup standards.
- Mobil Oil Corp – 3514 Main Street: Spill #9207319 – tank failure (opened 9/18/1992, closed 12/4/1996). Oil was found in the monitoring wells at this site. Contaminated soil and water were removed. Spill was cleaned up and closed but did not meet NYSDEC cleanup standards.

Historic Auto

One (1) Historic Auto record was identified for this site. This database identifies sites that are considered potential gas stations, filling stations, and/or service stations.

- Kendall Service Station – 3488 Main Street: 1935-1980

Enforcement & Compliance History Online
Three (3) ECHO records were identified for this site. This database identifies properties that have compliance and enforcement actions.

- Mobil Oil Corp – 3514 Main Street
- 7-Eleven #22491 – 3488 Main Street
- Basil Ford – 3484 Main Street

Property Risk Rating
This property has been given a Property Risk Rating of 1 due to a higher likelihood of contamination and that construction is proposed nearby to this site.

3.4 University Plaza – 3500 Main Street

Site Inspection
This site is currently a shopping plaza. The site includes several large buildings and the associated parking lots. The property is one parcel with the following SBL number: 79.32-2-24. Refer to Photos #5-6.

Aerial Photos
This site is depicted on the 1927 and 1938 photos as open land with small structures along Main Street. On the 1951, 1958, 1966, 1978, 1985, and 1995 photos, the site is depicted as a shopping plaza although the buildings are different than current configuration. On the 2006, 2009, 2013, and 2017 photos, the site is similar to the current configuration.

Sanborn Maps
This site is depicted on the 1957 and 1950 Sanborn Fire Insurance Maps as a shopping plaza. On the 1932 map, the site is depicted as a gas station with five tanks, a storefront, a residential dwelling, and an auto repair shop.

NYSDEC Spill Report Database
Three (3) Spill records were identified for this site:

- University Plaza – 3500 Main Street: Spill #9404727 – equipment failure (opened 7/6/1994, closed 7/21/1994). Gas tank fell off car. Spill was cleaned up, closed and met NYSDEC cleanup standards.
- University Plaza – 3500 Main Street: Spill #9404763 – equipment failure (opened 7/6/1994, closed 7/11/1994). This is a duplicate of Spill #9404727. Spill was cleaned up, closed and met NYSDEC cleanup standards.
- AJ Wright – 3500 Main Street: Spill #0813644 – equipment failure (opened 3/18/2009, closed 3/18/2009). A transformer failed spilling oil onto pavement. Spill was cleaned up, closed and met NYSDEC cleanup standards.

Property Risk Rating
This property has been given a Property Risk Rating of 3 since there is a lower likelihood of project impact due to the location of the tanks and historic contamination in relation to the currently proposed construction areas.

3.5 May Jen Chinese Restaurant – 47 Kenmore Avenue

Site Inspection
This site is currently a restaurant. The site includes the building and the associated parking lot. The property is one parcel with the following SBL number: 79.32-2-21. Refer to Photo #7.

Aerial Photos
This site is depicted on the 1927 and 1938 photos as open land. On the 1951, 1958, 1966, 1978, 1985, 1995, 2006, 2009, 2013, and 2017 photos, the site consists of a single building.

Sanborn Maps
This site is depicted on the 1957 Sanborn Fire Insurance Map as a storefront. On the 1932 and 1950 maps, the site is a vacant lot.

City Directories
The following business was identified on this site in the city directories:

Address	Use	Years
47 Kenmore Avenue	Shoe Repair, Laundry & Dry Cleaner	1973-1992

Property Risk Rating
This property has been given a Property Risk Rating of 3 since there is no record of spills or tanks.

3.6 Vacant Lot – 159 Kenmore Avenue

Site Inspection
This site is currently a vacant lot. The property is one parcel with the following SBL number: 79.31-3-23. Refer to Photo #8.

Aerial Photos
A single small building is depicted on this site on the 1927 and 1938 photos. On the 1951, 1958, 1966, 1978, 1985, 1995, and 2006 photos, there is a different small building on the site. The site is vacant on the 2009, 2013, and 2017 photos.

Sanborn Maps
This site is depicted on the 1950 and 1957 Sanborn Fire Insurance Maps as a gas station with two tanks. On the 1932 maps, the site is a residential dwelling.

City Directories
The following businesses were identified on this site in the city directories:

Address	Use	Years
165 Kenmore Avenue	Gas Station	1983
175 Kenmore Avenue	Gas Station	1964-1999

RCRA Non Generator
One (1) NON GEN record was identified for this site. This site was identified as a site that no longer generates, transports, treats, stores or disposes of hazardous waste.

- Kwik Fill – 175 Kenmore Avenue

Hazardous Waste Manifest
One (1) HW Manifest record was identified for this site. This site has or had manifests for hazardous materials that they utilized or stored onsite.

- Kwik Fill – 175 Kenmore Avenue

NYSDEC Bulk Storage Database
One (1) UST/AST record was listed for this site:

- Red Apple Food Mart #325 – 175 Kenmore Avenue: Three tanks (all closed-removed)

NYSDEC Spill Report Database
One (1) Spill record was identified for this site:

- Kwik Fill – 175 Kenmore Avenue: Spill #0651775 – tank failure (opened 12/28/2006, closed 3/5/2007). Contaminated soil found while removing lines. Spill was cleaned up and closed but did not meet NYSDEC cleanup standards.

Leaking Storage Tanks
One (1) LTANKS record was identified for this site:

- Kwik Fill – 175 Kenmore Avenue: Spill #9875345 – tank failure (opened 1/1/1999, closed 5/1/2000). Contaminated soil found while demolishing building. Spill was cleaned up and closed but did not meet NYSDEC cleanup standards.

Historic Auto
One (1) Historic Auto record was identified for this site. This database identifies sites that are considered potential gas stations, filling stations, and/or service stations.

- Edward Bush Service & Gas Station – 175 Kenmore Avenue: 1955

Enforcement & Compliance History Online
One (1) ECHO record was identified for this site. This database identifies properties that have compliance and enforcement actions.

- Kwik Fill – 175 Kenmore Avenue

Property Risk Rating
This property has been given a Property Risk Rating of 1 due to a higher likelihood of contamination and fee acquisition of this site is proposed.

3.7 Storefronts – 240-242 Niagara Falls Boulevard

Site Inspection
This site is currently three storefronts, Reflections Salon, Aftermath Tattoo Studio, and Mystic Blue Aquarium. The site includes the building and the associated parking lot. The property is two parcels with the following SBL numbers: 79.23-2-29 and 79.23-2-30. Refer to Photo #9.

Aerial Photos
The current building is depicted on the site on the 1927, 1938, 1951, 1958, 1966, 1978, 1985, 1995, 2006, 2009, 2013, and 2017 photos.

Sanborn Maps
This site is depicted on the 1950 and 1964 Sanborn Fire Insurance Maps as a gas station and auto repair shop at 240 Niagara Falls Boulevard and an auto repair shop at 242 Niagara Falls Boulevard. A gas tank was depicted within the ROW of Kenilworth Avenue on the 1950 map. On the 1928 map, the site is depicted as two storefronts with three gas tanks in front and one tank within the ROW of Kenilworth Avenue.

NYSDEC Bulk Storage Database
One (1) UST/AST record was listed for this site:

- Great Lakes Divers – 240 Niagara Falls Boulevard: 1 tank (closed – in place)

Leaking Storage Tanks
Three (3) LTANKS records were identified for this site:

- Bob Hills Old Gas Station – 240 Niagara Falls Boulevard: Spill #9608361 – tank overfill (opened 10/3/1996, closed 12/31/1996). Contamination was found during tank removal. Spill was cleaned up and closed but did not meet NYSDEC cleanup standards.
- Bob Hills Old Gas Station – 240 Niagara Falls Boulevard: Spill #9608691 – tank test failure (opened 10/12/1996, closed 10/15/1996). This is a duplicate of Spill 9608361. Spill was cleaned up, closed and met NYSDEC cleanup standards.
- Bob Hills Old Gas Station – 240 Niagara Falls Boulevard: Spill #9713199 – tank failure (opened 3/16/1998, closed 2/25/1998). Site investigation found soil contamination. Contaminated soil was removed. Spill was cleaned up, closed and met NYSDEC cleanup standards.

Historic Auto

One (1) Historic Auto record was identified for this site. This database identifies sites that are considered potential gas stations, filling stations, and/or service stations.

- George Brown Gas Station – 240-246 Niagara Falls Boulevard: 1971-1974

Property Risk Rating

This property has been given a Property Risk Rating of 1 due to a higher likelihood of contamination and that construction is proposed nearby to this site.

3.8 Sweeney's Garage – 424 Niagara Falls Boulevard

Site Inspection

This site is currently an auto repair shop. The site includes the building and the associated parking lots. The property is one parcel with the following SBL number: 67.79-2-9. Refer to Photo #10.

Aerial Photos

The current building is depicted on the site on the 1927, 1938, 1951, 1958, 1966, 1978, 1985, 1995, 2006, 2009, 2013, and 2017 photos.

Sanborn Maps

This site is depicted on the 1950 and 1964 Sanborn Fire Insurance Maps as two storefronts with an auto repair shop at the rear. On the 1928 map, the there are two gas tanks in front of the storefronts.

City Directories

The following businesses were identified on this site in the city directories:

Address	Use	Years
424 Niagara Falls Boulevard	Auto Repair Shop	1983-2018

Address	Use	Years
424 Niagara Falls Boulevard	Dry Cleaners	1983-1987

NYSDEC Spill Report Database
Four (4) Spill records were identified for this site:

- Sweeney's Garage – 424 Niagara Falls Boulevard: Spill #9006553 – deliberate (opened 9/1/1990, closed 9/24/1990). Oil was reportedly being dumped into street by an unknown citizen. No spill was found. Spill was closed and met NYSDEC cleanup standards.
- Sweeney's Garage – 424 Niagara Falls Boulevard: Spill #0075398 – unknown (opened 9/26/1990, closed 12/5/1990). Contamination was found while removing waste oil tank. Spill was cleaned up, closed and met NYSDEC cleanup standards.
- Sweeney's Garage – 424 Niagara Falls Boulevard: Spill #9975654 – deliberate (opened 1/1/2000, closed 1/24/2000). Owner reported that someone dumped an unknown material into their waste oil tank. No spill was found. Spill was closed and met NYSDEC cleanup standards.
- Sweeney's Garage – 424 Niagara Falls Boulevard: Spill #9306642 – deliberate (opened 8/1/1993, closed 9/3/1993). Oil was reportedly being drained onto street. No spill was found. Spill was closed and met NYSDEC cleanup standards.

Leaking Storage Tanks
One (1) LTANKS record was identified for this site:

- Sweeney's Garage – 424 Niagara Falls Boulevard: Spill #9802942 – tank failure (opened 6/3/1998, closed 9/14/1998). Contamination was found during tank removal. Spill was cleaned up and closed but did not meet NYSDEC cleanup standards.

Historic Auto
One (1) Historic Auto record was identified for this site. This database identifies sites that are considered potential gas stations, filling stations, and/or service stations.

- Sweeney's Garage – 424 Niagara Falls Boulevard: 1982-2014

Property Risk Rating
This property has been given a Property Risk Rating of 1 due to a higher likelihood of contamination and that construction is proposed nearby to this site.

3.9 American Auto World – 733 Niagara Falls Boulevard

Site Inspection
This site is currently an auto repair shop. The site includes the building and the associated parking lots. The property is one parcel with the following SBL number: 67.55-8-1. Refer to Photo #11.

Aerial Photos
This site is depicted as agricultural land on the 1927 and 1938 photos. The current building is depicted on the site on the 1951, 1966, 1978, 1985, 1995, 2006, 2009, 2013, and 2017 photos.

City Directories
The following business was identified on this site in the city directories:

Address	Use	Years
733 Niagara Falls Boulevard	Auto Repair Shop	1983-2018

RCRA Non Generator
One (1) NON GEN record was identified for this site. This site was identified as a site that no longer generates, transports, treats, stores or disposes of hazardous waste.

- AF Automotive – 733 Niagara Falls Boulevard

Hazardous Waste Manifest
One (1) HW Manifest record was identified for this site. This site has or had manifests for hazardous materials that they utilized or stored onsite.

- AF Automotive – 733 Niagara Falls Boulevard

NYSDEC Bulk Storage Database
One (1) UST/AST record was listed for this site:

- AF Automotive – 733 Niagara Falls Boulevard: Three tanks (closed-removed)

NYSDEC Spill Report Database
One (1) Spill record was identified for this site:

- AF Automotive – 733 Niagara Falls Boulevard: Spill #0485611 – unknown (opened 3/3/2005, closed 1/16/2014). Contamination was found during a site investigation. The contaminated soil was removed from the site. Spill was cleaned up and closed but did not meet NYSDEC cleanup standards.

Historic Auto
One (1) Historic Auto record was identified for this site. This database identifies sites that are considered potential gas stations, filling stations, and/or service stations.

- American Auto World – 733 Niagara Falls Boulevard: 1969-2014

Enforcement & Compliance History Online
One (1) ECHO record was identified for this site. This database identifies properties that have compliance and enforcement actions.

- AF Automotive – 733 Niagara Falls Boulevard

Property Risk Rating
This property has been given a Property Risk Rating of 1 due to a higher likelihood of contamination and that construction is proposed nearby to this site.

3.10 Empire Auto Electric – 803 Niagara Falls Boulevard

Site Inspection
This site is currently an auto repair shop. The site includes the building and the associated parking lots. The property is one parcel with the following SBL number: 67.47-12-4. Refer to Photo #12.

Aerial Photos
This site is depicted as vacant land on the 1927, 1938, and 1951 photos. A single building is depicted on the 1966, 1978 and 1985 photos. The building has been expanded on the 1995, 2006, 2009, 2013, and 2017 photos.

City Directories
The following business was identified on this site in the city directories:

Address	Use	Years
820 Niagara Falls Boulevard	Auto Repair Shop	1983-1993

Property Risk Rating
This property has been given a Property Risk Rating of 2 since there is no specific indication of tanks or spills.

3.11 NOCO Express – 820-828 Niagara Falls Boulevard

Site Inspection
This site is currently a gas station. The site includes the building, associated parking lots and a fueling area. The property is two parcels with the following SBL numbers: 67.47-3-5 and 67.47-3-4. Refer to Photo #13.

Aerial Photos
This site is depicted as vacant land on the 1927, 1938, and 1951 photos. A single building is depicted on the 1966 and 1978 photos. The current building is depicted on the site on the 1985, 1995, 2006, 2009, 2013, and 2017 photos.

Sanborn Maps
This site is depicted on the 1986 Sanborn Fire Insurance Map as a gas station.

City Directories
The following businesses were identified on this site in the city directories:

Address	Use	Years
826 Niagara Falls Boulevard	Auto Repair Shop	1983-1987
826 Niagara Falls Boulevard	Gas Station	1999-2018

NYSDEC Bulk Storage Database
Two (2) UST/AST records were listed for this site:

- NOCO Express – 820 Niagara Falls Boulevard: Three tanks (in service)
- Jim Woods Tire & Battery – 820 Niagara Falls Boulevard: Three tanks (closed-removed)

NYSDEC Spill Report Database
Seven (7) Spill records were identified for this site:

- Uni-Mart Store – Niagara Falls Boulevard& Moore Avenue: Spill #9611103 – human error (opened 12/6/1996, closed 12/6/1996). Customer overfilled tank. Spill was cleaned up and closed but did not meet NYSDEC cleanup standards.
- Former Uni-Mart – 820 Niagara Falls Boulevard: Spill #1003350 – equipment failure (opened 4/2/1996, closed 4/3/1996). A dispenser leaked gas onto the ground. Spill was cleaned up and closed but did not meet NYSDEC cleanup standards.
- Former Uni-Mart – 820 Niagara Falls Boulevard: Spill #9710897 – human error (opened 12/27/1997, closed 4/19/1999). Driver pulled away with nozzle in car. Spill was cleaned up, closed and met NYSDEC cleanup standards.

- Former Uni-Mart – 820 Niagara Falls Boulevard: Spill #9712476 – other (opened 2/9/1998, closed 1/30/2015). Contaminated soil was encountered in front of the active gas station while installing a water line in ROW. Spill was cleaned up and closed but did not meet NYSDEC cleanup standards.
- Former Uni-Mart – 820 Niagara Falls Boulevard: Spill #9806636 – equipment failure (opened 8/28/1998, closed 9/8/1998). The hose on a gas pump blew spilling gas on blacktop. Spill was cleaned up, closed and met NYSDEC cleanup standards.
- Former Uni-Mart – 820 Niagara Falls Boulevard: Spill #1205616 – equipment failure (opened 9/5/2012, closed 9/5/2012). Customer drove off with nozzle in car. Spill was cleaned up, closed and met NYSDEC cleanup standards.
- Former Uni-Mart – 820 Niagara Falls Boulevard: Spill #0211039 – equipment failure (opened 2/4/2003, closed 2/5/2003). The gas line on a truck failed, spilling hydraulic fluid onto blacktop. Spill was cleaned up, closed and met NYSDEC cleanup standards.

Leaking Storage Tanks
One (1) LTANKS record was identified for this site:

- Jim Woods Tire & Battery – 820 Niagara Falls Boulevard: Spill #8707234 – tank test failure (opened 10/20/1988, closed 10/20/1988) – A tank failed its tighness test. The tank was retested and passed. Spill was closed and met NYSDEC cleanup standards.

Historic Auto
One (1) Historic Auto record was identified for this site. This database identifies sites that are considered potential gas stations, filling stations, and/or service stations.

- Jim & Dee's Atlantic Service – 826 Niagara Falls Boulevard: 1969-1993

Property Risk Rating
This property has been given a Property Risk Rating of 1 due to a higher likelihood of contamination and that construction is proposed nearby to this site.

3.12 Sentry North Appliance Service – 845 Niagara Falls Boulevard

Site Inspection
This site is currently an appliance repair company. The site includes the building and the associated parking lot. The property is one parcel with the following SBL number: 67.47-7-16. Refer to Photo #14.

Aerial Photos
This site is depicted as agricultural land on the 1927, 1938 and 1951 photos. The current building is depicted on the site on the 1966, 1978, 1985, 1995, 2006, 2009, 2013, and 2017 photos.

City Directories
The following business was identified on this site in the city directories:

Address	Use	Years
845 Niagara Falls Boulevard	Appliance Repair Shop	1987-2018

Historic Cleaner
One (1) Historic Cleaner record was identified for this site. This database identifies sites that are considered potential dry cleaners, cleaners, laundries and/or laundromats.

- Economy Cleaners – 845 Niagara Falls Boulevard: 1980-1985

Property Risk Rating
This property has been given a Property Risk Rating of 3 since there is no record of spills or tanks.

3.13 Fancy Florist and Storefront – 853 Niagara Falls Boulevard

Site Inspection
This site is currently two storefronts, Fancy Florist and a vacant storefront. The site includes the building and the associated parking lot. The property is one parcel with the following SBL number: 67.47-7-3.1. Refer to Photo #15.

Aerial Photos
This site is depicted as agricultural land on the 1927 and 1938 photos. On the 1951 and 1966 photos, a single small building is depicted on the site. The current building is depicted on the site on the 1978, 1985, 1995, 2006, 2009, 2013, and 2017 photos.

City Directories
The following business was identified on this site in the city directories:

Address	Use	Years
853 Niagara Falls Boulevard	Auto Repair Shop	2004

NYSDEC Spill Report Database
One (1) Spill records was identified for this site:

- Carmella Termullo and John Zaprowski – 853-855 Niagara Falls Boulevard: Spill #0550174 – abandoned drums (opened 4/28/2005, closed 10/3/2005). Contamination was founding during an environmental site investigation. The contaminated soil was removed. Spill was cleaned up, closed and met NYSDEC cleanup standards.

Property Risk Rating

This property has been given a Property Risk Rating of 2 since the suspect use is in recent history and the cleaned-up spill met NYSDEC standards.

3.14 Corsi A First Klass Collision Center – 874 Niagara Falls Boulevard

Site Inspection

This site is currently an auto repair shop. The site includes the building and the associated parking lots. The property is one parcel with the following SBL number: 67.39-2-8. Refer to Photo #16.

Aerial Photos

This site is depicted as vacant land on the 1927, 1938, and 1951 photos. On the 1966 photo, a single small building is depicted on the site. The current building is depicted on the site on the 1978, 1985, 1995, 2006, 2009, 2013, and 2017 photos.

Sanborn Maps

This site is depicted on the 1986 Sanborn Fire Insurance Map as a car wash.

City Directories

The following business was identified on this site in the city directories:

Address	Use	Years
874 Niagara Falls Boulevard	Auto Repair Shop	1983-2014

Enforcement & Compliance History Online

One (1) ECHO record was identified for this site. This database identifies properties that have compliance and enforcement actions.

- Corsi Auto Body & Glass – 874 Niagara Falls Boulevard

Aerometric Information Retrieval System

One (1) AIRS record was identified for this site. This database identifies sites that are or were point source emissions sources.

- Corsi Auto Body & Glass – 874 Niagara Falls Boulevard

Property Risk Rating

This property has been given a Property Risk Rating of 1 due to a higher likelihood of contamination and that fee acquisition and construction are proposed for this site.

3.15 Lombardo Corporate Office – 899 Niagara Falls Boulevard

Site Inspection

This site is currently a funeral home corporate office. The site includes the building and the associated parking lots. The property is one parcel with the following SBL number: 67.39-5-2.11. Refer to Photo #17.

Aerial Photos

This site is depicted as agricultural land on the 1927 and 1938 photos. The current building is depicted on the site on the1951, 1966, 1978, 1985, 1995, 2006, 2009, 2013, and 2017 photos.

Sanborn Maps

A gas station (895 Niagara Falls Boulevard) is depicted on the 1957 Sanborn Fire Insurance Map.

City Directories

The following businesses were identified on this site in the city directories:

Address	Use	Years
899 Niagara Falls Boulevard	Auto Repair Shop	1993
899 Niagara Falls Boulevard	Funeral Home	2001-2014

NYSDEC Spill Report Database

One (1) Spill records was identified for this site:

- Former Gas Station – 895 Niagara Falls Boulevard: Spill #0075336 – unknown (opened 8/1/2000, closed 2/14/2001). Contamination was founding during a site investigation. The contaminated soil was removed. Spill was cleaned up, closed and met NYSDEC cleanup standards.

Property Risk Rating

This property has been given a Property Risk Rating of 1 due to a higher likelihood of contamination and that construction is proposed nearby to this site.

3.16 U-Haul – 925 Niagara Falls Boulevard

Site Inspection
This site is currently a truck rental company. The site includes the building and the associated parking lots. The property is one parcel with the following SBL number: 67.39-5-1. Refer to Photo #18.

Aerial Photos
A single small building is depicted on this site on the 1927 and 1938 photos. On the 1951 and 1966 photos, there are two small buildings on the site. The current building is depicted on the site on the 1978, 1985, 1995, 2006, 2009, 2013, and 2017 photos.

City Directories
The following business was identified on this site in the city directories:

Address	Use	Years
925 Niagara Falls Boulevard	Truck Rental Co.	1983-2018

NYSDEC Bulk Storage Database
One (1) UST/AST record was listed for this site:

- Boulevard U-Haul Center – 925 Niagara Falls Boulevard: 4 tanks (closed-removed)

NYSDEC Spill Report Database
Two (2) Spill records were identified for this site:

- NYSDOT Project/U-Haul – 925 Niagara Falls Boulevard: Spill #9803568 – other (opened 6/1/1998, closed 11/26/1999). NYSDOT found tank on their row during construction project. No contamination was found. Tank was removed. Spill was cleaned up, closed and met NYSDEC cleanup standards.
- NYSDOT Project/U-Haul – Niagara Falls Boulevard /Eggert Road: Spill #9975504 – other (opened 11/1/1999, closed 11/1/1999). This is a duplicate of Spill #9803568. Spill was closed and met NYSDEC cleanup standards.

Historic Auto
One (1) Historic Auto record was identified for this site. This database identifies sites that are considered potential gas stations, filling stations, and/or service stations.

- John's Super Shell Service – 925 Niagara Falls Boulevard: 1970-1985

Property Risk Rating

This property has been given a Property Risk Rating of 1 due to a higher likelihood of contamination and that fee acquisition and construction are proposed for this site.

3.17 Sun City Mattress – 926 Niagara Falls Boulevard

Site Inspection

This site is currently a mattress store. The site includes the building and the associated parking lot. The property is one parcel with the following SBL number: 67.39-2-4.1. Refer to Photo #19.

Aerial Photos

This site is depicted as vacant land on the 1927, 1938, and 1951 photos. The current building is depicted on the site on the 1966, 1978, 1985, 1995, 2006, 2009, 2013, and 2017 photos.

Sanborn Maps

This site is depicted on the 1986 Sanborn Fire Insurance Map as an auto repair shop.

City Directories

The following business was identified on this site in the city directories:

Address	Use	Years
926 Niagara Falls Boulevard	Auto Repair Shop	1983-1987

Property Risk Rating

This property has been given a Property Risk Rating of 1 due to a higher likelihood of contamination and that fee acquisition and construction are proposed for this site.

3.18 Partner's Bar & Pizzeria – 934 Niagara Falls Boulevard

Site Inspection

This site is currently a pizza restaurant. The site includes the building and the associated parking lots. The property is one parcel with the following SBL number: 67.39-2-1.1. Refer to Photo #20.

Aerial Photos

This site is depicted as vacant land on the 1927, 1938, and 1951 photos. On the 1966 and 1978 photos, a single small building is depicted on the site. The current building and parking lot are depicted on the site on the 1985, 1995, 2006, 2009, 2013, and 2017 photos.

Sanborn Maps
This site is depicted on the 1986 Sanborn Fire Insurance Map as a gas station.

City Directories
The following businesses were identified on this site in the city directories:

Address	Use	Years
934 Niagara Falls Boulevard	Auto Repair Shop	1983-2008
934 Niagara Falls Boulevard	Restaurant	2018

NYSDEC Bulk Storage Database
One (1) UST/AST record was listed for this site:

- Speedy Auto Service – 934 Niagara Falls Boulevard: 1 tank (closed-removed)

Property Risk Rating
This property has been given a Property Risk Rating of 1 due to a higher likelihood of contamination and that fee acquisition and construction are proposed for this site.

3.19 Stanton Optical – 2965 Sheridan Drive

Site Inspection
This site is currently a medical office and retail shop. The site includes the building, associated parking lots, and mowed lawn. The property is one parcel with the following SBL number: 67.31-2-1. Refer to Photo #21.

Aerial Photos
This site is depicted as vacant land on the 1927, 1938, 1951, and 1958 photos. On the 1966, 1978, 1985, 1995, 2006, and 2009 photos the site is depicted as a gas station. The current building and parking lot are depicted on the site on the 2013 and 2017 photos.

Sanborn Maps
This site is depicted on the 1986 Sanborn Fire Insurance Map as a gas station.

NYSDEC Bulk Storage Database
One (1) UST/AST record was listed for this site:

- Exxon Mobil Oil Corp – 2965 Sheridan Drive: 6 tanks (all closed-removed)

NYSDEC Spill Report Database
Four (4) Spill records were identified for this site:

- NYSDOT Project/Accadia – Niagara Falls Boulevard/Sheridan Drive: Spill #9975503 – other (opened 11/1/1999, closed 11/1/1999). NYSDOT removed tanks within their ROW. Spill was cleaned up, closed and met NYSDEC cleanup standards.
- NFG Excavation – Niagara Falls Boulevard/Eggert Road: Spill #9802491 – unknown (opened 5/27/1998, closed 1/17/2003). Spill was cleaned up, closed and met NYSDEC cleanup standards.
- Mobil Oil – 2965 Sheridan Drive: Spill #0105744 – unknown (opened 8/28/2001, closed 7/12/2007). During a dispenser upgrade at this site historic contamination was discovered. Six tanks and contaminated soil was removed from the site. Spill was cleaned up and closed but did not meet NYSDEC cleanup standards.
- Mobil Oil – 2965 Sheridan Drive: Spill #9007600 – equipment failure (opened 10/11/1990, closed 3/4/1991). A leaking hydraulic lift resulted in 5cy of contaminated soil. Spill was cleaned up, closed and met NYSDEC cleanup standards.

Leaking Storage Tanks

Six (6) LTANKS records were identified for this site:

- Mobil – Niagara Falls Boulevard & Sheridan Drive: Spill #8602251 – tank failure (opened 7/7/1986, closed 9/5/1986). Contamination found while excavating for tank test. Monitoring wells were installed and tanks were tested. All tanks tested tight. Spill was cleaned up, closed and met NYSDEC cleanup standards.
- Mobil Oil – 2965 Sheridan Drive: Spill #0605174 – tank test failure (opened 8/3/2006, closed 11/30/2007). A tank failed its tightness test. Vent pipe was found broken. Tank was repaired and retested. Spill was cleaned up, closed and met NYSDEC cleanup standards.
- Mobil Oil – 2965 Sheridan Drive: Spill #9008391 – tank failure (opened 5/16/1991, closed 5/16/1991). Sheen discovered in manway pit. Spill was cleaned up, closed and met NYSDEC cleanup standards.
- Mobil Oil – 2965 Sheridan Drive: Spill #9012026 – tank failure (opened 2/17/1991, closed 6/11/1992). UST had a line leak. Spill was cleaned up, closed and met NYSDEC cleanup standards.
- Mobil Oil – 2965 Sheridan Drive: Spill #9705822 – tank failure (opened 8/13/1997, closed 2/15/2000). A line was found leaking and contaminating groundwater. Spill was cleaned up and closed but did not meet NYSDEC cleanup standards.
- Mobil Oil – Sheridan Drive & Niagara Falls Boulevard: Spill #8908574 – tank test failure (opened 11/29/1989, closed 10/15/1990). A broken vent line caused soil contamination. The tank was removed. Spill was cleaned up, closed and met NYSDEC cleanup standards.

RCRA Generator
One (1) RCRA GEN record was identified for this site. This database identified sites that generates, transports, treats, stores, or disposes of hazardous waste.

- Mobil Oil Corp SS H4 – 2965 Sheridan Drive

Hazardous Waste Manifest
One (1) HW Manifest record was identified for this site. This site has or had manifests for hazardous materials that they utilized or stored onsite.

- Mobil Oil Corp SS H4 – 2965 Sheridan Drive

Historic Auto
One (1) Historic Auto record was identified for this site. This database identifies sites that are considered potential gas stations, filling stations, and/or service stations.

- Knoll Service Station – 2965 Sheridan Drive: 1970-2011

Enforcement & Compliance History Online
One (1) ECHO record was identified for this site. This database identifies properties that have compliance and enforcement actions.

- Mobil Oil Corp SS H4 – 2965 Sheridan Drive

Property Risk Rating
This property has been given a Property Risk Rating of 1 due to a higher likelihood of contamination and that fee acquisition and construction are proposed for this site.

3.20 El Palenque Restaurant – 951 Niagara Falls Boulevard

Site Inspection
This site is currently a Mexican restaurant. The site includes the building and the associated parking lot. The property is one parcel with the following SBL number: 67.10-1-9. Refer to Photo #22.

Aerial Photos
This site is depicted as vacant land on the 1927 photo. A small building is depicted on the site on the 1938 and 1951 photo. The building is no longer present on the 1966 photo. The current building and parking lot are depicted on the site on the 1978, 1985, 1995, 2006, 2009, 2013, and 2017 photos.

Sanborn Maps
This site is depicted on the 1957 Sanborn Fire Insurance Map as a gas station.

NYSDEC Spill Report Database
One (1) Spill record was identified for this site:

- Commercial Site – 951 Niagara Falls Boulevard: Spill #0911057 – other (opened 1/13/2010, closed 9/9/2013). An Environmental Site Assessment identified soil contamination and minor groundwater contamination. The contaminated soil was removed but minor amounts remained around sewer line. Spill was cleaned up and closed but did not meet NYSDEC cleanup standards.

Property Risk Rating
This property has been given a Property Risk Rating of 1 due to a higher likelihood of contamination construction is proposed nearby this site.

3.21 Monro Auto Service and Tire Centers – 2980 Sheridan Drive

Site Inspection
This site is currently an auto repair shop. The site includes the building and the associated parking lot. The property is one parcel with the following SBL number: 67.31-1-4. Refer to Photo #23.

Aerial Photos
This site is depicted as agricultural land on the 1927 photo. On the 1938 and 1951 photos, a single small building is depicted on the site. The current building and parking lot are depicted on the site on the 1966, 1978, 1985, 1995, 2006, 2009, 2013, and 2017 photos.

Sanborn Maps
This site is depicted on the 1986 Sanborn Fire Insurance Map as a gas station.

RCRA Non Generator
One (1) NON GEN record was identified for this site. This site was identified as a site that no longer generates, transports, treats, stores or disposes of hazardous waste.

- Monro Muffler Brake Inc. – 2980 Sheridan Drive

NYSDEC Bulk Storage Database
One (1) UST/AST record was listed for this site:

- Monro Muffler Brake Inc. – 2980 Sheridan Drive: One tank (in service)

NYSDEC Spill Report Database
Two (2) Spill records were identified for this site:

- Monro Muffler – 2980 Sheridan Drive: Spill #9514918 – housekeeping (opened 2/1/1996, closed 2/26/1996). A sheen was reported in the parking lot. No spill was found. Spill was closed and met NYSDEC cleanup standards.
- Underground Autosound – 2980 Sheridan Drive: Spill #1305137 – deliberate (opened 7/15/2013, closed 8/12/2013). NYSDEC received report of Unknown amounts petroleum being dumped into the shop drain. No spill was found. Spill was closed and met NYSDEC cleanup standards.

Historic Auto
One (1) Historic Auto record was identified for this site. This database identifies sites that are considered potential gas stations, filling stations, and/or service stations.

- Monro Muffler Brake Inc. – 2980 Sheridan Drive: 1977-1988

Enforcement & Compliance History Online
One (1) ECHO record was identified for this site. This database identifies properties that have compliance and enforcement actions.

- Monro Muffler Brake Inc. – 2980 Sheridan Drive

Property Risk Rating
This property has been given a Property Risk Rating of 1 due to a higher likelihood of contamination and that fee acquisition and construction are proposed for this site.

3.22 Firestone Complete Auto Care – 995 Niagara Falls Boulevard

Site Inspection
This site is currently an auto repair shop. The site includes the building and the associated parking lots. The property is one parcel with the following SBL number: 67.06-1-25.1. Refer to Photo #24.

Sanborn Maps
This site is depicted on the 1957 Sanborn Fire Insurance Map as a gas station.

Aerial Photos
This site is depicted as agricultural land on the 1927 photo. On the 1938 and 1951 photos, a single small building is depicted on the site. The current building and parking lot are depicted on the site on the 1966, 1978, 1985, 1995, 2006, 2009, 2013, and 2017 photos.

City Directories
The following business was identified on this site in the city directories:

Address	Use	Years
995 Niagara Falls Boulevard	Auto Repair Shop	1983-2018

RCRA Non Generator
One (1) NON GEN record was identified for this site. This site was identified as a site that no longer generates, transports, treats, stores or disposes of hazardous waste.

- Bridgestone Firestone – 995 Niagara Falls Boulevard

Hazardous Waste Manifest
One (1) HW Manifest record was identified for this site. This site has or had manifests for hazardous materials that they utilized or stored onsite.

- Firestone Stores – 995 Niagara Falls Boulevard

NYSDEC Bulk Storage Database
One (1) UST/AST record was listed for this site:

- Firestone Stores – 995 Niagara Falls Boulevard: One tank (in service)

NYSDEC Spill Report Database
Two (2) Spill records were identified for this site:

- Firestone Store – 995 Niagara Falls Boulevard: Spill #0375288– unknown (opened 9/9/2003, closed 11/6/2003). Contamination was found at the site. Contaminated soil and three tanks were removed. Spill was cleaned up and closed but did not meet NYSDEC cleanup standards.
- Firestone Store – 995 Niagara Falls Boulevard: Spill #9707595– equipment failure (opened 9/1/1997, closed 8/26/1998). Contamination was found during lift removal. Contaminated soil was removed. Spill was cleaned up, closed and met NYSDEC cleanup standards.

Leaking Storage Tanks
Three (3) LTANKS records were identified for this site:

- Firestone Tire – 995 Niagara Falls Boulevard: Spill #8605722 – tank failure (opened 12/9/1986, closed 12/12/1986). Tank was removed. Spill was cleaned up, closed and met NYSDEC cleanup standards.
- Firestone 955 NFB – Niagara Falls Boulevard/Maple Road: Spill #9206340 – tank failure (opened 8/4/1992, closed 1/19/1993). Contaminated soil was found. Spill was cleaned up, closed and met NYSDEC cleanup standards.
- Firestone – Niagara Falls Boulevard/Maple Road: Spill #9206303 – tank failure (opened 8/5/1992, closed 2/3/1993). This is a duplicate of Spill #9206340 (above). Spill was closed and met NYSDEC cleanup standards.

Enforcement & Compliance History Online
One (1) ECHO record was identified for this site. This database identifies properties that have compliance and enforcement actions.

- Bridgestone Firestone – 995 Niagara Falls Boulevard

Historic Auto
One (1) Historic Auto record was identified for this site. This database identifies sites that are considered potential gas stations, filling stations, and/or service stations.

- Latona's Service – 989 Niagara Falls Boulevard: 1971-1974

Property Risk Rating
This property has been given a Property Risk Rating of 1 due to a higher likelihood of contamination and that fee acquisition and construction are proposed for this site.

3.23 Pep Boys Auto Parts & Service – 1025 Niagara Falls Boulevard

Site Inspection
This site is currently auto parts store with an auto repair shop. The site includes the building and the associated parking lots. The property is one parcel with the following SBL number: 67.06-1-28.1. Refer to Photo #25.

Aerial Photos
This site is depicted as agricultural land on the 1927, 1938, and 1951 photos. On the 1958, 1966, 1978, and 1985 a small building is depicted on the site. The current building and parking lot are depicted on the site on the 1995, 2006, 2009, 2013, and 2017 photos.

City Directories
The following businesses were identified on this site in the city directories:

Address	Use	Years
1021 Niagara Falls Boulevard	Auto Repair Shop	1999-2014
1025 Niagara Falls Boulevard	Auto Repair Shop	2018

RCRA Non Generator
One (1) NON GEN record was identified for this site. This site was identified as a site that no longer generates, transports, treats, stores or disposes of hazardous waste.

- Pep Boys #193 – 1025 Niagara Falls Boulevard

Hazardous Waste Manifest
One (1) HW Manifest record was identified for this site. This site has or had manifests for hazardous materials that they utilized or stored onsite.

- Pep Boys #193 – 1025 Niagara Falls Boulevard

NYSDEC Bulk Storage Database
One (1) UST/AST record was listed for this site:

- Pep Boys #193 – 1025 Niagara Falls Boulevard: One tank (closed-removed)

NYSDEC Spill Report Database
Two (2) Spill records were identified for this site:

- Car Fire – 1009-1025 Niagara Falls Boulevard: Spill #1006430 – other (opened 9/7/2010, closed 9/8/2010). Car fire caused tank to drop onto pavement. Spill was cleaned up, closed and met NYSDEC cleanup standards.
- Pep Boys #193 – 1025 Niagara Falls Boulevard: Spill #9912271 – unknown (opened 1/25/2000, closed 5/2/2000). Contamination found during tank removal. Spill was cleaned up, closed and met NYSDEC cleanup standards.

Enforcement & Compliance History Online
One (1) ECHO record was identified for this site. This database identifies properties that have compliance and enforcement actions.

- Pep Boys #193 – 1025 Niagara Falls Boulevard

Property Risk Rating
This property has been given a Property Risk Rating of 1 due to a higher likelihood of contamination and that fee acquisition and construction are proposed for this site.

3.24 AudioMotive Creations – 1167 Niagara Falls Boulevard

Site Inspection
This site is currently an auto repair shop. The site includes the building and the associated parking lots. The property is one parcel with the following SBL number: 67.39-2-1.1. Refer to Photo #30.

Aerial Photos
This site is depicted as agricultural land on the 1927, 1938, and 1951 photos. The site is vacant on the 1958 photo. A single building is depicted on the site on the 1966, 1978, 1985, 1995, 2006, 2009, 2013, and 2017 photos.

City Directories
The following businesses were identified on this site in the city directories:

Address	Use	Years
1167 Niagara Falls Boulevard	Auto Repair Shop	1983-2018
1171 Niagara Falls Boulevard	Auto Repair Shop	1983-2018

NYSDEC Spill Report Database
Two (2) Spill records were identified for this site:

- Midas Drains – 1171 Niagara Falls Boulevard: Spill #9875468 – other (opened 3/8/1999, closed 10/12/1999). Oil was found in a storm culvert in front of this property. Floor drains were found to discharge to storm sewer. Drains were closed permanently. Spill was cleaned up, closed and met NYSDEC cleanup standards.
- Carubba Collision, Inc. – 1167 Niagara Falls Boulevard: Spill #9713614 – deliberate (opened 3/1/1998, closed 3/9/1998). Oil was found in a storm culvert in front of this property. Floor drains were found to discharge to storm sewer. Drains were closed permanently. Spill was cleaned up, closed and met NYSDEC cleanup standards.

RCRA Generator
One (1) RCRA GEN record was identified for this site. This database identified sites that generates, transports, treats, stores, or disposes of hazardous waste.

- Carubba Collision, Inc. – 1167 Niagara Falls Boulevard

Hazardous Waste Manifest
One (1) HW Manifest record was identified for this site. This site has or had manifests for hazardous materials that they utilized or stored onsite.

- Carubba Collision, Inc. – 1167 Niagara Falls Boulevard

Property Risk Rating
This property has been given a Property Risk Rating of 1 due to a higher likelihood of contamination and that fee acquisition and construction are proposed for this site.

3.25 Boulevard Mall – 1261-1269 Niagara Falls Boulevard

Site Inspection
This site is currently operated a shopping mall. The site includes several large building and the associated parking lots. The property is four parcels with the following SBL numbers: 54.03-1-24.4, 54.03-1-24.21, 54.03-1-24.22, and 67.06-1-1.111. Refer to Photos #26-29.

Aerial Photos

This site is depicted on the 1927, 1938, and 1951 photos as agricultural land. On the 1958 photo, a single large building is depicted on the site. Several additions have been constructed by the 1966 photo. On the 1978 and 1985 photos, more buildings have been constructed to the building and several smaller buildings are located around the main building. On the 1995, 2006, 2009, 2013, and 2017 photos, the site is similar to the current configuration.

NYSDEC Spill Report Database

Three (3) Spill records were identified for this site:

- Niagara Mohawk Boulevard Mall – 1227 Niagara Falls Boulevard: Spill #9106426 – equipment failure (opened 9/14/1991, closed 9/16/1991). Spill was cleaned up, closed and met NYSDEC cleanup standards.
- Kaufmann's – 1225 Niagara Falls Boulevard: Spill #0175412 – equipment failure (opened 10/17/2001, closed 12/24/2001). Contamination found while removing hydraulic lift. Spill was cleaned up, closed and met NYSDEC cleanup standards.
- Automatic Rolls/Northeast – Niagara Falls Boulevard - Mall: Spill #9406936 – traffic accident (opened 8/2/1994, closed 6/6/1995). Spill was cleaned up, closed and met NYSDEC cleanup standards.

NYSDEC Bulk Storage Database

One (1) UST/AST record was listed for this site:

- Kaufmann's Department Store – 1255 Niagara Falls Boulevard: 1 tank (closed-removed)

RCRA Generator

Four (4) RCRA GEN records were identified for this site. This database identified sites that generates, transports, treats, stores, or disposes of hazardous waste.

- Macy's – Boulevard #146 – 1255 Niagara Falls Boulevard
- Macy's – Boulevard Home #146B – 1255 Niagara Falls Boulevard
- Sears #1162 – 1261 Niagara Falls Boulevard
- Buy Buy Baby #3083 – 1261 Niagara Falls Boulevard

Enforcement & Compliance History Online

Four (4) ECHO records were identified for this site. This database identifies properties that have compliance and enforcement actions.

- Macy's – Boulevard #146 – 1255 Niagara Falls Boulevard
- Macy's – Boulevard Home #146B – 1255 Niagara Falls Boulevard
- Sears #1162 – 1261 Niagara Falls Boulevard

- Buy Buy Baby #3083 – 1261 Niagara Falls Boulevard

Property Risk Rating
This property has been given a Property Risk Rating of 3 since there is a lower likelihood of project impact due to the location of the tanks and historic contamination in relation to the currently proposed construction areas.

3.26 Plaza – 1200 Niagara Falls Boulevard

Site Inspection
This site is currently a shopping plaza with numerous businesses. The site includes two large buildings and the associated parking lots. The property is one parcel with the following SBL number: 54.79-3-2.1. Refer to Photo #31.

Aerial Photos
This site is depicted as agricultural land on the 1927, 1938, and 1951 photos. A single large building and associated parking lot is depicted on the 1958 and 1966 photos. A second building is depicted on the site on the 1978, 1985, 1995, 2006, 2009, 2013, and 2017 photos.

Sanborn Maps
This site is depicted on the 1986 Sanborn Fire Insurance Map as a plaza with two buildings containing storefronts.

NYSDEC Spill Report Database
One (1) Spill record was identified for this site:

- Wilson Farms – 1244 Niagara Falls Boulevard: Spill #9213436 – equipment failure (opened 3/1/1993, closed 3/12/1993). Spill was cleaned up, closed and met NYSDEC cleanup standards.

Historic Cleaner
One (1) Historic Cleaner record was identified for this site. This database identifies sites that are considered potential dry cleaners, cleaners, laundries and/or laundromats.

- Arthur Furst – 1226 Niagara Falls Boulevard: 1969-1973

Property Risk Rating
This property has been given a Property Risk Rating of 1 due to a higher likelihood of contamination and that fee acquisition and construction are proposed for this site.

3.27 Goodyear Auto Service – 1280 Niagara Falls Boulevard

Site Inspection
This site is currently an auto repair shop. The site includes the building and the associated parking lots. The property is one parcel with the following SBL number: 54.71-2-13.1. Refer to Photo #32.

Aerial Photos
This site is depicted as agricultural land on the 1927, 1938, 1951, and 1958 photos. On the 1966, 1978, 1985, 1995, 2006, 2009, 2013, and 2017 photos the current building is depicted on the site.

Sanborn Maps
This site is depicted on the 1986 Sanborn Fire Insurance Map as an auto repair shop.

City Directories
The following business was identified on this site in the city directories:

Address	Use	Years
1280 Niagara Falls Boulevard	Auto Repair Shop	1987-1993

NYSDEC Bulk Storage Database
One (1) UST/AST record was listed for this site:

- Goodyear Auto Service Center – 1280 Niagara Falls Boulevard: Two tanks (both in service).

Hazardous Waste Manifest
One (1) HW Manifest record was identified for this site. This site has or had manifests for hazardous materials that they utilized or stored onsite.

- Goodyear Auto Service Center – 1280 Niagara Falls Boulevard

NYSDEC Spill Report Database
Three (3) Spill records were identified for this site:

- Goodyear Auto Service Center – 1280 Niagara Falls Boulevard: Spill #9302662 – equipment failure (opened 5/1/1993, closed 8/18/1993). A lift leaked hydraulic fluid onto the ground. Spill was cleaned up, closed and met NYSDEC cleanup standards.
- Goodyear Auto Service Center – 1280 Niagara Falls Boulevard: Spill #9113171 – equipment failure (opened 3/27/1992, closed 2/8/1993). A lift failed causing 50 gallons of hydraulic oil to leak under the concrete. Spill was cleaned up, closed and met NYSDEC cleanup standards.

- Goodyear Auto Service Center – 1280 Niagara Falls Boulevard: Spill #9416566 – equipment failure (opened 3/21/1995, closed 7/8/1995). Contamination was found during the removal of a hydraulic lift. Spill was cleaned up, closed and met NYSDEC cleanup standards.

RCRA Generator
One (1) RCRA GEN record was identified for this site. This database identified sites that generates, transports, treats, stores, or disposes of hazardous waste.

- Goodyear Auto Service Center – 1280 Niagara Falls Boulevard

Enforcement & Compliance History Online
One (1) ECHO record was identified for this site. This database identifies properties that have compliance and enforcement actions.

- Goodyear Auto Service Center – 1280 Niagara Falls Boulevard

Property Risk Rating
This property has been given a Property Risk Rating of 1 due to a higher likelihood of contamination and that fee acquisition and construction are proposed for this site.

3.28 Valu Muffler & Brake Auto Center – 1346 Niagara Falls Boulevard

Site Inspection
This site is currently an auto repair shop. The site includes the building and the associated parking lot. The property is one parcel with the following SBL number: 54.71-2-10. Refer to Photo #33.

Aerial Photos
This site is depicted as agricultural land on the 1927 and 1938 photos. A single small building is depicted on the site on the 1951, 1958, 1966 1978, 1985, 1995, 2006, 2009, 2013, and 2017 photos.

Sanborn Maps
This site is depicted on the 1986 Sanborn Fire Insurance Map as a gas station.

City Directories
The following business was identified on this site in the city directories:

Address	Use	Years
1346 Niagara Falls Boulevard	Auto Repair Shop	1983-1995

Historic Auto
One (1) Historic Auto record was identified for this site. This database identifies sites that are considered potential gas stations, filling stations, and/or service stations.

- Zinnis Friendly Service – 1346 Niagara Falls Boulevard: 1969-2005

Property Risk Rating
This property has been given a Property Risk Rating of 1 due to a higher likelihood of contamination and that fee acquisition and construction are proposed for this site.

3.29 Delta Sonic Car Wash – 1355 Niagara Falls Boulevard

Site Inspection
This site is currently a car wash, gas station, and auto repair shop. The site includes several buildings, associated parking lots, and two fueling areas. The property is one parcel with the following SBL number: 54.14-2-5.11. Refer to Photos #34-35.

Aerial Photos
This site is depicted as agricultural land on the 1927, 1938, 1951, and 1958 photos. The site is depicted as a gas station on the 1966, 1978, 1985, 1995, 2006, 2009, 2013, and 2017 photos.

City Directories
The following business was identified on this site in the city directories:

Address	Use	Years
1355 Niagara Falls Boulevard	Gas Station, Car Wash	1983-2018

RCRA Non Generator
One (1) NON GEN record was identified for this site. This site was identified as a site that no longer generates, transports, treats, stores or disposes of hazardous waste.

- Delta Sonic Car Wash – 1355 Niagara Falls Boulevard

Hazardous Waste Manifest
One (1) HW Manifest record was identified for this site. This site has or had manifests for hazardous materials that they utilized or stored onsite.

- Delta Sonic Car Wash – 1355 Niagara Falls Boulevard

NYSDEC Bulk Storage Database
One (1) UST/AST record was listed for this site:

- Delta Sonic Car Wash – 1355 Niagara Falls Boulevard: 46 tanks (22 in service, 24 closed-removed)

NYSDEC Spill Report Database
Nine (9) Spill records were identified for this site:

- Underneath Dispenser 3/4 – 1355 Niagara Falls Boulevard: Spill #1306629 – equipment failure (opened 9/24/2013, closed 1/8/2014). Gas leaked out of a faulty dispenser causing soil contamination. Entire site was upgraded and all tanks and lines were replaced. Spill was cleaned up, closed and met NYSDEC cleanup standards.
- Spill Number 8504373 – 1355 Niagara Falls Boulevard: Spill #8504373 – unknown (opened 3/8/1986, closed 3/8/1986). Spill was cleaned up, closed and met NYSDEC cleanup standards.
- Delta Sonic - Boulevard – 1355 Niagara Falls Boulevard: Spill #0514837 – housekeeping (opened 3/27/2006, closed 6/22/2006). Oil was found in retention pond. Spill was cleaned up, closed and met NYSDEC cleanup standards.
- Delta Sonic - Boulevard – 1355 Niagara Falls Boulevard: Spill #0102552 – human error failure (opened 6/6/2001, closed 7/16/2001). Customer overfilled gas tank. Spill was cleaned up, closed and met NYSDEC cleanup standards.
- Delta Sonic - Boulevard – 1355 Niagara Falls Boulevard: Spill #9406720 – human error (opened 8/17/1994, closed 8/17/1994). A valve was left open during a fuel delivery. Spill was cleaned up, closed and met NYSDEC cleanup standards.
- Delta Sonic - Boulevard – 1355 Niagara Falls Boulevard: Spill #9807773 – other (opened 9/25/1998, closed 11/5/1998). Soil contamination found during line replacement. Spill was cleaned up, closed and met NYSDEC cleanup standards.
- Delta Sonic - Boulevard – 1355 Niagara Falls Boulevard: Spill #0900340 – equipment failure (opened 4/9/2009, closed 4/10/2009). Gas leaked onto the ground due to a faulty shut-off valve. Spill was cleaned up, closed and met NYSDEC cleanup standards.
- Delta Sonic - Boulevard – 1355 Niagara Falls Boulevard: Spill #0910621 – human error (opened 12/29/2009, closed 2/23/2010). Oil spilled into basement due to valve being left open. Spill was cleaned up, closed and met NYSDEC cleanup standards.
- Delta Sonic – 1355 Niagara Falls Boulevard: Spill #1508488 – equipment failure (opened 11/16/2015, closed 11/17/2015). Hydraulic line broke spilling oil onto the ground. Spill was cleaned up, closed and met NYSDEC cleanup standards.

Leaking Storage Tanks
Two (2) LTANKS records were identified for this site:

- Delta Sonic – 1355 Niagara Falls Boulevard: Spill #8703113 – tank test failure (opened 7/16/1987, closed 8/5/1987). Tank failed its tightness test. Tank was retested and passed. Spill was closed and met NYSDEC cleanup standards.

- Delta Sonic – 1355 Niagara Falls Boulevard: Spill #9204430 – tank failure (opened 11/12/1992, closed 12/10/1992). Groundwater contamination was found during tank removal. Spill was cleaned up, closed and met NYSDEC cleanup standards.

Historic Auto
One (1) Historic Auto record was identified for this site. This database identifies sites that are considered potential gas stations, filling stations, and/or service stations.

- Delta Sonic Car Wash – 1355 Niagara Falls Boulevard: 1993-2014

Enforcement & Compliance History Online
One (1) ECHO record was identified for this site. This database identifies properties that have compliance and enforcement actions.

- Delta Sonic Car Wash – 1355 Niagara Falls Boulevard

Aerometric Information Retrieval System
One (1) AIRS record was identified for this site. This database identifies sites that are or were point source emissions sources.

- Delta Sonic Car Wash – 1355 Niagara Falls Boulevard

Property Risk Rating
This property has been given a Property Risk Rating of 1 due to a higher likelihood of contamination and that fee acquisition and construction are proposed for this site.

3.30 Firestone Complete Auto Care – 3893 Maple Road

Site Inspection
This site is currently an auto repair shop. The site includes the building and the associated parking lot. The property is one parcel with the following SBL number: 54.03-1-13. Refer to Photo #36.

Aerial Photos
This site is depicted on the 1927, 1938, 1951, and 1958 photos as agricultural land. On the 1966 photo, the site is part of a parking lot. The current building is depicted on the 1978, 1985, 1995, 2006, 2009, 2013, and 2017 photos.

City Directories
The following businesses were identified on this site in the city directories:

Address	Use	Years
1303 Niagara Falls Boulevard	Auto Repair Shop	1983
3931 Maple Road	Auto Repair Shop	1988-2019

RCRA Non Generator
One (1) NON GEN record was identified for this site. This site was identified as a site that no longer generates, transports, treats, stores or disposes of hazardous waste.

- Bridgestone Firestone – 3893 Maple Road

NYSDEC Bulk Storage Database
One (1) UST/AST record was listed for this site:

- Firestone Complete Auto Care – 3931 Maple Road: One tank (in service)

Leaking Storage Tanks
One (1) LTANKS record was identified for this site:

- Firestone – 3931 Maple Road: Spill #9212411 – tank failure (opened 8/5/1992, closed 2/3/1993). A 550-gallon waste oil tank was removed. Spill was cleaned up, closed and met NYSDEC cleanup standards.

Enforcement & Compliance History Online
One (1) ECHO record was identified for this site. This database identifies properties that have compliance and enforcement actions.

- Bridgestone Firestone - 3893 Maple Road

Property Risk Rating
This property has been given a Property Risk Rating of 1 due to a higher likelihood of contamination and that fee acquisition and construction are proposed for this site.

3.31 Premiere Group – 3900 Maple Road

Site Inspection
This site is currently a retail store. The site includes the large building, associated parking lots, and mowed lawn. The property is one parcel with the following SBL number: 54.14-2-7.111. Refer to Photo #37.

Aerial Photos
This site is depicted on the 1927, 1938, 1951, 1958, and 1966 photos as agricultural land. On the 1978, 1985, 1995, 2006, and 2009 photos, a single building and large parking lot is depicted on the site. The current building and parking lot are depicted on the site on the 2013 and 2017 photos.

City Directories
The following businesses were identified on this site in the city directories:

Address	Use	Years
3900 Maple Road	Auto Repair Shop	1973-1998
3900 Maple Road	Store	2014-2019

RCRA Non Generator
One (1) NON GEN record was identified for this site. This site was identified as a site that no longer generates, transports, treats, stores or disposes of hazardous waste.

- Ed Taylor Lincold Mercury – 3900 Maple Road

Hazardous Waste Manifest
One (1) HW Manifest record was identified for this site. This site has or had manifests for hazardous materials that they utilized or stored onsite.

- Ed Taylor Lincold Mercury – 3900 Maple Road

NYSDEC Bulk Storage Database
One (1) UST/AST record was listed for this site:

- Ed Taylor Lincold Mercury – 3900 Maple Road: 6 tanks (closed-removed)

NYSDEC Spill Report Database
Three (3) Spill records were identified for this site:

- Former Ed Taylor Lincoln Mercury – 3900 Maple Road: Spill #1001596 – equipment failure (opened 5/11/2010, closed 6/23/2011). Contamination was found during installation of hydraulic lifts. Contaminated soil and two tanks were removed. Spill was cleaned up and closed but did not meet NYSDEC cleanup standards.
- Former Ed Taylor Lincoln Mercury – 3900 Maple Road: Spill #9975473 – housekeeping failure (opened 10/13/1999, closed 12/9/1999). Paving company was reportedly allowing petroleum to enter storm sewers. No cleanup was necessary. Spill was closed and met NYSDEC cleanup standards.
- Goldome – 3480 Maple Road: Spill #8702308 – unknown cause (opened 6/17/1987, closed 6/25/1986). Contamination was reported at the site. The site was inspected and none was found. Spill was closed and met NYSDEC cleanup standards.

Leaking Storage Tanks
One (1) LTANKS record was identified for this site:

- Former Ed Taylor Lincoln Mercury – 3900 Maple Road: Spill #9201849 – tank failure (opened 5/14/1992, closed 4/25/1994). Contamination was found during tank removal. Spill was cleaned up, closed and met NYSDEC cleanup standards.

Enforcement & Compliance History Online
One (1) ECHO record was identified for this site. This database identifies properties that have compliance and enforcement actions.

- Ed Taylor Lincold Mercury – 3900 Maple Road

Aerometric Information Retrieval System
One (1) AIRS record was identified for this site. This database identifies sites that are or were point source emissions sources.

- Premier Gourmet – 3900 Maple Road

Property Risk Rating
This property has been given a Property Risk Rating of 3 since the tanks and historic contamination are not adjacent to the proposed construction.

3.32 Sweet Home Middle School – 4150 Maple Road

Site Inspection
This site is currently a public school. The site includes the large building, associated parking lots, and athletic fields. The property is one parcel with the following SBL number: 54.04-1-5. Refer to Photo #38.

Aerial Photos
This site is depicted on the 1927, 1938, 1951, and 1958 photos as agricultural land. On the 1966, 1978, 1985, 1995, 2006, 2009, 2013, and 2017 photos a large building and athletic fields are depicted on the site.

City Directories
The following business was identified on this site in the city directories:

Address	Use	Years
4150 Maple Road	School	1963-2019

NYSDEC Bulk Storage Database
One (1) UST/AST record was listed for this site:

- Sweet Home Junior High School – 4150 Maple Road: 1 tank (closed-removed)

NYSDEC Spill Report Database
Two (2) Spill records were identified for this site:

- Sweet Home Junior High School – 4150 Maple Road: Spill #0608981 – other (opened 11/6/2006, closed 3/9/2007). A bushing broke on a pad mount transformer spilling oil. The contaminated soil was removed. Spill was cleaned up, closed and met NYSDEC cleanup standards.
- Sweet Home Junior High School – 4150 Maple Road: Spill #9509066 – human error (opened 10/23/1995, closed 10/23/1995). Muriatic acid and hypochloride were mixed in a container producing fumes but no spillage. Spill was closed and met NYSDEC cleanup standards.

Property Risk Rating
This property has been given a Property Risk Rating of 1 due to the large fee acquisition and construction that are proposed for this site.

3.33 NOCO Express – 4265 Maple Road

Site Inspection
This site is currently a gas station. The site includes the building, associated parking lot, and fueling area. The property is one parcel with the following SBL number: 54.74-3-13. Refer to Photo #39.

Aerial Photos
This site is depicted as agricultural land on the 1927, 1938, 1951, 1958, and 1966 photos. The site is depicted as a gas station on the 1978, 1985, 1995, 2006, 2009, 2013, and 2017 photos.

City Directories
The following business was identified on this site in the city directories:

Address	Use	Years
4265 Maple Road	Gas Station	2005-2014

NYSDEC Bulk Storage Database
One (1) UST/AST record was listed for this site:

- NOCO Express – 4265 Maple Road: Five tanks (2 in service, 3 closed-removed)

NYSDEC Spill Report Database
One (1) Spill record was identified for this site:

- Noco – 4265 Maple Road: Spill #0751262 – equipment failure (opened 12/26/2007, closed 8/3/2012). Contamination found while upgrading the pump island. The contaminated soil was removed. Spill was cleaned up and closed but did not meet NYSDEC cleanup standards.

Leaking Storage Tanks
One (1) LTANKS record was identified for this site:

- Noco Energy Station – Maple Road and Sweet Home Road: Spill #9709710 – tank removal (opened 11/19/1997, closed 3/11/1998). Contaminated soil was found and removed during tank removal. Spill was cleaned up and closed but did not meet NYSDEC cleanup standards.

Historic Auto
One (1) Historic Auto record was identified for this site. This database identifies sites that are considered potential gas stations, filling stations, and/or service stations.

- Dukarm's Service – 4265 Maple Road:1982-1989

Property Risk Rating
This property has been given a Property Risk Rating of 1 due to a higher likelihood of contamination and that fee acquisition and construction are proposed for this site.

3.34 Mobil – 4291 Maple Road

Site Inspection
This site is currently a gas station. The site includes the building, associated parking lot, and fueling area. The property is one parcel with the following SBL number: 54.04-2-17. Refer to Photo #40.

Aerial Photos
This site is depicted as agricultural land on the 1927, 1938, 1951, and 1958 photos. On the 1966, a small building is depicted on the site. The site is depicted as a gas station on the 1978, 1985, 1995, 2006, 2009, 2013, and 2017 photos.

City Directories
The following business was identified on this site in the city directories:

Address	Use	Years
4291 Maple Road	Gas Station	1973-2019

NYSDEC Bulk Storage Database
One (1) UST/AST record was listed for this site:

- EZ Mart – 4291 Maple Road: 9 tanks (3 in service, 6 closed-removed)

NYSDEC Spill Report Database
Four (4) Spill records were identified for this site:

- EZ Mart – 4291 Maple Road: Spill #9600093 – equipment failure (opened 4/2/1996, closed 4/3/1996). Spill was cleaned up, closed and met NYSDEC cleanup standards.
- EZ Mart – 4291 Maple Road: Spill #9811632 – housekeeping (opened 12/16/1998, closed 6/13/2007). Gas tank was taking on water. Soil contamination was found when the tank was uncovered. Spill was cleaned up and closed but did not meet NYSDEC cleanup standards.
- EZ Mart – 4291 Maple Road: Spill #8603239 – human error (opened 8/9/1986, closed 12/24/1986). An underground tank was punctured when new lines were installed. Spill was cleaned up, closed and met NYSDEC cleanup standards.
- Maple Sunoco – 4291 Maple Road: Spill #1303372 – unknown cause (opened 6/28/2013, closed 10/22/2014). A Phase II investigation showed soil and groundwater contamination. Three tanks were removed along with the contaminated soil. Spill was cleaned up and closed but did not meet NYSDEC cleanup standards.

Leaking Storage Tanks
Two (2) LTANKS records were identified for this site:

- North Camp RV & Marine – Maple Road & Sweet Home Road: Spill #8606881 - tank failure (opened 2/9/1987, closed 4/16/1987). Two tanks were removed and no contamination was found. Spill was cleaned up, closed and met NYSDEC cleanup standards.
- EZ Mart – 4291 Maple Road: Spill #1110941 – tank test failure (opened 12/8/2011, closed 6/28/2013). A tank was found to be taking on water. The tank was taken out of service. The leaking tank was removed under a new Spill #1303372 (see above). This spill record was closed but did not meet NYSDEC cleanup standards.

Historic Auto
One (1) Historic Auto record was identified for this site. This database identifies sites that are considered potential gas stations, filling stations, and/or service stations.

- Erin's Automotive & Transport – 4291 Maple Road: 1970-2014

Integrated Compliance Information System
One (1) ICIS record was identified for this site. This record identifies properties that have Federal Administrative and Judicial enforcement actions.

- Herrscher's Express – 4291 Maple Road

Enforcement & Compliance History Online
One (1) ECHO record was identified for this site. This database identifies properties that have compliance and enforcement actions.

- Herrscher's Express – 4291 Maple Road

Property Risk Rating
This property has been given a Property Risk Rating of 1 due to a higher likelihood of contamination and that fee acquisition and construction are proposed for this site.

3.35 Anchor Bar – 4300 Maple Road

Site Inspection
This site is currently a restaurant. The site includes the building, associated parking lot, and mowed lawn. The property is one parcel with the following SBL number: 54.04-2-18.14. Refer to Photo #41.

Aerial Photos
This site is depicted as agricultural land on the 1927, 1938, 1951, and 1958 photos. On the 1966 and 1978 photos, a small building is depicted on the site. On the 1985, 1995, 2006, 2009, 2013, and 2017 photos, the current building is depicted on the site.

Historic Auto
One (1) Historic Auto record was identified for this site. This database identifies sites that are considered potential gas stations, filling stations, and/or service stations.

- University Mobile Station – 4264 Maple Road: 1972

Property Risk Rating
This property has been given a Property Risk Rating of 1 due to a higher likelihood of contamination and that fee acquisition and construction are proposed for this site.

3.36 Ball Pump Station – 1201 Sweet Home Road

Site Inspection
This site is currently operated by the Erie County Water Authority as a water supply facility. The site includes two buildings, two large aboveground tanks, associated

parking areas, and open land. The property is one parcel with the following SBL number: 54.04-2-6.1. Refer to Photos #42-43.

Aerial Photos

This site is depicted as agricultural land on the 1927, 1938, 1951, 1958, and 1966 photos. On the 1978, 1985, 1995, 2006, 2009, 2013, and 2017 photos, there are two large aboveground tanks and a large building on the site.

NYSDEC Spill Report Database

Two (2) Spill records were identified for this site:

- Ball Pump Station and Tanks – Sweet Home Road: Spill #1603248 – unknown (opened 6/25/2016, closed 7/6/2016). Hydraulic fluid leaked from excavator. Spill was cleaned up and closed but did not meet NYSDEC cleanup standards.
- Ball Pump Station – Sweet Home Road: Spill #0375269 – equipment failure (opened 8/26/2003, closed 11/3/2003). Hydraulic line broke on boom truck. Spill was cleaned up and closed but did not meet NYSDEC cleanup standards.

Leaking Storage Tanks

One (1) LTANKS record was identified for this site:

- Ball Pump Station – Sweet Home Road: Spill #9209938 – tank failure (opened 11/20/1992, closed 2/3/1993). Soil contamination was found. Contaminated soil was removed and tank was filled with sand. Spill was cleaned up, closed and met NYSDEC cleanup standards.

RCRA Generator

One (1) RCRA GEN record was identified for this site. This database identified sites that generates, transports, treats, stores, or disposes of hazardous waste.

- Ball Pump Station and Tanks – Sweet Home Road

Hazardous Waste Manifest

One (1) HW Manifest record was identified for this site. This site has or had manifests for hazardous materials that they utilized or stored onsite.

- Ball Pump Station and Tanks – Sweet Home Road

Property Risk Rating

This property has been given a Property Risk Rating of 3 since there is a lower likelihood of project impact due to the location of the tanks and historic contamination in relation to the currently proposed construction areas.

3.37 University of Buffalo – Millersport Highway

Site Inspection

This site is currently the State University of New York at Buffalo North campus. The site includes many large buildings, associated parking lots, athletic facilities, maintained lawns and natural habitat including several large ponds. The property is one parcel with the following SBL number: 55.01-1-1. Refer to Photo #44.

Aerial Photos

This site is depicted as agricultural land and rural residential land on the 1927, 1938, 1951, 1958, and 1966 photos. On the 1978, 1985, 1995, 2006, 2009, 2013, and 2017 photos, the site is depicted as a university campus.

NYSDEC Bulk Storage Database

Two (2) UST/AST records were listed for this site:

- SUNY at Buffalo – North Campus- Alumni Arena Pool – The John Beane Center – Physical Plant: 1 tank (closed)
- SUNY at Buffalo – North Campus – Service Building: 113 tanks (55 in service, 53 closed-removed, 4 closed prior to 3/1991, and 1 converted to non-regulated use.)

NYSDEC Spill Report Database

Twelve (12) Spill records were identified for this site:

- SUNY at Buffalo – Millersport Highway: Spill #9000336 – abandoned drums (opened 4/10/1990, closed 4/12/1990). Four drums found when a containment pond was pumped out. Spill was cleaned up, closed and met NYSDEC cleanup standards.
- Gas from car at UB – SUNY at Buffalo: Spill #8806382 – equipment failure (opened 10/31/1988, closed 10/31/1988). Car was found leaking gas in parking lot. Spill was cleaned up, closed and met NYSDEC cleanup standards.
- University of Buffalo – Jarvis Hall: Spill #8708045 – human error (opened 12/16/1987, closed 4/5/1988). Oil stain was found in parking lot. Spill was cleaned up, closed and met NYSDEC cleanup standards.
- SUNYAB - Cooke Hall – Putnam Way: Spill #0175123 – equipment failure (opened 5/31/2001, closed 8/7/2001). A failed valve caused a tank to leak within the basement. Spill was cleaned up, closed and met NYSDEC cleanup standards.
- SUNYAB Amherst Tank – Maple and John Beane Center: Spill #0075497 – equipment failure (opened 11/15/2000, closed 2/23/2001). Contamination was found during tank removal. Contaminated soil and tank were removed. Spill was cleaned up, closed and met NYSDEC cleanup standards.
- Truck at SUNY Amherst – Frontier Road: Spill #9975668 – human error (opened 2/3/2000, closed 5/11/2000). Tractor trailer ripped off saddle tank at construction site. Spill was cleaned up, closed and met NYSDEC cleanup standards.

- SUNY Buffalo North Campus – Service Center Road: Spill #0101732 – unknown (opened 5/15/2001, closed 11/8/2001). Contamination was found during tank removal. Contaminated soil and tank were removed. Spill was cleaned up, closed and met NYSDEC cleanup standards.
- SUNYAB-Amherst – Millersport Building 40: Spill #9007861 – deliberate (opened 10/8/1990, closed 10/25/1990). Complaint of waste oil dumping at a construction site. No spill was found. Spill was closed and met NYSDEC cleanup standards.
- UB Campus – Skinnersville Road: Spill #9207489 – unknown (opened 9/28/1992, closed 10/20/1992). Sheen was reported coming from campus. No spill was found. Spill was closed and met NYSDEC cleanup standards.
- Blue Bird Bus Line – SUNY Amherst Campus: Spill #8805153 – equipment failure (opened 9/14/1988, closed 9/21/1988). Bus fuel tank leaking out fuel when making turns. Spill was cleaned up, closed and met NYSDEC cleanup standards.
- SUNY at Buffalo – Frontier Street: Spill #0206015 – deliberate (opened 9/11/2002, closed 9/11/2002). Janitors were reportedly dumping used cleaning supplies into sanitary sewer. No spill was found. Spill was closed and met NYSDEC cleanup standards.
- NYS SUNY Campus – Jarvis Hall: Spill #0104381 – unknown (opened 7/24/2001, closed 2/19/2002). Contamination was found during tank removal. Contaminated soil and tank were removed. Spill was cleaned up, closed and met NYSDEC cleanup standards.

<u>Leaking Storage Tanks</u>
Five (5) LTANKS records were identified for this site:

- University of Buffalo – North Campus – Baird Hall: Spill #0104703 – tank failure (opened 8/1/2001, closed 1/30/2003). Contamination was found during tank removal. Contaminated soil and tank were removed. Spill was cleaned up and closed but did not meet NYSDEC cleanup standards.
- Alumni Arena - SUNYAB – Webster Road: Spill #9805985 – tank failure (opened 8/1/1998, closed 11/27/1998). Tank was found to be taking on water. Contamination was found. Contaminated soil and tank were removed. Spill was cleaned up, closed and met NYSDEC cleanup standards.
- Jacob's Management Center – SUNY Buffalo: Spill #0102567 – tank failure (opened 6/7/2001, closed 1/29/2003). Soil contamination was found during tank removal. Contaminated soil and tank were removed. Spill was cleaned up and closed but did not meet NYSDEC cleanup standards.
- SUNY at Buffalo – Millersport Highway 265: Spill #9706838 – tank test failure (opened 9/5/1997, closed 7/24/2001). Tank failed tightness tank and was removed. Spill was cleaned up, closed and met NYSDEC cleanup standards.
- State University Buffalo North – Lockwood Library: Spill #0011535 – tank failure (opened 11/20/1992, closed 2/3/1993). Contamination was found during tank removal. Contaminated soil was removed. Spill was cleaned up, closed and met NYSDEC cleanup standards.

RCRA Generator
One (1) RCRA GEN record was identified for this site. This database identified sites that generates, transports, treats, stores, or disposes of hazardous waste

- CVS Pharmacy #1227 – 520 Lee Entrance

Enforcement & Compliance History Online
One (1) ECHO record was identified for this site. This database identifies properties that have compliance and enforcement actions.

- CVS Pharmacy #1227 – 520 Lee Entrance

Hazardous Waste Manifest
One (1) HW Manifest record was identified for this site. This site has or had manifests for hazardous materials that they utilized or stored onsite.

- CVS Pharmacy #1227 – 520 Lee Entrance

Property Risk Rating
This property has been given a Property Risk Rating of 3 since there is a lower likelihood of project impact due to the location of the tanks and historic contamination in relation to the currently proposed construction areas.

3.38 Office Building – 140 John James Audubon Parkway

Site Inspection
This site is currently an office building. The site includes the large building, associated parking lots, maintained lawns, and wooded land. The property is one parcel with the following SBL number: 41.03-1-74.1. Refer to Photo #45.

Aerial Photos
This site is depicted as agricultural land on the1927, 1938, 1957, 1958, and 1966 photos. On the 1978 photo, the site is wooded land. A single large building is depicted on this site on the 1985, 1995, 2006, 2009, 2013, and 2017 photos.

City Directories
The following business was identified on this site in the city directories:

Address	Use	Years
140 John James Audubon Parkway	Office Building	1983-2019

NYSDEC Bulk Storage Database
One (1) UST/AST record was listed for this site:

- CM Headquarters Building – 140 John James Audubon Parkway: 1 tank (closed-removed).

Leaking Storage Tanks
One (1) LTANKS record was identified for this site:

- Columbus McKinnon Inc. – 140 John James Audubon Parkway: Spill #9210347 – tank failure (opened 12/4/1992, closed 2/22/1993). A tank failed its tightness test and was removed. Spill was cleaned up, closed and met NYSDEC cleanup standards.

Property Risk Rating
This property has been given a Property Risk Rating of 3 since there is a lower likelihood of project impact due to the location of the tanks and historic contamination in relation to the currently proposed construction areas.

3.39 Town of Amherst – 350 John James Audubon Parkway

Site Inspection
This site is currently Town of Amherst offices including Amherst Police Department, Town Court, and Senior Transportation Service. In addition, the site contains the Buffalo & Erie County Public Library Audubon Branch. The site includes several buildings, associated parking lots, and maintained lawn. The property is one parcel with the following SBL number: 41.03-1-66. Refer to Photos #46-47.

Aerial Photos
This site is depicted as agricultural land on the 1927, 1938, 1951, 1958, and 1966 photos. On the 1978 photo, a single building is depicted on the site. A second building is depicted on the site on the 1985 photo and a third building is depicted on the 1995 photo. All the current buildings are depicted on the site on the 2006, 2009, 2013, and 2017 photos.

City Directories
The following businesses were identified on this site in the city directories:

Address	Use	Years
350 John James Audubon Parkway	Library	1992-2019
370-500 John James Audubon Parkway	Town Government Offices	1983-2019

NYSDEC Bulk Storage Database
One (1) UST/AST record was listed for this site:

- Town of Amherst Police Department – 500 John James Audubon Parkway: 8 tanks (6 in service, 2 closed-removed).

Leaking Storage Tanks
One (1) LTANKS record was identified for this site:

- Amherst Police Department – 500 John James Audubon Parkway: Spill #9408494 - tank test failure (opened 9/26/1994, closed 6/15/1995). The tank and contaminated soil were removed. Spill was cleaned up, closed and met NYSDEC cleanup standards.

Enforcement & Compliance History Online
One (1) ECHO record was identified for this site. This database identifies properties that have compliance and enforcement actions.

- Town of Amherst Police Department – 500 John James Audubon Parkway

Integrated Compliance Information System
One (1) ICIS record was identified for this site. This record identifies properties that have Federal Administrative and Judicial enforcement actions.

- Town of Amherst Police Department – 500 John James Audubon Parkway

Property Risk Rating
This property has been given a Property Risk Rating of 3 since there is a lower likelihood of project impact due to the location of the tanks and historic contamination in relation to the currently proposed construction areas.

The following properties were identified within the search radius and were reviewed. No identified environmental concerns were identified for these sites that would impact the proposed Project:

- NYSDOT BIN 1-07260-1 I-290 SB Brg Over Sweethome
- NYSDOT Bin 1001590 - Main St over NY Rt 1
- Wegmans #0082 - 675 Alberta Dr
- Station 124 - 48 Alameda Dr
- Orken Lawncare - 514 Capen Blvd
- Northtown Plaza - 2125 Eggert Rd
- Marty's Autopro Center - 2131 Eggert Rd
- Savers Store #1217 - 2309 Eggert Rd
- Hancock Fabrics - Eggert & Sheridan Dr
- New Opportunities Co - 245 Hawthorne Ave
- Goodyear Tire - 200 JJ Audubon Pkwy
- Honeywell Inc. - 251 JJ Audubon Pkwy
- Doug Al Automotive - 252 Kenmore Ave

- Tn. Tonawanda Parks - Lincoln Park
- Kwik Kleen Inc. - 3584 Main St
- Parkhill & Hart Laundry - 3586 Main St
- Benderson Development - 3608 Main St
- Boulevard Inn & Suit - 3612 Main St
- Blackwell Plaza Service - 3614 Main St
- Eddies Ashland Service - 3620 Main St
- Frontier Oil Co - 3624 Main St
- I/A/O 3 Mallard Ct - 3 Mallard Ct E
- Commercial Property - 4080-120 Maple Rd
- University Mobile St - 4264 Maple Rd
- Grand Island Sls Sv - 190 Meadow Lea
- Mel Ott Ball Field - Meyer Rd
- Baughman Magic Seal - 44 Meyer Rd
- Boulevard Tower Apts -120 Meyer Rd
- Dicks Sporting Goods - 281 Meyer Rd
- Union Concrete Co. - 451 Meyers Rd
- Ellicott Creek Flood - 2350 N Forest Rd
- United Cerebral Palsy - 2360 N Forest
- Conference Center - 2390 N Forest Rd
- FKQ Conference Center - 2401 N Forest Rd
- Jewish Community Cen - 2640 N Forest Rd
- Kadimah School - 2675 N Forest Rd
- Amherst Highway Dept. - N Forest Rd
- STS Car Service - 1435 Niagara Falls Blvd
- Blue Star Dry Cleaner - 1436 Niagara Falls Blvd
- Princeton Housing Assoc. - 165 Princeton Ave
- Morris & Reiman Wr - 3900 Rensch Rd
- Rensch Road Research - 4080 Rensch Rd
- Old Man Precision Auto - 4200 Rensh Rd
- Pinto Construction - 1193 Sweet Home Rd
- World Auto Painting - 2880 Sheridan Dr
- Prints Charming - 2900 Sheridan Dr
- Advance Auto Parts - 2907 Sheridan Dr
- Northtown Plaza - 3097 Sheridan Dr
- BJ's Amherst Gas - 3050 Sheridan Dr
- BJ's Wholesale Club - 3056 Sheridan Dr
- Northtown 1Hour Cleaner - 3075 Sheridan Dr
- Joseph's Services - 3077 Sheridan Dr
- BJ's Wholesale Club - 3080 Sheridan Dr
- Northtown Texaco - 3120 Sheridan Dr
- Ony Biotech 1576 - Sweet Home Rd
- NOCO Energy - 82 Treadwell Rd
- Windermere Blvd School - 291 Windermere Blvd
- Curtis Park U.P. Church - 748 Woodland Dr

4.0 CONCLUSIONS AND RECOMMENDATIONS

Thirty-nine (39) properties were identified in this Phase I ESA Report that may pose an environmental risk and have a chance to affect the Project. Each site is summarized in Table 1 with a recommendation for either possible additional investigatory work (i.e., a Phase II ESA) or the suggestion that an Environmental Monitor be made available to review soil conditions and address any concerns identified in the field.

While all of these listed properties have been identified as having a likelihood of the presence of subsurface soil or groundwater contamination or abandoned tanks, only a limited number will likely have a physical and economic impact on the Project. The reason for this is that documentation exists that some level of environmental remediation has already occurred and it is possible that remaining contamination will be at a concentration below the NYSDEC soil cleanup objectives (SCOs) or at least this may be assumed for those spill sites reported as having met NYSDEC's "standard". At some sites the physical limits of disruption may not be significant enough to impact contaminated materials on that property. Our recommendation would suggest a review of the site-specific construction impacts be performed against the information found within this report to develop a detailed environmental investigation or a monitoring plan for each site. In most cases, if property is acquired in fee, a Phase II ESA should be performed in areas where contamination may be suspected.

From the list, thirty (30) sites are or have been auto repair shops, gas stations or affiliated with auto sales and maintenance. Based on past experience this is a set of historical property usage that often are later determined to exhibit the presence of contamination as result of the release of fuels, oils, solvent cleaning solutions and other chemicals. These materials may be released from ASTs, USTs, cleaning stations, hydraulic lifts, floor drains, oil/water separators and as a result of intentional dumping. The presence of contamination is more common with older businesses operated prior to the onset of environmental regulations requiring tank registration and testing and proper waste disposal. Newer businesses established after approximately 1980 are less likely to have handled materials in a manner that would have contributed to contamination of the environment.

There is also a potential that some of these sites may have abandoned and unmarked USTs within or adjacent to the existing or proposed ROW because of known or suspected former use as petroleum storage/retail sites and their proximity to the roadway. Confirmation that the tanks are no longer present would require that a geophysical survey be conducted in the proposed and existing ROW in these locations to determine whether these USTs and ancillary piping are still present. Locating the USTs would prepare for their proper removal prior to construction; however, their removal, if present, can also be addressed during construction through a contingency in the budget. A total of thirty-two (32) sites have or likely had USTs present at some time. Many of these tanks have been removed though some of the reviewed records indicate that the remediation work did not meet NYSDEC standards meaning contamination was left behind in the subsurface. One of the most common causes of contamination on transportation projects is releases from USTs in close proximity to the adjacent roadway or utility corridor.

Three (3) of the sites are former dry cleaners that are of concern due to past usage of dry cleaning compounds. If deeper excavations (greater than 3 feet) are required adjacent to these sites, they should be investigated for the presence of chlorinated solvent contamination in the subsurface by analyzing select soil samples for Target Compound List (TCL) volatiles or that a contingency be placed within the budget to address possible soil remediation costs during construction.

Property fee acquisitions are proposed at twenty-four (24) of the sites identified in this report however, this may change as the Project is progressed. Since property acquisition is anticipated for these sites, we recommend that a Phase II ESA be considered at these sites, unless other circumstances apply.

Prior to or concurrent with final design, Phase II ESA Field Studies should be performed at those sites with the greatest likelihood of contamination, where substantial soil disturbance is proposed, and where historical usage and/or current environmental information identifies potential concern for property acquisition costs. The scope of the environmental investigation should include drilling investigations conducted with a direct push "hydraulic" rig or rotary drill rig to collect soil samples for retrieval and examination. Soil samples should be collected and analyzed for both Target Compound List (TCL) and Target Analyte List (TAL) parameters for volatile, semi-volatile, pesticides, PCBs, and metals including mercury, cyanide and hexavalent chromium. If any of the results indicate that the sample has the potential to be hazardous, the soil sample would be further analyzed under Toxicity Characteristic Leaching Procedure (TCLP) methodology (EPA method 1311) for the parameter(s) in question. This additional TCLP analysis would allow for the determination of whether the samples meet the definition of a RCRA hazardous waste. The results of these field studies would provide information to support the development of environmental remediation cost estimates and to determine budgetary allowances that should be set aside for construction.

To identify how contamination that is discovered in the field would be addressed, the Contractor would be required to prepare a site-wide Soil Management Plan (a.k.a. Contaminated Material Handling Plan) prior to the start of work outlining procedures to be followed any time evidence of contamination, and/or potential contamination, is suspected or identified. A soil management plan addresses excavation, handling, and disposal of contaminated soil. While this is not a NYSDOT project, contents of such a plan can be found under Section 205 - Contaminated Soil in NYSDOT's Standard Specifications. Once evidence of possible contamination is identified by the Contractor in the field, an Environmental Monitor would be called by the Contractor to assist with the screening and management of soils that show signs of contamination (i.e., strange or noxious odors, unnatural colors or sheen, odors characteristic of petroleum or solvent contamination, elevated volatile vapor readings as measured by field screening instruments). These measures would allow for the protection of on-site workers, collection of any necessary samples, and separation of contaminated from non-contaminated soil. As warranted, ambient air would be monitored for the protection of on-site workers and soil screening would be performed through visual observations and use of a photoionization

detector (PID) or similar instrument. The Environmental Monitor would follow the procedures described in a Field Organic Vapor Monitoring Plan prepared by the Contractor.

However, not all contaminated sites exhibit signs of contamination such as petroleum odors, unnatural colors or sheen, or elevated volatile vapor readings as measured by field screening instruments. During construction, soils excavated from industrial and commercial sites identified in this assessment as having the potential for contamination, would be closely reviewed and characterized by the Contractor to coordinate their proper management and disposal. The establishment and use of an excavated soil laydown yard(s) would be a necessary component of the Soil Management Plan to provide a means to stockpile and test suspect soils generated during this Project. Testing of materials associated with historical industrial property uses would be conducted before releasing soils to the Contractor as unclassified excavation.

Mitigation strategies would start by monitoring excavated soils for evidence of contamination. Any materials that were identified as contaminated would be handled within a temporary work exclusion zone that restricts the area to trained and properly protected workers in proximity to the excavated materials. A direct reading volatile vapor meter would be used by the environmental monitor to adjust the exclusion zone limits. Dust suppression techniques would be employed if necessary. The Contractor would also develop a Site-Specific Health and Safety Plan in conjunction with the Soil Management Plan to address the concerns associated with working with hazardous and contaminated materials found in the excavation materials.

Contaminated soils would be managed in areas identified for material stockpiles or direct loaded for transport to an approved landfill. Stockpiled soils would be either placed on impervious pavement or placed on polyethylene sheeting and covered with sheeting or an equivalent material and properly weighted to prevent contaminated runoff from precipitation and the release of odors. Any soils stored in roll-off containers awaiting transport would be completely covered and secured with waterproof tarpaulins. During transport, contaminated soils shall be covered to control dust emissions. Covering the materials during stockpile and transport would mitigate potential public exposure to dust and contamination.

These recommendations are based on the construction work proposed as of May 2024.

Table 1 - Summary of Recommendations

Site ID #	Property Name and Address	Current Owner	SBL Number(s)	Current or Former Uses				Potential Environmental Concerns	Property Risk Rating	ROW Taking (Y/N)	Recommendation
				Auto Related Industry (Gas Station, Auto Sales & Service, Auto Parts)	Dry Cleaner/ Laundry	Tanks	Other				
1	University at Buffalo – 3425 Main St	State University of New York	79.10-1-1.111 & 7910-1-1.12			X		Chemical/Solvent Contamination, Petroleum Contamination, Abandoned USTs	3	N	No Action Required – Monitor Only
2	Subway Restaurants – 3384 Main St	Raptis Co. LLC	79.47-3-10	X		X		Petroleum Contamination, Abandoned USTs	2	N	Contamination may be encountered if excavation is required.
3	Walgreens – 3490 Main St	Main/Kenmore Partners LLP	79.39-6-5	X		X		Chemical/Solvent Contamination, Petroleum Contamination, Abandoned USTs	1	N	Phase II ESA if ROW acquisition or excavation is required.
4	University Plaza – 3500 Main St	Uniplaza Inc.	79.32-2-24	X		X		Chemical/Solvent Contamination, Petroleum Contamination, Abandoned USTs	3	N	No Action Required – Monitor Only
5	May Jen Chinese Restaurant – 47 Kenmore Ave	Propitious Enterprises LLC	79.32-2-21		X			Chemical/Solvent Contamination	3	N	No Action Required – Monitor Only
6	Vacant Lot – 159 Kenmore Ave	United Refining Company of Pen	79.31-3-23	X		X		Petroleum Contamination, Abandoned USTs	1	Y	Phase II ESA if ROW acquisition or excavation is required.
7	Storefronts – 240 Niagara Falls Blvd	Kinh Van Troung	79.23-2-29 & 79.23-2-30	X		X		Petroleum Contamination, Abandoned USTs	1	N	Phase II ESA if ROW acquisition or excavation is required.
8	Sweeney's Garage – 424 Niagara Falls Blvd	Sweeney's Garage Inc.	67.79-2-9	X		X		Chemical/Solvent Contamination, Petroleum Contamination, Abandoned USTs	1	N	Phase II ESA if ROW acquisition or excavation is required.
9	American Auto World – 733 Niagara Falls Blvd	733 Niagara Falls Blvd Inc.	67.55-8-1	X		X		Chemical/Solvent Contamination, Petroleum Contamination, Abandoned USTs	1	N	Phase II ESA if ROW acquisition or excavation is required.
10	Empire Auto Electric – 803 Niagara Falls Blvd	William Sutherland	67.47-12-4	X				Chemical/Solvent Contamination, Petroleum Contamination	2	N	Contamination may be encountered if excavation is required.
11	NOCO Express – 820 Niagara Falls Blvd	NOCO Express Properties LLC	67.47-3-5 & 67.47-3-4	X		X		Petroleum Contamination, Abandoned USTs	1	N	Phase II ESA if ROW acquisition or excavation is required.
12	Sentry North Appliance Service – 845 Niagara Falls Blvd	Thomas Burgard	67.47-7-16		X			Chemical/Solvent Contamination	3	N	No Action Required – Monitor Only
13	Fancy Florist – 853 Niagara Falls Blvd	Fancy Florist LLC	67.47-7-3.1	X		X		Chemical/Solvent Contamination, Petroleum Contamination, Abandoned USTs	2	Y	Contamination may be encountered if excavation is required.
14	Corsi A First Klass Collision Center – 874 Niagara Falls Blvd	First Klass Property LLC	67.39-2-8	X				Chemical/Solvent Contamination, Petroleum Contamination	1	Y	Phase II ESA if ROW acquisition or excavation is required.
15	Lombardo Funeral Home – 899 Niagara Falls Blvd	JP Lombardo Holdings LLC	67.39-5-2.12	X		X		Petroleum Contamination, Abandoned USTs	1	Y	Phase II ESA if ROW acquisition or excavation is required.
16	U-Haul – 925 Niagara Falls Blvd	Amero Real Estate Co.	67.39-5-1	X		X		Chemical/Solvent Contamination, Petroleum Contamination, Abandoned USTs	1	Y	Phase II ESA if ROW acquisition or excavation is required.

Site ID #	Property Name and Address	Current Owner	SBL Number(s)	Current or Former Uses				Potential Environmental Concerns	Property Risk Rating	ROW Taking (Y/N)	Recommendation
				Auto Related Industry (Gas Station, Auto Sales & Service, Auto Parts)	Dry Cleaner/ Laundry	Tanks	Other				
17	Sun City Matttress – 926 Niagara Falls Blvd	926 NFB LLC	67.39-2-4.1	X				Chemical/Solvent Contamination, Petroleum Contamination	1	Y	Phase II ESA if ROW acquisition or excavation is required.
18	Partner's Bar & Pizzeria – 934 Niagara Falls Blvd	934 NFB LLC	67.39-2-1.1	X		X		Chemical/Solvent Contamination, Petroleum Contamination, Abandoned USTs	1	Y	Phase II ESA if ROW acquisition or excavation is required.
19	Stanton Optical – 2965 Sheridan Dr	M & M Properties Buffalo Inc.	67.31-2-1	X		X		Petroleum Contamination, Abandoned USTs	1	Y	Phase II ESA if ROW acquisition or excavation is required.
20	El Palenque Restaurant – 951 Niagara Falls Blvd	240 Assoc. Ltd Partnership	67.10-1-9	X		X		Petroleum Contamination, Abandoned USTs	1	N	Phase II ESA if ROW acquisition or excavation is required.
21	Monro Auto Service And Tire Centers – 2980 Sheridan Dr	Monroe Muffler Brake Inc.	67.31-1-4	X		X		Chemical/Solvent Contamination, Petroleum Contamination, Abandoned USTs	1	Y	Phase II ESA if ROW acquisition or excavation is required.
22	Firestone Complete Auto Care – 995 Niagara Falls Blvd	FC Amherst LLC	67.06-1-25.1	X		X		Chemical/Solvent Contamination, Petroleum Contamination, Abandoned USTs	1	Y	Phase II ESA if ROW acquisition or excavation is required.
23	Pep Boys Auto Parts & Service – 1025 Niagara Falls Blvd	Amherst Industries Inc.	67.06-1-28.1	X		X		Chemical/Solvent Contamination, Petroleum Contamination, Abandoned USTs	1	Y	Phase II ESA if ROW acquisition or excavation is required.
24	AudioMotive Creations – 1167 Niagara Falls Blvd	1171 NFB Realty LLC	67.39-2-1.1	X				Chemical/Solvent Contamination, Petroleum Contamination	1	Y	Phase II ESA if ROW acquisition or excavation is required.
25	Boulevard Mall – 1261-1265 Niagara Falls Blvd	Forest City Rental, JC Penney Properties, Inc., & Boulevard Mall Co	54.03-1-24.4, 54.03-1-24.21, 54.03-1-24.22, & 67.06-1-1.111			X		Petroleum Contamination, Abandoned USTs	3	Y	No Action Required – Monitor Only
26	Plaza – 1200 Niagara Falls Blvd	MJ Peterson Real Estate	54.79-3-2.1	X	X			Chemical/Solvent Contamination, Petroleum Contamination	1	Y	Phase II ESA if ROW acquisition or excavation is required.
27	Goodyear Auto Service – 1280 Niagara Falls Blvd	Michele J David Family Trust	54.71-2-13.1	X		X		Petroleum Contamination, Abandoned USTs	1	Y	Phase II ESA if ROW acquisition or excavation is required.
28	Valu Muffler & Brake Auto Center – 1346 Niagara Falls Blvd	Genesis Investment Inc.	54.71-2-10	X		X		Petroleum Contamination, Abandoned USTs	1	Y	Phase II ESA if ROW acquisition or excavation is required.
29	Delta Sonic Car Wash – 1355 Niagara Falls Blvd	Delta Sonic Car Wash System	54.14-2-5.11	X		X		Petroleum Contamination, Abandoned USTs	1	Y	Phase II ESA if ROW acquisition or excavation is required.
30	Firestone Complete Auto Care – 3893 Maple Rd	SMBC Leasing & Finance Inc.	54.03-1-13	X		X		Petroleum Contamination, Abandoned USTs	1	Y	Phase II ESA if ROW acquisition or excavation is required.
31	Premiere Group – 3900 Maple Rd	Prime Wines Corp.	54.14-2-7.111	X		X		Petroleum Contamination, Abandoned USTs	3	N	No Action Required – Monitor Only
32	Sweethome Middle School – 4150 Maple Rd	Sweet Home Central School District	54.04-1-5			X		Petroleum Contamination, Abandoned USTs	1	Y	Phase II ESA if ROW acquisition or excavation is required.

Site ID #	Property Name and Address	Current Owner	SBL Number(s)	Current or Former Uses				Potential Environmental Concerns	Property Risk Rating	ROW Taking (Y/N)	Recommendation
				Auto Related Industry (Gas Station, Auto Sales & Service, Auto Parts)	Dry Cleaner/ Laundry	Tanks	Other				
33	NOCO Express – 4265 Maple Rd	NOCO Express Properties, LLC	54.74-3-13	X		X		Petroleum Contamination, Abandoned USTs	1	Y	Phase II ESA if ROW acquisition or excavation is required.
34	Mobil – 4291 Maple Rd	Hawley Development Corp.	54.04-2-17	X		X		Petroleum Contamination, Abandoned USTs	1	Y	Phase II ESA if ROW acquisition or excavation is required.
35	Anchor Bar – 4300 Maple Rd	Flint River Realty Corp.	54.04-2-18.14	X		X		Petroleum Contamination, Abandoned USTs	1	Y	Phase II ESA if ROW acquisition or excavation is required.
36	Ball Pump Station – 1201 Sweethome Rd	Erie County Water Authority	54.04-2-6.1			X		Chemical/Solvent Contamination, Petroleum Contamination, Abandoned USTs	3	N	No Action Required – Monitor Only
37	University of Buffalo – Millersport Hwy	State University of New York at Buffalo	55.01-1-1			X		Chemical/Solvent Contamination, Petroleum Contamination, Abandoned USTs	3	Y	No Action Required – Monitor Only
38	Office Building – 140 John James Audubon Pkwy	Iskalo Office Holdings II LLC	41.03-1-74.1			X		Petroleum Contamination, Abandoned USTs	3	N	No Action Required – Monitor Only
39	Town of Amherst – 350 John James Audubon Pkwy	Town of Amherst	41.03-1-66			X		Petroleum Contamination, Abandoned USTs	3	Y	No Action Required – Monitor Only

Property Risk Rating: Properties were assigned a rating score from 1 to 3, with 1 represents a recommendation for a Phase II Field Investigation if purchase and/or disturbance is likely to occur at that site and a 3 representing a site where no additional investigation work is suggested at this time.

Project Study Area

Source: Esri, DigitalGlobe, GeoEye, Earthstar Geographics, CNES/Airbus DS, USDA, USGS, AeroGRID, IGN, and the GIS User Community

Legend

- Proposed Metro Rail Stations
- 150 Foot Radius from LPA Centerline

Project Location



* Note: Proposed alignment is current as of 1/4/2019. Miscellaneous colored lines are various NFTA bus routes

0 1,375 2,750 5,500 Feet

Figure 1: Metro Rail Expansion Project Hazardous Waste Study Area

Niagara Frontier Transportation Authority
Metro Rail Expansion Project
Erie County, New York

Date: 1/28/2019

WATTS ARCHITECTURE & ENGINEERING

Figure 2A: Sites of Potential Environmental Concern

1. Subway Restaurants - 3384 Main St
2. University at Buffalo - 3425 Main St
3. Walgreens - 3490 Main St
4. University Plaza - 3500 Main St
5. May Jen Chinese Restaurant - 47 Kenmore Ave
6. Vacant Lot - 159 Kenmore Ave

Source: Esri, DigitalGlobe, GeoEye, Earthstar Geographics, CNES/Airbus DS, USDA, USGS, AeroGRID, IGN, and the GIS User Community

N

0 0.035 0.07 0.14 Miles

Oxford Ave
Paige Ave
8
Capen Blvd
Allenhurst Rd
Cambridge Blvd
Ford Ave
Lyndale Ave
Hawthorne Ave
Grandview Ave
Niagara Falls Blvd
Windermere Blvd
Princeton Ave
Kenilworth Ave

7. Storefronts - 240 Niagara Falls Blvd
8. Sweeney's Garage - 424 Niagara Falls Blvd

Source: Esri, DigitalGlobe, GeoEye, Earthstar Geographics, CNES/Airbus DS, USDA, USGS, AeroGRID, IGN, and the GIS User Community

Figure 2B: Sites of Potential Environmental Concern

N

0 0.0275 0.055 0.11 Miles



Figure 2C: Sites of Potential Environmental Concern

9. American Auto World - 733 Niagara Falls Blvd
10. Empire Auto Electric - 803 Niagara Falls Blvd
11. NOCO Express - 820 Niagara Falls Blvd
12. Sentry North Appliance Service - 845 Niagara Falls Blvd
13. Storefronts - 853 Niagara Falls Blvd
14. Corsi A First Klass Collision Center - 874 Niagara Falls Blvd
15. Lombardo Funeral Home - 899 Niagara Falls Blvd
16. U-Haul - 925 Niagara Falls Blvd

Source: Esri, DigitalGlobe, GeoEye, Earthstar Geographics, CNES/Airbus DS, USDA, USGS, AeroGRID, IGN, and the GIS User Community

N

0 0.0225 0.045 0.09 Miles



17. Sun City Mattress - 926 Niagara Falls Blvd
18. Partner's Bar & Pizzeria - 934 Niagara Falls Blvd
19. Stanton Optical - 2965 Sheridan Dr
20. El Palenque Restaurant – 951 Niagara Falls Boulevard
21. Monro Auto Service And Tire Centers - 2980 Sheridan Dr
22. Firestone Complete Auto Care - 995 Niagara Falls Blvd
23. Pep Boys Auto Parts & Service - 1025 Niagara Falls Blvd
24. AudioMotive Creations - 1167 Niagara Falls Blvd

Source: Esri, DigitalGlobe, GeoEye, Earthstar Geographics, CNES/Airbus DS, USDA, USGS, AeroGRID, IGN, and the GIS User Community

Figure 2D: Sites of Potential Environmental Concern

N

0 0.0275 0.055 0.11 Miles



25. Boulevard Mall - 1265 Niagara Falls Blvd
26. Plaza - 1200 Niagara Falls Blvd
27. Goodyear Auto Service - 1280 Niagara Falls Blvd
28. Valu Muffler & Brake Auto Center - 1346 Niagara Falls Blvd
29. Delta Sonic Car Wash - 1355 Niagara Falls Blvd
30. Firestone Complete Auto Care - 3893 Maple Rd
31. Premiere Group - 3900 Maple Rd

Source: Esri, DigitalGlobe, GeoEye, Earthstar Geographics, CNES/Airbus DS, USDA, USGS, AeroGRID, IGN, and the GIS User Community

Figure 2E: Sites of Potential Environmental Concern

N

0 0.035 0.07 0.14 Miles





Figure 2F: Sites of Potential Environmental Concern

N

0 0.05 0.1 0.2 Miles



Figure 2G: Sites of Potential Environmental Concern

N

0 0.1 0.2 0.4 Miles



ATTACHMENT A

Sources of Information

REPORT REFERENCES

Source: Environmental Data Resources, Inc.
Metro Rail Expansion Corridor
Date: January 2019

Source: Environmental Data Resources, Inc.
Aerial Photographs
Date: 1927, 1938, 1951, 1958, 1966, 1978, 1985, 1995, 2006, 2009, 2013 and 2017

Source: Environmental Data Resources, Inc.
City Directories
Date: 1963, 1964, 1968, 1973, 1977, 1982, 1983, 1987, 1988, 1992, 1993, 1998, 1999, 2004, 2008, 2014, 2018, and 2019

Source: Environmental Data Resources, Inc.
Historic USGS Topographic Maps
Date: 1894, 1897, 1899, 1900, 1901, 1913, 1946, 1948, 1950, 1965, 1980, and 2013

Source: Stone & Stewart Publishers.
New Topographic Atlas of Erie County, New York
Date: 1866

Source: G.M. Hopkins & Co.
Atlas of the City of Buffalo, Erie County, New York
Date: 1872

Source: G.M. Hopkins & Co.
Atlas of the Vicinities of Niagara Falls, North Tonawanda, and Buffalo, New York
Date: 1893

Source: Century Atlas Co.
The New Century Atlas of Greater Buffalo, New York
Date: 1915

Source: NYS Department of Environmental Conservation
Spill Incidents Database Website
Date: 2019

Source: NYS Department of Environmental Conservation
Environmental Site Remediation Database Website
Date: 2019

Source: NYS Department of Environmental Conservation
Bulk Storage Database Website
Date: 2019

ACRONYMS

ACM	asbestos-containing materials
AIRS	Aerometric Information Retrieval System
ASTM	American Society for Testing and Materials
AST	Aboveground Storage Tank
CERCLIS	Comprehensive Environmental Response, Compensation and Liability Information System
CERC NFRAP	No Further Remedial Action Planned Sites
DSI	Detailed Site Assessment
EDR	Environmental Data Resources
EM	Electromagnetic Conductivity
EPA	U.S. Environmental Protection Agency
ERNS	Emergency Response Notification System
ESA	Environmental Site Assessment
Fed IC/EC	Federal Institutional and Engineering Controls
FIFRA	Federal Insecticide, Fungicide, and Rodenticide Act
FINDS	Facility Index System
FTTS	FIFRA/Toxic Substances Control Act Tracking Systems
GPR	Ground Penetrating Radar
HMIRS	Hazardous Materials Information Reporting System
HSWDS	Hazardous Substance Waste Disposal
HW/CM	Hazardous Waste/Contaminated Materials
IC/EC	State/Tribal Institutional & Engineering Controls
ICR	Industrial Code Rule
LQG	Large Quantity Generator
Manifest	Hazardous Waste Manifest
Metro	Niagara Frontier Transit Metro System, Inc.
MGP	Manufactured Gas Plants
MLTS	Material Licensing Tracking System
MOSF	Major Oil Storage Facility
NFRAP	No Further Remedial Action Planned
NON GEN	Non-Generator
NPDES	National Pollutant Discharge Elimination System
NPL	National Priority List
NYCRR	New York Codes, Rules and Regulations
NYSDEC	New York State Department of Environmental Conservation
NYSDOT	New York State Department of Transportation
NYSDOH	New York State Department of Health
NYSDOL	New York State Department of Labor

PADS PCB	Activity Database System
PBS	Petroleum Bulk Storage
PCB	Polychlorinated biphenyl
Phase I ESA	Phase I Environmental Site Assessment
Phase II ESA	Phase II Environmental Site Assessment (a.k.a., Detailed Site Assessment)
PID	Photon Ionization Detector
Project	Buffalo-Amherst-Tonawanda Corridor Transit Expansion
PRP	Potentially Responsible Party
RAATS	Resource Conservation and Recovery Act (RCRA) Administrative Action Tracking System
RADINFO	Radiation Information Database
RCRA	Resource Conservation and Recovery Act
RCRA COR	Corrective Action Sites
ROW	Right-of-way
SQG	Small Quantity Generator
TCLP	Toxicity Characteristic Leaching Procedure
TEM	NYSDOT's The Environmental Manual
TRIS	Toxic Chemical Inventory Release System
TSDF	Treatment, Storage, and Disposal Facility
USEPA	United States Environmental Protection Agency
USGS	United States Geological Survey
UST	Underground Storage Tank

ATTACHMENT B

Site Photogrpahs

Photo 1 – Site 3.1 – University at Buffalo: 3425 Main St

Photo 2 – Site 3.1 – University at Buffalo: 3425 Main St

Photo 3 – Site 3.2 – Subway Restaurant 3384 Main St

Photo 4 – Site 3.3 – Walgreens: 3490 Main St

Photo 5 – Site 3.4 – University Plaza: 3500 Main St

Photo 6 – Site 3.4 – University Plaza: 3500 Main St

Photo 7 – Site 3.5 – May Jen Chinese Restaurant: 47 Kenmore Ave

Photo 8 – Site 3.6 – Vacant Lot: 159 Kenmore Ave

Photo 9 – Site 3.7 – Storefronts: 240 Niagara Falls Blvd

Photo 10 – Site 3.8 – Sweeney's Garage: 424 Niagara Falls Blvd

Photo 11 – Site 3.9 – American Auto World: 733 Niagara Falls Blvd

Photo 12 – Site 3.10 – Empire Auto Electric: 803 Niagara Falls Blvd

Photo 13 – Site 3.11 – NOCO Express: 820 Niagara Falls Blvd

Photo 14 – Site 3.12 – Sentry North Appliance Service: 845 Niagara Falls Blvd

Photo 15 – Site 3.13 – Fancy Florist: 853 Niagara Falls Blvd


Photo 16 – Site 3.14 – Corsi A First Klass Collision Center: 874 Niagara Falls Blvd

Photo 17 – Site 3.15 – Lombardo Funeral Home: 899 Niagara Falls Blvd

Photo 18 – Site 3.16 – U-Haul: 925 Niagara Falls Blvd

Photo 19 – Site 3.17 – Sun City Matttress: 926 Niagara Falls Blvd

Photo 20 – Site 3.18 – Partner's Bar & Pizzeria: 934 Niagara Falls Blvd

Photo 21 – Site 3.19 – Stanton Optical: 2965 Sheridan Dr

Photo 22 – Site 3.20 – El Palenque Restaurant: 951 Niagara Falls Blvd

Photo 23 – Site 3.21 – Monro Auto Service & Tire Centers: 2980 Sheridan Dr

Photo 24 – Site 3.22 – Firestone Complete Auto Care: 995 Niagara Falls Blvd

Photo 25 – Site 3.23 – Pep Boys Auto Parts & Service: 1025 Niagara Falls Blvd

Photo 26 – Site 3.24 – Boulevard Mall: 1261-1265 Niagara Falls Blvd

Photo 27 – Site 3.24 – Boulevard Mall: 1261-1265 Niagara Falls Blvd

Photo 28 – Site 3.24 – Boulevard Mall: 1261-1265 Niagara Falls Blvd

Photo 29 – Site 3.24 – Boulevard Mall: 1261-1265 Niagara Falls Blvd

Photo 30 – Site 3.25 – AudioMotive Creations: 1167 Niagara Falls Blvd

Photo 31 – Site 3.26 – Plaza: 1200 Niagara Falls Blvd

Photo 32 – Site 3.27 – Goodyear Auto Service: 1280 Niagara Falls Blvd

Photo 33 – Site 3.28 – Valu Muffler & Brake Auto Center: 1346 Niagara Falls Blvd

Photo 34 – Site 3.29 – Delta Sonic Car Wash: 1355 Niagara Falls Blvd

Photo 35 – Site 3.29 – Delta Sonic Car Wash: 1355 Niagara Falls Blvd

Photo 36 – Site 3.30 – Firestone Complete Auto Care: 3893 Maple Rd

Photo 37 – Site 3.31 – Premiere Group: 3900 Maple Rd

Photo 38 – Site 3.32 – Sweethome Middle School: 4150 Maple Rd

Photo 39 – Site 3.33 – NOCO Express: 4265 Maple Rd

Photo 40 – Site 3.34 – Mobil: 4291 Maple Rd

Photo 41 – Site 3.35 – Anchor Bar: 4300 Maple Rd

Photo 42 – Site 3.36 – Ball Pump Station: 1201 Sweethome Rd

Photo 43 – Site 3.36 – Ball Pump Station: 1201 Sweethome Rd

Photo 44 – Site 3.37 – University of Buffalo: Millersport Hwy

Photo 45 – Site 3.38 – Office Building: 140 John James Audubon Pkwy

Photo 46 – Site 3.39 – Town of Amherst: 350 John James Audubon Pkwy

Photo 47 – Site 3.39 – Town of Amherst: 350 John James Audubon Pkwy

ATTACHMENT C

Environmental Data Resources Inc. (EDR) Environmental Reports

EDR Radius Map Report

Metro Rail Expansion Corridor
City of Buffalo, Towns of Tonawanda and Amherst
Buffalo, NY 14228

Inquiry Number: 05531774.2r
January 11, 2019

EDR Area / Corridor Report

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Mapped Sites Summary	2
Key Map	10
Map Findings Summary	11
Focus Maps	15
Map Findings	39
Orphan Summary	OR-1
Government Records Searched/Data Currency Tracking	GR-1

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2018 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-13), the ASTM Standard Practice for Environmental Site Assessments for Forestland or Rural Property (E 2247-16), the ASTM Standard Practice for Limited Environmental Due Diligence: Transaction Screen Process (E 1528-14) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

SUBJECT PROPERTY INFORMATION

ADDRESS

CITY OF BUFFALO, TOWNS OF TONAWANDA AND AMHERST
BUFFALO, NY 14228

TARGET PROPERTY SEARCH RESULTS

The Target Property was identified in the following databases.

Page Numbers and Map Identifcations refer to the EDR Area/Corridor Report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

STANDARD ENVIRONMENTAL RECORDS

Federal RCRA generators list

RCRA-SQG: RCRA - Small Quantity Generators

A review of the RCRA-SQG list, as provided by EDR, and dated 03/01/2018 has revealed that there is 1 RCRA-SQG site within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
BALL PUMP STATION AN EPA ID:: NYR000130872	SWEET HOME RD	C14 / 4	53

RCRA-CESQG: RCRA - Conditionally Exempt Small Quantity Generator

A review of the RCRA-CESQG list, as provided by EDR, and dated 03/01/2018 has revealed that there are 2 RCRA-CESQG sites within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
MACYS - BOULEVARD #1 EPA ID:: NYR000144683	***1255 NIAGARA FALLS B***	***J40 / 6***	***93***
MACYS - BOULEVARD HO EPA ID:: NYR000144691	1255 NIAGARA FALLS B	J41 / 6	96

EXECUTIVE SUMMARY

Federal ERNS list

ERNS: Emergency Response Notification System

A review of the ERNS list, as provided by EDR, and dated 09/24/2018 has revealed that there is 1 ERNS site within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
Not reported NRC Report #: 132164	500 JOHN JAMES AUDOB	A2 / 2	38

State and tribal leaking storage tank lists

NY LTANKS: Spills Information Database

A review of the NY LTANKS list, as provided by EDR, and dated 11/12/2018 has revealed that there are 7 NY LTANKS sites within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
AMHERST PD Site ID: 225772 Spill Number/Closed Date: 9408494 / 1995-06-15	500 JOHN JAMES PARKW	A8 / 2	48
NORTH CAMP RV & MARI Site ID: 76709 Spill Number/Closed Date: 8606881 / 1987-04-16	MAPLE & SWEETHOME	E16 / 4	55
FORMER ED TAYLOR LIN Site ID: 292060 Spill Number/Closed Date: 9201849 / 1994-04-25	***3900 MAPLE***	***F19 / 6***	***60***
NOCO ENERGY STATION Site ID: 199745 Spill Number/Closed Date: 9709710 / 1998-03-11	MAPLE AND SWEETHOME	E24 / 7	78
FIRESTONE Site ID: 231424 Spill Number/Closed Date: 9212411 / 1993-02-03	3931 MAPLE ROAD	F30 / 6	85
FIRESTONE TIRE Site ID: 247776 Spill Number/Closed Date: 8605722 / 1986-12-12	NIAGARA FALLS BOULEV	N50 / 6	105
MOBIL OIL Site ID: 178358 Spill Number/Closed Date: 8908630 / 1990-10-30	3514 MAIN STREET	P55 / 8	113

State and tribal registered storage tank lists

NY UST: Petroleum Bulk Storage (PBS) Database

A review of the NY UST list, as provided by EDR, has revealed that there are 3 NY UST sites within

the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
TOWN OF AMHERST POLI Database: UST, Date of Government Version: 09/25/2018	500 JOHN JAMES AUDUB	A7 / 2	44
ED TAYLOR LINC-MERC. Database: UST, Date of Government Version: 09/25/2018	3900 MAPLE RD.	F20 / 6	64
KAUFMANN'S DEPARTMEN Database: UST, Date of Government Version: 09/25/2018	1255 NIAGARA FALLS B	J42 / 6	98

NY AST: Petroleum Bulk Storage

A review of the NY AST list, as provided by EDR, has revealed that there are 3 NY AST sites within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
TOWN OF AMHERST POLI Database: AST, Date of Government Version: 09/25/2018 Facility Id: 9-446882	500 JOHN JAMES AUDUB	A6 / 2	40
STEVE BALDO LINCOLN Database: AST, Date of Government Version: 09/25/2018 Facility Id: 9-600542 Facility Id: 9-444146	3900 MAPLE ROAD	F21 / 6	67
FIRESTONE COMPLETE A Database: AST, Date of Government Version: 09/25/2018 Facility Id: 9-600298	3931 MAPLE ROAD	F31 / 6	86

ADDITIONAL ENVIRONMENTAL RECORDS

Records of Emergency Release Reports

NY Spills: Spills Information Database

A review of the NY Spills list, as provided by EDR, and dated 11/12/2018 has revealed that there are 18 NY Spills sites within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
ELLICOTT CREEK Site ID: 366967 Spill Number/Closed Date: 0604084 / 2006-07-17	INTER JOHNS JAMES AU	13 / 5	51
FORMER ED TAYLOR LIN Site ID: 434662 Site ID: 169140 Spill Number/Closed Date: 1001596 / 2011-06-23 Spill Number/Closed Date: 9975473 / 1999-12-09	***3900 MAPLE***	***F19 / 6***	***60***
GOLDOME Site ID: 234040 Spill Number/Closed Date: 8702308 / 1987-06-25	3840 MAPLE ROAD	G23 / 6	77
GAS STATION	4146 MAPLE ROAD	25 / 7	79

Site ID: 441937
Spill Number/Closed Date: 1008446 / 2010-12-15

NIAGARA MOHAWK TRANS NORTH BAILEY & MAPLE 27 / 7 81
Site ID: 147231
Spill Number/Closed Date: 9708434 / 1999-08-27

UNKNOWN SUBSTANCE 730 ALBERTA DR 28 / 6 82
Site ID: 150423
Spill Number/Closed Date: 0107228 / 2001-10-15

NIAGARA MOHAWK TRANS 4215 MAPLE ROAD 35 / 7 89
Site ID: 124354
Spill Number/Closed Date: 9802064 / 1998-05-19

WILSON FARMS 1244 NIAGARA FALLS B J36 / 6 90
Site ID: 106501
Spill Number/Closed Date: 9213436 / 1993-03-12

NIAGARA MOHAWK BOUL. 1227 NIAGARA FALLS B K44 / 6 99
Site ID: 239291
Spill Number/Closed Date: 9106426 / 1991-09-16

KAUFMANS 1225 NIAGARA FALLS B K45 / 6 100
Site ID: 64576
Spill Number/Closed Date: 0175412 / 2001-12-24

MIDAS DRAINS 1171 NIAGARA FALLS B 46 / 6 101
Site ID: 319992
Spill Number/Closed Date: 9875468 / 1999-10-12

AUTOMATIC ROLLS/NORT NIAGARA FALLS BLVD - L47 / 6 103
Site ID: 259191
Spill Number/Closed Date: 9406936 / 1995-06-06

NYSDOT PROJECT/ACCAD NIAGARA FALLS BLVD/S M49 / 6 104
Site ID: 101005
Spill Number/Closed Date: 9975503 / 1999-11-01

NFG EXCAVATION NIAGARA FALLS BLVD/E N51 / 6 106
Site ID: 129365
Spill Number/Closed Date: 9802491 / 2003-01-17

NYSDOT PROJECT/U-HAU NIAGARA FALLS BLVD/E O52 / 6 107
Site ID: 129366
Spill Number/Closed Date: 9975504 / 1999-11-01

BIG JOHN RESTAURANT BIG JOHN RESTAURANT 53 / 8 108
Site ID: 301849
Spill Number/Closed Date: 8708683 / 1988-05-31

UNIVERSITY PLAZA 3500 MAIN STREET P58 / 8 117
Site ID: 66354
Site ID: 66355
Spill Number/Closed Date: 9404727 / 1994-07-21
Spill Number/Closed Date: 9404763 / 1994-07-11

AJ WRIGHT 3500 MAIN ST P59 / 8 119
Site ID: 411338
Spill Number/Closed Date: 0813644 / 2009-03-18

Other Ascertainable Records

RCRA NonGen / NLR: RCRA - Non Generators / No Longer Regulated

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 03/01/2018 has revealed that there are 4 RCRA NonGen / NLR sites within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
ED TAYLOR LINCOLN ME EPA ID:: NYD986981934	***3900 MAPLE RD***	***F17 / 6***	***56***
BRIDGESTONE FIRESTON EPA ID:: NYD987008984	***3931 MAPLE RD***	***F29 / 6***	***83***
MOBIL OI CORP SS #HA EPA ID:: NYD987036084	***3514 MAIN ST***	***P54 / 8***	***110***
NIAGARA MOHAWK A NAT EPA ID:: NYP000971218	***KENMORE AVE & MAIN S***	***P57 / 8***	***115***

ICIS: Integrated Compliance Information System

A review of the ICIS list, as provided by EDR, and dated 11/18/2016 has revealed that there is 1 ICIS site within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
TOWN OF AMHERST POLI FRS ID:: 110024276503	***500 JOHN JAMES AUDUB***	***A5 / 2***	***39***

FINDS: Facility Index System/Facility Registry System

A review of the FINDS list, as provided by EDR, and dated 08/07/2018 has revealed that there are 13 FINDS sites within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
MUIR WOODS DEVELOPME Registry ID:: 110040178189	1081 & 1121 N FRENCH	1 / 2	38
VZW AUDUBON Registry ID:: 110056392210	500 JOHN JAMES AUDUB	A3 / 2	38
TOWN OF AMHERST POLI Registry ID:: 110024276503	***500 JOHN JAMES AUDUB***	***A5 / 2***	***39***
AMHERST-T SENIOR CIT Registry ID:: 110019766591	370 JOHN JAMES AUDUB	9 / 2	50
ISKALO OFFICE BLDG Registry ID:: 110055271067	2410 N FOREST RD	B11 / 5	50
NYSDOT BIN 1-07260-1 Registry ID:: 110008107020	***I290 SB BRG OVER SWE***	***D15 / 4***	***54***
ED TAYLOR LINCOLN ME Registry ID:: 110004480464	***3900 MAPLE RD***	***F17 / 6***	***56***
PREMIER GOURMET	3904 MAPLE RD	F18 / 6	59

Registry ID:: 110055353308			
BRIDGESTONE FIRESTON Registry ID:: 110004492692	***3931 MAPLE RD***	***F29 / 6***	***83***
MACYS - BOULEVARD HO Registry ID:: 110031350384	***1255 NIAGARA FALLS B***	***J37 / 6***	***91***
NYSDOT D257531 Registry ID:: 110008104452	***RTE 62 INTERSECTION***	***M48 / 6***	***104***
MOBIL OI CORP SS #HA Registry ID:: 110004505973	***3514 MAIN ST***	***P54 / 8***	***110***
NIAGARA MOHAWK A NAT Registry ID:: 110062911522	***KENMORE AVE & MAIN S***	***P60 / 8***	***120***

ECHO: Enforcement & Compliance History Information

A review of the ECHO list, as provided by EDR, and dated 09/02/2018 has revealed that there are 8 ECHO sites within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
TOWN OF AMHERST POLI Registry ID: 110024276503	***500 JOHN JAMES AUDUB***	***A5 / 2***	***39***
NYSDOT BIN 1-07260-1 Registry ID: 110008107020	***I290 SB BRG OVER SWE***	***D15 / 4***	***54***
ED TAYLOR LINCOLN ME Registry ID: 110004480464	***3900 MAPLE RD***	***F17 / 6***	***56***
BRIDGESTONE FIRESTON Registry ID: 110004492692	***3931 MAPLE RD***	***F29 / 6***	***83***
MACYS - BOULEVARD HO Registry ID: 110031350384	***1255 NIAGARA FALLS B***	***J37 / 6***	***91***
NYSDOT D257531 Registry ID: 110008104452	***RTE 62 INTERSECTION***	***M48 / 6***	***104***
MOBIL OI CORP SS #HA Registry ID: 110004505973	***3514 MAIN ST***	***P54 / 8***	***110***
NIAGARA MOHAWK A NAT Registry ID: 110062911522	***KENMORE AVE & MAIN S***	***P60 / 8***	***120***

NY AIRS: Air Emissions Data

A review of the NY AIRS list, as provided by EDR, and dated 11/06/2018 has revealed that there is 1 NY AIRS site within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
PREMIER GOURMET DEC Id: 9142200545	3904 MAPLE RD	F22 / 6	77

EXECUTIVE SUMMARY

NY MANIFEST: Facility and Manifest Data

A review of the NY MANIFEST list, as provided by EDR, and dated 10/01/2018 has revealed that there are 4 NY MANIFEST sites within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
ED TAYLOR LINCOLN ME EPA ID: NYD986981934	***3900 MAPLE RD***	***F17 / 6***	***56***
MACYS - BOULEVARD #1 EPA ID: NYR000144683	***1255 NIAGARA FALLS B***	***J40 / 6***	***93***
MOBIL OI CORP SS #HA EPA ID: NYD987036084	***3514 MAIN ST***	***P54 / 8***	***110***
NIAGARA MOHAWK A NAT EPA ID: NYP000971218	***KENMORE AVE & MAIN S***	***P57 / 8***	***115***

NY COOLING TOWERS: Registered Cooling Towers

A review of the NY COOLING TOWERS list, as provided by EDR, and dated 10/16/2018 has revealed that there are 8 NY COOLING TOWERS sites within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
Not reported	500 JOHN JAMES AUDUB	A4 / 2	39
Not reported	2410 NORTH FOREST RO	B10 / 5	50
Not reported	2410 N FOREST RD	B12 / 5	51
Not reported	4053 MAPLE RD	I32 / 7	88
Not reported	4053 MAPLE RD	I33 / 7	88
Not reported	4053 MAPLE RD	I34 / 7	89
Not reported	1255 NIAGRA FALLS BO	J38 / 6	92
Not reported	1255 NIAGARA FALLS B	J39 / 6	92

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR Hist Auto: EDR Exclusive Historical Auto Stations

A review of the EDR Hist Auto list, as provided by EDR, has revealed that there are 2 EDR Hist Auto sites within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
UNIVERSITY MOBILE ST	4264 MAPLE RD	H26 / 7	80
BLACKWELLS PLAZA SER	3514 MAIN ST	P56 / 8	114

EXECUTIVE SUMMARY

EDR Hist Cleaner: EDR Exclusive Historical Cleaners

A review of the EDR Hist Cleaner list, as provided by EDR, has revealed that there is 1 EDR Hist Cleaner site within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
FURST ARTHUR	1226 NIAGARA FLS BD	J43 / 6	99

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Page Numbers and Map Identifcations refer to the EDR Area/Corridor Report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Federal RCRA generators list

RCRA-LQG: RCRA - Large Quantity Generators

A review of the RCRA-LQG list, as provided by EDR, and dated 03/01/2018 has revealed that there are 2 RCRA-LQG sites within approximately 0.25 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
CVS PHARMACY #1227 EPA ID:: NYR000192013	***520 LEE ENTRANCE***	***E 0 - 1/8 (0.011 mi.)***	***Q61 / 5***	***120***
STATE UNIVERSITY OF EPA ID:: NYD071475867	***3435 MAIN ST***	***NW 0 - 1/8 (0.073 mi.)***	***AP201 / 8***	***498***

RCRA-SQG: RCRA - Small Quantity Generators

A review of the RCRA-SQG list, as provided by EDR, and dated 03/01/2018 has revealed that there are 2 RCRA-SQG sites within approximately 0.25 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
ADVANCE AUTO PARTS # EPA ID:: NYR000234690	2907 SHERIDAN DR	W 1/8 - 1/4 (0.172 mi.)	BD279 / 6	646
ONY BIOTECH EPA ID:: NY0000075754	1576 SWEET HOME RD N	NNW 1/8 - 1/4 (0.248 mi.)	345 / 4	781

EXECUTIVE SUMMARY

RCRA-CESQG: RCRA - Conditionally Exempt Small Quantity Generator

A review of the RCRA-CESQG list, as provided by EDR, and dated 03/01/2018 has revealed that there are 13 RCRA-CESQG sites within approximately 0.25 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
CARUBBA COLLISION, I EPA ID:: NYD022673313	***1167 NIAGARA FALLS B***	***E 0 - 1/8 (0.021 mi.)***	***AC119 / 6***	***234***
GOODYEAR AUTO SERVIC EPA ID:: NYD149982795	***1280 NIAGARA FALLS B***	***W 0 - 1/8 (0.029 mi.)***	***AD127 / 6***	***249***
MOBIL OIL CROP SS H4 EPA ID:: NYD986958890	***2965 SHERIDAN DR***	***W 0 - 1/8 (0.037 mi.)***	***AG145 / 6***	***284***
BASIL FORD EPA ID:: NYD118786128	***3484 MAIN ST***	***S 0 - 1/8 (0.066 mi.)***	***AO184 / 8***	***460***
SEARS #1162 EPA ID:: NYR000165175	***1261 NIAGARA FALLS B***	***E 0 - 1/8 (0.084 mi.)***	***AR211 / 6***	***551***
BYE BYE BABY #3083 EPA ID:: NYR000209254	***1261 NIAGARA FALLS B***	***E 0 - 1/8 (0.084 mi.)***	***AR212 / 6***	***556***
WEGMANS #0082 EPA ID:: NYR000147058	***675 ALBERTA DR***	***S 0 - 1/8 (0.107 mi.)***	***AU221 / 6***	***566***
BJS WHOLESALE CLUB # EPA ID:: NYR000197376	3056 SHERIDAN DR	E 1/8 - 1/4 (0.127 mi.)	AW253 / 6	614
SAVERS STORE #1217 EPA ID:: NYD981139850	***2309 EGGERT RD***	***W 1/8 - 1/4 (0.176 mi.)***	***BE281 / 6***	***649***
AMHERST CSD - WINDER EPA ID:: NYR000214213	291 WINDERMERE BLVD	E 1/8 - 1/4 (0.218 mi.)	BI315 / 8	736
FERRIC CONTRAST INC EPA ID:: NYR000101360	***1576 SWEET HOME RD R***	***NNW 1/8 - 1/4 (0.219 mi.)***	***BJ322 / 4***	***745***
DIMIEN LLC EPA ID:: NYD986938140	***1576 SWEET HOME RD S***	***NNW 1/8 - 1/4 (0.219 mi.)***	***BJ326 / 4***	***759***
DICKS SPORTING GOODS EPA ID:: NYR000224246	***281 MEYER RD***	***N 1/8 - 1/4 (0.239 mi.)***	***BK336 / 4***	***769***

Federal ERNS list

ERNS: Emergency Response Notification System

A review of the ERNS list, as provided by EDR, and dated 09/24/2018 has revealed that there are 5 ERNS sites within approximately 0.25 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
Not reported NRC Report #: 1056839	2980 SHERIDAN DRIVE	W 0 - 1/8 (0.032 mi.)	AF134 / 6	270
Not reported NRC Report #: 301753	123 LYNDALE AVE	W 1/8 - 1/4 (0.162 mi.)	BC273 / 8	642
Not reported NRC Report #: 53110	95 TREADWELL AVE	W 1/8 - 1/4 (0.189 mi.)	291 / 6	659
Not reported	174 UNIVERSITY AVENU	WSW 1/8 - 1/4 (0.221 mi.)	330 / 8	763

NRC Report #: 967914

Not reported NRC Report #: 543620	3640 MAIN ST	NE 1/8 - 1/4 (0.231 mi.)	334 / 9	768

State and tribal leaking storage tank lists

NY LTANKS: Spills Information Database

A review of the NY LTANKS list, as provided by EDR, and dated 11/12/2018 has revealed that there are 34 NY LTANKS sites within approximately 0.25 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
JIM WOODS TIRE & BAT Site ID: 314328 Spill Number/Closed Date: 8707234 / 1988-10-20	826 NIAGARA FALLS BL	W 0 - 1/8 (0.011 mi.)	R67 / 6	137
COLUMBUS MCKINNON, I Site ID: 216514 Spill Number/Closed Date: 9210347 / 1993-02-22	140 JOHN JAMES AUDOB	NE 0 - 1/8 (0.012 mi.)	S72 / 2	143
MOBIL Site ID: 113854 Spill Number/Closed Date: 8602251 / 1986-09-05	N.F.BLVD. & SHERIDAN	E 0 - 1/8 (0.016 mi.)	M92 / 6	165
SWEENEY'S GARAGE Site ID: 192730 Spill Number/Closed Date: 9802942 / 1998-09-14	***424 NIAGARA FALLS BL***	***W 0 - 1/8 (0.018 mi.)***	***AA108 / 8***	***204***
BOB HILLS OLD GAS ST Site ID: 304933 Site ID: 304934 Site ID: 304935 Spill Number/Closed Date: 9608361 / 1996-12-31 Spill Number/Closed Date: 9608691 / 1996-10-15 Spill Number/Closed Date: 9713199 / 1998-03-16	240 NIAGARA FALLS BL	W 0 - 1/8 (0.018 mi.)	T110 / 8	209
TN. TONAWANDA PARKS Site ID: 67295 Spill Number/Closed Date: 8700016 / 1987-06-02	LINCOLN PARK	E 0 - 1/8 (0.028 mi.)	126 / 6	248
KWIKFILL Site ID: 250608 Spill Number/Closed Date: 9875345 / 2000-05-01	***175 KENMORE AVE***	***SW 0 - 1/8 (0.030 mi.)***	***AE132 / 8***	***265***
FIRESTONE Site ID: 218987 Spill Number/Closed Date: 9206303 / 1992-10-02	NIAGARA FALLS BLVD.	NNW 0 - 1/8 (0.034 mi.)	G139 / 3	275
FIRESTONE 955 NFB Site ID: 191032 Spill Number/Closed Date: 9206340 / 1993-01-19	NIAGARA FALLS BLVD M	NNW 0 - 1/8 (0.034 mi.)	G140 / 3	276
MOBIL OIL Site ID: 368295 Site ID: 320414 Site ID: 320415 Site ID: 320416 Spill Number/Closed Date: 0605174 / 2007-11-30	***2965 SHERIDAN DRIVE***	***W 0 - 1/8 (0.037 mi.)***	***AG146 / 6***	***288***

Spill Number/Closed Date: 9008391 / 1991-05-16
Spill Number/Closed Date: 9012026 / 1992-06-11
Spill Number/Closed Date: 9705822 / 2000-02-15

SOUTHLAND CORP. 7-EL	MAIN STREET AT WINDE	SW 0 - 1/8 (0.039 mi.)	AH151 / 8	304
Site ID: 123202				
Spill Number/Closed Date: 8702468 / 1987-08-11				
EZ MART	***4291 MAPLE RD***	***SE 0 - 1/8 (0.045 mi.)***	***AI156 / 7***	***309***
Site ID: 458804				
Spill Number/Closed Date: 1110941 / 2013-06-28				
MOBIL OIL	SHERIDAN & NIAGARA F	W 0 - 1/8 (0.046 mi.)	AF159 / 6	327
Site ID: 277625				
Spill Number/Closed Date: 8908574 / 1990-10-15				
DELTA SONIC - BOULEV	***1355 NIAGARA FALLS B***	***NNW 0 - 1/8 (0.050 mi.)***	***AK167 / 3***	***354***
Site ID: 303871				
Site ID: 303872				
Spill Number/Closed Date: 8703113 / 1987-08-05				
Spill Number/Closed Date: 9204430 / 1992-12-10				
BASIL FORD	***3484 MAIN STREET***	***S 0 - 1/8 (0.066 mi.)***	***AO182 / 8***	***453***
Site ID: 327438				
Spill Number/Closed Date: 9501367 / 1995-11-17				
SUNY AT BUFFALO	***MILLERSPORT HIGHWAY***	***NNE 0 - 1/8 (0.069 mi.)***	***AN187 / 4***	***466***
Site ID: 257969				
Spill Number/Closed Date: 9706838 / 2001-07-24				
NYS UNIV. AT BUFFALO	301 MICHAEL HALL	NNE 0 - 1/8 (0.069 mi.)	AN188 / 4	469
Site ID: 308852				
Spill Number/Closed Date: 9300882 / 1993-04-29				
UNIVERSITY OF BUFFAL	***3435 MAIN STREET***	***NW 0 - 1/8 (0.073 mi.)***	***AP200 / 8***	***489***
Site ID: 80791				
Site ID: 80792				
Spill Number/Closed Date: 9004852 / 1993-12-23				
Spill Number/Closed Date: 9307528 / 1993-11-19				
MOBIL S/S 08-HA1	***3514 MAIN & KENMORE***	***NNE 0 - 1/8 (0.111 mi.)***	***227 / 8***	***574***
Site ID: 156910				
Spill Number/Closed Date: 9207319 / 1996-12-04				
ORKEN LAWNCARE	514 CAPEN BOULEVARD	E 0 - 1/8 (0.119 mi.)	231 / 8	586
Site ID: 235456				
Spill Number/Closed Date: 8901455 / 1989-05-13				
UNIVERSITY OF BUFFAL	NORTH CAMPUS - BAIRD	N 0 - 1/8 (0.122 mi.)	AY239 / 4	596
Site ID: 262404				
Spill Number/Closed Date: 0104703 / 2003-01-30				
ALUMNI ARENA -SUNYAB	WEBSTER ROAD	N 0 - 1/8 (0.122 mi.)	AY240 / 4	598
Site ID: 108226				
Spill Number/Closed Date: 9805985 / 1998-11-27				
JACOB'S MANAGEMENT C	SUNY BUFFALO	N 0 - 1/8 (0.122 mi.)	AY245 / 4	604
Site ID: 235289				
Spill Number/Closed Date: 0102567 / 2003-01-29				
SUNY BUFFALO	TALBERT HALL	N 0 - 1/8 (0.122 mi.)	AY246 / 4	605
Site ID: 245095				
Spill Number/Closed Date: 0102018 / 2002-02-19				
PORTER QUAD - ELLICO	JOHN JAMES AUDUBON P	N 0 - 1/8 (0.122 mi.)	AY247 / 4	606

Site ID: 197080 Spill Number/Closed Date: 0075540 / 2001-10-01				
STATE UNIV BUFFALO N Site ID: 290318 Spill Number/Closed Date: 0011535 / 2002-02-19	LOCKWOOD LIBRARY	N 0 - 1/8 (0.122 mi.)	AY248 / 4	608
PRINTS CHARMING - TA Site ID: 227982 Spill Number/Closed Date: 9410986 / 1994-12-20	2900 SHERIDAN DRIVE	W 1/8 - 1/4 (0.126 mi.)	AX252 / 6	613
JOE CONTINO RESIDENC Site ID: 140721 Spill Number/Closed Date: 9301533 / 1993-12-28	142 DALTON DRIVE	W 1/8 - 1/4 (0.129 mi.)	257 / 6	622
STS CAR SERVICE Site ID: 115595 Site ID: 123585 Spill Number/Closed Date: 9611396 / 1997-12-26 Spill Number/Closed Date: 9107450 / 1992-03-24	1435 NIAGARA FALLS B	NNW 1/8 - 1/4 (0.153 mi.)	BA266 / 3	630
JOAN MILLEY TANK Site ID: 238945 Spill Number/Closed Date: 9601286 / 1996-05-01	45 CONANT STREET	W 1/8 - 1/4 (0.210 mi.)	308 / 8	725
FURMAN RESIDENCE Site ID: 194382 Spill Number/Closed Date: 9313777 / 1996-05-28	99 CONANT AVENUE	W 1/8 - 1/4 (0.212 mi.)	309 / 8	726
NATIONAL GRID TRANSF Site ID: 489491 Spill Number/Closed Date: 1308736 / 2014-05-02	38 PARTRIDGE RUN	E 1/8 - 1/4 (0.216 mi.)	312 / 2	731
WINDERMERE BLVD SCHO Site ID: 235642 Spill Number/Closed Date: 9100547 / 1992-03-23	***291 WINDERMERE BLVD***	***E 1/8 - 1/4 (0.218 mi.)***	***BI314 / 8***	***732***
BALL PUMP STATION Site ID: 149088 Spill Number/Closed Date: 9209938 / 1993-02-03	***SWEET HOME ROAD***	***NNW 1/8 - 1/4 (0.218 mi.)***	***BJ317 / 4***	***738***

State and tribal registered storage tank lists

NY UST: Petroleum Bulk Storage (PBS) Database

A review of the NY UST list, as provided by EDR, has revealed that there are 21 NY UST sites within approximately 0.25 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
CM HEADQUARTERS BUIL Database: UST, Date of Government Version: 09/25/2018	140 JOHN JAMES AUDUB	NE 0 - 1/8 (0.012 mi.)	S71 / 2	141
GREAT LAKES DIVERS Database: UST, Date of Government Version: 09/25/2018	240 NIAGARA FALLS BL	W 0 - 1/8 (0.012 mi.)	T73 / 8	144
SWEETHOME JUNIOR HIG Database: UST, Date of Government Version: 09/25/2018	***4150 MAPLE RD***	***N 0 - 1/8 (0.012 mi.)***	***V77 / 7***	***149***
BOULEVARD U-HAUL CEN Database: UST, Date of Government Version: 09/25/2018	925 NIAGARA FALLS BO	E 0 - 1/8 (0.017 mi.)	Z102 / 6	181
NOCO EXPRESS S-74 Database: UST, Date of Government Version: 09/25/2018	820 NIAGARA FALLS BO	W 0 - 1/8 (0.018 mi.)	R105 / 6	197

EXECUTIVE SUMMARY

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
JIM WOODS TIRE & BAT Database: UST, Date of Government Version: 09/25/2018	820 NIAGARA FALLS BL	W 0 - 1/8 (0.018 mi.)	R106 / 6	200
A&F AUTOMOTIVE Database: UST, Date of Government Version: 09/25/2018	733 NIAGARA FALLS BL	E 0 - 1/8 (0.020 mi.)	AB116 / 6	224
NOCO EXPRESS S-24 Database: UST, Date of Government Version: 09/25/2018	4265 MAPLE ROAD	S 0 - 1/8 (0.023 mi.)	H123 / 7	242
RED APPLE FOOD MART Database: UST, Date of Government Version: 09/25/2018	175 KENMORE AVE	SW 0 - 1/8 (0.030 mi.)	AE131 / 8	261
EZ MART Database: UST, Date of Government Version: 09/25/2018	***4291 MAPLE RD***	***SE 0 - 1/8 (0.045 mi.)***	***AI156 / 7***	***309***
DELTA SONIC CAR WASH Database: UST, Date of Government Version: 09/25/2018	1355 NIAGARA FALLS B	NNW 0 - 1/8 (0.050 mi.)	AK169 / 3	368
7- ELEVEN STORE #224 Database: UST, Date of Government Version: 09/25/2018	3488 MAIN STREET	SSW 0 - 1/8 (0.056 mi.)	AH172 / 8	382
BASIL FORD INC. Database: UST, Date of Government Version: 09/25/2018	3484 MAIN STREET	S 0 - 1/8 (0.066 mi.)	AO183 / 8	456
CURTIS PARK U.P. CHU Database: UST, Date of Government Version: 09/25/2018	748 WOODLAND DR	W 0 - 1/8 (0.076 mi.)	204 / 6	538
NORTHTOWN PLAZA CAR Database: UST, Date of Government Version: 09/25/2018	2125 EGGERT RD	E 0 - 1/8 (0.084 mi.)	AQ209 / 6	546
PROPERTY Database: UST, Date of Government Version: 09/25/2018	3945 RENSCH RD	NW 0 - 1/8 (0.108 mi.)	AV224 / 4	570
MOBIL S/S 08-HA1 Database: UST, Date of Government Version: 09/25/2018	***3514 MAIN & KENMORE***	***NNE 0 - 1/8 (0.111 mi.)***	***227 / 8***	***574***
BJ'S AMHERST GAS STA Database: UST, Date of Government Version: 09/25/2018	3050 SHERIDAN DRIVE	E 0 - 1/8 (0.118 mi.)	AW230 / 6	582
PRINTS CHARMING Database: UST, Date of Government Version: 09/25/2018	2900 SHERIDAN DR	W 1/8 - 1/4 (0.126 mi.)	AX251 / 6	612
NORTHTOWN PLAZA Database: UST, Date of Government Version: 09/25/2018	3097 SHERIDAN DR	E 1/8 - 1/4 (0.197 mi.)	BG304 / 6	717
WINDERMERE BLVD SCHO Database: UST, Date of Government Version: 09/25/2018	***291 WINDERMERE BLVD***	***E 1/8 - 1/4 (0.218 mi.)***	***BI314 / 8***	***732***

NY CBS UST: Chemical Bulk Storage Database

A review of the NY CBS UST list, as provided by EDR, and dated 01/01/2002 has revealed that there is 1 NY CBS UST site within approximately 0.25 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
SUNY AT BUFFALO-NORT Facility Status: 4 Id/Status: 9-000276 Tank Status: 2	***THE JOHN BEANE CENTE***	***NNE 0 - 1/8 (0.069 mi.)***	***AN189 / 4***	***471***

EXECUTIVE SUMMARY

NY CBS: Chemical Bulk Storage Site Listing

A review of the NY CBS list, as provided by EDR, and dated 09/25/2018 has revealed that there are 2 NY CBS sites within approximately 0.25 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
PEP BOYS #0193	***1025 NIAGARA FALLS B***	***E 0 - 1/8 (0.016 mi.)***	***Y99 / 6***	***178***
Facility Status: Unregulated/Closed CBS Number: 9-000436				
SUNY AT BUFFALO-NORT	***THE JOHN BEANE CENTE***	***NNE 0 - 1/8 (0.069 mi.)***	***AN189 / 4***	***471***
Facility Status: Unregulated/Closed CBS Number: 9-000276				

NY AST: Petroleum Bulk Storage

A review of the NY AST list, as provided by EDR, has revealed that there are 10 NY AST sites within approximately 0.25 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
SPEEDY AUTO SERVICE	934 NIAGARA FALLS BL	W 0 - 1/8 (0.016 mi.)	O95 / 6	170
Database: AST, Date of Government Version: 09/25/2018 Facility Id: 9-600411				
PEP BOYS #193	1025 NIAGARA FALLS B	E 0 - 1/8 (0.016 mi.)	Y97 / 6	173
Database: AST, Date of Government Version: 09/25/2018 Facility Id: 9-600354				
FIRESTONE COMPLETE A	995 NIAGARA FALLS BO	E 0 - 1/8 (0.020 mi.)	L112 / 6	216
Database: AST, Date of Government Version: 09/25/2018 Facility Id: 9-600303				
GOODYEAR 0462	1280 NIAGARA FALLS B	W 0 - 1/8 (0.029 mi.)	AD128 / 6	255
Database: AST, Date of Government Version: 09/25/2018 Facility Id: 9-601188				
MONRO MUFFLER BRAKE	***2980 SHERIDAN DR***	***W 0 - 1/8 (0.035 mi.)***	***AF142 / 6***	***278***
Database: AST, Date of Government Version: 09/25/2018 Facility Id: 9-600273				
DELTA SONIC CAR WASH	1355 NIAGARA FALLS B	NNW 0 - 1/8 (0.050 mi.)	AK166 / 3	335
Database: AST, Date of Government Version: 09/25/2018 Facility Id: 9-225185				
SUNY AT BUFFALO - NO	SERVICE BUILDING	NW 0 - 1/8 (0.057 mi.)	AL177 / 8	394
Database: AST, Date of Government Version: 09/25/2018 Facility Id: 9-039403				
BASIL FORD	***3484 MAIN STREET***	***S 0 - 1/8 (0.066 mi.)***	***AO182 / 8***	***453***
Database: AST, Date of Government Version: 09/25/2018 Facility Id: 9-444227				
BJ'S WHOLESALE CLUB	3056 SHERIDAN DRIVE	E 1/8 - 1/4 (0.127 mi.)	AW255 / 6	619
Database: AST, Date of Government Version: 09/25/2018 Facility Id: 9-601364				
COMPUSOURCE SYSTEMS,	110 JOHN MUIR DRIVE	E 1/8 - 1/4 (0.228 mi.)	331 / 5	764
Database: AST, Date of Government Version: 09/25/2018 Facility Id: 9-506362				

State and tribal institutional control / engineering control registries

NY ENG CONTROLS: Registry of Engineering Controls

A review of the NY ENG CONTROLS list, as provided by EDR, and dated 11/12/2018 has revealed that there is 1 NY ENG CONTROLS site within approximately 0.25 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
NORTHTOWN INC. Site Code: 502175	***3097 SHERIDAN DRIVE***	***E 1/8 - 1/4 (0.197 mi.)***	***BG303 / 6***	***676***

NY INST CONTROL: Registry of Institutional Controls

A review of the NY INST CONTROL list, as provided by EDR, and dated 11/12/2018 has revealed that there is 1 NY INST CONTROL site within approximately 0.25 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
NORTHTOWN INC. Site Code: 502175	***3097 SHERIDAN DRIVE***	***E 1/8 - 1/4 (0.197 mi.)***	***BG303 / 6***	***676***

State and tribal Brownfields sites

NY BROWNFIELDS: Brownfields Site List

A review of the NY BROWNFIELDS list, as provided by EDR, and dated 11/12/2018 has revealed that there is 1 NY BROWNFIELDS site within approximately 0.25 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
NORTHTOWN INC. Site Code: 502175	***3097 SHERIDAN DRIVE***	***E 1/8 - 1/4 (0.197 mi.)***	***BG303 / 6***	***676***

ADDITIONAL ENVIRONMENTAL RECORDS

Records of Emergency Release Reports

NY Spills: Spills Information Database

A review of the NY Spills list, as provided by EDR, and dated 11/12/2018 has revealed that there are 109 NY Spills sites within approximately 0.25 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
CAR FIRE Site ID: 439785 Spill Number/Closed Date: 1006430 / 2010-09-08	1009-1025 NIAGARA FA	E 0 - 1/8 (0.011 mi.)	L65 / 6	135
UNI-MART STORE Site ID: 64458	NIAGARA FALLS BLV &	E 0 - 1/8 (0.011 mi.)	R68 / 6	138

Spill Number/Closed Date: 9611103 / 1996-12-06				
FIRESTONE SERVICE CE	955 NIAGARA FALLS BL	E 0 - 1/8 (0.012 mi.)	N70 / 6	140
Site ID: 60504				
Spill Number/Closed Date: 9707595 / 1998-08-26				
BALL PUMP STATION &	***SWEET HOME RD***	***SE 0 - 1/8 (0.012 mi.)***	***U75 / 4***	***146***
Site ID: 529699				
Spill Number/Closed Date: 1603248 / 2016-07-06				
PINTO CONSTRUCTION	1193 SWEET HOME RD	SE 0 - 1/8 (0.012 mi.)	U76 / 4	148
Site ID: 529635				
Spill Number/Closed Date: 1603187 / 2016-09-15				
SWEETHOME JUNIOR HIG	***4150 MAPLE RD***	***N 0 - 1/8 (0.012 mi.)***	***V77 / 7***	***149***
Site ID: 373071				
Site ID: 309801				
Spill Number/Closed Date: 0608981 / 2007-03-09				
Spill Number/Closed Date: 9509066 / 1995-10-23				
SHELDON RESIDENCE	333 NIAGARA FALLS BL	E 0 - 1/8 (0.013 mi.)	79 / 8	154
Site ID: 198095				
Spill Number/Closed Date: 0175270 / 2001-09-17				
FORMER GAS STATION	895 NIAGARA FALLS BL	E 0 - 1/8 (0.013 mi.)	80 / 6	155
Site ID: 186488				
Spill Number/Closed Date: 0075336 / 2001-02-14				
MOBIL OIL 08-D5Y	MAIN STREET AT WINSP	NE 0 - 1/8 (0.013 mi.)	P81 / 8	157
Site ID: 196518				
Spill Number/Closed Date: 9607732 / 1998-06-29				
MOBIL	MAIN & KENMORE	NE 0 - 1/8 (0.013 mi.)	P82 / 8	158
Site ID: 211261				
Spill Number/Closed Date: 8708684 / 1988-01-14				
NATIONAL GRID	1084 NIAGARA FALLS B	W 0 - 1/8 (0.014 mi.)	85 / 6	160
Site ID: 457756				
Spill Number/Closed Date: 1109965 / 2012-02-02				
COMMERCIAL SITE	951 NIAGARA FALLS BV	ESE 0 - 1/8 (0.015 mi.)	N88 / 6	162
Site ID: 423840				
Spill Number/Closed Date: 0911057 / 2013-09-09				
AT & T CELL SITE	1201 SWEET HOME RD	SE 0 - 1/8 (0.015 mi.)	U91 / 4	164
Site ID: 444543				
Spill Number/Closed Date: 1010924 / 2011-02-01				
CARMELLA TERMULLO AN	853-855 NIAGARA FALL	E 0 - 1/8 (0.016 mi.)	X93 / 6	166
Site ID: 344352				
Spill Number/Closed Date: 0550174 / 2005-10-03				
POLE 851 - REAR PARK	853 NIAGARA FALLS BL	E 0 - 1/8 (0.016 mi.)	X94 / 6	168
Site ID: 435255				
Spill Number/Closed Date: 1002149 / 2010-08-23				
PEP BOYS #0193	***1025 NIAGARA FALLS B***	***E 0 - 1/8 (0.016 mi.)***	***Y99 / 6***	***178***
Site ID: 213584				
Spill Number/Closed Date: 9912271 / 2000-05-02				
NYSDOT PROJECT/U-HAU	925 NIAGARA FALLS BL	E 0 - 1/8 (0.017 mi.)	Z101 / 6	180
Site ID: 149280				
Spill Number/Closed Date: 9803568 / 1999-11-26				
FORMER UNI-MART	820 NIAGARA FALLS BL	W 0 - 1/8 (0.018 mi.)	R104 / 6	185

Site ID: 436572
Site ID: 114383
Site ID: 114384
Site ID: 114385
Site ID: 468578
**Additional key fields are available in the Map Findings section*
Spill Number/Closed Date: 1003350 / 2010-06-28
Spill Number/Closed Date: 9710897 / 1999-04-19
Spill Number/Closed Date: 9712476 / 2015-01-30
Spill Number/Closed Date: 9806636 / 1998-09-08
Spill Number/Closed Date: 1205616 / 2012-09-05
**Additional key fields are available in the Map Findings section*

SWEENEY'S GARAGE	***424 NIAGARA FALLS BL***	***W 0 - 1/8 (0.018 mi.)***	***AA108 / 8***	***204***
Site ID: 192729 Site ID: 192731 Site ID: 70227 Spill Number/Closed Date: 0075398 / 2000-12-05 Spill Number/Closed Date: 9975654 / 2000-01-24 Spill Number/Closed Date: 9306642 / 1993-09-03				
POPPLETON RESIDENCE	232 NIAGARA FALLS BL	W 0 - 1/8 (0.018 mi.)	T109 / 8	208
Site ID: 204989 Spill Number/Closed Date: 0375180 / 2003-07-01				
FIRESTONE STORES	***995 NIAGARA FALLS BL***	***E 0 - 1/8 (0.020 mi.)***	***L111 / 6***	***213***
Site ID: 126415 Spill Number/Closed Date: 0375288 / 2003-11-06				
AF AUTOMOTIVE	733 NIAGARA FALLS BL	E 0 - 1/8 (0.020 mi.)	AB117 / 6	227
Site ID: 338209 Spill Number/Closed Date: 0485611 / 2014-01-16				
CARUBA COLLISON	1167 NIAGARA FALLS B	E 0 - 1/8 (0.021 mi.)	AC118 / 6	233
Site ID: 272765 Spill Number/Closed Date: 9713614 / 1998-03-09				
PROULX RESIDENCE	383 NIAGARA FALLS BL	E 0 - 1/8 (0.021 mi.)	120 / 8	238
Site ID: 266963 Spill Number/Closed Date: 9206098 / 1992-09-29				
NOCO	4265 MAPLE ROAD	S 0 - 1/8 (0.023 mi.)	H121 / 7	239
Site ID: 391458 Spill Number/Closed Date: 0751262 / 2012-08-03				
POLE 1038	1038 SWEET HOME ROAD	SSE 0 - 1/8 (0.028 mi.)	125 / 7	247
Site ID: 369227 Spill Number/Closed Date: 0605954 / 2006-08-24				
GOODYEAR AUTO SERVIC	***1280 NIAGARA FALLS B***	***W 0 - 1/8 (0.029 mi.)***	***AD127 / 6***	***249***
Site ID: 151005 Site ID: 235738 Site ID: 235739 Spill Number/Closed Date: 9302662 / 1993-08-18 Spill Number/Closed Date: 9113171 / 1993-02-08 Spill Number/Closed Date: 9416566 / 1995-07-18				
KWIKFILL	***175 KENMORE AVE***	***SW 0 - 1/8 (0.030 mi.)***	***AE132 / 8***	***265***
Site ID: 375449 Spill Number/Closed Date: 0651775 / 2007-03-05				
AMHERST HIGHWAY DEPA	NORTH FOREST	ESE 0 - 1/8 (0.031 mi.)	B133 / 5	267

Site ID: 312884
Site ID: 312885
Spill Number/Closed Date: 0375126 / 2003-06-05
Spill Number/Closed Date: 9207862 / 1992-10-08

MONROE MUFFLER	2980 SHERIDAN DRIVE	W 0 - 1/8 (0.032 mi.)	AF135 / 6	270
Site ID: 84149				
Spill Number/Closed Date: 9514918 / 1996-02-26				
UNDERGROUND AUTOSOUN	2980 SHERIDAN DR	W 0 - 1/8 (0.032 mi.)	AF137 / 6	271
Site ID: 485692				
Spill Number/Closed Date: 1305137 / 2013-08-12				
ROW	MAIN AND KENMORE	NE 0 - 1/8 (0.033 mi.)	P138 / 8	273
Site ID: 334620				
Spill Number/Closed Date: 0485256 / 2005-11-03				
I/A/O 3 MALLARD CT	3 MALLARD CT	E 0 - 1/8 (0.036 mi.)	143 / 2	282
Site ID: 413540				
Spill Number/Closed Date: 0901545 / 2009-10-22				
MOBIL OIL	***2965 SHERIDAN DRIVE***	***W 0 - 1/8 (0.037 mi.)***	***AG146 / 6***	***288***
Site ID: 126282				
Site ID: 320413				
Spill Number/Closed Date: 0105744 / 2007-07-12				
Spill Number/Closed Date: 9007600 / 1991-03-04				
BURLINGTON TRUCK ROL	I290 & NIAGARA FALLS	E 0 - 1/8 (0.038 mi.)	147 / 8	299
Site ID: 81947				
Spill Number/Closed Date: 9875466 / 1999-07-28				
SWEENEY'S GARAGE	PAIGE AT NIAGARA FAL	E 0 - 1/8 (0.039 mi.)	148 / 8	300
Site ID: 177550				
Spill Number/Closed Date: 9006553 / 1990-09-24				
WRIGHT DRUM	4 HAWTHORNE AVENUE	W 0 - 1/8 (0.039 mi.)	149 / 8	302
Site ID: 85006				
Spill Number/Closed Date: 9309436 / 1993-11-02				
MCKAY HEATING PLANT	3545 MAIN ST.	NE 0 - 1/8 (0.039 mi.)	150 / 8	303
Site ID: 276528				
Spill Number/Closed Date: 0375429 / 2003-12-18				
BASIL FORD	MAIN STREET AT WINDE	SW 0 - 1/8 (0.043 mi.)	AH153 / 8	306
Site ID: 194002				
Spill Number/Closed Date: 9514248 / 1996-02-09				
FORMER BASIL FORD	MAIN & WINDEMERE AVE	SSW 0 - 1/8 (0.044 mi.)	AH154 / 8	307
Site ID: 214917				
Spill Number/Closed Date: 9514250 / 1996-03-21				
EZ MART	***4291 MAPLE RD***	***SE 0 - 1/8 (0.045 mi.)***	***AI156 / 7***	***309***
Site ID: 188796				
Site ID: 191332				
Site ID: 320877				
Spill Number/Closed Date: 9600093 / 1996-04-03				
Spill Number/Closed Date: 9811632 / 2007-06-13				
Spill Number/Closed Date: 8603239 / 1986-12-24				
MAPLE SUNOCO	4291 MAPLE RD	SE 0 - 1/8 (0.045 mi.)	AI158 / 7	324
Site ID: 483849				
Spill Number/Closed Date: 1303372 / 2014-10-22				
UNDERNEATH DISPENSER	1355 NIAGARA FALLS B	NNW 0 - 1/8 (0.050 mi.)	AK162 / 3	332

Site ID: 487257
Spill Number/Closed Date: 1306629 / 2014-01-08

SPILL NUMBER 8504373	1355 NIAGARA FALLS B	NNW 0 - 1/8 (0.050 mi.)	AK163 / 3	333
Site ID: 197383				
Spill Number/Closed Date: 8504373 / 1986-03-08				
DELTA SONIC - BOULEV	***1355 NIAGARA FALLS B***	***NNW 0 - 1/8 (0.050 mi.)***	***AK167 / 3***	***354***
Site ID: 361654				
Site ID: 303870				
Site ID: 303873				
Site ID: 303874				
Site ID: 412268				
**Additional key fields are available in the Map Findings section*				
Spill Number/Closed Date: 0514837 / 2006-06-22				
Spill Number/Closed Date: 0102552 / 2001-07-16				
Spill Number/Closed Date: 9406720 / 1994-08-17				
Spill Number/Closed Date: 9807773 / 1998-11-05				
Spill Number/Closed Date: 0900340 / 2009-04-10				
**Additional key fields are available in the Map Findings section*				
DELTA SONIC	1355 NIAGRA FALLS BL	NNW 0 - 1/8 (0.050 mi.)	AK168 / 3	367
Site ID: 517036				
Spill Number/Closed Date: 1508488 / 2015-11-17				
WASTE OIL	CHALMERS AND KETTERI	W 0 - 1/8 (0.053 mi.)	170 / 8	380
Site ID: 89678				
Spill Number/Closed Date: 9201318 / 1992-05-08				
WALGREENS PARKING LO	3488 MAIN STREET	SSW 0 - 1/8 (0.056 mi.)	AH175 / 8	388
Site ID: 526339				
Spill Number/Closed Date: 1601035 / 2016-05-02				
7-ELEVEN STORE #2249	3488 MAIN STREET	SSW 0 - 1/8 (0.056 mi.)	AH176 / 8	389
Site ID: 109271				
Spill Number/Closed Date: 9211094 / 2000-11-03				
LOUISE RING TANK	61 WREXHAM NORTH	W 0 - 1/8 (0.062 mi.)	178 / 6	442
Site ID: 70586				
Spill Number/Closed Date: 0075364 / 2000-12-20				
ELMER SPAETH	392 HOMECREST DRIVE	S 0 - 1/8 (0.066 mi.)	180 / 7	443
Site ID: 169910				
Spill Number/Closed Date: 8602464 / 1987-02-20				
ELLICOTT COMPLEX-FAR	HALL AREA	NNE 0 - 1/8 (0.066 mi.)	AN181 / 4	445
Site ID: 174611				
Spill Number/Closed Date: 9705442 / 2014-02-19				
SUNY AT BUFFALO	***MILLERSPORT HIGHWAY***	***NNE 0 - 1/8 (0.069 mi.)***	***AN187 / 4***	***466***
Site ID: 305371				
Spill Number/Closed Date: 9000336 / 1990-04-12				
GAS FROM CAR AT UB	SUNY AT BUFFALO	NW 0 - 1/8 (0.073 mi.)	AP192 / 8	476
Site ID: 287055				
Spill Number/Closed Date: 8806382 / 1988-10-31				
SUNY AT BUFFALO	ATCHISON HALL SUNYAB	NW 0 - 1/8 (0.073 mi.)	AP193 / 8	477
Site ID: 270837				
Spill Number/Closed Date: 8803631 / 1988-10-26				
SUNY AT BUFFALO	MAIN STREET	NW 0 - 1/8 (0.073 mi.)	AP194 / 8	478
Site ID: 263237				

Spill Number/Closed Date: 8706241 / 1987-10-23

PADMOUNT TRANSFORMER	ALMEDA AVE	E 0 - 1/8 (0.073 mi.)	195 / 6	479
Site ID: 366567				
Spill Number/Closed Date: 0603784 / 2006-09-26				
BUFFALO COLLEGE	3435 MAIN ST AT MAIN	NW 0 - 1/8 (0.073 mi.)	AP196 / 8	480
Site ID: 555346				
Spill Number/Closed Date: 1704127 / 2017-07-27				
UNIVERSITY OF BUFFAL	***3435 MAIN STREET***	***NW 0 - 1/8 (0.073 mi.)***	***AP200 / 8***	***489***
Site ID: 447891				
Site ID: 392627				
Site ID: 471011				
Site ID: 80790				
Site ID: 426298				
Spill Number/Closed Date: 1100485 / 2011-05-23				
Spill Number/Closed Date: 0711200 / 2009-01-23				
Spill Number/Closed Date: 1207951 / 2013-04-04				
Spill Number/Closed Date: 0075177 / 2000-10-18				
Spill Number/Closed Date: 0913360 / 2010-03-22				
UB - SOUTH CAMPUS	MAIN	NW 0 - 1/8 (0.075 mi.)	AP202 / 8	536
Site ID: 367454				
Spill Number/Closed Date: 0650660 / 2006-07-21				
OIL DUMPING AT ALLEN	441 ALLENHURST ROAD	E 0 - 1/8 (0.076 mi.)	203 / 8	537
Site ID: 139601				
Spill Number/Closed Date: 9007944 / 1990-11-08				
POLE 2109	2125 EGGERT RD	E 0 - 1/8 (0.084 mi.)	AQ210 / 6	549
Site ID: 372550				
Site ID: 371946				
Spill Number/Closed Date: 0608552 / 2006-10-27				
Spill Number/Closed Date: 0608071 / 2007-02-14				
SIDE OF ROAD	145 MAYER RD	N 0 - 1/8 (0.087 mi.)	AS214 / 3	559
Site ID: 388537				
Spill Number/Closed Date: 0707774 / 2007-10-16				
RESIDENCE	405 HOMECREST DRIVE	S 0 - 1/8 (0.099 mi.)	217 / 7	561
Site ID: 397121				
Spill Number/Closed Date: 0801231 / 2008-04-30				
NEW OPPORTUNITIES CO	245 HAWTHORNE AVE	W 0 - 1/8 (0.099 mi.)	218 / 8	562
Site ID: 370617				
Spill Number/Closed Date: 0607131 / 2007-01-19				
TRANSFORMER HIT BY L	205 DALTON DRIVE	W 0 - 1/8 (0.104 mi.)	219 / 6	565
Site ID: 365967				
Spill Number/Closed Date: 0603288 / 2007-01-09				
TRANSFORMER POLE 505	675 ALBERTA DR	S 0 - 1/8 (0.107 mi.)	AU223 / 6	569
Site ID: 501704				
Spill Number/Closed Date: 1408152 / 2015-01-22				
ON PROPERTY	3945 RENSCH ROAD	NW 0 - 1/8 (0.108 mi.)	AV225 / 4	572
Site ID: 410697				
Spill Number/Closed Date: 0813038 / 2009-04-02				
BOULEVARD TOWER APTS	120 MEYER ROAD	N 0 - 1/8 (0.112 mi.)	AS229 / 3	580
Site ID: 272753				
Site ID: 272754				

Spill Number/Closed Date: 9402661 / 1995-05-20
Spill Number/Closed Date: 9975361 / 2000-08-11

BUFFALO SUB 124 Site ID: 527126 Spill Number/Closed Date: 1601748 / 2018-08-15	78 ALMEDA DR.	E 0 - 1/8 (0.120 mi.)	232 / 6	587
PRINTS CHARMING Site ID: 323647 Spill Number/Closed Date: 9211378 / 1994-06-16	SHERIDAN & EGGERT RO	W 0 - 1/8 (0.121 mi.)	AX233 / 6	588
HANCOCK FABRICS Site ID: 61606 Spill Number/Closed Date: 0375473 / 2004-02-17	EGGERT AND SHERIDAN	W 0 - 1/8 (0.121 mi.)	AX234 / 6	590
UNIVERSITY OF BUFFAL Site ID: 120931 Spill Number/Closed Date: 8708045 / 1988-04-05	JARVIS HALL	N 0 - 1/8 (0.122 mi.)	AY235 / 4	591
SUNYAB - COOKE HALL Site ID: 182388 Spill Number/Closed Date: 0175123 / 2001-08-07	PUTNAM WAY	N 0 - 1/8 (0.122 mi.)	AY236 / 4	592
SUNYAB AMHERST TANK Site ID: 255359 Spill Number/Closed Date: 0075497 / 2001-02-23	MAPLE AND JOHN BEANE	N 0 - 1/8 (0.122 mi.)	AY237 / 4	593
TRUCK AT SUNY AMHERS Site ID: 123447 Spill Number/Closed Date: 9975668 / 2000-05-11	FRONTIER ROAD	N 0 - 1/8 (0.122 mi.)	AY238 / 4	595
SUNY BUFFALO NORTH C Site ID: 277089 Spill Number/Closed Date: 0101732 / 2001-11-08	SERVICE CENTER RD	N 0 - 1/8 (0.122 mi.)	AY241 / 4	599
SUNYAB-AMHERST Site ID: 146156 Spill Number/Closed Date: 9007861 / 1990-10-25	MILLERSPORT BUILDING	N 0 - 1/8 (0.122 mi.)	AY242 / 4	601
UB CAMPUS Site ID: 263707 Spill Number/Closed Date: 9207489 / 1992-10-20	SKINNERSVILLE ROAD	N 0 - 1/8 (0.122 mi.)	AY243 / 4	602
BLUE BIRD BUS LINE Site ID: 149662 Spill Number/Closed Date: 8805153 / 1988-09-21	SUNY AMHERST CAMPUS	N 0 - 1/8 (0.122 mi.)	AY244 / 4	603
SUNY AT BUFFALO Site ID: 158489 Spill Number/Closed Date: 0206015 / 2002-09-11	FRONTIER ST	N 0 - 1/8 (0.122 mi.)	AY249 / 4	609
NYS SUNY CAMPUS Site ID: 120930 Spill Number/Closed Date: 0104381 / 2002-02-19	JARVIS HALL	N 0 - 1/8 (0.122 mi.)	AY250 / 4	610
TRUCK AT LASERTRON P Site ID: 252173 Spill Number/Closed Date: 9713482 / 1998-03-31	5101 NORTH BAILEY/MA	N 1/8 - 1/4 (0.141 mi.)	263 / 4	629
JACK HANNON Site ID: 181495 Spill Number/Closed Date: 0475296 / 2004-09-23	190 MARGARET RD	E 1/8 - 1/4 (0.154 mi.)	268 / 6	637
OLD BURGER KING Site ID: 272355	1420 NIAGARA FALLS B	NNW 1/8 - 1/4 (0.158 mi.)	269 / 3	638

Spill Number/Closed Date: 0275298 / 2002-11-27

RESIDENTIAL Site ID: 565512 Spill Number/Closed Date: 1709075 / 2018-01-03	151 CAPEN BLVD	E 1/8 - 1/4 (0.160 mi.)	270 / 8	639
BENDERSON DEVELOPEME Site ID: 565758 Spill Number/Closed Date: 1709316 / 2018-02-26	3608 MAIN STREET	NE 1/8 - 1/4 (0.161 mi.)	BB271 / 8	640
NIAGARA MOHAWK - LYN Site ID: 255660 Spill Number/Closed Date: 9505191 / 1995-09-07	123 LYNDALE AVENUE	W 1/8 - 1/4 (0.162 mi.)	BC272 / 8	641
NOCO ENERGY Site ID: 230969 Spill Number/Closed Date: 9010521 / 1991-02-13	82 TREADWELL ROAD	W 1/8 - 1/4 (0.162 mi.)	274 / 6	642
BJ'S WHOLESALE CLUB Site ID: 507061 Spill Number/Closed Date: 1500888 / 2015-07-14	3080 SHERIDAN DR	E 1/8 - 1/4 (0.164 mi.)	276 / 6	644
SEPTIC TANK FAILURE Site ID: 252578 Spill Number/Closed Date: 9602794 / 1996-05-30	4140 RENSCH ROAD	W 1/8 - 1/4 (0.178 mi.)	284 / 4	654
TANK AT LINDKE RESID Site ID: 60628 Spill Number/Closed Date: 9614121 / 1997-04-29	25 QUAKER RIDGE	W 1/8 - 1/4 (0.178 mi.)	285 / 6	655
BASEMENT Site ID: 478005 Spill Number/Closed Date: 1214739 / 2013-01-28	8 RADCLIFFE RD.	SSW 1/8 - 1/4 (0.180 mi.)	286 / 8	656
UNION CONCRETE CO. Site ID: 389743 Spill Number/Closed Date: 0751095 / 2008-01-30	451 MEYERS RD	WNW 1/8 - 1/4 (0.186 mi.)	288 / 4	657
BOULEVARD INN & SUIT Site ID: 401060 Spill Number/Closed Date: 0890608 / 2008-11-05	3612 MAIN ST.	NE 1/8 - 1/4 (0.195 mi.)	298 / 8	668
HOUSE Site ID: 348203 Spill Number/Closed Date: 0550518 / 2005-06-28	2699 NORTH FOREST RO	WSW 1/8 - 1/4 (0.195 mi.)	299 / 2	669
COLD PARTS CLEANER Site ID: 123586 Spill Number/Closed Date: 9205916 / 1992-08-24	1435 NIAGARA FALLS B	NNW 1/8 - 1/4 (0.196 mi.)	BH301 / 3	671
NORTHTOWN INC. Site ID: 494691 Spill Number/Closed Date: 1401409 / 2015-02-20	***3097 SHERIDAN DRIVE***	***E 1/8 - 1/4 (0.197 mi.)***	***BG303 / 6***	***676***
UNITED CEREBRAL PALS Site ID: 181709 Spill Number/Closed Date: 0207321 / 2002-11-26	2360 NORTH FOREST	ESE 1/8 - 1/4 (0.206 mi.)	306 / 5	723
GOVERNORS HALL AT UN Site ID: 572221 Spill Number/Closed Date: 1803562 / 2018-07-02	WHITE AND HADLEY RD	N 1/8 - 1/4 (0.214 mi.)	310 / 4	728
NATIONAL GRID POLE 2 Site ID: 577166 Spill Number/Closed Date: 1806439 / Not Reported	2352 EGGERT RD	W 1/8 - 1/4 (0.218 mi.)	316 / 6	737
BALL PUMP STATION	***SWEET HOME ROAD***	***NNW 1/8 - 1/4 (0.218 mi.)***	***BJ317 / 4***	***738***

Site ID: 149087 Spill Number/Closed Date: 0375269 / 2003-11-03				
HOUSE Site ID: 387060 Spill Number/Closed Date: 0750834 / 2007-09-12	381 WINDERMERE	E 1/8 - 1/4 (0.220 mi.)	329 / 8	762
MEL OTT BALL FIELD Site ID: 212706 Spill Number/Closed Date: 9201608 / 1992-05-21	MEYER ROAD	WNW 1/8 - 1/4 (0.229 mi.)	332 / 4	766
WASTE OIL IN YARD Site ID: 277197 Spill Number/Closed Date: 9401679 / 1994-05-06	224 UNIVERSITY AVENU	W 1/8 - 1/4 (0.231 mi.)	333 / 8	767
NOCO TRUCK Site ID: 177453 Spill Number/Closed Date: 9975577 / 1999-12-13	216 NORTH WREXHAM	W 1/8 - 1/4 (0.243 mi.)	338 / 6	773
NATIONAL GRID Site ID: 506207 Spill Number/Closed Date: 1500074 / 2015-07-13	311 MEYER RD	N 1/8 - 1/4 (0.245 mi.)	339 / 4	774
SEAN MAGIERSKI RESID Site ID: 534966 Spill Number/Closed Date: 1607324 / 2016-10-26	73 MONTROSE AVE	SW 1/8 - 1/4 (0.246 mi.)	342 / 8	779
WHITE CRYSTALLINE MA Site ID: 287702 Spill Number/Closed Date: 9502446 / 2000-12-13	674 HARRISON STREET	W 1/8 - 1/4 (0.250 mi.)	346 / 6	785

Other Ascertainable Records

RCRA NonGen / NLR: RCRA - Non Generators / No Longer Regulated

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 03/01/2018 has revealed that there are 21 RCRA NonGen / NLR sites within approximately 0.25 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
PEP BOYS - MANNY MOE EPA ID:: NY0000362657	***1025 NIAGARA FALLS B***	***E 0 - 1/8 (0.016 mi.)***	***Y98 / 6***	***175***
BRIDGESTONE FIRESTON EPA ID:: NYD987009016	***995 NIAGARA FALLS BL***	***E 0 - 1/8 (0.020 mi.)***	***L113 / 6***	***218***
A F AUTOMOTIVE EPA ID:: NYD986912830	***733 NIAGARA FALLS BL***	***E 0 - 1/8 (0.020 mi.)***	***AB114 / 6***	***220***
KWIK FILL MO325.325 EPA ID:: NYD986955151	***175 KENMORE AVE***	***SW 0 - 1/8 (0.030 mi.)***	***AE130 / 8***	***258***
MONRO MUFFLER BRAKE EPA ID:: NYD162544241	***2980 SHERIDAN DR***	***W 0 - 1/8 (0.035 mi.)***	***AF142 / 6***	***278***
STATION 124 EPA ID:: NYD980783351	***48 ALMEDA DR***	***E 0 - 1/8 (0.049 mi.)***	***AJ161 / 6***	***330***
DELTA SONIC - BOULEV EPA ID:: NYD986907996	***1355 NIAGARA FALLS B***	***NNW 0 - 1/8 (0.050 mi.)***	***AK167 / 3***	***354***
7-ELEVEN #22491	***3488 MAIN ST***	***SSW 0 - 1/8 (0.056 mi.)***	***AH173 / 8***	***385***

EPA ID:: NYD986898534				
STATE UNIVERSTIY CON EPA ID:: NYD980780258	SUNY AT BUFFALO 3435	NW 0 - 1/8 (0.067 mi.)	AP186 / 8	464
MARTY'S AUTOPRO CENT EPA ID:: NYD986981397	***2131 EGGERT RD***	***E 0 - 1/8 (0.071 mi.)***	***AQ191 / 6***	***471***
HONEYWELL INC EPA ID:: NYR000014944	***251 JOHN JAMES AUDUB***	***SW 0 - 1/8 (0.078 mi.)***	***206 / 2***	***541***
BAUGHMAN MAGIC SEAL EPA ID:: NYR000219659	44 MEYER RD	N 1/8 - 1/4 (0.131 mi.)	AZ259 / 3	624
STS CAR SVC CTR EPA ID:: NYD986966976	***1435 NIAGARA FALLS B***	***NNW 1/8 - 1/4 (0.153 mi.)***	***BA267 / 3***	***633***
NORTHTOWN ONE HOUR C EPA ID:: NYD045166667	***3077 SHERIDAN DR***	***E 1/8 - 1/4 (0.192 mi.)***	***BG297 / 6***	***664***
NORTHTOWN INC EPA ID:: NYR000013375	***3097 SHERIDAN DR***	***E 1/8 - 1/4 (0.197 mi.)***	***BG302 / 6***	***672***
WORLD AUTO PAINTING EPA ID:: NYD121947063	***2880 SHERIDAN DR***	***W 1/8 - 1/4 (0.201 mi.)***	***305 / 6***	***720***
NATIONAL FUEL GAS CO EPA ID:: NYD982791014	***104 LONGMEADOW AVE***	***E 1/8 - 1/4 (0.215 mi.)***	***311 / 6***	***729***
AMHERST CUSTOM CHEMI EPA ID:: NYR000124230	1576 SWEET HOME RD -	NNW 1/8 - 1/4 (0.219 mi.)	BJ318 / 4	740
UNIVERSITY AT BUFFAL EPA ID:: NYR000100883	***1576 SWEET HOME RD***	***NNW 1/8 - 1/4 (0.219 mi.)***	***BJ323 / 4***	***752***
LASER PHOTONICS TECH EPA ID:: NYR000054650	***1576 SWEET HOME RD R***	***NNW 1/8 - 1/4 (0.219 mi.)***	***BJ325 / 4***	***755***
PRINCETON HOUSING AS EPA ID:: NYD038630554	***165 PRINCETON AVE***	***NNE 1/8 - 1/4 (0.245 mi.)***	***340 / 8***	***775***

ICIS: Integrated Compliance Information System

A review of the ICIS list, as provided by EDR, and dated 11/18/2016 has revealed that there are 3 ICIS sites within approximately 0.25 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
HERRSCHER'S EXPRESS FRS ID:: 110037232410	***4291 MAPLE ROAD***	***SE 0 - 1/8 (0.045 mi.)***	***AI155 / 7***	***308***
SUNY AT BUFFALO - SO FRS ID:: 110000880100	***3435 MAIN STREET***	***NW 0 - 1/8 (0.073 mi.)***	***AP199 / 8***	***487***
GI-RO DRY CLEANERS FRS ID:: 110004355705	***3077 SHERIDAN DR?NOR***	***E 1/8 - 1/4 (0.192 mi.)***	***BG294 / 6***	***660***

EXECUTIVE SUMMARY

US AIRS: Aerometric Information Retrieval System Facility Subsystem

A review of the US AIRS list, as provided by EDR, has revealed that there are 4 US AIRS sites within approximately 0.25 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
CORSI AUTO BODY AND Database: US AIRS MINOR, Date of Government Version: 10/12/2016 EPA plant ID:: 110019656521	874 NIAGARA FALLS BL	W 0 - 1/8 (0.015 mi.)	W86 / 6	161
DELTA SONIC - BOULEV Database: US AIRS MINOR, Date of Government Version: 10/12/2016 EPA plant ID:: 110004450460	***1355 NIAGARA FALLS B***	***NNW 0 - 1/8 (0.050 mi.)***	***AK167 / 3***	***354***
STATE UNIVERSITY OF Database: US AIRS (AFS), Date of Government Version: 10/12/2016 EPA plant ID:: 110000880100	***3435 MAIN ST***	***NW 0 - 1/8 (0.073 mi.)***	***AP201 / 8***	***498***
GI-RO DRY CLEANERS Database: US AIRS MINOR, Date of Government Version: 10/12/2016	***3077 SHERIDAN DR?NOR***	***E 1/8 - 1/4 (0.192 mi.)***	***BG294 / 6***	***660***

FINDS: Facility Index System/Facility Registry System

A review of the FINDS list, as provided by EDR, and dated 08/07/2018 has revealed that there are 55 FINDS sites within approximately 0.25 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
CVS PHARMACY #1227 Registry ID:: 110045410765	***520 LEE ENTRANCE U-B***	***E 0 - 1/8 (0.011 mi.)***	***Q63 / 5***	***134***
NYSDOT BIN 1-07260-2 Registry ID:: 110008107039	***I290 NB BRG OVER SWE***	***ESE 0 - 1/8 (0.011 mi.)***	***D64 / 4***	***135***
SIBLEYS Registry ID:: 110019259933	BLVD MALL 1255 NIAG	E 0 - 1/8 (0.014 mi.)	83 / 6	159
AMHERST POLICE SECUR Registry ID:: 110064397013	350 JOHN JAMES AUDUB	ENE 0 - 1/8 (0.014 mi.)	84 / 2	159
CORSI AUTO BODY AND Registry ID:: 110019656521	***874 NIAGARA FALLS BL***	***W 0 - 1/8 (0.015 mi.)***	***W87 / 6***	***161***
AMHERST MEDICAL CENT Registry ID:: 110012159537	1185 SWEET HOME RD	ESE 0 - 1/8 (0.015 mi.)	C90 / 4	164
PEP BOYS - MANNY MOE Registry ID:: 110004316124	***1025 NIAGARA FALLS B***	***E 0 - 1/8 (0.016 mi.)***	***Y98 / 6***	***175***
BRIDGESTONE FIRESTON Registry ID:: 110004492718	***995 NIAGARA FALLS BL***	***E 0 - 1/8 (0.020 mi.)***	***L113 / 6***	***218***
A F AUTOMOTIVE Registry ID:: 110004452814	***733 NIAGARA FALLS BL***	***E 0 - 1/8 (0.020 mi.)***	***AB114 / 6***	***220***
NOCO EXPRESS # 24 Registry ID:: 110043256357	4265 MAPLE ROAD	S 0 - 1/8 (0.023 mi.)	H124 / 7	246
GOODYEAR AUTO SERVIC Registry ID:: 110004384069	***1280 NIAGARA FALLS B***	***W 0 - 1/8 (0.029 mi.)***	***AD127 / 6***	***249***
KWIK FILL MO325.325 Registry ID:: 110004468086	***175 KENMORE AVE***	***SW 0 - 1/8 (0.030 mi.)***	***AE130 / 8***	***258***
COMMERCIAL DEVELOPME	4080-4120 MAPLE RD	N 0 - 1/8 (0.034 mi.)	141 / 4	278

Registry ID:: 110023022851				
MONRO MUFFLER BRAKE Registry ID:: 110004385433	***2980 SHERIDAN DR***	***W 0 - 1/8 (0.035 mi.)***	***AF142 / 6***	***278***
MOBIL OIL CROP SS H4 Registry ID:: 110004470117	***2965 SHERIDAN DR***	***W 0 - 1/8 (0.037 mi.)***	***AG145 / 6***	***284***
HERRSCHER'S EXPRESS Registry ID:: 110064416421 Registry ID:: 110037232410	***4291 MAPLE ROAD***	***SE 0 - 1/8 (0.045 mi.)***	***AI155 / 7***	***308***
STATION 124 Registry ID:: 110004392648	***48 ALMEDA DR***	***E 0 - 1/8 (0.049 mi.)***	***AJ161 / 6***	***330***
DELTA SONIC - BOULEV Registry ID:: 110004450460	***1355 NIAGARA FALLS B***	***NNW 0 - 1/8 (0.050 mi.)***	***AK167 / 3***	***354***
GOOD YEAR TIRE Registry ID:: 110042346397	200 JOHN JAMES AUDUB	NE 0 - 1/8 (0.056 mi.)	171 / 2	381
7-ELEVEN #22491 Registry ID:: 110004445672	***3488 MAIN ST***	***SSW 0 - 1/8 (0.056 mi.)***	***AH173 / 8***	***385***
FKQ CONFERENCE CENTE Registry ID:: 110019717895	2401 N FOREST RD	ESE 0 - 1/8 (0.062 mi.)	AM179 / 5	443
BASIL FORD Registry ID:: 110000875198	***3484 MAIN ST***	***S 0 - 1/8 (0.066 mi.)***	***AO184 / 8***	***460***
MARTY'S AUTOPRO CENT Registry ID:: 110004480197	***2131 EGGERT RD***	***E 0 - 1/8 (0.071 mi.)***	***AQ191 / 6***	***471***
SUNY AT BUFFALO - SO Registry ID:: 110000880100	***3435 MAIN STREET***	***NW 0 - 1/8 (0.073 mi.)***	***AP199 / 8***	***487***
HONEYWELL INC Registry ID:: 110004519398	***251 JOHN JAMES AUDUB***	***SW 0 - 1/8 (0.078 mi.)***	***206 / 2***	***541***
STATE UNIVERSTIY CON Registry ID:: 110004392416	***SUNY AT BUFFALO 3435***	***NW 0 - 1/8 (0.080 mi.)***	***AP207 / 8***	***545***
BYE BYE BABY #3083 Registry ID:: 110059662618	***1261 NIAGARA FALLS B***	***E 0 - 1/8 (0.084 mi.)***	***AR212 / 6***	***556***
SEARS #1162 Registry ID:: 110038898967	***1261 NIAGARA FALLS B***	***E 0 - 1/8 (0.084 mi.)***	***AR213 / 6***	***558***
WEGMANS #0082 Registry ID:: 110031306664	***675 ALBERTA DR***	***S 0 - 1/8 (0.107 mi.)***	***AU222 / 6***	***569***
CRYSTAL KIMMONS Registry ID:: 110070107677	***605 NATURAL SCIENCE***	***NNE 0 - 1/8 (0.109 mi.)***	***226 / 4***	***573***
CONFERENCE CENTER CO Registry ID:: 110017754759	***2390 FOREST ROAD***	***ESE 0 - 1/8 (0.111 mi.)***	***228 / 5***	***580***
BJS WHOLESALE CLUB # Registry ID:: 110046537048	***3056 SHERIDAN DR***	***E 1/8 - 1/4 (0.127 mi.)***	***AW256 / 6***	***621***
BAUGHMAN MAGIC SEAL Registry ID:: 110064675178	***44 MEYER RD***	***N 1/8 - 1/4 (0.131 mi.)***	***AZ261 / 3***	***628***
RENSCH ROAD RESEARCH Registry ID:: 110019730380	4080 RENSCH ROAD	NW 1/8 - 1/4 (0.141 mi.)	262 / 4	628
STS CAR SVC CTR Registry ID:: 110004474382	***1435 NIAGARA FALLS B***	***NNW 1/8 - 1/4 (0.153 mi.)***	***BA267 / 3***	***633***
KADIMAH SCHOOL OF BU	2675 NORTH FOREST RD	WSW 1/8 - 1/4 (0.163 mi.)	275 / 2	643

Registry ID:: 110019254064				
JEWISH COMMUNITY CEN Registry ID:: 110028138628	***2640 NORTH FOREST RO***	***WSW 1/8 - 1/4 (0.165 mi.)***	***277 / 2***	***645***
ADVANCE AUTO PARTS # Registry ID:: 110070205816	***2907 SHERIDAN DR***	***W 1/8 - 1/4 (0.172 mi.)***	***BD280 / 6***	***648***
SAVERS STORE #1217 Registry ID:: 110004400826	***2309 EGGERT RD***	***W 1/8 - 1/4 (0.176 mi.)***	***BE281 / 6***	***649***
NORTHTOWN ONE HOUR C Registry ID:: 110004355705	***3077 SHERIDAN DR***	***E 1/8 - 1/4 (0.192 mi.)***	***BG297 / 6***	***664***
NORTHTOWN INC Registry ID:: 110000882386	***3097 SHERIDAN DR***	***E 1/8 - 1/4 (0.197 mi.)***	***BG302 / 6***	***672***
WORLD AUTO PAINTING Registry ID:: 110004381874	***2880 SHERIDAN DR***	***W 1/8 - 1/4 (0.201 mi.)***	***305 / 6***	***720***
NATIONAL FUEL GAS CO Registry ID:: 110004433649	***104 LONGMEADOW AVE***	***E 1/8 - 1/4 (0.215 mi.)***	***311 / 6***	***729***
AMHERST CSD - WINDER Registry ID:: 110063000782	***291 WINDERMERE BLVD***	***E 1/8 - 1/4 (0.218 mi.)***	***BI313 / 8***	***732***
ONY BIOTECH Registry ID:: 110019775037	***1576 SWEET HOME ROAD***	***NNW 1/8 - 1/4 (0.219 mi.)***	***BJ319 / 4***	***744***
AMHERST CUSTOM CHEMI Registry ID:: 110017776450	***1576 SWEET HOME RD -***	***NNW 1/8 - 1/4 (0.219 mi.)***	***BJ320 / 4***	***744***
FERRIC CONTRAST INC Registry ID:: 110012253211	***1576 SWEET HOME RD R***	***NNW 1/8 - 1/4 (0.219 mi.)***	***BJ322 / 4***	***745***
UNIVERSITY AT BUFFAL Registry ID:: 110012241911	***1576 SWEET HOME RD***	***NNW 1/8 - 1/4 (0.219 mi.)***	***BJ323 / 4***	***752***
LASER PHOTONICS TECH Registry ID:: 110004543101	***1576 SWEET HOME RD R***	***NNW 1/8 - 1/4 (0.219 mi.)***	***BJ325 / 4***	***755***
DIMIEN LLC Registry ID:: 110004459504	***1576 SWEET HOME RD S***	***NNW 1/8 - 1/4 (0.219 mi.)***	***BJ326 / 4***	***759***
SQUIRREL FREE INCORP Registry ID:: 110011484429	1576 SWEET HOME ROAD	NNW 1/8 - 1/4 (0.219 mi.)	BJ328 / 4	762
NYSDOT BIN 1001590 Registry ID:: 110008066172	***MAIN ST OVER NY RT 1***	***WSW 1/8 - 1/4 (0.233 mi.)***	***335 / 8***	***768***
DICKS SPORTING GOODS Registry ID:: 110067044576	***281 MEYER RD***	***N 1/8 - 1/4 (0.239 mi.)***	***BK336 / 4***	***769***
PRINCETON HOUSING AS Registry ID:: 110004353404	***165 PRINCETON AVE***	***NNE 1/8 - 1/4 (0.245 mi.)***	***340 / 8***	***775***
ELLICOTT CREEK FLOOD Registry ID:: 110019180394	2350 NORTH FOREST RO	ESE 1/8 - 1/4 (0.248 mi.)	BL344 / 5	780

ECHO: Enforcement & Compliance History Information

A review of the ECHO list, as provided by EDR, and dated 09/02/2018 has revealed that there are 44 ECHO sites within approximately 0.25 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
CVS PHARMACY #1227	***520 LEE ENTRANCE U-B***	***E 0 - 1/8 (0.011 mi.)***	***Q63 / 5***	***134***

Registry ID: 110045410765				
NYSDOT BIN 1-07260-2 Registry ID: 110008107039	***I290 NB BRG OVER SWE***	***ESE 0 - 1/8 (0.011 mi.)***	***D64 / 4***	***135***
CORSI AUTO BODY AND Registry ID: 110019656521	***874 NIAGARA FALLS BL***	***W 0 - 1/8 (0.015 mi.)***	***W87 / 6***	***161***
PEP BOYS - MANNY MOE Registry ID: 110004316124	***1025 NIAGARA FALLS B***	***E 0 - 1/8 (0.016 mi.)***	***Y98 / 6***	***175***
BRIDGESTONE FIRESTON Registry ID: 110004492718	***995 NIAGARA FALLS BL***	***E 0 - 1/8 (0.020 mi.)***	***L113 / 6***	***218***
A F AUTOMOTIVE Registry ID: 110004452814	***733 NIAGARA FALLS BL***	***E 0 - 1/8 (0.020 mi.)***	***AB114 / 6***	***220***
GOODYEAR AUTO SERVIC Registry ID: 110004384069	***1280 NIAGARA FALLS B***	***W 0 - 1/8 (0.029 mi.)***	***AD127 / 6***	***249***
KWIK FILL MO325.325 Registry ID: 110004468086	***175 KENMORE AVE***	***SW 0 - 1/8 (0.030 mi.)***	***AE130 / 8***	***258***
MONRO MUFFLER BRAKE Registry ID: 110004385433	***2980 SHERIDAN DR***	***W 0 - 1/8 (0.035 mi.)***	***AF142 / 6***	***278***
MOBIL OIL CROP SS H4 Registry ID: 110004470117	***2965 SHERIDAN DR***	***W 0 - 1/8 (0.037 mi.)***	***AG145 / 6***	***284***
HERRSCHER'S EXPRESS Registry ID: 110037232410	***4291 MAPLE ROAD***	***SE 0 - 1/8 (0.045 mi.)***	***AI155 / 7***	***308***
STATION 124 Registry ID: 110004392648	***48 ALMEDA DR***	***E 0 - 1/8 (0.049 mi.)***	***AJ161 / 6***	***330***
DELTA SONIC CAR WASH Registry ID: 110004450460	1355 NIAGARA FALLS B	NNW 0 - 1/8 (0.050 mi.)	AK164 / 3	334
7-ELEVEN #22491 Registry ID: 110004445672	***3488 MAIN ST***	***SSW 0 - 1/8 (0.056 mi.)***	***AH173 / 8***	***385***
BASIL FORD Registry ID: 110000875198	***3484 MAIN ST***	***S 0 - 1/8 (0.066 mi.)***	***AO184 / 8***	***460***
MARTY'S AUTOPRO CENT Registry ID: 110004480197	***2131 EGGERT RD***	***E 0 - 1/8 (0.071 mi.)***	***AQ191 / 6***	***471***
SUNY AT BUFFALO - SO Registry ID: 110000880100	***3435 MAIN STREET***	***NW 0 - 1/8 (0.073 mi.)***	***AP199 / 8***	***487***
HONEYWELL INC Registry ID: 110004519398	***251 JOHN JAMES AUDUB***	***SW 0 - 1/8 (0.078 mi.)***	***206 / 2***	***541***
STATE UNIVERSTIY CON Registry ID: 110004392416	***SUNY AT BUFFALO 3435***	***NW 0 - 1/8 (0.080 mi.)***	***AP207 / 8***	***545***
BYE BYE BABY #3083 Registry ID: 110059662618	***1261 NIAGARA FALLS B***	***E 0 - 1/8 (0.084 mi.)***	***AR212 / 6***	***556***
SEARS #1162 Registry ID: 110038898967	***1261 NIAGARA FALLS B***	***E 0 - 1/8 (0.084 mi.)***	***AR213 / 6***	***558***
WEGMANS #0082 Registry ID: 110031306664	***675 ALBERTA DR***	***S 0 - 1/8 (0.107 mi.)***	***AU222 / 6***	***569***
CRYSTAL KIMMONS Registry ID: 110070107677	***605 NATURAL SCIENCE***	***NNE 0 - 1/8 (0.109 mi.)***	***226 / 4***	***573***
CONFERENCE CENTER CO	***2390 FOREST ROAD***	***ESE 0 - 1/8 (0.111 mi.)***	***228 / 5***	***580***

Registry ID: 110017754759				
BJS WHOLESALE CLUB # Registry ID: 110046537048	***3056 SHERIDAN DR***	***E 1/8 - 1/4 (0.127 mi.)***	***AW256 / 6***	***621***
BAUGHMAN MAGIC SEAL Registry ID: 110064675178	***44 MEYER RD***	***N 1/8 - 1/4 (0.131 mi.)***	***AZ261 / 3***	***628***
STS CAR SVC CTR Registry ID: 110004474382	***1435 NIAGARA FALLS B***	***NNW 1/8 - 1/4 (0.153 mi.)***	***BA267 / 3***	***633***
JEWISH COMMUNITY CEN Registry ID: 110028138628	***2640 NORTH FOREST RO***	***WSW 1/8 - 1/4 (0.165 mi.)***	***277 / 2***	***645***
ADVANCE AUTO PARTS # Registry ID: 110070205816	***2907 SHERIDAN DR***	***W 1/8 - 1/4 (0.172 mi.)***	***BD280 / 6***	***648***
SAVERS STORE #1217 Registry ID: 110004400826	***2309 EGGERT RD***	***W 1/8 - 1/4 (0.176 mi.)***	***BE281 / 6***	***649***
NORTHTOWN ONE HOUR C Registry ID: 110004355705	***3077 SHERIDAN DR***	***E 1/8 - 1/4 (0.192 mi.)***	***BG297 / 6***	***664***
NORTHTOWN INC Registry ID: 110000882386	***3097 SHERIDAN DR***	***E 1/8 - 1/4 (0.197 mi.)***	***BG302 / 6***	***672***
WORLD AUTO PAINTING Registry ID: 110004381874	***2880 SHERIDAN DR***	***W 1/8 - 1/4 (0.201 mi.)***	***305 / 6***	***720***
NATIONAL FUEL GAS CO Registry ID: 110004433649	***104 LONGMEADOW AVE***	***E 1/8 - 1/4 (0.215 mi.)***	***311 / 6***	***729***
AMHERST CSD - WINDER Registry ID: 110063000782	***291 WINDERMERE BLVD***	***E 1/8 - 1/4 (0.218 mi.)***	***BI313 / 8***	***732***
ONY BIOTECH Registry ID: 110019775037	***1576 SWEET HOME ROAD***	***NNW 1/8 - 1/4 (0.219 mi.)***	***BJ319 / 4***	***744***
AMHERST CUSTOM CHEMI Registry ID: 110017776450	***1576 SWEET HOME RD -***	***NNW 1/8 - 1/4 (0.219 mi.)***	***BJ320 / 4***	***744***
UNIVERSITY AT BUFFAL Registry ID: 110012241911	***1576 SWEET HOME RD***	***NNW 1/8 - 1/4 (0.219 mi.)***	***BJ323 / 4***	***752***
FERRIC CONTRAST INC Registry ID: 110012253211	1576 SWEET HOME RD R	NNW 1/8 - 1/4 (0.219 mi.)	BJ324 / 4	755
LASER PHOTONICS TECH Registry ID: 110004543101	***1576 SWEET HOME RD R***	***NNW 1/8 - 1/4 (0.219 mi.)***	***BJ325 / 4***	***755***
DIMIEN LLC Registry ID: 110004459504	***1576 SWEET HOME RD S***	***NNW 1/8 - 1/4 (0.219 mi.)***	***BJ326 / 4***	***759***
NYSDOT BIN 1001590 Registry ID: 110008066172	***MAIN ST OVER NY RT 1***	***WSW 1/8 - 1/4 (0.233 mi.)***	***335 / 8***	***768***
DICKS SPORTING GOODS Registry ID: 110067044576	***281 MEYER RD***	***N 1/8 - 1/4 (0.239 mi.)***	***BK336 / 4***	***769***
PRINCETON HOUSING AS Registry ID: 110004353404	***165 PRINCETON AVE***	***NNE 1/8 - 1/4 (0.245 mi.)***	***340 / 8***	***775***

EXECUTIVE SUMMARY

NY AIRS: Air Emissions Data

A review of the NY AIRS list, as provided by EDR, and dated 11/06/2018 has revealed that there are 2 NY AIRS sites within approximately 0.25 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
SUNY AT BUFFALO - SO DEC Id: 9140200680	***3435 MAIN ST***	***NW 0 - 1/8 (0.073 mi.)***	***AP197 / 8***	***481***
ONY INC DEC Id: 9142200207	1576 SWEET HOME ROAD	NNW 1/8 - 1/4 (0.219 mi.)	BJ327 / 4	761

NY DRYCLEANERS: Registered Drycleaners

A review of the NY DRYCLEANERS list, as provided by EDR, and dated 03/07/2018 has revealed that there is 1 NY DRYCLEANERS site within approximately 0.25 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
GI-RO/NORTHTOWN CLEA Facility Id: 9-1422-00286	3077 SHERIDAN DRIVE,	E 1/8 - 1/4 (0.192 mi.)	BG296 / 6	664

NY HSWDS: Hazardous Substance Waste Disposal Site Inventory

A review of the NY HSWDS list, as provided by EDR, and dated 01/01/2003 has revealed that there is 1 NY HSWDS site within approximately 0.25 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
MORRIS AND REIMAN WR	3900 RENSCH RD.	NW 0 - 1/8 (0.078 mi.)	205 / 4	540

NY MANIFEST: Facility and Manifest Data

A review of the NY MANIFEST list, as provided by EDR, and dated 10/01/2018 has revealed that there are 29 NY MANIFEST sites within approximately 0.25 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
CVS PHARMACY #1227 EPA ID: NYR000192013	***520 LEE ENTRANCE***	***E 0 - 1/8 (0.011 mi.)***	***Q61 / 5***	***120***
BALL PUMP STATION & EPA ID: NYR000130872	***SWEET HOME RD***	***SE 0 - 1/8 (0.012 mi.)***	***U75 / 4***	***146***
PEP BOYS - MANNY MOE EPA ID: NY0000362657	***1025 NIAGARA FALLS B***	***E 0 - 1/8 (0.016 mi.)***	***Y98 / 6***	***175***
FIRESTONE STORES EPA ID: NYP000863829	***995 NIAGARA FALLS BL***	***E 0 - 1/8 (0.020 mi.)***	***L111 / 6***	***213***
A F AUTOMOTIVE EPA ID: NYD986912830	***733 NIAGARA FALLS BL***	***E 0 - 1/8 (0.020 mi.)***	***AB114 / 6***	***220***
CARUBBA COLLISION, I EPA ID: NYD022673313	***1167 NIAGARA FALLS B***	***E 0 - 1/8 (0.021 mi.)***	***AC119 / 6***	***234***
GOODYEAR AUTO SERVIC EPA ID: NYD149982795	***1280 NIAGARA FALLS B***	***W 0 - 1/8 (0.029 mi.)***	***AD127 / 6***	***249***
KWIK FILL MO325.325	***175 KENMORE AVE***	***SW 0 - 1/8 (0.030 mi.)***	***AE130 / 8***	***258***

EPA ID: NYD986955151				
MOBIL OIL CROP SS H4 EPA ID: NYD986958890	***2965 SHERIDAN DR***	***W 0 - 1/8 (0.037 mi.)***	***AG145 / 6***	***284***
STATION 124 EPA ID: NYD980783351	48 ALMEDA DR	E 0 - 1/8 (0.049 mi.)	AJ160 / 6	328
DELTA SONIC - BOULEV EPA ID: NYD986907996	***1355 NIAGARA FALLS B***	***NNW 0 - 1/8 (0.050 mi.)***	***AK167 / 3***	***354***
7-ELEVEN #22491 EPA ID: NYD986898534	***3488 MAIN ST***	***SSW 0 - 1/8 (0.056 mi.)***	***AH173 / 8***	***385***
BASIL FORD EPA ID: NYD118786128	***3484 MAIN ST***	***S 0 - 1/8 (0.066 mi.)***	***AO184 / 8***	***460***
MARTY'S AUTOPRO CENT EPA ID: NYD986981397	***2131 EGGERT RD***	***E 0 - 1/8 (0.071 mi.)***	***AQ191 / 6***	***471***
HONEYWELL INC EPA ID: NYR000014944	***251 JOHN JAMES AUDUB***	***SW 0 - 1/8 (0.078 mi.)***	***206 / 2***	***541***
SEARS #1162 EPA ID: NYR000165175 EPA ID: NYR000209254	***1261 NIAGARA FALLS B***	***E 0 - 1/8 (0.084 mi.)***	***AR211 / 6***	***551***
BELL ATLANTIC EPA ID: NYP000941245	MAIN ST & CAPEN BLVD	NW 0 - 1/8 (0.090 mi.)	AL215 / 8	560
WEGMANS #0082 EPA ID: NYR000147058	***675 ALBERTA DR***	***S 0 - 1/8 (0.107 mi.)***	***AU221 / 6***	***566***
BJS WHOLESALE CLUB # EPA ID: NYR000197376	3056 SHERIDAN DR	E 1/8 - 1/4 (0.127 mi.)	AW254 / 6	617
BAUGHMAN MAGIC SEAL EPA ID: NYR000219659	44 MEYER RD	N 1/8 - 1/4 (0.131 mi.)	AZ260 / 3	626
STS CAR SVC CTR EPA ID: NYD986966976	***1435 NIAGARA FALLS B***	***NNW 1/8 - 1/4 (0.153 mi.)***	***BA267 / 3***	***633***
SAVERS #1217 EPA ID: NYD981139850	2309 EGGERT RD	W 1/8 - 1/4 (0.176 mi.)	BE282 / 6	651
NORTHTOWN ONE HOUR C EPA ID: NYD045166667	***3077 SHERIDAN DR***	***E 1/8 - 1/4 (0.192 mi.)***	***BG297 / 6***	***664***
NORTHTOWN INC EPA ID: NYR000013375	***3097 SHERIDAN DR***	***E 1/8 - 1/4 (0.197 mi.)***	***BG302 / 6***	***672***
WORLD AUTO PAINTING EPA ID: NYD121947063	***2880 SHERIDAN DR***	***W 1/8 - 1/4 (0.201 mi.)***	***305 / 6***	***720***
FERRIC CONTRAST INC EPA ID: NYR000101360 EPA ID: NY0000075754	***1576 SWEET HOME RD R***	***NNW 1/8 - 1/4 (0.219 mi.)***	***BJ322 / 4***	***745***
LASER PHOTONICS TECH EPA ID: NYR000054650	***1576 SWEET HOME RD R***	***NNW 1/8 - 1/4 (0.219 mi.)***	***BJ325 / 4***	***755***
DICKS SPORTING GOODS EPA ID: NYR000224246	281 MEYER RD	N 1/8 - 1/4 (0.239 mi.)	BK337 / 4	771
PRINCETON HOUSING AS EPA ID: NYD038630554	***165 PRINCETON AVE***	***NNE 1/8 - 1/4 (0.245 mi.)***	***340 / 8***	***775***

WI MANIFEST: Hazardous Waste Manifest Data

A review of the WI MANIFEST list, as provided by EDR, and dated 12/31/2017 has revealed that there is 1 WI MANIFEST site within approximately 0.25 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
STATE UNIVERSITY OF	***3435 MAIN ST***	***NW 0 - 1/8 (0.073 mi.)***	***AP201 / 8***	***498***
ACT Status: A FID: 0 EPA ID: NYD071475867				

PA MANIFEST: Manifest Information

A review of the PA MANIFEST list, as provided by EDR, and dated 12/31/2017 has revealed that there are 2 PA MANIFEST sites within approximately 0.25 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
CVS PHARMACY 1227 Generator EPA Id: NYR000192013	520 LEE ENTRANCE UB	E 0 - 1/8 (0.011 mi.)	Q62 / 5	133
STATE UNIVERSITY OF Generator EPA Id: NYD071475867	3435 MAIN ST	NW 0 - 1/8 (0.073 mi.)	AP198 / 8	483

NY SPDES: State Pollutant Discharge Elimination System

A review of the NY SPDES list, as provided by EDR, and dated 07/18/2018 has revealed that there is 1 NY SPDES site within approximately 0.25 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
SUNY AT BUFFALO - SO	***3435 MAIN ST***	***NW 0 - 1/8 (0.073 mi.)***	***AP197 / 8***	***481***
Permit Number: NY0204218				

NY COOLING TOWERS: Registered Cooling Towers

A review of the NY COOLING TOWERS list, as provided by EDR, and dated 10/16/2018 has revealed that there are 8 NY COOLING TOWERS sites within approximately 0.25 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
Not reported	10 JOHN JAMES AUDUBO	E 0 - 1/8 (0.012 mi.)	B69 / 5	139
Not reported	4150 MAPLE RD.	N 0 - 1/8 (0.012 mi.)	V78 / 7	154
Not reported	1185 SWEET HOME RD	ESE 0 - 1/8 (0.015 mi.)	C89 / 4	163
Not reported	2402 NORTH FOREST RO	ESE 0 - 1/8 (0.067 mi.)	AM185 / 5	463
Not reported	300 CORPORATE PKWY	SE 1/8 - 1/4 (0.187 mi.)	BF289 / 7	659
Not reported	300 CORPORATE PKWY	SE 1/8 - 1/4 (0.187 mi.)	BF290 / 7	659
Not reported	1576 SWEET HOME ROAD	NNW 1/8 - 1/4 (0.219 mi.)	BJ321 / 4	745
Not reported	2350 N FOREST RD	ESE 1/8 - 1/4 (0.248 mi.)	BL343 / 5	780

EXECUTIVE SUMMARY

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR Hist Auto: EDR Exclusive Historical Auto Stations

A review of the EDR Hist Auto list, as provided by EDR, has revealed that there are 25 EDR Hist Auto sites within approximately 0.25 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
JIM & DEES ATLANTIC	826 NIAGARA FALLS B	W 0 - 1/8 (0.011 mi.)	R66 / 6	136
BROWN GEORGE A	240-246 NIAGARA FALL	W 0 - 1/8 (0.012 mi.)	T74 / 8	145
LATONAS SERVICE	989 NIAGARA FLS BD	E 0 - 1/8 (0.016 mi.)	L100 / 6	180
JOHNS SUPER SHELL SE	925 NIAGARA FLS BD	E 0 - 1/8 (0.017 mi.)	Z103 / 6	185
SWEENEYS GARAGE AUTO	424 NIAGARA FALLS B	W 0 - 1/8 (0.018 mi.)	AA107 / 8	203
AMERICAN AUTO WORLD	733 NIAGARA FALLS BL	E 0 - 1/8 (0.020 mi.)	AB115 / 6	223
DUKARMS SERVICE	4265 MAPLE RD	S 0 - 1/8 (0.023 mi.)	H122 / 7	242
BUSH EDW BLVD FRONTI	175 KENMORE AVE	SW 0 - 1/8 (0.030 mi.)	AE129 / 8	258
MONRO MUFFLER BRAKE	2980 SHERIDAN DR	W 0 - 1/8 (0.032 mi.)	AF136 / 6	271
KNOLL SERVICE STATIO	2965 SHERIDAN DR	W 0 - 1/8 (0.037 mi.)	AG144 / 6	283
ZINNIS FRIENDLY SERV	1346 NIAGARA FALLS B	NW 0 - 1/8 (0.042 mi.)	152 / 6	305
ERINS AUTOMOTIVE & T	4291 MAPLE RD	SE 0 - 1/8 (0.045 mi.)	AI157 / 7	323
DELTA SONIC CAR WASH	1355 NIAGARA FALLS B	NNW 0 - 1/8 (0.050 mi.)	AK165 / 3	334
KENDALL REFG CO FILL	3488 MAIN ST	SSW 0 - 1/8 (0.056 mi.)	AH174 / 8	388
COLDEN AUTO COLLISIO	2131 EGGERT RD	E 0 - 1/8 (0.071 mi.)	AQ190 / 6	471
TOTAL AUTOMOTIVE INC	2125 EGGERT RD	E 0 - 1/8 (0.084 mi.)	AQ208 / 6	546
KEATING JOS P GAS ST	3384 MAIN ST	WNW 0 - 1/8 (0.093 mi.)	216 / 8	561
OLD MAN PRECISION AU	4200 RENSH RD	WNW 1/8 - 1/4 (0.149 mi.)	264 / 4	630
PITZ DAVID & PHILIP	1435 NIAGARA FLS BD	NNW 1/8 - 1/4 (0.153 mi.)	BA265 / 3	630
BLACKWELL PLAZA SERV	3614 MAIN ST	NE 1/8 - 1/4 (0.169 mi.)	BB278 / 8	646
DOUG AL AUTOMOTIVE A	252 KENMORE AVE	WSW 1/8 - 1/4 (0.177 mi.)	283 / 8	653
EDDIES ASHLAND SERVI	3620 MAIN ST	NE 1/8 - 1/4 (0.184 mi.)	BB287 / 8	657
FRONTIER OIL CO BR G	3624 MAIN ST	NE 1/8 - 1/4 (0.191 mi.)	BB292 / 8	660
NORTHTOWN TEXACO SER	3120 SHERIDAN DR	E 1/8 - 1/4 (0.210 mi.)	BG307 / 6	725
GRAND ISLAND SLS SV	190 MEADOW LEA	E 1/8 - 1/4 (0.245 mi.)	341 / 6	779

EDR Hist Cleaner: EDR Exclusive Historical Cleaners

A review of the EDR Hist Cleaner list, as provided by EDR, has revealed that there are 6 EDR Hist Cleaner sites within approximately 0.25 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
ECONOMY CLEANERS	845 NIAGARA FALLS BL	E 0 - 1/8 (0.016 mi.)	R96 / 6	172
KWIK KLEEN INC BR SW	3584 MAIN ST	NE 0 - 1/8 (0.104 mi.)	AT220 / 8	566
PARKHILL & HART LNDR	3586 MAIN ST	NE 1/8 - 1/4 (0.130 mi.)	AT258 / 8	624
NORTHTOWN ONE HOUR C	3075 SHERIDAN DR	E 1/8 - 1/4 (0.192 mi.)	BG293 / 6	660
JOSEPHS SERVICES	3077 SHERIDAN DRIVE	E 1/8 - 1/4 (0.192 mi.)	BG295 / 6	663
BLUE STAR DRY CLEANE	1436 NIAGARA FALLS B	NNW 1/8 - 1/4 (0.196 mi.)	BH300 / 3	670

MAPPED SITES SUMMARY

Target Property:
CITY OF BUFFALO, TOWNS OF TONAWANDA AND AMHERST
BUFFALO, NY 14228

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION
1 / 2	MUIR WOODS DEVELOPME	1081 & 1121 N FRENCH	FINDS	TP
A2 / 2		500 JOHN JAMES AUDOB	ERNS	TP
A3 / 2	VZW AUDUBON	500 JOHN JAMES AUDUB	FINDS	TP
A4 / 2		500 JOHN JAMES AUDUB	NY COOLING TOWERS	TP
A5 / 2	TOWN OF AMHERST POLI	500 JOHN JAMES AUDUB	ICIS, FINDS, ECHO	TP
A6 / 2	TOWN OF AMHERST POLI	500 JOHN JAMES AUDUB	NY AST	TP
A7 / 2	TOWN OF AMHERST POLI	500 JOHN JAMES AUDUB	NY UST	TP
A8 / 2	AMHERST PD	500 JOHN JAMES PARKW	NY LTANKS	TP
9 / 2	AMHERST-T SENIOR CIT	370 JOHN JAMES AUDUB	FINDS	TP
B10 / 5		2410 NORTH FOREST RO	NY COOLING TOWERS	TP
B11 / 5	ISKALO OFFICE BLDG	2410 N FOREST RD	FINDS	TP
B12 / 5		2410 N FOREST RD	NY COOLING TOWERS	TP
13 / 5	ELLICOTT CREEK	INTER JOHNS JAMES AU	NY Spills	TP
C14 / 4	BALL PUMP STATION AN	SWEET HOME RD	RCRA-SQG	TP
D15 / 4	NYSDOT BIN 1-07260-1	I290 SB BRG OVER SWE	FINDS, ECHO	TP
E16 / 4	NORTH CAMP RV & MARI	MAPLE & SWEETHOME	NY LTANKS	TP
F17 / 6	ED TAYLOR LINCOLN ME	3900 MAPLE RD	RCRA NonGen / NLR, FINDS, ECHO, NY MANIF...	TP
F18 / 6	PREMIER GOURMET	3904 MAPLE RD	FINDS	TP
F19 / 6	FORMER ED TAYLOR LIN	3900 MAPLE	NY LTANKS, NY Spills	TP
F20 / 6	ED TAYLOR LINC-MERC.	3900 MAPLE RD.	NY UST	TP
F21 / 6	STEVE BALDO LINCOLN	3900 MAPLE ROAD	NY AST	TP
F22 / 6	PREMIER GOURMET	3904 MAPLE RD	NY AIRS	TP
G23 / 6	GOLDOME	3840 MAPLE ROAD	NY Spills	TP
E24 / 7	NOCO ENERGY STATION	MAPLE AND SWEETHOME	NY LTANKS	TP
25 / 7	GAS STATION	4146 MAPLE ROAD	NY Spills	TP
H26 / 7	UNIVERSITY MOBILE ST	4264 MAPLE RD	EDR Hist Auto	TP
27 / 7	NIAGARA MOHAWK TRANS	NORTH BAILEY & MAPLE	NY Spills	TP
28 / 6	UNKNOWN SUBSTANCE	730 ALBERTA DR	NY Spills	TP
F29 / 6	BRIDGESTONE FIRESTON	3931 MAPLE RD	RCRA NonGen / NLR, FINDS, ECHO	TP
F30 / 6	FIRESTONE	3931 MAPLE ROAD	NY LTANKS	TP
F31 / 6	FIRESTONE COMPLETE A	3931 MAPLE ROAD	NY AST	TP
I32 / 7		4053 MAPLE RD	NY COOLING TOWERS	TP
I33 / 7		4053 MAPLE RD	NY COOLING TOWERS	TP
I34 / 7		4053 MAPLE RD	NY COOLING TOWERS	TP
35 / 7	NIAGARA MOHAWK TRANS	4215 MAPLE ROAD	NY Spills	TP
J36 / 6	WILSON FARMS	1244 NIAGARA FALLS B	NY Spills	TP
J37 / 6	MACYS - BOULEVARD HO	1255 NIAGARA FALLS B	FINDS, ECHO	TP
J38 / 6		1255 NIAGRA FALLS BO	NY COOLING TOWERS	TP
J39 / 6		1255 NIAGARA FALLS B	NY COOLING TOWERS	TP

MAPPED SITES SUMMARY

Target Property:
CITY OF BUFFALO, TOWNS OF TONAWANDA AND AMHERST
BUFFALO, NY 14228

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
J40 / 6	MACYS - BOULEVARD #1	1255 NIAGARA FALLS B	RCRA-CESQG, NY MANIFEST	TP		
J41 / 6	MACYS - BOULEVARD HO	1255 NIAGARA FALLS B	RCRA-CESQG	TP		
J42 / 6	KAUFMANN'S DEPARTMEN	1255 NIAGARA FALLS B	NY UST	TP		
J43 / 6	FURST ARTHUR	1226 NIAGARA FLS BD	EDR Hist Cleaner	TP		
K44 / 6	NIAGARA MOHAWK BOUL.	1227 NIAGARA FALLS B	NY Spills	TP		
K45 / 6	KAUFMANS	1225 NIAGARA FALLS B	NY Spills	TP		
46 / 6	MIDAS DRAINS	1171 NIAGARA FALLS B	NY Spills	TP		
L47 / 6	AUTOMATIC ROLLS/NORT	NIAGARA FALLS BLVD -	NY Spills	TP		
M48 / 6	NYSDOT D257531	RTE 62 INTERSECTION	FINDS, ECHO	TP		
M49 / 6	NYSDOT PROJECT/ACCAD	NIAGARA FALLS BLVD/S	NY Spills	TP		
N50 / 6	FIRESTONE TIRE	NIAGARA FALLS BOULEV	NY LTANKS	TP		
N51 / 6	NFG EXCAVATION	NIAGARA FALLS BLVD/E	NY Spills	TP		
O52 / 6	NYSDOT PROJECT/U-HAU	NIAGARA FALLS BLVD/E	NY Spills	TP		
53 / 8	BIG JOHN RESTAURANT	BIG JOHN RESTAURANT	NY Spills	TP		
P54 / 8	MOBIL OI CORP SS #HA	3514 MAIN ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIF...	TP		
P55 / 8	MOBIL OIL	3514 MAIN STREET	NY LTANKS	TP		
P56 / 8	BLACKWELLS PLAZA SER	3514 MAIN ST	EDR Hist Auto	TP		
P57 / 8	NIAGARA MOHAWK A NAT	KENMORE AVE & MAIN S	RCRA NonGen / NLR, NY MANIFEST	TP		
P58 / 8	UNIVERSITY PLAZA	3500 MAIN STREET	NY Spills	TP		
P59 / 8	AJ WRIGHT	3500 MAIN ST	NY Spills	TP		
P60 / 8	NIAGARA MOHAWK A NAT	KENMORE AVE & MAIN S	FINDS, ECHO	TP		
Q61 / 5	CVS PHARMACY #1227	520 LEE ENTRANCE	RCRA-LQG, NY MANIFEST	56	0.011	East
Q62 / 5	CVS PHARMACY 1227	520 LEE ENTRANCE UB	PA MANIFEST	56	0.011	East
Q63 / 5	CVS PHARMACY #1227	520 LEE ENTRANCE U-B	FINDS, ECHO	56	0.011	East
D64 / 4	NYSDOT BIN 1-07260-2	I290 NB BRG OVER SWE	FINDS, ECHO	58	0.011	ESE
L65 / 6	CAR FIRE	1009-1025 NIAGARA FA	NY Spills	58	0.011	East
R66 / 6	JIM & DEES ATLANTIC	826 NIAGARA FALLS B	EDR Hist Auto	60	0.011	West
R67 / 6	JIM WOODS TIRE & BAT	826 NIAGARA FALLS BL	NY LTANKS	60	0.011	West
R68 / 6	UNI-MART STORE	NIAGARA FALLS BLV &	NY Spills	60	0.011	East
B69 / 5		10 JOHN JAMES AUDUBO	NY COOLING TOWERS	61	0.012	East
N70 / 6	FIRESTONE SERVICE CE	955 NIAGARA FALLS BL	NY Spills	61	0.012	East
S71 / 2	CM HEADQUARTERS BUIL	140 JOHN JAMES AUDUB	NY UST	63	0.012	NE
S72 / 2	COLUMBUS MCKINNON, I	140 JOHN JAMES AUDOB	NY LTANKS	63	0.012	NE
T73 / 8	GREAT LAKES DIVERS	240 NIAGARA FALLS BL	NY UST	64	0.012	West
T74 / 8	BROWN GEORGE A	240-246 NIAGARA FALL	EDR Hist Auto	64	0.012	West
U75 / 4	BALL PUMP STATION &	SWEET HOME RD	NY Spills, NY MANIFEST	64	0.012	SE
U76 / 4	PINTO CONSTRUCTION	1193 SWEET HOME RD	NY Spills	64	0.012	SE
V77 / 7	SWEETHOME JUNIOR HIG	4150 MAPLE RD	NY UST, NY Spills	65	0.012	North
V78 / 7		4150 MAPLE RD.	NY COOLING TOWERS	65	0.012	North

MAPPED SITES SUMMARY

Target Property:
CITY OF BUFFALO, TOWNS OF TONAWANDA AND AMHERST
BUFFALO, NY 14228

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
79 / 8	SHELDON RESIDENCE	333 NIAGARA FALLS BL	NY Spills	67	0.013	East
80 / 6	FORMER GAS STATION	895 NIAGARA FALLS BL	NY Spills	68	0.013	East
P81 / 8	MOBIL OIL 08-D5Y	MAIN STREET AT WINSP	NY Spills	69	0.013	NE
P82 / 8	MOBIL	MAIN & KENMORE	NY Spills	69	0.013	NE
83 / 6	SIBLEYS	BLVD MALL 1255 NIAG	FINDS	73	0.014	East
84 / 2	AMHERST POLICE SECUR	350 JOHN JAMES AUDUB	FINDS	74	0.014	ENE
85 / 6	NATIONAL GRID	1084 NIAGARA FALLS B	NY Spills	76	0.014	West
W86 / 6	CORSI AUTO BODY AND	874 NIAGARA FALLS BL	US AIRS	78	0.015	West
W87 / 6	CORSI AUTO BODY AND	874 NIAGARA FALLS BL	FINDS, ECHO	78	0.015	West
N88 / 6	COMMERCIAL SITE	951 NIAGARA FALLS BV	NY Spills	79	0.015	ESE
C89 / 4		1185 SWEET HOME RD	NY COOLING TOWERS	80	0.015	ESE
C90 / 4	AMHERST MEDICAL CENT	1185 SWEET HOME RD	FINDS	80	0.015	ESE
U91 / 4	AT & T CELL SITE	1201 SWEET HOME RD	NY Spills	81	0.015	SE
M92 / 6	MOBIL	N.F.BLVD. & SHERIDAN	NY LTANKS	82	0.016	East
X93 / 6	CARMELLA TERMULLO AN	853-855 NIAGARA FALL	NY Spills	83	0.016	East
X94 / 6	POLE 851 - REAR PARK	853 NIAGARA FALLS BL	NY Spills	83	0.016	East
O95 / 6	SPEEDY AUTO SERVICE	934 NIAGARA FALLS BL	NY AST	83	0.016	West
R96 / 6	ECONOMY CLEANERS	845 NIAGARA FALLS BL	EDR Hist Cleaner	84	0.016	East
Y97 / 6	PEP BOYS #193	1025 NIAGARA FALLS B	NY AST	85	0.016	East
Y98 / 6	PEP BOYS - MANNY MOE	1025 NIAGARA FALLS B	RCRA NonGen / NLR, FINDS, ECHO, NY MANIF...	85	0.016	East
Y99 / 6	PEP BOYS #0193	1025 NIAGARA FALLS B	NY CBS, NY Spills	85	0.016	East
L100 / 6	LATONAS SERVICE	989 NIAGARA FLS BD	EDR Hist Auto	87	0.016	East
Z101 / 6	NYSDOT PROJECT/U-HAU	925 NIAGARA FALLS BL	NY Spills	88	0.017	East
Z102 / 6	BOULEVARD U-HAUL CEN	925 NIAGARA FALLS BO	NY UST	88	0.017	East
Z103 / 6	JOHNS SUPER SHELL SE	925 NIAGARA FLS BD	EDR Hist Auto	88	0.017	East
R104 / 6	FORMER UNI-MART	820 NIAGARA FALLS BL	NY Spills	94	0.018	West
R105 / 6	NOCO EXPRESS S-74	820 NIAGARA FALLS BO	NY UST	94	0.018	West
R106 / 6	JIM WOODS TIRE & BAT	820 NIAGARA FALLS BL	NY UST	94	0.018	West
AA107 / 8	SWEENEYS GARAGE AUTO	424 NIAGARA FALLS B	EDR Hist Auto	95	0.018	West
AA108 / 8	SWEENEY'S GARAGE	424 NIAGARA FALLS BL	NY LTANKS, NY Spills	95	0.018	West
T109 / 8	POPPLETON RESIDENCE	232 NIAGARA FALLS BL	NY Spills	96	0.018	West
T110 / 8	BOB HILLS OLD GAS ST	240 NIAGARA FALLS BL	NY LTANKS	97	0.018	West
L111 / 6	FIRESTONE STORES	995 NIAGARA FALLS BL	NY Spills, NY MANIFEST	103	0.020	East
L112 / 6	FIRESTONE COMPLETE A	995 NIAGARA FALLS BO	NY AST	103	0.020	East
L113 / 6	BRIDGESTONE FIRESTON	995 NIAGARA FALLS BL	RCRA NonGen / NLR, FINDS, ECHO	103	0.020	East
AB114 / 6	A F AUTOMOTIVE	733 NIAGARA FALLS BL	RCRA NonGen / NLR, FINDS, ECHO, NY MANIF...	104	0.020	East
AB115 / 6	AMERICAN AUTO WORLD	733 NIAGARA FALLS BL	EDR Hist Auto	104	0.020	East
AB116 / 6	A&F AUTOMOTIVE	733 NIAGARA FALLS BL	NY UST	104	0.020	East
AB117 / 6	AF AUTOMOTIVE	733 NIAGARA FALLS BL	NY Spills	104	0.020	East

MAPPED SITES SUMMARY

Target Property:
CITY OF BUFFALO, TOWNS OF TONAWANDA AND AMHERST
BUFFALO, NY 14228

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
AC118 / 6	CARUBA COLLISON	1167 NIAGARA FALLS B	NY Spills	111	0.021	East
AC119 / 6	CARUBBA COLLISION, I	1167 NIAGARA FALLS B	RCRA-CESQG, NY MANIFEST	111	0.021	East
120 / 8	PROULX RESIDENCE	383 NIAGARA FALLS BL	NY Spills	113	0.021	East
H121 / 7	NOCO	4265 MAPLE ROAD	NY Spills	120	0.023	South
H122 / 7	DUKARMS SERVICE	4265 MAPLE RD	EDR Hist Auto	120	0.023	South
H123 / 7	NOCO EXPRESS S-24	4265 MAPLE ROAD	NY UST	120	0.023	South
H124 / 7	NOCO EXPRESS # 24	4265 MAPLE ROAD	FINDS	120	0.023	South
125 / 7	POLE 1038	1038 SWEET HOME ROAD	NY Spills	147	0.028	SSE
126 / 6	TN. TONAWANDA PARKS	LINCOLN PARK	NY LTANKS	149	0.028	East
AD127 / 6	GOODYEAR AUTO SERVIC	1280 NIAGARA FALLS B	RCRA-CESQG, NY Spills, FINDS, ECHO, NY M...	153	0.029	West
AD128 / 6	GOODYEAR 0462	1280 NIAGARA FALLS B	NY AST	153	0.029	West
AE129 / 8	BUSH EDW BLVD FRONTI	175 KENMORE AVE	EDR Hist Auto	158	0.030	SW
AE130 / 8	KWIK FILL MO325.325	175 KENMORE AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIF...	158	0.030	SW
AE131 / 8	RED APPLE FOOD MART	175 KENMORE AVE	NY UST	158	0.030	SW
AE132 / 8	KWIKFILL	175 KENMORE AVE	NY LTANKS, NY Spills	158	0.030	SW
B133 / 5	AMHERST HIGHWAY DEPA	NORTH FOREST	NY Spills	164	0.031	ESE
AF134 / 6		2980 SHERIDAN DRIVE	ERNS	170	0.032	West
AF135 / 6	MONROE MUFFLER	2980 SHERIDAN DRIVE	NY Spills	170	0.032	West
AF136 / 6	MONRO MUFFLER BRAKE	2980 SHERIDAN DR	EDR Hist Auto	170	0.032	West
AF137 / 6	UNDERGROUND AUTOSOUN	2980 SHERIDAN DR	NY Spills	170	0.032	West
P138 / 8	ROW	MAIN AND KENMORE	NY Spills	172	0.033	NE
G139 / 3	FIRESTONE	NIAGARA FALLS BLVD.	NY LTANKS	178	0.034	NNW
G140 / 3	FIRESTONE 955 NFB	NIAGARA FALLS BLVD M	NY LTANKS	178	0.034	NNW
141 / 4	COMMERCIAL DEVELOPME	4080-4120 MAPLE RD	FINDS	180	0.034	North
AF142 / 6	MONRO MUFFLER BRAKE	2980 SHERIDAN DR	NY AST, RCRA NonGen / NLR, FINDS, ECHO	183	0.035	West
143 / 2	I/A/O 3 MALLARD CT	3 MALLARD CT	NY Spills	188	0.036	East
AG144 / 6	KNOLL SERVICE STATIO	2965 SHERIDAN DR	EDR Hist Auto	193	0.037	West
AG145 / 6	MOBIL OIL CROP SS H4	2965 SHERIDAN DR	RCRA-CESQG, FINDS, ECHO, NY MANIFEST	193	0.037	West
AG146 / 6	MOBIL OIL	2965 SHERIDAN DRIVE	NY LTANKS, NY Spills	193	0.037	West
147 / 8	BURLINGTON TRUCK ROL	I290 & NIAGARA FALLS	NY Spills	200	0.038	East
148 / 8	SWEENEY'S GARAGE	PAIGE AT NIAGARA FAL	NY Spills	204	0.039	East
149 / 8	WRIGHT DRUM	4 HAWTHORNE AVENUE	NY Spills	206	0.039	West
150 / 8	MCKAY HEATING PLANT	3545 MAIN ST.	NY Spills	206	0.039	NE
AH151 / 8	SOUTHLAND CORP. 7-EL	MAIN STREET AT WINDE	NY LTANKS	208	0.039	SW
152 / 6	ZINNIS FRIENDLY SERV	1346 NIAGARA FALLS B	EDR Hist Auto	223	0.042	NW
AH153 / 8	BASIL FORD	MAIN STREET AT WINDE	NY Spills	225	0.043	SW
AH154 / 8	FORMER BASIL FORD	MAIN & WINDEMERE AVE	NY Spills	231	0.044	SSW
AI155 / 7	HERRSCHER'S EXPRESS	4291 MAPLE ROAD	ICIS, FINDS, ECHO	237	0.045	SE
AI156 / 7	EZ MART	4291 MAPLE RD	NY LTANKS, NY UST, NY Spills	237	0.045	SE

MAPPED SITES SUMMARY

Target Property:
CITY OF BUFFALO, TOWNS OF TONAWANDA AND AMHERST
BUFFALO, NY 14228

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
AI157 / 7	ERINS AUTOMOTIVE & T	4291 MAPLE RD	EDR Hist Auto	237	0.045	SE
AI158 / 7	MAPLE SUNOCO	4291 MAPLE RD	NY Spills	237	0.045	SE
AF159 / 6	MOBIL OIL	SHERIDAN & NIAGARA F	NY LTANKS	245	0.046	West
AJ160 / 6	STATION 124	48 ALMEDA DR	NY MANIFEST	258	0.049	East
AJ161 / 6	STATION 124	48 ALMEDA DR	RCRA NonGen / NLR, FINDS, ECHO	258	0.049	East
AK162 / 3	UNDERNEATH DISPENSER	1355 NIAGARA FALLS B	NY Spills	264	0.050	NNW
AK163 / 3	SPILL NUMBER 8504373	1355 NIAGARA FALLS B	NY Spills	264	0.050	NNW
AK164 / 3	DELTA SONIC CAR WASH	1355 NIAGARA FALLS B	ECHO	264	0.050	NNW
AK165 / 3	DELTA SONIC CAR WASH	1355 NIAGARA FALLS B	EDR Hist Auto	264	0.050	NNW
AK166 / 3	DELTA SONIC CAR WASH	1355 NIAGARA FALLS B	NY AST	264	0.050	NNW
AK167 / 3	DELTA SONIC - BOULEV	1355 NIAGARA FALLS B	NY LTANKS, NY Spills, RCRA NonGen / NLR,...	264	0.050	NNW
AK168 / 3	DELTA SONIC	1355 NIAGRA FALLS BL	NY Spills	264	0.050	NNW
AK169 / 3	DELTA SONIC CAR WASH	1355 NIAGARA FALLS B	NY UST	264	0.050	NNW
170 / 8	WASTE OIL	CHALMERS AND KETTERI	NY Spills	282	0.053	West
171 / 2	GOOD YEAR TIRE	200 JOHN JAMES AUDUB	FINDS	297	0.056	NE
AH172 / 8	7- ELEVEN STORE #224	3488 MAIN STREET	NY UST	298	0.056	SSW
AH173 / 8	7-ELEVEN #22491	3488 MAIN ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIF...	298	0.056	SSW
AH174 / 8	KENDALL REFG CO FILL	3488 MAIN ST	EDR Hist Auto	298	0.056	SSW
AH175 / 8	WALGREENS PARKING LO	3488 MAIN STREET	NY Spills	298	0.056	SSW
AH176 / 8	7-ELEVEN STORE #2249	3488 MAIN STREET	NY Spills	298	0.056	SSW
AL177 / 8	SUNY AT BUFFALO - NO	SERVICE BUILDING	NY AST	302	0.057	NW
178 / 6	LOUISE RING TANK	61 WREXHAM NORTH	NY Spills	329	0.062	West
AM179 / 5	FKQ CONFERENCE CENTE	2401 N FOREST RD	FINDS	329	0.062	ESE
180 / 7	ELMER SPAETH	392 HOMECREST DRIVE	NY Spills	349	0.066	South
AN181 / 4	ELLICOTT COMPLEX-FAR	HALL AREA	NY Spills	350	0.066	NNE
AO182 / 8	BASIL FORD	3484 MAIN STREET	NY LTANKS, NY AST	350	0.066	South
AO183 / 8	BASIL FORD INC.	3484 MAIN STREET	NY UST	350	0.066	South
AO184 / 8	BASIL FORD	3484 MAIN ST	RCRA-CESQG, FINDS, ECHO, NY MANIFEST	350	0.066	South
AM185 / 5		2402 NORTH FOREST RO	NY COOLING TOWERS	352	0.067	ESE
AP186 / 8	STATE UNIVERSTIY CON	SUNY AT BUFFALO 3435	RCRA NonGen / NLR	356	0.067	NW
AN187 / 4	SUNY AT BUFFALO	MILLERSPORT HIGHWAY	NY LTANKS, NY Spills	365	0.069	NNE
AN188 / 4	NYS UNIV. AT BUFFALO	301 MICHAEL HALL	NY LTANKS	365	0.069	NNE
AN189 / 4	SUNY AT BUFFALO-NORT	THE JOHN BEANE CENTE	NY CBS UST, NY CBS	365	0.069	NNE
AQ190 / 6	COLDEN AUTO COLLISIO	2131 EGGERT RD	EDR Hist Auto	376	0.071	East
AQ191 / 6	MARTY'S AUTOPRO CENT	2131 EGGERT RD	RCRA NonGen / NLR, FINDS, ECHO, NY MANIF...	376	0.071	East
AP192 / 8	GAS FROM CAR AT UB	SUNY AT BUFFALO	NY Spills	384	0.073	NW
AP193 / 8	SUNY AT BUFFALO	ATCHISON HALL SUNYAB	NY Spills	384	0.073	NW
AP194 / 8	SUNY AT BUFFALO	MAIN STREET	NY Spills	384	0.073	NW
195 / 6	PADMOUNT TRANSFORMER	ALMEDA AVE	NY Spills	384	0.073	East

MAPPED SITES SUMMARY

Target Property:
CITY OF BUFFALO, TOWNS OF TONAWANDA AND AMHERST
BUFFALO, NY 14228

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
AP196 / 8	BUFFALO COLLEGE	3435 MAIN ST AT MAIN	NY Spills	387	0.073	NW
AP197 / 8	SUNY AT BUFFALO - SO	3435 MAIN ST	NY AIRS, NY SPDES	387	0.073	NW
AP198 / 8	STATE UNIVERSITY OF	3435 MAIN ST	PA MANIFEST	387	0.073	NW
AP199 / 8	SUNY AT BUFFALO - SO	3435 MAIN STREET	ICIS, FINDS, ECHO	387	0.073	NW
AP200 / 8	UNIVERSITY OF BUFFAL	3435 MAIN STREET	NY LTANKS, NY Spills	387	0.073	NW
AP201 / 8	STATE UNIVERSITY OF	3435 MAIN ST	RCRA-LQG, US AIRS, WI MANIFEST	387	0.073	NW
AP202 / 8	UB - SOUTH CAMPUS	MAIN	NY Spills	394	0.075	NW
203 / 8	OIL DUMPING AT ALLEN	441 ALLENHURST ROAD	NY Spills	400	0.076	East
204 / 6	CURTIS PARK U.P. CHU	748 WOODLAND DR	NY UST	402	0.076	West
205 / 4	MORRIS AND REIMAN WR	3900 RENSCH RD.	NY HSWDS	410	0.078	NW
206 / 2	HONEYWELL INC	251 JOHN JAMES AUDUB	RCRA NonGen / NLR, FINDS, ECHO, NY MANIF...	411	0.078	SW
AP207 / 8	STATE UNIVERSTIY CON	SUNY AT BUFFALO 3435	FINDS, ECHO	424	0.080	NW
AQ208 / 6	TOTAL AUTOMOTIVE INC	2125 EGGERT RD	EDR Hist Auto	445	0.084	East
AQ209 / 6	NORTHTOWN PLAZA CAR	2125 EGGERT RD	NY UST	445	0.084	East
AQ210 / 6	POLE 2109	2125 EGGERT RD	NY Spills	445	0.084	East
AR211 / 6	SEARS #1162	1261 NIAGARA FALLS B	RCRA-CESQG, NY MANIFEST	446	0.084	East
AR212 / 6	BYE BYE BABY #3083	1261 NIAGARA FALLS B	RCRA-CESQG, FINDS, ECHO	446	0.084	East
AR213 / 6	SEARS #1162	1261 NIAGARA FALLS B	FINDS, ECHO	446	0.084	East
AS214 / 3	SIDE OF ROAD	145 MAYER RD	NY Spills	461	0.087	North
AL215 / 8	BELL ATLANTIC	MAIN ST & CAPEN BLVD	NY MANIFEST	475	0.090	NW
216 / 8	KEATING JOS P GAS ST	3384 MAIN ST	EDR Hist Auto	490	0.093	WNW
217 / 7	RESIDENCE	405 HOMECREST DRIVE	NY Spills	524	0.099	South
218 / 8	NEW OPPORTUNITIES CO	245 HAWTHORNE AVE	NY Spills	524	0.099	West
219 / 6	TRANSFORMER HIT BY L	205 DALTON DRIVE	NY Spills	549	0.104	West
AT220 / 8	KWIK KLEEN INC BR SW	3584 MAIN ST	EDR Hist Cleaner	550	0.104	NE
AU221 / 6	WEGMANS #0082	675 ALBERTA DR	RCRA-CESQG, NY MANIFEST	563	0.107	South
AU222 / 6	WEGMANS #0082	675 ALBERTA DR	FINDS, ECHO	563	0.107	South
AU223 / 6	TRANSFORMER POLE 505	675 ALBERTA DR	NY Spills	563	0.107	South
AV224 / 4	PROPERTY	3945 RENSCH RD	NY UST	568	0.108	NW
AV225 / 4	ON PROPERTY	3945 RENSCH ROAD	NY Spills	568	0.108	NW
226 / 4	CRYSTAL KIMMONS	605 NATURAL SCIENCE	FINDS, ECHO	576	0.109	NNE
227 / 8	MOBIL S/S 08-HA1	3514 MAIN & KENMORE	NY LTANKS, NY UST	585	0.111	NNE
228 / 5	CONFERENCE CENTER CO	2390 FOREST ROAD	FINDS, ECHO	586	0.111	ESE
AS229 / 3	BOULEVARD TOWER APTS	120 MEYER ROAD	NY Spills	591	0.112	North
AW230 / 6	BJ'S AMHERST GAS STA	3050 SHERIDAN DRIVE	NY UST	624	0.118	East
231 / 8	ORKEN LAWNCARE	514 CAPEN BOULEVARD	NY LTANKS	630	0.119	East
232 / 6	BUFFALO SUB 124	78 ALMEDA DR.	NY Spills	631	0.120	East
AX233 / 6	PRINTS CHARMING	SHERIDAN & EGGERT RO	NY Spills	640	0.121	West
AX234 / 6	HANCOCK FABRICS	EGGERT AND SHERIDAN	NY Spills	640	0.121	West

MAPPED SITES SUMMARY

Target Property:
CITY OF BUFFALO, TOWNS OF TONAWANDA AND AMHERST
BUFFALO, NY 14228

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
AY235 / 4	UNIVERSITY OF BUFFAL	JARVIS HALL	NY Spills	642	0.122	North
AY236 / 4	SUNYAB - COOKE HALL	PUTNAM WAY	NY Spills	642	0.122	North
AY237 / 4	SUNYAB AMHERST TANK	MAPLE AND JOHN BEANE	NY Spills	642	0.122	North
AY238 / 4	TRUCK AT SUNY AMHERS	FRONTIER ROAD	NY Spills	642	0.122	North
AY239 / 4	UNIVERSITY OF BUFFAL	NORTH CAMPUS - BAIRD	NY LTANKS	642	0.122	North
AY240 / 4	ALUMNI ARENA -SUNYAB	WEBSTER ROAD	NY LTANKS	642	0.122	North
AY241 / 4	SUNY BUFFALO NORTH C	SERVICE CENTER RD	NY Spills	642	0.122	North
AY242 / 4	SUNYAB-AMHERST	MILLERSPORT BUILDING	NY Spills	642	0.122	North
AY243 / 4	UB CAMPUS	SKINNERSVILLE ROAD	NY Spills	642	0.122	North
AY244 / 4	BLUE BIRD BUS LINE	SUNY AMHERST CAMPUS	NY Spills	642	0.122	North
AY245 / 4	JACOB'S MANAGEMENT C	SUNY BUFFALO	NY LTANKS	642	0.122	North
AY246 / 4	SUNY BUFFALO	TALBERT HALL	NY LTANKS	642	0.122	North
AY247 / 4	PORTER QUAD - ELLICO	JOHN JAMES AUDUBON P	NY LTANKS	642	0.122	North
AY248 / 4	STATE UNIV BUFFALO N	LOCKWOOD LIBRARY	NY LTANKS	642	0.122	North
AY249 / 4	SUNY AT BUFFALO	FRONTIER ST	NY Spills	642	0.122	North
AY250 / 4	NYS SUNY CAMPUS	JARVIS HALL	NY Spills	642	0.122	North
AX251 / 6	PRINTS CHARMING	2900 SHERIDAN DR	NY UST	664	0.126	West
AX252 / 6	PRINTS CHARMING - TA	2900 SHERIDAN DRIVE	NY LTANKS	664	0.126	West
AW253 / 6	BJS WHOLESALE CLUB #	3056 SHERIDAN DR	RCRA-CESQG	671	0.127	East
AW254 / 6	BJS WHOLESALE CLUB #	3056 SHERIDAN DR	NY MANIFEST	671	0.127	East
AW255 / 6	BJ'S WHOLESALE CLUB	3056 SHERIDAN DRIVE	NY AST	671	0.127	East
AW256 / 6	BJS WHOLESALE CLUB #	3056 SHERIDAN DR	FINDS, ECHO	671	0.127	East
257 / 6	JOE CONTINO RESIDENC	142 DALTON DRIVE	NY LTANKS	682	0.129	West
AT258 / 8	PARKHILL & HART LNDR	3586 MAIN ST	EDR Hist Cleaner	684	0.130	NE
AZ259 / 3	BAUGHMAN MAGIC SEAL	44 MEYER RD	RCRA NonGen / NLR	690	0.131	North
AZ260 / 3	BAUGHMAN MAGIC SEAL	44 MEYER RD	NY MANIFEST	690	0.131	North
AZ261 / 3	BAUGHMAN MAGIC SEAL	44 MEYER RD	FINDS, ECHO	690	0.131	North
262 / 4	RENSCH ROAD RESEARCH	4080 RENSCH ROAD	FINDS	742	0.141	NW
263 / 4	TRUCK AT LASERTRON P	5101 NORTH BAILEY/MA	NY Spills	747	0.141	North
264 / 4	OLD MAN PRECISION AU	4200 RENSH RD	EDR Hist Auto	785	0.149	WNW
BA265 / 3	PITZ DAVID & PHILIP	1435 NIAGARA FLS BD	EDR Hist Auto	810	0.153	NNW
BA266 / 3	STS CAR SERVICE	1435 NIAGARA FALLS B	NY LTANKS	810	0.153	NNW
BA267 / 3	STS CAR SVC CTR	1435 NIAGARA FALLS B	RCRA NonGen / NLR, FINDS, ECHO, NY MANIF...	810	0.153	NNW
268 / 6	JACK HANNON	190 MARGARET RD	NY Spills	812	0.154	East
269 / 3	OLD BURGER KING	1420 NIAGARA FALLS B	NY Spills	836	0.158	NNW
270 / 8	RESIDENTIAL	151 CAPEN BLVD	NY Spills	845	0.160	East
BB271 / 8	BENDERSON DEVELOPEME	3608 MAIN STREET	NY Spills	850	0.161	NE
BC272 / 8	NIAGARA MOHAWK - LYN	123 LYNDALE AVENUE	NY Spills	855	0.162	West
BC273 / 8		123 LYNDALE AVE	ERNS	855	0.162	West

MAPPED SITES SUMMARY

Target Property:
CITY OF BUFFALO, TOWNS OF TONAWANDA AND AMHERST
BUFFALO, NY 14228

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
274 / 6	NOCO ENERGY	82 TREADWELL ROAD	NY Spills	856	0.162	West
275 / 2	KADIMAH SCHOOL OF BU	2675 NORTH FOREST RD	FINDS	862	0.163	WSW
276 / 6	BJ'S WHOLESALE CLUB	3080 SHERIDAN DR	NY Spills	868	0.164	East
277 / 2	JEWISH COMMUNITY CEN	2640 NORTH FOREST RO	FINDS, ECHO	871	0.165	WSW
BB278 / 8	BLACKWELL PLAZA SERV	3614 MAIN ST	EDR Hist Auto	893	0.169	NE
BD279 / 6	ADVANCE AUTO PARTS #	2907 SHERIDAN DR	RCRA-SQG	910	0.172	West
BD280 / 6	ADVANCE AUTO PARTS #	2907 SHERIDAN DR	FINDS, ECHO	910	0.172	West
BE281 / 6	SAVERS STORE #1217	2309 EGGERT RD	RCRA-CESQG, FINDS, ECHO	927	0.176	West
BE282 / 6	SAVERS #1217	2309 EGGERT RD	NY MANIFEST	927	0.176	West
283 / 8	DOUG AL AUTOMOTIVE A	252 KENMORE AVE	EDR Hist Auto	933	0.177	WSW
284 / 4	SEPTIC TANK FAILURE	4140 RENSCH ROAD	NY Spills	938	0.178	West
285 / 6	TANK AT LINDKE RESID	25 QUAKER RIDGE	NY Spills	941	0.178	West
286 / 8	BASEMENT	8 RADCLIFFE RD.	NY Spills	952	0.180	SSW
BB287 / 8	EDDIES ASHLAND SERVI	3620 MAIN ST	EDR Hist Auto	970	0.184	NE
288 / 4	UNION CONCRETE CO.	451 MEYERS RD	NY Spills	981	0.186	WNW
BF289 / 7		300 CORPORATE PKWY	NY COOLING TOWERS	985	0.187	SE
BF290 / 7		300 CORPORATE PKWY	NY COOLING TOWERS	985	0.187	SE
291 / 6		95 TREADWELL AVE	ERNS	996	0.189	West
BB292 / 8	FRONTIER OIL CO BR G	3624 MAIN ST	EDR Hist Auto	1008	0.191	NE
BG293 / 6	NORTHTOWN ONE HOUR C	3075 SHERIDAN DR	EDR Hist Cleaner	1012	0.192	East
BG294 / 6	GI-RO DRY CLEANERS	3077 SHERIDAN DR?NOR	ICIS, US AIRS	1015	0.192	East
BG295 / 6	JOSEPHS SERVICES	3077 SHERIDAN DRIVE	EDR Hist Cleaner	1015	0.192	East
BG296 / 6	GI-RO/NORTHTOWN CLEA	3077 SHERIDAN DRIVE,	NY DRYCLEANERS	1015	0.192	East
BG297 / 6	NORTHTOWN ONE HOUR C	3077 SHERIDAN DR	RCRA NonGen / NLR, FINDS, ECHO, NY MANIF...	1015	0.192	East
298 / 8	BOULEVARD INN & SUIT	3612 MAIN ST.	NY Spills	1028	0.195	NE
299 / 2	HOUSE	2699 NORTH FOREST RO	NY Spills	1030	0.195	WSW
BH300 / 3	BLUE STAR DRY CLEANE	1436 NIAGARA FALLS B	EDR Hist Cleaner	1037	0.196	NNW
BH301 / 3	COLD PARTS CLEANER	1435 NIAGARA FALLS B	NY Spills	1037	0.196	NNW
BG302 / 6	NORTHTOWN INC	3097 SHERIDAN DR	RCRA NonGen / NLR, FINDS, ECHO, NY MANIF...	1042	0.197	East
BG303 / 6	NORTHTOWN INC.	3097 SHERIDAN DRIVE	NY ENG CONTROLS, NY INST CONTROL, NY BRO	1042	0.197	East
BG304 / 6	NORTHTOWN PLAZA	3097 SHERIDAN DR	NY UST	1042	0.197	East
305 / 6	WORLD AUTO PAINTING	2880 SHERIDAN DR	RCRA NonGen / NLR, FINDS, ECHO, NY MANIF...	1060	0.201	West
306 / 5	UNITED CEREBRAL PALS	2360 NORTH FOREST	NY Spills	1090	0.206	ESE
BG307 / 6	NORTHTOWN TEXACO SER	3120 SHERIDAN DR	EDR Hist Auto	1107	0.210	East
308 / 8	JOAN MILLEY TANK	45 CONANT STREET	NY LTANKS	1110	0.210	West
309 / 8	FURMAN RESIDENCE	99 CONANT AVENUE	NY LTANKS	1120	0.212	West
310 / 4	GOVERNORS HALL AT UN	WHITE AND HADLEY RD	NY Spills	1128	0.214	North
311 / 6	NATIONAL FUEL GAS CO	104 LONGMEADOW AVE	RCRA NonGen / NLR, FINDS, ECHO	1134	0.215	East
312 / 2	NATIONAL GRID TRANSF	38 PARTRIDGE RUN	NY LTANKS	1139	0.216	East

MAPPED SITES SUMMARY

Target Property:
CITY OF BUFFALO, TOWNS OF TONAWANDA AND AMHERST
BUFFALO, NY 14228

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
BI313 / 8	AMHERST CSD - WINDER	291 WINDERMERE BLVD	FINDS, ECHO	1150	0.218	East
BI314 / 8	WINDERMERE BLVD SCHO	291 WINDERMERE BLVD	NY LTANKS, NY UST	1150	0.218	East
BI315 / 8	AMHERST CSD - WINDER	291 WINDERMERE BLVD	RCRA-CESQG	1150	0.218	East
316 / 6	NATIONAL GRID POLE 2	2352 EGGERT RD	NY Spills	1150	0.218	West
BJ317 / 4	BALL PUMP STATION	SWEET HOME ROAD	NY LTANKS, NY Spills	1151	0.218	NNW
BJ318 / 4	AMHERST CUSTOM CHEMI	1576 SWEET HOME RD -	RCRA NonGen / NLR	1154	0.219	NNW
BJ319 / 4	ONY BIOTECH	1576 SWEET HOME ROAD	FINDS, ECHO	1154	0.219	NNW
BJ320 / 4	AMHERST CUSTOM CHEMI	1576 SWEET HOME RD -	FINDS, ECHO	1154	0.219	NNW
BJ321 / 4		1576 SWEET HOME ROAD	NY COOLING TOWERS	1154	0.219	NNW
BJ322 / 4	FERRIC CONTRAST INC	1576 SWEET HOME RD R	RCRA-CESQG, FINDS, NY MANIFEST	1154	0.219	NNW
BJ323 / 4	UNIVERSITY AT BUFFAL	1576 SWEET HOME RD	RCRA NonGen / NLR, FINDS, ECHO	1154	0.219	NNW
BJ324 / 4	FERRIC CONTRAST INC	1576 SWEET HOME RD R	ECHO	1154	0.219	NNW
BJ325 / 4	LASER PHOTONICS TECH	1576 SWEET HOME RD R	RCRA NonGen / NLR, FINDS, ECHO, NY MANIF...	1154	0.219	NNW
BJ326 / 4	DIMIEN LLC	1576 SWEET HOME RD S	RCRA-CESQG, FINDS, ECHO	1154	0.219	NNW
BJ327 / 4	ONY INC	1576 SWEET HOME ROAD	NY AIRS	1154	0.219	NNW
BJ328 / 4	SQUIRREL FREE INCORP	1576 SWEET HOME ROAD	FINDS	1154	0.219	NNW
329 / 8	HOUSE	381 WINDERMERE	NY Spills	1161	0.220	East
330 / 8		174 UNIVERSITY AVENU	ERNS	1167	0.221	WSW
331 / 5	COMPUSOURCE SYSTEMS,	110 JOHN MUIR DRIVE	NY AST	1203	0.228	East
332 / 4	MEL OTT BALL FIELD	MEYER ROAD	NY Spills	1209	0.229	WNW
333 / 8	WASTE OIL IN YARD	224 UNIVERSITY AVENU	NY Spills	1219	0.231	West
334 / 9		3640 MAIN ST	ERNS	1221	0.231	NE
335 / 8	NYSDOT BIN 1001590	MAIN ST OVER NY RT 1	FINDS, ECHO	1228	0.233	WSW
BK336 / 4	DICKS SPORTING GOODS	281 MEYER RD	RCRA-CESQG, FINDS, ECHO	1264	0.239	North
BK337 / 4	DICKS SPORTING GOODS	281 MEYER RD	NY MANIFEST	1264	0.239	North
338 / 6	NOCO TRUCK	216 NORTH WREXHAM	NY Spills	1285	0.243	West
339 / 4	NATIONAL GRID	311 MEYER RD	NY Spills	1294	0.245	North
340 / 8	PRINCETON HOUSING AS	165 PRINCETON AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIF...	1294	0.245	NNE
341 / 6	GRAND ISLAND SLS SV	190 MEADOW LEA	EDR Hist Auto	1295	0.245	East
342 / 8	SEAN MAGIERSKI RESID	73 MONTROSE AVE	NY Spills	1301	0.246	SW
BL343 / 5		2350 N FOREST RD	NY COOLING TOWERS	1307	0.248	ESE
BL344 / 5	ELLICOTT CREEK FLOOD	2350 NORTH FOREST RO	FINDS	1307	0.248	ESE
345 / 4	ONY BIOTECH	1576 SWEET HOME RD N	RCRA-SQG	1312	0.248	NNW
346 / 6	WHITE CRYSTALLINE MA	674 HARRISON STREET	NY Spills	1318	0.250	West

Key Map - 05531774.2r



SITE NAME: Metro Rail Expansion Corridor	CLIENT: Watts Architecture & Engineering
ADDRESS: City of Buffalo, Towns of Tonawanda and Amherst	CONTACT: Lisa Connors
CITY/STATE: Buffalo NY	INQUIRY #: 05531774.2r
ZIP: 14228	DATE: 01/11/19 2:51 PM

Copyright © 2019 EDR, Inc. © 2015 TomTom Rel. 2015.

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTAL RECORDS								
Federal NPL site list								
NPL	0.250		0	0	NR	NR	NR	0
Proposed NPL	0.250		0	0	NR	NR	NR	0
NPL LIENS	0.250		0	0	NR	NR	NR	0
Federal Delisted NPL site list								
Delisted NPL	0.250		0	0	NR	NR	NR	0
Federal CERCLIS list								
FEDERAL FACILITY	0.250		0	0	NR	NR	NR	0
SEMS	0.250		0	0	NR	NR	NR	0
Federal CERCLIS NFRAP site list								
SEMS-ARCHIVE	0.250		0	0	NR	NR	NR	0
Federal RCRA CORRACTS facilities list								
CORRACTS	0.250		0	0	NR	NR	NR	0
Federal RCRA non-CORRACTS TSD facilities list								
RCRA-TSDF	0.250		0	0	NR	NR	NR	0
Federal RCRA generators list								
RCRA-LQG	0.250		2	0	NR	NR	NR	2
RCRA-SQG	0.250	1	0	2	NR	NR	NR	3
RCRA-CESQG	0.250	2	7	6	NR	NR	NR	15
Federal institutional controls / engineering controls registries								
LUCIS	0.250		0	0	NR	NR	NR	0
US ENG CONTROLS	0.250		0	0	NR	NR	NR	0
US INST CONTROL	0.250		0	0	NR	NR	NR	0
Federal ERNS list								
ERNS	0.250	1	1	4	NR	NR	NR	6
State- and tribal - equivalent CERCLIS								
NY SHWS	0.250		0	0	NR	NR	NR	0
State and tribal landfill and/or solid waste disposal site lists								
NY SWF/LF	0.250		0	0	NR	NR	NR	0
State and tribal leaking storage tank lists								
INDIAN LUST	0.250		0	0	NR	NR	NR	0
NY LTANKS	0.250	7	26	8	NR	NR	NR	41
NY HIST LTANKS	0.250		0	0	NR	NR	NR	0
State and tribal registered storage tank lists								
FEMA UST	0.250		0	0	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NY UST	0.250	3	18	3	NR	NR	NR	24
NY CBS UST	0.250		1	0	NR	NR	NR	1
NY MOSF UST	0.250		0	0	NR	NR	NR	0
NY CBS	0.250		2	0	NR	NR	NR	2
NY MOSF	0.250		0	0	NR	NR	NR	0
NY AST	0.250	3	8	2	NR	NR	NR	13
NY CBS AST	0.250		0	0	NR	NR	NR	0
NY MOSF AST	0.250		0	0	NR	NR	NR	0
INDIAN UST	0.250		0	0	NR	NR	NR	0
NY TANKS	0.250		0	0	NR	NR	NR	0
State and tribal institutional control / engineering control registries								
NY RES DECL	0.250		0	0	NR	NR	NR	0
NY ENG CONTROLS	0.250		0	1	NR	NR	NR	1
NY INST CONTROL	0.250		0	1	NR	NR	NR	1
State and tribal voluntary cleanup sites								
NY VCP	0.250		0	0	NR	NR	NR	0
INDIAN VCP	0.250		0	0	NR	NR	NR	0
State and tribal Brownfields sites								
NY BROWNFIELDS	0.250		0	1	NR	NR	NR	1
NY ERP	0.250		0	0	NR	NR	NR	0
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS	0.250		0	0	NR	NR	NR	0
Local Lists of Landfill / Solid Waste Disposal Sites								
NY SWTIRE	0.250		0	0	NR	NR	NR	0
NY SWRCY	0.250		0	0	NR	NR	NR	0
INDIAN ODI	0.250		0	0	NR	NR	NR	0
DEBRIS REGION 9	0.250		0	0	NR	NR	NR	0
ODI	0.250		0	0	NR	NR	NR	0
IHS OPEN DUMPS	0.250		0	0	NR	NR	NR	0
Local Lists of Hazardous waste / Contaminated Sites								
US HIST CDL	0.250		0	0	NR	NR	NR	0
NY DEL SHWS	0.250		0	0	NR	NR	NR	0
US CDL	0.250		0	0	NR	NR	NR	0
Local Lists of Registered Storage Tanks								
NY HIST UST	0.250		0	0	NR	NR	NR	0
NY HIST AST	0.250		0	0	NR	NR	NR	0
Local Land Records								
NY LIENS	0.250		0	0	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
LIENS 2	0.250		0	0	NR	NR	NR	0
Records of Emergency Release Reports								
HMIRS	0.250		0	0	NR	NR	NR	0
NY Spills	0.250	18	82	27	NR	NR	NR	127
NY Hist Spills	0.250		0	0	NR	NR	NR	0
NY SPILLS 90	0.250		0	0	NR	NR	NR	0
NY SPILLS 80	0.250		0	0	NR	NR	NR	0
Other Ascertainable Records								
RCRA NonGen / NLR	0.250	4	11	10	NR	NR	NR	25
FUDS	0.250		0	0	NR	NR	NR	0
DOD	0.250		0	0	NR	NR	NR	0
SCRD DRYCLEANERS	0.250		0	0	NR	NR	NR	0
US FIN ASSUR	0.250		0	0	NR	NR	NR	0
EPA WATCH LIST	0.250		0	0	NR	NR	NR	0
2020 COR ACTION	0.250		0	0	NR	NR	NR	0
TSCA	0.250		0	0	NR	NR	NR	0
TRIS	0.250		0	0	NR	NR	NR	0
SSTS	0.250		0	0	NR	NR	NR	0
ROD	0.250		0	0	NR	NR	NR	0
RMP	0.250		0	0	NR	NR	NR	0
RAATS	0.250		0	0	NR	NR	NR	0
PRP	0.250		0	0	NR	NR	NR	0
PADS	0.250		0	0	NR	NR	NR	0
ICIS	0.250	1	2	1	NR	NR	NR	4
FTTS	0.250		0	0	NR	NR	NR	0
MLTS	0.250		0	0	NR	NR	NR	0
COAL ASH DOE	0.250		0	0	NR	NR	NR	0
COAL ASH EPA	0.250		0	0	NR	NR	NR	0
PCB TRANSFORMER	0.250		0	0	NR	NR	NR	0
RADINFO	0.250		0	0	NR	NR	NR	0
HIST FTTS	0.250		0	0	NR	NR	NR	0
DOT OPS	0.250		0	0	NR	NR	NR	0
CONSENT	0.250		0	0	NR	NR	NR	0
INDIAN RESERV	0.250		0	0	NR	NR	NR	0
FUSRAP	0.250		0	0	NR	NR	NR	0
UMTRA	0.250		0	0	NR	NR	NR	0
LEAD SMELTERS	0.250		0	0	NR	NR	NR	0
US AIRS	0.250		3	1	NR	NR	NR	4
US MINES	0.250		0	0	NR	NR	NR	0
ABANDONED MINES	0.250		0	0	NR	NR	NR	0
FINDS	0.250	13	31	24	NR	NR	NR	68
UXO	0.250		0	0	NR	NR	NR	0
DOCKET HWC	0.250		0	0	NR	NR	NR	0
ECHO	0.250	8	24	20	NR	NR	NR	52
FUELS PROGRAM	0.250		0	0	NR	NR	NR	0
NY AIRS	0.250	1	1	1	NR	NR	NR	3
NY COAL ASH	0.250		0	0	NR	NR	NR	0
NY DRYCLEANERS	0.250		0	1	NR	NR	NR	1
NY E DESIGNATION	0.250		0	0	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NY Financial Assurance	0.250		0	0	NR	NR	NR	0
NY HSWDS	0.250		1	0	NR	NR	NR	1
NY MANIFEST	0.250	4	18	11	NR	NR	NR	33
WI MANIFEST	0.250		1	0	NR	NR	NR	1
PA MANIFEST	0.250		2	0	NR	NR	NR	2
NY SPDES	0.250		1	0	NR	NR	NR	1
NY VAPOR REOPENED	0.250		0	0	NR	NR	NR	0
NY UIC	0.250		0	0	NR	NR	NR	0
NY COOLING TOWERS	0.250	8	4	4	NR	NR	NR	16
EDR HIGH RISK HISTORICAL RECORDS								
EDR Exclusive Records								
EDR MGP	0.250		0	0	NR	NR	NR	0
EDR Hist Auto	0.250	2	17	8	NR	NR	NR	27
EDR Hist Cleaner	0.250	1	2	4	NR	NR	NR	7
EDR RECOVERED GOVERNMENT ARCHIVES								
Exclusive Recovered Govt. Archives								
NY RGA HWS	0.250		0	0	NR	NR	NR	0
NY RGA LF	0.250		0	0	NR	NR	NR	0
- Totals --		77	265	140	0	0	0	482

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

Focus Map - 1 - 05531774.2r



Sites
Target Property
Search Buffer
Focus Map - No Sites
Focus Map - Sites
Power Line
Pipe Line
National Priority List Sites
Dept. Defense Sites
Indian Reservations BIA

0 1/8 1/4 Miles

SITE NAME: Metro Rail Expansion Corridor	CLIENT: Watts Architecture & Engineering
ADDRESS: City of Buffalo, Towns of Tonawanda and Amherst	CONTACT: Lisa Connors
CITY/STATE: Buffalo NY	INQUIRY #: 05531774.2r
ZIP: 14228	DATE: 01/11/19

Copyright © 2019 EDR, Inc. © 2015 TomTom Rel. 2015.

MAPPED SITES SUMMARY - FOCUS MAP 1

Target Property:
CITY OF BUFFALO, TOWNS OF TONAWANDA AND AMHERST
BUFFALO, NY 14228

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION

NO MAPPED SITES FOUND

Focus Map - 2 - 05531774.2r



Sites
Target Property
Search Buffer
Focus Map - No Sites
Focus Map - Sites
Power Line
Pipe Line
National Priority List Sites
Dept. Defense Sites
Indian Reservations BIA

SITE NAME: Metro Rail Expansion Corridor	CLIENT: Watts Architecture & Engineering
ADDRESS: City of Buffalo, Towns of Tonawanda and Amherst	CONTACT: Lisa Connors
CITY/STATE: Buffalo NY	INQUIRY #: 05531774.2r
ZIP: 14228	DATE: 01/11/19

Copyright © 2019 EDR, Inc. © 2015 TomTom Rel. 2015.

MAPPED SITES SUMMARY - FOCUS MAP 2

Target Property:
CITY OF BUFFALO, TOWNS OF TONAWANDA AND AMHERST
BUFFALO, NY 14228

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION
1 / 2	MUIR WOODS DEVELOPME	1081 & 1121 N FRENCH	FINDS	TP
A2 / 2		500 JOHN JAMES AUDOB	ERNS	TP
A3 / 2	VZW AUDUBON	500 JOHN JAMES AUDUB	FINDS	TP
A4 / 2		500 JOHN JAMES AUDUB	NY COOLING TOWERS	TP
A5 / 2	TOWN OF AMHERST POLI	500 JOHN JAMES AUDUB	ICIS, FINDS, ECHO	TP
A6 / 2	TOWN OF AMHERST POLI	500 JOHN JAMES AUDUB	NY AST	TP
A7 / 2	TOWN OF AMHERST POLI	500 JOHN JAMES AUDUB	NY UST	TP
A8 / 2	AMHERST PD	500 JOHN JAMES PARKW	NY LTANKS	TP
9 / 2	AMHERST-T SENIOR CIT	370 JOHN JAMES AUDUB	FINDS	TP
S71 / 2	CM HEADQUARTERS BUIL	140 JOHN JAMES AUDUB	NY UST	63 0.012 NE
S72 / 2	COLUMBUS MCKINNON, I	140 JOHN JAMES AUDOB	NY LTANKS	63 0.012 NE
84 / 2	AMHERST POLICE SECUR	350 JOHN JAMES AUDUB	FINDS	74 0.014 ENE
143 / 2	I/A/O 3 MALLARD CT	3 MALLARD CT	NY Spills	188 0.036 East
171 / 2	GOOD YEAR TIRE	200 JOHN JAMES AUDUB	FINDS	297 0.056 NE
206 / 2	HONEYWELL INC	251 JOHN JAMES AUDUB	RCRA NonGen / NLR, FINDS, ECHO, NY MANIF...	411 0.078 SW
275 / 2	KADIMAH SCHOOL OF BU	2675 NORTH FOREST RD	FINDS	862 0.163 WSW
277 / 2	JEWISH COMMUNITY CEN	2640 NORTH FOREST RO	FINDS, ECHO	871 0.165 WSW
299 / 2	HOUSE	2699 NORTH FOREST RO	NY Spills	1030 0.195 WSW
312 / 2	NATIONAL GRID TRANSF	38 PARTRIDGE RUN	NY LTANKS	1139 0.216 East

Focus Map - 3 - 05531774.2r

SITE NAME: Metro Rail Expansion Corridor	CLIENT: Watts Architecture & Engineering
ADDRESS: City of Buffalo, Towns of Tonawanda and Amherst	CONTACT: Lisa Connors
CITY/STATE: Buffalo NY	INQUIRY #: 05531774.2r
ZIP: 14228	DATE: 01/11/19

Copyright © 2019 EDR, Inc. © 2015 TomTom Rel. 2015.

MAPPED SITES SUMMARY - FOCUS MAP 3

Target Property:
CITY OF BUFFALO, TOWNS OF TONAWANDA AND AMHERST
BUFFALO, NY 14228

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
G139 / 3	FIRESTONE	NIAGARA FALLS BLVD.	NY LTANKS	178	0.034	NNW
G140 / 3	FIRESTONE 955 NFB	NIAGARA FALLS BLVD M	NY LTANKS	178	0.034	NNW
AK162 / 3	UNDERNEATH DISPENSER	1355 NIAGARA FALLS B	NY Spills	264	0.050	NNW
AK163 / 3	SPILL NUMBER 8504373	1355 NIAGARA FALLS B	NY Spills	264	0.050	NNW
AK164 / 3	DELTA SONIC CAR WASH	1355 NIAGARA FALLS B	ECHO	264	0.050	NNW
AK165 / 3	DELTA SONIC CAR WASH	1355 NIAGARA FALLS B	EDR Hist Auto	264	0.050	NNW
AK166 / 3	DELTA SONIC CAR WASH	1355 NIAGARA FALLS B	NY AST	264	0.050	NNW
AK167 / 3	DELTA SONIC - BOULEV	1355 NIAGARA FALLS B	NY LTANKS, NY Spills, RCRA NonGen / NLR,...	264	0.050	NNW
AK168 / 3	DELTA SONIC	1355 NIAGRA FALLS BL	NY Spills	264	0.050	NNW
AK169 / 3	DELTA SONIC CAR WASH	1355 NIAGARA FALLS B	NY UST	264	0.050	NNW
AS214 / 3	SIDE OF ROAD	145 MAYER RD	NY Spills	461	0.087	North
AS229 / 3	BOULEVARD TOWER APTS	120 MEYER ROAD	NY Spills	591	0.112	North
AZ259 / 3	BAUGHMAN MAGIC SEAL	44 MEYER RD	RCRA NonGen / NLR	690	0.131	North
AZ260 / 3	BAUGHMAN MAGIC SEAL	44 MEYER RD	NY MANIFEST	690	0.131	North
AZ261 / 3	BAUGHMAN MAGIC SEAL	44 MEYER RD	FINDS, ECHO	690	0.131	North
BA265 / 3	PITZ DAVID & PHILIP	1435 NIAGARA FLS BD	EDR Hist Auto	810	0.153	NNW
BA266 / 3	STS CAR SERVICE	1435 NIAGARA FALLS B	NY LTANKS	810	0.153	NNW
BA267 / 3	STS CAR SVC CTR	1435 NIAGARA FALLS B	RCRA NonGen / NLR, FINDS, ECHO, NY MANIF...	810	0.153	NNW
269 / 3	OLD BURGER KING	1420 NIAGARA FALLS B	NY Spills	836	0.158	NNW
BH300 / 3	BLUE STAR DRY CLEANE	1436 NIAGARA FALLS B	EDR Hist Cleaner	1037	0.196	NNW
BH301 / 3	COLD PARTS CLEANER	1435 NIAGARA FALLS B	NY Spills	1037	0.196	NNW

Focus Map - 4 - 05531774.2r



Sites
Target Property
Search Buffer
Focus Map - No Sites
Focus Map - Sites
Power Line
Pipe Line
National Priority List Sites
Dept. Defense Sites
Indian Reservations BIA

0 1/8 1/4 Miles

SITE NAME: Metro Rail Expansion Corridor	CLIENT: Watts Architecture & Engineering
ADDRESS: City of Buffalo, Towns of Tonawanda and Amherst	CONTACT: Lisa Connors
CITY/STATE: Buffalo NY	INQUIRY #: 05531774.2r
ZIP: 14228	DATE: 01/11/19

Copyright © 2019 EDR, Inc. © 2015 TomTom Rel. 2015.

MAPPED SITES SUMMARY - FOCUS MAP 4

Target Property:
CITY OF BUFFALO, TOWNS OF TONAWANDA AND AMHERST
BUFFALO, NY 14228

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
C14 / 4	BALL PUMP STATION AN	SWEET HOME RD	RCRA-SQG	TP		
D15 / 4	NYSDOT BIN 1-07260-1	I290 SB BRG OVER SWE	FINDS, ECHO	TP		
E16 / 4	NORTH CAMP RV & MARI	MAPLE & SWEETHOME	NY LTANKS	TP		
D64 / 4	NYSDOT BIN 1-07260-2	I290 NB BRG OVER SWE	FINDS, ECHO	58	0.011	ESE
U75 / 4	BALL PUMP STATION &	SWEET HOME RD	NY Spills, NY MANIFEST	64	0.012	SE
U76 / 4	PINTO CONSTRUCTION	1193 SWEET HOME RD	NY Spills	64	0.012	SE
C89 / 4		1185 SWEET HOME RD	NY COOLING TOWERS	80	0.015	ESE
C90 / 4	AMHERST MEDICAL CENT	1185 SWEET HOME RD	FINDS	80	0.015	ESE
U91 / 4	AT & T CELL SITE	1201 SWEET HOME RD	NY Spills	81	0.015	SE
141 / 4	COMMERCIAL DEVELOPME	4080-4120 MAPLE RD	FINDS	180	0.034	North
AN181 / 4	ELLICOTT COMPLEX-FAR	HALL AREA	NY Spills	350	0.066	NNE
AN187 / 4	SUNY AT BUFFALO	MILLERSPORT HIGHWAY	NY LTANKS, NY Spills	365	0.069	NNE
AN188 / 4	NYS UNIV. AT BUFFALO	301 MICHAEL HALL	NY LTANKS	365	0.069	NNE
AN189 / 4	SUNY AT BUFFALO-NORT	THE JOHN BEANE CENTE	NY CBS UST, NY CBS	365	0.069	NNE
205 / 4	MORRIS AND REIMAN WR	3900 RENSCH RD.	NY HSWDS	410	0.078	NW
AV224 / 4	PROPERTY	3945 RENSCH RD	NY UST	568	0.108	NW
AV225 / 4	ON PROPERTY	3945 RENSCH ROAD	NY Spills	568	0.108	NW
226 / 4	CRYSTAL KIMMONS	605 NATURAL SCIENCE	FINDS, ECHO	576	0.109	NNE
AY235 / 4	UNIVERSITY OF BUFFAL	JARVIS HALL	NY Spills	642	0.122	North
AY236 / 4	SUNYAB - COOKE HALL	PUTNAM WAY	NY Spills	642	0.122	North
AY237 / 4	SUNYAB AMHERST TANK	MAPLE AND JOHN BEANE	NY Spills	642	0.122	North
AY238 / 4	TRUCK AT SUNY AMHERS	FRONTIER ROAD	NY Spills	642	0.122	North
AY239 / 4	UNIVERSITY OF BUFFAL	NORTH CAMPUS - BAIRD	NY LTANKS	642	0.122	North
AY240 / 4	ALUMNI ARENA -SUNYAB	WEBSTER ROAD	NY LTANKS	642	0.122	North
AY241 / 4	SUNY BUFFALO NORTH C	SERVICE CENTER RD	NY Spills	642	0.122	North
AY242 / 4	SUNYAB-AMHERST	MILLERSPORT BUILDING	NY Spills	642	0.122	North
AY243 / 4	UB CAMPUS	SKINNERSVILLE ROAD	NY Spills	642	0.122	North
AY244 / 4	BLUE BIRD BUS LINE	SUNY AMHERST CAMPUS	NY Spills	642	0.122	North
AY245 / 4	JACOB'S MANAGEMENT C	SUNY BUFFALO	NY LTANKS	642	0.122	North
AY246 / 4	SUNY BUFFALO	TALBERT HALL	NY LTANKS	642	0.122	North
AY247 / 4	PORTER QUAD - ELLICO	JOHN JAMES AUDUBON P	NY LTANKS	642	0.122	North
AY248 / 4	STATE UNIV BUFFALO N	LOCKWOOD LIBRARY	NY LTANKS	642	0.122	North
AY249 / 4	SUNY AT BUFFALO	FRONTIER ST	NY Spills	642	0.122	North
AY250 / 4	NYS SUNY CAMPUS	JARVIS HALL	NY Spills	642	0.122	North
262 / 4	RENSCH ROAD RESEARCH	4080 RENSCH ROAD	FINDS	742	0.141	NW
263 / 4	TRUCK AT LASERTRON P	5101 NORTH BAILEY/MA	NY Spills	747	0.141	North
264 / 4	OLD MAN PRECISION AU	4200 RENSH RD	EDR Hist Auto	785	0.149	WNW
284 / 4	SEPTIC TANK FAILURE	4140 RENSCH ROAD	NY Spills	938	0.178	West
288 / 4	UNION CONCRETE CO.	451 MEYERS RD	NY Spills	981	0.186	WNW

MAPPED SITES SUMMARY - FOCUS MAP 4

Target Property:
CITY OF BUFFALO, TOWNS OF TONAWANDA AND AMHERST
BUFFALO, NY 14228

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
310 / 4	GOVERNORS HALL AT UN	WHITE AND HADLEY RD	NY Spills	1128	0.214	North
BJ317 / 4	BALL PUMP STATION	SWEET HOME ROAD	NY LTANKS, NY Spills	1151	0.218	NNW
BJ318 / 4	AMHERST CUSTOM CHEMI	1576 SWEET HOME RD -	RCRA NonGen / NLR	1154	0.219	NNW
BJ319 / 4	ONY BIOTECH	1576 SWEET HOME ROAD	FINDS, ECHO	1154	0.219	NNW
BJ320 / 4	AMHERST CUSTOM CHEMI	1576 SWEET HOME RD -	FINDS, ECHO	1154	0.219	NNW
BJ321 / 4		1576 SWEET HOME ROAD	NY COOLING TOWERS	1154	0.219	NNW
BJ322 / 4	FERRIC CONTRAST INC	1576 SWEET HOME RD R	RCRA-CESQG, FINDS, NY MANIFEST	1154	0.219	NNW
BJ323 / 4	UNIVERSITY AT BUFFAL	1576 SWEET HOME RD	RCRA NonGen / NLR, FINDS, ECHO	1154	0.219	NNW
BJ324 / 4	FERRIC CONTRAST INC	1576 SWEET HOME RD R	ECHO	1154	0.219	NNW
BJ325 / 4	LASER PHOTONICS TECH	1576 SWEET HOME RD R	RCRA NonGen / NLR, FINDS, ECHO, NY MANIF...	1154	0.219	NNW
BJ326 / 4	DIMIEN LLC	1576 SWEET HOME RD S	RCRA-CESQG, FINDS, ECHO	1154	0.219	NNW
BJ327 / 4	ONY INC	1576 SWEET HOME ROAD	NY AIRS	1154	0.219	NNW
BJ328 / 4	SQUIRREL FREE INCORP	1576 SWEET HOME ROAD	FINDS	1154	0.219	NNW
332 / 4	MEL OTT BALL FIELD	MEYER ROAD	NY Spills	1209	0.229	WNW
BK336 / 4	DICKS SPORTING GOODS	281 MEYER RD	RCRA-CESQG, FINDS, ECHO	1264	0.239	North
BK337 / 4	DICKS SPORTING GOODS	281 MEYER RD	NY MANIFEST	1264	0.239	North
339 / 4	NATIONAL GRID	311 MEYER RD	NY Spills	1294	0.245	North
345 / 4	ONY BIOTECH	1576 SWEET HOME RD N	RCRA-SQG	1312	0.248	NNW

Focus Map - 5 - 05531774.2r



Sites
Target Property
Search Buffer
Focus Map - No Sites
Focus Map - Sites
Power Line
Pipe Line
National Priority List Sites
Dept. Defense Sites
Indian Reservations BIA

0 1/8 1/4 Miles

SITE NAME: Metro Rail Expansion Corridor	CLIENT: Watts Architecture & Engineering
ADDRESS: City of Buffalo, Towns of Tonawanda and Amherst	CONTACT: Lisa Connors
CITY/STATE: Buffalo NY	INQUIRY #: 05531774.2r
ZIP: 14228	DATE: 01/11/19

Copyright © 2019 EDR, Inc. © 2015 TomTom Rel. 2015.

MAPPED SITES SUMMARY - FOCUS MAP 5

Target Property:
CITY OF BUFFALO, TOWNS OF TONAWANDA AND AMHERST
BUFFALO, NY 14228

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION
B10 / 5		2410 NORTH FOREST RO	NY COOLING TOWERS	TP
B11 / 5	ISKALO OFFICE BLDG	2410 N FOREST RD	FINDS	TP
B12 / 5		2410 N FOREST RD	NY COOLING TOWERS	TP
13 / 5	ELLICOTT CREEK	INTER JOHNS JAMES AU	NY Spills	TP
Q61 / 5	CVS PHARMACY #1227	520 LEE ENTRANCE	RCRA-LQG, NY MANIFEST	56 0.011 East
Q62 / 5	CVS PHARMACY 1227	520 LEE ENTRANCE UB	PA MANIFEST	56 0.011 East
Q63 / 5	CVS PHARMACY #1227	520 LEE ENTRANCE U-B	FINDS, ECHO	56 0.011 East
B69 / 5		10 JOHN JAMES AUDUBO	NY COOLING TOWERS	61 0.012 East
B133 / 5	AMHERST HIGHWAY DEPA	NORTH FOREST	NY Spills	164 0.031 ESE
AM179 / 5	FKQ CONFERENCE CENTE	2401 N FOREST RD	FINDS	329 0.062 ESE
AM185 / 5		2402 NORTH FOREST RO	NY COOLING TOWERS	352 0.067 ESE
228 / 5	CONFERENCE CENTER CO	2390 FOREST ROAD	FINDS, ECHO	586 0.111 ESE
306 / 5	UNITED CEREBRAL PALS	2360 NORTH FOREST	NY Spills	1090 0.206 ESE
331 / 5	COMPUSOURCE SYSTEMS,	110 JOHN MUIR DRIVE	NY AST	1203 0.228 East
BL343 / 5		2350 N FOREST RD	NY COOLING TOWERS	1307 0.248 ESE
BL344 / 5	ELLICOTT CREEK FLOOD	2350 NORTH FOREST RO	FINDS	1307 0.248 ESE

Focus Map - 6 - 05531774.2r



Sites
Target Property
Search Buffer
Focus Map - No Sites
Focus Map - Sites
Power Line
Pipe Line
National Priority List Sites
Dept. Defense Sites
Indian Reservations BIA

0 1/8 1/4 Miles

SITE NAME: Metro Rail Expansion Corridor	CLIENT: Watts Architecture & Engineering
ADDRESS: City of Buffalo, Towns of Tonawanda and Amherst	CONTACT: Lisa Connors
CITY/STATE: Buffalo NY	INQUIRY #: 05531774.2r
ZIP: 14228	DATE: 01/11/19

Copyright © 2019 EDR, Inc. © 2015 TomTom Rel. 2015.

MAPPED SITES SUMMARY - FOCUS MAP 6

Target Property:
CITY OF BUFFALO, TOWNS OF TONAWANDA AND AMHERST
BUFFALO, NY 14228

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
F17 / 6	ED TAYLOR LINCOLN ME	3900 MAPLE RD	RCRA NonGen / NLR, FINDS, ECHO, NY MANIF...	TP		
F18 / 6	PREMIER GOURMET	3904 MAPLE RD	FINDS	TP		
F19 / 6	FORMER ED TAYLOR LIN	3900 MAPLE	NY LTANKS, NY Spills	TP		
F20 / 6	ED TAYLOR LINC-MERC.	3900 MAPLE RD.	NY UST	TP		
F21 / 6	STEVE BALDO LINCOLN	3900 MAPLE ROAD	NY AST	TP		
F22 / 6	PREMIER GOURMET	3904 MAPLE RD	NY AIRS	TP		
G23 / 6	GOLDOME	3840 MAPLE ROAD	NY Spills	TP		
28 / 6	UNKNOWN SUBSTANCE	730 ALBERTA DR	NY Spills	TP		
F29 / 6	BRIDGESTONE FIRESTON	3931 MAPLE RD	RCRA NonGen / NLR, FINDS, ECHO	TP		
F30 / 6	FIRESTONE	3931 MAPLE ROAD	NY LTANKS	TP		
F31 / 6	FIRESTONE COMPLETE A	3931 MAPLE ROAD	NY AST	TP		
J36 / 6	WILSON FARMS	1244 NIAGARA FALLS B	NY Spills	TP		
J37 / 6	MACYS - BOULEVARD HO	1255 NIAGARA FALLS B	FINDS, ECHO	TP		
J38 / 6		1255 NIAGRA FALLS BO	NY COOLING TOWERS	TP		
J39 / 6		1255 NIAGARA FALLS B	NY COOLING TOWERS	TP		
J40 / 6	MACYS - BOULEVARD #1	1255 NIAGARA FALLS B	RCRA-CESQG, NY MANIFEST	TP		
J41 / 6	MACYS - BOULEVARD HO	1255 NIAGARA FALLS B	RCRA-CESQG	TP		
J42 / 6	KAUFMANN'S DEPARTMEN	1255 NIAGARA FALLS B	NY UST	TP		
J43 / 6	FURST ARTHUR	1226 NIAGARA FLS BD	EDR Hist Cleaner	TP		
K44 / 6	NIAGARA MOHAWK BOUL.	1227 NIAGARA FALLS B	NY Spills	TP		
K45 / 6	KAUFMANS	1225 NIAGARA FALLS B	NY Spills	TP		
46 / 6	MIDAS DRAINS	1171 NIAGARA FALLS B	NY Spills	TP		
L47 / 6	AUTOMATIC ROLLS/NORT	NIAGARA FALLS BLVD -	NY Spills	TP		
M48 / 6	NYSDOT D257531	RTE 62 INTERSECTION	FINDS, ECHO	TP		
M49 / 6	NYSDOT PROJECT/ACCAD	NIAGARA FALLS BLVD/S	NY Spills	TP		
N50 / 6	FIRESTONE TIRE	NIAGARA FALLS BOULEV	NY LTANKS	TP		
N51 / 6	NFG EXCAVATION	NIAGARA FALLS BLVD/E	NY Spills	TP		
O52 / 6	NYSDOT PROJECT/U-HAU	NIAGARA FALLS BLVD/E	NY Spills	TP		
L65 / 6	CAR FIRE	1009-1025 NIAGARA FA	NY Spills	58	0.011	East
R66 / 6	JIM & DEES ATLANTIC	826 NIAGARA FALLS B	EDR Hist Auto	60	0.011	West
R67 / 6	JIM WOODS TIRE & BAT	826 NIAGARA FALLS BL	NY LTANKS	60	0.011	West
R68 / 6	UNI-MART STORE	NIAGARA FALLS BLV &	NY Spills	60	0.011	East
N70 / 6	FIRESTONE SERVICE CE	955 NIAGARA FALLS BL	NY Spills	61	0.012	East
80 / 6	FORMER GAS STATION	895 NIAGARA FALLS BL	NY Spills	68	0.013	East
83 / 6	SIBLEYS	BLVD MALL 1255 NIAG	FINDS	73	0.014	East
85 / 6	NATIONAL GRID	1084 NIAGARA FALLS B	NY Spills	76	0.014	West
W86 / 6	CORSI AUTO BODY AND	874 NIAGARA FALLS BL	US AIRS	78	0.015	West
W87 / 6	CORSI AUTO BODY AND	874 NIAGARA FALLS BL	FINDS, ECHO	78	0.015	West
N88 / 6	COMMERCIAL SITE	951 NIAGARA FALLS BV	NY Spills	79	0.015	ESE

MAPPED SITES SUMMARY - FOCUS MAP 6

Target Property:
CITY OF BUFFALO, TOWNS OF TONAWANDA AND AMHERST
BUFFALO, NY 14228

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
M92 / 6	MOBIL	N.F.BLVD. & SHERIDAN	NY LTANKS	82	0.016	East
X93 / 6	CARMELLA TERMULLO AN	853-855 NIAGARA FALL	NY Spills	83	0.016	East
X94 / 6	POLE 851 - REAR PARK	853 NIAGARA FALLS BL	NY Spills	83	0.016	East
O95 / 6	SPEEDY AUTO SERVICE	934 NIAGARA FALLS BL	NY AST	83	0.016	West
R96 / 6	ECONOMY CLEANERS	845 NIAGARA FALLS BL	EDR Hist Cleaner	84	0.016	East
Y97 / 6	PEP BOYS #193	1025 NIAGARA FALLS B	NY AST	85	0.016	East
Y98 / 6	PEP BOYS - MANNY MOE	1025 NIAGARA FALLS B	RCRA NonGen / NLR, FINDS, ECHO, NY MANIF...	85	0.016	East
Y99 / 6	PEP BOYS #0193	1025 NIAGARA FALLS B	NY CBS, NY Spills	85	0.016	East
L100 / 6	LATONAS SERVICE	989 NIAGARA FLS BD	EDR Hist Auto	87	0.016	East
Z101 / 6	NYSDOT PROJECT/U-HAU	925 NIAGARA FALLS BL	NY Spills	88	0.017	East
Z102 / 6	BOULEVARD U-HAUL CEN	925 NIAGARA FALLS BO	NY UST	88	0.017	East
Z103 / 6	JOHNS SUPER SHELL SE	925 NIAGARA FLS BD	EDR Hist Auto	88	0.017	East
R104 / 6	FORMER UNI-MART	820 NIAGARA FALLS BL	NY Spills	94	0.018	West
R105 / 6	NOCO EXPRESS S-74	820 NIAGARA FALLS BO	NY UST	94	0.018	West
R106 / 6	JIM WOODS TIRE & BAT	820 NIAGARA FALLS BL	NY UST	94	0.018	West
L111 / 6	FIRESTONE STORES	995 NIAGARA FALLS BL	NY Spills, NY MANIFEST	103	0.020	East
L112 / 6	FIRESTONE COMPLETE A	995 NIAGARA FALLS BO	NY AST	103	0.020	East
L113 / 6	BRIDGESTONE FIRESTON	995 NIAGARA FALLS BL	RCRA NonGen / NLR, FINDS, ECHO	103	0.020	East
AB114 / 6	A F AUTOMOTIVE	733 NIAGARA FALLS BL	RCRA NonGen / NLR, FINDS, ECHO, NY MANIF...	104	0.020	East
AB115 / 6	AMERICAN AUTO WORLD	733 NIAGARA FALLS BL	EDR Hist Auto	104	0.020	East
AB116 / 6	A&F AUTOMOTIVE	733 NIAGARA FALLS BL	NY UST	104	0.020	East
AB117 / 6	AF AUTOMOTIVE	733 NIAGARA FALLS BL	NY Spills	104	0.020	East
AC118 / 6	CARUBA COLLISON	1167 NIAGARA FALLS B	NY Spills	111	0.021	East
AC119 / 6	CARUBBA COLLISION, I	1167 NIAGARA FALLS B	RCRA-CESQG, NY MANIFEST	111	0.021	East
126 / 6	TN. TONAWANDA PARKS	LINCOLN PARK	NY LTANKS	149	0.028	East
AD127 / 6	GOODYEAR AUTO SERVIC	1280 NIAGARA FALLS B	RCRA-CESQG, NY Spills, FINDS, ECHO, NY M...	153	0.029	West
AD128 / 6	GOODYEAR 0462	1280 NIAGARA FALLS B	NY AST	153	0.029	West
AF134 / 6		2980 SHERIDAN DRIVE	ERNS	170	0.032	West
AF135 / 6	MONROE MUFFLER	2980 SHERIDAN DRIVE	NY Spills	170	0.032	West
AF136 / 6	MONRO MUFFLER BRAKE	2980 SHERIDAN DR	EDR Hist Auto	170	0.032	West
AF137 / 6	UNDERGROUND AUTOSOUN	2980 SHERIDAN DR	NY Spills	170	0.032	West
AF142 / 6	MONRO MUFFLER BRAKE	2980 SHERIDAN DR	NY AST, RCRA NonGen / NLR, FINDS, ECHO	183	0.035	West
AG144 / 6	KNOLL SERVICE STATIO	2965 SHERIDAN DR	EDR Hist Auto	193	0.037	West
AG145 / 6	MOBIL OIL CROP SS H4	2965 SHERIDAN DR	RCRA-CESQG, FINDS, ECHO, NY MANIFEST	193	0.037	West
AG146 / 6	MOBIL OIL	2965 SHERIDAN DRIVE	NY LTANKS, NY Spills	193	0.037	West
152 / 6	ZINNIS FRIENDLY SERV	1346 NIAGARA FALLS B	EDR Hist Auto	223	0.042	NW
AF159 / 6	MOBIL OIL	SHERIDAN & NIAGARA F	NY LTANKS	245	0.046	West
AJ160 / 6	STATION 124	48 ALMEDA DR	NY MANIFEST	258	0.049	East
AJ161 / 6	STATION 124	48 ALMEDA DR	RCRA NonGen / NLR, FINDS, ECHO	258	0.049	East

MAPPED SITES SUMMARY - FOCUS MAP 6

Target Property:
CITY OF BUFFALO, TOWNS OF TONAWANDA AND AMHERST
BUFFALO, NY 14228

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
178 / 6	LOUISE RING TANK	61 WREXHAM NORTH	NY Spills	329	0.062	West
AQ190 / 6	COLDEN AUTO COLLISIO	2131 EGGERT RD	EDR Hist Auto	376	0.071	East
AQ191 / 6	MARTY'S AUTOPRO CENT	2131 EGGERT RD	RCRA NonGen / NLR, FINDS, ECHO, NY MANIF...	376	0.071	East
195 / 6	PADMOUNT TRANSFORMER	ALMEDA AVE	NY Spills	384	0.073	East
204 / 6	CURTIS PARK U.P. CHU	748 WOODLAND DR	NY UST	402	0.076	West
AQ208 / 6	TOTAL AUTOMOTIVE INC	2125 EGGERT RD	EDR Hist Auto	445	0.084	East
AQ209 / 6	NORTHTOWN PLAZA CAR	2125 EGGERT RD	NY UST	445	0.084	East
AQ210 / 6	POLE 2109	2125 EGGERT RD	NY Spills	445	0.084	East
AR211 / 6	SEARS #1162	1261 NIAGARA FALLS B	RCRA-CESQG, NY MANIFEST	446	0.084	East
AR212 / 6	BYE BYE BABY #3083	1261 NIAGARA FALLS B	RCRA-CESQG, FINDS, ECHO	446	0.084	East
AR213 / 6	SEARS #1162	1261 NIAGARA FALLS B	FINDS, ECHO	446	0.084	East
219 / 6	TRANSFORMER HIT BY L	205 DALTON DRIVE	NY Spills	549	0.104	West
AU221 / 6	WEGMANS #0082	675 ALBERTA DR	RCRA-CESQG, NY MANIFEST	563	0.107	South
AU222 / 6	WEGMANS #0082	675 ALBERTA DR	FINDS, ECHO	563	0.107	South
AU223 / 6	TRANSFORMER POLE 505	675 ALBERTA DR	NY Spills	563	0.107	South
AW230 / 6	BJ'S AMHERST GAS STA	3050 SHERIDAN DRIVE	NY UST	624	0.118	East
232 / 6	BUFFALO SUB 124	78 ALMEDA DR.	NY Spills	631	0.120	East
AX233 / 6	PRINTS CHARMING	SHERIDAN & EGGERT RO	NY Spills	640	0.121	West
AX234 / 6	HANCOCK FABRICS	EGGERT AND SHERIDAN	NY Spills	640	0.121	West
AX251 / 6	PRINTS CHARMING	2900 SHERIDAN DR	NY UST	664	0.126	West
AX252 / 6	PRINTS CHARMING - TA	2900 SHERIDAN DRIVE	NY LTANKS	664	0.126	West
AW253 / 6	BJS WHOLESALE CLUB #	3056 SHERIDAN DR	RCRA-CESQG	671	0.127	East
AW254 / 6	BJS WHOLESALE CLUB #	3056 SHERIDAN DR	NY MANIFEST	671	0.127	East
AW255 / 6	BJ'S WHOLESALE CLUB	3056 SHERIDAN DRIVE	NY AST	671	0.127	East
AW256 / 6	BJS WHOLESALE CLUB #	3056 SHERIDAN DR	FINDS, ECHO	671	0.127	East
257 / 6	JOE CONTINO RESIDENC	142 DALTON DRIVE	NY LTANKS	682	0.129	West
268 / 6	JACK HANNON	190 MARGARET RD	NY Spills	812	0.154	East
274 / 6	NOCO ENERGY	82 TREADWELL ROAD	NY Spills	856	0.162	West
276 / 6	BJ'S WHOLESALE CLUB	3080 SHERIDAN DR	NY Spills	868	0.164	East
BD279 / 6	ADVANCE AUTO PARTS #	2907 SHERIDAN DR	RCRA-SQG	910	0.172	West
BD280 / 6	ADVANCE AUTO PARTS #	2907 SHERIDAN DR	FINDS, ECHO	910	0.172	West
BE281 / 6	SAVERS STORE #1217	2309 EGGERT RD	RCRA-CESQG, FINDS, ECHO	927	0.176	West
BE282 / 6	SAVERS #1217	2309 EGGERT RD	NY MANIFEST	927	0.176	West
285 / 6	TANK AT LINDKE RESID	25 QUAKER RIDGE	NY Spills	941	0.178	West
291 / 6		95 TREADWELL AVE	ERNS	996	0.189	West
BG293 / 6	NORTHTOWN ONE HOUR C	3075 SHERIDAN DR	EDR Hist Cleaner	1012	0.192	East
BG294 / 6	GI-RO DRY CLEANERS	3077 SHERIDAN DR?NOR	ICIS, US AIRS	1015	0.192	East
BG295 / 6	JOSEPHS SERVICES	3077 SHERIDAN DRIVE	EDR Hist Cleaner	1015	0.192	East
BG296 / 6	GI-RO/NORTHTOWN CLEA	3077 SHERIDAN DRIVE,	NY DRYCLEANERS	1015	0.192	East

MAPPED SITES SUMMARY - FOCUS MAP 6

Target Property:
CITY OF BUFFALO, TOWNS OF TONAWANDA AND AMHERST
BUFFALO, NY 14228

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
BG297 / 6	NORTHTOWN ONE HOUR C	3077 SHERIDAN DR	RCRA NonGen / NLR, FINDS, ECHO, NY MANIF...	1015	0.192	East
BG302 / 6	NORTHTOWN INC	3097 SHERIDAN DR	RCRA NonGen / NLR, FINDS, ECHO, NY MANIF...	1042	0.197	East
BG303 / 6	NORTHTOWN INC.	3097 SHERIDAN DRIVE	NY ENG CONTROLS, NY INST CONTROL, NY BRO	1042	0.197	East
BG304 / 6	NORTHTOWN PLAZA	3097 SHERIDAN DR	NY UST	1042	0.197	East
305 / 6	WORLD AUTO PAINTING	2880 SHERIDAN DR	RCRA NonGen / NLR, FINDS, ECHO, NY MANIF...	1060	0.201	West
BG307 / 6	NORTHTOWN TEXACO SER	3120 SHERIDAN DR	EDR Hist Auto	1107	0.210	East
311 / 6	NATIONAL FUEL GAS CO	104 LONGMEADOW AVE	RCRA NonGen / NLR, FINDS, ECHO	1134	0.215	East
316 / 6	NATIONAL GRID POLE 2	2352 EGGERT RD	NY Spills	1150	0.218	West
338 / 6	NOCO TRUCK	216 NORTH WREXHAM	NY Spills	1285	0.243	West
341 / 6	GRAND ISLAND SLS SV	190 MEADOW LEA	EDR Hist Auto	1295	0.245	East
346 / 6	WHITE CRYSTALLINE MA	674 HARRISON STREET	NY Spills	1318	0.250	West

Focus Map - 7 - 05531774.2r



Sites
Target Property
Search Buffer
Focus Map - No Sites
Focus Map - Sites
Power Line
Pipe Line
National Priority List Sites
Dept. Defense Sites
Indian Reservations BIA

0 1/8 1/4 Miles

SITE NAME: Metro Rail Expansion Corridor	CLIENT: Watts Architecture & Engineering
ADDRESS: City of Buffalo, Towns of Tonawanda and Amherst	CONTACT: Lisa Connors
CITY/STATE: Buffalo NY	INQUIRY #: 05531774.2r
ZIP: 14228	DATE: 01/11/19

Copyright © 2019 EDR, Inc. © 2015 TomTom Rel. 2015.

MAPPED SITES SUMMARY - FOCUS MAP 7

Target Property:
CITY OF BUFFALO, TOWNS OF TONAWANDA AND AMHERST
BUFFALO, NY 14228

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
E24 / 7	NOCO ENERGY STATION	MAPLE AND SWEETHOME	NY LTANKS	TP		
25 / 7	GAS STATION	4146 MAPLE ROAD	NY Spills	TP		
H26 / 7	UNIVERSITY MOBILE ST	4264 MAPLE RD	EDR Hist Auto	TP		
27 / 7	NIAGARA MOHAWK TRANS	NORTH BAILEY & MAPLE	NY Spills	TP		
I32 / 7		4053 MAPLE RD	NY COOLING TOWERS	TP		
I33 / 7		4053 MAPLE RD	NY COOLING TOWERS	TP		
I34 / 7		4053 MAPLE RD	NY COOLING TOWERS	TP		
35 / 7	NIAGARA MOHAWK TRANS	4215 MAPLE ROAD	NY Spills	TP		
V77 / 7	SWEETHOME JUNIOR HIG	4150 MAPLE RD	NY UST, NY Spills	65	0.012	North
V78 / 7		4150 MAPLE RD.	NY COOLING TOWERS	65	0.012	North
H121 / 7	NOCO	4265 MAPLE ROAD	NY Spills	120	0.023	South
H122 / 7	DUKARMS SERVICE	4265 MAPLE RD	EDR Hist Auto	120	0.023	South
H123 / 7	NOCO EXPRESS S-24	4265 MAPLE ROAD	NY UST	120	0.023	South
H124 / 7	NOCO EXPRESS # 24	4265 MAPLE ROAD	FINDS	120	0.023	South
125 / 7	POLE 1038	1038 SWEET HOME ROAD	NY Spills	147	0.028	SSE
AI155 / 7	HERRSCHER'S EXPRESS	4291 MAPLE ROAD	ICIS, FINDS, ECHO	237	0.045	SE
AI156 / 7	EZ MART	4291 MAPLE RD	NY LTANKS, NY UST, NY Spills	237	0.045	SE
AI157 / 7	ERINS AUTOMOTIVE & T	4291 MAPLE RD	EDR Hist Auto	237	0.045	SE
AI158 / 7	MAPLE SUNOCO	4291 MAPLE RD	NY Spills	237	0.045	SE
180 / 7	ELMER SPAETH	392 HOMECREST DRIVE	NY Spills	349	0.066	South
217 / 7	RESIDENCE	405 HOMECREST DRIVE	NY Spills	524	0.099	South
BF289 / 7		300 CORPORATE PKWY	NY COOLING TOWERS	985	0.187	SE
BF290 / 7		300 CORPORATE PKWY	NY COOLING TOWERS	985	0.187	SE

Focus Map - 8 - 05531774.2r



Sites
Target Property
Search Buffer
Focus Map - No Sites
Focus Map - Sites
Power Line
Pipe Line
National Priority List Sites
Dept. Defense Sites
Indian Reservations BIA

0 1/8 1/4 Miles

SITE NAME: Metro Rail Expansion Corridor	CLIENT: Watts Architecture & Engineering
ADDRESS: City of Buffalo, Towns of Tonawanda and Amherst	CONTACT: Lisa Connors
CITY/STATE: Buffalo NY	INQUIRY #: 05531774.2r
ZIP: 14228	DATE: 01/11/19

Copyright © 2019 EDR, Inc. © 2015 TomTom Rel. 2015.

MAPPED SITES SUMMARY - FOCUS MAP 8

Target Property:
CITY OF BUFFALO, TOWNS OF TONAWANDA AND AMHERST
BUFFALO, NY 14228

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
53 / 8	BIG JOHN RESTAURANT	BIG JOHN RESTAURANT	NY Spills	TP		
P54 / 8	MOBIL OI CORP SS #HA	3514 MAIN ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIF...	TP		
P55 / 8	MOBIL OIL	3514 MAIN STREET	NY LTANKS	TP		
P56 / 8	BLACKWELLS PLAZA SER	3514 MAIN ST	EDR Hist Auto	TP		
P57 / 8	NIAGARA MOHAWK A NAT	KENMORE AVE & MAIN S	RCRA NonGen / NLR, NY MANIFEST	TP		
P58 / 8	UNIVERSITY PLAZA	3500 MAIN STREET	NY Spills	TP		
P59 / 8	AJ WRIGHT	3500 MAIN ST	NY Spills	TP		
P60 / 8	NIAGARA MOHAWK A NAT	KENMORE AVE & MAIN S	FINDS, ECHO	TP		
T73 / 8	GREAT LAKES DIVERS	240 NIAGARA FALLS BL	NY UST	64	0.012	West
T74 / 8	BROWN GEORGE A	240-246 NIAGARA FALL	EDR Hist Auto	64	0.012	West
79 / 8	SHELDON RESIDENCE	333 NIAGARA FALLS BL	NY Spills	67	0.013	East
P81 / 8	MOBIL OIL 08-D5Y	MAIN STREET AT WINSP	NY Spills	69	0.013	NE
P82 / 8	MOBIL	MAIN & KENMORE	NY Spills	69	0.013	NE
AA107 / 8	SWEENEYS GARAGE AUTO	424 NIAGARA FALLS B	EDR Hist Auto	95	0.018	West
AA108 / 8	SWEENEY'S GARAGE	424 NIAGARA FALLS BL	NY LTANKS, NY Spills	95	0.018	West
T109 / 8	POPPLETON RESIDENCE	232 NIAGARA FALLS BL	NY Spills	96	0.018	West
T110 / 8	BOB HILLS OLD GAS ST	240 NIAGARA FALLS BL	NY LTANKS	97	0.018	West
120 / 8	PROULX RESIDENCE	383 NIAGARA FALLS BL	NY Spills	113	0.021	East
AE129 / 8	BUSH EDW BLVD FRONTI	175 KENMORE AVE	EDR Hist Auto	158	0.030	SW
AE130 / 8	KWIK FILL MO325.325	175 KENMORE AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIF...	158	0.030	SW
AE131 / 8	RED APPLE FOOD MART	175 KENMORE AVE	NY UST	158	0.030	SW
AE132 / 8	KWIKFILL	175 KENMORE AVE	NY LTANKS, NY Spills	158	0.030	SW
P138 / 8	ROW	MAIN AND KENMORE	NY Spills	172	0.033	NE
147 / 8	BURLINGTON TRUCK ROL	I290 & NIAGARA FALLS	NY Spills	200	0.038	East
148 / 8	SWEENEY'S GARAGE	PAIGE AT NIAGARA FAL	NY Spills	204	0.039	East
149 / 8	WRIGHT DRUM	4 HAWTHORNE AVENUE	NY Spills	206	0.039	West
150 / 8	MCKAY HEATING PLANT	3545 MAIN ST.	NY Spills	206	0.039	NE
AH151 / 8	SOUTHLAND CORP. 7-EL	MAIN STREET AT WINDE	NY LTANKS	208	0.039	SW
AH153 / 8	BASIL FORD	MAIN STREET AT WINDE	NY Spills	225	0.043	SW
AH154 / 8	FORMER BASIL FORD	MAIN & WINDEMERE AVE	NY Spills	231	0.044	SSW
170 / 8	WASTE OIL	CHALMERS AND KETTERI	NY Spills	282	0.053	West
AH172 / 8	7- ELEVEN STORE #224	3488 MAIN STREET	NY UST	298	0.056	SSW
AH173 / 8	7-ELEVEN #22491	3488 MAIN ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIF...	298	0.056	SSW
AH174 / 8	KENDALL REFG CO FILL	3488 MAIN ST	EDR Hist Auto	298	0.056	SSW
AH175 / 8	WALGREENS PARKING LO	3488 MAIN STREET	NY Spills	298	0.056	SSW
AH176 / 8	7-ELEVEN STORE #2249	3488 MAIN STREET	NY Spills	298	0.056	SSW
AL177 / 8	SUNY AT BUFFALO - NO	SERVICE BUILDING	NY AST	302	0.057	NW
AO182 / 8	BASIL FORD	3484 MAIN STREET	NY LTANKS, NY AST	350	0.066	South
AO183 / 8	BASIL FORD INC.	3484 MAIN STREET	NY UST	350	0.066	South

MAPPED SITES SUMMARY - FOCUS MAP 8

Target Property:
CITY OF BUFFALO, TOWNS OF TONAWANDA AND AMHERST
BUFFALO, NY 14228

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
AO184 / 8	BASIL FORD	3484 MAIN ST	RCRA-CESQG, FINDS, ECHO, NY MANIFEST	350	0.066	South
AP186 / 8	STATE UNIVERSTIY CON	SUNY AT BUFFALO 3435	RCRA NonGen / NLR	356	0.067	NW
AP192 / 8	GAS FROM CAR AT UB	SUNY AT BUFFALO	NY Spills	384	0.073	NW
AP193 / 8	SUNY AT BUFFALO	ATCHISON HALL SUNYAB	NY Spills	384	0.073	NW
AP194 / 8	SUNY AT BUFFALO	MAIN STREET	NY Spills	384	0.073	NW
AP196 / 8	BUFFALO COLLEGE	3435 MAIN ST AT MAIN	NY Spills	387	0.073	NW
AP197 / 8	SUNY AT BUFFALO - SO	3435 MAIN ST	NY AIRS, NY SPDES	387	0.073	NW
AP198 / 8	STATE UNIVERSITY OF	3435 MAIN ST	PA MANIFEST	387	0.073	NW
AP199 / 8	SUNY AT BUFFALO - SO	3435 MAIN STREET	ICIS, FINDS, ECHO	387	0.073	NW
AP200 / 8	UNIVERSITY OF BUFFAL	3435 MAIN STREET	NY LTANKS, NY Spills	387	0.073	NW
AP201 / 8	STATE UNIVERSITY OF	3435 MAIN ST	RCRA-LQG, US AIRS, WI MANIFEST	387	0.073	NW
AP202 / 8	UB - SOUTH CAMPUS	MAIN	NY Spills	394	0.075	NW
203 / 8	OIL DUMPING AT ALLEN	441 ALLENHURST ROAD	NY Spills	400	0.076	East
AP207 / 8	STATE UNIVERSTIY CON	SUNY AT BUFFALO 3435	FINDS, ECHO	424	0.080	NW
AL215 / 8	BELL ATLANTIC	MAIN ST & CAPEN BLVD	NY MANIFEST	475	0.090	NW
216 / 8	KEATING JOS P GAS ST	3384 MAIN ST	EDR Hist Auto	490	0.093	WNW
218 / 8	NEW OPPORTUNITIES CO	245 HAWTHORNE AVE	NY Spills	524	0.099	West
AT220 / 8	KWIK KLEEN INC BR SW	3584 MAIN ST	EDR Hist Cleaner	550	0.104	NE
227 / 8	MOBIL S/S 08-HA1	3514 MAIN & KENMORE	NY LTANKS, NY UST	585	0.111	NNE
231 / 8	ORKEN LAWNCARE	514 CAPEN BOULEVARD	NY LTANKS	630	0.119	East
AT258 / 8	PARKHILL & HART LNDR	3586 MAIN ST	EDR Hist Cleaner	684	0.130	NE
270 / 8	RESIDENTIAL	151 CAPEN BLVD	NY Spills	845	0.160	East
BB271 / 8	BENDERSON DEVELOPEME	3608 MAIN STREET	NY Spills	850	0.161	NE
BC272 / 8	NIAGARA MOHAWK - LYN	123 LYNDALE AVENUE	NY Spills	855	0.162	West
BC273 / 8		123 LYNDALE AVE	ERNS	855	0.162	West
BB278 / 8	BLACKWELL PLAZA SERV	3614 MAIN ST	EDR Hist Auto	893	0.169	NE
283 / 8	DOUG AL AUTOMOTIVE A	252 KENMORE AVE	EDR Hist Auto	933	0.177	WSW
286 / 8	BASEMENT	8 RADCLIFFE RD.	NY Spills	952	0.180	SSW
BB287 / 8	EDDIES ASHLAND SERVI	3620 MAIN ST	EDR Hist Auto	970	0.184	NE
BB292 / 8	FRONTIER OIL CO BR G	3624 MAIN ST	EDR Hist Auto	1008	0.191	NE
298 / 8	BOULEVARD INN & SUIT	3612 MAIN ST.	NY Spills	1028	0.195	NE
308 / 8	JOAN MILLEY TANK	45 CONANT STREET	NY LTANKS	1110	0.210	West
309 / 8	FURMAN RESIDENCE	99 CONANT AVENUE	NY LTANKS	1120	0.212	West
BI313 / 8	AMHERST CSD - WINDER	291 WINDERMERE BLVD	FINDS, ECHO	1150	0.218	East
BI314 / 8	WINDERMERE BLVD SCHO	291 WINDERMERE BLVD	NY LTANKS, NY UST	1150	0.218	East
BI315 / 8	AMHERST CSD - WINDER	291 WINDERMERE BLVD	RCRA-CESQG	1150	0.218	East
329 / 8	HOUSE	381 WINDERMERE	NY Spills	1161	0.220	East
330 / 8		174 UNIVERSITY AVENU	ERNS	1167	0.221	WSW
333 / 8	WASTE OIL IN YARD	224 UNIVERSITY AVENU	NY Spills	1219	0.231	West

MAPPED SITES SUMMARY - FOCUS MAP 8

Target Property:
CITY OF BUFFALO, TOWNS OF TONAWANDA AND AMHERST
BUFFALO, NY 14228

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
335 / 8	NYSDOT BIN 1001590	MAIN ST OVER NY RT 1	FINDS, ECHO	1228	0.233	WSW
340 / 8	PRINCETON HOUSING AS	165 PRINCETON AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIF...	1294	0.245	NNE
342 / 8	SEAN MAGIERSKI RESID	73 MONTROSE AVE	NY Spills	1301	0.246	SW

Focus Map - 9 - 05531774.2r

SITE NAME: Metro Rail Expansion Corridor	CLIENT: Watts Architecture & Engineering
ADDRESS: City of Buffalo, Towns of Tonawanda and Amherst	CONTACT: Lisa Connors
CITY/STATE: Buffalo NY	INQUIRY #: 05531774.2r
ZIP: 14228	DATE: 01/11/19

Copyright © 2019 EDR, Inc. © 2015 TomTom Rel. 2015.

MAPPED SITES SUMMARY - FOCUS MAP 9

Target Property:
CITY OF BUFFALO, TOWNS OF TONAWANDA AND AMHERST
BUFFALO, NY 14228

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION
334 / 9		3640 MAIN ST	ERNS	1221 0.231 NE

1
Target Property
MUIR WOODS DEVELOPMENT
1081 & 1121 N FRENCH RD
GETZVILLE, NY 14221

FINDS **1016353244**
N/A

FINDS:

Actual: 575 ft.

Registry ID: 110040178189

Focus Map: 2

Environmental Interest/Information System
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

A2
Target Property
500 JOHN JAMES AUDOBON
AMHERST, NY

ERNS **92132164**
N/A

Site 1 of 7 in cluster A

Actual: 577 ft.

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

Focus Map: 2

A3
Target Property
VZW AUDUBON
500 JOHN JAMES AUDUBON PKWY
AMHERST, NY 14228

FINDS **1016700579**
N/A

Site 2 of 7 in cluster A

Actual: 577 ft.

FINDS:

Focus Map: 2

Registry ID: 110056392210

Environmental Interest/Information System
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

A4 **NY COOLING TOWERS** **S121996787**
Target Property **500 JOHN JAMES AUDUBON PKWY** **N/A**
AMHERST, NY 14228

Site 3 of 7 in cluster A

Actual: 577 ft.
Focus Map: 2

COOLING TOWERS:

Equipment Unique ID:	7280
Equipment Borough:	500
Intended Use:	Air Conditioning
Manufacturer:	Baltimore Aircoil Company
Model:	J1205-B33R
Cooling Capacity:	5
Cooling Capacity Unit:	Tonnage
Commissioned Date:	10/01/1999
Inspection Date:	10/01/2015
Date of Bacteriological Collection:	10/01/2015
Date of Legionella Collection:	09/24/2015
Last Legionella Result > 1,000 CFU/mL:	no
Latitude:	43.018239269
Longitude:	-78.782716189

A5 **TOWN OF AMHERST POLICE DEPT.** **ICIS** **1009324337**
Target Property **500 JOHN JAMES AUDUBON PKWY** **FINDS** **N/A**
AMHERST, NY 14228 **ECHO**

Site 4 of 7 in cluster A

Actual: 577 ft.
Focus Map: 2

ICIS:

Enforcement Action ID:	02-2008-7946
FRS ID:	110024276503
Action Name:	Town of Amherst Police Department
Facility Name:	TOWN OF AMHERST POLICE DEPARTMENT
Facility Address:	500 JOHN JAMES AUDUBON PARKWAY, AMHERST, NY 14228
Enforcement Action Type:	RCRA 9006 AO For Comp And/Or Pen (UST) - UST Expedited Settlement Program
Facility County:	ERIE
Program System Acronym:	ICIS
Enforcement Action Forum Desc:	Administrative - Formal
EA Type Code:	9006E
Facility SIC Code:	Not reported
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	43.018245
Longitude in Decimal Degrees:	-78.782753
Permit Type Desc:	Not reported
Program System Acronym:	7731382
Facility NAICS Code:	Not reported
Tribal Land Code:	Not reported

Facility Name:	TOWN OF AMHERST POLICE DEPARTMENT
Address:	500 JOHN JAMES AUDUBON PARKWAY,
Tribal Indicator:	N
Fed Facility:	No
NAIC Code:	Not reported
SIC Code:	9221

FINDS:

TOWN OF AMHERST POLICE DEPT. (Continued) **1009324337**

Registry ID: 110024276503

Environmental Interest/Information System

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1009324337
Registry ID:	110024276503
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110024276503

A6 **TOWN OF AMHERST POLICE DEPT.** **NY AST** **U003318311**
Target Property **500 JOHN JAMES AUDUBON PKWY** **N/A**
AMHERST, NY 14228

Site 5 of 7 in cluster A

Actual: 577 ft.

Focus Map: 2

AST:

Region:	STATE
DEC Region:	9
Site Status:	Active
Facility Id:	9-446882
Program Type:	PBS
UTM X:	191926.49966
UTM Y:	4769716.97433
Expiration Date:	07/28/2023
Site Type:	Municipality (Incl. Waste Water Treatment Plants, Utilities, Swimming Pools, etc.)

Affiliation Records:

Site Id:	54442
Affiliation Type:	Facility Owner
Company Name:	TOWN OF AMHERST POLICE DEPARTMENT
Contact Type:	TECHNICAL SERVICES OFFICER
Contact Name:	THOMAS BARILLARI
Address1:	500 JOHN JAMES AUDUBON PARKWAY
Address2:	Not reported
City:	AMHERST
State:	NY
Zip Code:	14228
Country Code:	001
Phone:	(716) 689-1311
EMail:	Not reported

TOWN OF AMHERST POLICE DEPT. (Continued) **U003318311**

Fax Number:	Not reported
Modified By:	VMKREUTZ
Date Last Modified:	2018-06-20

Site Id:	54442
Affiliation Type:	Mail Contact
Company Name:	AMHERST POLICE DEPT.
Contact Type:	Not reported
Contact Name:	THOMAS BARILLARI
Address1:	500 JOHN JAMES AUDUBON PKWY
Address2:	Not reported
City:	AMHERST
State:	NY
Zip Code:	14228
Country Code:	001
Phone:	(716) 689-1311
EMail:	Not reported
Fax Number:	Not reported
Modified By:	AESKALSK
Date Last Modified:	2017-04-11

Site Id:	54442
Affiliation Type:	Facility Operator
Company Name:	TOWN OF AMHERST POLICE DEPT.
Contact Type:	Not reported
Contact Name:	THOMAS BARILLARI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(716) 689-1311
EMail:	Not reported
Fax Number:	Not reported
Modified By:	AYLAGATI
Date Last Modified:	2017-02-09

Site Id:	54442
Affiliation Type:	Emergency Contact
Company Name:	TOWN OF AMHERST POLICE DEPARTMENT
Contact Type:	Not reported
Contact Name:	CAPT. KEVIN BROWN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(716) 689-1311
EMail:	Not reported
Fax Number:	Not reported
Modified By:	VMKREUTZ
Date Last Modified:	2018-06-20

Tank Info:

TOWN OF AMHERST POLICE DEPT. (Continued) **U003318311**

Tank Number: 200
Tank Id: 173916
Material Code: 0008
Common Name of Substance: Diesel

Equipment Records:

D01 - Pipe Type - Steel/Carbon Steel/Iron
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)
A99 - Tank Internal Protection - Other
C01 - Pipe Location - Aboveground
G04 - Tank Secondary Containment - Double-Walled (Underground)
L00 - Piping Leak Detection - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 12/01/1998
Capacity Gallons: 275
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: AESKALSK
Last Modified: 04/14/2017
Material Name: diesel

Tank Number: 200D
Tank Id: 234586
Material Code: 0008
Common Name of Substance: Diesel

Equipment Records:

K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
E00 - Piping Secondary Containment - None
F00 - Pipe External Protection - None
C00 - Pipe Location - No Piping
G00 - Tank Secondary Containment - None
I04 - Overfill - Product Level Gauge (A/G)
J00 - Dispenser - None
L00 - Piping Leak Detection - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
D00 - Pipe Type - No Piping

Tank Location: 2
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 12/01/1998

TOWN OF AMHERST POLICE DEPT. (Continued) **U003318311**

Capacity Gallons:	50
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	AESKALSK
Last Modified:	04/14/2017
Material Name:	diesel

Tank Number:	201D
Tank Id:	276256

Equipment Records:

F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
C01 - Pipe Location - Aboveground
G04 - Tank Secondary Containment - Double-Walled (Underground)
L00 - Piping Leak Detection - None

Tank Location:	2
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	11/07/2017
Capacity Gallons:	70
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	VMKREUTZ
Last Modified:	06/20/2018
Material Name:	diesel

Tank Number:	300
Tank Id:	173917
Material Code:	0013
Common Name of Substance:	Lube Oil

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
L09 - Piping Leak Detection - Exempt Suction Piping
C01 - Pipe Location - Aboveground

TOWN OF AMHERST POLICE DEPT. (Continued) **U003318311**

I04 - Overfill - Product Level Gauge (A/G)
G04 - Tank Secondary Containment - Double-Walled (Underground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location:	2
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	12/01/1990
Capacity Gallons:	200
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	AESKALSK
Last Modified:	04/14/2017
Material Name:	lube oil

A7
Target Property
TOWN OF AMHERST POLICE DEPT.
500 JOHN JAMES AUDUBON PKWY
AMHERST, NY 14228

NY UST **U004064695**
N/A

Site 6 of 7 in cluster A

Actual:
577 ft.

Focus Map:
2

UST:

Id/Status:	9-446882 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	9
Expiration Date:	07/28/2023
UTM X:	191926.49966
UTM Y:	4769716.97433
Site Type:	Municipality (Incl. Waste Water Treatment Plants, Utilities, Swimming Pools, etc.)

Affiliation Records:

Site Id:	54442
Affiliation Type:	Facility Owner
Company Name:	TOWN OF AMHERST POLICE DEPARTMENT
Contact Type:	TECHNICAL SERVICES OFFICER
Contact Name:	THOMAS BARILLARI
Address1:	500 JOHN JAMES AUDUBON PARKWAY
Address2:	Not reported
City:	AMHERST
State:	NY
Zip Code:	14228
Country Code:	001
Phone:	(716) 689-1311
EMail:	Not reported
Fax Number:	Not reported
Modified By:	VMKREUTZ
Date Last Modified:	2018-06-20

Site Id:	54442
Affiliation Type:	Mail Contact
Company Name:	AMHERST POLICE DEPT.
Contact Type:	Not reported
Contact Name:	THOMAS BARILLARI
Address1:	500 JOHN JAMES AUDUBON PKWY

TOWN OF AMHERST POLICE DEPT. (Continued) **U004064695**

Address2:	Not reported
City:	AMHERST
State:	NY
Zip Code:	14228
Country Code:	001
Phone:	(716) 689-1311
EMail:	Not reported
Fax Number:	Not reported
Modified By:	AESKALSK
Date Last Modified:	2017-04-11

Site Id:	54442
Affiliation Type:	Facility Operator
Company Name:	TOWN OF AMHERST POLICE DEPT.
Contact Type:	Not reported
Contact Name:	THOMAS BARILLARI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(716) 689-1311
EMail:	Not reported
Fax Number:	Not reported
Modified By:	AYLAGATI
Date Last Modified:	2017-02-09

Site Id:	54442
Affiliation Type:	Emergency Contact
Company Name:	TOWN OF AMHERST POLICE DEPARTMENT
Contact Type:	Not reported
Contact Name:	CAPT. KEVIN BROWN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(716) 689-1311
EMail:	Not reported
Fax Number:	Not reported
Modified By:	VMKREUTZ
Date Last Modified:	2018-06-20

Tank Info:

Tank Number:	1
Tank ID:	167931
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	5000
Install Date:	05/01/1979
Date Tank Closed:	12/01/1997
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel

TOWN OF AMHERST POLICE DEPT. (Continued) **U004064695**

Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 03
Date Test: 08/01/1995
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
I00 - Overfill - None
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
D99 - Pipe Type - Other

Tank Number: 100
Tank ID: 172986
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 5000
Install Date: 12/01/1997
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 21
Date Test: 05/07/2010
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: PTDIEZ
Last Modified: 07/21/2017

Equipment Records:

H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
D08 - Pipe Type - Equivalent Technology
J01 - Dispenser - Pressurized Dispenser
E04 - Piping Secondary Containment - Double walled UG
C02 - Pipe Location - Underground/On-ground
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
G04 - Tank Secondary Containment - Double-Walled (Underground)
F99 - Pipe External Protection - Other
L07 - Piping Leak Detection - Pressurized Piping Leak Detector

Tank Number: 2

TOWN OF AMHERST POLICE DEPT. (Continued) **U004064695**

Tank ID: 167932
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 15000
Install Date: 05/01/1979
Date Tank Closed: 12/01/1995
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: 05
Date Test: 08/01/1989
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping

Tank Number: 400
Tank ID: 173918
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 500
Install Date: 12/01/1990
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Fiberglass coated steel
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Tightness Test Method: 21
Date Test: 05/07/2010
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: AESKALSK
Last Modified: 04/14/2017

Equipment Records:

D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
E00 - Piping Secondary Containment - None
K01 - Spill Prevention - Catch Basin
B02 - Tank External Protection - Original Sacrificial Anode
C00 - Pipe Location - No Piping

TOWN OF AMHERST POLICE DEPT. (Continued) **U004064695**

F00 - Pipe External Protection - None
H02 - Tank Leak Detection - Interstitial - Manual Monitoring
A00 - Tank Internal Protection - None
I01 - Overfill - Float Vent Valve
J00 - Dispenser - None
G04 - Tank Secondary Containment - Double-Walled (Underground)

A8 **AMHERST PD** **NY LTANKS** **S101659197**
Target **500 JOHN JAMES PARKWAY** **N/A**
Property **AMHERST, NY**

Site 7 of 7 in cluster A

Actual: **577 ft.**
Focus Map: **2**

LTANKS:

Spill Number/Closed Date:	9408494 / 1995-06-15
Facility ID:	9408494
Site ID:	225772
Spill Date:	1994-09-26
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B3
Cleanup Ceased:	1995-06-15
SWIS:	1522
Investigator:	SORGI
Referred To:	Not reported
Reported to Dept:	1994-09-26
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	1995-06-15
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1994-10-03
Spill Record Last Update:	2002-03-25
Spiller Name:	Not reported
Spiller Company:	AMHERST POLICE DEPT
Spiller Address:	500 JOHN JAMES PARKWAY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	9
DER Facility ID:	186359
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MJS 10/03/94: MJS REVIEW FILE. CONTACTED RP AND GAVE OPTIONS. TANK TO BE RETESTED NEXT WEEK. RP WILL INFORM OF DATE. LETTER TO RP. 12/19/94: MJS TELECON FROM RP. WATER HAS FLOWED INTO TANK FROM TOP PUSHING OUT PETRO. MJS TO INPECT AT 1130 HRS AND MEET W/ RP. AMHERST WAITING FOR BIDS FROM CONTRACTORS FOR REMOVAL. 12/19/94: 1130 HRS - MJS SITE INSPECT. MET W/ JEFF BURROUGHS AND PAUL FREIHEIT. HEAVY OIL LAYER ON WATER IN EXCAVATION. TANK FAILED RETEST. BIDS DUE ON 12/21/94. THEY WILL INFORM OF START DATE. 12/23/94: MJS TELECON W/ JEFF BURROUGHS. ELMWOOD WILL DO CLEANUP. JOB TO START WEEK OF 1/2/95. EMERGENCY GENERATOR A/G TANK MUST BE SET BEFORE TANK CAN BE REMOVED. OIL IN EXC WILL BE REMOVED WEKK OF 12/26/94. 12/28/94: MJS TELECON W/ MR BURROUGHS. ELMWOOD TO PUMP OUT OIL THIS WEEK. HE IS TRYING TO

AMHERST PD (Continued) **S101659197**

AVOID FORMAL BIDDING PROCESS BECAUSE THIS WOULD TAKE APPROX 2 MONTHS. 12/29/94: LETTER TO TOWN OF AMHERST(RP). TANK MUST BE REMOVED WITHIN 30 DAYS. 01/10/95: MJS MET W/ MR BURROUGHS. TOWN PROPOSES TO CLOSE TANK IN PLACE. ELEC CONDUIT RUNS DIRECTLY OVER TANK. MJS SUGGESTED REMOVAL OF TANK. MR BURROUGHS WILL INFORM OF FINAL DECISION. 01/19/95: MJS TELECON W/ MR BURROUGHS. TOWN WILL REMOVE TANK. CONTRACTOR MOVING ELEC CONDUIT TODAY. TANK SCHEDULED FOR REMOVAL WEEK OF 1/23. MR BURROUGHS TO INFORM OF START DATE. 02/02/95: MJS INSPECT. CONDUITS MOVED. NO WORK TODAY. MJS TELECON W/ JOE KLOC. JUNCTION BOX IS PLACE 2' FROM TANK AND SHORING MAY BE NECESSARY. MJS TELECON MR BURROUGHS. TOWN MAY TEMP REMOVE BOX FOR REMOVAL. 02/08/95: MJS TELECON W/ MR BURROUGHS. TANK SCHEDULED FOR REMOVAL TOMORROW. MJS WILL INSPECT. 02/09/95: 1030 HRS - MJS INSPECT. MET W/ MR BURROUGHS, MR FREIHEIT AND MR KLOC. TANK REMOVED. CONTAM SOIL IN TANK PIT FLOOR. MJS INFORMED MR BURROUGHS THAT SOIL MUST BE REMOVED AND DISPOSED. HE AGREED. 02/09/95: 1430 HRS - MJS INSPECT. CONTAM SOIL REMOVED AND STAGED ON PLASTIC. EXCAVATION BACKFILLED. EXCAVATION SAMPLE TAKEN. 02/14/95: SOIL DISPOSAL LETTER TO MR BURROUGHS. RESPONSE DUE 3/1/95. 03/02/95: RECEIVED ANALYTICAL RESULTS FOR TANK PIT EXCAVATION AND CONTAM SOIL PILE. NO VIOLATIONS OF GIUDANCE VALUES. NEED DISPOSAL DOCUMENTATION FOR CLOSURE OF FILE. 03/10/95: RECEIVED FAILING TANK TEST REPORT FROM JEFF BURROUGHS. 03/13/95: LETTER TO JEFF BURROUGHS. DISPOSAL RECEIPTS NEEDED FOR CLOSURE. 06/15/95: RECEIVED DISPOSAL RECEIPT FOR SOIL FROM ELMWOOD TANK. 12 TONS DISPOSED AT LAKEVIEW LANDFILL. FILE COMPLETE. NO FURTHER ACTION REQUIRED. MJS CLOSE FILE. "
Not reported

Remarks: "15000 GAL FUEL OIL TANK FAILED TIGHTNESS TEST."

All TTF:

Facility ID:	9408494
Spill Number:	9408494
Spill Tank Test:	1543178
Site ID:	225772
Tank Number:	Not reported
Tank Size:	0
Material:	0008
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	225772
Operable Unit ID:	1006197
Operable Unit:	01
Material ID:	377929
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00

AMHERST PD (Continued) **S101659197**

Units: L
Recovered: .00
Oxygenate: Not reported

---

9 **AMHERST-T SENIOR CITIZEN CENTER** **FINDS** **1007814111**
Target Property **370 JOHN JAMES AUDUBON PARKWAY** **N/A**
AMHERST, NY 14221

FINDS:

Actual: 579 ft.

Registry ID: 110019766591

Focus Map: 2

Environmental Interest/Information System

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

B10 **NY COOLING TOWERS** **S121999288**
Target Property **2410 NORTH FOREST ROAD** **N/A**
AMHERST, NY 14068

Site 1 of 5 in cluster B

Actual: 576 ft.

COOLING TOWERS:

Focus Map: 5

Equipment Unique ID:	9891
Equipment Borough:	2410
Intended Use:	Air Conditioning
Manufacturer:	Aaon
Model:	RL-075-3-0-CF04-222
Cooling Capacity:	75
Cooling Capacity Unit:	Tonnage
Commissioned Date:	10/04/2010
Inspection Date:	Not reported
Date of Bacteriological Collection:	Not reported
Date of Legionella Collection:	Not reported
Last Legionella Result > 1,000 CFU/mL:	no
Latitude:	43.010048434
Longitude:	-78.777646357

B11 **ISKALO OFFICE BLDG** **FINDS** **1016393312**
Target Property **2410 N FOREST RD** **N/A**
GETZVILLE, NY 14226

Site 2 of 5 in cluster B

Actual: 576 ft.

FINDS:

Focus Map: 5

Registry ID: 110055271067

Environmental Interest/Information System

ISKALO OFFICE BLDG (Continued) **1016393312**

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

B12 **NY COOLING TOWERS** **S121999285**
Target Property **2410 N FOREST RD** **N/A**
AMHERST, NY 14068

Site 3 of 5 in cluster B

Actual: 576 ft.
Focus Map: 5

COOLING TOWERS:

Equipment Unique ID:	9889
Equipment Borough:	2410
Intended Use:	Air Conditioning
Manufacturer:	Aaon
Model:	RL-075-3-0-CF04-222
Cooling Capacity:	75
Cooling Capacity Unit:	Tonnage
Commissioned Date:	10/04/2010
Inspection Date:	Not reported
Date of Bacteriological Collection:	Not reported
Date of Legionella Collection:	Not reported
Last Legionella Result > 1,000 CFU/mL:	no
Latitude:	43.010048434
Longitude:	-78.777646357

---

13 **ELLICOTT CREEK** **NY Spills** **S108058417**
Target Property **INTER JOHNS JAMES AUDUBON** **N/A**
AMHERST, NY

Actual: 570 ft.
Focus Map: 5

SPILLS:

Spill Number/Closed Date:	0604084 / 2006-07-17
Facility ID:	0604084
Facility Type:	ER
DER Facility ID:	316992
Site ID:	366967
DEC Region:	9
Spill Cause:	Unknown
Spill Class:	E6
SWIS:	1522
Spill Date:	2006-07-13
Investigator:	SACALAND
Referred To:	TOWN OF AMHERST
Reported to Dept:	2006-07-13
CID:	444
Water Affected:	ELLICOTT CREEK
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	2006-07-13
Recommended Penalty:	False

ELLICOTT CREEK (Continued) **S108058417**

UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-07-13
Spill Record Last Update:	2006-07-17
Spiller Name:	MICHEAL
Spiller Company:	ELLICOTT CREEK
Spiller Address:	INTER JOHNS JAMES ADUBON
Spiller Company:	001
Contact Name:	MICHEAL
DEC Memo:	"7/13/06:SAC TELECON JIM ZYMANEK - TOWN OF AMHERST DISASTER COORDINATOR AND FIRE CHIEF. SAC ASKED IF THERE HAD BEEN ANY SEWER DYING THAT HAD BEEN DONE. MR. ZYMANEK SAID HE KNOWS THERE HAS BEEN WORK DONE IN THE AREA AND THAT HE WOULD CHECK TO SEE IF THERE AS BEEN ANYTHING RECENT. HEAVY RAINS FROM THE DAY BEFORE MAY HAVE FLUSHED THE DYE INTO THE CREEK. 7/14/06:SAC DISCUSS COMPLAINT W/RMC. RMC HAS BEEN IN THE WILLLIAMSVILLE/AMHERST AREA AROUND ELLICOTT CREEK AND HAS OBSERVED ALGAE BLOOMS WITH BRIGHT GREEN COLOR. COMPLAINT IS MOST LIKELY ATTRIBUTABLE TO THAT. 7/17/06:SAC TELECON JIM ZYMANEK. MR. ZYMANEK SAID THAT HE INSPECTED AND COULD NOT VERIFY COMPLAINT. HE FELT THAT WHATEVER DYE MAY HAVE RINSED INTO THE CREEK FROM THE RAIN HAD DEGRADED AND COULD NO LONGER BE OBSERVED. HE ALSO ACKNOWLEDGED THE PRESENCE OF A ALGAE IN THE CREEK. NO SPILL, THEREFORE NO FURTHER ACTION REQUIRED. COMPUTER FILE ONLY - NO PAPER FILE."
Remarks:	"LOOKS LIKE A GREENISH COLOR, UNSURE WHERE OR WHAT HAPPENED"

All Materials:

Site ID:	366967
Operable Unit ID:	1124893
Operable Unit:	01
Material ID:	2114400
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Site ID:	366967
Operable Unit ID:	1124893
Operable Unit:	01
Material ID:	2114399
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

C14 **BALL PUMP STATION AND TANKS** **RCRA-SQG** **1007990567**
Target **SWEET HOME RD** **NYR000130872**
Property **AMHERST, NY 14226**

Site 1 of 3 in cluster C

Actual: **597 ft.**

Focus Map: **4**

RCRA-SQG:

Date form received by agency:	01/01/2007
Facility name:	BALL PUMP STATION AND TANKS
Facility address:	SWEET HOME RD AMHERST, NY 14226
EPA ID:	NYR000130872
Mailing address:	UNION RD CHEEKTOWAGA, NY 14226
Contact:	THOMAS J WIK
Contact address:	UNION RD CHEEKTOWAGA, NY 14226
Contact country:	US
Contact telephone:	716-685-8233
Telephone ext.:	WIK
Contact email:	TWIK@ECWA.ORG
EPA Region:	02
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	ERIE COUNTY WATER AUTHORITY
Owner/operator address:	UNION RD CHEEKTOWAGA, NY 14227
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Municipal
Owner/Operator Type:	Owner
Owner/Op start date:	01/01/1972
Owner/Op end date:	Not reported

Owner/operator name:	NO NAME FOUND
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Municipal
Owner/Operator Type:	Operator
Owner/Op start date:	01/01/1972
Owner/Op end date:	Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No

BALL PUMP STATION AND TANKS (Continued) **1007990567**

Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: BALL PUMP STATION AND TANKS
Classification: Small Quantity Generator

Date form received by agency: 12/19/2005
Site name: BALL PUMP STATION AND TANKS
Classification: Large Quantity Generator

. Waste code: D008
. Waste name: LEAD

Date form received by agency: 02/24/2005
Site name: BALL PUMP STATION & TANKS
Classification: Large Quantity Generator

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

D15 **NYSDOT BIN 1-07260-1** **FINDS** **1016255709**
Target **I290 SB BRG OVER SWEET HOME RD** **ECHO** **N/A**
Property **AMHERST, NY 14228**

Site 1 of 2 in cluster D

Actual: 600 ft.

FINDS:

Focus Map: 4

Registry ID: 110008107020

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

NYSDOT BIN 1-07260-1 (Continued) **1016255709**

ECHO:
Envid: 1016255709
Registry ID: 110008107020
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110008107020

E16 Target Property **NORTH CAMP RV & MARINE** **NY LTANKS** **S100250621**
MAPLE & SWEETHOME **N/A**
AMHERST, NY

Site 1 of 2 in cluster E

Actual: 596 ft.
Focus Map: 4

LTANKS:
Spill Number/Closed Date: 8606881 / 1987-04-16
Facility ID: 8606881
Site ID: 76709
Spill Date: 1987-02-09
Spill Cause: Tank Failure
Spill Source: Gasoline Station or other PBS Facility
Spill Class: Not reported
Cleanup Ceased: 1987-04-16
SWIS: 1522
Investigator: PRINGLE
Referred To: Not reported
Reported to Dept: 1987-02-09
CID: Not reported
Water Affected: Not reported
Spill Notifier: Citizen
Last Inspection: 1987-04-16
Recommended Penalty: False
Meets Standard: True
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 1987-02-10
Spill Record Last Update: 1987-04-30
Spiller Name: Not reported
Spiller Company: NORTHCAMP RV & MARINE
Spiller Address: 4291 MAPLE RD
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 9
DER Facility ID: 71661
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was MNP / / : INVENTORY RECORDS & SITE INSP. NEEDED. / / : MNP SITE INSP. 2/20/87, NO OBSV. WELLS AT STATION, INV. RECORDS TO BE SENT;. / / : LETTER 3/16/87, REPLY 3/23/87;TELECON W/INSINNA 3/30/87, 2 TANKS FAILED PETROTITE, TO BE REMOVED;HOLD FOR REMOVAL & NOTIFICATION. / / : MNP SITE INSP. 2/20/87, NO OBSV. WELLS AT STATION, INV. RECORDS TO BE SENT; LETTER 03/16/87, REPLY 03/23/87 - NG, NO REPLY. / / : MNP SITE INSP. 4/14,16/87, 2 TANKS REMOVED, NO CONTAMINATION FOUND;NO FURTHER ACTION NEEDED. "
Remarks: "SUSPECT LEAKING UNDERGROUND TANK"

All Materials:
Site ID: 76709
Operable Unit ID: 904487
Operable Unit: 01

NORTH CAMP RV & MARINE (Continued) **S100250621**

Material ID:	472435
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

F17 **ED TAYLOR LINCOLN MERCURY** **RCRA NonGen / NLR** **1000555652**
Target **3900 MAPLE RD** **FINDS** **NYD986981934**
Property **AMHERST, NY 14226** **ECHO**
NY MANIFEST

Site 1 of 9 in cluster F

Actual: **584 ft.**

Focus Map: **6**

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	ED TAYLOR LINCOLN MERCURY
Facility address:	3900 MAPLE RD AMHERST, NY 14226-1091
EPA ID:	NYD986981934
Mailing address:	MAPLE RD AMHERST, NY 14226
Contact:	Not reported
Contact address:	MAPLE RD AMHERST, NY 14226
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	ED TAYLOR
Owner/operator address:	UNKNOWN UNKNOWN, NY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	ED TAYLOR
Owner/operator address:	UNKNOWN UNKNOWN, NY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported

ED TAYLOR LINCOLN MERCURY (Continued) **1000555652**

Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: ED TAYLOR LINCOLN MERCURY
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: ED TAYLOR LINCOLN MERCURY
Classification: Not a generator, verified

Date form received by agency: 10/10/1991
Site name: ED TAYLOR LINCOLN MERCURY
Classification: Small Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Violation Status: No violations found

FINDS:

Registry ID: 110004480464

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport,

ED TAYLOR LINCOLN MERCURY (Continued) **1000555652**

and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000555652
Registry ID:	110004480464
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004480464

NY MANIFEST:

Country:	USA
EPA ID:	NYD986981934
Facility Status:	Not reported
Location Address 1:	3900 MAPLE ROAD
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	AMHERST
Location State:	NY
Location Zip:	14226
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD986981934
Mailing Name:	TAYLOR (ED) LINCOLN
Mailing Contact:	ROBERT ORTT
Mailing Address 1:	3900 MAPLE ROAD
Mailing Address 2:	Not reported
Mailing City:	AMHERST
Mailing State:	NY
Mailing Zip:	14226
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7168382600

NY MANIFEST:

Document ID:	PAC9223373
Manifest Status:	C
seq:	Not reported
Year:	1993
Trans1 State ID:	PAAH0172
Trans2 State ID:	Not reported
Generator Ship Date:	07/14/1993
Trans1 Recv Date:	07/14/1993
Trans2 Recv Date:	/ /
TSD Site Recv Date:	07/19/1993
Part A Recv Date:	07/21/1993
Part B Recv Date:	07/30/1993
Generator EPA ID:	NYD986981934
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD981737109

ED TAYLOR LINCOLN MERCURY (Continued) **1000555652**

TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00075
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

F18
Target
Property

PREMIER GOURMET **FINDS** **1016401455**
3904 MAPLE RD **N/A**
AMHERST, NY 14226

Site 2 of 9 in cluster F

Actual:
584 ft.

FINDS:

Focus Map:
6

Registry ID: 110055353308

Environmental Interest/Information System

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access
additional FINDS: detail in the EDR Site Report.

F19 **FORMER ED TAYLOR LINCOLN MERCURY** **NY LTANKS** **S110308839**
Target **3900 MAPLE** **NY Spills** **N/A**
Property **AMHERST, NY 14226**

Site 3 of 9 in cluster F

Actual: **584 ft.**

Focus Map: **6**

LTANKS:

Spill Number/Closed Date:	9201849 / 1994-04-25
Facility ID:	9201849
Site ID:	292060
Spill Date:	1992-05-14
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	1994-04-25
SWIS:	1522
Investigator:	SORGI
Referred To:	Not reported
Reported to Dept:	1992-05-14
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	1992-05-20
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1992-05-18
Spill Record Last Update:	2007-09-17
Spiller Name:	ROBERT ORT
Spiller Company:	ED TAYLOR LINCOLN MERCURY
Spiller Address:	3900 MAPLE ROAD
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	9
DER Facility ID:	236464
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MJS 05/20/92: MJS SITE INSPECTION, MET BOB ORT FROM PARTS DEPT. MJS CHECKED SOIL PILE. APPROX 25 YARDS ON PLASTIC AND COVERED. HEAVY PETRO ODOR. 05/21/92: MSJ SENT LETTER TO MR ORT. 04/20/94: MJS REVIEW FILE. NEED DISPOSAL RECEIPT FOR SOIL. MJS SENT LETTER TO RP. 04/25/94: MJS RECEIVED DISPOSAL DOCUMENTATION FROM RP. NO FURTHER ACTION REQUIRED. MJS CLOSE FILE. "
Remarks:	"CONTAMINATION FOUND DURING TANK REMOVAL."

All Materials:

Site ID:	292060
Operable Unit ID:	969274
Operable Unit:	01
Material ID:	413138
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

FORMER ED TAYLOR LINCOLN MERCURY (Continued) **S110308839**

SPILLS:

Spill Number/Closed Date:	1001596 / 2011-06-23
Facility ID:	1001596
Facility Type:	ER
DER Facility ID:	389530
Site ID:	434662
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	1522
Spill Date:	2010-05-11
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	2010-05-11
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	2011-06-20
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2010-05-11
Spill Record Last Update:	2011-06-23
Spiller Name:	EDWARD TAYLOR
Spiller Company:	EDWARD TAYLOR
Spiller Address:	7 ROCK DOVE LANE
Spiller Company:	001
Contact Name:	ED TAYLOR
DEC Memo:	"05/12/10 RMC/SITE. EXCAVATION FOR TWO LIFTS WAS THOUGHT TO BE COMPLETED. PRODUCT ON WATER IN BOTH EXCAVATIONS. EXCAVATION TO CONTINUE. RMC TO REINSPECT. 05/24/10 RMC/FILE. WENT BACK TO THE SITE SEVERAL MORE TIMES. NO ONE ON SITE. COULD SEE THROUGH THE GARAGE DOORS THAT EXCAVATIONS STILL OPEN. CALLED MARK HANNA LAST WEEK. HE WILL ARRANGE ANOTHER INSPECTION. CALL DUE 6/1/10. 07/13/10 RMC/FILE. MET MARK HANNA ON SITE LAST MONTH AFTER ADDITIONAL EXCAVATIONS. WATER IN EXCAVATION STILL HEAVILY CONTAMINAED WITH HYDRAULIC OIL. OIL SEEMS TO BE UNIFORM ACROSS THE INTERIOR OF THE BUILDING. ALSO NEED ADDITIONAL WORK FOR OTHER PETROLEUM CONTAMINATION ON THE EAST END OF THE BUILDING. ULTIMATE USE OF THE BUILDING NOT YET DETERMINED. UPDATE 7/30/10. 11/17/10 RMC/FILE. CONTACTED MARK HANNA, PRP HAS NOT AUTHORIZED ANY FURTHER WORK ON THE SITE. 11/18/10 RMC/FILE. SENT PRP LETTER REQUESTING ASSESSMENT AND RAP. UPDATE 12/10/10. 11/23/10 RMC/ED TAYLOR/PHONE. MR TAYLOR WAS IN THE BUILDING AND THINKS THE OIL IN THE HOLES IS GONE NOW. RMC ASKED IT ANYONE PULLED LIQUID FROM THE EXCAVAITONS AND CHECKED IT. THEY DID NOT. RMC TOLD MR TAYLOR THAT DEC HAS ALREADY CHECKED THE SITE TWO DIFFERENT TIMES WHEN THE OIL WAS GONE AND RMC FOUND A HEAVY SHEEN TO THICK LAYER OF WHAT APPEARS TO BE HYDRAULIC OIL IN EVERY EXCAVATION. HE WILL TALK TO HIS CONSULTANT(S) AND GET BACK TO DEC. RMC REQUESTED THAY THE PREVIOUS PHASE I AND II REPORTS BE SUBMITTED AND A WORK TO DATE REPORT BE GENERATED. DUE 12/10/10 02/11/11 RMC/FILE. CONTACTED MARK HANNA AND ED TAYLOR. REPORTS TO BE SUBMITTED ASAP. ALSO PLAN ON TAKING THE BUILDING DOWN SOON. PLATES WILL BE PUT OVER THE EXCAVATIONS. 03/03/11 RMC/FILE. RECEIVED 10/07 PHASE I BY TETRA TECH. BUILDING BUILD IN 1968 APPEARS

FORMER ED TAYLOR LINCOLN MERCURY (Continued) **S110308839**

TO BE ALWAYS USED AS A DEALERSHIP. ALSO RECEIVED ANALYTICAL RESULTS FROM 10/8/10. NO LOCATION MAP, NO NARRATIVE, JUST RESULTS. 03/11/11 RMC/MARK HANNA PHONE. BUILDING DOWN. HE WANTS TO KNOW WHAT WE WANT. RMC ADVISED ASSESSMENT CAPABLE OF DETERMINING JUST HOW BIG OF AN AREA PRODUCES HYDRAULIC OIL ONCE A TEST PIT IS OPEN AND A PLAN TO CLEAN UP THE WASTE OIL AREA ON THE EAST SIDE OF THE BUILDING. UPDATE 4/1/11 05/12/11 RMC/SITE. ALSO INSPECTED SITE LAST MONTH WITH HANNA. THREE AREAS NEEDED FURTHER WORK IN LAST INSPECTION. THESE AREAS HAVE BEEN FURTHER EXCAVATED. CONTRACTOR REPORTED AND RMC CONFIRMED THAT SHEEN CONTINUES IN 2 OF 3 EXCAVATIONS. TWO TANKS PREVIOUSLY FILLED WITH CONCRETE NEED TO BE CUT AND CLEANED, CONCRETE IS CONTAMINATED. SOIL STILL ON SITE FOR DISPOSAL. 05/16/11 RMC/HANNA/PHONE. HE TALKED WITH SUTTON WILL TALK AGAIN ABOUT ORC. RMC ADVISED THAT TO DATE NO REPORT ON WORK HAS BEEN SUBMITTED. UPDATE 5/30/11. 05/20/11 RMC/FILE. ORC WORK PLAN RECEIVED AND APPROVED BY GS. 06/23/11 RMC/FILE. REVIEWED 6/17/11 CLOSURE REPORT. ORC WAS COMPLETED PER THE 5/19/11 PLAN. DISPOSED OF 1125 TONS IMPACTED SOIL, 2 DRUMS, 60000 GALLONS IMPACTED WATER. 2 ORPHAN USTS WERE REMOVED. POST EXCAVATION RESULTS SHOW NO EXCEEDACNES. SHEEN STILL PRODUCED IN AREAS OF THE OLD BUILDING. SITE TO BE MADE INACTIVE. LETTER "

Remarks: "while pulling in floor hydraulic lifts, discovered petroleum contamination. Digging to clean, there are 9 lifts at the facility. Discovered petroleum contamination at the first will continue to report if additional contamination is discovered. will collect excavation samples and leave the hole open for 1 day."

All Materials:

Site ID:	434662
Operable Unit ID:	1185475
Operable Unit:	01
Material ID:	2179837
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	9975473 / 1999-12-09
Facility ID:	9975473
Facility Type:	ER
DER Facility ID:	142428
Site ID:	169140
DEC Region:	9
Spill Cause:	Housekeeping
Spill Class:	D6
SWIS:	1522
Spill Date:	1999-10-13
Investigator:	SORGI
Referred To:	Not reported
Reported to Dept:	1999-10-13
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Local Agency

FORMER ED TAYLOR LINCOLN MERCURY (Continued) **S110308839**

Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	1999-10-13
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-10-13
Spill Record Last Update:	1999-12-24
Spiller Name:	Not reported
Spiller Company:	JOSEPH MYLES (PAVER)
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MJS 10/13/99: MJS TOOK REPORT FROM MR BECKER, TOWN OF AMHERST. HE RECEIVED COMPLAINT THAT PAVING COMPANY WAS DUMPING MATERIAL DOWN STORM SEWERS. MR BECKER STATED THAT HE INSPECTED SITE AND FOUND THAT THEY ARE NOT DUMPING BUT DUE TO SLOPPY HOUSEKEEPING, A SMALL AMOUNT OF MATERIAL DID ENTER SEWER RECEIVERS DURING APPLICATION OF TACK COAT. PETROLEUM SHEEN IN SOME RECEIVERS. MR BECKER ASKED THAT DEC INSPECT. 10/13/99: MJS SITE INSPECTION, CHECKED STORM RECEIVERS AND FOUND PETROLEUM SHEEN FROM MATERIAL DRIBBLING INTO RECEIVER, NO PRODUCT. THIS IS A MINOR INCIDENT. NO CLEANUP NECESSARY. 10/14/99: MJS TELECON TO RP AND ADVISED HIM TO TAKE MORE CARE. HE APOLOGIZED FOR SLOPPINESS. 12/09/99: MJS REVIEW FILE. NO FURTHER ACTION NECESSARY. MJS CLOSE FILE."
Remarks:	"MR BECKER INSPECTED THIS SITE BASED ON A COMPLAINT HE RECEIVED THAT THE PAVING COMPANY WORKING ON THE ED TAYLOR LOT IS DUMPING MATERIAL DOWN THE STORM SEWER."

All Materials:

Site ID:	169140
Operable Unit ID:	1093860
Operable Unit:	01
Material ID:	292033
Material Code:	0018A
Material Name:	tar
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Site ID:	169140
Operable Unit ID:	1093860
Operable Unit:	01
Material ID:	292032
Material Code:	0004B
Material Name:	blacktop
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

F20 **ED TAYLOR LINC-MERC. INC.** **NY UST** **U004081090**
Target **3900 MAPLE RD.** **N/A**
Property **AMHERST, NY 14226**

Site 4 of 9 in cluster F

Actual:
584 ft.

Focus Map:
6

UST:

Id/Status:	9-444146 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	9
Expiration Date:	N/A
UTM X:	188603.83302
UTM Y:	4766898.55341
Site Type:	Other Wholesale/Retail Sales

Affiliation Records:

Site Id:	54389
Affiliation Type:	Facility Owner
Company Name:	EDWARD H TAYLOR
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	90 THERIN DR.
Address2:	Not reported
City:	HAMBURG
State:	NY
Zip Code:	14075
Country Code:	001
Phone:	(716) 838-2600
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	54389
Affiliation Type:	Mail Contact
Company Name:	EDWARD H TAYLOR
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	90 THERIN DR.
Address2:	Not reported
City:	HAMBURG
State:	NY
Zip Code:	14075
Country Code:	001
Phone:	(716) 838-2600
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	54389
Affiliation Type:	Facility Operator
Company Name:	ED TAYLOR LINC-MERC. INC.
Contact Type:	Not reported
Contact Name:	ED TAYLOR LINC-MERC.,INC.
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN

ED TAYLOR LINC-MERC. INC. (Continued) **U004081090**

Zip Code:	Not reported
Country Code:	001
Phone:	(716) 838-2600
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	54389
Affiliation Type:	Emergency Contact
Company Name:	EDWARD H TAYLOR
Contact Type:	Not reported
Contact Name:	EDWARD H. TAYLOR
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(716) 648-1919
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	1
Tank ID:	167799
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	1000
Install Date:	05/01/1980
Date Tank Closed:	02/01/1992
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None

ED TAYLOR LINC-MERC. INC. (Continued) **U004081090**

Tank Number:	2
Tank ID:	167800
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	290
Install Date:	01/01/1975
Date Tank Closed:	08/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
D02 - Pipe Type - Galvanized Steel
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
F01 - Pipe External Protection - Painted/Asphalt Coating

Tank Number:	7
Tank ID:	238949
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	1000
Install Date:	Not reported
Date Tank Closed:	04/21/2011
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	aeskalsk
Last Modified:	04/14/2017

Equipment Records:

J00 - Dispenser - None
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None

ED TAYLOR LINC-MERC. INC. (Continued) **U004081090**

C00 - Pipe Location - No Piping
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None

F21 **STEVE BALDO LINCOLN MERCURY** **NY AST** **U003318272**
Target **3900 MAPLE ROAD** **N/A**
Property **AMHERST, NY 14226**

Site 5 of 9 in cluster F

Actual: **584 ft.**

Focus Map: **6**

AST:

Region:	STATE
DEC Region:	9
Site Status:	Unregulated/Closed
Facility Id:	9-600542
Program Type:	PBS
UTM X:	188603.83302
UTM Y:	4766898.55341
Expiration Date:	N/A
Site Type:	Other Wholesale/Retail Sales

Affiliation Records:

Site Id:	55387
Affiliation Type:	Mail Contact
Company Name:	STEVE BALDO LINCOLN MERCURY
Contact Type:	Not reported
Contact Name:	BOB ORTT
Address1:	3900 MAPLE ROAD
Address2:	Not reported
City:	AMHERST
State:	NY
Zip Code:	14226
Country Code:	001
Phone:	(716) 838-2600
EMail:	Not reported
Fax Number:	Not reported
Modified By:	AESKALSK
Date Last Modified:	2006-03-22

Site Id:	55387
Affiliation Type:	Facility Operator
Company Name:	STEVE BALDO LINCOLN MERCURY
Contact Type:	Not reported
Contact Name:	ROBERT ORTT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NY
Zip Code:	Not reported
Country Code:	001
Phone:	(716) 838-2600
EMail:	Not reported
Fax Number:	Not reported
Modified By:	bfgraber
Date Last Modified:	2007-11-06

Site Id:	55387
Affiliation Type:	Emergency Contact

STEVE BALDO LINCOLN MERCURY (Continued) **U003318272**

Company Name:	STEVE BALDO
Contact Type:	Not reported
Contact Name:	ROBERT ORTT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(716) 838-2600
EMail:	Not reported
Fax Number:	Not reported
Modified By:	bfgraber
Date Last Modified:	2007-11-06

Site Id:	55387
Affiliation Type:	Facility Owner
Company Name:	STEVE BALDO
Contact Type:	PARTS MANAGER
Contact Name:	ROBERT ORTT
Address1:	3900 MAPLE RD
Address2:	Not reported
City:	AMHERST
State:	NY
Zip Code:	14226
Country Code:	001
Phone:	(716) 838-2600
EMail:	Not reported
Fax Number:	Not reported
Modified By:	bfgraber
Date Last Modified:	2007-11-06

Tank Info:

Tank Number:	01
Tank Id:	174232
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

E00 - Piping Secondary Containment - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D07 - Pipe Type - Plastic
K00 - Spill Prevention - None
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
G01 - Tank Secondary Containment - Diking (Aboveground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported

STEVE BALDO LINCOLN MERCURY (Continued) **U003318272**

Install Date:	06/01/1999
Capacity Gallons:	250
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	09/01/2007
Register:	True
Modified By:	aeskalsk
Last Modified:	04/14/2017
Material Name:	waste oil/used oil

Tank Number:	02
Tank Id:	210639
Material Code:	0013
Common Name of Substance:	Lube Oil

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
E00 - Piping Secondary Containment - None
L09 - Piping Leak Detection - Exempt Suction Piping
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	330
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	09/01/2007
Register:	True
Modified By:	aeskalsk
Last Modified:	04/14/2017
Material Name:	lube oil

Tank Number:	03
Tank Id:	210640
Material Code:	0013
Common Name of Substance:	Lube Oil

Equipment Records:

E00 - Piping Secondary Containment - None
L09 - Piping Leak Detection - Exempt Suction Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

STEVE BALDO LINCOLN MERCURY (Continued) **U003318272**

C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	09/01/2007
Register:	True
Modified By:	aeskalsk
Last Modified:	04/14/2017
Material Name:	lube oil

Tank Number:	4
Tank Id:	167801
Material Code:	9999
Common Name of Substance:	Other

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
A01 - Tank Internal Protection - Epoxy Liner
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G99 - Tank Secondary Containment - Other

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	04/01/1988
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	other

Tank Number:	5

STEVE BALDO LINCOLN MERCURY (Continued) **U003318272**

Tank Id: 167802
Material Code: 9999
Common Name of Substance: Other

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
A01 - Tank Internal Protection - Epoxy Liner
D01 - Pipe Type - Steel/Carbon Steel/Iron
G99 - Tank Secondary Containment - Other

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 04/01/1988
Capacity Gallons: 275
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: TRANSLAT
Last Modified: 04/14/2017
Material Name: other

Tank Number: 6
Tank Id: 167803
Material Code: 9999
Common Name of Substance: Other

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
A01 - Tank Internal Protection - Epoxy Liner
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G99 - Tank Secondary Containment - Other

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 04/01/1988
Capacity Gallons: 260
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported

STEVE BALDO LINCOLN MERCURY (Continued) **U003318272**

Date Tank Closed: Not reported
Register: True
Modified By: TRANSLAT
Last Modified: 04/14/2017
Material Name: other

Affiliation Records:
Site Id: 54389
Affiliation Type: Facility Owner
Company Name: EDWARD H TAYLOR
Contact Type: Not reported
Contact Name: Not reported
Address1: 90 THERIN DR.
Address2: Not reported
City: HAMBURG
State: NY
Zip Code: 14075
Country Code: 001
Phone: (716) 838-2600
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 54389
Affiliation Type: Mail Contact
Company Name: EDWARD H TAYLOR
Contact Type: Not reported
Contact Name: Not reported
Address1: 90 THERIN DR.
Address2: Not reported
City: HAMBURG
State: NY
Zip Code: 14075
Country Code: 001
Phone: (716) 838-2600
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 54389
Affiliation Type: Facility Operator
Company Name: ED TAYLOR LINC-MERC. INC.
Contact Type: Not reported
Contact Name: ED TAYLOR LINC-MERC.,INC.
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (716) 838-2600
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

STEVE BALDO LINCOLN MERCURY (Continued) **U003318272**

Site Id:	54389
Affiliation Type:	Emergency Contact
Company Name:	EDWARD H TAYLOR
Contact Type:	Not reported
Contact Name:	EDWARD H. TAYLOR
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(716) 648-1919
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	01
Tank Id:	174232
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

E00 - Piping Secondary Containment - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D07 - Pipe Type - Plastic
K00 - Spill Prevention - None
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
G01 - Tank Secondary Containment - Diking (Aboveground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	06/01/1999
Capacity Gallons:	250
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	09/01/2007
Register:	True
Modified By:	aeskalsk
Last Modified:	04/14/2017
Material Name:	waste oil/used oil

Tank Number:	02
Tank Id:	210639
Material Code:	0013

STEVE BALDO LINCOLN MERCURY (Continued) **U003318272**

Common Name of Substance: Lube Oil

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
E00 - Piping Secondary Containment - None
L09 - Piping Leak Detection - Exempt Suction Piping
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 330
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 09/01/2007
Register: True
Modified By: aeskalsk
Last Modified: 04/14/2017
Material Name: lube oil

Tank Number: 03
Tank Id: 210640
Material Code: 0013
Common Name of Substance: Lube Oil

Equipment Records:

E00 - Piping Secondary Containment - None
L09 - Piping Leak Detection - Exempt Suction Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 275
Tightness Test Method: NN

STEVE BALDO LINCOLN MERCURY (Continued) **U003318272**

Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 09/01/2007
Register: True
Modified By: aeskalsk
Last Modified: 04/14/2017
Material Name: lube oil

Tank Number: 4
Tank Id: 167801
Material Code: 9999
Common Name of Substance: Other

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
A01 - Tank Internal Protection - Epoxy Liner
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G99 - Tank Secondary Containment - Other

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 04/01/1988
Capacity Gallons: 275
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: TRANSLAT
Last Modified: 04/14/2017
Material Name: other

Tank Number: 5
Tank Id: 167802
Material Code: 9999
Common Name of Substance: Other

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
A01 - Tank Internal Protection - Epoxy Liner
D01 - Pipe Type - Steel/Carbon Steel/Iron

STEVE BALDO LINCOLN MERCURY (Continued) **U003318272**

G99 - Tank Secondary Containment - Other

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	04/01/1988
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	other

Tank Number:	6
Tank Id:	167803
Material Code:	9999
Common Name of Substance:	Other

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
A01 - Tank Internal Protection - Epoxy Liner
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G99 - Tank Secondary Containment - Other

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	04/01/1988
Capacity Gallons:	260
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	other

F22 **PREMIER GOURMET** **NY AIRS** **S121492793**
Target **3904 MAPLE RD** **N/A**
Property **AMHERST, NY 14226**

Site 6 of 9 in cluster F

Actual: **584 ft.**
Focus Map: **6**

AIRS:

Permit Type:	AFR
Permit Status:	Issued
Issue Date:	05/16/2012
Expiration Date:	Not reported
County Fips:	Not reported
DEC Id:	9142200545
Emission Unit Id:	Not reported
Process Id:	Not reported
Contaminant Name/cas:	Not reported
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	Not reported
Unit:	Not reported
Auth Type Code:	2
Latitude:	Not reported
Longitude:	Not reported

G23 **GOLDOME** **NY Spills** **S104497560**
Target **3840 MAPLE ROAD** **N/A**
Property **AMHERST, NY**

Site 1 of 3 in cluster G

Actual: **584 ft.**
Focus Map: **6**

SPILLS:

Spill Number/Closed Date:	8702308 / 1987-06-25
Facility ID:	8702308
Facility Type:	ER
DER Facility ID:	192836
Site ID:	234040
DEC Region:	9
Spill Cause:	Unknown
Spill Class:	D6
SWIS:	1522
Spill Date:	1987-06-17
Investigator:	ROSS
Referred To:	Not reported
Reported to Dept:	1987-06-17
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Fire Department
Cleanup Ceased:	1987-06-25
Cleanup Meets Std:	True
Last Inspection:	1987-06-25
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1987-06-22
Spill Record Last Update:	2000-07-25
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999

GOLDOME (Continued) **S104497560**

Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was LQR / / : RLL SITE INSP. 06/17/87, CONTAMINATION FOUND, REFERRED TO SPILL UNIT 06/17/87. / / : LQR SITE INSP. NO CONTAMINATION FOUND. "
Remarks: ""

All Materials:
Site ID: 234040
Operable Unit ID: 906598
Operable Unit: 01
Material ID: 468610
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

E24 Target Property **NOCO ENERGY STATION** **NY LTANKS** **S102960661**
MAPLE AND SWEETHOME **N/A**
AMHERST, NY

Site 2 of 2 in cluster E

Actual: 595 ft.
Focus Map: 7

LTANKS:
Spill Number/Closed Date: 9709710 / 1998-03-11
Facility ID: 9709710
Site ID: 199745
Spill Date: 1997-11-19
Spill Cause: Tank Overfill
Spill Source: Gasoline Station or other PBS Facility
Spill Class: B3
Cleanup Ceased: Not reported
SWIS: 1522
Investigator: COOKE
Referred To: Not reported
Reported to Dept: 1997-11-20
CID: 999
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 1997-11-20
Spill Record Last Update: 1998-03-17
Spiller Name: GARY ROESCH
Spiller Company: NOCO ENERGY
Spiller Address: 700 GRAND ISLAND BLVD
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 9

NOCO ENERGY STATION (Continued) **S102960661**

DER Facility ID: 166230
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was JDC 12/2/97: INSPECTED SITE AND FOUND REMOVAL OF TANKS AND SOIL COMPLETED. JDC SENT GENERAL CLEANUP LETTER. 12/23/97: JDC RECEIVED POST TEST RESULTS AND FOUND MINOR VIOLATIONS OF STARS. SOIL DISPOSED OF TO NOCO'S FACILITY. BASED ON THIS INFORMATION SITE WILL BE MADE INACTIVE. NO FURTHER ACTION REQUIRED. "
Remarks: "2 -10 k fiberglass and 1-4k tank removed contamination soil found all spills being tranported to river road treatment facility at noco"

All Materials:
Site ID: 199745
Operable Unit ID: 1052741
Operable Unit: 01
Material ID: 328042
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Site ID: 199745
Operable Unit ID: 1052741
Operable Unit: 01
Material ID: 328043
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

---

25 **GAS STATION** **NY Spills** **S110612014**
Target **4146 MAPLE ROAD** **N/A**
Property **AMHERST, NY 14226**

Actual: **599 ft.**
Focus Map: **7**

SPILLS:
Spill Number/Closed Date: 1008446 / 2010-12-15
Facility ID: 1008446
Facility Type: ER
DER Facility ID: 396959
Site ID: 441937
DEC Region: 9
Spill Cause: Equipment Failure
Spill Class: C3
SWIS: 1522
Spill Date: 2010-11-11
Investigator: RJJONAK
Referred To: Not reported
Reported to Dept: 2010-11-11
CID: Not reported
Water Affected: Not reported

GAS STATION (Continued) **S110612014**

Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	DEC
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-11-11
Spill Record Last Update:	2010-12-15
Spiller Name:	ARUNDEEH VIG
Spiller Company:	ARUNDEEH VIG
Spiller Address:	4146 MAPLE ROAD
Spiller Company:	999
Contact Name:	ARUNDEEH VIG
DEC Memo:	"11/11/2010: ECO MIKE PHELPS AT SITE AT 1730...HE SAID THAT HE OBSERVED A GASOLINE ODOR,DURING A PBS INSPECTION,COMING FROM A VALVE UNDER THE UST TANK TOP COVER...BOBBIE VIG,STATION OWNER,HAS HIRED A TECHICIAN TO INSPECT THIS TOMORROW AND HE WILL CONTACT ME OF THE RESULTS...ECO PHELPS DID NOT OBSERVE ANY FUEL SPILLAGE,JUST A PETROLEUM ODOR. 12/3/2010: BOBBIE VIV TELECON RJJ,HE SAID THAT THEIR CONTRACTOR DID NOT FIND ANY PROBLEMS,ONLY WATER,AND NO PETROLEUM ODORS OF ANY KIND...THEY PUMPED OUT THE WATER AND WILL HAVE THIS DISPOPSED OF...MR. VIG WILL SEND ME THE DISPOSAL RECEIPTS. 12/13/2010: RECEIVED THE DISPOSAL RECEIPTS FROM RUSSO'S DEVELOPMENT,WHO WERE HIRED BY THE PROPERTY OWNER,FOR THE WATER PUMPED OUT FROM THE SUMPS,WHICH WAS TAKEN TO INDUSTRIAL OIL TANK SERVICE CORP. IN ORISKANY,NY...THE WATER HAS BEEN PUMPED OUT OF THE SUMPS & PROPERLY DISPOSED OF...NO FURTHER ACTION NEEDED...SPILL CLOSED OUT."
Remarks:	"Following up on complaint from spills Ray Jonak. Valve on top of the tank is leaking, Arundeeh has a Techinican coming tomorrow to fix the tank."

All Materials:

Site ID:	441937
Operable Unit ID:	1192469
Operable Unit:	01
Material ID:	2187798
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

H26 **UNIVERSITY MOBILE STATION** **EDR Hist Auto** **1022026584**
Target **4264 MAPLE RD** **N/A**
Property **BUFFALO, NY 14226**

Site 1 of 5 in cluster H

Actual: EDR Hist Auto
595 ft.

Focus Map: Year: Name: Type:
7 1972 UNIVERSITY MOBILE STATION Gasoline Service Stations

27 **NIAGARA MOHAWK TRANSFORME** **NY Spills** **S102963715**
Target **NORTH BAILEY & MAPLE ROAD** **N/A**
Property **AMHERST, NY**

Actual:
587 ft.

Focus Map:
7

SPILLS:

Spill Number/Closed Date:	9708434 / 1999-08-27
Facility ID:	9708434
Facility Type:	ER
DER Facility ID:	125352
Site ID:	147231
DEC Region:	9
Spill Cause:	Traffic Accident
Spill Class:	C3
SWIS:	1522
Spill Date:	1997-10-18
Investigator:	SACALAND
Referred To:	Not reported
Reported to Dept:	1997-10-18
CID:	369
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	1997-10-28
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-10-18
Spill Record Last Update:	1999-09-08
Spiller Name:	FRANK GRABOWSKI
Spiller Company:	NIAGARA MOHAWK
Spiller Address:	300 ERIE BOULEVARD WEST
Spiller Company:	001
Contact Name:	DON STAMER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SAC 10/27/97: SAC TELECON FRANK GRABOWSKI, NIAGARA MOHAWK, SPILL LOCATION WAS IN BACK OF THE SCOTCH & SIRLOIN ON A TRANSFORMER PAD. POSSIBLE PCB OIL. 10/28/97: SAC SITE INSPECTION, NOTED STAIN ON THE PAD AND SOME CRUSHED STONE THAT WAS STAINED. 10/30/97: SAC TELECON FRANK GRABOWSKI, HE HAD INSPECTED SITE AND ALSO NOTED THE STAINING, HE IS HAVING EP&S PERFORM FURTHER CLEANUP & WILL WIPE TEST THE PAD IN CASE IT IS PCB OIL. 12/06/97: SAC SITE INSPECTION, STAINING WAS GONE. 12/08/97: SAC RECEIVED CONFIRMATORY ANALYTICAL RESULTS. 12/10/97: SAC TELECON TO LINDA SCOTT, EP&S, REGARDING CONFIRMATORY RESULTS, RESULTS WERE REPORTED AS ug/WIPE, PER LINDA SCOTT WIPE SIZE WAS 10 cm x 10 cm, THEREFORE THE UNIT WIPE = 100 sq.cm. SAC TELECON CAMERON O'CONNOR, NYSDOH, LEVELS REPORTED WERE BELOW EPA GUIDANCE VALUES FOR CLEANUP LEVELS. 08/18/99: SAC DRAFTED LETTER REQUESTING DISPOSAL RECEIPTS BY 9/30/99. 08/27/99: SAC RECEIVED DISPOSAL RECEIPT."
Remarks:	"car hit pole causing transformer leak to concrete. pads and boons applied. spill contained and all will be recovered."

All Materials:

Site ID:	147231
Operable Unit ID:	1054977
Operable Unit:	01
Material ID:	330410
Material Code:	0020A
Material Name:	transformer oil

NIAGARA MOHAWK TRANSFORME (Continued) **S102963715**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	10.00
Oxygenate:	Not reported

---

28 **UNKNOWN SUBSTANCE** **NY Spills** **S105235461**
Target **730 ALBERTA DR** **N/A**
Property **AMHERST, NY**

Actual:
585 ft.

Focus Map:
6

SPILLS:

Spill Number/Closed Date:	0107228 / 2001-10-15
Facility ID:	0107228
Facility Type:	ER
DER Facility ID:	127911
Site ID:	150423
DEC Region:	9
Spill Cause:	Unknown
Spill Class:	E5
SWIS:	1522
Spill Date:	2001-10-12
Investigator:	BRENNAN
Referred To:	Not reported
Reported to Dept:	2001-10-12
CID:	252
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-10-12
Spill Record Last Update:	2002-02-08
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	UNK
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KAB 10/15/01: KAB RECEIVED REPORT OF WHITE POWDERY SUBSTANCE IN ROLL OF COINS. ERIE COUNTY EMERGENCY SERVICES WILL RESPOND. NO ACTION BY SPILLS NECESSARY. CLOSE OUT. "
Remarks:	"POLICE DEPT AND FBI ON WAY TO AMBERCROMBIE AND FINCH AT BOULEVARD MALL TO INTERVIEW SUBJ WHO STATES THEY DISCOVERED WHITE POWDER IN A ROLL OF COINS."

All Materials:

Site ID:	150423
Operable Unit ID:	844282
Operable Unit:	01
Material ID:	532056
Material Code:	0064A
Material Name:	unknown material

UNKNOWN SUBSTANCE (Continued) **S105235461**

Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

F29 **BRIDGESTONE FIRESTONE** **RCRA NonGen / NLR** **1000789437**
Target **3931 MAPLE RD** **FINDS** **NYD987008984**
Property **AMHERST, NY 14226** **ECHO**

Site 7 of 9 in cluster F

Actual: **584 ft.**

Focus Map: **6**

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	BRIDGESTONE FIRESTONE
Facility address:	3931 MAPLE RD AMHERST, NY 14226-1043
EPA ID:	NYD987008984
Mailing address:	RTE 9 SUITE 411 WOODBRIDGE, NY 07095
Contact:	Not reported
Contact address:	RTE 9 SUITE 411 WOODBRIDGE, NY 07095
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	BRIDGESTONE FIRESTONE
Owner/operator address:	900 RTE 9 SUITE 411 WOODBRIDGE, NJ 07095
Owner/operator country:	US
Owner/operator telephone:	908-855-1900
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	BRIDGESTONE FIRESTONE
Owner/operator address:	900 RTE 9 SUITE 411 WOODBRIDGE, NJ 07095
Owner/operator country:	US
Owner/operator telephone:	908-855-1900
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported

BRIDGESTONE FIRESTONE (Continued) **1000789437**

Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: BRIDGESTONE FIRESTONE
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: BRIDGESTONE FIRESTONE
Classification: Not a generator, verified

Date form received by agency: 07/14/1992
Site name: BRIDGESTONE FIRESTONE
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D008
. Waste name: LEAD

. Waste code: D018
. Waste name: BENZENE

Violation Status: No violations found

FINDS:

Registry ID: 110004492692

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport,

BRIDGESTONE FIRESTONE (Continued) **1000789437**

and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000789437
Registry ID:	110004492692
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004492692

F30 **FIRESTONE** **NY LTANKS** **S100494703**
Target **3931 MAPLE ROAD** **N/A**
Property **AMHERST, NY**

Site 8 of 9 in cluster F

Actual: 584 ft.

Focus Map: 6

LTANKS:

Spill Number/Closed Date:	9212411 / 1993-02-03
Facility ID:	9212411
Site ID:	231424
Spill Date:	1992-08-05
Spill Cause:	Tank Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	E6
Cleanup Ceased:	1993-02-03
SWIS:	1522
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	1993-01-19
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1993-02-03
Spill Record Last Update:	2002-03-22
Spiller Name:	Not reported
Spiller Company:	BRIDGESTONE/FIRESTONE
Spiller Address:	1200 FIRESTONE PARKWAY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	9
DER Facility ID:	190730
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 02/02/93: RMC/REVIEVED REPORT, NO ACTION REQUIRED....CLOSE OUT. "
Remarks:	"TANK REMOVAL - 550-GAL. WASTE OIL."

All Materials:

Site ID:	231424
Operable Unit ID:	976906

FIRESTONE (Continued) **S100494703**

Operable Unit:	01
Material ID:	402265
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

F31 **FIRESTONE COMPLETE AUTO CARE #018112** **NY AST** **U003400028**
Target **3931 MAPLE ROAD** **N/A**
Property **AMHERST, NY 14226**

Site 9 of 9 in cluster F

Actual: **584 ft.**

Focus Map: **6**

AST:

Region:	STATE
DEC Region:	9
Site Status:	Active
Facility Id:	9-600298
Program Type:	PBS
UTM X:	188744.80052
UTM Y:	4766849.89887
Expiration Date:	05/13/2022
Site Type:	Auto Service/Repair (No Gasoline Sales)

Affiliation Records:

Site Id:	55156
Affiliation Type:	Facility Owner
Company Name:	JC PENNEY CO INC
Contact Type:	ENVIRONMENTAL MANAGER
Contact Name:	DEBRA HAMLIN
Address1:	PO BOX 659000; ATTN: REAL ESTATE COUNSEL
Address2:	Not reported
City:	DALLAS
State:	TX
Zip Code:	75236
Country Code:	001
Phone:	(972) 431-1000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	AESKALSK
Date Last Modified:	2018-01-16

Site Id:	55156
Affiliation Type:	Mail Contact
Company Name:	BRIDGESTONE RETAIL OPERATIONS LLC
Contact Type:	Not reported
Contact Name:	DEBRA HAMLIN- BSRO
Address1:	200 4TH AVE SOUTH
Address2:	ATTN: ENVIRONMENTAL DEPT. - BSRO
City:	NASHVILLE
State:	TN
Zip Code:	37201
Country Code:	001

FIRESTONE COMPLETE AUTO CARE #018112 (Continued) **U003400028**

Phone:	(615) 937-9379
EMail:	ENVGEN@BFRC.COM
Fax Number:	Not reported
Modified By:	AESKALSK
Date Last Modified:	2018-01-16

Site Id:	55156
Affiliation Type:	Facility Operator
Company Name:	FIRESTONE COMPLETE AUTO CARE #30F2
Contact Type:	Not reported
Contact Name:	MARK SCHMIEGEL
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(716) 837-7721
EMail:	Not reported
Fax Number:	Not reported
Modified By:	AESKALSK
Date Last Modified:	2015-04-24

Site Id:	55156
Affiliation Type:	Emergency Contact
Company Name:	SMBC LEASING & FINANCE INC.
Contact Type:	Not reported
Contact Name:	MARK SCHMIEGEL
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(716) 289-6215
EMail:	Not reported
Fax Number:	Not reported
Modified By:	AESKALSK
Date Last Modified:	2015-04-24

Tank Info:

Tank Number:	1
Tank Id:	172331
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

E00 - Piping Secondary Containment - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)
I03 - Overfill - Automatic Shut-Off
K00 - Spill Prevention - None

FIRESTONE COMPLETE AUTO CARE #018112 (Continued) **U003400028**

D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	11/01/1990
Capacity Gallons:	300
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	AESKALSK
Last Modified:	01/16/2018
Material Name:	waste oil/used oil

I32 **NY COOLING TOWERS** **S122436426**
Target Property **4053 MAPLE RD** **N/A**
BUFFALO, NY 14226

Site 1 of 3 in cluster I

Actual: **592 ft.**
Focus Map: **7**

COOLING TOWERS:

Equipment Unique ID:	12381
Equipment Borough:	4053
Intended Use:	Air Conditioning
Manufacturer:	Evapco
Model:	LSWA-41-2
Cooling Capacity:	100
Cooling Capacity Unit:	Tonnage
Commissioned Date:	05/21/1987
Inspection Date:	08/09/2018
Date of Bacteriological Collection:	08/09/2018
Date of Legionella Collection:	08/09/2018
Last Legionella Result > 1,000 CFU/mL:	no
Latitude:	42.99077647
Longitude:	-78.810123777

I33 **NY COOLING TOWERS** **S122436424**
Target Property **4053 MAPLE RD** **N/A**
BUFFALO, NY 14226

Site 2 of 3 in cluster I

Actual: **592 ft.**
Focus Map: **7**

COOLING TOWERS:

Equipment Unique ID:	12379
Equipment Borough:	4053
Intended Use:	Air Conditioning
Manufacturer:	Evapco
Model:	LSW-58C
Cooling Capacity:	100

(Continued) **S122436424**

Cooling Capacity Unit:	Tonnage
Commissioned Date:	05/21/1986
Inspection Date:	08/09/2018
Date of Bacteriological Collection:	08/09/2018
Date of Legionella Collection:	08/09/2018
Last Legionella Result > 1,000 CFU/mL:	no
Latitude:	42.99077647
Longitude:	-78.810123777

I34 **NY COOLING TOWERS** **S122436425**
Target Property **4053 MAPLE RD** **N/A**
BUFFALO, NY 14226

Site 3 of 3 in cluster I

Actual: 592 ft.
Focus Map: 7

COOLING TOWERS:

Equipment Unique ID:	12380
Equipment Borough:	4053
Intended Use:	Air Conditioning
Manufacturer:	BAC
Model:	F-1742KMR
Cooling Capacity:	75
Cooling Capacity Unit:	Tonnage
Commissioned Date:	05/21/1987
Inspection Date:	08/09/2018
Date of Bacteriological Collection:	08/09/2018
Date of Legionella Collection:	08/09/2018
Last Legionella Result > 1,000 CFU/mL:	no
Latitude:	42.99077647
Longitude:	-78.810123777

---

35 **NIAGARA MOHAWK TRANSFORME** **NY Spills** **S103274443**
Target Property **4215 MAPLE ROAD** **N/A**
AMHERST, NY

Actual: 596 ft.
Focus Map: 7

SPILLS:

Spill Number/Closed Date:	9802064 / 1998-05-19
Facility ID:	9802064
Facility Type:	ER
DER Facility ID:	107700
Site ID:	124354
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	1522
Spill Date:	1998-05-17
Investigator:	SORGI
Referred To:	Not reported
Reported to Dept:	1998-05-17
CID:	365
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported

NIAGARA MOHAWK TRANSFORME (Continued) **S103274443**

Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-05-17
Spill Record Last Update:	1998-05-21
Spiller Name:	Not reported
Spiller Company:	NIAGARA MOHAWK
Spiller Address:	300 ERIE BLVD
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MJS 05/19/98: SPILL RECEIVED OVER WEEKEND - NO CALL OUT - MINOR QUANTITY. SPILL CLEANED BY NIAGARA MOHAWK. NO FURTHER ACTION REQUIRED. MJS CLOSE FILE."
Remarks:	"WIRE SHORTED OUT ON SIDE OF TRANSFORMER & BLEW A HOLE IN IT"

All Materials:

Site ID:	124354
Operable Unit ID:	1060128
Operable Unit:	01
Material ID:	323967
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	5.00
Oxygenate:	Not reported

J36 **WILSON FARMS** **NY Spills** **S102175078**
Target **1244 NIAGARA FALLS BLVD.** **N/A**
Property **TONAWANDA, NY**

Site 1 of 8 in cluster J

Actual: **588 ft.**

Focus Map: **6**

SPILLS:

Spill Number/Closed Date:	9213436 / 1993-03-12
Facility ID:	9213436
Facility Type:	ER
DER Facility ID:	93816
Site ID:	106501
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	1564
Spill Date:	1993-03-01
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	1993-03-01
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Other
Cleanup Ceased:	1993-03-12
Cleanup Meets Std:	True
Last Inspection:	1993-03-03

WILSON FARMS (Continued) **S102175078**

Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1993-03-08
Spill Record Last Update:	1993-03-15
Spiller Name:	Not reported
Spiller Company:	RYDER TRUCK RENTAL
Spiller Address:	2834 KENMORE AVENUE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 03/01/93: RMC/JIM JEZIORSKI, DRIVER/SITE - CROSSOVER FAILED, CAUSE UNKNOWN. LEAK WAS REPAIRED BY 1400. LOST 20-40 GALS. TO LOT. SPILL COVERS 150' X 150' AREA OF LOT; LARGE AMOUNT OF SNOW & ICE CONTAMINATED. 03/02/93: RMC/RICK BELL, RYDER/PHONE - ADVISED THAT WE REQUIRE PADS TO BE PLACED DAILY WHILE SNOW MELTS AND THE MAINTENANCE OF BOOM AROUND AND IN STORM SEWER DRAIN. TO MEET ON-SITE 3/3/93. 03/03/93: RMC/SITE LOOKED GOOD, SNOW MELTED SOME, LIGHT BROKEN SHEEN, PLACED BOOM AROUND SEWER AS A PRECAUTION. 03/12/93: RMC/RICK BELL/PHONE ADVISED TO CHECK ONE MORE TIME FOR ANY ABSORBANTS THAT NEED TO BE PICKED UP. DISPOSED OF SPILL ABSORBANT BY DOUBLE BAGGING AND IN NORMAL PICK UP....NO FURTHER ACTION NEEDED, CLOS. "
Remarks:	"CROSSOVER FAILED; 30 GALS. LOST TO PARKING LOT."

All Materials:

Site ID:	106501
Operable Unit ID:	980612
Operable Unit:	01
Material ID:	403225
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	30.00
Units:	G
Recovered:	20.00
Oxygenate:	Not reported

J37 **MACYS - BOULEVARD HOME #146B** **FINDS 1010436143**
Target **1255 NIAGARA FALLS BLVD** **ECHO N/A**
Property **AMHERST, NY 14226**

Site 2 of 8 in cluster J

Actual: 589 ft.

FINDS:

Focus Map: 6

Registry ID: 110031350384

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

MACYS - BOULEVARD HOME #146B (Continued) **1010436143**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1010436143
Registry ID:	110031350384
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110031350384

J38 **NY COOLING TOWERS** **S121997146**
Target Property **1255 NIAGRA FALLS BOULEVARD** **N/A**
AMHERST, NY 14226

Site 3 of 8 in cluster J

Actual: **589 ft.**
Focus Map: **6**

COOLING TOWERS:

Equipment Unique ID:	7697
Equipment Borough:	1255
Intended Use:	Air Conditioning
Manufacturer:	BAC
Model:	FXT87C
Cooling Capacity:	87
Cooling Capacity Unit:	Tonnage
Commissioned Date:	01/01/1990
Inspection Date:	08/23/2017
Date of Bacteriological Collection:	08/23/2017
Date of Legionella Collection:	08/23/2017
Last Legionella Result > 1,000 CFU/mL:	no
Latitude:	42.989000885
Longitude:	-78.82247957

J39 **NY COOLING TOWERS** **S121997145**
Target Property **1255 NIAGARA FALLS BOULEVARD** **N/A**
AMHERST, NY 14226

Site 4 of 8 in cluster J

Actual: **589 ft.**
Focus Map: **6**

COOLING TOWERS:

Equipment Unique ID:	7696
Equipment Borough:	1255
Intended Use:	Air Conditioning
Manufacturer:	BAC
Model:	3269
Cooling Capacity:	269
Cooling Capacity Unit:	Tonnage
Commissioned Date:	01/01/1990
Inspection Date:	08/23/2017
Date of Bacteriological Collection:	08/23/2017
Date of Legionella Collection:	08/23/2017
Last Legionella Result > 1,000 CFU/mL:	no
Latitude:	42.989000885
Longitude:	-78.82247957

J40 **MACYS - BOULEVARD #146** **RCRA-CESQG** **1010328737**
Target **1255 NIAGARA FALLS BLVD** **NY MANIFEST** **NYR000144683**
Property **AMHERST, NY 14226**

Site 5 of 8 in cluster J

Actual:
589 ft.

Focus Map:
6

RCRA-CESQG:

Date form received by agency:	02/27/2007
Facility name:	MACYS - BOULEVARD #146
Facility address:	1255 NIAGARA FALLS BLVD AMHERST, NY 14226
EPA ID:	NYR000144683
Mailing address:	NIAGARA FALLS BLVD AMHERST, NY 14226
Contact:	ELIZABETH M KONKLE
Contact address:	RTE 18 SOUTH & RUES LANE MACYS EAST BRUNSWICK #088 EAST BRUNSWICK, NJ 08816
Contact country:	US
Contact telephone:	732-631-5593
Contact email:	ELIZABETH.KONKLE@MACYS.COM
EPA Region:	02
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	MACYS EAST
Owner/operator address:	W 7TH ST CINCINNATI, OH 45202
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	02/01/2006
Owner/Op end date:	Not reported

Owner/operator name:	MACYS EAST
Owner/operator address:	Not reported Not reported
Owner/operator country:	Not reported
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported

MACYS - BOULEVARD #146 (Continued) **1010328737**

Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 02/01/2006
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Historical Generators:
Date form received by agency: 02/26/2007
Site name: MACYS - BOULEVARD #146
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 02/26/2007
Site name: MACYS - BOULEVARD #146
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYR000144683
Facility Status: Not reported
Location Address 1: 1255 NIAGARA FALLS BOULEVARD
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: AMHERST
Location State: NY
Location Zip: 14225
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000144683

MACYS - BOULEVARD #146 (Continued) **1010328737**

Mailing Name:	MACY'S EAST STORE #146 BOULEVARD
Mailing Contact:	OPERATIONS MANAGER
Mailing Address 1:	1255 NIAGARA FALLS BOULEVARD
Mailing Address 2:	Not reported
Mailing City:	AMHERST
Mailing State:	NY
Mailing Zip:	14225
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7168379400

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	MIK435642742
Trans2 State ID:	Not reported
Generator Ship Date:	06/19/2018
Trans1 Recv Date:	06/19/2018
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/25/2018
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000144683
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	MID980991566
TSDF ID 2:	Not reported
Manifest Tracking Number:	018414677JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	53
Units:	P - Pounds
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	D001
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported

MACYS - BOULEVARD #146 (Continued) **1010328737**

Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

Click this hyperlink while viewing on your computer to access
2 additional NY MANIFEST: record(s) in the EDR Site Report.

J41 **MACYS - BOULEVARD HOME #146B** **RCRA-CESQG** **1010328739**
Target **1255 NIAGARA FALLS BLVD** **NYR000144691**
Property **AMHERST, NY 14226**

Site 6 of 8 in cluster J

Actual: **589 ft.**

Focus Map: **6**

RCRA-CESQG:
Date form received by agency: 02/27/2007
Facility name: MACYS - BOULEVARD HOME #146B
Facility address: 1255 NIAGARA FALLS BLVD
AMHERST, NY 14226
EPA ID: NYR000144691
Mailing address: NIAGARA FALLS BLVD
AMHERST, NY 14226
Contact: ELIZABETH M KONKLE
Contact address: NIAGARA FALLS BLVD
AMHERST, NY 14226
Contact country: US
Contact telephone: 732-631-5593
Contact email: ELIZABETH.KONKLE@MACYS.COM
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:
Owner/operator name: MACYS EAST
Owner/operator address: W 7TH ST
CINCINNATI, OH 45202
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 02/01/2006
Owner/Op end date: Not reported

MACYS - BOULEVARD HOME #146B (Continued) **1010328739**

Owner/operator name: MACYS EAST
Owner/operator address: Not reported
Not reported
Owner/operator country: Not reported
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 02/01/2006
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Historical Generators:
Date form received by agency: 02/26/2007
Site name: MACYS - BOULEVARD HOME #146B
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 02/26/2007
Site name: MACYS - BOULEVARD HOME #146B
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

J42 **KAUFMANN'S DEPARTMENT STORE** **NY UST** **U004047317**
Target **1255 NIAGARA FALLS BLVD** **N/A**
Property **AMHERST, NY 14226**

Site 7 of 8 in cluster J

Actual:
589 ft.

Focus Map:
6

UST:

Id/Status:	9-600730 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	9
Expiration Date:	N/A
UTM X:	188542.36807
UTM Y:	4766611.28829
Site Type:	Other Wholesale/Retail Sales

Affiliation Records:

Site Id:	337426
Affiliation Type:	Mail Contact
Company Name:	KAUFMANNS DEPARTMENT STORE
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	1255 NIAGARA FALLS BLVD
Address2:	Not reported
City:	AMHERST
State:	NY
Zip Code:	14226
Country Code:	001
Phone:	Not reported
EMail:	Not reported
Fax Number:	Not reported
Modified By:	AESKALSK
Date Last Modified:	2005-02-11

Site Id:	337426
Affiliation Type:	Facility Operator
Company Name:	KAUFMANNS DEPARTMENT STORE
Contact Type:	Not reported
Contact Name:	KAUFMANN'S DEPARTMENT STORE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	Not reported
EMail:	Not reported
Fax Number:	Not reported
Modified By:	AESKALSK
Date Last Modified:	2005-02-11

Tank Info:

Tank Number:	1
Tank ID:	181982
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	16000
Install Date:	Not reported

KAUFMANN'S DEPARTMENT STORE (Continued) **U004047317**

Date Tank Closed:	07/06/1992
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	AESKALSK
Last Modified:	04/14/2017

J43 **FURST ARTHUR** **EDR Hist Cleaner** **1019992500**
Target **1226 NIAGARA FLS BD** **N/A**
Property **TONAWANDA, NY 14150**

Site 8 of 8 in cluster J

Actual: EDR Hist Cleaner
589 ft.

Focus Map:
6

Year:	Name:	Type:
1969	FURST ARTHUR	Drycleaning Plants, Except Rugs
1969	FURST ARTHUR	Drycleaning Plants, Except Rugs
1970	FURST ARTHUR	Drycleaning Plants, Except Rugs
1971	FURST ARTHUR	Drycleaning Plants, Except Rugs
1972	FURST ARTHUR	Drycleaning Plants, Except Rugs
1973	FURST ARTHUR	Drycleaning Plants, Except Rugs

K44 **NIAGARA MOHAWK BOUL. MALL** **NY Spills** **S102174193**
Target **1227 NIAGARA FALLS BLVD** **N/A**
Property **AMHERST, NY**

Site 1 of 2 in cluster K

Actual: SPILLS:
590 ft.

Focus Map:
6

Spill Number/Closed Date:	9106426 / 1991-09-16
Facility ID:	9106426
Facility Type:	ER
DER Facility ID:	196825
Site ID:	239291
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	1522
Spill Date:	1991-09-14
Investigator:	MXFRANKS
Referred To:	Not reported
Reported to Dept:	1991-09-14
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	1991-09-16
Cleanup Meets Std:	True

NIAGARA MOHAWK BOUL. MALL (Continued) **S102174193**

Last Inspection:	1991-09-14
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1991-09-16
Spill Record Last Update:	1991-10-07
Spiller Name:	Not reported
Spiller Company:	NIAGARA MOWHAWK
Spiller Address:	DEWEY AVENUE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MF 09/16/91: MF 9/14/91 SITE VISIT,/SPILLER, SMALL AMOUNT OF SPILLAGE CONTAINED IN VAULT. CLEAN UP DEBRIS TO BE TAKEN TO DEWEY AVE FOR EVENTUAL DISPOSAL. NO FURTHER ACTION NECESSARY. "
Remarks:	"TRANSFORMER RUSTED, OIL LEAKED INTO VAULT. CLEAN UP CREW ON THE WAY. NO CALL BACK NECESSARY."

All Materials:

Site ID:	239291
Operable Unit ID:	960718
Operable Unit:	01
Material ID:	422131
Material Code:	0016A
Material Name:	non PCB oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	9.00
Oxygenate:	Not reported

K45 **KAUFMANS** **NY Spills** **S105236058**
Target **1225 NIAGARA FALLS BLVD** **N/A**
Property **AMHERST, NY**

Site 2 of 2 in cluster K

Actual: **590 ft.**

Focus Map: **6**

SPILLS:

Spill Number/Closed Date:	0175412 / 2001-12-24
Facility ID:	0175412
Facility Type:	ER
DER Facility ID:	62190
Site ID:	64576
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	1522
Spill Date:	2001-10-17
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	2001-11-13
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported

KAUFMANS (Continued) **S105236058**

Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-11-13
Spill Record Last Update:	2001-12-24
Spiller Name:	Not reported
Spiller Company:	KAUFMANS
Spiller Address:	1225 NIAGARA FALLS BLVD
Spiller Company:	001
Contact Name:	FRANK REPASKY
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 12/24/01 RMC/FILE. REPORTED AS MINOR PROBLEM, NO ACTION REQUIRED, ALL WITH IN BUILDING, CLOSE OUT "
Remarks:	"CONTAMINATION FOUND WHILE REMOVING HYDRAULIC LIFT. REMOVED 2 buckets. ALREADY INSTALLED NEW ELEVATOR "

All Materials:

Site ID:	64576
Operable Unit ID:	850786
Operable Unit:	01
Material ID:	524745
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

---

46 **MIDAS DRAINS** **NY Spills** **S103829192**
Target **1171 NIAGARA FALLS BLVD** **N/A**
Property **AMHERST, NY**

Actual:
592 ft.

Focus Map:
6

SPILLS:

Spill Number/Closed Date:	9875468 / 1999-10-12
Facility ID:	9875468
Facility Type:	ER
DER Facility ID:	257808
Site ID:	319992
DEC Region:	9
Spill Cause:	Other
Spill Class:	D3
SWIS:	1522
Spill Date:	1999-03-18
Investigator:	FXGALLEG
Referred To:	Not reported
Reported to Dept:	1999-03-18
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	1999-03-18

MIDAS DRAINS (Continued) **S103829192**

Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-03-18
Spill Record Last Update:	1999-10-13
Spiller Name:	ANTHONY SERRINO
Spiller Company:	ANTHONY SERRIO
Spiller Address:	111 CLEARFIELD
Spiller Company:	001
Contact Name:	LARRY HAXTON
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was FG 03/18/99: JDC ON SITE, MET JACK CARONE, CARUBBA BROTHERS AND MR HAXTON OF MIDAS, OBSERVED MINOR AMOUNT OF OIL IN THE EXCAVATION FOR THE NEW STORM DI. APPLIED SOME SORBENT PADS AND ADVISED THAT THEY BE DISPOSED TO NORMAL REFUSE FOR NYSDOT. SPOKE WITH MR HAXTON WHO REPORTED THAT ALL FLOOR WASHINGS GO TO SINGLE FLOOR DRAIN. WASTE OIL IS COLLECTED IN 275 INDOOR TANK AND RECYCLED. BOTH WASTE OIL AND NEW OILS ARE KEPT IN DIKE AREA. DRAIN WAS FREE OF OILS, UNKNOWN DISCHARGE POINT. WILL CONTACT OWNER. SPOKE WITH CARUBBA BROTHERS WHO STATED THAT ALL FLOOR DRAINAGE GOES TO SEPARTOR TANK, NEWLY INSTALLED TO REPLACE OLD ONE. SAYS TANK IS EMPTIED ONCE EVERY 2 YEARS, DID NOT INSPECT. CALLED OWNER ANTHONY SERRINO, HE STATED THE BUILDINGS WERE CONSTRUCTED IN 52'AND USED SEPTIC TANKS BEFORE THE DRAINAGE WAS DIRECTED INTO SANITARY, COULD NOT REMEMBER DATE. ADVISED MR SERRINO THAT HE MUST RETURN A LETTER TO MY ATTENTION STATING THE CURRENT DRAINAGE POSTER. JDC TELECON TO DON BECKER, TOWN OF AMHERST, 691-4331, AND ADVISED ON THE MATTER. HE WILL INVESTGATE HIS FILES FOR ANY CURRENT DATA AND CALL BACK. JDC WILL SEND LETTER TP POTENTIAL RP AFTER WORD FROM AMHERST. 03/22/99: JDC TELECON WITH DON BECKER, TOWN OF AMHERST, HE WAS ON SITE AND CONFIRMED VIA DYE TESTING THAT TWO FLOOR DRAINS DISCHARGE TO STORM SEWER. HE ADVISED MR HAXON, MANAGER AT MIDAS THAT HE MUST SEAL DRAINS PERMENANTLY. JDC TELECON TO MR HAXTON, HE AGREED TO SEAL DRAINS IN CONCRETE. HE WILL CONTACT MR SERRINO, OWNER ABOUT THIS ACTION. REQUESTED HE CONTACT ME WHEN WORK IS COMPLETE. 10/12/99: JDC TELECON FROM DON BECKER, HE HAD INSPECTED THE FACILITY AND SAID THAT THE DRAINS HAD BEEN FILLED IN. NO FURTHER WORK IS REQUIRED. THE SITE CAN BE CLOSED."
Remarks:	"RECEIVED A CALL FROM DOT THAT OIL WAS DISCOVERD IN STORM CULVERT BOX BEING REPLACED IN FRONT OF MIDAS/ CARUBBA COLLISION."

All Materials:

Site ID:	319992
Operable Unit ID:	1074895
Operable Unit:	01
Material ID:	307110
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	5.00
Oxygenate:	Not reported

L47 **AUTOMATIC ROLLS/NORTHEAST** **NY Spills** **S102178810**
Target **NIAGARA FALLS BLVD - MALL** **N/A**
Property **AMHERST, NY**

Site 1 of 6 in cluster L

Actual: **596 ft.**

Focus Map: **6**

SPILLS:

Spill Number/Closed Date:	9406936 / 1995-06-06
Facility ID:	9406936
Facility Type:	ER
DER Facility ID:	212057
Site ID:	259191
DEC Region:	9
Spill Cause:	Traffic Accident
Spill Class:	C2
SWIS:	1522
Spill Date:	1994-08-22
Investigator:	SORGI
Referred To:	Not reported
Reported to Dept:	1994-08-22
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Fire Department
Cleanup Ceased:	1995-06-06
Cleanup Meets Std:	True
Last Inspection:	1995-08-23
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1994-08-23
Spill Record Last Update:	1995-07-07
Spiller Name:	Not reported
Spiller Company:	AUTOMATIC ROLLS/NORTHEAST
Spiller Address:	2 CORCORAN DRIVE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MJS 08/22/94: 2130 HRS - MJS/JIM ZYMANEK SITE. LEAK STOPPED. SPILLAGE ON NIAGARA FALLS BLVD AND PARKING LOT. SPEEDI DRI APPLIED BY F.D. MINOR AMOUNT IN STORM SEWER. COULD NOT REACH ANYONE AT RP PHONE. HIRED EPS. 08/23/94: 0900 HRS - MJS/JIM ZYMANEK/EPS SITE. EPS DRUMMED SPEEDI DRI. PRODUCT PADDED OUT OF STORM RECEIVERS. 3 DRUMS WASTE GENERATED. STAGED ON SITE. CLEANUP COMPLETE. 08/31/94: RECEIVED PAY-PACK FROM EPS FOR INITIAL RESPONSE. 09/16/94: RECEIVED PAY- PACK FROM LAB FOR ANALYTICAL. 09/30/94: RECEIVED PAY- PACK FROM EPS FOR DISPOSAL. 10/03/94: MJS REVIEW FILE. RESPONSIBILITY LETTER SENT TO RP. 10/11/94: MJS TELECON FROM RON WAWRZASZEK FROM RP. HE WANTS TO PAY BILL. MJS EXPLAINED TO HIM THAT BILL WILL COME FROM AG'S OFFICE. 05/18/95: MJS REVIEW FILE. NEED DISPOSAL RECEIPT FOR CLOSURE OF FILE. MJS TELECON TO LINDA CARR(EPS). SHE WILL HAVE RECEIPT FORWARDED. "
Remarks:	"ROAD DEBRIS RUPTURED SADDLE TANK."

All Materials:

Site ID:	259191
Operable Unit ID:	1004365
Operable Unit:	01
Material ID:	379960
Material Code:	0008
Material Name:	diesel

AUTOMATIC ROLLS/NORTHEAST (Continued) **S102178810**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	60.00
Units:	G
Recovered:	60.00
Oxygenate:	Not reported

M48 **NYSDOT D257531** **FINDS** **1016255495**
Target Property **RTE 62 INTERSECTION W RTE 324** **ECHO** **N/A**
AMHERST, NY 14226

Site 1 of 3 in cluster M

Actual: 598 ft.

Focus Map: 6

FINDS:

Registry ID: 110008104452

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016255495
Registry ID:	110008104452
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110008104452

M49 **NYSDOT PROJECT/ACCADIA** **NY Spills** **S104283639**
Target Property **NIAGARA FALLS BLVD/SHERID** **N/A**
AMHERST, NY

Site 2 of 3 in cluster M

Actual: 598 ft.

Focus Map: 6

SPILLS:

Spill Number/Closed Date:	9975503 / 1999-11-01
Facility ID:	9975503
Facility Type:	ER
DER Facility ID:	89558
Site ID:	101005
DEC Region:	9
Spill Cause:	Other
Spill Class:	C3
SWIS:	1522
Spill Date:	1999-11-01
Investigator:	LEARY
Referred To:	Not reported
Reported to Dept:	1999-11-01
CID:	Not reported

NYSDOT PROJECT/ACCADIA (Continued) **S104283639**

Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-11-01
Spill Record Last Update:	1999-11-01
Spiller Name:	JANINE SHEPHERD
Spiller Company:	NYSDOT/FIRESTONE
Spiller Address:	125 MAIN STREET
Spiller Company:	001
Contact Name:	JACK CARONE
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RNL 11/01/99: RNL RECEIVED INFORMATION FROM JACK CARONE FOR SPILL 9805840, A NYSDOT HIGHWAY PROJECT TANK REMOVAL, HE ALSO INCLUDED DATA ON THIS TANK REMOVAL AT SHERIDAN DRIVE AND NIAGARA FALLS BLVD. FOR THE SAME HIGHWAY PROJECT RNL CEHCKED WITH PBS, THEY HAD NO INFORMATION ON THIS SITE, RNL OPENED SPILL, SAMPLE RESULTS WITHIN STARS, CLOSEOUT RNL NOTE, SEE ALSO SPILL 9804615 "
Remarks:	"NYSDOT REMOVED TANKS WITHIN THEIR ROW"

All Materials:

Site ID:	101005
Operable Unit ID:	1093871
Operable Unit:	01
Material ID:	292066
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

N50 **FIRESTONE TIRE** **NY LTANKS** **S100154810**
Target **NIAGARA FALLS BOULEVARD** **N/A**
Property **AMHERST, NY**

Site 1 of 4 in cluster N

Actual: **598 ft.**

Focus Map: **6**

LTANKS:

Spill Number/Closed Date:	8605722 / 1986-12-12
Facility ID:	8605722
Site ID:	247776
Spill Date:	1986-12-09
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1986-12-12
SWIS:	1522
Investigator:	ROSS
Referred To:	Not reported

FIRESTONE TIRE (Continued) **S100154810**

Reported to Dept:	1986-12-09
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	1986-12-12
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1986-12-12
Spill Record Last Update:	1987-01-05
Spiller Name:	Not reported
Spiller Company:	FIRESTONE TIRE
Spiller Address:	NIAGARA FALLS BOULEVARD
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	9
DER Facility ID:	203460
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was LQR / / : LQR SITE INSPECTION 12/09/86, CLEANUP UNDERWAY, TANKS BEING REMOVED, SOIL TO MODERN. / / : LQR SITE INSPECTION 12/09/86, CLEANUP UNDERWAY, TANKS BEING REMOVED, SOIL TO MODERN;LQR TELCON ELMWOOD TANK 12/12/86 TANK REMOVED COMPLT. "
Remarks:	""

All Materials:

Site ID:	247776
Operable Unit ID:	902660
Operable Unit:	01
Material ID:	474885
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

N51 **NFG EXCAVATION** **NY Spills** **S103274730**
Target Property **NIAGARA FALLS BLVD/EGGERT AMHERST, NY** **N/A**

Site 2 of 4 in cluster N

Actual: 598 ft.
Focus Map: 6

SPILLS:

Spill Number/Closed Date:	9802491 / 2003-01-17
Facility ID:	9802491
Facility Type:	ER
DER Facility ID:	111523
Site ID:	129365
DEC Region:	9
Spill Cause:	Unknown
Spill Class:	D4
SWIS:	1522

NFG EXCAVATION (Continued) **S103274730**

Spill Date:	1998-05-27
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	1998-05-27
CID:	999
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-05-27
Spill Record Last Update:	2003-01-17
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 01/16/03 RMC/FILE. SITE REASSIGNED TO RMC FROM SAC. RMC TO VIST SITE. UPDATE 1/31/03 01/17/03 RMC/SITE, WALKED AREA. DEC HAS HAS NUMEROUS SPILLS IN THIS AREA. IT IS NOT KNOWN WHERE NFG FOUND ODORS IN THE SOIL 5 YEARS AGO. RMC DISCUSSED WITH PJB, TO CLOSE SITE DUE TO PASSAGE OF TIME. CLOSE OUT."
Remarks:	"several excavations indicate strong petroleum contamination ***(FORMERLY MJS FILE)***"

All Materials:

Site ID:	129365
Operable Unit ID:	1060493
Operable Unit:	01
Material ID:	320819
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

O52 **NYSDOT PROJECT/U-HAUL** **NY Spills** **S104283640**
Target **NIAGARA FALLS BLVD/EGGERT** **N/A**
Property **AMHERST, NY**

Site 1 of 2 in cluster O

Actual: **598 ft.**

Focus Map: **6**

SPILLS:

Spill Number/Closed Date:	9975504 / 1999-11-01
Facility ID:	9975504
Facility Type:	ER
DER Facility ID:	111523
Site ID:	129366
DEC Region:	9

NYSDOT PROJECT/U-HAUL (Continued) **S104283640**

Spill Cause:	Other
Spill Class:	E5
SWIS:	1522
Spill Date:	1999-11-01
Investigator:	LEARY
Referred To:	Not reported
Reported to Dept:	1999-11-01
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-11-01
Spill Record Last Update:	1999-11-02
Spiller Name:	Not reported
Spiller Company:	NONE
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RNL 11/01/99: RNL RECEIVED INFORMATION FROM JACK CARONE FOR SPILL 9805840, A NYSDOT HIGHWAY PROJECT TANK REMOVAL, HE ALSO INCLUDED DATA ON THIS TANK REMOVAL AT EGGERT ROAD AND NIAGARA FALLS BLVD. FOR THE SAME HIGHWAY PROJECT RNL CHECK WITH PBS, THEY HAD NO DATA ON THIS SITE, RNL OPENED SPILL, SAMPLE RESULTS WITHIN STARS, CLOSEOUT"
Remarks:	"NYSDOT REMOVED TANKS WITHIN THEIR ROW"

All Materials:

Site ID:	129366
Operable Unit ID:	1093872
Operable Unit:	01
Material ID:	292067
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

---

53 **BIG JOHN RESTAURANT** **NY Spills** **S102175954**
Target **BIG JOHN RESTAURANT** **N/A**
Property **TONAWANDA, NY**

Actual:
602 ft.

Focus Map:
8

SPILLS:

Spill Number/Closed Date:	8708683 / 1988-05-31
Facility ID:	8708683
Facility Type:	ER
DER Facility ID:	243914
Site ID:	301849
DEC Region:	9

BIG JOHN RESTAURANT (Continued) **S102175954**

Spill Cause:	Abandoned Drums
Spill Class:	Not reported
SWIS:	1564
Spill Date:	1988-01-12
Investigator:	MXFRANKS
Referred To:	Not reported
Reported to Dept:	1988-01-12
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Citizen
Cleanup Ceased:	1988-05-31
Cleanup Meets Std:	True
Last Inspection:	1988-01-15
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1988-01-12
Spill Record Last Update:	1988-06-06
Spiller Name:	Not reported
Spiller Company:	JOE PEZZINO
Spiller Address:	546 NIAGARA FALLS BLVD
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MF / / : RESTAURANT OWNER TO PROPERLY DISPOSE OF DRUM. / / : MF 1/12/88 SITE VISIT MET/JOHN OWNER, HE AGREED TO DISPOSE OF OIL, PUT PADS IN PLACE & PUT 1 CAP ON DRUM. / / : MF 1/15/88 SITE VISIT, OWNER NOT IN, LEFT MESSAGE TO CALL ME. OIL DRUM GONE. / / : MF 1/25/88 JOE PEZZINO TELECON, HE RECEIVED LETTER, & DOES'T HAVE RECEIPT. I TOLD HIM TO CALL THE DARLING CO. & GET ONE. 02/19/88: MF RECEIVED DEPOSAL RECEIPT FOR OIL (DARLING), CALLED DON PHILLIPS(DARLING), THEY DID PICK UP OIL BY MISTAKE & RECYCLED IT. 05/31/88: MF TALKED/NANCY OVERFIELD, SHE CLAIMS CASE TURNED OVER TO AGRICULTURE & MARKETS. THEY ARE GOING AFTER DARLING INC., NO FUTHER ACTION NECESSARY BY SPILLS. "
Remarks:	"55 GALLON FOUND BEHIND RESTAURANT LEAKING DUE TO MISSING BUNG"

All Materials:

Site ID:	301849
Operable Unit ID:	913357
Operable Unit:	01
Material ID:	568051
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

P54 **MOBIL OI CORP SS #HA1** **RCRA NonGen / NLR** **1004759010**
Target **3514 MAIN ST** **FINDS** **NYD987036084**
Property **BUFFALO, NY 14214** **ECHO**
NY MANIFEST

Site 1 of 10 in cluster P

Actual:
651 ft.

Focus Map:
8

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	MOBIL OI CORP SS #HA1
Facility address:	3514 MAIN ST BUFFALO, NY 14214
EPA ID:	NYD987036084
Mailing address:	GALLOWS RD 7W109 FAIRFAX, NY 22037
Contact:	ROBIN BUNN
Contact address:	GALLOWS RD 7W109 FAIRFAX, NY 22037
Contact country:	US
Contact telephone:	703-849-3330
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	MOBIL OIL CORP
Owner/operator address:	3225 GALLOWS RD FAIRFAX, VA 22037
Owner/operator country:	US
Owner/operator telephone:	703-849-3330
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	MOBIL OIL CORP
Owner/operator address:	3225 GALLOWS RD FAIRFAX, VA 22037
Owner/operator country:	US
Owner/operator telephone:	703-849-3330
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No

MOBIL OI CORP SS #HA1 (Continued) **1004759010**

On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: MOBIL OI CORP SS #HA1
Classification: Not a generator, verified

Date form received by agency: 06/21/1993
Site name: MOBIL OI CORP SS #HA1
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D018
. Waste name: BENZENE

Violation Status: No violations found

FINDS:

Registry ID: 110004505973

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004759010
Registry ID: 110004505973
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004505973

MOBIL OI CORP SS #HA1 (Continued) **1004759010**

NY MANIFEST:

Country:	USA
EPA ID:	NYD987036084
Facility Status:	Not reported
Location Address 1:	3514 MAIN STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BUFFALO
Location State:	NY
Location Zip:	14213
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD987036084
Mailing Name:	MOBIL OIL CORPORATION/MARKETING ENVIRON
Mailing Contact:	JUSTIN GABRESKI
Mailing Address 1:	3225 GALLOWS ROAD
Mailing Address 2:	Not reported
Mailing City:	FAIRFAX
Mailing State:	VA
Mailing Zip:	22037
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7166341291

NY MANIFEST:

Document ID:	NYB5257836
Manifest Status:	C
seq:	Not reported
Year:	1993
Trans1 State ID:	31705FNY
Trans2 State ID:	Not reported
Generator Ship Date:	10/01/1993
Trans1 Recv Date:	10/01/1993
Trans2 Recv Date:	/ /
TSD Site Recv Date:	10/01/1993
Part A Recv Date:	11/17/1993
Part B Recv Date:	10/15/1993
Generator EPA ID:	NYD987036084
Trans1 EPA ID:	NYD057770109
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD057770109
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES

MOBIL OI CORP SS #HA1 (Continued) **1004759010**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

P55 **MOBIL OIL** **NY LTANKS** **S100154548**
Target **3514 MAIN STREET** **N/A**
Property **AMHERST, NY**

Site 2 of 10 in cluster P

Actual: **651 ft.**

Focus Map: **8**

LTANKS:

Spill Number/Closed Date:	8908630 / 1990-10-30
Facility ID:	8908630
Site ID:	178358
Spill Date:	1989-11-01
Spill Cause:	Tank Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Not reported
Cleanup Ceased:	1990-06-27
SWIS:	1522
Investigator:	LYONS
Referred To:	Not reported
Reported to Dept:	1989-11-30
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1989-12-08
Spill Record Last Update:	1991-03-04
Spiller Name:	Not reported
Spiller Company:	MOBIL OIL
Spiller Address:	3225 GALLOWS ROAD
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	9
DER Facility ID:	149795
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MEL 12/01/89: MEL RECIEVED SPILL. 10/30/90: MEL. ANALYTICAL RESULTS FROM SAMPLING ON 06/27/90 INDICATE THAT REMEDIATION NOT NECESSARY AT THIS TIME. NO FURTHER ACTION NECESSARY, RECOMMEND FILE BE CLOSED. "

MOBIL OIL (Continued) **S100154548**

Remarks: "SITE INVESTIGATION OF OLD MOBIL STATION."

All Materials:

Site ID:	178358
Operable Unit ID:	933678
Operable Unit:	01
Material ID:	445364
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

P56 **BLACKWELLS PLAZA SERVICE** **EDR Hist Auto** **1014537585**
Target **3514 MAIN ST** **N/A**
Property **BUFFALO, NY 14226**

Site 3 of 10 in cluster P

Actual: EDR Hist Auto
651 ft.

Focus Map:
8

Year:	Name:	Type:
1950	LANDES & BLACKWELL FILLING STA	GASOLINE STATIONS
1955	LANDES & BLACKWELL SERV STA BR	GASOLINE STATIONS
1960	BLACKWELL PLAZA SERV GAS STA	GASOLINE STATIONS
1964	BLACKWELL PLAZA SERVICE GAS STA	GASOLINE STATIONS
1969	BLACKWELLS PLAZA SERVICE	Gasoline Service Stations
1970	BLACKWELL PLAZA SERVICE GAS STA	GASOLINE STATIONS
1970	BLACKWELLS PLAZA SERVICE	Gasoline Service Stations
1971	BLACKWELLS PLAZA SERVICE	Gasoline Service Stations
1972	BLACKWELLS PLAZA SERVICE	Gasoline Service Stations
1973	BLACKWELLS PLAZA SERVICE	Gasoline Service Stations
1974	BLACKWELLS PLAZA SERVICE	Gasoline Service Stations
1975	BLACKWELLS PLAZA SERVICE	Gasoline Service Stations
1976	BLACKWELLS PLAZA SERVICE	Gasoline Service Stations
1977	BLACKWELLS PLAZA SERVICE	Gasoline Service Stations
1978	BLACKWELLS PLAZA SERVICE	Gasoline Service Stations
1979	BLACKWELLS PLAZA SERVICE	Gasoline Service Stations
1980	BLACKWELL PLAZA SERVICE GAS STA	GASOLINE STATIONS
1982	BLACKDELLS PLAZA SERVICE INC	Gasoline Service Stations
1983	BLACKDELLS PLAZA SERVICE INC	Gasoline Service Stations
1985	BLACKWELLS PLAZA SERVICE INC	Gasoline Service Stations
1986	BLACKWELLS PLAZA SERVICE INC	Gasoline Service Stations
1987	BLACKWELLS PLAZA SERVICE INC	Gasoline Service Stations
1988	BLACKWELLS PLAZA SERVICE INC	Gasoline Service Stations
1989	BLACKWELLS PLAZA SERVICE INC	Gasoline Service Stations
1990	BLACKWELLS PLAZA SERVICE INC	Gasoline Service Stations
1991	BLACKWELLS PLAZA SERVICE INC	Gasoline Service Stations

P57 **NIAGARA MOHAWK A NATIONAL GRID CO** **RCRA NonGen / NLR** **1016959794**
Target **KENMORE AVE & MAIN ST** **NY MANIFEST** **NYP000971218**
Property **BUFFALO, NY 14226**

Site 4 of 10 in cluster P

Actual:
652 ft.

Focus Map:
8

RCRA NonGen / NLR:
Date form received by agency: 06/26/2015
Facility name: NIAGARA MOHAWK A NATIONAL GRID CO
Facility address: KENMORE AVE & MAIN ST
BUFFALO, NY 14226
EPA ID: NYP000971218
Mailing address: ERIE BLVD W
SYRACUSE, NY 13202
Contact: LENNY DELVEECHIO
Contact address: ERIE BLVD W
SYRACUSE, NY 13202
Contact country: US
Contact telephone: 315-428-6670
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D008
. Waste name: LEAD

Historical Generators:
Date form received by agency: 10/28/2014
Site name: NIAGARA MOHAWK A NATIONAL GRID CO
Classification: Large Quantity Generator

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP000971218
Facility Status: Not reported
Location Address 1: KENMORE AVE

NIAGARA MOHAWK A NATIONAL GRID CO (Continued) **1016959794**

Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BUFFALO
Location State:	NY
Location Zip:	14226
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP000971218
Mailing Name:	NIAGARA MOHAWK A NATIONAL GRID CO
Mailing Contact:	L MONTESANO
Mailing Address 1:	144 KENSINGTON AVE
Mailing Address 2:	Not reported
Mailing City:	BUFFALO
Mailing State:	NY
Mailing Zip:	14214
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7168317209

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NYD986980753
Trans2 State ID:	Not reported
Generator Ship Date:	11/14/2014
Trans1 Recv Date:	11/14/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/14/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP000971218
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD049836679
TSDF ID 2:	Not reported
Manifest Tracking Number:	003045022FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

NIAGARA MOHAWK A NATIONAL GRID CO (Continued) **1016959794**

Quantity:	680
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	12
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	Not reported
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	D008
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

P58 **UNIVERSITY PLAZA** **NY Spills** **S102178706**
Target **3500 MAIN STREET** **N/A**
Property **AMHERST, NY**

Site 5 of 10 in cluster P

Actual: **652 ft.**
Focus Map: **8**

SPILLS:

Spill Number/Closed Date:	9404727 / 1994-07-21
Facility ID:	9404727
Facility Type:	ER
DER Facility ID:	63547
Site ID:	66354
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	1522
Spill Date:	1994-07-06
Investigator:	SORGI
Referred To:	Not reported
Reported to Dept:	1994-07-06
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Passenger Vehicle
Spill Notifier:	Fire Department
Cleanup Ceased:	1994-07-11
Cleanup Meets Std:	True
Last Inspection:	1994-07-11
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1994-07-08
Spill Record Last Update:	1994-08-11
Spiller Name:	Not reported
Spiller Company:	UNKNOWN VEHICLE
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MJS 07/11/94: MJS RECEIVED REPORT ON 7/7/94. NO FURTHER ACTION REQUIRED AT THIS TIME. CLEANUP COMPLETE. MJS INSPECT. NO FREE PRODUCT FOUND. DEBRIS DISPOSED IN REGULAR WASTE STREAM. MJS CLOSE FILE. "

UNIVERSITY PLAZA (Continued) **S102178706**

Remarks: "GAS TANK FELL OFF CAR"

All Materials:
Site ID: 66354
Operable Unit ID: 998999
Operable Unit: 01
Material ID: 381329
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 10.00
Units: G
Recovered: 10.00
Oxygenate: Not reported

Spill Number/Closed Date: 9404763 / 1994-07-11
Facility ID: 9404763
Facility Type: ER
DER Facility ID: 63547
Site ID: 66355
DEC Region: 9
Spill Cause: Equipment Failure
Spill Class: D3
SWIS: 1522
Spill Date: 1994-07-06
Investigator: RMCROSSE
Referred To: Not reported
Reported to Dept: 1994-07-07
CID: Not reported
Water Affected: Not reported
Spill Source: Passenger Vehicle
Spill Notifier: Local Agency
Cleanup Ceased: 1994-07-11
Cleanup Meets Std: True
Last Inspection: 1994-07-11
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1994-07-08
Spill Record Last Update: 1994-08-08
Spiller Name: Not reported
Spiller Company: UNKNOWN VEHICLE
Spiller Address: Not reported
Spiller Company: 999
Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 07/11/94: RMC/SITE AREA CLEAR, NO SPILL ACTION REQUIRED, CLOSE OUT. "
Remarks: "GAS TANK FELL OFF CAR"

All Materials:
Site ID: 66355
Operable Unit ID: 999027
Operable Unit: 01
Material ID: 381365
Material Code: 0009

UNIVERSITY PLAZA (Continued) **S102178706**

Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	10.00
Oxygenate:	Not reported

P59 **AJ WRIGHT** **NY Spills** **S109581086**
Target **3500 MAIN ST** **N/A**
Property **BUFFALO, NY**

Site 6 of 10 in cluster P

Actual: **652 ft.**

Focus Map: **8**

SPILLS:

Spill Number/Closed Date:	0813644 / 2009-03-18
Facility ID:	0813644
Facility Type:	ER
DER Facility ID:	360557
Site ID:	411338
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	1502
Spill Date:	2009-03-18
Investigator:	JFOTTO
Referred To:	Not reported
Reported to Dept:	2009-03-18
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-03-18
Spill Record Last Update:	2009-03-18
Spiller Name:	LISA MONTASANO
Spiller Company:	NATIONAL GRID
Spiller Address:	144 KENSINGTON AVE
Spiller Company:	999
Contact Name:	LISA MONTASANO
DEC Memo:	"THIS IS A MINOR SPILL THAT WAS CLEANED UP. NO ACTION NECESSARY BY SPILLS. CLOSED ELECTRONIC FILE"
Remarks:	"CALLER STATES THAT DUE TO A FAILED TRANSFORMER ABOUT 1 GALLON WAS SPILLED TO PAVEMENT. NON PCB OIL. CLEAN UP IS PENDING."

All Materials:

Site ID:	411338
Operable Unit ID:	1167807
Operable Unit:	01
Material ID:	2159391
Material Code:	0020A
Material Name:	transformer oil

AJ WRIGHT (Continued) **S109581086**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

P60 **NIAGARA MOHAWK A NATIONAL GRID CO** **FINDS** **1017392226**
Target **KENMORE AVE & MAIN ST** **ECHO** **N/A**
Property **BUFFALO, NY 14226**

Site 7 of 10 in cluster P

Actual: **652 ft.**

FINDS:

Focus Map: **8**

Registry ID: 110062911522

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1017392226
Registry ID:	110062911522
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110062911522

Q61 **CVS PHARMACY #1227** **RCRA-LQG** **1014957965**
East **520 LEE ENTRANCE** **NY MANIFEST** **NYR000192013**
< 1/8 **AMHERST, NY 14228**
0.011 mi.
56 ft. **Site 1 of 3 in cluster Q**

Actual: **580 ft.**

RCRA-LQG:

Date form received by agency:	03/14/2016
Facility name:	CVS PHARMACY #1227
Facility address:	520 LEE ENTRANCE U-B COMMONS AMHERST, NY 14228
EPA ID:	NYR000192013
Mailing address:	CVS DR MAIL DROP 23062A WOONSOCKET, RI 02895
Contact:	NICOLE WILKINSON
Contact address:	CVS DR MAIL CODE 2340 WOONSOCKET, RI 02895
Contact country:	US
Contact telephone:	401-770-7132

Focus Map: **5**

CVS PHARMACY #1227 (Continued) **1014957965**

Contact email: NICOLE.WILKINSON@CVSHEALTH.COM
EPA Region: 02
Classification: Large Quantity Generator
Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name: CVS ALBANY, L.L.C.
Owner/operator address: CVS DR
WOONSOCKET, RI 02895
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 05/30/1991
Owner/Op end date: Not reported

Owner/operator name: CVS ALBANY LLC
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 05/30/1991
Owner/Op end date: Not reported

Owner/operator name: U/B COMMONS, INC.
Owner/operator address: MAIN ST
AMHERST, NY 14226
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 04/01/1991
Owner/Op end date: Not reported

Owner/operator name: U-B COMMONS INC

CVS PHARMACY #1227 (Continued) **1014957965**

Owner/operator address: MAIN ST
AMHERST, NY 14226
Owner/operator country: US
Owner/operator telephone: 716-839-1400
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 04/01/1991
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D009
. Waste name: MERCURY

. Waste code: P001
. Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

. Waste code: P075
. Waste name: NICOTINE, & SALTS

CVS PHARMACY #1227 (Continued) **1014957965**

. Waste code: U002
. Waste name: ACETONE (I)

Historical Generators:
Date form received by agency: 07/28/2015
Site name: CVS PHARMACY #1227
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D004
. Waste name: ARSENIC

. Waste code: D005
. Waste name: BARIUM

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D010
. Waste name: SELENIUM

. Waste code: D011
. Waste name: SILVER

. Waste code: D016
. Waste name: 2,4-D

. Waste code: D018
. Waste name: BENZENE

. Waste code: D024

CVS PHARMACY #1227 (Continued) **1014957965**

. Waste name: M-CRESOL

. Waste code: D027
. Waste name: 1,4-DICHLOROBENZENE

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: P001
. Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

. Waste code: P012
. Waste name: ARSENIC OXIDE AS2O3

. Waste code: P075
. Waste name: NICOTINE, & SALTS

. Waste code: P188
. Waste name: BENZOIC ACID, 2-HYDROXY-, COMPD. WITH (3AS-CIS)-1,2,3,3A,8,8A-HEXAHYDRO-1,3A,8-TRIMETHYLPYRROLO[2,3-

. Waste code: U002
. Waste name: ACETONE (I)

. Waste code: U010
. Waste name: AZIRINO[2',3':3,4]PYRROLO[1,2-A]INDOLE-4,7-DIONE, 6-AMINO-8-[[(AMINOCARBONYL)OXY]METHYL]-1,1A,2,8,8A,8B-HEXAHYDRO-8A-METHOXY-5-METHYL-, [1AS-(1AALPHA, 8BETA,8AALPHA,8BALPHA)]-

. Waste code: U031
. Waste name: 1-BUTANOL (I)

. Waste code: U034
. Waste name: ACETALDEHYDE, TRICHLORO-

. Waste code: U035
. Waste name: BENZENEBUTANOIC ACID, 4-[BIS(2-CHLOROETHYL)AMINO]-

. Waste code: U044
. Waste name: CHLOROFORM

. Waste code: U058
. Waste name: CYCLOPHOSPHAMIDE

. Waste code: U059
. Waste name: DAUNOMYCIN

. Waste code: U070
. Waste name: BENZENE, 1,2-DICHLORO-

. Waste code: U072
. Waste name: BENZENE, 1,4-DICHLORO-

CVS PHARMACY #1227 (Continued) **1014957965**

. Waste code: U089
. Waste name: DIETHYLSTILBESTEROL

. Waste code: U122
. Waste name: FORMALDEHYDE

. Waste code: U129
. Waste name: CYCLOHEXANE, 1,2,3,4,5,6-HEXACHLORO-, (1ALPHA,2ALPHA,3BETA,4ALPHA,5ALPHA,6BETA)-

. Waste code: U132
. Waste name: HEXACHLOROPHENE

. Waste code: U150
. Waste name: MELPHALAN

. Waste code: U151
. Waste name: MERCURY

. Waste code: U154
. Waste name: METHANOL (I)

. Waste code: U165
. Waste name: NAPHTHALENE

. Waste code: U188
. Waste name: PHENOL

. Waste code: U200
. Waste name: RESERPINE

. Waste code: U201
. Waste name: 1,3-BENZENEDIOL

. Waste code: U204
. Waste name: SELENIOUS ACID

. Waste code: U205
. Waste name: SELENIUM SULFIDE

. Waste code: U206
. Waste name: GLUCOPYRANOSE, 2-DEOXY-2-(3-METHYL-3-NITROSOUREIDO)-, D-

. Waste code: U210
. Waste name: ETHENE, TETRACHLORO-

. Waste code: U279
. Waste name: CARBARYL (OR) 1-NAPHTHALENOL, METHYLCARBAMATE

. Waste code: U411
. Waste name: PHENOL, 2-(1-METHYLETHOXY)-, METHYLCARBAMATE (OR) PROPOXUR

Date form received by agency: 11/03/2014
Site name: CVS PHARMACY #1227
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001

CVS PHARMACY #1227 (Continued) **1014957965**

. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D004
. Waste name: ARSENIC

. Waste code: D005
. Waste name: BARIUM

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D010
. Waste name: SELENIUM

. Waste code: D011
. Waste name: SILVER

. Waste code: D016
. Waste name: 2,4-D

. Waste code: D018
. Waste name: BENZENE

. Waste code: D024
. Waste name: M-CRESOL

. Waste code: D027
. Waste name: 1,4-DICHLOROBENZENE

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: D039

CVS PHARMACY #1227 (Continued) **1014957965**

. Waste name: TETRACHLOROETHYLENE

. Waste code: P001
. Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

. Waste code: P012
. Waste name: ARSENIC OXIDE AS2O3

. Waste code: P075
. Waste name: NICOTINE, & SALTS

. Waste code: P188
. Waste name: BENZOIC ACID, 2-HYDROXY-, COMPD. WITH (3AS-CIS)-1,2,3,3A,8,8A-HEXAHYDRO-1,3A,8-TRIMETHYLPYRROLO[2,3-

. Waste code: U002
. Waste name: ACETONE (I)

. Waste code: U010
. Waste name: AZIRINO[2',3':3,4]PYRROLO[1,2-A]INDOLE-4,7-DIONE, 6-AMINO-8-[[(AMINOCARBONYL)OXY]METHYL]-1,1A,2,8,8A,8B-HEXAHYDRO-8A-METHOXY-5-METHYL-, [1AS-(1AALPHA, 8BETA,8AALPHA,8BALPHA)]-

. Waste code: U031
. Waste name: 1-BUTANOL (I)

. Waste code: U034
. Waste name: ACETALDEHYDE, TRICHLORO-

. Waste code: U035
. Waste name: BENZENEBUTANOIC ACID, 4-[BIS(2-CHLOROETHYL)AMINO]-

. Waste code: U044
. Waste name: CHLOROFORM

. Waste code: U058
. Waste name: CYCLOPHOSPHAMIDE

. Waste code: U059
. Waste name: DAUNOMYCIN

. Waste code: U070
. Waste name: BENZENE, 1,2-DICHLORO-

. Waste code: U072
. Waste name: BENZENE, 1,4-DICHLORO-

. Waste code: U089
. Waste name: DIETHYLSTILBESTEROL

. Waste code: U122
. Waste name: FORMALDEHYDE

. Waste code: U129
. Waste name: CYCLOHEXANE, 1,2,3,4,5,6-HEXACHLORO-,

CVS PHARMACY #1227 (Continued) **1014957965**

(1ALPHA,2ALPHA,3BETA,4ALPHA,5ALPHA,6BETA)-

. Waste code: U132
. Waste name: HEXACHLOROPHENE

. Waste code: U150
. Waste name: MELPHALAN

. Waste code: U151
. Waste name: MERCURY

. Waste code: U154
. Waste name: METHANOL (I)

. Waste code: U165
. Waste name: NAPHTHALENE

. Waste code: U188
. Waste name: PHENOL

. Waste code: U200
. Waste name: RESERPINE

. Waste code: U201
. Waste name: 1,3-BENZENEDIOL

. Waste code: U204
. Waste name: SELENIOUS ACID

. Waste code: U205
. Waste name: SELENIUM SULFIDE

. Waste code: U206
. Waste name: GLUCOPYRANOSE, 2-DEOXY-2-(3-METHYL-3-NITROSOUREIDO)-, D-

. Waste code: U210
. Waste name: ETHENE, TETRACHLORO-

. Waste code: U279
. Waste name: CARBARYL (OR) 1-NAPHTHALENOL, METHYLCARBAMATE

. Waste code: U411
. Waste name: PHENOL, 2-(1-METHYLETHOXY)-, METHYLCARBAMATE (OR) PROPOXUR

Date form received by agency: 03/14/2014
Site name: CVS PHARMACY #1227
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

CVS PHARMACY #1227 (Continued) **1014957965**

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: P001
. Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

. Waste code: P075
. Waste name: NICOTINE, & SALTS

. Waste code: P081
. Waste name: NITROGLYCERINE (R)

. Waste code: P188
. Waste name: BENZOIC ACID, 2-HYDROXY-, COMPD. WITH (3AS-CIS)-1,2,3,3A,8,8A-HEXAHYDRO-1,3A,8-TRIMETHYLPYRROLO[2,3-

Date form received by agency: 07/01/2013
Site name: CVS PHARMACY #1227
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D009
. Waste name: MERCURY

. Waste code: D011
. Waste name: SILVER

. Waste code: P001
. Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

. Waste code: P042
. Waste name: 1,2-BENZENEDIOL, 4-[1-HYDROXY-2-(METHYLAMINO)ETHYL]-, (R)-

CVS PHARMACY #1227 (Continued) **1014957965**

. Waste code: P075
. Waste name: NICOTINE, & SALTS

. Waste code: P081
. Waste name: NITROGLYCERINE (R)

Date form received by agency: 03/05/2012
Site name: CVS PHARMACY #1227
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: P001
. Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

. Waste code: P042
. Waste name: 1,2-BENZENEDIOL, 4-[1-HYDROXY-2-(METHYLAMINO)ETHYL]-, (R)-

. Waste code: P075
. Waste name: NICOTINE, & SALTS

. Waste code: P081
. Waste name: NITROGLYCERINE (R)

Biennial Reports:

Last Biennial Reporting Year: 2017

Annual Waste Handled:
Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.
Amount (Lbs): 107

Waste code: D002
Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS

CVS PHARMACY #1227 (Continued) **1014957965**

CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Amount (Lbs): 8

Waste code: D009
Waste name: MERCURY
Amount (Lbs): 1

Waste code: P001
Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%
Amount (Lbs): 12

Waste code: P075
Waste name: NICOTINE, & SALTS
Amount (Lbs): 12

Waste code: U002
Waste name: ACETONE (I)
Amount (Lbs): 62

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYR000192013
Facility Status: Not reported
Location Address 1: 520 LEE ENTRANCE U-B COMMONS
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: AMHERST
Location State: NY
Location Zip: 14228
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000192013
Mailing Name: CVS PHARMACY #1227
Mailing Contact: CVS PHARMACY #1227
Mailing Address 1: 520 LEE ENTRANCE U-B COMMONS
Mailing Address 2: Not reported
Mailing City: AMHERST
Mailing State: NY
Mailing Zip: 14228
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported

CVS PHARMACY #1227 (Continued) **1014957965**

Year:	2018
Trans1 State ID:	MNS000110924
Trans2 State ID:	Not reported
Generator Ship Date:	06/19/2018
Trans1 Recv Date:	06/19/2018
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/02/2018
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000192013
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	MID980615298
TSDF ID 2:	Not reported
Manifest Tracking Number:	011300261FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D002
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
15 additional NY MANIFEST: record(s) in the EDR Site Report.

Q62
East
< 1/8
0.011 mi.
56 ft.

CVS PHARMACY 1227
520 LEE ENTRANCE UB COMMONS
AMHERST, NY 14228

Site 2 of 3 in cluster Q

PA MANIFEST | **S118068948** | **N/A**

Actual:
580 ft.

Focus Map:
5

Manifest Details:

Year:	2014
Manifest Number:	007234453FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000192013
Generator Date:	11/05/2014
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	401-765-1500
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	2
Waste Number:	D001
Container Number:	1
Container Type:	Fiber or plastic boxes, cartons, cases
Waste Quantity:	10
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Year:	2014
Manifest Number:	007234453FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000192013
Generator Date:	11/05/2014
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	401-765-1500
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	U002
Container Number:	1
Container Type:	Burlap, cloth, paper or plastic bags
Waste Quantity:	12
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592

CVS PHARMACY 1227 (Continued) **S118068948**

Date TSP Sig:	Not reported
Year:	2014
Manifest Number:	007234453FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000192013
Generator Date:	11/05/2014
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	401-765-1500
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D001
Container Number:	1
Container Type:	Burlap, cloth, paper or plastic bags
Waste Quantity:	12
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Q63 **CVS PHARMACY #1227** **FINDS 1016003742**
East **520 LEE ENTRANCE U-B COMMONS** **ECHO N/A**
< 1/8 **AMHERST, NY 14228**
0.011 mi.
56 ft. **Site 3 of 3 in cluster Q**

Actual:
580 ft.

Focus Map:
5

FINDS:

Registry ID: 110045410765

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016003742
Registry ID:	110045410765
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110045410765

D64 **NYSDOT BIN 1-07260-2** **FINDS** **1016255710**
ESE **I290 NB BRG OVER SWEET HOME RD** **ECHO** **N/A**
< 1/8 **AMHERST, NY 14228**
0.011 mi.
58 ft. **Site 2 of 2 in cluster D**

Actual: FINDS:
600 ft.

Focus Map: Registry ID: 110008107039
4

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016255710
Registry ID:	110008107039
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110008107039

L65 **CAR FIRE** **NY Spills** **S110539639**
East **1009-1025 NIAGARA FALLS BLVD.** **N/A**
< 1/8 **AMHERST, NY**
0.011 mi.
58 ft. **Site 2 of 6 in cluster L**

Actual: SPILLS:
596 ft.

Focus Map:
6

Spill Number/Closed Date:	1006430 / 2010-09-08
Facility ID:	1006430
Facility Type:	ER
DER Facility ID:	394777
Site ID:	439785
DEC Region:	9
Spill Cause:	Other
Spill Class:	D4
SWIS:	1522
Spill Date:	2010-09-07
Investigator:	SACALAND
Referred To:	Not reported
Reported to Dept:	2010-09-08
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Passenger Vehicle
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2010-09-14
Spill Record Last Update:	2010-09-14

CAR FIRE (Continued) **S110539639**

Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	DOMINIC CREAMER
DEC Memo:	"9/8/10:SAC RECEIVED MESSAGE FROM DOMINIC CREAMER - TOWN OF AMHERST FIRE DEPT. FIRE DEPT. RESPONDED TO A CAR FIRE. WHILE EXTINGUISHING THE FIRE, THE VEHICLE'S FUEL TANK DROPPED TO THE PAVEMENT SPILLING GASOLINE. THE FIRE DEPT WAS INITIALLY UNAWARE OF THIS AND WHILE USING FIREFIGHTING FOAM, CAUSED SOME FUEL TO ENTER THE STORM DRAIN. PADS AND BOOM WERE USED TO ABSORB WHAT PRODUCT ENTERED THE DRAIN. AS A FURTHER PRECAUTION, ADDITIONAL FOAM WAS USED TO FLUSH ANY REMAINING PRODUCT FROM THE STORM DRAINAGE SYSTEM AND SUPPRESS ANY REMAINING VAPORS. SPILL CLEANED UP. NO FURTHER WORK REQUIRED BY SPILLS. COMPUTER FILE ONLY."
Remarks:	"CAR FIRE CAUSED VEHICLE FUEL TANK TO DROP TO THE PAVEMENT."

All Materials:

Site ID:	439785
Operable Unit ID:	1190418
Operable Unit:	01
Material ID:	2185414
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

R66 **JIM & DEES ATLANTIC SERVICE** **EDR Hist Auto** **1020352957**
West **826 NIAGARA FALLS B** **N/A**
< 1/8 **BUFFALO, NY 14223**
0.011 mi.
60 ft. **Site 1 of 7 in cluster R**

Actual: EDR Hist Auto
598 ft.

Focus Map: **6**

Year:	Name:	Type:
1969	ATLANTIC JIM & DEES	Gasoline Service Stations
1969	JIM & DEES ATLANTIC SERVICE	Gasoline Service Stations
1970	JIM & DEES ATLANTIC SERVICE	Gasoline Service Stations
1970	ATLANTIC JIM & DEES	Gasoline Service Stations
1971	JIM & DEES ATLANTIC SERVICE	Gasoline Service Stations
1971	ATLANTIC JIM & DEES	Gasoline Service Stations
1972	JIM & DEES ATLANTIC SERVICE	Gasoline Service Stations
1972	ATLANTIC JIM & DEES	Gasoline Service Stations
1973	JIM & DEES ATLANTIC SERVICE	Gasoline Service Stations
1973	ATLANTIC JIM & DEES	Gasoline Service Stations
1974	ATLANTIC JIM & DEES	Gasoline Service Stations
1974	JIM & DEES ATLANTIC SERVICE	Gasoline Service Stations
1975	ATLANTIC JIM & DEES	Gasoline Service Stations
1975	JIM & DEES ATLANTIC SERVICE	Gasoline Service Stations
1976	WOOD JAMES B	Gasoline Service Stations
1977	WOOD JAMES B	Gasoline Service Stations
1978	WOOD JAMES B	Gasoline Service Stations

JIM & DEES ATLANTIC SERVICE (Continued) **1020352957**

1979	WOOD JAMES B	Gasoline Service Stations
1980	WOOD JAMES B	Gasoline Service Stations
1982	WOOD JAMES B	Gasoline Service Stations
1983	WOOD JAMES B	Gasoline Service Stations
1985	WOOD JAMES B	Gasoline Service Stations
1986	WOODS TIRE & BATTERY	Gasoline Service Stations
1987	WOODS TIRE & BATTERY	Gasoline Service Stations
1988	WOODS TIRE & BATTERY	Gasoline Service Stations
1989	WOODS TIRE & BATTERY	Gasoline Service Stations
1990	WOODS TIRE & BATTERY	Gasoline Service Stations
1991	WOODS TIRE & BATTERY	Gasoline Service Stations
1992	WOODS TIRE & BATTERY	Gasoline Service Stations
1993	WOODS TIRE & BATTERY	Gasoline Service Stations

R67 **JIM WOODS TIRE & BATTERY** **NY LTANKS** **S100250830**
West **826 NIAGARA FALLS BLVD** **N/A**
< 1/8 **AMHERST, NY**
0.011 mi.
60 ft. **Site 2 of 7 in cluster R**

Actual: LTANKS:
598 ft.

Spill Number/Closed Date:	8707234 / 1988-10-20
Facility ID:	8707234
Site ID:	314328
Spill Date:	1987-11-20
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C1
Cleanup Ceased:	1988-10-20
SWIS:	1522
Investigator:	COOKE
Referred To:	Not reported
Reported to Dept:	1987-11-20
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1987-11-23
Spill Record Last Update:	2009-08-04
Spiller Name:	Not reported
Spiller Company:	JIM WOODS TIRE & BATTERY
Spiller Address:	826 NIAGARA FALLS BLVD.
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	9
DER Facility ID:	277913
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was JDC / / : MJH TELECON 11/20/87, TANK TO BE EMPTIED, SPILLER MADE AWARE OF REMOVAL REQUIREMENTS. / / : JDC TELCON W/ MR WOODS, WOODS TIRE AN DBATTERY 11/30/87 - REQUESTED RETEST RESULTS WHEN COMPLETED. TEST BEING PERFORMED 11/30/87. / / : JDC TELCON W/ MR WOODS 12/14/87 - EXPLAINED TANK ABANDONMENT PROCEDURES TO MR WOODS. HE WILL BE

Focus Map:
6

JIM WOODS TIRE & BATTERY (Continued) **S100250830**

RELATING COMPLETION DATE. 03/31/88: TANK RETEST RESULTS SHOULD HAVE BEEN RECEIVED BY THE DEPT. ALL RESULTS TO DATE HAVE NOT BEEN SORTED,THEREFORE A SEARCH WOULD BE IMPRACTICAL. WILL CHECK PBS RECORDS AT A LATER DATE. 03/31/88: JDC SPOKE W/ JIM WOODS AND REQUESTED RETEST RESULTS. RESULTS WERE MAILED TO MR LOCEY. WILL CHECK W/ MR LOCEY TO OBTAIN TEST RESULTS. 09/26/88: JDC SPOKE W/ CERTIFIED TESTING AND REQUESTED A COPY OF THE RETEST RESULTS. 10/20/88: JDC RECEIVED TEST RESULTS SHOWING TANK TO BE TIGHT. NO FURTHER ACTION WILL BE REQUIRED. "

Remarks: "8000 GALLON TANK FAILURE RATE 0.3 GPH"

All TTF:

Facility ID:	8707234
Spill Number:	8707234
Spill Tank Test:	1532407
Site ID:	314328
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	314328
Operable Unit ID:	912964
Operable Unit:	01
Material ID:	466200
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

R68 **UNI-MART STORE** **NY Spills** **S102447810**
East **NIAGARA FALLS BLV & MOORE** **N/A**
< 1/8 **TONAWANDA, NY**
0.011 mi.
60 ft. **Site 3 of 7 in cluster R**

Actual:
599 ft.

Focus Map:
6

SPILLS:

Spill Number/Closed Date:	9611103 / 1996-12-06
Facility ID:	9611103
Facility Type:	ER
DER Facility ID:	62117
Site ID:	64458
DEC Region:	9

UNI-MART STORE (Continued) **S102447810**

Spill Cause:	Human Error
Spill Class:	D6
SWIS:	1564
Spill Date:	1996-12-06
Investigator:	SORGI
Referred To:	Not reported
Reported to Dept:	1996-12-06
CID:	351
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	1996-12-06
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-12-09
Spill Record Last Update:	1996-12-20
Spiller Name:	Not reported
Spiller Company:	UNKNOWN VEHICLE
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MJS 12/06/96: MJS SITE INSPECT. FOUND HEAVY SHEEN ON WET ASPHALT PARKING LOT. APPEARS THAT CUSTOMER OVERFILLED TANK. NO CLEANUP REQUIRED/POSSIBLE. MJS SPOKE TO EMPLOYEE INSIDE STORE. SHE IS NOT AWARE OF EXACT CAUSE. MJS CLOSE FILE."
Remarks:	"CALLER REPORTED GASOLINE ODOR AND HEAVY SHEEN IN SERVICE AREA. SHEEN ENETRING STORM SEWER SPILL FAXED FROM REGION 9 "

All Materials:

Site ID:	64458
Operable Unit ID:	1039130
Operable Unit:	01
Material ID:	343309
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

B69 **NY COOLING TOWERS** **S121998348**
East **10 JOHN JAMES AUDUBON PARKWAY** **N/A**
< 1/8 **AMHERST, NY 14228**
0.012 mi.
61 ft. **Site 4 of 5 in cluster B**

Actual:
576 ft.

Focus Map:
5

COOLING TOWERS:

Equipment Unique ID:	8926
Equipment Borough:	10
Intended Use:	Air Conditioning
Manufacturer:	BALTIMORE AIRCOIL

(Continued) **S121998348**

Model:	VF1-027-41K
Cooling Capacity:	40
Cooling Capacity Unit:	Tonnage
Commissioned Date:	07/01/2008
Inspection Date:	Not reported
Date of Bacteriological Collection:	Not reported
Date of Legionella Collection:	Not reported
Last Legionella Result > 1,000 CFU/mL:	no
Latitude:	43.010846079
Longitude:	-78.778738419

N70 **FIRESTONE SERVICE CENTER** **NY Spills** **S102667965**
East **955 NIAGARA FALLS BLVD** **N/A**
< 1/8 **AMHERST, NY**
0.012 mi.
61 ft. **Site 3 of 4 in cluster N**

Actual:
598 ft.

Focus Map:
6

SPILLS:

Spill Number/Closed Date:	9707595 / 1998-08-26
Facility ID:	9707595
Facility Type:	ER
DER Facility ID:	59057
Site ID:	60504
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	B4
SWIS:	1522
Spill Date:	1997-09-01
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	1997-09-26
CID:	999
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	1997-10-03
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-09-26
Spill Record Last Update:	1999-09-13
Spiller Name:	STEVEN KRACKER
Spiller Company:	FIRESTONE SERVICE
Spiller Address:	955 NIAGARA FALLS BLVD
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 10/03/97 RMC/COOPER/PHONE DEC NOT CALLED DUE TO AN OVERSIGHT, EXCAVATION SAMPLED, NO INSPECTION OF EXCAVATION POSSIBLE AS NEW LIFT ALREADY INSTALLED, DISPOSAL AND EXCAVATION SAMPLE RESULTS DUE 10/30/97 10/14/97 RMC/FILE RECEIVED SAMPLE RESULTS FROM LIFT EXCAVATION, MEETS STARS, DISPOSAL DUE 11/15/97 12/26/97 RMC/FILE LETTER ON DISPOSAL, RESPONSE DUE 1/9/98 01/1/98 RMC/FILE RP CALLED ADVISING THAT DISPOSAL PENDING, DUE 2/15/98 04/23/98 RMC/FILE LEFT MESSAGE FOR COOPER REQUESTING DISPOSAL RECEIPTS, DUE 5/1/98 04/28/98 RMC/FILE LEFT MESSAVE FOR DENNIS JAGIELLO TO CALL ABOUT DISPOSAL

FIRESTONE SERVICE CENTER (Continued) **S102667965**

RECEIPT, UPDATE 5/5/98 06/1/98 RMC/FILE LEFT MESSAGE FOR JAGIELLO TO CALL, CALL DUE 6/16 08/10/98 RMC/DENNIS JAGIELLO/PHONE RECIEPT WILL BE SENT DUE 8/13/98 08/26/98 RMC/FILE RECIEVED DISPOSAL RECEIPT, OK, CLOSE OUT GHT"

Remarks: "HYDRAULIC OIL LIFT REPLACEMENT FOUND CONTAMINATED SOIL. SOIL STAGED ON SITE, NOTIFIED END WEEK AFTER DISCOVERY. LEFT LIM ???? REPAIRED, BACKFILLED, ??? INSPECTION POSSIBLE."

All Materials:

Site ID:	60504
Operable Unit ID:	1050932
Operable Unit:	01
Material ID:	329607
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

S71 **CM HEADQUARTERS BUILDING** **NY UST** **U003318683**
NE **140 JOHN JAMES AUDUBON PARKWAY** **N/A**
< 1/8 **AMHERST, NY 14228**
0.012 mi.
63 ft. **Site 1 of 2 in cluster S**

Actual:
580 ft.

Focus Map:
2

UST:

Id/Status:	9-600005 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	9
Expiration Date:	N/A
UTM X:	192061.05191
UTM Y:	4769248.81991
Site Type:	Other

Affiliation Records:

Site Id:	54875
Affiliation Type:	Facility Owner
Company Name:	COLUMBUS MCKINNON CORPORATION
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	140 JOHN JAMES AUDOBON PARKWAY
Address2:	Not reported
City:	AMHERST
State:	NY
Zip Code:	14228
Country Code:	001
Phone:	(716) 689-5499
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	54875
Affiliation Type:	Mail Contact

CM HEADQUARTERS BUILDING (Continued) **U003318683**

Company Name:	COLUMBUS MCKINNON CORPORATION
Contact Type:	Not reported
Contact Name:	PETER A. GRANT
Address1:	140 JOHN JAMES AUDOBON PARKWAY
Address2:	Not reported
City:	AMHERST
State:	NY
Zip Code:	14228
Country Code:	001
Phone:	(716) 689-5610
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	54875
Affiliation Type:	Facility Operator
Company Name:	CM HEADQUARTERS BUILDING
Contact Type:	Not reported
Contact Name:	PETER A GRANT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(716) 689-5400
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	54875
Affiliation Type:	Emergency Contact
Company Name:	COLUMBUS MCKINNON CORPORATION
Contact Type:	Not reported
Contact Name:	PETER A GRANT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(716) 689-5400
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	1
Tank ID:	169153
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	08/01/1980

CM HEADQUARTERS BUILDING (Continued) **U003318683**

Date Tank Closed:	11/01/1992
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
I00 - Overfill - None
F05 - Pipe External Protection - Jacketed
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground

S72 **COLUMBUS MCKINNON, INC.** **NY LTANKS** **S100494451**
NE **140 JOHN JAMES AUDOBON** **N/A**
< 1/8 **AMHERST, NY**
0.012 mi.
63 ft. **Site 2 of 2 in cluster S**

Actual:
580 ft.

Focus Map:
2

LTANKS:

Spill Number/Closed Date:	9210347 / 1993-02-22
Facility ID:	9210347
Site ID:	216514
Spill Date:	1992-12-04
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	1993-02-22
SWIS:	1522
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	1992-12-04
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	1992-12-18
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1992-12-09
Spill Record Last Update:	1993-02-23
Spiller Name:	Not reported
Spiller Company:	COLUMBUS MCKINNON, INC.
Spiller Address:	140 JOHN JAMES AUDOBON
Spiller County:	001

COLUMBUS MCKINNON, INC. (Continued) **S100494451**

Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 9
DER Facility ID: 179263
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 12/07/92: RMC/TIM V./PHONE - PLAN TO INSTALL WELL AND RETEST. RESULTS DUE 1/30/92. 12/07/92: RMC/SITE - NO VISUAL CONTAMINATION. RMC/PAUL RESULTS DUE 1/30/92. 12/11/92: RMC/SITE - NO VISUAL CONTAMINATION. RMC/PAUL SUOZZI WILL CARBON FILTER TANK PIT WATER AND RETEST. RESULTS DUE 1/30/92. 12/21/92: RMC - RECEIVED RESULTS. GAVE OKAY ON BACKFILL. DISPOSAL RECEIPT DUE 2/1/93. 02/22/93: RMC/RECEIVED RECEIPT FOR MATERIALS INSIDE THE TANK. EXCAVATED MATERIAL WAS NOT CONTAMINATED AND WAS USED FOR PART OF THE BACKFILL. NO FURTHER ACTION REQUIRED...CLOSE OUT. "
Remarks: "TANK FAILURE."

All Materials:
Site ID: 216514
Operable Unit ID: 974599
Operable Unit: 01
Material ID: 403811
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Not reported
Recovered: .00
Oxygenate: Not reported

T73 **GREAT LAKES DIVERS** **NY UST** **U004257580**
West **240 NIAGARA FALLS BLVD** **N/A**
< 1/8 **TONAWANDA, NY 14223**
0.012 mi.
64 ft. **Site 1 of 4 in cluster T**

Actual:
618 ft.

Focus Map:
8

UST:
Id/Status: 9-601679 / Unregistered
Program Type: PBS
Region: STATE
DEC Region: 9
Expiration Date: N/A
UTM X: 188091.98499
UTM Y: 4763541.87662
Site Type: Other

Affiliation Records:
Site Id: 537372
Affiliation Type: Facility Owner
Company Name: ROBERT HILLS
Contact Type: Not reported
Contact Name: Not reported
Address1: 5150 BANK ST
Address2: Not reported
City: CLARENCE
State: NY
Zip Code: Not reported

GREAT LAKES DIVERS (Continued) **U004257580**

Country Code:	001
Phone:	(716) 759-2454
EMail:	Not reported
Fax Number:	Not reported
Modified By:	SRMCDONN
Date Last Modified:	2016-12-09

Site Id:	537372
Affiliation Type:	Mail Contact
Company Name:	ROBERT HILLS
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	5150 BANK ST
Address2:	Not reported
City:	CLARENCE
State:	NY
Zip Code:	Not reported
Country Code:	001
Phone:	(716) 759-2454
EMail:	Not reported
Fax Number:	Not reported
Modified By:	SRMCDONN
Date Last Modified:	2016-12-09

Tank Info:

Tank Number:	1
Tank ID:	266117
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	700
Install Date:	Not reported
Date Tank Closed:	10/04/1996
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	SRMCDONN
Last Modified:	04/14/2017

T74 **BROWN GEORGE A** **EDR Hist Auto** **1020378320**
West **240-246 NIAGARA FALLS BLV** **N/A**
< 1/8 **BUFFALO, NY 14223**
0.012 mi.
64 ft. **Site 2 of 4 in cluster T**

Actual: EDR Hist Auto
618 ft.

Focus Map:
8

Year:	Name:	Type:
1971	BROWN GEORGE A	Gasoline Service Stations
1972	BROWN GEORGE A	Gasoline Service Stations
1973	BROWN GEORGE A	Gasoline Service Stations
1974	BROWN GEORGE A	Gasoline Service Stations

U75 **BALL PUMP STATION & TANKS** **NY Spills** **S118706163**
SE **SWEET HOME RD** **NY MANIFEST** **N/A**
< 1/8 **AMHERST, NY 14226**
0.012 mi.
64 ft. **Site 1 of 3 in cluster U**

Actual:
598 ft.

Focus Map:
4

SPILLS:

Spill Number/Closed Date:	1603248 / 2016-07-06
Facility ID:	1603248
Facility Type:	ER
DER Facility ID:	483801
Site ID:	529699
DEC Region:	9
Spill Cause:	Unknown
Spill Class:	D3
SWIS:	1522
Spill Date:	2016-06-25
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	2016-07-05
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2016-07-05
Spill Record Last Update:	2016-07-06
Spiller Name:	Not reported
Spiller Company:	PINTO
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	REV
DEC Memo:	"07/05/16 RMC/FILE. DUPLICATE OF 1603187 CLOSE OUT"
Remarks:	"The following information was received through the DEC website Report an Environmental Violation Online or sent directly by the complainant to an OPP dispatch mailbox: Who Did It: A excavator on-site. Pinto is the company. What Occurred: Leaked a lot of hydraulic fluid into the ground 10 ft from the construction of a new drinking water tank. When Did It Occur: Thursday of last week. 6/30/2016 County: Erie Municipality: Amherst Location Or Address: 1193 sweet home road. How Did It Occur: Additional Details: The spill left a huge wet spot. The company attempted to cover it. Complainants Name: Complainants Phone: Complainants Email: Date of Submittal: 07/05/2016"

All Materials:

Site ID:	529699
Operable Unit ID:	1278521
Operable Unit:	01
Material ID:	2283431
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported

BALL PUMP STATION & TANKS (Continued) **S118706163**

Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

NY MANIFEST:

Country:	USA
EPA ID:	NYR000130872
Facility Status:	Not reported
Location Address 1:	1193 SWEET HOME RD
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	AMHERST
Location State:	NY
Location Zip:	14226
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000130872
Mailing Name:	BALL PUMP STATION & TANKS
Mailing Contact:	THOMAS WIK
Mailing Address 1:	3030 UNION RD
Mailing Address 2:	Not reported
Mailing City:	BUFFALO
Mailing State:	NY
Mailing Zip:	14227
Mailing Zip 4:	1097
Mailing Country:	USA
Mailing Phone:	7166858233

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2008
Trans1 State ID:	NJD080631369
Trans2 State ID:	NJD054126164
Generator Ship Date:	01/11/2008
Trans1 Recv Date:	01/11/2008
Trans2 Recv Date:	02/01/2008
TSD Site Recv Date:	02/01/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000130872
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	000250667VES
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N

BALL PUMP STATION & TANKS (Continued) **S118706163**

Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200.0
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1.0
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Waste Code:	Not reported
Waste Code 1_2:	B007
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

U76 **PINTO CONSTRUCTION** **NY Spills** **S118706107**
SE **1193 SWEET HOME RD** **N/A**
< 1/8 **AMHERST, NY 14221**
0.012 mi.
64 ft. **Site 2 of 3 in cluster U**

Actual:
598 ft.

Focus Map:
4

SPILLS:

Spill Number/Closed Date:	1603187 / 2016-09-15
Facility ID:	1603187
Facility Type:	ER
DER Facility ID:	486606
Site ID:	529635
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	D3
SWIS:	1522
Spill Date:	2016-06-30
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	2016-07-01
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	2016-07-05
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2016-07-01

PINTO CONSTRUCTION (Continued) **S118706107**

Spill Record Last Update:	2016-09-15
Spiller Name:	JIM PANEPINTO
Spiller Company:	PINTO CONSTRUCTION
Spiller Address:	1 BABCOCK STREET
Spiller Company:	999
Contact Name:	BRYAN MAYBACK
DEC Memo:	"07/01/16 RMC/BRIAN MAYBACH/PHONE. SMALL SPILL CLEANED UP. RMC REQUESTED NAME OF PROPERTY OWNER AND DISPOSAL RECEIPT FOR THE YARD OF MATERIAL DUG OUT. DUE 7/30/16. 07/05/16 RMC/FILE. RECEIVED AN ANONYMOUS COMPLAINT. RMC WENT TO THE SITE 9 AM. PINTON NOT WORKING ON THE SITE TODAY. PROJECT SUPERINTENDENT SEAN STEWART, DN TANKS SHOWED ME THE AREA OF THE SPILL. LOCATED JUST NORTH OF THE NEW TANK BING INSTALLED. HUNDREDEDS OF YARDS OF STONE HAVE BEEN PUT IN TO SUPPORT PERIMETER OPERATIONS. THE SPILL WAS ON THAT STONE. THE STONE WILL BE REMOVED UPON COMPLETION OF THE WORK. STEWART REPORTED THAT PINTO REMOVED ALL THE VISUALLY IMPACTED SOIL. 09/15/16 RMC/FILE. RECIEVED DISPOSAL RECEIPT FOR 1.87 TONS. NO FURTHER ACTION REQUIRED. CLOSE OUT."
Remarks:	"Caller vised an excavator bust a line and spilled aprx 2 gal of oil onto soil. Clean up is in progress."

All Materials:

Site ID:	529635
Operable Unit ID:	1278458
Operable Unit:	01
Material ID:	2283367
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	2.00
Oxygenate:	Not reported

V77 **SWEETHOME JUNIOR HIGH SCHOOL** **NY UST U003316486**
North **4150 MAPLE RD** **NY Spills N/A**
< 1/8 **AMHERST, NY 14226**
0.012 mi.
65 ft. **Site 1 of 2 in cluster V**

Actual:
596 ft.

Focus Map:
7

UST:

Id/Status:	9-024511 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	9
Expiration Date:	N/A
UTM X:	189392.05673
UTM Y:	4766847.49824
Site Type:	School

Affiliation Records:

Site Id:	52149
Affiliation Type:	Facility Owner
Company Name:	SWEETHOME CENTRAL SCHOOL DIST
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	1901 SWEET HOME RD

SWEETHOME JUNIOR HIGH SCHOOL (Continued) **U003316486**

Address2:	Not reported
City:	AMHERST
State:	NY
Zip Code:	14228
Country Code:	001
Phone:	(716) 689-5200
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	52149
Affiliation Type:	Mail Contact
Company Name:	SWEETHOME CENTRAL SCHOOL DIST
Contact Type:	Not reported
Contact Name:	KENNETH KOCH
Address1:	1741 SWEET HOME RD
Address2:	Not reported
City:	AMHERST
State:	NY
Zip Code:	14228
Country Code:	001
Phone:	(716) 689-5245
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	52149
Affiliation Type:	Facility Operator
Company Name:	SWEETHOME JUNIOR HIGH SCHOOL
Contact Type:	Not reported
Contact Name:	JACK AULT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(716) 837-3500
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	52149
Affiliation Type:	Emergency Contact
Company Name:	SWEETHOME CENTRAL SCHOOL DIST
Contact Type:	Not reported
Contact Name:	KENNETH KOCH
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(716) 694-7741

SWEETHOME JUNIOR HIGH SCHOOL (Continued) **U003316486**

EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Tank Info:

Tank Number: 331
Tank ID: 160867
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 15000
Install Date: 01/01/1963
Date Tank Closed: 08/01/1992
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: 01
Date Test: 10/01/1987
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

SPILLS:

Spill Number/Closed Date: 0608981 / 2007-03-09
Facility ID: 0608981
Facility Type: ER
DER Facility ID: 250096
Site ID: 373071
DEC Region: 9
Spill Cause: Other
Spill Class: C3
SWIS: 1522
Spill Date: 2006-11-06
Investigator: RJJONAK
Referred To: Not reported
Reported to Dept: 2006-11-06
CID: 444
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported

SWEETHOME JUNIOR HIGH SCHOOL (Continued) **U003316486**

Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-11-06
Spill Record Last Update:	2007-03-09
Spiller Name:	MIKE MORROW
Spiller Company:	NATIONAL GRID
Spiller Address:	144 KENSINGTON AVENUE
Spiller Company:	001
Contact Name:	MIKE MORROW
DEC Memo:	"11/6/2006: RJJ AT SITE AT 1330...A BUSHING BROKE ON A PADMOUNT TRANSFORMER CAUSING ~5 GAL OF NON-PCB OIL TO SPILL OUT ON THE CONCRETE PAD AND A SMALL AMOUNT ON THE SOIL...NATIONAL GRID PERSONNAL USED ABSORBANTS TO CLEAN UP THE SPILL AND SCRAPED UP THE AFFECTED SOIL,THEN THEY WILL DISPOSE THE MATERIAL AND SEND ME THE DISPOSAL RECEIPTS...NONE OF THE OIL REACHED ANY RECEIVERS OR WATERWAYS. 3/9/2007: RECEIVED THE DISPOSAL RECEIPTS FOR 1-55 GAL DRUM OF MATERIAL TAKEN TO OP-TECH'S WAVERLY LANDFILL...THE SPILL HAS BEEN CLEANED UP AND PROPERLY DISPOSED OF...NO FURTHER ACTION NEEDED...SPILL CLOSED OUT."
Remarks:	"A BUSHING BROKE ON A PADMOUNT: AND BEING CLEANED UP"

All Materials:

Site ID:	373071
Operable Unit ID:	1130796
Operable Unit:	01
Material ID:	2120468
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	5.00
Oxygenate:	Not reported

Spill Number/Closed Date:	9509066 / 1995-10-23
Facility ID:	9509066
Facility Type:	ER
DER Facility ID:	250096
Site ID:	309801
DEC Region:	9
Spill Cause:	Human Error
Spill Class:	B4
SWIS:	1522
Spill Date:	1995-10-23
Investigator:	PRINGLE
Referred To:	Not reported
Reported to Dept:	1995-10-23
CID:	205
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True

SWEETHOME JUNIOR HIGH SCHOOL (Continued) **U003316486**

Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1995-10-23
Spill Record Last Update:	1995-11-17
Spiller Name:	Not reported
Spiller Company:	SWEET HOME MIDDLE SCHOOL
Spiller Address:	4150 MAPLE ROAD
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MNP 10/23/95: MNP TELECONS W/ JAMES ZYMANEK - TOWN OF AMHERST DISASTER COORDINATER. MURIATIC ACID & HYPOCHLORIDE MIXED IN CONTAINER, NO SPILLAGE. FUMES GENERATED. ZYMANEK SEEKING GUIDANCE TO NETRALIZE. RECOMMENDED DILUTION W/ WATER & LIME, THEN FLUSH TO SANITARY SEWER AFTER OBTAINING PERMISSION FROM TOWN SEWER DEPARTMENT. ZYMANEK OK'D DISCHARGE TO SEWER. NO DEC RESPONSE REQUIRED, COMPLETE. NOTE: FOUND OUT LATER ON RADIO THAT SCHOOL HAD BEEN CLOSED & SOME STUDENTS SENT TO HOSPITAL. PETER BEUCHI ADVISED OF INCIDENT."
Remarks:	"MURIATIC ACID AND HYPOCHLORIDE MIXED IN CONTAINER. FD AND HAZ MAT ON SCENE"

All Materials:

Site ID:	309801
Operable Unit ID:	1019635
Operable Unit:	01
Material ID:	360032
Material Code:	1114A
Material Name:	hypochloride
Case No.:	Not reported
Material FA:	Other
Quantity:	15.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Site ID:	309801
Operable Unit ID:	1019635
Operable Unit:	01
Material ID:	360031
Material Code:	0029C
Material Name:	hydrogen chloride
Case No.:	07647010
Material FA:	Hazardous Material
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

V78 **NY COOLING TOWERS** **S121996992**
North **4150 MAPLE RD.** **N/A**
< 1/8 **AMHERST, NY 14226**
0.012 mi.
65 ft. **Site 2 of 2 in cluster V**

Actual: **596 ft.**

Focus Map: **7**

COOLING TOWERS:

Equipment Unique ID:	7508
Equipment Borough:	4150
Intended Use:	Air Conditioning
Manufacturer:	BAC
Model:	VTO 145 MCR
Cooling Capacity:	145
Cooling Capacity Unit:	Tonnage
Commissioned Date:	09/17/2015
Inspection Date:	08/22/2018
Date of Bacteriological Collection:	08/22/2018
Date of Legionella Collection:	08/22/2018
Last Legionella Result > 1,000 CFU/mL:	no
Latitude:	42.990826501
Longitude:	-78.809482473

---

79 **SHELDON RESIDENCE** **NY Spills** **S105141680**
East **333 NIAGARA FALLS BLVD** **N/A**
< 1/8 **AMHERST, NY**
0.013 mi.
67 ft.

Actual: **609 ft.**

Focus Map: **8**

SPILLS:

Spill Number/Closed Date:	0175270 / 2001-09-17
Facility ID:	0175270
Facility Type:	ER
DER Facility ID:	164856
Site ID:	198095
DEC Region:	9
Spill Cause:	Human Error
Spill Class:	C3
SWIS:	1522
Spill Date:	2001-08-17
Investigator:	RJJONAK
Referred To:	Not reported
Reported to Dept:	2001-08-17
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	2001-09-17
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-08-17
Spill Record Last Update:	2001-09-19
Spiller Name:	ART MULLER
Spiller Company:	NOCO
Spiller Address:	700 GRAND ISLAND BLVD
Spiller Company:	001
Contact Name:	MICHAEL SHELDON
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was

SHELDON RESIDENCE (Continued) **S105141680**

RJJ 8/17/2001: RJJ AT SITE AT 1745...NOCO REMOVED 2-275 FUEL OIL TANKS FROM UNDER A CRAWL SPACE,BUT ONE OF THEM RUPTURED SPILLING ABOUT 5 GAL OF FUEL OIL...NOCO SCRAPED UP THE SOIL AND PLACED ABSORBANTS ON THE SPILL,THEY WILL RETURN TO PICK UP AND CHANGE THE PADS,IF NECESSARY...MIKE YOUNT,NOCO,WILL SEND ME THE REPORT. 8/20/2001: RECEIVED THE SPILL REPORT FROM MIKE YOUNT,NOCO...NOCO USED 1 BAG OF ABSORBANT PADS TO SOAK UP THE FUEL OIL WHICH SPILLED FROM ONE OF THE 275 GAL FUEL OIL TANKS THEY REMOVED FROM UNDER THE HOUSE...THEY DISPOSED THE FUEL SOAKED PADS AT THEIR RIVER ROAD NOCO TERMINAL IN THEIR 'PROFILED' MODERN DUMPSTER... NOCO WILL RETURN THERE TO CHANGE AND PICK UP THE REMAINING PADS...MIKE WILL KEEP ME INFORMED ON THEIR ACTIONS. 9/17/2001: RJJ AT SITE AT 1000...MICHAEL SHELDON,OWNER,LET ME INSIDE TO CHECK ON BASEMENT...NOCO HAS REMOVED ALL THE ABSORBANTS AND DISPOSED THEM IN THEIR DUMPSTER...IN THE BASEMENT THERE WAS NO ODOR OF ANY KIND...ALL THE FUEL OIL WAS RECOVERED AND DISPOSED OF...NO FURTHER ACTION NEEDED...SPILL CLOSED OUT."

Remarks: "APPROX. 5 GALS. SPILLED FROM TANK THAT WAS SUPPOSED TO BE EMPTY TO CRAWL SPACE BENEATH RESIDENCE. NOCO WAS IN THE PROCESS OF REMOVING 2 275-GALS. A/G UST'S THAT WERE LOCATED IN THE CRAWL SPACE."

All Materials:

Site ID:	198095
Operable Unit ID:	853025
Operable Unit:	01
Material ID:	524590
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

80
East
< 1/8
0.013 mi.
68 ft.

FORMER GAS STATION
895 NIAGARA FALLS BLVD
AMHERST, NY

NY Spills **S104789203**
N/A

Actual:
597 ft.

Focus Map:
6

SPILLS:

Spill Number/Closed Date:	0075336 / 2001-02-14
Facility ID:	0075336
Facility Type:	ER
DER Facility ID:	155867
Site ID:	186488
DEC Region:	9
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	1522
Spill Date:	2000-08-01
Investigator:	RJJONAK
Referred To:	Not reported
Reported to Dept:	2000-08-29
CID:	Not reported
Water Affected:	Not reported

FORMER GAS STATION (Continued) **S104789203**

Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	2001-01-10
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-08-29
Spill Record Last Update:	2001-02-22
Spiller Name:	Not reported
Spiller Company:	STUART SCHEFF
Spiller Address:	899 NIAGARA FALLS BLVD.
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RJJ 08/30/2000: RJJ TELECON JOHN BLANCHARD, DAY ENVIRONMENTAL, JOHN EXPLAINED WHAT THEY DID AT 895 NIAGARA FALLS BLVD...THEY DID A MODIFIED PHASE 1 & PHASE 2 REPORT FOR HSBC BANK, AND FOUND ONE AREA OF CONTAMINATION THAT EXCEEDS 'STARS'...JOHN WILL ASK THE BANK IF HE CAN SEND ME THE REPORT...I WILL DRAFT A 'RESPONSIBLE PARTY' LETTER AND SEND IT TO THE PROPERTY OWNER, STUART SCHEFF, WHO LIVES NEXT DOOR. 11/06/2000: RJJ RECEIVED THE PHASE 2 REPORT FROM JOHN BLANCHARD...TEST BORING #10, NEAR NIAGARA FALLS BLVD., ON THE WESTSIDE OF THE PROPERTY, APPEARS TO BE THE ONLY PROBLEM ...STUART SCHEFF, OWNER, HAS HIRED AN ENVIRONMENTAL FIRM TO CLEAN UP THE CONTAMINATION. 01/10/2001: RJJ SITE INSPECTION, DAY ENVIRONMENTAL STARTED TO EXCAVATE CONTAMINATED SOIL, AT TP-10, WHERE THE ANALYTICAL RESULTS WERE ABOVE OUR GUILDANCE VALUES...JOHN BLANCHARD WILL TAKE 4 SIDE AND 1 FLOOR SAMPLES AND ANALYZE FOR TAGM 4046 AND SEND ME THE RESULTS AND THE DISPOSAL RECEIPTS. 02/14/2001: RJJ RECEIVED THE SOIL REMOVAL REPORT FROM STUART SCHEFF...ALL THE ANAYLITICAL RESULTS ARE BELOW OUR TAGM LEVELS, AND ALL THE SOIL DISPOSAL RECEIPTS ARE IN ORDER...I WILL SEND A 'CLOSURE' LETTER TO MR. SCHEFF, NO FURTHER ACTION NEEDED...SPILL CLOSED OUT."
Remarks:	"WHILE DOING A MODIFIED PHASE I SITE ASSESSMENT WHICH INCLUDES SOME SOIL BORINGS, CONTAMINATED SOIL FOUND IN 1 OUT OF 11 BORINGS BASED ON PID AND ANALYTICAL RESULTS."

All Materials:

Site ID:	186488
Operable Unit ID:	838199
Operable Unit:	01
Material ID:	538897
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

P81 **MOBIL OIL 08-D5Y** **NY Spills** **S102403034**
NE **MAIN STREET AT WINSPEAR** **N/A**
< 1/8 **BUFFALO, NY**
0.013 mi.
69 ft. **Site 8 of 10 in cluster P**

Actual:
652 ft.

Focus Map:
8

SPILLS:

Spill Number/Closed Date:	9607732 / 1998-06-29
Facility ID:	9607732
Facility Type:	ER
DER Facility ID:	163579
Site ID:	196518
DEC Region:	9
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	1502
Spill Date:	1996-09-19
Investigator:	PRINGLE
Referred To:	Not reported
Reported to Dept:	1996-09-19
CID:	323
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-09-19
Spill Record Last Update:	1998-07-31
Spiller Name:	MICHAEL LAMARRE
Spiller Company:	MOBIL BUSINESS RESOURCES
Spiller Address:	464 DOUGHTY BLVD
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MNP 09/30/96: MNP TELECON W/ KEVIN CRONIN - GTI. THEY FOUND 1.5 IN. OF OIL IN MW. SAMPLE COLLECTED & OIL BAILED OUT. HE HAS NOT RETURNED TO SITE SINCE. I REQUESTED INITIAL REPORT & SUGGESTED JOINT INSP. NEXT TIME HE GOES TO SITE. LETTER TO SENT TO LAMARRE - MOBIL. 02/24/97: RECEIVED UST REMOVAL REPORT FROM GTI. 02/25/97: MNP REVIEW OF GTI REPORT. A 1K HEATING OIL TANK, 1K WASTE OIL TANK, & HYDRAULIC LIFT WERE REMOVED. NO PETROLEUM CONTAMINATED SOILS FOUND & SAMPLE RESULTS FOR BOTH TANK PITS MEET STAR #1 GUIDANCE VALUES. NO TESTING OF LIFT PIT PERFORMED. OIL STAINED SOIL FOUND IN OLD AUTO SERVICE PIT DURING DEMOLITION, SAMPLE SLIGHTLY EXCEEDED GUIDANCE VALUE FOR BENZO(a)PYRENE AT 43 ug/kg (PPB), SOIL WAS PUT BACK IN PIT. 2 OF OIL PRODUCT WAS DISCOVERED IN MW NEXT TO GARAGE SERVICE BAY. SAMPLE RESULTS OF MW INDICATE VOLATILES EXCEEDING NYSDEC GW STANDARDS WHILE SEMIVOLATILES ARE BELOW STANDARDS. GTI RECOMENDS REDEVELOPMENT & SAMPLING OF THE MW, I CONCUR. 03/11/97: OFFICE MEETING W/ MICHAEL LAMARRE - MOBIL OIL & GTI. 03/ /97: LETTER REQUESTING MOBIL SAMPLE ALL MW'S FOR EPA METHOD 8021 STARS #1 & 1 MW FOR EPA METHOD 8270 ALSO. 04/10/97: RECEIVED 4/8/97 MOBIL LETTER. THEY ONLY AGREED TO SAMPLE 1 MW & CHECK THE OTHER TANK MONITORING WELLS VISUALLY FOR PETROLEUM SHEENS. NO SCHEDULE GIVEN. 07/17/97: MNP FILE REVIEW. NO SCHEDULE OR SAMPLE RESULTS TO DATE. 3/9/98 MOBIL SUBMITTED ANALYTICAL

MOBIL OIL 08-D5Y (Continued) **S102403034**

DATA FROM THE MW ON SITE IN A LTR DATED 3/2/98. RESULTS ARE SLIGHTLY ABOVE GROUNDWATER STANDARDS. THE OTHER WELLS ON SITE WERE CHECKED FOR A SHEEN. NONE WAS FOUND. SITE CAN BE MADE INACTIVE. 6/29/98 INACTIVE LETTER SENT."

Remarks: "POSS TAMPERING OF MONITORING WELL. INVESTIGATION IS CONTINUING AT THIS TIME."

All Materials:

Site ID:	196518
Operable Unit ID:	1038886
Operable Unit:	01
Material ID:	346992
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

P82 **MOBIL** **NY Spills** **S102175955**
NE **MAIN & KENMORE** **N/A**
< 1/8 **BUFFALO, NY**
0.013 mi.
69 ft. **Site 9 of 10 in cluster P**

Actual:
652 ft.

Focus Map:
8

SPILLS:

Spill Number/Closed Date:	8708684 / 1988-01-14
Facility ID:	8708684
Facility Type:	ER
DER Facility ID:	175113
Site ID:	211261
DEC Region:	9
Spill Cause:	Deliberate
Spill Class:	Not reported
SWIS:	1502
Spill Date:	1988-01-12
Investigator:	PRINGLE
Referred To:	Not reported
Reported to Dept:	1988-01-12
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Citizen
Cleanup Ceased:	1988-01-14
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1988-01-12
Spill Record Last Update:	1988-01-26
Spiller Name:	Not reported
Spiller Company:	MOBIL STATION
Spiller Address:	MAIN STREET
Spiller Company:	001

MOBIL (Continued) **S102175955**

Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was MNP / / : MNP NOTIFIED BSA 1/12/88. / / : MNP NOTIFIED BSA 1/12/88; MNP TELECON BSA 01/14/88, NO SPILLAGE FOUND, SPEEDI-DRY FOUND, NO CLEANUP POSSIBLE OR NECESSARY, COMPLETE. "
Remarks: "NOTIFIER OBSERVED STATION ATTENDANT POURING SUSPECTED WASTE OIL INTO SEWER"

All Materials:
Site ID: 211261
Operable Unit ID: 913359
Operable Unit: 01
Material ID: 464058
Material Code: 0022
Material Name: waste oil/used oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 5.00
Units: G
Recovered: .00
Oxygenate: Not reported

83
East
< 1/8
0.014 mi.
73 ft.

SIBLEYS **FINDS** **1007763570**
BLVD MALL 1255 NIAG FLLS BLVD **N/A**
AMHERST, NY 14226

Actual:
586 ft.

Focus Map:
6

FINDS:

Registry ID: 110019259933

Environmental Interest/Information System
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

84
ENE
< 1/8
0.014 mi.
74 ft.

AMHERST POLICE SECURE STORAGE BLDG **FINDS** **1017813324**
350 JOHN JAMES AUDUBON PKWY **N/A**
AMHERST, NY 14228

Actual:
580 ft.

Focus Map:
2

FINDS:

Registry ID: 110064397013

Environmental Interest/Information System
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

AMHERST POLICE SECURE STORAGE BLDG (Continued) **1017813324**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

---

85 **NATIONAL GRID** **NY Spills** **S111318811**
West **1084 NIAGARA FALLS BLVD** **N/A**
< 1/8 **TONAWANDA, NY 14150**
0.014 mi.
76 ft.

Actual:
593 ft.

Focus Map:
6

SPILLS:

Spill Number/Closed Date:	1109965 / 2012-02-02
Facility ID:	1109965
Facility Type:	ER
DER Facility ID:	412232
Site ID:	457756
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	1564
Spill Date:	2011-11-08
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	2011-11-08
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2011-11-08
Spill Record Last Update:	2012-02-02
Spiller Name:	LISA MONTESANO
Spiller Company:	NATIONAL GRID
Spiller Address:	144 KENSINGTON AVENUE
Spiller Company:	999
Contact Name:	LISA MONTESANO
DEC Memo:	"11/17/11:SAC TELECON LISA MONTESANO - NATIONAL GRID. MS. MONTESANO SAID THAT THEY WILL NOT BE REMOVING OR REPLACING TRANSFORMERS, AND WILL REMAIN IN SERVICE. TRANSFORMERS ARE NOT MANUFACTURERS CERTIFIED NON-PCB. THEREFORE, THEY MUST ASSUME THAT THE PRODUCT CONTAINS HAZARDOUS LEVEL OF PCBs AND WILL BE DISPOSED OF ACCORDINGLY. SPILL WAS TO ASPHALT PAVEMENT SO NO CONFIRMATORY SAMPLING IS POSSIBLE. 02/01/12 RMC/FILE. LEFT MESSAGE FOR LISA M REQUESTING A REPORT. DUE 2/29/12 02/02/12 RMC/FILE. RECEIVED DISPOSAL RECEIPTS. CLOSE OUT. "
Remarks:	"Caller advised 4 ounces of oil spilled onto pavement. Clean up is pending."

All Materials:

Site ID:	457756
Operable Unit ID:	1207878
Operable Unit:	01
Material ID:	2205192
Material Code:	0020A

NATIONAL GRID (Continued) **S111318811**

Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

W86 **CORSI AUTO BODY AND GLASS INC.** **US AIRS** **1007803125**
West **874 NIAGARA FALLS BLVD.** **N/A**
< 1/8 **TONAWANDA, NY 14223**
0.015 mi.
78 ft. **Site 1 of 2 in cluster W**

Actual:
597 ft.

Focus Map:
6

US AIRS MINOR:

Envid:	1007803125
Region Code:	02
Programmatic ID:	AIR 020000003602990116
Facility Registry ID:	110019656521
D and B Number:	Not reported
Primary SIC Code:	3711
NAICS Code:	999999
Default Air Classification Code:	MIN
Facility Type of Ownership Code:	POF
Air CMS Category Code:	Not reported
HPV Status:	Not reported

W87 **CORSI AUTO BODY AND GLASS INC.** **FINDS** **1016051303**
West **874 NIAGARA FALLS BLVD** **ECHO** **N/A**
< 1/8 **TONAWANDA, NY 14223**
0.015 mi.
78 ft. **Site 2 of 2 in cluster W**

Actual:
597 ft.

Focus Map:
6

FINDS:

Registry ID: 110019656521

Environmental Interest/Information System
AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

AIR MINOR

CORSI AUTO BODY AND GLASS INC. (Continued) **1016051303**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016051303
Registry ID:	110019656521
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110019656521

N88 **COMMERCIAL SITE** **NY Spills** **S110139573**
ESE **951 NIAGARA FALLS BVLD** **N/A**
< 1/8 **AMHERST, NY**
0.015 mi.
79 ft. **Site 4 of 4 in cluster N**

Actual:
597 ft.

Focus Map:
6

SPILLS:

Spill Number/Closed Date:	0911057 / 2013-09-09
Facility ID:	0911057
Facility Type:	ER
DER Facility ID:	372777
Site ID:	423840
DEC Region:	9
Spill Cause:	Other
Spill Class:	B3
SWIS:	1522
Spill Date:	2010-01-13
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	2010-01-13
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	2011-05-26
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-01-13
Spill Record Last Update:	2013-09-09
Spiller Name:	Not reported
Spiller Company:	240 ASSOCIATES LTD PARTNERSHIP
Spiller Address:	79 CHESTNUT STREET
Spiller Company:	001
Contact Name:	SUSAN YARGER
DEC Memo:	"02/04/10 RMC/FILE. REVIEWED PHASE II REPORT. SOIL CONTAMINATION IN OLD TANK FIEDLS. MINOR GW CONTAMINATION. MUST REMEDIATE THE IMPACTED AREAS. ADVISED TTL. UPDATE 3/30/10. 05/03/10 RMC/SUSAN YARGER/PHONE. STILL WORKING OUT DETAILS OF WHO WILL DO THE WORK IN THE PROPERTY TRANSFER. UPDATE 6/1/10. 05/18/11 RMC/FILE. TALKED WITH SUSAN YARGER, CLIENT DID NOT PURCHASE THE PROPERTY, RMC TO INSPECT. UPDATE 5/30/11 05/26/11 RMC/SITE. ACTIVE RESTAURANT, NO VISUAL PETROLEUM EQUIPMENT 05/27/11 RMC/SAC/MEETING. WENT OVER REPORT. REMEDIATION REQUIRED IN AREA OF OLD PETROLEUM EQUIPMENT, LETTER DRAFTED. REMEDIATION PLAN DUE 7/30/11. 08/01/11 RMC/FILE. RECEIVED PHONE MESSAGE FROM OWNER THAT REMEDIATION WILL BE DONE AND IS BEING PLANNED. UPDATE 8/30/11.

COMMERCIAL SITE (Continued) **S110139573**

04/16/13 RMC/FILE. NOTHING HAS BEEN DONE. LETTER WITH ROE TO PROPERTY OWNER. RESPONSE DUE 5/10/13. 05/06/13 RMC/FILE. RECEIVED LETTER DATED 4/29 FROM THE OWNER. THEY PLAN TO REMEDIATE. RMC SENT EMAIL REQUESTING WORK PLAN AND SCHEDULE. DUE 5/30/13. 06/07/13 RMC/FILE. REVIEWD REMEDIAL PLAN FROM TTL DATED 5/24/13. PLAN ON EXCAVATING OUT IMPACTED SOILS. RMC AGREED TO THE PLAN BUT DID CALL PAUL CHASCO, TTL, 419-324-2222*1147 AND ADVISED THAT RESULTS SHOULD BE COMPARED TO CP51 UNRESTRICTED NUMBERS. THEY HAVE YET TO TAKE DISPOSAL CHARACTERIZATION SAMPLES. UPDATE 7/15/13. 06/17/13 RMC/FILE. EXCAVATION COMPLETED LAST WEEK. RMC INSPECTED SEVERAL TIMES DURING THE WORK. COULD NOT GET TO CLEAN NUISANCE CHARACTERISTICS ON THE WALLS ON NFB OR EGGERT. HOWEVER AS MUCH AS COULD REASONABLE BE WAS REMOVED. UP AGAINST SEWER LINE TO THE NORTH. DUG UP TO AND THEN DID TEST PIT ON THE OTHER SIDE. REPORT DUE 7/30/13. 9/9/13 RMC/FILE. RECEIVED REPORT DATED 8/13. EXCAVATED 408 TONS IMPACTED SOILS. COLLECTED 8 SAMPLES. CP 51 EXCEEDACNES SW8, MINOR, SW14 THAT WAS AGAINST SEWER PIPE WHICH SERVICED SEVERAL DIFFERENT BUILDINGS SHOWS EXCEEDANCES. TEST PIT ON THE OTHER SIDE TO THE NORTH MET CP51. PREVIOUS SAMPLE RESULTS ALONG EGGERT, GP 5 AND GP 6, MET CP51, WATER THAT AREA SHOWED MINOR EXCEEDANCES. RMC CONCLUDES THAT THE SOURCE HAS BEEN REMOVED AND THE SITE CAN BE MADE INACTIVE. LETTER INACTIVE."

Remarks: "Caller reporting elevated sample levels in soil and groundwater.
Caller states clean up pending."

All Materials:

Site ID:	423840
Operable Unit ID:	1179642
Operable Unit:	01
Material ID:	2173412
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

C89 **NY COOLING TOWERS** **S122987445**
ESE **1185 SWEET HOME RD** **N/A**
< 1/8 **AMHERST, NY 14228**
0.015 mi.
80 ft. **Site 2 of 3 in cluster C**

Actual:
597 ft.

Focus Map:
4

COOLING TOWERS:

Equipment Unique ID:	9430
Equipment Borough:	1185
Intended Use:	Air Conditioning
Manufacturer:	BAC
Model:	VXT65CR
Cooling Capacity:	65
Cooling Capacity Unit:	Tonnage
Commissioned Date:	07/01/1986
Inspection Date:	08/17/2018
Date of Bacteriological Collection:	09/14/2018
Date of Legionella Collection:	08/17/2018
Last Legionella Result > 1,000 CFU/mL:	no

(Continued) **S122987445**

Latitude: 42.994718697
Longitude: -78.801833304

C90 **AMHERST MEDICAL CENTER** **FINDS** **1016080619**
ESE **1185 SWEET HOME RD** **N/A**
< 1/8 **AMHERST, NY 14226**
0.015 mi.
80 ft. **Site 3 of 3 in cluster C**

Actual:
597 ft.

FINDS:

Focus Map:
4

Registry ID: 110012159537

Environmental Interest/Information System
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

U91 **AT & T CELL SITE** **NY Spills** **S110751816**
SE **1201 SWEET HOME RD** **N/A**
< 1/8 **AMHERST, NY**
0.015 mi.
81 ft. **Site 3 of 3 in cluster U**

Actual:
599 ft.

SPILLS:

Focus Map:
4

Spill Number/Closed Date:	1010924 / 2011-02-01
Facility ID:	1010924
Facility Type:	ER
DER Facility ID:	399433
Site ID:	444543
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	1522
Spill Date:	2011-01-26
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	2011-01-26
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2011-01-26
Spill Record Last Update:	2011-02-01
Spiller Name:	JAMES CRANMER
Spiller Company:	AT & T

AT & T CELL SITE (Continued) **S110751816**

Spiller Address: 1201 SWEET HOME RD
Spiller Company: 999
Contact Name: JAMES CRANMER
DEC Memo: "02/01/11 RMC/FILE. MINOR SPILL, LESS THAN 1 GALLON, REPORTED AS BEING CLEANED UP. NO SPILL ACTION REQUIRED. CLOSE OUT. NO PAPER FILE. "
Remarks: "small amount less 1 gallon, while service was being performed, generator from exhaust lost a mist onto snow.clean up in progress. Cell phone (214) 949-5211"

All Materials:
Site ID: 444543
Operable Unit ID: 1194988
Operable Unit: 01
Material ID: 2190930
Material Code: 0015
Material Name: motor oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G
Recovered: 1.00
Oxygenate: Not reported

M92 **MOBIL** **NY LTANKS** **S100250643**
East **N.F.BLVD. & SHERIDAN DR.** **N/A**
< 1/8 **TONAWANDA, NY**
0.016 mi.
82 ft. **Site 3 of 3 in cluster M**

Actual:
597 ft.

Focus Map:
6

LTANKS:
Spill Number/Closed Date: 8602251 / 1986-09-05
Facility ID: 8602251
Site ID: 113854
Spill Date: 1986-07-07
Spill Cause: Tank Failure
Spill Source: Gasoline Station or other PBS Facility
Spill Class: Not reported
Cleanup Ceased: 1986-09-05
SWIS: 1564
Investigator: MJHINTON
Referred To: Not reported
Reported to Dept: 1986-07-07
CID: Not reported
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: 1986-08-27
Recommended Penalty: False
Meets Standard: True
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 1986-07-09
Spill Record Last Update: 1986-09-08
Spiller Name: Not reported
Spiller Company: MOBIL STATION
Spiller Address: N.F.BLVD. & SHERIDAN DR.
Spiller County: 001

MOBIL (Continued) **S100250643**

Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	9
DER Facility ID:	99335
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MJH / / : SITE INSP. 7/7/86 BY MJH, PRODUCT IN EXCAVATION,MOBIL TO RETEST ALL TANKS;TELECON 7/8/86, R. WRIGHT AGREED TO PUT IN WELLS & TEST TANKS. / / : TELCON 7/30/86 W/ R. WRIGHT REGULAR TANK FAILED TEST, RECOVERY WELL INSTALLED 7/23/86, TELCON 7/31/86 W/ R. WRIGHT REQUESTED TEST RESULTS. / / : TELCON 7/30/86, R. WRIGHT REGULAR TANK FAILED TEST, RECOVERY WELL INSTALLED 7/23/86; TELCON 7/31/86, R. WRIGHT, REQUESTED TEST RESULTS. / / : 3 GROUND WATER MONITORING WELLS INSTALLED, NO VISABLE PRODUCT IN ANY WELL, APPROX. 1/16 PRODUCT IN STORAGE TANK. / / : NO EVIDENCE OF PRODUCT IN WELLS INVENTORY RECORDS INDICATE NO LOSS, ALL TANKS TEST TIGHT BY PETRO TIGHT METHOD. "
Remarks:	"EXCAVATION TO LINES FOR TANK TEST, PRODUCT FOUND & TEST NOT PERFORMED"

All Materials:

Site ID:	113854
Operable Unit ID:	899682
Operable Unit:	01
Material ID:	552155
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

X93 **CARMELLA TERMULLO AND JOHN ZAPROWSKI** **NY Spills** **S106868548**
East **853-855 NIAGARA FALLS BLVD** **N/A**
< 1/8 **AMHERST, NY 14226**
0.016 mi.
83 ft. **Site 1 of 2 in cluster X**

Actual:
598 ft.

Focus Map:
6

SPILLS:

Spill Number/Closed Date:	0550174 / 2005-10-03
Facility ID:	0550174
Facility Type:	ER
DER Facility ID:	291035
Site ID:	344352
DEC Region:	9
Spill Cause:	Abandoned Drums
Spill Class:	B3
SWIS:	1522
Spill Date:	2005-04-28
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	2005-04-28
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other

CARMELLA TERMULLO AND JOHN ZAPROWSKI (Continued) **S106868548**

Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	2005-09-01
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-04-28
Spill Record Last Update:	2005-10-03
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	Not reported
Contact Name:	BOB KNOER
DEC Memo:	"04/28/05 RMC/FILE. REPORT DUE 5/30/05. 05/31/05 RMC/FILE. REVIEWED REPORT. EXCEEDANCES IN OLD UST FIELD. RMC CONTACTED CHANEL WHITE AND REQUESTED PHASE I. SHE WILL ALSO SEND AND UPDATED MAP AS THERE IS AN ERROR ON THE ONE PROVIDED, UPDATE 6/30/05 06/03/05 RMC/FILE. RECEIVED PHASE I AND COMPLETED PHASE II. REVIEWED PHASE II SHOWED CONTAMINATION ISOLATED TO FORMER UST PIT. RECORDS SHOW TWO TANKS INSTALLED ON THE PROPERTY. CONSULTANTS CAN ONLY ACCOUNT FOR ONE. ONE TANK REPORTED TO HAVE BEEN REMOVED IN 1987. THEY BELIEVE THE SECOND REPORT IS IN ERROR. DISCUSSED WITH SAC. CONF CALL WITH CANEL WHITE, ATTORNEY AND ANDY KUCSERIK PLAN TO DIG OUT CONTAMINATION. WILL CALL TO NOTIFY WHEN, CALL DUE 7/15/05. 08/01/05 RMC/FILE. CALLED CHANEL WHITE, THEY HAVE HIRED NWECC TO DIG OUT, WORK WILL START BY 9/1/05. 08/30/05 RMC/GREG WEBEER/PHONE. PLAN ON STARTING TOMORROW. RMC TO INSPECT 9/1/05. 09/01/05 RMC/TONY, NWECC/SITE. EXCAVATION COMPLETED. SIDEWALLS AND BOTTOM DENSE CLAY. EXCAVATION ABOUT 15 BY 20 BY 7 FEET DEEP. LOCATED AT THE NORTH EAST CORNER OF THE BUILDING. ABOUT A 100 GALLONS OF CONTAMINATED WATER IN THE BOTTOM. PLAN ON PUMPING INTO DRUMS AND THEN SCRAPING THE BOTTOM AGAIN. DISPOSAL AND SAMPLE REPORT DUE 10/15/05. 10/03/05 RMC/FILE. REVIEWED REPORT RECEIVED 9/20/05. 105 TONS IMPACED SOIL REMOVED, FIVE POST EXCAVATION SAMPLES SHOW NO EXCEEDANCES, NO FURTHER ACTION REQUIRED, CLOSE OUT. LETTER. "
Remarks:	"found elevated levels in area where ust was once located, report to follow in 30 days."

All Materials:

Site ID:	344352
Operable Unit ID:	1102994
Operable Unit:	01
Material ID:	583207
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	False

X94 **POLE 851 - REAR PARKING LOT** **NY Spills** **S110489538**
East **853 NIAGARA FALLS BLVD** **N/A**
< 1/8 **AMHERST, NY**
0.016 mi.
83 ft. **Site 2 of 2 in cluster X**

Actual: **598 ft.**

Focus Map: **6**

SPILLS:

Spill Number/Closed Date:	1002149 / 2010-08-23
Facility ID:	1002149
Facility Type:	ER
DER Facility ID:	390156
Site ID:	435255
DEC Region:	9
Spill Cause:	Traffic Accident
Spill Class:	C3
SWIS:	1522
Spill Date:	2010-05-25
Investigator:	RJJONAK
Referred To:	Not reported
Reported to Dept:	2010-05-25
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-05-25
Spill Record Last Update:	2010-08-23
Spiller Name:	Not reported
Spiller Company:	UNK
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	LIS MONTESANO
DEC Memo:	"5/25/2010: RJJ AT SITE AT 1715...A DELIVERY TRUCK CAUGHT SOME CABLES,CAUSING THE UTILITY POLE TO SNAP,CAUSING THE TRANSFORMER TO FALL AND SPILLED 20 GAL OF TRANSFORMER OIL ONTO THE ASHPALT DRIVEWAY...NATIONAL GRID PERSONNEL USED SPEEDI-DRY & ABSORBANTS TO CONTAIN/CLEANED UP THE SPILL... A SMALL AMOUNT OF OIL(<1 GAL) REACHED SOME SOIL,AT THE EDGE OF THE DRIVEWAY,SO NATIONAL GRID WILL ALSO SCRAPE UP THIS AFFECTED SOIL...NONE OF THE OIL REACHED ANY WATERWAYS...LISA MONTESANO,NATIONAL GRID,OBTAINED A SAMPLE OF THE OIL TO BE ANALYZED FOR ANY PCBS...I WILL CHECK ON CLEAN UP TOMORROW. 5/26/2010: RJJ AT SITE AT 1030...NATIONAL GRID CLEANED UP THE SPILL SATISFACTORLY,HOWEVER,THERE IS A STAIN ON THE ASPHALT...IF THE OIL CONTAINS ANY PCBS,THEN NATIONAL GRID WILL RETURN AND REMEDIATE FURTHER...WE WILL WAIT UNTIL THE ANALYTICAL RESULTS COME BACK. 6/1/2010: RECEIVED THE ANALYTICAL RESULTS FROM THE TRANSFORMER OIL...ALL THE PCB RESULTS ARE <50 PPM,SO THE OIL IS NON-HAZARDOUS. 6/4/2010: LISA MONTESANO TELECON RJJ,SHE SAID THAT NATIONAL GRID WILL RE-SEAL THE ASPHALT DRIVEWAY,SINCE THERE IS A LARGE STAIN THERE. 8/23/2010: RECEIVED THE DISPOSAL RECEIPTS,FROM OP-TECH,FOR THE 4 DRUMS OF SPILL MATERIAL TAKEN TO AMERICAN REF-FUEL OF NIAGARA...THE SPILL HAS BEEN CLEANED UP & PROPERLY DISPOSED OF...NO FURTHER ACTION NEEDED...SPILL CLOSED OUT."
Remarks:	"20 gallons of dielectric oil onto black top; clean up crew is en

POLE 851 - REAR PARKING LOT (Continued) **S110489538**

route; not known if PCB; spill contained"

All Materials:

Site ID:	435255
Operable Unit ID:	1186038
Operable Unit:	01
Material ID:	2180805
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	20.00
Oxygenate:	Not reported

Spill Number/Closed Date:	1002149 / 2010-08-23
Facility ID:	1002149
Facility Type:	ER
DER Facility ID:	390156
Site ID:	435255
DEC Region:	9
Spill Cause:	Traffic Accident
Spill Class:	C3
SWIS:	1522
Spill Date:	2010-05-25
Investigator:	RJJONAK
Referred To:	Not reported
Reported to Dept:	2010-05-25
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-05-25
Spill Record Last Update:	2010-08-23
Spiller Name:	LISA MONTESANO
Spiller Company:	NATIONAL GRID
Spiller Address:	144 KENSINGTON AVENUE
Spiller Company:	999
Contact Name:	LIS MONTESANO
DEC Memo:	"5/25/2010: RJJ AT SITE AT 1715...A DELIVERY TRUCK CAUGHT SOME CABLES,CAUSING THE UTILITY POLE TO SNAP,CAUSING THE TRANSFORMER TO FALL AND SPILLED 20 GAL OF TRANSFORMER OIL ONTO THE ASHPALT DRIVEWAY...NATIONAL GRID PERSONNEL USED SPEEDI-DRY & ABSORBANTS TO CONTAIN/CLEANED UP THE SPILL... A SMALL AMOUNT OF OIL(<1 GAL) REACHED SOME SOIL,AT THE EDGE OF THE DRIVEWAY,SO NATIONAL GRID WILL ALSO SCRAPE UP THIS AFFECTED SOIL...NONE OF THE OIL REACHED ANY WATERWAYS...LISA MONTESANO,NATIONAL GRID,OBTAINED A SAMPLE OF THE OIL TO BE ANALYZED FOR ANY PCBS...I WILL CHECK ON CLEAN UP TOMORROW. 5/26/2010: RJJ AT SITE AT 1030...NATIONAL GRID CLEANED UP THE SPILL SATISFACTORLY,HOWEVER,THERE IS A STAIN ON THE ASPHALT...IF THE OIL

POLE 851 - REAR PARKING LOT (Continued) **S110489538**

CONTAINS ANY PCBS,THEN NATIONAL GRID WILL RETURN AND REMEDIATE FURTHER...WE WILL WAIT UNTIL THE ANALYTICAL RESULTS COME BACK.
6/1/2010: RECEIVED THE ANALYTICAL RESULTS FROM THE TRANSFORMER OIL...ALL THE PCB RESULTS ARE <50 PPM,SO THE OIL IS NON-HAZARDOUS.
6/4/2010: LISA MONTESANO TELECON RJJ,SHE SAID THAT NATIONAL GRID WILL RE-SEAL THE ASPHALT DRIVEWAY,SINCE THERE IS A LARGE STAIN THERE.
8/23/2010: RECEIVED THE DISPOSAL RECEIPTS,FROM OP-TECH,FOR THE 4 DRUMS OF SPILL MATERIAL TAKEN TO AMERICAN REF-FUEL OF NIAGARA...THE SPILL HAS BEEN CLEANED UP & PROPERLY DISPOSED OF...NO FURTHER ACTION NEEDED...SPILL CLOSED OUT."

Remarks: "20 gallons of dielectric oil onto black top; clean up crew is en route; not known if PCB; spill contained"

All Materials:

Site ID:	435255
Operable Unit ID:	1186038
Operable Unit:	01
Material ID:	2180805
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	20.00
Oxygenate:	Not reported

O95 **SPEEDY AUTO SERVICE BY MONRO #457** **NY AST** **U003400093**
West **934 NIAGARA FALLS BLVD.** **N/A**
< 1/8 **BUFFALO, NY 14223**
0.016 mi.
83 ft. **Site 2 of 2 in cluster O**

Actual:
598 ft.

Focus Map:
6

AST:

Region:	STATE
DEC Region:	9
Site Status:	Unregulated/Closed
Facility Id:	9-600411
Program Type:	PBS
UTM X:	188260.50662
UTM Y:	4765650.23257
Expiration Date:	N/A
Site Type:	Other

Affiliation Records:

Site Id:	55259
Affiliation Type:	Facility Owner
Company Name:	MONRO MUFFLER BRAKE, INC.
Contact Type:	DIRECTOR OF FACILITIES
Contact Name:	THOMAS M. GIANNONE
Address1:	200 HOLLEDER PKWY
Address2:	Not reported
City:	ROCHESTER
State:	NY
Zip Code:	14615-3808
Country Code:	001
Phone:	(585) 647-6400
EMail:	Not reported

SPEEDY AUTO SERVICE BY MONRO #457 (Continued) **U003400093**

Fax Number:	Not reported
Modified By:	LDGOMEZ
Date Last Modified:	2008-06-24

Site Id:	55259
Affiliation Type:	Mail Contact
Company Name:	MONRO MUFFLER BRAKE, INC.
Contact Type:	DIRECTOR OF FACILITIES
Contact Name:	THOMAS M. GIANNONE
Address1:	200 HOLLEDER PKWY.
Address2:	Not reported
City:	ROCHESTER
State:	NY
Zip Code:	14615-3808
Country Code:	001
Phone:	(585) 647-6400
EMail:	Not reported
Fax Number:	Not reported
Modified By:	aeskalsk
Date Last Modified:	2013-07-26

Site Id:	55259
Affiliation Type:	Facility Operator
Company Name:	SPEEDY AUTO SERVICE BY MONRO
Contact Type:	Not reported
Contact Name:	MONRO MUFFLER BRAKE, INC.
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 953-5001
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	55259
Affiliation Type:	Emergency Contact
Company Name:	MONRO MUFFLER BRAKE, INC.
Contact Type:	Not reported
Contact Name:	THOMAS M. GIANNONE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(585) 647-6400
EMail:	Not reported
Fax Number:	Not reported
Modified By:	aeskalsk
Date Last Modified:	2013-07-26

Tank Info:

SPEEDY AUTO SERVICE BY MONRO #457 (Continued) **U003400093**

Tank Number:	1
Tank Id:	173258
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

L09 - Piping Leak Detection - Exempt Suction Piping
K00 - Spill Prevention - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I01 - Overfill - Float Vent Valve
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
G04 - Tank Secondary Containment - Double-Walled (Underground)
D00 - Pipe Type - No Piping

Tank Location:	2
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	10/01/1998
Capacity Gallons:	240
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	05/22/2008
Register:	True
Modified By:	aeskalsk
Last Modified:	04/14/2017
Material Name:	waste oil/used oil

R96 **ECONOMY CLEANERS** **EDR Hist Cleaner** **1019979944**
East **845 NIAGARA FALLS BLVD** **N/A**
< 1/8 **BUFFALO, NY 14226**
0.016 mi.
84 ft. **Site 4 of 7 in cluster R**

Actual: EDR Hist Cleaner
598 ft.

Focus Map: **6**

Year:	Name:	Type:
1980	ECONOMY CLEANERS	Drycleaning Plants, Except Rugs
1982	ECONOMY CLEANERS	Drycleaning Plants, Except Rugs
1983	ECONOMY CLEANERS	Drycleaning Plants, Except Rugs
1985	ECONOMY CLEANERS	Drycleaning Plants, Except Rugs

Y97 **PEP BOYS #193** **NY AST** **1000890415**
East **1025 NIAGARA FALLS BOULEVARD** **N/A**
< 1/8 **AMHERST, NY 14226**
0.016 mi.
85 ft. **Site 1 of 3 in cluster Y**

Actual:
595 ft.

Focus Map:
6

AST:

Region:	STATE
DEC Region:	9
Site Status:	Active
Facility Id:	9-600354
Program Type:	PBS
UTM X:	188301.88305
UTM Y:	4765858.91972
Expiration Date:	10/21/2022
Site Type:	Other Wholesale/Retail Sales

Affiliation Records:

Site Id:	55204
Affiliation Type:	Facility Owner
Company Name:	THE PEP BOYS - MANNY, MOE AND JACK
Contact Type:	DIRECTOR-ENVIRONMENTAL & DOT HAZMAT COMPLIANCE
Contact Name:	ANGELA BANKS
Address1:	3111 WEST ALLEGHENY AVENUE
Address2:	Not reported
City:	PHILADELPHIA
State:	PA
Zip Code:	19132
Country Code:	001
Phone:	(215) 227-9277
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TJWALKER
Date Last Modified:	2015-06-24

Site Id:	55204
Affiliation Type:	Mail Contact
Company Name:	THE PEP BOYS - MANNY, MOE AND JACK
Contact Type:	Not reported
Contact Name:	ANGELA BANKS, ENV. DEPT
Address1:	3111 WEST ALLEGHENY AVENUE
Address2:	Not reported
City:	PHILADELPHIA
State:	PA
Zip Code:	19132
Country Code:	001
Phone:	(215) 430-9645
EMail:	ANGELA-BANKS@PEPBOYS.COM
Fax Number:	Not reported
Modified By:	TJWALKER
Date Last Modified:	2015-06-24

Site Id:	55204
Affiliation Type:	Facility Operator
Company Name:	PEP BOYS #193
Contact Type:	Not reported
Contact Name:	PEP BOYS
Address1:	Not reported
Address2:	Not reported
City:	Not reported

PEP BOYS #193 (Continued) **1000890415**

State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(716) 831-0370
EMail:	Not reported
Fax Number:	Not reported
Modified By:	SLZIEMBA
Date Last Modified:	2012-10-12

Site Id:	55204
Affiliation Type:	Emergency Contact
Company Name:	THE PEP BOYS - MANNY, MOE AND JACK
Contact Type:	Not reported
Contact Name:	ANGELA BANKS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(215) 212-9645
EMail:	Not reported
Fax Number:	Not reported
Modified By:	SLZIEMBA
Date Last Modified:	2012-10-12

Tank Info:

Tank Number:	1
Tank Id:	172842
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

G12 - Tank Secondary Containment - Double-Walled (AG only)
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H02 - Tank Leak Detection - Interstitial - Manual Monitoring
E00 - Piping Secondary Containment - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
J00 - Dispenser - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
L00 - Piping Leak Detection - None

Tank Location:	2
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	08/01/1994
Capacity Gallons:	500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported

PEP BOYS #193 (Continued) **1000890415**

Register:	True
Modified By:	TJWALKER
Last Modified:	04/14/2017
Material Name:	waste oil/used oil

Y98 **PEP BOYS - MANNY MOE & JACK THE #193** **RCRA NonGen / NLR** **1004755767**
East **1025 NIAGARA FALLS BLVD** **FINDS** **NY0000362657**
< 1/8 **AMHERST, NY 14226** **ECHO**
0.016 mi. **NY MANIFEST**
85 ft. **Site 2 of 3 in cluster Y**

Actual:
595 ft.

Focus Map:
6

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	PEP BOYS - MANNY MOE & JACK THE #193
Facility address:	1025 NIAGARA FALLS BLVD AMHERST, NY 14226
EPA ID:	NY0000362657
Mailing address:	W ALLEGHENY AVE PHILADELPHIA, NY 19132
Contact:	MARYROSE PETRIZZO
Contact address:	W ALLEGHENY AVE PHILADELPHIA, NY 19132
Contact country:	US
Contact telephone:	215-227-9277
Contact email:	Not reported
EPA Region:	02
Land type:	Private
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	THE PEP BOYS - MANNY MOE & JACK
Owner/operator address:	3111 W ALLEGHENY AVE PHILADEPHIA, PA 19132
Owner/operator country:	US
Owner/operator telephone:	215-227-9277
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	THE PEP BOYS - MANNY MOE & JACK
Owner/operator address:	3111 W ALLEGHENY AVE PHILADEPHIA, PA 19132
Owner/operator country:	US
Owner/operator telephone:	215-227-9277
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

PEP BOYS - MANNY MOE & JACK THE #193 (Continued) **1004755767**

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: PEP BOYS - MANNY MOE & JACK THE #193
Classification: Not a generator, verified

Date form received by agency: 06/07/1994
Site name: PEP BOYS - MANNY MOE & JACK THE #193
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D018
. Waste name: BENZENE

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 11/16/2012
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110004316124

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA

PEP BOYS - MANNY MOE & JACK THE #193 (Continued) **1004755767**

program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004755767
Registry ID:	110004316124
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004316124

NY MANIFEST:

Country:	USA
EPA ID:	NY0000362657
Facility Status:	Not reported
Location Address 1:	1025 NIAGARA FALLS BLVD
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	AMHERST
Location State:	NY
Location Zip:	14226
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NY0000362657
Mailing Name:	PEP BOYS - MANNY MOE & JACK THE #193
Mailing Contact:	PEP BOYS - MANNY MOE & JACK THE #193
Mailing Address 1:	1025 NIAGARA FALLS BLVD
Mailing Address 2:	Not reported
Mailing City:	AMHERST
Mailing State:	NY
Mailing Zip:	14226
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	MNS000110924
Trans2 State ID:	Not reported
Generator Ship Date:	06/28/2018
Trans1 Recv Date:	06/28/2018
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/02/2018
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000362657
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	MID980615298
TSDF ID 2:	Not reported

PEP BOYS - MANNY MOE & JACK THE #193 (Continued) **1004755767**

Manifest Tracking Number:	011300318FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	5
Units:	P - Pounds
Number of Containers:	1
Container Type:	BA - Burlap, plastic, paper bags
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	D001
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
5 additional NY MANIFEST: record(s) in the EDR Site Report.

Y99 **PEP BOYS #0193** **NY CBS S104651400**
East **1025 NIAGARA FALLS BOULEVARD** **NY Spills N/A**
< 1/8 **AMHERST, NY 14226**
0.016 mi.
85 ft. **Site 3 of 3 in cluster Y**

Actual:
595 ft.

Focus Map:
6

CBS:

CBS Number:	9-000436
Program Type:	CBS
Facility Status:	Unregulated/Closed
Expiration Date:	Not reported
Dec Region:	9
UTMX:	188323.63329
UTMY:	4765905.02468

SPILLS:

Spill Number/Closed Date:	9912271 / 2000-05-02
Facility ID:	9912271
Facility Type:	ER
DER Facility ID:	176955
Site ID:	213584
DEC Region:	9

PEP BOYS #0193 (Continued) **S104651400**

Spill Cause:	Unknown
Spill Class:	C4
SWIS:	1522
Spill Date:	2000-01-25
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	2000-01-25
CID:	388
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-01-25
Spill Record Last Update:	2002-03-25
Spiller Name:	JOHN C. KERELO
Spiller Company:	PEP BOYS
Spiller Address:	3111 WEST ALLEGHENY AVE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 01/26/00: RMC TELECON FROM GREG WEBER OF NATURE'S WAY, THEY REMOVED A 550 GALLON WASTE OIL TANK ALONG WITH IMPACTED SOILS, SAMPLES WILL BE TAKEN, REPORT DUE 3/15/00 01/26/00: RMC TELECON FROM TONY K. OF NATURE'S WAY, HE HAS COMPLETED REMOVAL OF IMPACTED SOILS, THREE LOADS FOR DISPOSAL, TWO SAMPLES TAKEN, REPORT DUE 3/15/00 04/10/00: RMC TELECON TO NATURE'S WAY, LEFT MESSAGE THAT NO REPORT RECEIVED, DUE 5/5/00 05/02/00: RMC RECEIVED 2 INCH REPORT FOR ONE 550 GALLON WASTE OIL TANK, LOOKED AT ANALYTICAL RESULTS AND DISPOSAL DOCUMENTS ONLY, NO EXCEEDANCES IN RESULTS, DISPOSAL DOCUMENTED FOR 52 TONS CONTAMINATED SOIL, NO FURTHER ACTION REQUIRED, CLOSE OUT"
Remarks:	"CALLER REPORTS RESIDUALS FROM TANK REMOVAL FOUND AROUND AREA OF TANK."

All Materials:

Site ID:	213584
Operable Unit ID:	1086805
Operable Unit:	01
Material ID:	294160
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

L100 **LATONAS SERVICE** **EDR Hist Auto** **1020179066**
East **989 NIAGARA FLS BD** **N/A**
< 1/8 **BUFFALO, NY 14226**
0.016 mi.
87 ft. **Site 3 of 6 in cluster L**

Actual: EDR Hist Auto
597 ft.

Focus Map: Year: Name: Type:
6 1971 LATONAS SERVICE Gasoline Service Stations
1972 LATONAS SERVICE Gasoline Service Stations
1973 LATONAS SERVICE Gasoline Service Stations
1974 LATONAS SERVICE Gasoline Service Stations

Z101 **NYSDOT PROJECT/U-HAUL** **NY Spills** **S103572273**
East **925 NIAGARA FALLS BLVD** **N/A**
< 1/8 **AMHERST, NY**
0.017 mi.
88 ft. **Site 1 of 3 in cluster Z**

Actual: SPILLS:
597 ft.

Focus Map:
6

Spill Number/Closed Date:	9803568 / 1999-11-26
Facility ID:	9803568
Facility Type:	ER
DER Facility ID:	127014
Site ID:	149280
DEC Region:	9
Spill Cause:	Other
Spill Class:	C3
SWIS:	1522
Spill Date:	1998-06-01
Investigator:	FXGALLEG
Referred To:	Not reported
Reported to Dept:	1998-06-01
CID:	999
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-06-19
Spill Record Last Update:	1999-11-29
Spiller Name:	REID RINER
Spiller Company:	AMERCO REAL ESTATE/NYSDOT
Spiller Address:	PO BOX 29046
Spiller Company:	001
Contact Name:	PHOEBE GROW
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was FG 06/22/98: JDC SITE INSPECTION, FOUND EXCAVATION CLOSED AND RESURFACED WITH BLACKTOP. ACCORDING TO MR CARONE, NYSDOT, NO FREE PRODCUT WAS AT THE TOP OF THE TANK. TANK IS OUT FOR BID ON REMOVAL. EXPECT WORK TO BEGIN NEXT MONTH. 07/17/98: JDC SITE INSPECTION, FOUND NO NEW ACTIVITY. WILL FOLLOWUP ON PROPERTY OWNERSHIP. 07/27/98: JDC TELECON WITH EXECUTIVE DIRECTIVE OF U-HAUL, PHOEBE GROW, ADVISED HER OF THE TANK DISCOVERY. SHE STATED THAT HER PARENT COMPANY AMERCO REAL ESTATE, PO BOX 29046, PHONIX, AZ 85038, WHO BE THE CONTACT. MR REID

NYSDOT PROJECT/U-HAUL (Continued) **S103572273**

RINER, DEPT OF FUELS AND ENVIRONMENT AT 800-528-0463. JDC WILL SEND LETTER TO HIS ATTENTION REGARDING FURTHER SITE INVESTIGATION. 09/10/98: JDC REVIEWED SOIL TEST DATA DATED 2/25/98 FOR VOLITILES AND SEMI-VOLATILES THAT SHOWED NO VIOLATIONS. WILL WAIT UNTIL TANK IS REMOVED FROM ROADWAY BEFORE MAKING FINAL DETERMINATION. 10/20/98: JDC TELECON LINDA, SHE STATED THAT THE TANK WAS REMOVED AND EIGHT DRUMS OF TANK CLEANINGS WERE GENERATED. DISPOSAL WILL BE MADE AS NON-HAZARDOUS. NO CONTAMINATED SOILS WERE DETECTED DURING TANK REMOVAL. 10/01/99: FG ASSUMED SITE RESPONSIBILITY AS JDC NO LONGER WORKS FOR DEPARTMENT 11/26/99: DUPLICATE SPILL 9975504 GENERATED ON THIS SITE CLOSED. 11/26/99: FG RECEIVED EXCAVATION SAMPLE RESULTS, ALL BELOW STARS. DISPOSAL RECEIPTS RECEIVED. SITE CAN BE CLOSED. NO FURTHER WORK REQUIRED. "

Remarks: "NYSDOT FOUND TANK ON THEIR ROW DURING CONSTRUCTION PROJECT (257531) SOUTH EAST CORNER OF EGGERT AND SHERIDAN. NYSDOT WILL ARRANGE REMOVAL"
Not reported

All Materials:

Site ID:	149280
Operable Unit ID:	1061396
Operable Unit:	01
Material ID:	321890
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Z102 **BOULEVARD U-HAUL CENTER** **NY UST** **U003316406**
East **925 NIAGARA FALLS BOULEVARD** **N/A**
< 1/8 **AMHERST, NY 14226**
0.017 mi.
88 ft. **Site 2 of 3 in cluster Z**

Actual:
597 ft.

Focus Map:
6

UST:

Id/Status:	9-022136 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	9
Expiration Date:	N/A
UTM X:	188317.69081
UTM Y:	4765590.37601
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	52065
Affiliation Type:	Facility Owner
Company Name:	U-HAUL CO OF WESTERN NEW YORK
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	6161 TRANSIT ROAD
Address2:	Not reported
City:	DEPEW
State:	NY
Zip Code:	14043

BOULEVARD U-HAUL CENTER (Continued) **U003316406**

Country Code:	001
Phone:	(716) 681-5166
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	52065
Affiliation Type:	Mail Contact
Company Name:	U-HAUL CO OF WESTERN NEW YORK
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	6161 TRANSIT ROAD
Address2:	Not reported
City:	DEPEW
State:	NY
Zip Code:	14043
Country Code:	001
Phone:	(716) 681-5166
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	52065
Affiliation Type:	Facility Operator
Company Name:	BOULEVARD U-HAUL CENTER
Contact Type:	Not reported
Contact Name:	U-HAUL CO OF WESTERN NEW YORK
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(716) 832-1778
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	52065
Affiliation Type:	Emergency Contact
Company Name:	U-HAUL CO OF WESTERN NEW YORK
Contact Type:	Not reported
Contact Name:	JOHN BORATKO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(716) 681-5166
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

BOULEVARD U-HAUL CENTER (Continued) **U003316406**

Tank Info:

Tank Number:	1
Tank ID:	160581
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	8000
Install Date:	01/01/1971
Date Tank Closed:	02/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number:	2
Tank ID:	160582
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	6000
Install Date:	04/01/1983
Date Tank Closed:	02/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
H03 - Tank Leak Detection - Vapor Well
G00 - Tank Secondary Containment - None

BOULEVARD U-HAUL CENTER (Continued) **U003316406**

J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
I00 - Overfill - None

Tank Number:	3
Tank ID:	160583
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	1000
Install Date:	01/01/1971
Date Tank Closed:	02/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

I00 - Overfill - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
H03 - Tank Leak Detection - Vapor Well
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser

Tank Number:	5
Tank ID:	160584
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	02/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT

BOULEVARD U-HAUL CENTER (Continued) **U003316406**

Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Z103 **JOHNS SUPER SHELL SERVICE** **EDR Hist Auto** **1021510893**
East **925 NIAGARA FLS BD** **N/A**
< 1/8 **BUFFALO, NY 14226**
0.017 mi.
88 ft. **Site 3 of 3 in cluster Z**

Actual: EDR Hist Auto
597 ft.

Focus Map:
6

Year:	Name:	Type:
1970	JOHNS SUPER SHELL SERVICE	Gasoline Service Stations
1971	JOHNS SUPER SHELL SERVICE	Gasoline Service Stations
1972	JOHNS SUPER SHELL SERVICE	Gasoline Service Stations
1973	JOHNS SUPER SHELL SERVICE	Gasoline Service Stations
1974	JOHNS SUPER SHELL SERVICE	Gasoline Service Stations
1975	JOHNS SUPER SHELL SERVICE	Gasoline Service Stations
1976	JOHNS SUPER SHELL SERVICE	Gasoline Service Stations
1977	HERON AUTO SERVICE INC	Gasoline Service Stations
1978	HERON AUTO SERVICE INC	Gasoline Service Stations
1979	HERON AUTO SERVICE INC	Gasoline Service Stations
1980	HERON AUTO SERVICE INC	Gasoline Service Stations
1982	HERON AUTO SERVICE INC	Gasoline Service Stations
1983	HERON AUTO SERVICE INC	Gasoline Service Stations
1985	HERON AUTO SERVICE INC	Gasoline Service Stations

R104 **FORMER UNI-MART** **NY Spills** **S102963803**
West **820 NIAGARA FALLS BLVD.** **N/A**
< 1/8 **TONAWANDA, NY 14223**
0.018 mi.
94 ft. **Site 5 of 7 in cluster R**

Actual: SPILLS:
599 ft.

Focus Map:
6

Spill Number/Closed Date:	1003350 / 2010-06-28
Facility ID:	1003350
Facility Type:	ER
DER Facility ID:	391505
Site ID:	436572
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	1564
Spill Date:	2010-06-25
Investigator:	RJJONAK
Referred To:	Not reported
Reported to Dept:	2010-06-25

FORMER UNI-MART (Continued) **S102963803**

CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2010-06-25
Spill Record Last Update:	2010-06-28
Spiller Name:	MIKE YOUNT
Spiller Company:	NOCO ENERGY
Spiller Address:	700 GRAND ISLAND BOULEVARD
Spiller Company:	999
Contact Name:	MIKE YOUNT
DEC Memo:	"6/28/2010: RJJ TELECON MIKE YOUNT,NOCO ENERGY,HE SAID THAT THERE WAS A DRIP IN DISPENSER #2 ON THE METER WHICH CAUSED ~2 GAL OF GASOLINE TO LEAKED OUT,ALL UNDER THE DISPENSER,WHICH DOES NOT HAVE A DISPENSER SUMP...NOCO PERSONNEL SCRAPED UP AS MUCH OF THE AFFECTED SOIL/STONE AS THEY COULD,THEN SPRAYED A BIO-REMEDIATION AGENT UNDER THE DISPENSER...THEY DISPOSED THE SMALL AMOUNT OF SOIL IN THEIR DUMPSTER...THE SPILL HAS BEEN CONTAINED AND THE AFFECTED SOIL HAS BEEN PROPERLY DISPOSED OF...NO FURTHER ACTION NEEDED...SPILL CLOSED OUT. ***** NOTE,COMPUTER FILE ONLY *****"
Remarks:	"LEAK IN THE UNION AT THE METER INSIDE THE DISPENSER, CAUSED SMALL AMOUNT TO DRIP. THERE ARE NO DISPENSER SUMPS AT THIS LOCATION. MR. YOUNT SAID THEY APPLIED SIMPLE GREEN TO THE AFFECTED AREA."

All Materials:

Site ID:	436572
Operable Unit ID:	1187265
Operable Unit:	01
Material ID:	2182143
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	2.00
Oxygenate:	Not reported

Spill Number/Closed Date:	9710897 / 1999-04-19
Facility ID:	9710897
Facility Type:	ER
DER Facility ID:	99758
Site ID:	114383
DEC Region:	9
Spill Cause:	Human Error
Spill Class:	D3
SWIS:	1516
Spill Date:	1997-12-27
Investigator:	SORGI
Referred To:	Not reported
Reported to Dept:	1997-12-27

FORMER UNI-MART (Continued) **S102963803**

CID:	282
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	1997-12-28
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-12-27
Spill Record Last Update:	1999-05-06
Spiller Name:	ALLEN MORITZ
Spiller Company:	UNIMART GAS STATION
Spiller Address:	820 NIAGARA FALLS BLVD
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MJS 04/19/99: MJS REOPENED FILE, NOTES LOST DUE TO COMPUTER PROBLEM. HARD COPY CANNOT BE LOCATED IN ACHIVES. FROM RECOLLECTION: MJS INSPECTED SITE WITHIN A DAY AFTER RECEIVING COMPLAINT. STAIN ON BLACKTOP. CLEANUP SATISFACTORY. NO FURTHER ACTION NEEDED. MJS RECLOSE FILE."
Remarks:	"driver pulled away with the nozzle still in the car.kemilworth fd responded and put down speedy dry. "

All Materials:

Site ID:	114383
Operable Unit ID:	1057267
Operable Unit:	01
Material ID:	329168
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	10.00
Oxygenate:	Not reported

Spill Number/Closed Date:	9712476 / 2015-01-30
Facility ID:	9712476
Facility Type:	ER
DER Facility ID:	268331
Site ID:	114384
DEC Region:	9
Spill Cause:	Other
Spill Class:	C3
SWIS:	1564
Spill Date:	1998-02-01
Investigator:	RJJONAK
Referred To:	Not reported
Reported to Dept:	1998-02-09
CID:	999
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Local Agency

FORMER UNI-MART (Continued) **S102963803**

Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	2002-06-27
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-02-09
Spill Record Last Update:	2015-01-30
Spiller Name:	CHUCK BOWER
Spiller Company:	UNI-MART INC
Spiller Address:	477 EAST BEAVER AVE
Spiller Company:	001
Contact Name:	FRANK JORDAN
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RJJ 02/09/98: MJS SITE INSPECT. MET WITH JOHN PUZAN(NYS-DOT) AND BERNIE DIPIZIO(CONTRACTOR). TRENCHING FOR WATER LINE IN FRONT OF GAS STATION AND FOUND CONTAMINATED SOIL. SOIL STOCKPILED ON PLASTIC. DOT WILL SAMPLE AND DISPOSE. TRENCH NOW BACKFILLED. 09/29/98: MJS TELECON TO JOHN PUZAN. HE STATED SOIL DISPOSED. ADVISED HIM TO FORWARD DOCUMENTATION. 12/28/98 RMC/SCOTT OVERHOFF,EPS/PHONE BORINGS WERE DONE RESULTS SHOW CONTAMINATION, REPORT TO FOLLOW 12/30/98: RECEIVED REPORT FROM EPS INC. SIGNIFICANT CONTAMINATION FOUND BETWEEN PUMP ISLAND AND SIDEWALK. 04/01/99: RECEIVED REMEDIATION PROPOSAL FROM SCOTT OVERHOFF AT EPS. THEY PROPOSE INSTALLATION OF FOUR EXTRACTION WELLS IN AREA OF CONTAMINATION FOR VACUUM ENHANCED TOTAL FLUID EXTRACTION WITH MOBILE TRAILER UNIT WATER TO BE DRAWN INTO A 10 GPM AIR STRIPPER AND POLISHED WITH CARBON. 04/23/99: MJS TELECON WITH SCOTT OVERHOFF AND VERBALLY APPROVED PROPOSAL. HE WILL NOTIFY WHEN WORK STARTS. 09/09/1999: MJS REVIEW FILE. UNKNOWN WHETHER REMEDIATION PLAN IMPLEMENTED AT THIS POINT. MJS TELECON WITH CARL CROSSEN. HE WILL HAVE SCOTT OVERHOFF GET BACK TO ME. MJS TELECON FROM MR OVERHOFF. HE STATED REMEDIAL PLAN NEVER IMPLEMENTED. ENV MANAGER AT UNI-MART IS NOW DIFFERTENT(CHUCK BOWER) AND HE IS NOW PROPOSING TO PERFORM A MAGNETOMETER SURVEY PRIOR TO ANY WORK BECAUSE TANKS WERE FOUND ON TWO OTHER SPILL SITES. MJS ASKED FOR LETTER REGARDING THEIR INTENTIONS. 12/27/00 RMC/FILE. RECEIVED AS MJS LEFT THE DEPT, REVIEWED, SITE REQUIRES REMEDIATION, PLAN SUBMITTED IN 3/99, HOWEVER NOT INSTALLED, LETTER, RESPONSE DUE 1/31/01 03/14/01 RMC/WILDER/PHONE. WILL RESPOND WITH LETTER BY 3/30/01 03/29/01 RMC/MARK WILDER/PHONE. PROPOSAL INTO RP, WILL RESPOND BY 4/15/01 04/27/01 RMC/FILE. RECEIVED PLAN TO INSTALL ADDITIONAL MONITORING POINTS, WORK SCHEDULED THIS MONTH, REPORT DUE 5/30/01 09/13/01 RMC/FILE. RECEIVED SOIL AND GROUND WATER REPORT. SIGNIFICANT EXCEEDANCES IN SOIL AND GROUND WATER AROUND THE PUMP ISLAND AREA, LEFT MESSAGE FOR MR BOWER ADVISING THE REMEDIATION IS REQUIRED, UPDATE 9/30/01 11/27/01 RMC/FILE. RECEIVED REPORT. RP HAD ADDITIONAL WATER AND A HIGH VAC. PILOT TEST DONE. REMEDIATION IS REQUIRED IN THE ISLAND AREA. RMC CONTACTED CHUCK BOWER AND ADVISED THAT THE SITE WOULD BE TRANSITIONED TO ANOTHER DEC AGENT,(RJJ). 1/30/2002: PAT MULCHAHY,C&W,TELECON RJJ,SAID THAT HE WILL SEND ME THEIR REPORT AND WORK PLAN FOR THE ADDITIONAL REMEDIATION IN THE PUMP ISLAND AREA. 2/28/2002: RECEIVED THE NOV. AND DEC. 2001 RECOVERY WELL EVACUATION GROUNDWATER ANALYSIS SUMMARY REPORT FROM C&W...MTBE WAS DETECTED IN PZ-1 AT 67,300 PPB,AND BETX WAS MOST PREVALENT IN WATER FROM WELLS MW-3/4,RANGING FROM 9-71,693 PPB...C&W IS RECOMMENDING THAT THEY PERFORM AN ELECTROMAGNETIC GEOPHYSICAL SURVEY TO LOCATE POTENTIAL UST'S,AND PERFORM QUARTELY SAMPLING OF THE ON-SITE WELLS AND COLLECT

FORMER UNI-MART (Continued) **S102963803**

GROUNDWATER LEVEL DATA...I WILL DISCUSS THIS WITH PAT MULCAHY,C&W. 5/22/2002: RECEIVED THE MARCH 2002 RECOVERY WELL EVACUTION & GROUNDWATER ANALYSIS SUMMARY REPORT FROM C&W...12 MONITORING WELLS SAMPLED RANGING FROM 7.98 PPB TO 39,300 PPB MTBE,AND 11 WELLS EXCEEDED OUR TAGA 4046 GROUNDWATER LEVELS...C&W RECOMMENDS: PERFORMING AN ELECTROMAGNETIC GEOPHYSICAL SURVEY TO LOCATE ANY UST'S, AND TO CONTINUE TO PERFORM QUARTERLY SAMPLING OF THE ON-SITE WELLS AND COLLECT GROUNDWATER LEVEL DATA TO OBSERVE CHANGES IN WATER LEVELS,FLOW DIRECTION AND WATER QUALITY OVER TIME. 6/20/2002: RECEIVED A LETTER FROM C&W STATING THAT THEY WILL PERFORM AN ELECTROMAGNETIC SURVEY ON THE PROPERTY ON 6/27. 6/27/2002: RJJ AT SITE AT 1100...C&W HAS STARTED THEIR ELECTROMAGNECTIC GEOPHYSICAL SURVEY TO DETERMINE IF ANY UNKNOWN UST'S ARE PRESENT. 10/1/2002: RECEIVED THE RECOVERY WELL EVACUATION & GROUNDWATER ANALSIS SUMMARY REPORT FROM C&W (JUNE 2002)...IT INDICATES THAT MTBE WAS DETECTED IN THE WELLS RANGING FROM 2-116,320 PPB...BETX WAS DETECTED IN WELLS OW-1.MW/RW-3&4,AND PZ-1...C&W WILL CONTINUE TO PERFORM QUARTERLY SAMPLING OF THE ON-SITE WELLS AND COLLECT GROUNDWATER DATA...THEY WILL ALSO SEND ME THE GEOPHYSICAL SURVEY,WHICH WAS PERFORMED ON 6/27/2002. 2/14/2003: RECEIVED THE MONITORING WELL WATER SAMPLING REPORT WHICH WAS PERFORMED ON 12/9/2002...BOTH MTBE AND BETX WAS DETECTED IN WELLS MW-4,AND MW-2...C&W WILL REVIEW THE DATA AND SEND ME THEIR PROPOSED WORK PLAN. 6/2/2003: RECEIVED THE HISTORICAL RESEARCH & GEOPHYSICAL SURVEY RESULTS FROM C&W...IT INDICATES THAT THERE ARE 2 AREAS OF ANOMALIES IN THE PARKING LOT,WHICH C&W WILL TALK WITH CHUCK BOWER AND DRAFT A WORK PLAN...PAT MULCAHY WILL KEEP ME INFORMED. 6/30/2003: RECEIVED THE GROUNDWATER ANALYTICAL REPORT FROM C&W FOR MARCH 2003...IT INDICATES THAT BETX RANGED FROM 7.7-34,400 PPB IN 10 OUT OF 11 WELLS...MTBE WAS DETECTED IN 10 OF THE 11 WELLS SAMPLED,WITH THE HIGHEST CONC. IN MW/RW-3 AT 34,400 PPB...THE SAMPLES FROM 8 OF THE 11 WELLS EXCEEDED OUR STANDARDS...C&W IS CONTINUING TO REVIEW THE DATA...ONCE THIS PROCESS IS COMPLETED,THEY WILL DRAFT A WORKPLAN. 8/26/2003: RECEIVED THE GROUNDWATER ANALYTICAL REPORT FROM C&W FOR THE WORK THEY DID IN JUNE 2003...THE HIGHEST CONCENTRATION OF MTBE WAS DETECTED IN MW/RW-3 AT A CONCENTRATION OF 37,100 PPB...C&W WILL SUBMIT THEIR WORKPLAN AFTER THEY RECEIVE CLEARANCE FROM UNI-MARTS. 10/1/2003: PAT MULCANY,C&W,TELECON RJJ,HE SAID THAT UNI-MART HAS REJECTED THEIR WORKPLAN,SO HE WILL DRAFT UP A NEW WORKPLAN AND RE-SUBMIT IT TO THEM...PAT WILL KEEP ME INFORMED. 11/17/2003: RECEIVED THE GROUNDWATER ANALYTICAL REPORT FROM C&W FOR THE WORK THEY DID ON 9/11/2003...THE HIGHEST CONCENTRATION OF MTBE WAS DETECTED IN MW/RW-3 AT A CONCENTRATION OF 150,000 PPB...ALL 12 WATER SAMPLES EXCEEDED OUR NYSDEC STANDARDS...I WILL DISCUSS THIS WITH PAT MULCAHY,C&W,AND SEE IF THEY RE-SUBMITTED THEIR WORKPLAN TO UNI-MART...PAT MULCAHY TELECON RJJ,HE SAID THAT THEY DID SEND THEIR NEW WORKPLAN TO UNI-MART,AND ARE AWAITING THEIR REPLY...PAT WILL KEEP ME INFORMED. 2/13/2004: RJJ TELECON C&W...DENNIS HOFFMAN IS NOW OVERSEEING THIS SITE FOR C&W,SINCE PAT MULCAHY HAS SINCE LEFT...DENNIS WILL KEEP ME INFORMED. 3/3/2004: CHUCH BOWER TELECON RJJ,HE SAID THAT HE WILL CONTACT C&W AND HAVE THEM SEND HIM OPTIONS ON HOW TO REMEDIATE THE SITE,THAN SEND THE WORKPLAN TO ME FOR APPROVAL...THIS SHOULD BE DONE IN APRIL. 3/24/2004: RECEIVED THE GROUNDWATER ANALYTICAL REPORT FROM C&W DETAILING THE MONITORING WELL WATER EVENT PERFORMED ON 12/3/2003...THE SAMPLES FROM 11 OF THE 12 WELLS ANALYZED EXCEEDED OUR GROUNDWATER STANDARDS...THE MAX. CONCENTRATION OF MTBE WAS IN MW/RW-3 AT 113,000 PPB...THE MAX. CONCENTRATION OF BETX COMPOUNDS WAS 12,508 PPB IN MW/RW-3...

FORMER UNI-MART (Continued) **S102963803**

5/17/2004: RECEIVED THE PROPOSED REMEDIAL ACTION PLAN FROM C&W FOR THE SITE...IT CONSISTS OF SOIL REMOVAL AND INSTALLING AN OXYGEN ENHANCEMENT SYSTEM VIA WELL INJECTION POINTS,ALL LOCATED IN THE AREA AROUND MW/RW-4...AFTER REVIEWING THIS WORKPLAN,I AGREE WITH IT...DRAFTED AND SENT A LETTER WITH MY APPROVAL OF THIS RAP. 9/20/2004: RECEIVED THE GROUNDWATER ANALYTICAL REPORT FROM C&W FROM THE SAMPLING EVENT PERFORMED ON 3/18/2004...MTBE WAS DETECTED IN ALL 12 WELLS WITH THE HIGHEST CONCENTRATION AT 50,000 PPB IN MW/RW-3...I WILL CONTACT C&W TO SEE IF THEY HAVE STARTED ON THE RAP YET. 9/22/2004: RJJ TELECO RANDY KLOSKO,C&W,HE SAID THAT THEY NOW HAVE THE OXYGEN ENHANCHMENT SYSTEM UP AND RUNNING,AS PER THE RAP. 5/13/2005: RANDY KLOSKO TELECON RJJ,HE SAID THAT RYAN MCCANN WILL NOW BE THE PROJECT MANAGER OF THIS SITE,AND THAT HE WILL HAVE RYAN SEND ME THE LASTEST UPDATE/REPORT AND DISCUSS THE SITE WITH ME. 7/14/2005: RECEIVED THE GROUNDWATER ANALYTICAL SUMMARY REPORT FROM C&W DETAILING THEIR ACTIVITIES PERFORMED ON 6/30/2004,9/28/2004,12/18/2004 & 3/16/2005...THEY RECOMMEND:(1)CONTINUE THE OXYGEN INJECTION (2) REVIEW THE 'TIGHTNESS' TESTING OF THE UST'S (3) CONTINUE WITH QUARTERLY GROUNDWATER SAMPLING (4) VAC-UP THE HEAVILY CONTAMINATED GROUNDWATER FROM THE CULVERT WELL (5) INJECT HYDROCARBON DEGRADING BACTERIA INTO CULVERT WELL (6) REPAIR DAMAGED ROAD BOXES...C&W HAS SENT THESE RECOMENDATIONS TO MR. CHUCH BOWER,UNI-MART FOR HIS REVIEW. 8/16/2005: RECEIVED THE GROUNDWATER ANALYTICAL SUMMARY REPORT FROM C&W,WHICH THEY PERFORMED ON 6/29/2005...OVERALL,THE LEVELS OF CONTAMINATION HAVE DROPPED SIGNIFICANTLY AT THE SITE...THE AREAS THAT DID SEE AN INCREASE IN CONTAMINANTS ARE AREAS OUTSIDE OF THE EFFECTIVE RADIUS OF INFLUENCE OF THE OXYGEN INJECTION SYSTEM...C&W IS STILL AWAITING APPROVAL FROM UNI-MART FOR THEIR RECOMMENDATIONS FOR FURTHER REMEDIAL ACTIVITIES. 1/24/2006: RJJ TELECON MARK WILDER,EPS OF VERMONT(FORMERLY C&W).HE SAID THAT EPS/VERMONT WILL TAKE OVER(CONTINUE THE C&W WORK) ALL OF UNI-MART STORES AND THAT HE WILL SEND ME THE LATEST ANALYTICAL RESULTS(REPORT)FROM THEIR SAMPLING EVENT IN DEC. 2005...HE WILL ALSO CONTACT CHUCK BOWER AND DISCUSS THE SITE WITH HIM. 3/30/2006: RECEIVED THE DISPOSAL RECEIPTS FROM EPS OF VERMONT FOR THE 47.32 TONS OF GASOLINE CONTAMINATED SOIL AND 4400 GAL OF THE GASOLINE/WATER MIXTURE WHICH WAS ENCOUNTERED WHEN THEY INSTALLED THE O2 SYSTEM. 5/2/2006: RECEIVED BOTH,THE FOURTH QUARTER 2005 & FIRST QUARTER 2006 MONITORING REPORTS FROM EPS OF VERMONT...SOME WELLS HAVE EXHIBITED A DECREASE IN TOTAL TARGET CONCENTRATIONS,HOWEVER,OCCASIONAL DRAMATIC INCREASES HAVE ALSO OCCURED...EPS WILL,CONTINUE THE 02 INJECTION,REVIEW 'TIGHTNESS' TESTING OF USTS,CONTINUE QUARTER MONITORING,& UTILIZE A VAC-TRUCK TO REMOVE CONTAMINATED GROUNDWATER FROM CULVERT WELL. 8/22/2006: RECEIVED THE SECOND QUARTER(2006) MONITORING REPORT FROM EPS OF VERMONT,WHICH WAS COMPLETED ON 6/16/2006...AS LIKE BOTH PREVIOUS QUARTERLY MONITORING REPORTS,THE RESULTS WERE SIMILAR...SOME WELLS EXHIBITED A DECREASE AND SOME HAD A DRAMATIC INCREASE IN TOTAL CONCENTRATIONS...I WILL DISCUSS THIS WITH EPS TO SEE IF THEIR RECOMMENDATIONS WILL BE IMPLEMENTED. 10/23/2006: RECEIVED THE QUARTERLY MONITORING REPORT FROM EP&S OF VERMONT FOR THE THIRD QUARTER OF 2006...AGAIN,SOME WELLS HAVE EXHIBITED A DECREASE AND SOME HAD AN INCREASE...AGAIN ,I WILL DISCUSS THIS REPORT WITH EP&S. 2/2/2007: RECEIVED THE FOURTH QUARTER(2006) MONITORING REPORT FROM EP&S...I WILL DISCUSS THESE RESULTS AND FUTURE REMEDIATION ACTIVITIES WITH THE NEW UNI-MARTS CONTACT PERSON PATTI TURIANO(#(814)234-6000). 2/15/2007: PATTI TURIANO,UNI-MARTS, TELECON RJJ,SHE SAID THAT THEY WILL PROCEED WITH ALL OF EP&S'S RECOMMENDATIONS AND KEEP ME INFORMED.

FORMER UNI-MART (Continued) **S102963803**

5/10/2007: RECEIVED THE FIRST QUARTERLY MONITORING REPORT(2007)FROM EP&S(VERMONT)...IN GENERAL,SOME OF THE WELLS HAVE EXHIBITED A DECREASING TREND IN ANALYTE CONCENTRATIONS FROM 10/2001 TO PRESENT,HOWEVER,OCCASIONAL DRAMATIC INCREASES HAVE OCCURED THAT THEY FEEL MAY BE ATTRIBUTED TO ON-SITE ACTIVITIES...EPSVT WILL CONTINUE WITH THE O2 INJECTION,REVIEW TIGHTNESS TESTING OF USTS,AND CONTINUE WITH THE QUARTERLY GROUNDWATER SAMPLING,PER EPSVT'S RECOMMENDATIONS. 8/13/2007: FRANK JORDAN,UNIMART,(#724-772-7075 #213)TELECON RJJ,HE SAID THAT HE IS THE NEW CONTACT PERSON FOR UNIMART...HE WILL OBTAIN THE TANK TIGHNESS TEST RESULTS,THEN THEY WILL HAVE EP&S OF VERMONT DRAFT A WORKPLAN FOR FURTHER REMEDIATION...FOR NOW,EP&S WILL CONTINUE WITH THEIR QUARTERLY MONITORING/SAMPLING. 8/17/2007: RECEIVED THE SECOND QUARTER 2007 MONITORING REPORT FROM EP&S OF VERMONT...AGAIN,LIKE THE FIRST QUARTER RESULTS,SOME WELLS HAVE DECREASED TOTAL ANALYTE CONCENTRATIONS WHILE MOST HAVE INCREASED,,,WELLS RW-3 & PZ-1,WHICH ARE LOCATED TO THE NORTH AND EAST OF THE PUMP ISLAND,HAVE THE HIGHEST CONCENTRATIONS AT THE SITE...EP&S WILL CONTINUE WITH THEIR QUARTERLY MONITORING/SAMPLING AND I WILL WAIT FOR UNIMART'S NEW WORKPLAN. 11/14/2007: FRANK JORDAN TELECON RJJ,HE SAID THAT HE WILL HAVE UNIMART FORWARD THE TANK TIGHNESS TEST RESULTS AND ALSO CONTACT EP&S AND HAVE THEM SEND ME THE THIRD QUARTER MONITORING RESULTS AND HE WILL DISCUSS THE WORKPLAN WITH THEM. 11/15/2007: RECEIVED THE THIRD QUARTER MONITORING 2007 REPORT FROM EP&S OF VERMONT...AGAIN,SOME WELLS SHOW A DECREASE AND SOME WELLS SHOW AN INCREASE IN TOTAL ANALYTE CONCENTRATIONS...EPSVT HAS SUMITTED A WORKPLAN TO PERFORM ADDITIONAL REMEDIAL ACTIVITIES AT SITE AND IS AWAITING CLIENT RESPONSE. 3/5/2008: RECEIVED THE FOURTH QUARTER 2007 MONITORING REPORT FROM EP&S OF VERMONT...RW-3 STILL HAS THE HIGHEST CONCENTRATION OF CONTAMINANTS ON SITE...THEY WILL CONTINUE WITH QUARTERLY GROUNDWATER SAMPLING AND ARE STILL WAITING FOR APPROVAL OF THEIR WORKPLAN BY UNIMART...I WILL DISCUSS THIS REPORT WITH FRANK JORDON(UNIMART). 3/10/2008: FRANK JORDON TELECON RJJ,HE SAID THAT THEY PLAN ON EXTENDING THE O2 SYSTEM ON THE PROPERTY AND INSTALLING 5 ADDITIONAL INJECTION WELLS...FRANK WILL KEEP ME INFORMED ON THEIR ACTIVITIES. 3/11/2008: RECEIVED THE ABOVE PROPOSED 2008 WORK PLAN FROM KLEINFELDER/UNIMART...AFTER REVIEWING THIS PLAN,I AGREE WITH IT. 4/17/2008: RECEIVED THE FIRST QUARTER 2008 SITE MONITORING REPORT FROM KLEINFELDER EAST,INC.,ON BEHALF OF UNI-MARTS,IIC....ALSO,THE INSTALLATION OF THE MATRIX O2 INJECTION SYSTEM IS PLANNED FOR LATTER THIS MONTH. 5/12/2008: KLEINFELDER HAS INSTALLED THE EXTENDED MATRIX O2 INJECTION SYSTEM ON 4/17/2008 AND TODAY THE SYSTEM BEGAN OPERATION,AS PER THE WORK PLAN. 8/19/2008: RECEIVED THE SECOND QUARTER 2008 SITE MONITORING REPORT FROM KLEINFELDER,ON BEHALF OF UNI-MARTS,LLC...DISSOLVED OXYGEN CONCENTRATIONS IN GROUNDWATER WERE MONITORED ON 6/23/2008...KLEINFELDER WILL CONTINUE WITH THEIR QUARTERLY MONITORING/SAMPLING. 11/3/2008: RECEIVED THE THIRD QUARTER 2008 GROUNDWATER MONITORING & SAMPLING REPORT FROM KLEINFELDER,ON BEHALF OF UNI-MARTS,LLC...DISSOLVED OXYGEN(DO)CONCENTRATIONS IN GROUNDWATER WERE MONITORED FROM 6/23-9/18/2008...THE HIGHEST MTBE CONCENTRATION WAS 9200 PPB IN RW-3. 2/3/2009: RECEIVED THE FOURTH QUARTER 2008 GROUNDWATER & SAMPLING REPORT FROM KLEINFELDER...THE HIGHEST MTBE CONCENTRATION WAS 9260 PPB AT RW-3...THE HIGHEST BENZENE CONCENTRATION WAS 358 PPB AT OW-1...KLEINFELDER EAST,INC.,ON BEHALF OF UNI-MARTS,LLC., WILL CONTINUE WITH THEIR QUARTERLY MONITORING/SAMPLING,EVENTHOUGH,THIS SITE NOW BELONGS AND IS OPERATED BY NOCO. 5/5/2009: RECEIVED THE 2009 FIRST QUARTER MONITORING REPORT FROM KLEINFELDER...THE HIGHEST MTBE CONCENTRATION WAS 8380 PPB AT

FORMER UNI-MART (Continued) **S102963803**

RW-3...THE HIGHEST TOTAL BETX CONCENTRATION WAS 3427 PPB AT PZ-1...THE MATRIX 02 INJECTION SYSTEM WILL CONTINUE TO OPERATE AND KLEINFELDER WILL CONTINUE WITH THEIR QUARTERLY MONITORING/SAMPLING,AS PER THE WORKPLAN. 8/11/2009: RECEIVED THE 2009 SECOND QUARTER MONITORING REPORT FROM KLEINFELDER...THE HIGHEST MTBE CONCENTRATION WAS 8260 PPB AT RW-3...THE HIGHEST BETX CONCENTRATION WAS 4245 PPB AT RW-4...THE MATRIX O2 SYSTEM IS CONTINUING TO OPERATE & KLEINFELDER WILL CONTINUE WITH THEIR QUARTERLY MONITORING/SAMPLING,AS PER THE WORKPLAN...ALSO,KLEINFELDER PERSONNEL MADE REPAIRS TO MW-4,5,RW-3,4,& CW-1 ON 5/5/2009. 10/20/2009: RECEIVED THE THIRD QUARTER 2009 SITE MONITORING REPORT FROM KLEINFELDER...THE HIGHEST MTBE CONCENTRATION WAS 7700 PPB AT RW-3...THE HIGHEST BETX CONCENTRATION WAS 4703 PPB AT OW-1...KLEINFELDER WILL CONTINUE WITH THEIR QUARTERLY MONITORING/SAMPLING. 2/12/2010: FRANK JORDAN,KLEINFELDER,TELECON RJJ,HE SAID THAT LEIHIGH GAS NOW OWNS THIS PROPERTY,AND AT THIS TIME,HE DOES NOT KNOW IF KLEINFELDER WILL CONTINUE WITH THE REMEDATION...THE NEW OWNERS ARE DISCUSSING THEIR OPTIONS...FRANK WILL KEEP ME INFORMED...(THE O2 SYSTEM IS STILL OPERATIONAL) 5/14/2010: RJJ TELECON FRANK JORDAN,HE SAID THAT I SHOULD CALL ATTORNEY TOBY LONG((804)787-8036...HE IS THE WORKING FOR UNIMART,WHO HAVE FILED BANKRUPTCY...AS OF NOW,THE O2 SYSTEM IS NOT OPERATIONAL AND NO ONE IS MONITORING THE REMEDIAL WORK ON THE PROPERTY,WHICH MAY NOW BE OWNED BY QUICK-PIC,A SUBSIDIARY OF LEIHIGH GAS...MR. LONG WILL TRY TO FIND OUT ADDITIONAL INFORMATION AND CONTACT ME NEXT WEEK. 5/17/2010: AFTER REVIEWING PBS RECORDS,NOCO ENERGY CORP. OWNS & OPERATES THE STATION AS OF 10/2006...I WILL DISCUSS THIS WITH MIKE YOUNT,NOCO...ALSO,I WILL CONTACT UNIMARTS INC. TO TRY TO OBTAIN ADDITIONAL INFORMATION...MIKE YOUNT TELECON RJJ,HE SAID THAT THEY HAVE PETITIONED UNIMART,IN THE BANKRUTCY CASE,TO HAVE THEM PAY FOR THE CONTINUED REMEDIATION OF THE PROPERTY...NOCO/MYSELF WILL WAIT FOR THE BANKRUPTCY TRUSTEE TO MAKE THEIR DETERMINATION,WHICH COULD BE NEXT MONTH. 10/26/2010: RJJ TELECON TOBY LONG,HE SAID THAT THE LITIGATION TRUSTEE IS MR. GIG SAYBAH (212) 808-7612 AND THAT I NEED TO ADDRESS ANY QUESTIONS TO HIM...I TELECON MR. SAYBAH AND LEFT A MESSAGE FOR HIM TO CONTACT ME. 12/2/2010: GIG SAYBAH TELECON RJJ,HE SAID THAT IT APPEARS THAT THERE IS NO MONEY AVAILABLE/REMAINING IN THE BANKRUPTCY CASE,AND UNIMARTS INC. NO LONGER EXISTS...MIKE YOUNT(NOCO) ALSO TELECON ME AND SAID THAT THEY WILL CONTACT THEIR ENVIROMENTAL CONTARCTOR(BENCHMARK) AND HAVE THEM REVIEW THE SPILL DATA THEN DRAFT UP A NEW WORKPLAN FOR MY REVIEW AND THEN NOCO WILL CONTINUE WITH THE REMEDIATION OF THE PROPERTY,WHICH THEY NOW OWN. 5/4/2011: MIKE YOUNT TELECON RJJ,HE SAID THAT THEY ARE STILL IN THE PROCESS OF DRAFTING A REMEDIATION PLAN TO ADDRESS THE SUBSURFACE CONTAMINATION ON THE SITE...THEY PLAN ON EXCAVATING THE CONTAIMINATED SOIL...MIKE WILL KEEP ME INFORMED. 12/13/2011: MIKE YOUNT TELECON RJJ,HE SAID THAT THEY PLAN ON EXCAVATING THE CONTAMINATED SOIL ON SITE IN THE SPRING OF 2012...NOCO WILL HAVE THEIR CONTRACTOR(BENCHMARK ENVIRONMENTAL) DRAFT UP A WORKPLAN FOR MY REVIEW. 1/11/2012: MIKE YOUNT,NOW AT BENCHMARK ENVIRONMENTAL,TELECON RJJ,HE SAID THAT HE WILL PROPOSE A COMPLETE ROUND OF GROUNDWATER SAMPLING TO DETERMINE THE PRESENT CONDITIONS,THEN, BASED ON THOSE ANALYTICAL RESULTS,DRAFT A WORKPLAN,POSSIBLE 1 YEAR OF MONITORING,TO DETERMINE THE NEXT REMEDIAL COURSE OF ACTION...THEY WILL ALSO LOOK INTO RE-STARTING THE O2 SYSTEM...MIKE WILL KEEP ME INFORMED. 6/1/2012: RECEIVED THE FIRST QUARTER 2012 GROUNDWATER MONITORING REPORT FROM NOCO,VIA E-MAIL...MOST OF THE RESULTS ARE SIMILAR TO THE PREVIOUS SAMPLING EVENTS. 9/18/2012: RECEIVED THE 'SUBSURFACE ENVIRONMENTAL

FORMER UNI-MART (Continued) **S102963803**

INVESTIGATION REPORT' FROM NOCO EXPRESS PROPERTIES,LLC...THEY ARE REQUESTING THE DEC TO CLOSE THIS SPILL...I WILL REVIEW THIS WITH SAC. 2/1/2013: MIKE YOUNT TELECON RJJ,HE SAID THAT LATER THIS YEAR,NOCO PLANS ON UPGRADING THIS STATION...NEW PUMP ISLAND,NEW USTS,& PIPING...NOCO WILL KEEP US INFORMED. 9/16/2013: TIM BOYLE,NOCO ENERGY(# 523-7323),TELECON RJJ,HE SAID THAT HE IS THE NEW CONTACT PERSON FOR THIS SITE AND THAT NOCO DOES HAVE PLANS TO UPGRADE THIS STATION THIS YEAR...TIM WILL KEEP ME INFORMED. 9/19/2013: MIKE LESAKOWSKI,TURNKEY ENVIRONMENTAL,TELECON RJJ,HE SAID THAT NOCO PLANS ON UPGRADING THIS SITE IN OCTOBER...AT THAT TIME,TURNKEY WILL BE ON SITE OVERSEEING THE REMEDIATION...MIKE WILL KEEP ME INFORMED. 11/14/2013: TIM BOYLE,NOCO,E-MAILED ME AN UPDATE ON THIS SITE...NOCO NOW PLANS ON UPGRADING THE ENTIRE PROPERTY AND DEMOLISHING THE EXISTING BUILDING...THIS REDEVELOPMENT/UPGRADE WILL BEGIN IN THE SPRING OF 2014...AT THAT TIME,NOCO WILL ADDRESS ALL THE ENVIRONMENTAL ISSUES. 9/16/2014: TIM BOYLE,NOCO,TELECON RJJ,HE SAID THAT HAVE BEGUN TO DECOMMISION THIS SITE AND NEXT WEEK,THEY WILL BEGIN TO EXCAVATE THE SUBSURFACE...TIM WILL KEEP ME INFORMED. 11/13/2014: TIM BOYLE TELECON RJJ,HE SAID THAT THEY WILL BEGIN EXCAVATING THE SUBSURFACE,NEXT WEEK,AND WILL CONTACT ME WHEN THEY ENCOUNTER ANY PETROLEUM CONTAMINATED SOIL. 12/2/2014: RJJ AT SITE AT 1030...NOCO'S CONTRACTOR,PRIME TIME SERVICES,ARE IN THE PROCESS OF A TANK TOP UPGRADE,AND ARE NOT REMOVING THE USTS...NEXT WEEK,THEY WILL BEGIN TO EXCAVATE THE SUBSURFACE,WHERE THE O2 SYSTEM IS AND WHERE THE OLD DISPENSER WERE...BENCHMARK WILL OVERSEE THIS AND ANY PETROLEUM CONTAMINATION THEY ENCOUNTER WILL BE REMOVED/DISPOSED OF. 12/5/2014: RJJ AT SITE AT 0930...YESTERDAY,PRIME TIME SERVICES BEGAN EXCAVATING THE PETROLEUM CONTAMINATED SOIL,NEAR THE OLD PUMP ISLAND DISPENSERS...THEY REMOVED AND TRANSPORTED ~220 TONS OF SOIL TO NOCO'S TONAWANDA TERMINAL...TODAY,THEY ARE CONTINUING EXCAVATING NORTHWARD/EASTWARD TOWARD NIAGARA FALLS BLVD.,AND EXPECT AN ADDTIONAL 300 TONS TO BE REMOVED TODAY...BRYAN MAYBACK,BENCHMARK,IS OVERSEEING THE SOIL REMOVAL AND HE WILL OBTAIN ALL THE CONFIRMATORY SIDEWALL/BOTTOM SOIL SAMPLES,AND KEEP ME INFORMED...(ON THE EASTSIDE,TOWARD THE SIDEWALK,THEY CAN ONLY EXCAVATE UP TO THE UTILITY LINES) 12/8/2014: RJJ AT SITE AT 1300...PRIME TIME IS CONTINUING TO EXCAVATE THE CONTAMINATED SOIL...THUS FAR,THEY HAVE REMOVED/DISPOSED ~600 TONS...BRYAN MAYBACK IS OBTAINING THE CONFIRMATORY SOIL SAMPLES,PER OUR DISCUSSION. 12/9/2014: RJJ AT SITE AT 0930...TODAY THEY HAVE ENCOUNTERED AN OLD 500 GAL WASTE OIL TANK...THIS UST IS RIGHT WHERE THE O2 SYSTEM WAS AND APPEARS TO BE THE CAUSE OF THIS CONTAMINATION...NOCO WILL CONTINUE REMOVING THIS CONTAMINATION AND REMOVE THIS UST LATER TODAY...THUS FAR,THEY HAVE REMOVED ~1100 TONS OF SOIL. 12/10/2014: RJJ AT SITE AT 0930...NOCO IS CONTINUING EXCAVATING,WESTWARD,WHERE THE UST WAS...THEY ARE ALSO EXCAVATING SOUTHWARD AND HAVE ENCOUNTERED ADDITIONAL CONTAMINATION FROM THE OLD TANK FIELD...THUS FAR,THEY HAVE REMOVED ~1500 TONS OF SOIL AND SHOULD BE ~1800 LATER TODAY...BRIAN MAYBACK WILL CONTINUE TO OBTAIN CONFIRMATORY SOIL SAMPLES. 12/11/2014: RJJ AT SITE AT 1245...NOCO HAS FINISHED EXCAVATING THE SITE...THEY HAVE REMOVED ~2000 TONS OF SOIL AND TRANSPORTED IT ALL TO THE TONAWANDA TERMINAL...BRYAN MAYBACK HAS OBTAINED ALL THE CONFIRMATORY SOIL SAMPLES FROM THIS ODD SHAPED EXCAVATION,PER OUR DISCUSSIONS,AND HE WILL SEND ME THEIR REPORT. 1/30/2015: RECEIVED THE FINAL CLOSURE REPORT FROM BENCHMARK/TURNKEY,WHICH INCLUDES THE DISPOSAL RECEIPTS FOR THE 1943.76 TONS OF PETROLEUM CONTAMINATED SOIL TAKEN TO NOCO'S TONAWANDA TERMINAL & ALL THE CONFIRMATORY ANALYTICAL RESULTS FROM THE

FORMER UNI-MART (Continued) **S102963803**

EXCAVATION...A FEW COMPOUNDS WERE SLIGHTLY HIGHER THAN OUR CP-51 GUIDANCE VALUES,HOWEVER,THESE WERE IN THE AREA WHERE FURTHER EXCAVATION WAS NOT POSSIBLE DUE TO UTILITIES NEARBY...SINCE A FEW ANALYTICAL RESULTS ARE HIGHER THAN OUR CP-51 GUIDANCE VALUES,THE SITE WILL REMAIN IN AN 'INACTIVE' STATUS,HOWEVER,NO FURTHER ADDITIONAL REMEDIATION WILL BE REQUIRED AT THIS TIME...DRAFTED & SENT AN 'INACTIVE' LETTER TO CURRENT PROPETY OWNERS...SPILL CLOSED OUT."

Remarks: "while installing a water line during a nysdot project, gasoline contaminated soil was encountered in front of the active gas station - corner of moore & niagara falls blvd - it is a uni-mart station"

All Materials:

Site ID:	114384
Operable Unit ID:	1055353
Operable Unit:	01
Material ID:	327077
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	9806636 / 1998-09-08
Facility ID:	9806636
Facility Type:	ER
DER Facility ID:	99758
Site ID:	114385
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	D3
SWIS:	1516
Spill Date:	1998-08-28
Investigator:	SORGI
Referred To:	Not reported
Reported to Dept:	1998-08-28
CID:	322
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	1998-09-08
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1998-08-28
Spill Record Last Update:	1998-09-18
Spiller Name:	JOEL MIKULBC
Spiller Company:	UNIMART INC
Spiller Address:	820 NIAGARA FALLS BLVD
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MJS 09/08/98: MJS SITE INSPECT. CLEANUP SATISFACTORY. STAIN ON

FORMER UNI-MART (Continued) **S102963803**

BLACKTOP. NO FURTHER ACTION REQUIRED. MJS CLOSE FILE. "
Remarks: "hose on gas pump blew - contained and speedi dry put down"

All Materials:
Site ID: 114385
Operable Unit ID: 1064236
Operable Unit: 01
Material ID: 317786
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 5.00
Units: G
Recovered: 5.00
Oxygenate: Not reported

Spill Number/Closed Date: 1205616 / 2012-09-05
Facility ID: 1205616
Facility Type: ER
DER Facility ID: 422864
Site ID: 468578
DEC Region: 9
Spill Cause: Human Error
Spill Class: D4
SWIS: 1564
Spill Date: 2012-09-05
Investigator: RMCROSSE
Referred To: Not reported
Reported to Dept: 2012-09-05
CID: Not reported
Water Affected: Not reported
Spill Source: Gasoline Station or other PBS Facility
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: Not reported
UST Trust: Not reported
Remediation Phase: 0
Date Entered In Computer: 2012-09-05
Spill Record Last Update: 2012-09-05
Spiller Name: Not reported
Spiller Company: NOCO
Spiller Address: 700 GRAND ISLAND BLVD
Spiller Company: 999
Contact Name: TIM TOMPKINS
DEC Memo: "RMC/FILE. NO SPILL ACTION REQUIRED. CLOSE OUT NO PAPER FILE."
Remarks: "Customer drive off broke seal. Gallon lost and it evaporated."

All Materials:
Site ID: 468578
Operable Unit ID: 1218495
Operable Unit: 01
Material ID: 2216873
Material Code: 0009
Material Name: gasoline

FORMER UNI-MART (Continued) **S102963803**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	0211039 / 2003-02-05
Facility ID:	0211039
Facility Type:	ER
DER Facility ID:	102865
Site ID:	118355
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	3200
Spill Date:	2003-02-04
Investigator:	RJJONAK
Referred To:	Not reported
Reported to Dept:	2003-02-04
CID:	390
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	2003-02-04
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-02-04
Spill Record Last Update:	2003-02-05
Spiller Name:	CALLER
Spiller Company:	MODERN DISPOSAL
Spiller Address:	4746 MODEL CITY RD
Spiller Company:	001
Contact Name:	UNK
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RJJ 2/4/2003: RJJ AT SITE AT 1000...ONE OF MODERN'S DUMPSTER TRUCK BROKE A HYDRAULIC HOSE,SPILLING ABOUT 20 GAL OF HYDRAULIC OIL,ALL ON THE BLACKTOP DRIVEWAY AT 0700...THEY USED ABSORBANT PADS AND SPEEDY DRY TO CONTAIN AND PICK UP THE SPILL,WHICH WAS ALL IN A SMALL AREA UNDER THE TRUCK...THEY CLEANED UP THE MATERIAL AND DISPOSED IT IN THEIR DUMPSTER...THE SPILL HAS BEEN CLEANED UP AND PROPERLY DISPOSED OF...NO FURTHER ACTION NEEDED...SPILL CLOSED OUT. **** NOTE,THERE IS NO PAPER FILE FOR THIS SPILL ****"
Remarks:	"line failed on truck - spilled to blacktop parking lot only - clean up is almost complete"

All Materials:

Site ID:	118355
Operable Unit ID:	864238
Operable Unit:	01
Material ID:	514403
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported

FORMER UNI-MART (Continued) **S102963803**

Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	20.00
Oxygenate:	Not reported

R105 **NOCO EXPRESS S-74** **NY UST** **U003318519**
West **820 NIAGARA FALLS BOULEVARD** **N/A**
< 1/8 **TONAWANDA, NY 14223**
0.018 mi.
94 ft. **Site 6 of 7 in cluster R**

Actual:
599 ft.

Focus Map:
6

UST:

Id/Status:	9-494062 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	9
Expiration Date:	10/16/2021
UTM X:	188215.32611
UTM Y:	4765303.72497
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	54677
Affiliation Type:	Mail Contact
Company Name:	NOCO EXPRESS PROPERTIES, LLC
Contact Type:	EHS/VP
Contact Name:	TOM ANDERSON
Address1:	2440 SHERIDAN DRIVE
Address2:	Not reported
City:	TONAWANDA
State:	NY
Zip Code:	14150
Country Code:	999
Phone:	(716) 504-3319
EMail:	TANDERSON@NOCO.COM
Fax Number:	Not reported
Modified By:	SACALAND
Date Last Modified:	2018-08-02

Site Id:	54677
Affiliation Type:	Facility Operator
Company Name:	NOCO EXPRESS S-74
Contact Type:	Not reported
Contact Name:	RAMON CRUZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(716) 832-0810
EMail:	Not reported
Fax Number:	Not reported
Modified By:	AESKALSK
Date Last Modified:	2017-11-01

NOCO EXPRESS S-74 (Continued) **U003318519**

Site Id:	54677
Affiliation Type:	Emergency Contact
Company Name:	NOCO EXPRESS PROPERTIES, LLC
Contact Type:	Not reported
Contact Name:	TOM ANDERSON
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(716) 353-3096
EMail:	Not reported
Fax Number:	Not reported
Modified By:	SJWALSH
Date Last Modified:	2016-10-04

Site Id:	54677
Affiliation Type:	Facility Owner
Company Name:	NOCO EXPRESS PROPERTIES, LLC
Contact Type:	VICE PRESIDENT
Contact Name:	TOM ANDERSON
Address1:	2440 SHERIDAN DRIVE
Address2:	Not reported
City:	TONAWANDA
State:	NY
Zip Code:	14150
Country Code:	001
Phone:	(800) 500-6626
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TAMAMUN
Date Last Modified:	2016-09-27

Tank Info:

Tank Number:	1
Tank ID:	168594
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	10000
Install Date:	08/01/1989
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol

Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	AESKALSK
Last Modified:	09/20/2018

Equipment Records:

NOCO EXPRESS S-74 (Continued) **U003318519**

J01 - Dispenser - Pressurized Dispenser
B02 - Tank External Protection - Original Sacrificial Anode
E04 - Piping Secondary Containment - Double walled UG
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
A00 - Tank Internal Protection - None
K01 - Spill Prevention - Catch Basin
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
G04 - Tank Secondary Containment - Double-Walled (Underground)
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Number:	2
Tank ID:	168595
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	10000
Install Date:	08/01/1989
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	AESKALSK
Last Modified:	09/20/2018

Equipment Records:

B02 - Tank External Protection - Original Sacrificial Anode
E04 - Piping Secondary Containment - Double walled UG
J01 - Dispenser - Pressurized Dispenser
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
K01 - Spill Prevention - Catch Basin
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
G04 - Tank Secondary Containment - Double-Walled (Underground)
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Number:	3
Tank ID:	168596
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	10000
Install Date:	08/01/1989
Date Tank Closed:	Not reported

NOCO EXPRESS S-74 (Continued) **U003318519**

Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	AESKALSK
Last Modified:	09/20/2018

Equipment Records:

J01 - Dispenser - Pressurized Dispenser
B02 - Tank External Protection - Original Sacrificial Anode
E04 - Piping Secondary Containment - Double walled UG
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
A00 - Tank Internal Protection - None
K01 - Spill Prevention - Catch Basin
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
G04 - Tank Secondary Containment - Double-Walled (Underground)
H05 - Tank Leak Detection - In-Tank System (ATG)

R106 **JIM WOODS TIRE & BATTERY** **NY UST** **U003316981**
West **820 NIAGARA FALLS BLVD** **N/A**
< 1/8 **TONAWANDA, NY 14223**
0.018 mi.
94 ft. **Site 7 of 7 in cluster R**

Actual:
599 ft.

Focus Map:
6

UST:

Id/Status:	9-125202 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	9
Expiration Date:	N/A
UTM X:	188215.32611
UTM Y:	4765303.72497
Site Type:	Unknown

Affiliation Records:

Site Id:	52843
Affiliation Type:	Facility Owner
Company Name:	JAMES S WOOD
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	6 HOWARD LANE
Address2:	Not reported
City:	TONAWANDA
State:	NY
Zip Code:	14150
Country Code:	001
Phone:	(716) 835-2548
EMail:	Not reported
Fax Number:	Not reported

JIM WOODS TIRE & BATTERY (Continued) **U003316981**

Modified By:	TRANSLAT
Date Last Modified:	2004-03-04
Site Id:	52843
Affiliation Type:	Mail Contact
Company Name:	JAMES S WOOD
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	6 HOWARD LANE
Address2:	Not reported
City:	TONAWANDA
State:	NY
Zip Code:	14150
Country Code:	001
Phone:	(716) 835-2548
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04
Site Id:	52843
Affiliation Type:	Facility Operator
Company Name:	JIM WOODS TIRE & BATTERY
Contact Type:	Not reported
Contact Name:	JAMES S WOOD
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(716) 833-7744
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04
Site Id:	52843
Affiliation Type:	Emergency Contact
Company Name:	JAMES S WOOD
Contact Type:	Not reported
Contact Name:	JAMES S WOOD
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(716) 835-2548
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	1

JIM WOODS TIRE & BATTERY (Continued) **U003316981**

Tank ID:	163022
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	8000
Install Date:	Not reported
Date Tank Closed:	10/01/1989
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)
D00 - Pipe Type - No Piping

Tank Number:	2
Tank ID:	163023
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	8000
Install Date:	Not reported
Date Tank Closed:	10/01/1989
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

JIM WOODS TIRE & BATTERY (Continued) **U003316981**

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
D00 - Pipe Type - No Piping

Tank Number:	3
Tank ID:	163024
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	8000
Install Date:	Not reported
Date Tank Closed:	10/01/1989
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	03
Date Test:	02/01/1988
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)
D00 - Pipe Type - No Piping

AA107 **SWEENEYS GARAGE AUTO RPR** **EDR Hist Auto** **1014539358**
West **424 NIAGARA FALLS BLVD** **N/A**
< 1/8 **BUFFALO, NY 14223**
0.018 mi.
95 ft. **Site 1 of 2 in cluster AA**

Actual: EDR Hist Auto
606 ft.

Focus Map:
8

Year:	Name:	Type:
1982	SWEENEYS GARAGE	General Automotive Repair Shops
1983	SWEENEYS GARAGE	General Automotive Repair Shops
1985	SWEENEYS GARAGE	General Automotive Repair Shops
1986	SWEENEYS GARAGE	General Automotive Repair Shops
1987	SWEENEYS GARAGE	General Automotive Repair Shops
1988	SWEENEYS GARAGE	General Automotive Repair Shops
1989	SWEENEYS GARAGE	General Automotive Repair Shops
1990	SWEENEYS GARAGE	General Automotive Repair Shops
1991	SWEENEYS GARAGE	General Automotive Repair Shops
1992	SWEENEYS GARAGE	General Automotive Repair Shops
1993	SWEENEYS GARAGE INC	General Automotive Repair Shops
1994	SWEENEYS GARAGE INC	General Automotive Repair Shops
1995	SWEENEYS GARAGE INC	General Automotive Repair Shops

SWEENEYS GARAGE AUTO RPR (Continued) **1014539358**

1996	SWEENEYS GARAGE INC	General Automotive Repair Shops
1997	SWEENEYS GARAGE INC	General Automotive Repair Shops
1998	SWEENEYS GARAGE AUTO RPR	AUTOMOBILE REPAIRING & SERVICE
1998	SWEENEYS GARAGE INC	General Automotive Repair Shops
1999	SWEENEYS GARAGE INC	General Automotive Repair Shops
2000	SWEENEYS GARAGE INC	General Automotive Repair Shops
2001	SWEENEYS GARAGE INC	General Automotive Repair Shops
2002	SWEENEYS GARAGE INC	General Automotive Repair Shops
2003	SWEENEYS GARAGE INC	General Automotive Repair Shops
2004	SWEENEYS GARAGE INC	General Automotive Repair Shops
2005	SWEENEYS GARAGE INC	General Automotive Repair Shops
2006	SWEENEYS GARAGE INC	General Automotive Repair Shops
2007	SWEENEYS GARAGE INC	General Automotive Repair Shops
2008	SWEENEYS GARAGE INC	General Automotive Repair Shops
2009	SWEENEYS GARAGE INC	General Automotive Repair Shops
2010	SWEENEYS GARAGE INC	General Automotive Repair Shops
2011	SWEENEYS GARAGE INC	General Automotive Repair Shops
2012	SWEENEYS GARAGE INC	General Automotive Repair Shops
2013	SWEENEYS GARAGE INC	General Automotive Repair Shops
2014	SWEENEYS GARAGE INC	General Automotive Repair Shops

AA108 **SWEENEY'S GARAGE** **NY LTANKS S102178081**
West **424 NIAGARA FALLS BLVD.** **NY Spills N/A**
< 1/8 **TONAWANDA, NY**
0.018 mi.
95 ft. **Site 2 of 2 in cluster AA**

Actual:
606 ft.

Focus Map:
8

LTANKS:

Spill Number/Closed Date:	9802942 / 1998-09-14
Facility ID:	9802942
Site ID:	192730
Spill Date:	1998-06-03
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	1564
Investigator:	COOKE
Referred To:	Not reported
Reported to Dept:	1998-06-03
CID:	999
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1998-06-05
Spill Record Last Update:	1998-09-18
Spiller Name:	PHILIP BASINSKI
Spiller Company:	SWEENEY'S GARAGE
Spiller Address:	424 NIAGARA FALLS BLVD
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	9

SWEENEY'S GARAGE (Continued) **S102178081**

DER Facility ID: 160700
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was JDC 6/3/98: RECEIVED NOTICE THAT INITIAL FINDING FOR A TANK REMOVAL FOUND CONTAMINATION. NATURES WAY HIRED TO DO TANK REMOVAL. 9/14/98: JDC RECEIVED CLOSURE REPORT AND FOUND MINOR VIOLATIONS OF STARS IN POST TEST RESULTS. BASED ON REPORT WILL IDENTIFY SITE AS INACTIVE."
Remarks: "natures way hired to remove fuel in tank - uncovered gasoline tank and found minor contamination"

All Materials:
Site ID: 192730
Operable Unit ID: 1063602
Operable Unit: 01
Material ID: 321264
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

SPILLS:
Spill Number/Closed Date: 0075398 / 2000-12-05
Facility ID: 0075398
Facility Type: ER
DER Facility ID: 160700
Site ID: 192729
DEC Region: 9
Spill Cause: Unknown
Spill Class: B3
SWIS: 1564
Spill Date: 2000-09-26
Investigator: RMCROSSE
Referred To: Not reported
Reported to Dept: 2000-09-26
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: 2000-09-29
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2000-09-26
Spill Record Last Update: 2001-01-29
Spiller Name: PHIL SWEENEY
Spiller Company: SWEENEY'S GARAGE
Spiller Address: 424 NIAGARA FALLS BLVD.
Spiller Company: 001
Contact Name: PHIL SWEENEY
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 09/29/00: RMC AND RNL SITE INSPECTION, MET NATURE'S WAY AND PHIL

SWEENEY'S GARAGE (Continued) **S102178081**

SWEENEY, REMOVED 55 GALLON WASTE OIL TANK INSIDE THE BUILDING, SMALL DUMP TRUCK OF CONTAMINATED SOIL REMOVED, APPEARS TO BE LAYER OF CONTAMINATED MATERIAL JUST BELOW THE CONCRETE FLOOR, SAMPLES TAKEN, UPDATE 11/1/00 11/09/00: RMC RECEIVED STOCKPILED CONTAMINATED SOIL RESULTS RMC TELECON TO RUSS SAVAGE OF NATURE'S WAY, REQUESTED DISPOSAL AND EXCAVTION SAMPLE RESULTS, DUE 11/30/00 11/30/00: RMC TELECON GREG WEBER OF NATURE'S WAY, REQUESTED REPORT, DUE 12/15/00 12/05/00: RMC RECEIVED REPORT, NO EXCEEDANCES, DISPOSAL FOR 20 TONS CONTAMINATED SOIL DOCUMENTED, RMC SENT CLOSEOUT LETTER"

Remarks: "CONTAMINATION FOUND WHILE REMOVING WASTE OIL TANK IN SIDE BUILDING "

All Materials:

Site ID:	192729
Operable Unit ID:	838253
Operable Unit:	01
Material ID:	538964
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	9975654 / 2000-01-24
Facility ID:	9975654
Facility Type:	ER
DER Facility ID:	160700
Site ID:	192731
DEC Region:	9
Spill Cause:	Deliberate
Spill Class:	E5
SWIS:	1564
Spill Date:	2000-01-01
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	2000-01-24
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-01-24
Spill Record Last Update:	2000-06-06
Spiller Name:	Not reported
Spiller Company:	NONE
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 01/24/00: RMC TELECON TO PHIL, OWNER OF FACILITY, RMC ADVISED

SWEENEY'S GARAGE (Continued) **S102178081**

THAT SWEENY IS RESPONSIBLE FOR DISPOSING OF EXTRA WASTE OIL AND THAT THEY SHOULD PUT A LOCK ON THE CONTAINER, NO ACTION REQUIRED, CLOSE OUT "

Remarks: "CALLER BELIEVED THAT SOMEONE DUMPED UNKNOWN MATERIAL IN THEIR WASTE OIL TANK "

All Materials:

Site ID:	192731
Operable Unit ID:	1091796
Operable Unit:	01
Material ID:	290193
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	9306642 / 1993-09-03
Facility ID:	9306642
Facility Type:	ER
DER Facility ID:	66694
Site ID:	70227
DEC Region:	9
Spill Cause:	Deliberate
Spill Class:	D3
SWIS:	1564
Spill Date:	1993-08-01
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	1993-08-26
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Local Agency
Cleanup Ceased:	1993-09-02
Cleanup Meets Std:	True
Last Inspection:	1993-09-02
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1993-09-01
Spill Record Last Update:	1994-10-11
Spiller Name:	Not reported
Spiller Company:	SWEENEY'S GARAGE
Spiller Address:	424 NIAGARA FALLS BLVD
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 09/02/93: RMC/PHIL BASINSKI, OWNER/SITE - STREET HAS VERY MINOR OIL DRIPS IN SEVERAL SPOTS. SHOP & LOT VERY CLEAN. OWNER HAS RECEIPT HISTORY FOR WASTE OIL DISPOSAL. NO ACTION REQUIRED. 09/03/93: RMC ADVISED COUNCILMAN LENIHAN'S OFFICE OF FINDINGS. CLOSED OUT. "
Remarks:	"DRAINS OIL TO STREET; OIL SPILLAGE TO STREET."

SWEENEY'S GARAGE (Continued) **S102178081**

All Materials:

Site ID:	70227
Operable Unit ID:	984807
Operable Unit:	01
Material ID:	396492
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

T109 **POPPLETON RESIDENCE** **NY Spills** **S106015572**
West **232 NIAGARA FALLS BLVD** **N/A**
< 1/8 **TONAWANDA, NY**
0.018 mi.
96 ft. **Site 3 of 4 in cluster T**

Actual:
619 ft.

Focus Map:
8

SPILLS:

Spill Number/Closed Date:	0375180 / 2003-07-01
Facility ID:	0375180
Facility Type:	ER
DER Facility ID:	170296
Site ID:	204989
DEC Region:	9
Spill Cause:	Unknown
Spill Class:	E6
SWIS:	1564
Spill Date:	2003-06-23
Investigator:	RJJONAK
Referred To:	Not reported
Reported to Dept:	2003-06-30
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	2003-07-01
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-06-30
Spill Record Last Update:	2003-07-01
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	LISA POPPLETON
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RJJ 7/1/2003: RJJ AT SITE AT 1000...MEET WITH LISA POPPLETON,SHE EXPLAINED THAT HER DOCTOR TOLD HER THAT HER PROBLEM WAS SOMETHING SHE ATE,AND SHE ALSO SAID THAT THERE IS NO PIPE IN THE BACKYARD,JUST AN OLD PIECE OF PIPE SHE DUG UP...I CHECKED THE AREA AND FOUND NO

POPPLETON RESIDENCE (Continued) **S106015572**

EVIDENCE OF ANY PETROLEUM PROBLEMS,NO PIPE AND NO ODORS...NO FURTHER ACTION NEEDED...SPILL CLOSED OUT. **** NOTE: THERE IS NO PAPER FILE FOR THIS SPILL ****"

Remarks: "CALLER BECAME ILL AFTER WORKING IN HER YARD. INDICATES PROPERTY USED TO BE OWNED BY CURTISS WRIGHT AIRFIELD. SAID THERE IS A CAPPED PIPE IN HER YARD. BELIEVES THERE MAY BE SOMETHING IN HER PROPERTY. HOUSE WAS BUILT IN 1920."

All Materials:

Site ID:	204989
Operable Unit ID:	882139
Operable Unit:	01
Material ID:	494378
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

T110 **BOB HILLS OLD GAS STATION** **NY LTANKS** **S103238653**
West **240 NIAGARA FALLS BLVD** **N/A**
< 1/8 **TONAWANDA, NY**
0.018 mi.
97 ft. **Site 4 of 4 in cluster T**

Actual:
618 ft.

Focus Map:
8

LTANKS:

Spill Number/Closed Date:	9608361 / 1996-12-31
Facility ID:	9608361
Site ID:	304933
Spill Date:	1996-10-03
Spill Cause:	Tank Overfill
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C3
Cleanup Ceased:	1996-12-31
SWIS:	1564
Investigator:	COOKE
Referred To:	Not reported
Reported to Dept:	1996-10-04
CID:	199
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	1996-10-09
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1996-10-04
Spill Record Last Update:	1997-01-27
Spiller Name:	BOB HILLS
Spiller Company:	BOB HILLS
Spiller Address:	5150 BANK STREET
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported

BOB HILLS OLD GAS STATION (Continued) **S103238653**

Spiller Extention: Not reported
DEC Region: 9
DER Facility ID: 246316
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was JDC 10/8/96 JDC ON SITE AND MET W/ BOB HILLS, PRP, DISCUSSED TANK CLOSURE OPTIONS. GASOLINE CONTAMINATED SOILS DETECTED IN SANDY SOILS AT TANK TOP AT EASTEND OF PROPERTY. SECOND TANK SHOWD NO PHYSICAL SIGNS OF CONTAMINATION. TANKS ARE UNDERSTOOD TO BE 800 GALLONS EACH ONCE USED FOR GASOLINE STORAGE WHEN THE AREA WAS ASERVICE STATION. WILL SEND LETTER OUTLINING REQUIREMENTS. 10/11/96: JDC TELCON W/ MR HILLS. HE WILL DO TANK WORK, NON-CONTRACTWED, ANTICIPATES HAVING TANKS EXPOSED BY THE WEEKEND. ADVISED HE CONTACT ME FOR INSPECTION. 10/12/96: RMC RESPONDED TO C.O. ODORS AND TANK LIQUIDS BEING DUMPED INTO SEWERS. TWO 1K TANKS REMOVED, HEAVY PETROLEUM ODORS FROM TANK EXCAVATION. JDC VISISTED AND MET W/ RP, AGAIN ADVISED HIM OF PROPER TANK REMOVAL REQUIREMENTS AND THE NEED TO SECURE CONTAMINATED SOILS ON SITE. HE ANTICIPATES OBTAINING ROLL-OFF BOXES TO STORE SOILS. MORE SOIL WILL BE REMOVED OVER THE NEXT FEW DAYS BASED ON EVIDENCE OF CONTAMIATION OBSERVED IN THE EXCAVATION. 10/18/96: JDC ON SITE AND FOUND THIRD TANK REMOVED FROM NORTH EXCAVATION. PETROLEUM ODORS DETECETED, NO FREE PRODUCT ON GW. JDC TELCON W/ BOB HILL, ADVISED THAT HE NEEDS TO REMOVE MORE SOILS FROM BOTH NORTH AND SOUTH EXCAVATIONS. RECEIVED INITIAL POST TEST RESULTS FROM SOUTH EXCAVATION, WALL SAMPLES EXCEED STANDARDS, HE WILL REMOVE MORE SOILS AND RETEST. SAC RECIEVED CALL FROM WAYNE DUSALL, AT 838-1810 CITIZEN REGARDING THIRD TANK BEING REMOVED. 10/21/96: MR DUSALL CALLED AND STATED RP HAS RESUMED CLEANUP AND HE IS CONCERNED PROPER ACTIONS INVOLVING THE CLEANUP. CALLED MR DUSALL, NO ANSWER. 10/25/96: JDC ON SITE AND FOUND NORTH EXCAVATION BACKFILLED. ANALITICAL RESULTS SHOW MINOR EXCEEDANCES. AUTHORIZED MR HILL DO BACKFILL. SOILS REMOVED AND DISPOSED OF BY WASTE MANAGMENT, MORE SOILS TO BE EXCAVATED. EXPECT WORK TO CONTINUE NXT WEEK. GASOLINE CONTAMINATION PRESENT IN SOUTH EXCAVATION, NO FREE PRODUCT. 10/29/96: JDC ON SITE AND MET W/ MR HILLS, NORTH EXCAVATION BACKFILLED. SOUTH EXCAVATION HAS STRONG GASOLINE ODODR. HE WILL REMOVE MORE SOILS FROM THE EXCAVATION NEAR THE OLD FILL LINES. TWO LOADS OF SOIL HAS BEEN REMOVED BY WASTE MANAGEMENT, 10 YRDS STOCKPILED ON SITE. HE WILL COLLECT POST SAMPLES ON SIDEWALLS AND NOT THE BOTTOM, EARLIER SAMPLING PASSED UNDER INACTIVE STATUS. 11/4/96: JDC TELCON W/ BOB HILLS, 5TH TANK WAS DISCOVERD AT SOUTH END OF PROPERTY PARTIALLY UNDER THE SIDEWALK. TOWN INSPECTOR WAS ON SITE AND ADVISED RP HE WOULD NEED TO REPLACE SIDEWALK AFTER THE TANK IS REMOVED. ALL SOILS EXCAVATED TO DATE HAVE BEEN COLLECTED AND DISPOSED OF. LATEST SAMPLING RESULTS ALONG THE NFBLVD SIDE IF THE EXCAVTION INDICATED HEAVY CONTAMINATION. ADVISED RP HE MAY WANT TO PLACED. HE WILL NOTIFY WHEN TANK IS TO BE REMOVED. 11/7/96: JDC SPOKE W/ JACK FISHER, LAB CONSULTANT REGARDING SITE STATUS AND SAMPLING REQUIREMNETS. NATURE'S WAY WILL PUMP OUT TANK WATER AND EXCAVATION WATER NEXT WEEK FOR DISPOSAL. IN ADDITION SAMPLES WILL BE COMPOSITED FOR THE SIDEWALLS AND BOTTOM OF THE EXCAVATION. 11/7/96: JDC INSPECTED SITE AND FOUND 5TH TANK EXPOSED, NO PRODUCT ON GW. TANK TO BE EXCAVATED OUT NEXT WEEK. 11/13/96: JDC TELCON W/ BOB HILLS, 5TH TANK REMOVED A SINGLE LOAD OF CONTAMIATED SOILS REMAIN FOR DISPOSAL. SOIL TEST COMPLETE. NEED COPY OF DISPOSAL DOCUMENTS AND LAB WORK TO CLOSE FILE. 11/20/96: JDC ON SITE AND FOUND EXCAVATION BACKFILLED. NEED FINAL DISPOSAL AND POST TEST RESULTS. 12/10/96: JDC ON SITE AND CONFIRMED TANKS AND CONTAMINATED SOILS WERE REMOVED. WILL SEND LETTER REQUESTING DISPOSAL INFORMATION. 12/16/96:

BOB HILLS OLD GAS STATION (Continued) **S103238653**

JDC TELCON BOB HILLS, HE WILL FORWARD COPIES OF DISPOSAL RECEIPTS AND POST TESTING. 12/19/96: JDC ON SITE AND FOUND RESULTS SATISFACTORY. NEED DISPOSAL RECEIPTS TO CLOSE. 12/31/96: JDC RECEIVED DISPOSAL RECEIPTS AND FOUND COMPLETE, NO FURTHER ACTION REQUIRED SITE IS INACTIVE DUE TO MINOR LEVELS OF CONTAMINATION FOUND IN TANK PIT SAMPLE RESULTS."

Remarks: "TWO ABANDONED TANKS. CONTAMINATION IN BACKFILL OF ONE OF THE TANKS NEAR THE FILL PIPE."

All Materials:

Site ID:	304933
Operable Unit ID:	1039407
Operable Unit:	01
Material ID:	344097
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	9608691 / 1996-10-15
Facility ID:	9608691
Site ID:	304934
Spill Date:	1996-10-12
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	1564
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	1996-10-12
CID:	257
Water Affected:	Not reported
Spill Notifier:	Citizen
Last Inspection:	1996-10-12
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1996-10-12
Spill Record Last Update:	1996-10-18
Spiller Name:	Not reported
Spiller Company:	BOB HILLS
Spiller Address:	5150 BANK STREET
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	9
DER Facility ID:	246316
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 10/12/96 RMC/HILLS/SITE PROPERTY OWNER REMOVING OWN TANKS, A JDC SITE, RP PUMPED TANK AND PIT WATER TO LAND WHICH ENTERED STORM SEWER

BOB HILLS OLD GAS STATION (Continued) **S103238653**

SYSTEM 50 FEET NORTH OF PROPERTY, SHEEN ON SURFACE OF WATER LEADING TO STORM SEWER, RP ADVISED HE GOT NO READING ON CG INDICATOR METER, RMC ADVISED THAT CG INDICATOR METER NOT PROPER FOR DETERMINING CONTAMINATION IN SOIL OR WATER AS IT IS A HEALTH AND SAFETY TOOL ONLY,RMC ADVISED TO NOT PUMP ANY MORE WATER OFF SITE UNLESS TESTED AND MEETS NYS GW STANDARDS, ESTIMATE TWO LOADS SOIL REMOVED, MORE NEEDS REMOVAL BEFORE TESTING, VERY STRONG GASOLINE ODOR IN SOILS REMOVED, TWO TANKS REMOVED, ONE TANK REMAINS TO BE REMOVED, CLOSE OUT AS DUPLICATE OF 9608361"

Remarks: "caller says there is a old gas station and owner is today removing tanks and the hole area smeels of gas"

All Materials:

Site ID:	304934
Operable Unit ID:	1036907
Operable Unit:	01
Material ID:	344418
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	9713199 / 1998-03-16
Facility ID:	9713199
Site ID:	304935
Spill Date:	1998-02-25
Spill Cause:	Tank Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	1564
Investigator:	COOKE
Referred To:	Not reported
Reported to Dept:	1998-02-25
CID:	999
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	1998-02-25
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1998-02-26
Spill Record Last Update:	1998-05-05
Spiller Name:	JOHN PUZAN
Spiller Company:	NYSDOT
Spiller Address:	125 MAIN STREET
Spiller County:	001
Spiller Contact:	BOB HILLS
Spiller Phone:	(716) 259-2454
Spiller Extention:	Not reported
DEC Region:	9
DER Facility ID:	246316

BOB HILLS OLD GAS STATION (Continued) **S103238653**

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was JDC 2/25/98: JDC ON SITE AND FOUND SOILS REMOVED FROM UTILITY TRENCH. BEING STOCKPILED FOR DISPOSAL BY NYSDOT. ADVISED MR PUZAN, NYSDOT OF PAST ACTIVITIES ON SITE UNDER SPILL NUMBER 9608361. WILL SEND LETTER REQUESTING DISPOSAL. INSPECTED TRENCH AND DETECTED NO CONTAMINATION. 3/16/98: RECEIVED AND FOUND DISPOSAL AND ANALITICAL INFORMATION SATISFACTORY. NO FURTHER ACTION REQUIRED, SITE CLOSED."

Remarks: "URS CONSULTANTS HIRED TO LOCATE CONTAMINATION FOUND IN SOIL @ 240 NIAGRA FALLS BLVD IN TRENCH FOR NEW WATERLINE. PID LEVELS @ 230 PPM."

All Materials:

Site ID:	304935
Operable Unit ID:	1056127
Operable Unit:	01
Material ID:	324222
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

L111 **FIRESTONE STORES** **NY Spills** **1009232252**
East **995 NIAGARA FALLS BLVD** **NY MANIFEST** **N/A**
< 1/8 **AMHERST, NY 14226**
0.020 mi.
103 ft. **Site 4 of 6 in cluster L**

Actual:
597 ft.

Focus Map:
6

SPILLS:

Spill Number/Closed Date:	0375288 / 2003-11-06
Facility ID:	0375288
Facility Type:	ER
DER Facility ID:	274517
Site ID:	126415
DEC Region:	9
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	1500
Spill Date:	2003-09-09
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	2003-09-09
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	2003-10-23
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-09-09
Spill Record Last Update:	2003-11-06
Spiller Name:	BERNARD KIEFFER

FIRESTONE STORES (Continued) **1009232252**

Spiller Company: PETROLEUM SALES
Spiller Address: 300 OHIO
Spiller Company: 001
Contact Name: BERNARD KIEFFER
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 09/21/03 RMC/FILE. SUB SURFACE INVESTIGATION REPORT DUE 11/30/03 09/24/03 RMC/PETER GORTON/PHONE. THEY HAVE BEEN HIRED BY THE BUYER AND SELLER TO PREPARE SITE FOR TRANSFER. REPORTS DUE 11/30/03. THEY MAY GO RIGHT TO REMOVAL. UPDATE 11/30/03 10/01/03 RMC/PETER GORTON/PHONE. HE WILL SEND OVER BORING LOCATION MAP AND SKETCH WHERE THEY THINK REMOVAL IS NECESSARY. THEY PLAN ON STARTING NEXT WEEK. HE WILL BE ON SITE WITH METER TO GUIDE EXCAVATIONS. UPDATE 10/30/03 10/01/03 RMC/FILE. RECEIVED SITE PLAN WITH AREA PLANNED FOR EXCAVATION DETAILED. UPDATE 10/30/03 10/16/03 RMC/SITE. EXCAVATING CONTAMINATED SOILS. TO REMOVE ALL CAN SEE AND SMELL THEN TEST ALL WALLS AND BOTTOM FOR STARS. 10/20/03 RMC/SITE. FOUND UST, TO REMOVE. 10/21/03 RMC/SITE. REMOVED ONE UST, FOUND ANOTHER NEAR 8 INCH NATURAL GAS LINE ALONG NFB. 10/21/03 RMC/PAN AMERICAN/PHONE. REMOVED SECOND UST FOUND THIRD UNDER THE 8 INCH NATURAL GAS LINE. RMC ADVISED THAT IF IT CAN'T BE REMOVED. IT MUST BE CUT, CLEANED, AND FILLED TO CONSIDER CLOSURE. ADVISED SAC. UPDATE 10/30/03 10/23/03 RMC/SITE. REMOVED A TOTAL OF THREE USTS SO FAR. NATURAL GAS LINE WAS NOT WHERE IT WAS MARKED AND WAS NEVER FOUND. EXCAVATED TO THE ROW ALONG NFB. REPORT DUE 11/30/03 11/05/03 RMC/FILE. RECEIVED REPORT. A 3K,2K,AND 1K UST WERE REMOVED ALONG WITH 6500 GALLONS CONTAMINATED WATER AND 1373 TONS CONTAMINATED SOIL. PETROLEM IMPACTED SOILS OBSERVED TO REMAIN ALONG NFB ROW. MATERIAL IS NOT ACCESSIBLE. PHASE ONES, REFERRED TO IN THE REPORT, DONE OVER THE YEARS NOT SUBMITTED FOR REVIEW. ALL SAMPLES TAKEN MEET TAGM. DISPOSAL NOT DOCUMENTED FOR WATER, CONTACTED PEI LEFT MESSAGE REQUESTING. DUE 12/30/03 11/06/03 RMC/FILE. RECEIVED DISPOSAL DOCUMENTS FOR CONTAMINATED WATER REMOVED. NO FURTHER ACTION AT THIS TIME, LETTER, INACTIVE. "
Remarks: "contamination noted on a test pit survey. geoprobe study will be done."

All Materials:
Site ID: 126415
Operable Unit ID: 884145
Operable Unit: 01
Material ID: 494481
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

NY MANIFEST:
Country: USA
EPA ID: NYP000863829
Facility Status: Not reported
Location Address 1: 995 NIAGARA FALLS BLVD
Code: BP
Location Address 2: Not reported

FIRESTONE STORES (Continued) **1009232252**

Total Tanks:	Not reported
Location City:	AMHERST
Location State:	NY
Location Zip:	14226
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP000863829
Mailing Name:	FIRESTONE STORES
Mailing Contact:	FIRESTONE STORES
Mailing Address 1:	995 NIAGARA FALLS BLVD
Mailing Address 2:	Not reported
Mailing City:	AMHERST
Mailing State:	NY
Mailing Zip:	14226
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7168379700

NY MANIFEST:

Document ID:	NYA4079946
Manifest Status:	K
seq:	Not reported
Year:	1986
Trans1 State ID:	NEWYORK
Trans2 State ID:	3052-MP
Generator Ship Date:	12/10/1986
Trans1 Recv Date:	12/10/1986
Trans2 Recv Date:	/ /
TSD Site Recv Date:	12/15/1986
Part A Recv Date:	03/02/1987
Part B Recv Date:	12/26/1986
Generator EPA ID:	NYP000863829
Trans1 EPA ID:	NYD041037441
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD043815703
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00685
Units:	G - Gallons (liquids only)* (8.3 pounds)

FIRESTONE STORES (Continued) **1009232252**

Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

L112 **FIRESTONE COMPLETE AUTO CARE #001570** **NY AST** **U003400033**
East **995 NIAGARA FALLS BOULEVARD** **N/A**
< 1/8 **AMHERST, NY 14226**
0.020 mi.
103 ft. **Site 5 of 6 in cluster L**

Actual:
597 ft.

Focus Map:
6

AST:
Region: STATE
DEC Region: 9
Site Status: Active
Facility Id: 9-600303
Program Type: PBS
UTM X: 188335.15344
UTM Y: 4765814.40388
Expiration Date: 05/13/2022
Site Type: Auto Service/Repair (No Gasoline Sales)

Affiliation Records:
Site Id: 55161
Affiliation Type: Facility Owner
Company Name: FC AMHERST LLC
Contact Type: ENVIRONMENTAL MANAGER
Contact Name: DEBRA HAMLIN
Address1: 47-09 30TH STREET, SUITE 600
Address2: Not reported
City: LONG ISLAND
State: NY
Zip Code: 11101
Country Code: 001
Phone: (212) 586-8800
EMail: Not reported
Fax Number: Not reported
Modified By: AESKALSK
Date Last Modified: 2018-01-23

Site Id: 55161
Affiliation Type: Mail Contact
Company Name: BRIDGESTONE RETAIL OPERATIONS LLC
Contact Type: Not reported
Contact Name: DEBRA HAMLIN
Address1: 200 4TH AVE SOUTH
Address2: ATTN: ENVIRONMENTAL DEPT - BSRO
City: NASHVILLE
State: TN
Zip Code: 37201
Country Code: 001
Phone: (615) 937-9379
EMail: ENVGEN@BFRC.COM
Fax Number: Not reported

FIRESTONE COMPLETE AUTO CARE #001570 (Continued) **U003400033**

Modified By: AESKALSK
Date Last Modified: 2018-01-25

Site Id: 55161
Affiliation Type: Facility Operator
Company Name: FIRESTONE COMPLETE AUTO CARE #001570
Contact Type: Not reported
Contact Name: DAVID BOFFEY
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (716) 837-9700
EMail: Not reported
Fax Number: Not reported
Modified By: AESKALSK
Date Last Modified: 2018-01-23

Site Id: 55161
Affiliation Type: Emergency Contact
Company Name: FC AMHERST LLC
Contact Type: Not reported
Contact Name: DAVID BOFFEY
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (716) 837-9700
EMail: Not reported
Fax Number: Not reported
Modified By: AESKALSK
Date Last Modified: 2017-05-12

Tank Info:

Tank Number: 1
Tank Id: 172336
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Equipment Records:

F00 - Pipe External Protection - None
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
K00 - Spill Prevention - None
G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)
I03 - Overfill - Automatic Shut-Off
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)

FIRESTONE COMPLETE AUTO CARE #001570 (Continued) **U003400033**

C01 - Pipe Location - Aboveground
D11 - Pipe Type - Flexible Piping
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	05/05/2006
Capacity Gallons:	300
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	AESKALSK
Last Modified:	01/23/2018
Material Name:	waste oil/used oil

L113 **BRIDGESTONE FIRESTONE** **RCRA NonGen / NLR** **1000789440**
East **995 NIAGARA FALLS BLVD** **FINDS** **NYD987009016**
< 1/8 **AMHERST, NY 14226** **ECHO**
0.020 mi.
103 ft. **Site 6 of 6 in cluster L**

Actual:
597 ft.

Focus Map:
6

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	BRIDGESTONE FIRESTONE
Facility address:	995 NIAGARA FALLS BLVD AMHERST, NY 14226-1101
EPA ID:	NYD987009016
Mailing address:	RTE 9 SUITE 411 WOODBRIDGE, NY 07095
Contact:	Not reported
Contact address:	RTE 9 SUITE 411 WOODBRIDGE, NY 07095
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	BRIDGESTONE
Owner/operator address:	900 RTE 9 SUITE 411 WOODBRIDGE, NJ 07095
Owner/operator country:	US
Owner/operator telephone:	908-855-1900
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	BRIDGESTONE

BRIDGESTONE FIRESTONE (Continued) **1000789440**

Owner/operator address: 900 RTE 9 SUITE 411
WOODBRIDGE, NJ 07095
Owner/operator country: US
Owner/operator telephone: 908-855-1900
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: BRIDGESTONE FIRESTONE
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: BRIDGESTONE FIRESTONE
Classification: Not a generator, verified

Date form received by agency: 07/14/1992
Site name: BRIDGESTONE FIRESTONE
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D008
. Waste name: LEAD

. Waste code: D018
. Waste name: BENZENE

BRIDGESTONE FIRESTONE (Continued) **1000789440**

Violation Status: No violations found

FINDS:

Registry ID: 110004492718

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000789440
Registry ID: 110004492718
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004492718

AB114 **A F AUTOMOTIVE** **RCRA NonGen / NLR** **1000447102**
East **733 NIAGARA FALLS BLVD** **FINDS** **NYD986912830**
< 1/8 **AMHERST, NY 14226** **ECHO**
0.020 mi. **NY MANIFEST**
104 ft. **Site 1 of 4 in cluster AB**

Actual:
600 ft.

Focus Map:
6

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: A F AUTOMOTIVE
Facility address: 733 NIAGARA FALLS BLVD
AMHERST, NY 14226
EPA ID: NYD986912830
Mailing address: NIAGARA FALLS BLVD
AMHERST, NY 14226
Contact: Not reported
Contact address: NIAGARA FALLS BLVD
AMHERST, NY 14226
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: VINCENT SCAMMURRA
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private

A F AUTOMOTIVE (Continued) **1000447102**

Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: VINCENT SCAMMURRA
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: A F AUTOMOTIVE
Classification: Not a generator, verified

Date form received by agency: 03/21/1995
Site name: A F AUTOMOTIVE
Classification: Unverified

. Waste code: NONE
. Waste name: None

Date form received by agency: 09/14/1990
Site name: A F AUTOMOTIVE
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE

A F AUTOMOTIVE (Continued) **1000447102**

MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Violation Status: No violations found

FINDS:

Registry ID: 110004452814

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000447102
Registry ID:	110004452814
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004452814

NY MANIFEST:

Country:	USA
EPA ID:	NYD986912830
Facility Status:	Not reported
Location Address 1:	733 NIAGARA FALLS BOULEVARD
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	AMHERST
Location State:	NY
Location Zip:	14226
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD986912830
Mailing Name:	A F AUTOMOTIVE
Mailing Contact:	ALVIN FABRY
Mailing Address 1:	733 NIAGARA FALLS BOULEVARD
Mailing Address 2:	Not reported
Mailing City:	AMHERST
Mailing State:	NY
Mailing Zip:	14226
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7168330228

NY MANIFEST:

Document ID:	NYB1610343
Manifest Status:	C
seq:	Not reported
Year:	1990

A F AUTOMOTIVE (Continued) **1000447102**

Trans1 State ID:	LN7808
Trans2 State ID:	Not reported
Generator Ship Date:	09/10/1990
Trans1 Recv Date:	09/10/1990
Trans2 Recv Date:	/ /
TSD Site Recv Date:	09/10/1990
Part A Recv Date:	10/05/1990
Part B Recv Date:	10/01/1990
Generator EPA ID:	NYD986912830
Trans1 EPA ID:	NYD981876006
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD043815703
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00220
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AB115 **AMERICAN AUTO WORLD** **EDR Hist Auto** **1020611820**
East **733 NIAGARA FALLS BLVD** **N/A**
< 1/8 **AMHERST, NY 14226**
0.020 mi.
104 ft. **Site 2 of 4 in cluster AB**

Actual: EDR Hist Auto
600 ft.

Focus Map:
6

Year:	Name:	Type:
1969	LINCOLN PARK SERVICE STATION	Gasoline Service Stations
1970	LINCOLN PARK SERVICE STATION	Gasoline Service Stations
1971	LINCOLN PARK SERVICE STATION	Gasoline Service Stations
1974	NAPIERALA ROBERT J	Automotive Services, NEC
1975	NAPIERALA ROBERT J	Automotive Services, NEC
1985	A F AUTOMOTIVE	General Automotive Repair Shops
1986	A F AUTOMOTIVE	General Automotive Repair Shops

AMERICAN AUTO WORLD (Continued) **1020611820**

1987	A F AUTOMOTIVE	General Automotive Repair Shops
1988	A F AUTOMOTIVE	General Automotive Repair Shops
1989	A F AUTOMOTIVE	General Automotive Repair Shops
1990	A F AUTOMOTIVE	General Automotive Repair Shops
1991	A F AUTOMOTIVE	General Automotive Repair Shops
1992	A F AUTOMOTIVE	General Automotive Repair Shops
1993	FABRY ALVIN	Engine Repair
1994	FABRY ALVIN	Engine Repair
1995	FABRY ALVIN	Engine Repair
1996	FABRY ALVIN	Engine Repair
1997	FABRY ALVIN	Engine Repair
1998	FABRY ALVIN INC	Engine Repair
1999	FABRY ALVIN INC	Engine Repair
2000	FABRY ALVIN INC	Engine Repair
2001	FABRY ALVIN INC	Engine Repair
2002	FABRY ALVIN INC	Engine Repair
2002	A H F AUTOMOTIVE INC	General Automotive Repair Shops
2003	FABRY ALVIN INC	Engine Repair
2003	A H F AUTOMOTIVE INC	General Automotive Repair Shops
2004	FABRY ALVIN INC	Engine Repair
2004	A H F AUTOMOTIVE INC	General Automotive Repair Shops
2006	AMERICAN AUTO WORLD	General Automotive Repair Shops
2007	AMERICAN AUTO WORLD	General Automotive Repair Shops
2008	AMERICAN AUTO WORLD	General Automotive Repair Shops
2009	AMERICAN AUTO WORLD	General Automotive Repair Shops
2010	AMERICAN AUTO WORLD	General Automotive Repair Shops
2010	AHF AUTOMOTIVE INCORPORATED	General Automotive Repair Shops
2011	AHF AUTOMOTIVE INCORPORATED	General Automotive Repair Shops
2011	AMERICAN AUTO WORLD	General Automotive Repair Shops
2012	AMERICAN AUTO WORLD	General Automotive Repair Shops
2012	AHF AUTOMOTIVE INCORPORATED	General Automotive Repair Shops
2013	AMERICAN AUTO WORLD	General Automotive Repair Shops
2014	AMERICAN AUTO WORLD	General Automotive Repair Shops

AB116 **A&F AUTOMOTIVE** **NY UST** **U004045840**
East **733 NIAGARA FALLS BLVD** **N/A**
< 1/8 **AMHERST, NY 14226**
0.020 mi.
104 ft. **Site 3 of 4 in cluster AB**

Actual:
600 ft.

Focus Map:
6

UST:

Id/Status:	9-600729 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	9
Expiration Date:	N/A
UTM X:	188265.36057
UTM Y:	4765013.49737
Site Type:	Other Wholesale/Retail Sales

Affiliation Records:

Site Id:	337425
Affiliation Type:	Facility Owner
Company Name:	A&F AUTOMOTIVE
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	733 NIAGARA FALLS BLVD
Address2:	Not reported

A&F AUTOMOTIVE (Continued) **U004045840**

City: AMHERST
State: NY
Zip Code: 14228
Country Code: 001
Phone: Not reported
EMail: Not reported
Fax Number: Not reported
Modified By: AESKALSK
Date Last Modified: 2005-02-11

Site Id: 337425
Affiliation Type: Mail Contact
Company Name: A&F AUTOMOTIVE
Contact Type: Not reported
Contact Name: Not reported
Address1: 733 NIAGARA FALLS BLVD
Address2: Not reported
City: AMHERST
State: NY
Zip Code: 14228
Country Code: 001
Phone: Not reported
EMail: Not reported
Fax Number: Not reported
Modified By: AESKALSK
Date Last Modified: 2005-02-11

Site Id: 337425
Affiliation Type: Facility Operator
Company Name: A&F AUTOMOTIVE
Contact Type: Not reported
Contact Name: A&F AUTOMOTIVE
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: Not reported
EMail: Not reported
Fax Number: Not reported
Modified By: AESKALSK
Date Last Modified: 2005-02-11

Tank Info:

Tank Number: 1
Tank ID: 181978
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 5000
Install Date: Not reported
Date Tank Closed: 07/14/1986
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009

A&F AUTOMOTIVE (Continued) **U004045840**

Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: AESKALSK
Last Modified: 04/14/2017

Tank Number: 2
Tank ID: 181979
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 5000
Install Date: Not reported
Date Tank Closed: 07/14/1986
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: AESKALSK
Last Modified: 04/14/2017

Tank Number: 3
Tank ID: 181980
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 6000
Install Date: Not reported
Date Tank Closed: 07/14/1986
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: AESKALSK
Last Modified: 04/14/2017

AB117 **AF AUTOMOTIVE** **NY Spills** **S106866955**
East **733 NIAGARA FALLS BLVD** **N/A**
< 1/8 **AMHERST, NY 14226**
0.020 mi.
104 ft. **Site 4 of 4 in cluster AB**

Actual:
600 ft.

Focus Map:
6

SPILLS:

Spill Number/Closed Date:	0485611 / 2014-01-16
Facility ID:	0485611
Facility Type:	ER
DER Facility ID:	273539
Site ID:	338209
DEC Region:	9
Spill Cause:	Unknown
Spill Class:	B2
SWIS:	1522
Spill Date:	2005-03-03
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	2005-03-03
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	2013-05-16
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-03-03
Spill Record Last Update:	2014-01-16
Spiller Name:	ALVIN FABRY
Spiller Company:	AF AUTOMOTIVE
Spiller Address:	733 NIAGARA FALLS BLVD
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"03/03/05 RMC/FILE. RECEIVED RESULTS, ABOVE TAGM, ADDITIONAL ASSESSMENT AND REMEDIATION REQUIRED. CHECKED ASSESSOR, PRP LETTER TO OWNER OF LAND AND BUSINESS ON SITE. RESPONSE DUE 3/30/05. 03/08/05 RMC/JIM ALLEN, ATTORNEY FOR PROPERTY OWNERS, 884-5600/PHONE. HE IS CONCERNED THAT THE OWNERS DID NOT RECEIVE A COPY OF THE RESULTS. HE STATED THAT THE ALLENS PAID TO HAVE THE USTS REMOVED IN THE 80'S. RMC TO FAX A COPY OF THE RESULTS AND SPILL FILE TO HIM. RMC AGREED SIT DOWN WITH THE OWNERS AND TO EXTEND THE RESPONSE DATE TO 4/30/05. 04/15/05 RMC/JIM ALLEN/PHONE. DISCUSSED RESULTS. AT ALLENS REQUEST RMC LOCATED 1986 LETTER TO THE DEPARTMENT FROM FLEISCHMANN SERVICE. THIS WAS A SIMPLE NOTIFICATION THAT THREE UST WERE REMOVED. UPDATE 4/30/05. 05/09/05 RMC/JIM ALLEN/FILE. OWNER NEVER USED USTS, PRP HAS HIRED ANOTHER CONSULTANT, HE WILL HAVE A RESPONSE BY 5/30/05. 07/08/2005 RMC/JIM ALLEN/PHONE. HAS HAD PHASE ONE DONE BY PETER GORTON, SUN OIL COMPANY HAS OWNED FOR MANY YEARS, THEN HAD LEASED, AND THEN SOLD THE STATION. HE PLANS ON EXPLORING CLEANUP BY OTHER PARTIES. HE WILL SEND PHASE ONE AND LETTER REQUESTING THREE MONTHS WORK ON OTHER PRPS. UPDATE 10/30/05 08/05/05 RMC/FILE. RECEIVED LETTER REQUESTING 4 MONTHS TO WORK WITH PRPS AND DO AN ASSESSMENT. RMC AGREED AND CONFIRMED WITH MR. ALLEN ON 8/8. UPDATE 11/30/05. 12/28/05 RMC/FILE. LEFT MESSAGE FOR JIM ALLEN, CALL DUE 12/30/05. 01/17/06 RMC/FILE. CALLED JIM ALLEN. LEFT MESSAGE. CALL DUE 1/24/06.

AF AUTOMOTIVE (Continued) **S106866955**

01/23/06 RMC/FILE. RETURNED JIM ALLENS CALL. HIS CLIENT HAS AN OFFER MAYBE, THEY ARE ALSO LOOKING AT SUN OIL. THEY HAVE CONTACTED SLATER FOR ADVICE. UPDATE 2/23/06. 03/01/06 RMC/FILE. LEFT MESSAGE FOR PRP's ATTORNEY TO CALL. CALL DUE 3/10/06. 03/02/06 RMC/JIM ALLEN/PHONE. OWNER IN STILL WORKING TO SELL THE PROPERTY AS IS. HE WILL ATTEMPT TO GET SUN TO DO THE WORK IF HE CAN'T MARKET IT SOON. UPDATE 5/1/06. 04/28/06 RMC/FILE. RECEIVED LETTER FROM PRP ATTORNY ADVISING THAT PROPERTY HAS BEEN SOLD. RMC CHECKED WITH THE ASSESSOR, TRANSFER YET TO SHOW ON THEIR COMPUTER. RMC TO CHECK AGAIN IN A FEW WEEKS. UPDATE 5/30/06. 05/26/06 RMC/FILE. CHECKED OWNERSHIP. STILL HAS NOT CHANGED. CALL AGAIN 6/30/06. 06/19/06 RMC/FILE. CHECKED ASSESSOR. NO CHANGE YET. CONTACTED JIM ALLEN TO OBTAIN CONTACT INFORMATION. SENT PRP LETTER. RESPONSE DUE 7/14/06. 07/24/06 RMC/FILE. RECEIVED MESSAGE FROM AND LETTER FROM PRP ATTORNEY ANGELA DEMERLE. PRP PLANS ON ATTEMPTING TO GET SUN INVOLVED, UPDATE 10/30/06. 12/15/06 RMC/FILE. RECEIVED LETTER FROM PRP ATTORNEY, WANTS ANOTHER 90 DAYS. REPORT DUE 3/30/07. 07/26/07 RMC/FILE. LEFT MESSAGE FOR ANGELA DEMERLE. UPDATE 8/1/07. 07/27/07 RMC/FILE. RECEIVED MESSAGE BACK FROM ANGELA DEMERLE. SHE WILL ADVISE HER CLIENT THAT THEY NEED TO GET MOVING AS SHE HAS BEEN UNABLE TO GET A RESPONSE FROM SUN, UPDATE 8/15/07. 01/10/08 RMC/ANGELA DEMERLE, HSE, 845-4222/PHONE. AFTER DATING CONTAMINATION AND DISCUSSIONS SHE WAS UNABLE TO BRING SUNOCO ON BOARD, SHE ADVISED HE CLIENTS OF THIS PAST FALL. RMC SENT LETTER REQUESTING WORK PLAN AND SCHEDULE BY 2/15/08. 02/11/08 RMC/GILL HARDEEP? 716-400-1684/PHONE. PARTNER WILL BE BACK IN COUNTRY IN MARCH. WILL SEND PLAN IN BY 4/15/08. 08/04/08 RMC/FILE. NO RESPONSE LETTER. RESPONSE DUE 8/16/08. 08/14/08 RMC/Dan Randhewa, 716-400-1680/PHONE. HE IS GETTING PLANS AND PRICES FROM NWECC, GES, AND AFI. PLAN DUE 9/15/08 10/23/08 RMC/FILE. CONTACTED DAN RANDHEWA, REQUESTED RAP AND SCHEDULE WITH IN TWO WEEKS, DUE 11/15/08. 01/09/09 RMC/FILE. CONTACTED DAN RANDHEWA, HE CLAIMS TO BE CLOSE TO HIRING ROJ CHOPRA. RMC ADVISED RAP AND SHORT SCHEDULE IN WEEK OR SPILLS WILL SEND TO LEGAL. UPDATE 1/16/09. 01/15/09 RMC/ROJ CHOPRA/PHONE. HE WILL SUBMIT A PLAN, DUE 1/16/09. 04/02/09 RMC/FILE. REVIEWED PLAN RECEIVED 3/31/09. RAP IS TO INSTALL 6 INJECTION WELLS. SAMPLE AFTER 16 WEEKS. RMC CONTACTED RAJ CHOPRA AND ADVISED RMC HAS NOT SEEN RESULTS WITH SOIL TYPES IN THIS AREA. RMC ADVISED THAT THEY ARE WELCOME TO ATTEMPT THIS METHOD BUT RMC BELIEVES IT WILL ONLY COST MONEY AND DELAY THE NEED TO REMOVED SOURCE SOILS. HE WILL ADVISE HIS CLIENT OF RMC'S CONCERNS. UPDATE 5/1/09. 06/05/09 RMC/DAN RANDHEWA/PHONE. NO WORK HAS BEEN DONE. HE WILL CONTACT HIS CONTACTOR. UPDATE 6/10/09 06/17/09 RMC/FILE. RECEIVED FAX THAT INJECTION WELLS WILL BE INSTALLED WEEK OF 6/15TH. 06/17/09 RMC/SITE. WELLS BEING INSTALLED. UPDATE 7/30/09. 09/09/09 RMC/FILE NO REPORT RECEIVED LEFT MESSAGE FOR DAN RANDHEWA. UPDATE 9/30/09. 11/19/09 RMC/FILE. NO REPORT RECEIVED LEFT MESSAGE FOR DAN REANDHEWA, CALL DUE 11/25/09. 12/29/09 RMC/FILE. NO REPORT RECEIVED CALLED DAN REANDHEWA. HE WILL AGAIN CONTACT CONTRACTOR FOR THE REPORT. DUE 1/7/10. 01/11/10 RMC/FILE. RECIVED MESSAGE TO CALL RAJ CHOPRA, 716-480-2125. RETURNED MESSAGE ADVISING THAT REPORT WAS OVERDUE. 02/04/10 RMC/FILE. NO RESPONSE. CALLED ROJ CHOPRA. PREOXIDE WAS NOT PUT IN AS THEY FAILED TO BE ABLE TO NEGOTIATE A DEAL IN TIME. RMC REQUESTED THE WELLS BE SAMPLED ASAP. DUE 2/28/10 03/03/10 RMC/FILE. NO GW REPORT LETTER. RESPONSE DUE 3/15/10. 03/17/10 RMC/FILE. RECEVED GW SAMPLE RESULTS SIGNIFICANT EXCEECANCES IN WELL PREVIOUS SIGNIFICANT SOIL EXCEEDANCES IN SOIL OVER MAJORITY OF THE NORTH AND WEST SIDES. NOTE THAT REMEDIATION OPTIONS ARE BEING LOOKED AT. THEY HAVE YET TO IMPLEMENT THE 3/09 PLAN AGREED UPON. RMC LEFT

AF AUTOMOTIVE (Continued) **S106866955**

MESSAGE FOR RAJ CHOPRA AND DISCUSSED WITH DAN RANDHEWA THAT RAP IMPLEMENTATION OVER DUE. WORK STARTED OR LEGAL BY 3/30/10. 05/03/10 RMC/ROJ CHOPRA/PHONE. ORC WAS PUT IN ABOUT 4/1/10. DID NOT CALL AND ADVISED OF WORK WILL SAMPLE AGAIN AT THE END OF THE MONTH. REPORT DUE 7/30/10. 05/18/11 RMC/FILE. NO RESPONSE FROM CALLS TO OWNERS OR CONSULTANT. CALLED ROJ CHOPRA, HE HAS NOT BEEN AUTHORIZED TO DO FURTHER WORK. CALLED ASSESSOR, NOW NAMED 733 NIAGARA FALLS BOULVARD INC, AT 71 SWANSON TERRACE WILLIAMSVILLE NY. CALLED DAN RANDEHAWA, HE ADVISED HE STILL OWNS THE PROPERTY. RMC ADVISED THAT DEC HAS MADE NUMEROUS ATTEMPTS TO GET REPORT AND FAILURE SUPPLY REPORT IN 10 DAYS WILL RESULT IN LEGAL REFERRAL. 05/27/11 RMC/SITE. 6 DRUMS CUTTINGS AND/OR PURGE WATER REMAIN ON SITE. WELLS APPEAR TO HAVE NOT BEEN OPENED FOR SAMPLING IN A LONG TIME. 06/02/11 RMC/FILE. DRAFED LEGAL REFERRAL. 10/20/11 GPS: DISCUSSED WITH OGC ATTORNEY. SENT LETTER & ORDER TO RP IN AUGUST. RESPONDENT CONTACTED OGC IN SEPTEMBER AND WAS TOLD ATHONY PARLATO WAS REPRESENTING THEM. OGC TALKED TO PARLETO ON OCT 12TH AND WAS TOLD HE WOULD NEED TO DISCUSS WITH CLIENT AND CONTRACTOR. WAITING FOR RESPONSE BACK. 01/13/12 RMC/FILE. TALED WITH JIM ALLEN, PREVIOUS OWNERS ATTORNEY, HE AGAIN ADVISED THAT PROPERTY WAS SOLD AND CONTAMINATION WAS FULLY DISCLOSED. THE PROPERTY WAS DISCOUNTED BECAUSE OF THE CONTAMINATION. ADVISED DAVE STEVER. 02/02/12 RMC/DAVE STEVER/MEETING. NO CHANGE. UPDATE 6/1/12. 04/19/12 RMC/SITE. NO CHANGE FROM LAST VISIT, 5/27/11. 6 DRUMS ON SITE. ONE TIPPED OVER. 04/21/12 RMC/FILE. HAD HEARING WITH PRPS, STEVER, AND ALJ. RMC WAS PROVIDED SAMPLE ROUND OF THREE WELLS, LOCATIONS NOT GIVEN. RESULTS STILL IN THE ORDER OF 500 TO 5000 TIMES THE GW STANDARDS. NO SOIL ANALYSIS PROVIDED. RMC AGAIN ADVISED THAT PEROXIDE INJECTIONS, UNDER THE PROGRAM PROPOSED, HAVE LITTLE CHANCE OF DECONTAMINATING THE SITE. DISCUSSED OPTIONS. PRPS TO GET AN ATTORNEY, HAVE CONSULTANT CONTACT RMC FOR DISCUSSION ON REMIDIAL NEEDS, AND MEET BACK AGAIN 6/14/12. 03/05/13 RMC/FILE. RECEIVED SIGNED ROE FROM LEGAL. 03/12/13 RMC/FILE DISCUSSED SITE W/GS WHO DISCUSSED WITH ALBANY. TO USE SPILL FUND MONEY AND EMPIRE GEO. 03/13/13 RMC/FILE. DID PIN PAPER WORK, E-DOCED FILE SENT ELECTRONIC COPY TO EMPIRE GEO. 03/15/13 RMC/FILE. TALKED WITH DAVE STEINER, EMPIRE. THEY ARE PLANNING ON PROBING 3/20 FOR DISPOSAL SAMPLES. CALLED DANNY AT 400-1680 AND ADVISED. HE IS PLANNING ON BEING ON SITE ANYWAY THAT DAY. 03/29/13 RMC/FILE. RECEIVED DISPOSAL SAMPLE RESULTS. ALL NON HAZ. 05/03/13 RMC/FILE. CONTRACTOR STARTING PROJECT TODAY. 05/06/13 RMC/SITE. EXCAVATING FOR THE SECOND DAY. 4 TRUCKS ON TODAY. FINDING STRONG CONTAMINATION. SOME 3 INCH PRODUCT PIPES. 05/15/13 RMC/FILE INSPECTED SITE SEVERAL TIMES THIS AND LAST WEEK. EXCAVATION CONTINUES. FINDING CONTAMINATION AS EXPECTED. EXCAVATION SHOULD END TOMORROW. 05/16/13 RMC/SITE. EXCAVATION WORK COMPLETED. HAVE EXCAVATED ALL ACCESSIBLE IMPACTED SOILS KNOWN. STONE AND GRADING TO BE COMPLETED BY TOMORROW. REPORT DUE 6/30/13. 01/16/14 RMC/FILE. RECEIVED EMPIRE GEO REMEDIAL REPORT DATED 09/20/13. EXCAVATED ALL 2128 TONS IMPACTED SOIL. CONTAMINATED SOIL, NOT ACCESSIBLE, WAS LEFT BEHIND AROUND THE BUILDING, ALONG NIAGARA FALLS BLVD, AND AT UTILITIES. 20 POST EXCAVATION SIDEWALL SAMPLES TAKEN WITH SIX SHOWING CP51 EXCEEDANCES. 8 BOTTOM SAMPLES TAKEN WITH NO CP51 EXCEEDANCE. THE SAMPLE EXCEEDANCES ARE MINOR EXCEPT AT SAMPLES W4 ALONG THE BUILDINGS NORTH SIDE AND W16 ADJACENT TO UTILITIES AND NIAGARA FALLS BLVD. SITE TO HAVE NO FURTHER ACTION AT THIS TIME. LETTER, ISR DRAFTED, INACTIVE. "

Remarks: "FOUND PETROLEUM CONTAMINATION WHILE DOING GEOPROBE FOR POTENTIAL SALE, RESULTS WILL BE FAXED OVER."

AF AUTOMOTIVE (Continued) **S106866955**

All Materials:

Site ID:	338209
Operable Unit ID:	1100168
Operable Unit:	01
Material ID:	580421
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Spill Number/Closed Date:	0485611 / 2014-01-16
Facility ID:	0485611
Facility Type:	ER
DER Facility ID:	273539
Site ID:	338209
DEC Region:	9
Spill Cause:	Unknown
Spill Class:	B2
SWIS:	1522
Spill Date:	2005-03-03
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	2005-03-03
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	2013-05-16
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-03-03
Spill Record Last Update:	2014-01-16
Spiller Name:	Hardeep Gill / Randhawa Dhanwan
Spiller Company:	733 NIAGARA FALLS BOULVARD INC, AT 71 SWANSON TERRACE WILLIA
Spiller Address:	71 SWANSON TERRACE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"03/03/05 RMC/FILE. RECEIVED RESULTS, ABOVE TAGM, ADDITIONAL ASSESSMENT AND REMEDIATION REQUIRED. CHECKED ASSESSOR, PRP LETTER TO OWNER OF LAND AND BUSINESS ON SITE. RESPONSE DUE 3/30/05. 03/08/05 RMC/JIM ALLEN, ATTORNEY FOR PROPERTY OWNERS, 884-5600/PHONE. HE IS CONCERNED THAT THE OWNERS DID NOT RECEIVE A COPY OF THE RESULTS. HE STATED THAT THE ALLENS PAID TO HAVE THE USTS REMOVED IN THE 80'S. RMC TO FAX A COPY OF THE RESULTS AND SPILL FILE TO HIM. RMC AGREED SIT DOWN WITH THE OWNERS AND TO EXTEND THE RESPONSE DATE TO 4/30/05. 04/15/05 RMC/JIM ALLEN/PHONE. DISCUSSED RESULTS. AT ALLENS REQUEST RMC LOCATED 1986 LETTER TO THE DEPARTMENT FROM FLEISCHMANN SERVICE. THIS WAS A SIMPLE NOTIFICATION THAT THREE UST WERE REMOVED. UPDATE 4/30/05. 05/09/05 RMC/JIM ALLEN/FILE. OWNER NEVER USED USTS, PRP HAS

AF AUTOMOTIVE (Continued) **S106866955**

HIRED ANOTHER CONSULTANT, HE WILL HAVE A RESPONSE BY 5/30/05. 07/08/2005 RMC/JIM ALLEN/PHONE. HAS HAD PHASE ONE DONE BY PETER GORTON, SUN OIL COMPANY HAS OWNED FOR MANY YEARS, THEN HAD LEASED, AND THEN SOLD THE STATION. HE PLANS ON EXPLORING CLEANUP BY OTHER PARTIES. HE WILL SEND PHASE ONE AND LETTER REQUESTING THREE MONTHS WORK ON OTHER PRPS. UPDATE 10/30/05 08/05/05 RMC/FILE. RECEIVED LETTER REQUESTING 4 MONTHS TO WORK WITH PRPS AND DO AN ASSESSMENT. RMC AGREED AND CONFIRMED WITH MR. ALLEN ON 8/8. UPDATE 11/30/05. 12/28/05 RMC/FILE. LEFT MESSAGE FOR JIM ALLEN, CALL DUE 12/30/05. 01/17/06 RMC/FILE. CALLED JIM ALLEN. LEFT MESSAGE. CALL DUE 1/24/06. 01/23/06 RMC/FILE. RETURNED JIM ALLENS CALL. HIS CLIENT HAS AN OFFER MAYBE, THEY ARE ALSO LOOKING AT SUN OIL. THEY HAVE CONTACTED SLATER FOR ADVICE. UPDATE 2/23/06. 03/01/06 RMC/FILE. LEFT MESSAGE FOR PRP's ATTORNEY TO CALL. CALL DUE 3/10/06. 03/02/06 RMC/JIM ALLEN/PHONE. OWNER IN STILL WORKING TO SELL THE PROPERTY AS IS. HE WILL ATTEMPT TO GET SUN TO DO THE WORK IF HE CAN'T MARKET IT SOON. UPDATE 5/1/06. 04/28/06 RMC/FILE. RECEIVED LETTER FROM PRP ATTORNY ADVISING THAT PROPERTY HAS BEEN SOLD. RMC CHECKED WITH THE ASSESSOR, TRANSFER YET TO SHOW ON THEIR COMPUTER. RMC TO CHECK AGAIN IN A FEW WEEKS. UPDATE 5/30/06. 05/26/06 RMC/FILE. CHECKED OWNERSHIP. STILL HAS NOT CHANGED. CALL AGAIN 6/30/06. 06/19/06 RMC/FILE. CHECKED ASSESSOR. NO CHANGE YET. CONTACTED JIM ALLEN TO OBTAIN CONTACT INFORMATION. SENT PRP LETTER. RESPONSE DUE 7/14/06. 07/24/06 RMC/FILE. RECEIVED MESSAGE FROM AND LETTER FROM PRP ATTORNEY ANGELA DEMERLE. PRP PLANS ON ATTEMPTING TO GET SUN INVOLVED, UPDATE 10/30/06. 12/15/06 RMC/FILE. RECEIVED LETTER FROM PRP ATTORNEY, WANTS ANOTHER 90 DAYS. REPORT DUE 3/30/07. 07/26/07 RMC/FILE. LEFT MESSAGE FOR ANGELA DEMERLE. UPDATE 8/1/07. 07/27/07 RMC/FILE. RECEIVED MESSAGE BACK FROM ANGELA DEMERLE. SHE WILL ADVISE HER CLIENT THAT THEY NEED TO GET MOVING AS SHE HAS BEEN UNABLE TO GET A RESPONSE FROM SUN, UPDATE 8/15/07. 01/10/08 RMC/ANGELA DEMERLE, HSE, 845-4222/PHONE. AFTER DATING CONTAMINATION AND DISCUSSIONS SHE WAS UNABLE TO BRING SUNOCO ON BOARD, SHE ADVISED HE CLIENTS OF THIS PAST FALL. RMC SENT LETTER REQUESTING WORK PLAN AND SCHEDULE BY 2/15/08. 02/11/08 RMC/GILL HARDEEP? 716-400-1684/PHONE. PARTNER WILL BE BACK IN COUNTRY IN MARCH. WILL SEND PLAN IN BY 4/15/08. 08/04/08 RMC/FILE. NO RESPONSE LETTER. RESPONSE DUE 8/16/08. 08/14/08 RMC/Dan Randhewa, 716-400-1680/PHONE. HE IS GETTING PLANS AND PRICES FROM NWECC, GES, AND AFI. PLAN DUE 9/15/08 10/23/08 RMC/FILE. CONTACTED DAN RANDHEWA, REQUESTED RAP AND SCHEDULE WITH IN TWO WEEKS, DUE 11/15/08. 01/09/09 RMC/FILE. CONTACTED DAN RANDHEWA, HE CLAIMS TO BE CLOSE TO HIRING ROJ CHOPRA. RMC ADVISED RAP AND SHORT SCHEDULE IN WEEK OR SPILLS WILL SEND TO LEGAL. UPDATE 1/16/09. 01/15/09 RMC/ROJ CHOPRA/PHONE. HE WILL SUBMIT A PLAN, DUE 1/16/09. 04/02/09 RMC/FILE. REVIEWED PLAN RECEIVED 3/31/09. RAP IS TO INSTALL 6 INJECTION WELLS. SAMPLE AFTER 16 WEEKS. RMC CONTACTED RAJ CHOPRA AND ADVISED RMC HAS NOT SEEN RESULTS WITH SOIL TYPES IN THIS AREA. RMC ADVISED THAT THEY ARE WELCOME TO ATTEMPT THIS METHOD BUT RMC BELIEVES IT WILL ONLY COST MONEY AND DELAY THE NEED TO REMOVED SOURCE SOILS. HE WILL ADVISE HIS CLIENT OF RMC'S CONCERNS. UPDATE 5/1/09. 06/05/09 RMC/DAN RANDHEWA/PHONE. NO WORK HAS BEEN DONE. HE WILL CONTACT HIS CONTACTOR. UPDATE 6/10/09 06/17/09 RMC/FILE. RECEIVED FAX THAT INJECTION WELLS WILL BE INSTALLED WEEK OF 6/15TH. 06/17/09 RMC/SITE. WELLS BEING INSTALLED. UPDATE 7/30/09. 09/09/09 RMC/FILE NO REPORT RECEIVED LEFT MESSAGE FOR DAN RANDHEWA. UPDATE 9/30/09. 11/19/09 RMC/FILE. NO REPORT RECEIVED LEFT MESSAGE FOR DAN REANDHEWA, CALL DUE 11/25/09. 12/29/09 RMC/FILE. NO REPORT RECEIVED CALLED DAN REANDHEWA. HE WILL AGAIN CONTACT CONTRACTOR FOR

AF AUTOMOTIVE (Continued) **S106866955**

THE REPORT. DUE 1/7/10. 01/11/10 RMC/FILE. RECIVED MESSAGE TO CALL RAJ CHOPRA, 716-480-2125. RETURNED MESSAGE ADVISING THAT REPORT WAS OVERDUE. 02/04/10 RMC/FILE. NO RESPONSE. CALLED ROJ CHOPRA. PREOXIDE WAS NOT PUT IN AS THEY FAILED TO BE ABLE TO NEGOTIATE A DEAL IN TIME. RMC REQUESTED THE WELLS BE SAMPLED ASAP. DUE 2/28/10 03/03/10 RMC/FILE. NO GW REPORT LETTER. RESPONSE DUE 3/15/10. 03/17/10 RMC/FILE. RECEVED GW SAMPLE RESULTS SIGNIFICANT EXCEECANCES IN WELL PREVIOUS SIGNIFICANT SOIL EXCEEDANCES IN SOIL OVER MAJORITY OF THE NORTH AND WEST SIDES. NOTE THAT REMEDIATION OPTIONS ARE BEING LOOKED AT. THEY HAVE YET TO IMPLEMENT THE 3/09 PLAN AGREED UPON. RMC LEFT MESSAGE FOR RAJ CHOPRA AND DISCUSSED WITH DAN RANDHEWA THAT RAP IMPLEMENTATION OVER DUE. WORK STARTED OR LEGAL BY 3/30/10. 05/03/10 RMC/ROJ CHOPRA/PHONE. ORC WAS PUT IN ABOUT 4/1/10. DID NOT CALL AND ADVISED OF WORK WILL SAMPLE AGAIN AT THE END OF THE MONTH. REPORT DUE 7/30/10. 05/18/11 RMC/FILE. NO RESPONSE FROM CALLS TO OWNERS OR CONSULTANT. CALLED ROJ CHOPRA, HE HAS NOT BEEN AUTHORIZED TO DO FURTHER WORK. CALLED ASSESSOR, NOW NAMED 733 NIAGARA FALLS BOULVARD INC, AT 71 SWANSON TERRACE WILLIAMSVILLE NY. CALLED DAN RANDEHAWA, HE ADVISED HE STILL OWNS THE PROPERTY. RMC ADVISED THAT DEC HAS MADE NUMEROUS ATTEMPTS TO GET REPORT AND FAILURE SUPPLY REPORT IN 10 DAYS WILL RESULT IN LEGAL REFERRAL. 05/27/11 RMC/SITE. 6 DRUMS CUTTINGS AND/OR PURGE WATER REMAIN ON SITE. WELLS APPEAR TO HAVE NOT BEEN OPENED FOR SAMPLING IN A LONG TIME. 06/02/11 RMC/FILE. DRAFED LEGAL REFERRAL. 10/20/11 GPS: DISCUSSED WITH OGC ATTORNEY. SENT LETTER & ORDER TO RP IN AUGUST. RESPONDENT CONTACTED OGC IN SEPTEMBER AND WAS TOLD ATHONY PARLATO WAS REPRESENTING THEM. OGC TALKED TO PARLETO ON OCT 12TH AND WAS TOLD HE WOULD NEED TO DISCUSS WITH CLIENT AND CONTRACTOR. WAITING FOR RESPONSE BACK. 01/13/12 RMC/FILE. TALED WITH JIM ALLEN, PREVIOUS OWNERS ATTORNEY, HE AGAIN ADVISED THAT PROPERTY WAS SOLD AND CONTAMINATION WAS FULLY DISCLOSED. THE PROPERTY WAS DISCOUNTED BECAUSE OF THE CONTAMINATION. ADVISED DAVE STEVER. 02/02/12 RMC/DAVE STEVER/MEETING. NO CHANGE. UPDATE 6/1/12. 04/19/12 RMC/SITE. NO CHANGE FROM LAST VISIT, 5/27/11. 6 DRUMS ON SITE. ONE TIPPED OVER. 04/21/12 RMC/FILE. HAD HEARING WITH PRPS, STEVER, AND ALJ. RMC WAS PROVIDED SAMPLE ROUND OF THREE WELLS, LOCATIONS NOT GIVEN. RESULTS STILL IN THE ORDER OF 500 TO 5000 TIMES THE GW STANDARDS. NO SOIL ANALYSIS PROVIDED. RMC AGAIN ADVISED THAT PEROXIDE INJECTIONS, UNDER THE PROGRAM PROPOSED, HAVE LITTLE CHANCE OF DECONTAMINATING THE SITE. DISCUSSED OPTIONS. PRPS TO GET AN ATTORNEY, HAVE CONSULTANT CONTACT RMC FOR DISCUSSION ON REMIDIAL NEEDS, AND MEET BACK AGAIN 6/14/12. 03/05/13 RMC/FILE. RECEIVED SIGNED ROE FROM LEGAL. 03/12/13 RMC/FILE DISCUSSED SITE W/GS WHO DISCUSSED WITH ALBANY. TO USE SPILL FUND MONEY AND EMPIRE GEO. 03/13/13 RMC/FILE. DID PIN PAPER WORK, E-DOCED FILE SENT ELECTRONIC COPY TO EMPIRE GEO. 03/15/13 RMC/FILE. TALKED WITH DAVE STEINER, EMPIRE. THEY ARE PLANNING ON PROBING 3/20 FOR DISPOSAL SAMPLES. CALLED DANNY AT 400-1680 AND ADVISED. HE IS PLANNING ON BEING ON SITE ANYWAY THAT DAY. 03/29/13 RMC/FILE. RECEIVED DISPOSAL SAMPLE RESULTS. ALL NON HAZ. 05/03/13 RMC/FILE. CONTRACTOR STARTING PROJECT TODAY. 05/06/13 RMC/SITE. EXCAVATING FOR THE SECOND DAY. 4 TRUCKS ON TODAY. FINDING STRONG CONTAMINATION. SOME 3 INCH PRODUCT PIPES. 05/15/13 RMC/FILE INSPECTED SITE SEVERAL TIMES THIS AND LAST WEEK. EXCAVATION CONTINUES. FINDING CONTAMINATION AS EXPECTED. EXCAVATION SHOULD END TOMORROW. 05/16/13 RMC/SITE. EXCAVATION WORK COMPLETED. HAVE EXCAVATED ALL ACCESSIBLE IMPACTED SOILS KNOWN. STONE AND GRADING TO BE COMPLETED BY TOMORROW. REPORT DUE 6/30/13. 01/16/14 RMC/FILE. RECEIVED EMPIRE GEO REMEDIAL REPORT DATED 09/20/13. EXCAVATED ALL

AF AUTOMOTIVE (Continued) **S106866955**

2128 TONS IMPACTED SOIL. CONTAMINATED SOIL, NOT ACCESSIBLE, WAS LEFT BEHIND AROUND THE BUILDING, ALONG NIAGARA FALLS BLVD, AND AT UTILITIES. 20 POST EXCAVATION SIDEWALL SAMPLES TAKEN WITH SIX SHOWING CP51 EXCEEDANCES. 8 BOTTOM SAMPLES TAKEN WITH NO CP51 EXCEEDANCE. THE SAMPLE EXCEEDANCES ARE MINOR EXCEPT AT SAMPLES W4 ALONG THE BUILDINGS NORTH SIDE AND W16 ADJACENT TO UTILITIES AND NIAGARA FALLS BLVD. SITE TO HAVE NO FURTHER ACTION AT THIS TIME. LETTER, ISR DRAFTED, INACTIVE. "

Remarks: "FOUND PETROLEUM CONTAMINATION WHILE DOING GEOPROBE FOR POTENTIAL SALE, RESULTS WILL BE FAXED OVER."

All Materials:

Site ID:	338209
Operable Unit ID:	1100168
Operable Unit:	01
Material ID:	580421
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

AC118 **CARUBA COLLISON** **NY Spills** **S103036539**
East **1167 NIAGARA FALLS BLVD** **N/A**
< 1/8 **AMHERST, NY**
0.021 mi.
111 ft. **Site 1 of 2 in cluster AC**

Actual:
591 ft.

Focus Map:
6

SPILLS:

Spill Number/Closed Date:	9713614 / 1998-03-09
Facility ID:	9713614
Facility Type:	ER
DER Facility ID:	221972
Site ID:	272765
DEC Region:	9
Spill Cause:	Deliberate
Spill Class:	E6
SWIS:	1522
Spill Date:	1998-03-01
Investigator:	COOKE
Referred To:	Not reported
Reported to Dept:	1998-03-06
CID:	999
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	1998-03-09
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-03-09
Spill Record Last Update:	1998-03-23

CARUBA COLLISON (Continued) **S103036539**

Spiller Name:	Not reported
Spiller Company:	NONE
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	JOE CARUBBA
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was JDC 3/9/98: JDC ON SITE AND MET WITH JOE CARUBBA, INSPECTED SITE AND FOUND NO EVIDENCE OF SPILLING TO FLOOR DRAINS. ALL DRAINS SPILL TO OIL WATER SEPARATOR WHICH IS CLEANED OUT ANNUALLY. ALL SOLVENTS AND WASTE PAINTS ARE COLLECTED AND RECYCLED THROUGH MATERIAL VENDERS. AUTO MAINTEBANCE IS NOT PERFORMED AS PART OF THEIR BUSNESS, JUST BODY WORK. BASED ON SITE INSPECTION AND INTERVIEW WITH MR CARUBBA, NO FURTHER ACTION IS REQUIRED."
Remarks:	"ALLEGED DUMPING OF WASTE OILS & ANTI-FREEZE TO FLOOR DRAINS. REPORT REFERRED TO SPILLS BY BECI UNIT"

All Materials:

Site ID:	272765
Operable Unit ID:	1059576
Operable Unit:	01
Material ID:	324619
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Site ID:	272765
Operable Unit ID:	1059576
Operable Unit:	01
Material ID:	324620
Material Code:	0043A
Material Name:	antifreeze
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AC119 **CARUBBA COLLISION, INC.** **RCRA-CESQG 1000424068**
East **1167 NIAGARA FALLS BLVD** **NY MANIFEST NYD022673313**
< 1/8 **AMHERST, NY 14226**
0.021 mi.
111 ft. **Site 2 of 2 in cluster AC**

Actual:
591 ft.

Focus Map:
6

RCRA-CESQG:

Date form received by agency:	01/01/2007
Facility name:	CARUBBA COLLISION, INC.
Facility address:	1167 NIAGARA FALLS BLVD AMHERST, NY 14226
EPA ID:	NYD022673313
Mailing address:	NIAGARA FALLS BLVD AMHERST, NY 14226

CARUBBA COLLISION, INC. (Continued) **1000424068**

Contact: SAM CARUBBA
Contact address: NIAGARA FALLS BLVD
AMHERST, NY 14226
Contact country: US
Contact telephone: 716-834-0466
Contact email: Not reported
EPA Region: 02
Land type: Facility is not located on Indian land. Additional information is not known.
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:
Owner/operator name: ANTHONY CARUBBA
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: ANTHONY CARUBBA
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No

CARUBBA COLLISION, INC. (Continued) **1000424068**

Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: CARUBBA COLLISION, INC.
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 03/02/1994
Site name: CARUBBA COLLISION
Classification: Large Quantity Generator

Date form received by agency: 02/25/1992
Site name: CARUBBA COLL
Classification: Large Quantity Generator

Date form received by agency: 06/09/1986
Site name: CARUBBA COLLISION, INC.
Classification: Small Quantity Generator

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 06/23/1994
Date achieved compliance: 07/27/1994
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/23/1994
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 08/09/2002
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 06/17/1994
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 07/27/1994
Evaluation lead agency: State

CARUBBA COLLISION, INC. (Continued) **1000424068**

NY MANIFEST:

Country:	USA
EPA ID:	NYD022673313
Facility Status:	Not reported
Location Address 1:	1167 NIAGARA FALLS BLVD
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	AMHERST
Location State:	NY
Location Zip:	14226
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD022673313
Mailing Name:	CARUBBA COLLISION INCORPORATED
Mailing Contact:	CARUBBA COLLISION INCORPORATED
Mailing Address 1:	1500 NIAGARA FALLS BLVD
Mailing Address 2:	Not reported
Mailing City:	TONAWANDA
Mailing State:	NY
Mailing Zip:	14150
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7168340466

NY MANIFEST:

Document ID:	ILA1521706
Manifest Status:	Not reported
seq:	Not reported
Year:	2004
Trans1 State ID:	UPW151288
Trans2 State ID:	Not reported
Generator Ship Date:	12/01/2004
Trans1 Recv Date:	12/01/2004
Trans2 Recv Date:	12/23/2004
TSD Site Recv Date:	12/30/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD022673313
Trans1 EPA ID:	TXR000050930
Trans2 EPA ID:	Not reported
TSDF ID 1:	ILD980613
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F005 - UNKNOWN

CARUBBA COLLISION, INC. (Continued) **1000424068**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00035
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

---

120 East < 1/8 0.021 mi. 113 ft. **PROULX RESIDENCE** **NY Spills** **S102174779**
383 NIAGARA FALLS BLVD **N/A**
AMHERST, NY

Actual: 608 ft.

Focus Map: 8

SPILLS:

Spill Number/Closed Date:	9206098 / 1992-09-29
Facility ID:	9206098
Facility Type:	ER
DER Facility ID:	217458
Site ID:	266963
DEC Region:	9
Spill Cause:	Unknown
Spill Class:	E6
SWIS:	1522
Spill Date:	1992-08-01
Investigator:	SORGI
Referred To:	Not reported
Reported to Dept:	1992-08-26
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Affected Persons
Cleanup Ceased:	1992-08-26
Cleanup Meets Std:	True
Last Inspection:	1992-08-26
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1992-08-27
Spill Record Last Update:	1992-10-13
Spiller Name:	Not reported
Spiller Company:	NONE
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MJS 08/26/92: MJS SITE INSPECT. STAINED AREA IS 2' X 3'. HAS NO PETROLEUM ODOR. POSSIBLE BROKEN DRAIN TILE IN THIS AREA. BLACK MATERIAL LOOKS TO BE SAME AS BLACK COATING ON TRANSFORMER POLE. 09/29/92: MJS - NO PETROLEUM CONTAMINATION. NO FURTHER ACTION

PROULX RESIDENCE (Continued) **S102174779**

NECESSARY BY SPILL UNIT. "
Remarks: "CALLER HAS NOTICED OILY BLACK STAINING ON LAWN"

All Materials:
Site ID: 266963
Operable Unit ID: 969852
Operable Unit: 01
Material ID: 410277
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Not reported
Recovered: .00
Oxygenate: Not reported

H121 **NOCO** **NY Spills** **U003317675**
South **4265 MAPLE ROAD** **N/A**
< 1/8 **AMHERST, NY 14226**
0.023 mi.
120 ft. **Site 2 of 5 in cluster H**

Actual: **594 ft.**

Focus Map: **7**

SPILLS:
Spill Number/Closed Date: 0751262 / 2012-08-03
Facility ID: 0751262
Facility Type: ER
DER Facility ID: 341082
Site ID: 391458
DEC Region: 9
Spill Cause: Equipment Failure
Spill Class: B3
SWIS: 1522
Spill Date: 2007-12-26
Investigator: rmcrosse
Referred To: Not reported
Reported to Dept: 2007-12-26
CID: Not reported
Water Affected: Not reported
Spill Source: Gasoline Station or other PBS Facility
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: 2011-08-26
Recommended Penalty: False
UST Trust: Not reported
Remediation Phase: 0
Date Entered In Computer: 2007-12-26
Spill Record Last Update: 2012-08-03
Spiller Name: Not reported
Spiller Company: NOCO ENERGY CORPORATION
Spiller Address: 700 GRAND ISLAND BLVD
Spiller Company: 999
Contact Name: MIKE YOUNT
DEC Memo: "12/27/07 RMC/SITE. KEVIN FROM PRIME TIME SERVICES ON SITE. THEY ARE CUTTING TRENCHES IN AREA OF THE PUMP ISLANDS IN ORDER TO INSTALL NEW PIPING. THE OPEN TRENCH TO THE NORTH IS THE LENGTH OF THE PAD ABOUT 3

NOCO (Continued) **U003317675**

FOOT DEEP AND 4 FOOT WIDE. ALL SIDED CHECKED HAVE STRONG PETROLEUM TYPE ODORS. RMC DISCUSSED WITH SAC AND PUT A CALL INTO MIKE YOUNT AT 479-7932. 12/27/07 RMC/MIKE YOUNT/PHONE. HE WILL INSTRUCT CONTRACTOR TO REMOVE ALL THE CONTAMINATION THAT CAN BE SEEN AND SMELLED AND TEST. RMC TO REINSPECT. UPDATE 1/10/08. 12/28/07 RMC/MIKE LESAKOWSKI, BENCHMARK 716-818-3954/PHONE. BROCK GREEN WILL BE NO SITE. PLAN ON EXCAVATING TO THE SIDE WALK AND BUILDING. IF CAN DIG OUT OF IT WILL DO BORINGS AND REVISIT IF NECESSARY. UPDATE 1/10/08, 12/31/07 RMC/BROCK GREEN, 225-3314/SITE. REMEDIAL EXCAVATIONSTARTED, REMOVED TO THE SIDEWALK TO 6 TO 8 FEET. EXCAVATION WILL CONTINUE FOR SEVERAL MORE DAYS. SAMPLES TAKEN, UPDATE 1/10/08. 12/31/07 RMC/BROCK GREEN/PHONE. WILL TAKE 3 BOTTOM SAMPLES AND 6 SIDEWALL WALL SAMPLES IN THE AREA OF THE ISLAND. UPDATE 1/10/08. 01/29/08 RMC/FILE. MIKE YOUNT/PHONE. RECEIVED EXCAVATION REPORT, 1114 TONS IMPACTED SOIL REMOVED TO BIOCELL ON RIVER ROAD. POST EXCAVATION SAMPLE RESULTS SHOW FURTHER ASSESSMENT NEEDED, DISCUSSED WITH MIKE YOUNT. HE WILL HIRE A COMPANY TO DO AN ASSESSMENT, UPDATE 3/30/08. 08/05/08 RMC/FILE. NO ASSESSMENT RECEIVED. LETTER. RESPONSE DUE 8/30/08. 08/27/08 RMC/MIKE LESAKOWSKI, BENCHMARK, 856-0597. REPORT WILL BE SENT. DUE 9/15/08. 09/12/08 RMC/FILE. REVIEWED BENCHMARK REPORT. TWO WELLS INSTALLED BOTH SHOW EXCEEDANCES. SOIL TESTS AND BORING LOGS INDICATE THE NEED FOR REMEDIATION. CALLED AND LEFT MESSAGE FOR MIKE YOUNT, CALL DUE 9/30/08. 11/07/08 RMC/FILE. NO RESPONSE. PRP LETTER. PLAN AND SCHEDULE DUE 11/29/08. 12/22/08 RMC/FILE. REVIEWED REPORT RECEIVED 12/11/08. EXCAVATION REQUIRED BETWEEN ISLAND PAD AND SWEETHOME. PRP WANTS TO DO WORK IN CONJUNCTION WITH 2010 ROAD PROJECT. DISCUSSED WITH SAC. OK AS LONG AS THEY DO QUARTERLY MONITORING. LEFT MESSAGE FOR MIKE LESAKOWSKI, BENCHMARK, 856-0583 ADVISING SUCH, GW REPORT DUE 1/30/09. 01/08/09 RMC/MIKE LESAKOWSKI/PHONE. DISCUSSED WELLS. WILL INSTALL 3 AND DO QUARTERLEY MONITORING. ALSO WILL GET CONTACT FOR ROAD PROJECT. UPDATE 3/30/09. 03/23/09 RMC/FILE. RECEIVED QUARTLY GW REPORT. NEXT ROUND DUE 6/30/09. 06/02/09 RMC/FILE. REVIEWED GW REPORT RECEIVED 5/29/09. LEVELS EXCEED TOGS BUT GENERALLY LOWER. FURTHER EXCAVATION PLANNED SPRING 10. NEXT GW SAMPLE EVENT REPORT DUE 11/30/09. 08/20/09 RMC/FILE. RECEIVED GW MONITORING REPORT. LEVELS HIGHER. FURTHER EXCAVATION PLANNED FOR SPRING 2010. NEXT ROUND DUE 1/1/10 02/23/10 NO RESULTS LETTER. DUE 3/15/10 03/02/10 RMC/FILE. RECEIVED TWO QUARTERS OF MW SAMPLE DATE. EXCEEDANCES CONTINUE. EXCAVATION PLAN DUE 5/1/10. 09/01/10 RMC/FILE. LEFT MESSAGE FOR MIKE YOUNT REQUESTING REPORT. DUE 9/15. 10/26/10 RMC/FILE. LEFT ANOTHER MESSAGE FOR MIKE YOUNT REQUESTING A MEETING TO WORK OUT DETAILS OF A STIP. CALL DUE 11/1/10 04/04/11 RMC/FILE. REPORT RECEIVED. EXCEEDANCES CONTINUE. 04/28/11 RMC/FILE. NOCO ADVISED THAT EXCAVATION WILL BE DONE IN 9 OF 11. UPDATE 9/1/11 8/25/11:SAC INSPECT SITE. MET W/PAUL WERTHMAN JR. EXCAVATION HAS BEGUN. RED CLAY OBSERVED. THERE WAS A VEIN OF GRAVEL THAT WAS OBSERVED WHERE THERE WAS STAINING AND PRODUCT WAS LEACHING FROM IT. EXCAVATION WENT TO ABOUT 6 FT. WORK WILL CONTINUE INTO TOMORROW. 8/26/11:SAC INSPECT SITE. MET W/MIKE YOUNT AND PAUL WERTHMAN JR. EXCAVATION IS CONTINUING. PER MR. WERTHMAN, EXCAVATION AT DEEPEST POINT IS 6.5 FT AND STEPPED UP IN THE EAST DIRECTION TO ABOUT 4 FT. EXCAVATION IS LIMITED ON SOUTH IDE DUE TO WATER LINE SEWRE LINE AND TANKS. CANNOT GO ANY FURTHER IN THE WEST DIRECTION DUE TO CANOPY/PUMP ISLANDS AND IT'S CLOSE TO THE 1ST EXCAVATION WHERE CONTAMINATED SOIL WAS REMOVED. BOTTOM SAMPLES ARE UNDER 2 ppm ON THE PID METER AND 13 ppm ON THE PID METER FOR THE EAST WALL SAMPLES. SLIGHT SHEEN ON WATER IN EXCAVATION FROM VEIN OF GRAVEL THAT COULD NOT BE REMOVED FURTHER IN THE WEST DIRECTION. THEY

NOCO (Continued) **U003317675**

ANTICIPATE COMPLETING EXCAVATION TODAY AND BACKFILLING ON MONDAY, 8/29. SAC INSPECT SITE LATE IN THE AFTERNOON. NO ONE AT THE SITE. EXCAVATION APPEARS TO BE COMPLETED AS IT EXTENDS NEAR THE DRIVEWAY ENTRANCE ON MAPLE ROAD. CLAY BOTTOM AND SIDES OBSERVED. 8/29/11:SAC INSPECT SITE. MET W/MIKE YOUNT AND PAUL WERTHMAN JR. EXCAVATION WAS COMPLETED AND THEY ARE IN THE PROCESS OF BACKFILLING. MR. WERTHMAN SAID PID METER READINGS WERE LOW CONFIMING COMPLETION OF THE SIDE WALLS AND BOTTOM. ALSO, THEY WERE LIMITED TO THE NORTH BASED ON THE SEWER LINE THAT RAN NEAR THE EXCAVATION. EXCAVATION APPEARS TO BE MAINLY CLAY. SMALL AMOUNT OF PRODUCT RAN BACK INTO THE HOLE FROM THE SMALL LAYER OF PEA STONE IN THE SOUTHWEST CORNER OF EXCAVATION. THEY CANNOT REMOVE THIS ANY FURTHER BECAUSE OF THE PROXIMITY TO THE CAONPY/PUMP ISLANDS AND THIS NEAR THE OLD EXCAVATION. 02/02/12 RMC/FILE. CALLED MIKE YOUNT, BENCHMARK, 856-0599. REQUESTED REPORT, DUE 2/29/12 03/08/12 RMC/FILE. REVIEWED TURNKEY REPORT DATED 11/11. EXCAVATED A TOTAL OF 1846 TONS IMPACTED SOIL, (732 IN 2011 AND 1114 IN 2008). POST EXCAVATION SAMPLES SHOW THAT ALL THE BOTTOM SAMPLES MEET CP51. EXCEEDANCES IN SEVERAL SIDEWALL SAMPLES. MOST SIGNIFICANT IS SAMPLES TAKEN BETWEEN THE 2008 AND 2011 EXCAVATIONS. LEFT 6 FOOT +/- STRIP BETWEEN THE TO SO AS TO AVOID COLLAPSE OF PREVIOUS BACKFILL THAT WOULD DAMAGE INSTALLED EQUIPTMENT. ALSO EXCEEDANCES ALONG THE SOUTH SIDE WALL. COULD NOT DIG ANY CLOSER TO THE ROAD. CALLED MIKE YOUNT AND REQUESTED PAPER COPY OF RAW DATA AND DISPOSAL REEIPTS AND A TABLE CORRECTING A FEW ERRORS NOTED. UPDATE 3/30/12. 04/25/12 RMC/FILE. RECEIVED DOCUMENTS AND CORRECTED TABLE AS REQUESTED. SEE 3/8/12 ENTRY. SENT TO MANAGMENT FOR REVIEW. 05/01/12 RMC/FILE SAC WOULD LIKE SOME ADDITIONAL MONITORING. 6/22/12:SAC TELECON MIKE YOUNT - BENCHMARK/TURNKEY. MR. YOUNT SAID HE WILL CONTACT TOM WOELFLE FROM DDS ENVIRONMENTAL TO INSTALL THE ADDITIONAL GEOPROBE/BORING. 08/03/12 RMC/FILE. REVIEWED ADDIONAL INVESTIGATION REPORT REQUESTED. 4 BORINGS, ONE SAMPLE COLLECTED FROM AREA WITH HIGHEST PID READING IN BORING 3. MET CP51. NO FURTHER ACTION REQUIRED AT THIS TIME. LETTER INACTIVE."

Remarks: "CONTAMINATION FOUND WHILE UPGRADING THE PUMP ISLAND. NO MWS ON THE SITE. BENCHMARK ENV. WILL STOCKPILE."

All Materials:

Site ID:	391458
Operable Unit ID:	1148511
Operable Unit:	01
Material ID:	2138994
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

H122 **DUKARMS SERVICE** **EDR Hist Auto** **1020747550**
South **4265 MAPLE RD** **N/A**
< 1/8 **WILLIAMSVILLE, NY 14226**
0.023 mi.
120 ft. **Site 3 of 5 in cluster H**

Actual: EDR Hist Auto
594 ft.

Focus Map:
7

Year:	Name:	Type:
1982	DUKARMS SERVICE	Gasoline Service Stations
1983	DUKARMS SERVICE	Gasoline Service Stations
1985	DUKARMS SERVICE	Gasoline Service Stations
1986	DUKARMS SERVICE	Gasoline Service Stations
1987	DUKARMS SERVICE	Gasoline Service Stations
1988	DUKARMS SERVICE	Gasoline Service Stations
1989	DUKARMS SERVICE	Gasoline Service Stations

H123 **NOCO EXPRESS S-24** **NY UST** **U004159945**
South **4265 MAPLE ROAD** **N/A**
< 1/8 **AMHERST, NY 14226**
0.023 mi.
120 ft. **Site 4 of 5 in cluster H**

Actual: UST:
594 ft.

Focus Map:
7

Id/Status:	9-119938 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	9
Expiration Date:	08/24/2022
UTM X:	189780.79307
UTM Y:	4766793.94791
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	52774
Affiliation Type:	Facility Owner
Company Name:	NOCO EXPRESS PROPERTIES LLC
Contact Type:	VP OF ENVIRONMENTAL HEALTH & SAFETY
Contact Name:	TOM ANDERSON
Address1:	2440 SHERIDAN DRIVE
Address2:	Not reported
City:	TONAWANDA
State:	NY
Zip Code:	14150
Country Code:	001
Phone:	(800) 500-6626
EMail:	Not reported
Fax Number:	Not reported
Modified By:	AESKALSK
Date Last Modified:	2016-09-21

Site Id:	52774
Affiliation Type:	Mail Contact
Company Name:	NOCO ENERGY CORP
Contact Type:	Not reported
Contact Name:	TOM ANDERSON
Address1:	2440 SHERIDAN DRIVE
Address2:	Not reported
City:	TONAWANDA
State:	NY

NOCO EXPRESS S-24 (Continued) **U004159945**

Zip Code:	14150
Country Code:	001
Phone:	(716) 504-3319
EMail:	TANDERSON@NOCO.COM
Fax Number:	Not reported
Modified By:	SRMCDONN
Date Last Modified:	2016-10-26

Site Id:	52774
Affiliation Type:	Facility Operator
Company Name:	NOCO EXPRESS S-24
Contact Type:	Not reported
Contact Name:	RAMON CRUZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(716) 837-8479
EMail:	Not reported
Fax Number:	Not reported
Modified By:	AESKALSK
Date Last Modified:	2017-11-01

Site Id:	52774
Affiliation Type:	Emergency Contact
Company Name:	NOCO EXPRESS PROPERTIES LLC
Contact Type:	Not reported
Contact Name:	TOM ANDERSON
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(716) 353-3096
EMail:	Not reported
Fax Number:	Not reported
Modified By:	SJWALSH
Date Last Modified:	2016-10-12

Tank Info:

Tank Number:	1
Tank ID:	177275
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	12000
Install Date:	11/01/1997
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	NOT DEFINED
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol

NOCO EXPRESS S-24 (Continued) **U004159945**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: AESKALSK
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
K01 - Spill Prevention - Catch Basin
F05 - Pipe External Protection - Jacketed
D11 - Pipe Type - Flexible Piping
G04 - Tank Secondary Containment - Double-Walled (Underground)
B05 - Tank External Protection - Jacketed
H05 - Tank Leak Detection - In-Tank System (ATG)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
C02 - Pipe Location - Underground/On-ground
I03 - Overfill - Automatic Shut-Off
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
J01 - Dispenser - Pressurized Dispenser
E04 - Piping Secondary Containment - Double walled UG

Tank Number: 1-A
Tank ID: 177276
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 10000
Install Date: 12/01/1969
Date Tank Closed: 11/01/1997
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 02
Date Test: 01/01/1992
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
I00 - Overfill - None
H05 - Tank Leak Detection - In-Tank System (ATG)
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel

Tank Number: 2
Tank ID: 177277

NOCO EXPRESS S-24 (Continued) **U004159945**

Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	12000
Install Date:	11/01/1997
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	NOT DEFINED
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	AESKALSK
Last Modified:	04/14/2017

Equipment Records:

H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
K01 - Spill Prevention - Catch Basin
F05 - Pipe External Protection - Jacketed
B05 - Tank External Protection - Jacketed
D11 - Pipe Type - Flexible Piping
G04 - Tank Secondary Containment - Double-Walled (Underground)
H05 - Tank Leak Detection - In-Tank System (ATG)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
C02 - Pipe Location - Underground/On-ground
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
E04 - Piping Secondary Containment - Double walled UG
J01 - Dispenser - Pressurized Dispenser

Tank Number:	2-A
Tank ID:	177278
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	10000
Install Date:	12/01/1969
Date Tank Closed:	11/01/1997
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	02
Date Test:	01/01/1992
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

I00 - Overfill - None
H05 - Tank Leak Detection - In-Tank System (ATG)

NOCO EXPRESS S-24 (Continued) **U004159945**

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number:	3
Tank ID:	166174
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	12/01/1969
Date Tank Closed:	11/01/1997
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	02
Date Test:	01/01/1992
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

I00 - Overfill - None
H05 - Tank Leak Detection - In-Tank System (ATG)
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

H124 **NOCO EXPRESS # 24** **FINDS** **1014813839**
South **4265 MAPLE ROAD** **N/A**
< 1/8 **AMHERST, NY 14226**
0.023 mi.
120 ft. **Site 5 of 5 in cluster H**

Actual: FINDS:
594 ft.

Focus Map: Registry ID: 110043256357
7

Environmental Interest/Information System

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit

NOCO EXPRESS # 24 (Continued) **1014813839**

Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

---

125 SSE < 1/8 0.028 mi. 147 ft. **POLE 1038** **NY Spills** **S108130262**
1038 SWEET HOME ROAD **N/A**
AMHERST, NY

Actual: 594 ft.

Focus Map: 7

SPILLS:

Spill Number/Closed Date:	0605954 / 2006-08-24
Facility ID:	0605954
Facility Type:	ER
DER Facility ID:	319112
Site ID:	369227
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	1522
Spill Date:	2006-08-23
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	2006-08-23
CID:	409
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-08-23
Spill Record Last Update:	2006-08-24
Spiller Name:	DAVE SLATTERY
Spiller Company:	POLE 1038
Spiller Address:	1038 SWEET HOME ROAD
Spiller Company:	001
Contact Name:	DAVE SLATTERY
DEC Memo:	"08/24/06 RMC/FILE. MINOR SPILL, PRP REPORTED AS CLEANUP UNDER WAY. NO SPILL ACTION REQUIRED, CLOSE OUT NO PAPER FILE. "
Remarks:	"HAS BEEN CONTAINED AND CLEAN UP IN PROCESS."

All Materials:

Site ID:	369227
Operable Unit ID:	1127070
Operable Unit:	01
Material ID:	2116650
Material Code:	0020A
Material Name:	transformer oil

POLE 1038 (Continued) **S108130262**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

126
East
< 1/8
0.028 mi.
149 ft.

Actual:
601 ft.

Focus Map:
6

TN. TONAWANDA PARKS DEPT. **NY LTANKS** **S100154933**
LINCOLN PARK **N/A**
TONAWANDA, NY

LTANKS:

Spill Number/Closed Date:	8700016 / 1987-06-02
Facility ID:	8700016
Site ID:	67295
Spill Date:	1987-04-01
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Not reported
Cleanup Ceased:	1987-06-02
SWIS:	1564
Investigator:	ROSS
Referred To:	Not reported
Reported to Dept:	1987-04-01
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	1987-06-02
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1987-04-03
Spill Record Last Update:	1987-06-02
Spiller Name:	Not reported
Spiller Company:	TOWN OF TONAWANDA
Spiller Address:	500 WOODWARD AVENUE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	9
DER Facility ID:	64317
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was LQR / / : LQR TELCON SPILLER 04/01/87,SPILLER TO ISOLATE LINES AND TEST. / / : LQR SITE INSP. 04/9-10/87,TANK REMOVED,CLEAN UP UNDER WAY. / / : LQR TELCON 04/30/87,SOIL TO BE TESTED. / / : RESULTS REC. 05/27/87,JCD SITE INSP. GRAVEL TO BE REUSED IN EXCAVATI0ON. "
Remarks:	"2000 GAL TANK .42GPH LEAK RATE."

All TTF:

Facility ID:	8700016
Spill Number:	8700016
Spill Tank Test:	1530684
Site ID:	67295

TN. TONAWANDA PARKS DEPT. (Continued) **S100154933**

Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	67295
Operable Unit ID:	905891
Operable Unit:	01
Material ID:	559712
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

AD127 **GOODYEAR AUTO SERVICE CENTER** **RCRA-CESQG** **1000194046**
West **1280 NIAGARA FALLS BLVD** **NY Spills** **NYD149982795**
< 1/8 **TONAWANDA, NY 14150** **FINDS**
0.029 mi. **ECHO**
153 ft. **Site 1 of 2 in cluster AD** **NY MANIFEST**

Actual:
587 ft.

Focus Map:
6

RCRA-CESQG:

Date form received by agency:	01/01/2007
Facility name:	GOODYEAR AUTO SERVICE CENTER
Facility address:	1280 NIAGARA FALLS BLVD TONAWANDA, NY 14150
EPA ID:	NYD149982795
Mailing address:	ELWOOD DAVIS RD SUITE 309 LIVERPOOL, NY 13088
Contact:	Not reported
Contact address:	ELWOOD DAVIS RD SUITE 309 LIVERPOOL, NY 13088
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any

GOODYEAR AUTO SERVICE CENTER (Continued) **1000194046**

land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	GOODYEAR T & R CO
Owner/operator address:	NOT REQUIRED
	NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	GOODYEAR T & R CO
Owner/operator address:	NOT REQUIRED
	NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	01/01/2006
Site name:	GOODYEAR AUTO SERVICE CENTER

GOODYEAR AUTO SERVICE CENTER (Continued) **1000194046**

Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 04/13/1995
Site name: GOODYEAR AUTO SERVICE CENTER
Classification: Not a generator, verified

. Waste code: NONE
. Waste name: None

Date form received by agency: 10/31/1986
Site name: GOODYEAR AUTO SERVICE CENTER
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: X001
. Waste name: WASTE OILS

Violation Status: No violations found

SPILLS:
Spill Number/Closed Date: 9302662 / 1993-08-18
Facility ID: 9302662
Facility Type: ER
DER Facility ID: 128339
Site ID: 151005
DEC Region: 9
Spill Cause: Equipment Failure
Spill Class: C3
SWIS: 1564
Spill Date: 1993-05-01
Investigator: SORGI
Referred To: Not reported
Reported to Dept: 1993-05-26
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: 1993-08-04
Cleanup Meets Std: True
Last Inspection: 1993-05-27
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1993-05-28
Spill Record Last Update: 1993-08-19
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: Not reported
Spiller Company: 001
Contact Name: Not reported

GOODYEAR AUTO SERVICE CENTER (Continued) **1000194046**

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was MJS 05/26/93: MJS/STEVE ROBLEE/TELECON - S.L. ROBLEE WILL REMOVE LIFT AND STOCKPILE CONTAMINATED SOIL. WORK TO BEGIN 5/27/93. 05/27/93: MJS/STEVE ROBLEE/SITE - CONTAMINATED SOIL STOCKPILED BEHIND BLDG. ON PLASTIC. TO HAVE PILE COVERED AT END OF DAY. SOME RESIDUAL CONTAMINATION IN EXCAVATION. ASKED TO CLEAN HOLE & SAMPLE 8270. 05/28/93: MJS/STEVE ROBLEE/TELECON - SAMPLES SUBMITTED TO LAB FROM SOIL PILE & EXCAVATION. HE WILL FORWARD ANALYTICAL RESULTS AND DISPOSAL RECEIPTS WHEN HE RECEIVES THEM. 06/01/93: MJS SENT OPTION LETTER TO R.P. MR. ROBLEE INDICATED THAT SOIL WILL BE DISPOSED. 07/26/93: MJS RECEIVED ANALYTICAL FOR EXCAVATION SAMPLE. DETECTION LIMIT IS 500 PPB. ALL PARAMETERS ND. NO FURTHER EXCAVATION NECESSARY. NEED ANALYTICAL & DISPOSAL RECEIPTS FOR SOIL FOR CLOSURE OF FILE. 08/12/93: MJS RECEIVED DISPOSAL RECEIPT FOR CONTAMINATED SOIL. 26 TONS OF SOIL DISPOSED AT BFI ON 8/4/92. 08/16/93: MJS/STEVE ROBLEE/TELECON - NEED ANALYTICAL ON CONTAMINATED SOIL FOR CLOSURE OF FILE. HE WILL FORWARD THE RESULTS. 08/18/93: MJS RECEIVED ANALYTICAL FOR STOCKPILED SOIL (CONTAMINATED). ALL REQUIRED PAPERWORK HAS NOW BEEN RECEIVED. NO FURTHER ACTION REQUIRED. MJS TO CLOSE FILE. 09/29/95: This is additional information about material spilled from the translation of the old spill file: HYDRAULIC FLUID."

Remarks: "HYDRAULIC LIFT LEAKED FLUID TO GROUND."

All Materials:

Site ID:	151005
Operable Unit ID:	980988
Operable Unit:	01
Material ID:	399778
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	9113171 / 1993-02-08
Facility ID:	9113171
Facility Type:	ER
DER Facility ID:	194179
Site ID:	235738
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	1564
Spill Date:	1992-03-27
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	1992-03-27
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	1993-01-09
Cleanup Meets Std:	True
Last Inspection:	1992-05-11

GOODYEAR AUTO SERVICE CENTER (Continued) **1000194046**

Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1992-04-01
Spill Record Last Update:	1993-02-10
Spiller Name:	Not reported
Spiller Company:	S.L. ROBLEE INC.
Spiller Address:	BOX 375
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 03/30/92: RMC/SITE PIPING FAILED AT TANK BOTTOM. HAD THEM EXCAVATE TO CONCRETE PAD BEFORE REPAIR. LIFE ONLY 7 YEARS OLD. REMOVER 55 GALLONS OF OIL/WATER FROM HOLE, PUT IN WASTE OIL TANK. RP TO SAMPLE. 05/11/92: RNL/PHONE TO REMOVE ANOTHER LIFT TODAY. 05/11/92: RMC/STEVE ROBLEE/SITE REMOVED NORTH LIFT,CONTAMINATED GW AND SOIL, WILL REMOVE GROSS CONTAMINATION AND WATER. SAMPLE 8020+8270 OF COMPOSIT BOTTON. EXCAVATED MATERIAL WILL BE LANDFILLED AFTER TEST. 06/11/92: RMC RECEIVED TEST RESULTS/ NON HAZARDOUS. 07/28/92: RMC RECEIVED SAMPLING RESULTS OK. 07/28/92: RMC RECEIVED SAMPLING RESULTS OK. WAITING FOR DISPOSAL RECEIPTS. 09/18/92: RMC/DISPOSAL LETTER RESPONSE DUE 10/9. 11/01/92: RMC/DISPOSAL LETTER RESPONSE DUE 10/9 REVISED TO 11/30/92. 02/01/93: RMC/DISPOSAL LETTER RESPONSE DUE 10/9 REVISED TO 11/30/92 SECOND DISPOSAL LETTER DUE 2/15/93. 02/08/93: RMC/RECEIVED DISPOSAL RECEIPT CLOSE OUT. "
Remarks:	"LIFT FAILED LOST 50 GALLONS OF HYDRAULIC FLUID UNDER CONCRETE. WILL EXCAVATE 3/30/92"

All Materials:

Site ID:	235738
Operable Unit ID:	963948
Operable Unit:	01
Material ID:	414695
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50.00
Units:	G
Recovered:	50.00
Oxygenate:	Not reported

Spill Number/Closed Date:	9416566 / 1995-07-18
Facility ID:	9416566
Facility Type:	ER
DER Facility ID:	194179
Site ID:	235739
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	1564
Spill Date:	1995-03-21
Investigator:	COOKE
Referred To:	Not reported
Reported to Dept:	1995-03-21
CID:	Not reported
Water Affected:	Not reported

GOODYEAR AUTO SERVICE CENTER (Continued) **1000194046**

Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	1995-07-18
Cleanup Meets Std:	True
Last Inspection:	1995-07-18
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1995-03-30
Spill Record Last Update:	1995-08-04
Spiller Name:	Not reported
Spiller Company:	GOODYEAR
Spiller Address:	1280 NIAGARA FALLS BLVD
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was JDC 03/21/95: JDC ON SITE MET W/ BILL SUHR, GOODYEAR AND ADVISED ON CLEANUP OPTIONS. AMERICAN LIFT REMOVED ANDSTAGED SOIL FOR DISPOSAL. SAMPLES COLLECTED. NO FREE OILS OBSERVED. NEED DISPOSAL DOCS. CKBK 4/17/95. 04/11/95: RECEIVED POST SAMPLES FOUND RESULTS WITHIN GUIDLINES. WILL CLOSED WHEN DISPOSAL IS COMPLETED. CK BK 4/19. 07/18/95: INSPECTED SITE AND FOUND SOILS REMOVED AND COLLECTED DISPOSAL DOCUMENTATION. POST TEST AND DISPOSAL PAPERWORK SATIFACTORY, NO FURTHER WORK REQUIRED. "
Remarks:	"LIFT REMOVED HYDRAULIC OIL FOUND IN SOILS AND GW"

All Materials:

Site ID:	235739
Operable Unit ID:	1010292
Operable Unit:	01
Material ID:	371716
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

FINDS:

Registry ID: 110004384069

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

GOODYEAR AUTO SERVICE CENTER (Continued) **1000194046**

ECHO:
Envid: 1000194046
Registry ID: 110004384069
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004384069

NY MANIFEST:
Country: USA
EPA ID: NYD149982795
Facility Status: Not reported
Location Address 1: 1280 NIAGARA FALLS BLVD
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: TONAWANDA
Location State: NY
Location Zip: 14150
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD149982795
Mailing Name: GOODYEAR AUTO SERVICE CENTER
Mailing Contact: GOODYEAR AUTO SERVICE CENTER
Mailing Address 1: 1280 NIAGARA FALLS BLVD
Mailing Address 2: Not reported
Mailing City: TONAWANDA
Mailing State: NY
Mailing Zip: 14150
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AD128 **GOODYEAR 0462** **NY AST** **A100350617**
West **1280 NIAGARA FALLS BOULEVARD** **N/A**
< 1/8 **TONAWANDA, NY 14150**
0.029 mi.
153 ft. **Site 2 of 2 in cluster AD**

Actual:
587 ft.

Focus Map:
6

AST:
Region: STATE
DEC Region: 9
Site Status: Active
Facility Id: 9-601188
Program Type: PBS
UTM X: 188343.20185
UTM Y: 4766714.61985
Expiration Date: 06/01/2020
Site Type: Auto Service/Repair (No Gasoline Sales)

Affiliation Records:
Site Id: 435475
Affiliation Type: Facility Owner
Company Name: EDWARD SEEBERG MARITAL TRUST II, STEVE SEEBERG, TR
Contact Type: TRUSTEE
Contact Name: STEVE SEEBERG

GOODYEAR 0462 (Continued) **A100350617**

Address1:	110 VIA CAPRI
Address2:	Not reported
City:	PALM BEACH GARDENS
State:	FL
Zip Code:	33418
Country Code:	001
Phone:	(980) 722-9535
EMail:	Not reported
Fax Number:	Not reported
Modified By:	AESKALSK
Date Last Modified:	2015-05-22

Site Id:	435475
Affiliation Type:	Mail Contact
Company Name:	GOODYEAR AUTO SERVICE CENTER
Contact Type:	Not reported
Contact Name:	DON GERASS
Address1:	1280 NIAGARA FALLS BOULEVARD
Address2:	Not reported
City:	TONAWANDA
State:	NY
Zip Code:	14150
Country Code:	001
Phone:	(716) 837-8720
EMail:	GSR0462@GOODYEAR.COM
Fax Number:	Not reported
Modified By:	AESKALSK
Date Last Modified:	2015-05-22

Site Id:	435475
Affiliation Type:	Facility Operator
Company Name:	GOODYEAR 0462
Contact Type:	Not reported
Contact Name:	DON GERASS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(716) 837-8720
EMail:	Not reported
Fax Number:	Not reported
Modified By:	AESKALSK
Date Last Modified:	2015-05-22

Site Id:	435475
Affiliation Type:	Emergency Contact
Company Name:	EDWARD SEEBERG MARITAL TRUST II, STEVE SEEBERG, TR
Contact Type:	Not reported
Contact Name:	GOODYEAR
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999

GOODYEAR 0462 (Continued) **A100350617**

Phone: (330) 796-2121
EMail: Not reported
Fax Number: Not reported
Modified By: AESKALSK
Date Last Modified: 2015-05-22

Tank Info:

Tank Number: 0001
Tank Id: 234634
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
L00 - Piping Leak Detection - None

Tank Location: 2
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/01/1994
Capacity Gallons: 245
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: AESKALSK
Last Modified: 04/14/2017
Material Name: waste oil/used oil

Tank Number: 0002
Tank Id: 234635
Material Code: 0015
Common Name of Substance: Motor Oil

Equipment Records:

L00 - Piping Leak Detection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None

GOODYEAR 0462 (Continued) **A100350617**

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)

Tank Location:	2
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1990
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	AESKALSK
Last Modified:	04/14/2017
Material Name:	motor oil

AE129 **BUSH EDW BLVD FRONTIER SERV GAS STA** **EDR Hist Auto** **1014538420**
SW **175 KENMORE AVE** **N/A**
< 1/8 **BUFFALO, NY**
0.030 mi.
158 ft. **Site 1 of 4 in cluster AE**

Actual:
626 ft.

EDR Hist Auto

Focus Map:
8

Year:	Name:	Type:
1955	BUSH EDW BLVD FRONTIER SERV GAS	GASOLINE STATIONS

AE130 **KWIK FILL MO325.325** **RCRA NonGen / NLR** **1000553105**
SW **175 KENMORE AVE** **FINDS** **NYD986955151**
< 1/8 **BUFFALO, NY 14226** **ECHO**
0.030 mi. **NY MANIFEST**
158 ft. **Site 2 of 4 in cluster AE**

Actual:
626 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	KWIK FILL MO325.325
Facility address:	175 KENMORE AVE BUFFALO, NY 14226-3035
EPA ID:	NYD986955151
Mailing address:	BRADLEY ST PO BOX 599 WARREN, NY 16365
Contact:	Not reported
Contact address:	BRADLEY ST PO BOX 599 WARREN, NY 16365
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Focus Map:
8

Owner/Operator Summary:

Owner/operator name:	UNITED REFINING

KWIK FILL MO325.325 (Continued) **1000553105**

Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: UNITED REFINING
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: KWIK FILL MO325.325
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: KWIK FILL MO325.325
Classification: Not a generator, verified

Date form received by agency: 04/29/1991
Site name: KWIK FILL MO325.325
Classification: Small Quantity Generator

. Waste code: D001

KWIK FILL MO325.325 (Continued) **1000553105**

. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Violation Status: No violations found

FINDS:

Registry ID: 110004468086

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000553105
Registry ID:	110004468086
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004468086

NY MANIFEST:

Country:	USA
EPA ID:	NYD986955151
Facility Status:	Not reported
Location Address 1:	175 KENMORE AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BUFFALO
Location State:	NY
Location Zip:	14226
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD986955151
Mailing Name:	RED APPLE
Mailing Contact:	ANNETTE COPPINGS
Mailing Address 1:	175 KENMORE AVE
Mailing Address 2:	Not reported
Mailing City:	BUFFALO
Mailing State:	NY
Mailing Zip:	14226
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7168328080

KWIK FILL MO325.325 (Continued) **1000553105**

NY MANIFEST:

Document ID:	TXA0946507
Manifest Status:	Not reported
seq:	01
Year:	1999
Trans1 State ID:	88888
Trans2 State ID:	41747
Generator Ship Date:	05/05/1999
Trans1 Recv Date:	05/05/1999
Trans2 Recv Date:	05/11/1999
TSD Site Recv Date:	05/19/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986955151
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCD987574647
TSDF ID 1:	TXD077603371
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00200
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AE131 **RED APPLE FOOD MART #325** **NY UST** **U003318556**
SW **175 KENMORE AVE** **N/A**
< 1/8 **BUFFALO, NY 14223**
0.030 mi.
158 ft. **Site 3 of 4 in cluster AE**

Actual:
626 ft.

Focus Map:
8

UST:

Id/Status:	9-497975 / Unregulated/Closed
Program Type:	PBS
Region:	STATE

RED APPLE FOOD MART #325 (Continued) **U003318556**

DEC Region: 9
Expiration Date: N/A
UTM X: 188124.01550
UTM Y: 4763278.26759
Site Type: Retail Gasoline Sales

Affiliation Records:

Site Id: 54714
Affiliation Type: Facility Owner
Company Name: UNITED REFINING CO OF PA
Contact Type: Not reported
Contact Name: Not reported
Address1: PO BOX 599
Address2: Not reported
City: WARREN
State: PA
Zip Code: 16365
Country Code: 001
Phone: (814) 723-1500
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 54714
Affiliation Type: Mail Contact
Company Name: UNITED REFINING CO OF PA
Contact Type: Not reported
Contact Name: W.L. SPOON
Address1: PO BOX 599
Address2: Not reported
City: WARREN
State: PA
Zip Code: 16365
Country Code: 001
Phone: (814) 723-1500
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 54714
Affiliation Type: Facility Operator
Company Name: RED APPLE FOOD MART #325
Contact Type: Not reported
Contact Name: STATION MANAGER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (716) 832-8080
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

RED APPLE FOOD MART #325 (Continued) **U003318556**

Site Id:	54714
Affiliation Type:	Emergency Contact
Company Name:	UNITED REFINING CO OF PA
Contact Type:	Not reported
Contact Name:	W.L. SPOON
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(814) 723-1500
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BVCAMPBE
Date Last Modified:	2012-02-01

Tank Info:

Tank Number:	1
Tank ID:	168694
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	10000
Install Date:	01/01/1984
Date Tank Closed:	01/01/2000
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	02
Date Test:	12/01/1996
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B07 - Tank External Protection - Retrofitted Sacrificial Anode
C02 - Pipe Location - Underground/On-ground
A00 - Tank Internal Protection - None
I00 - Overfill - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H99 - Tank Leak Detection - Other

Tank Number:	2
Tank ID:	168695
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	10000
Install Date:	01/01/1984

RED APPLE FOOD MART #325 (Continued) **U003318556**

Date Tank Closed: 01/01/2000
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 02
Date Test: 12/01/1996
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
B07 - Tank External Protection - Retrofitted Sacrificial Anode
A00 - Tank Internal Protection - None
I00 - Overfill - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H99 - Tank Leak Detection - Other

Tank Number: 3
Tank ID: 168696
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 8000
Install Date: 01/01/1984
Date Tank Closed: 01/01/2000
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 02
Date Test: 12/01/1996
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

J02 - Dispenser - Suction Dispenser
B07 - Tank External Protection - Retrofitted Sacrificial Anode
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
I00 - Overfill - None
H99 - Tank Leak Detection - Other

AE132 **KWIKFILL** **NY LTANKS** **S108298333**
SW **175 KENMORE AVE** **NY Spills** **N/A**
< 1/8 **AMHERST, NY 14226**
0.030 mi.
158 ft. **Site 4 of 4 in cluster AE**

Actual:
626 ft.

Focus Map:
8

LTANKS:

Spill Number/Closed Date:	9875345 / 2000-05-01
Facility ID:	9875345
Site ID:	250608
Spill Date:	1999-01-01
Spill Cause:	Tank Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	1522
Investigator:	SORGI
Referred To:	Not reported
Reported to Dept:	1999-01-19
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	2000-01-12
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1999-01-19
Spill Record Last Update:	2001-09-28
Spiller Name:	TODD FRANCE
Spiller Company:	UNITED REFINING
Spiller Address:	PO BOX 780
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	9
DER Facility ID:	205427
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MJS 01/19/99: SAC TELECON DOUG LIDDELL OF ESG, HE USED A PID METER DURING THE REMOVAL, THE EXCAVATION WAS REGISTERRING A 100 - 250 ppm READING ON THE METER AFTER THE REMOVAL OF CONTAMINATED SOIL. 06/28/99: MJS FILE REVIEW, HAVE HEARD NOTHING SINCE INITIAL REPORT. MJS TELECON TO TODD FRANCE AT UNITED. THEY ARE STILL WAITING TO REMOVE TANKS. MEETING TOMORROW IN OFFICE WITH UNITED TO REVIEW ALL ACTIVE FILES. 06/29/99: MJS MEETING WITH UNITED, (BI-ANNUAL MEETING WITH UNITED PERSONNEL) UNITED STATED FACILITY IS CLOSED. LINES REMOVED, TANKS STILL IN PLACE. THEY ARE WAITING FOR FUNDING FOR TANK REMOVAL, INVESTIGATION, CLEANUP. 01/11/00: SAC TELECON CRAIG ZINK OF GES, THEY HAVE BEGUN THE TANK REMOVAL AND HAVE FOUND CONTAMINATED SOIL DURING THE REMOVAL, THEY EXPECT TO HAVE THE EXCAVATION COMPLETED BY TOMORROW AFTERNOON AND ARE REQUESTING AN INSPECTION THEN. 01/12/00: MJS SITE INSPECTION, MET WITH STEVE COOPER, NIAGARA TANK AND PUMP. TANKS REMOVED, ELMWOOD TANK CLEANING TANKS. SOME SOIL REMOVAL COMPLETED. REMAINING CONTAMINATION IS WATERY AND THEY CAN NOT TRANSPORT AS IS. WORK TO CONTINUE TOMORROW. THEY ARE DISCUSSING HOW TO REDUCE WATER CONTENT. THEY WILL PROBABLY ADD LIME TO WATERY SOILS TO MAKE TRANSPORT/DISPOSAL POSSIBLE. EXCAVATION WALLS ARE VIRGIN CLAY AND WILL CLEANUP READILY. 01/13/00: MJS TELECON WITH CRAIG ZINK, GES.

KWIKFILL (Continued) **S108298333**

THEY CONTINUED SOIL REMOVAL TODAY BUT RAN INTO PROBLEMS WITH WEATHER AND COULD NOT FINISH JOB. THEY ADDED LIME AS DISCUSSED ABOVE AND REMOVED PART OF REMAINING CONTAMINATION. THEY HAVE TWO WALLS CLEAN AT THIS TIME AND WILL CONTINUE EXCAVATION TOMORROW MORNING. MJS TO INSPECT. 01/14/00: MJS SITE INSPECTION, 1100 HOURS, NOBODY AT SITE. EXCAVATION OPEN AND CONTAMINATION REMAINS. MJS TELECON TO GES - LEFT MESSAGE FOR THEM TO CALL BACK. 01/14/00: MJS TELECON WITH MR ZINK. THEY PLAN TO CONTINUE WORK ON MON 1/17. TWO SIDEWALLS, BOTTOM AND PUMP ISLAND AREA NOT YET CLEAN . 04/11/00: MJS REVIEW REPORT RECEIVED ON 3/27. FOUR SIDEWALL SAMPLES AND TWO FLOOR SAMPLES OBTAINED (POST-EXCAVATION). ALL RESULTS MEET STARS #1 GUIDELINES EXCEPT FOR LOW-LEVELS ON SOUTH WALL SAMPLE: BENZENE (31 PPB), MTBE (390), 1,2,4-TRIMETHYLBENZENE (130) AND M,P-XYLENES (200). THIS SAMPLE REANALYZED VIA TCLP AND ONLY GROUNDWATER STANDARD EXCEEDENCES ARE NAPTHALENE (11 PPB) AND 1,2,4-TRIMETHYLBENZENE (7.3 PPB). REPORT INDICATES APPROX 200 CUBIC YARDS SOIL DISPOSED. DISPOSAL RECEIPTS FORTHCOMING. NO FURTHER REMEDIAL WORK NEEDED BASED ON SAMPLE RESULTS. NEED DISPOSAL DOCUMENTATION FOR FILE CLOSURE (INACTIVE). MJS DRAFTED LETTER TO RP REQUESTING DISPOSAL DOCUMENTATION ASAP FOR FILE INACTIVATION. 05/01/00: MJS RECEIVED DISPOSAL DOCUMENTATION FROM TODD FRANCE, UNITED. 363.83 TONS SOIL DISPOSED AT CHAUTAUQUA COUNTY ELLERY LANDFILL. NO FURTHER ACTION REQUIRED. MJS MAKE FILE INACTIVE AND SENT INACTIVE LETTER TO RP."

Remarks: "CONTAMINATED SOIL FOUND WHILE REMOVING LINES, TANK WILL BE REMOVED IN THE NEXT COUPLE OF MONTHS, APPROX. 10 CU YDS. REMOVED, CONTRACTOR COULD NOT DIG ANYMORE DUE TO THE UTILITIES, SAMPLES WERE TAKEN FROM THE EXCAVATION AND EXCAVATION WAS BACKFILLED, STAINED SOIL REMAINED ON EXCAVATION SIDES, EXCAVATION BOTTOM SOIL HAD ODORS"

All Materials:

Site ID:	250608
Operable Unit ID:	1074796
Operable Unit:	01
Material ID:	306968
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Spill Number/Closed Date:	0651775 / 2007-03-05
Facility ID:	0651775
Facility Type:	ER
DER Facility ID:	325081
Site ID:	375449
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	1522
Spill Date:	2006-12-28
Investigator:	RMCROSSE
Referred To:	Not reported

KWIKFILL (Continued) **S108298333**

Reported to Dept:	2006-12-28
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	2006-12-29
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-12-28
Spill Record Last Update:	2007-07-30
Spiller Name:	TODD FRANCE
Spiller Company:	UNITED REFINING COMPANY
Spiller Address:	P.O. BOX 780
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"12/28/06 RMC/J. SMITH/PHONE. DIGGING NOW. WILL CALL WHEN DONE. CALL DUE 1/5/07. 12/29/06 RMC/J SMITH/PHONE. EXCAVATION COMPLETED AND BACKFILLED WITHOUT INSPECTION. 12/29/06 RMC/DKK/PHONE. DKK ADVISED TO INSPECT. DEPENDENT ON INSPECTION MAY ASK THEM TO OPEN THE EXCAVATION. 12/29/06 RMC/J SMITH/SITE. EXCAVATED ONE LOAD STOCKPILED FOR DISPOSAL. ALSO 3 DRUMS LIQUID AND 4 OF SLUDGED FOR DISPOSAL. SMITH ADVISED THAT SITE WAS DUG TO VISUAL CLEAN AND SCREENED WITH PID. HE HAS PICTURES AND ABOUT 5 SAMPLES WILL BE RUN. RMC ADVISED TO SUBMIT REPORT. DUE 3/1/07. 03/06/07 RMC/FILE. RECEIVED REPORT. EXCAVATION, SAMPLING, AND DISPOSAL DOCUMENTED. NO EXCEEDANCES IN SAMPLE RESULTS. NO FURTHER ACTION REQUIRED. INACTIVE DUE TO ELEVATED PID READINGS. LETTER. INACTIVE. "
Remarks:	"FOUND HYDRAULIC CONTAMINATION WHEN BUILDING WAS TORN DOWN. PLANNING ON DIGGING TO CLEAN."

All Materials:

Site ID:	375449
Operable Unit ID:	1133084
Operable Unit:	01
Material ID:	2122887
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	False

B133 **AMHERST HIGHWAY DEPARTMEN** **NY Spills** **S102174863**
ESE **NORTH FOREST** **N/A**
< 1/8 **AMHERST, NY**
0.031 mi.
164 ft. **Site 5 of 5 in cluster B**

Actual:
576 ft.

Focus Map:
5

SPILLS:

Spill Number/Closed Date:	0375126 / 2003-06-05
Facility ID:	0375126
Facility Type:	ER

AMHERST HIGHWAY DEPARTMEN (Continued) **S102174863**

DER Facility ID:	252272
Site ID:	312884
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	1522
Spill Date:	2003-06-05
Investigator:	JFOTTO
Referred To:	Not reported
Reported to Dept:	2003-06-05
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-06-05
Spill Record Last Update:	2003-06-05
Spiller Name:	Not reported
Spiller Company:	WASTE MANAGEMENT
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was JFO 06/05/03 JFO TELCON WITH RUSS OF WASTE MAN. THE SPILL HAS BEEN CLEANED UP. NO ACTION NECESSARY. CLOSED THERE IS NO PAPER FILE FOR THIS SPILL"
Remarks:	"HYDRAULIC LINE BROKE ON A WASTE MANAGEMENT TRUCK SPILLING 5 GALLONS OF OIL TO THE PARKING LOT. SPILL HAS BEEN CLEANED UP."

All Materials:

Site ID:	312884
Operable Unit ID:	882108
Operable Unit:	01
Material ID:	494317
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	5.00
Oxygenate:	Not reported

Spill Number/Closed Date:	9207862 / 1992-10-08
Facility ID:	9207862
Facility Type:	ER
DER Facility ID:	252272
Site ID:	312885
DEC Region:	9
Spill Cause:	Housekeeping
Spill Class:	D6
SWIS:	1522

AMHERST HIGHWAY DEPARTMEN (Continued) **S102174863**

Spill Date:	1992-10-06
Investigator:	COOKE
Referred To:	Not reported
Reported to Dept:	1992-10-06
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Citizen
Cleanup Ceased:	1992-10-06
Cleanup Meets Std:	True
Last Inspection:	1992-10-06
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1992-10-09
Spill Record Last Update:	1992-10-13
Spiller Name:	Not reported
Spiller Company:	AMHERST HIGHWAY DEPT
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was JDC 10/08/92: JDC TELCON W/ DAVE BRAMER, DUPTY SUPER AMHERST SUPER. WHO STATED DYE USED W/ PESTICIDE APPLICATION AS INDICATOR FOR APLLICATION. "
Remarks:	"GREEN DYE SPOTTED IN DRAINAGE DITCH"

All Materials:

Site ID:	312885
Operable Unit ID:	971516
Operable Unit:	01
Material ID:	408474
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Site ID:	312885
Operable Unit ID:	971516
Operable Unit:	01
Material ID:	408475
Material Code:	0048A
Material Name:	dye
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

AF134
West
< 1/8
0.032 mi.
170 ft.

2980 SHERIDAN DRIVE
TONAWANDA, NY 14150

Site 1 of 6 in cluster AF

ERNS **2013056839**
N/A

Actual:
598 ft.

Focus Map:
6

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

AF135
West
< 1/8
0.032 mi.
170 ft.

MONROE MUFFLER
2980 SHERIDAN DRIVE
TONAWANDA, NY

Site 2 of 6 in cluster AF

NY Spills **S102245168**
N/A

Actual:
598 ft.

Focus Map:
6

SPILLS:

Spill Number/Closed Date:	9514918 / 1996-02-26
Facility ID:	9514918
Facility Type:	ER
DER Facility ID:	77401
Site ID:	84149
DEC Region:	9
Spill Cause:	Housekeeping
Spill Class:	D3
SWIS:	1564
Spill Date:	1996-02-01
Investigator:	SORGI
Referred To:	Not reported
Reported to Dept:	1996-02-21
CID:	297
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	1996-02-21
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-02-21
Spill Record Last Update:	1996-02-28
Spiller Name:	BOB PRICE (MNGR)
Spiller Company:	MONROE MUFFLER
Spiller Address:	2980 SHERIDAN DRIVE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MJS 02/26/96: MJS SITE INSPECT ON 2/21/96 - MET WITH BOB PRICE(MNGR). HE EXPLAINED THAT SMALL SPILL (APPROX TWO QUARTS) OCCURRED LAST WEEK IN REPAIR BAY FROM LEAKING OIL FILTER GASKET ON VEHICLE. SPEEDI DRI APPLIED AND DISPOSED IN REGULAR WASTE STREAM. LIGHT SHEEN IN SMALL AREA ON ASPHALT JUST OUTSIDE REPAIR BAY - NO THREAT. NO FURTHER ACTION REQUIRED. MJS CLOSE FILE. "
Remarks:	"sheen in parking lot apparently coming from building and possibly going into storm drain"

MONROE MUFFLER (Continued) **S102245168**

All Materials:

Site ID:	84149
Operable Unit ID:	1026021
Operable Unit:	01
Material ID:	355040
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

AF136 **MONRO MUFFLER BRAKE INC** **EDR Hist Auto** **1021842794**
West **2980 SHERIDAN DR** **N/A**
< 1/8 **TONAWANDA, NY 14150**
0.032 mi.
170 ft. **Site 3 of 6 in cluster AF**

Actual: EDR Hist Auto
598 ft.

Focus Map:
6

Year:	Name:	Type:
1977	BUNDY FREDERICK W	Gasoline Service Stations
1978	BUNDY FREDERICK W	Gasoline Service Stations
1979	BUNDY FREDERICK W	Gasoline Service Stations
1980	BUNDY FREDERICK W	Gasoline Service Stations
1986	MONRO MUFFLER & BRAKE	Automotive Repair Shops, NEC
1987	MONROE MUFFLER & BRAKE	Automotive Repair Shops, NEC
1988	MONROE MUFFLER & BRAKE	Automotive Repair Shops, NEC

AF137 **UNDERGROUND AUTOSOUND** **NY Spills** **S113820057**
West **2980 SHERIDAN DR** **N/A**
< 1/8 **TONAWANDA, NY**
0.032 mi.
170 ft. **Site 4 of 6 in cluster AF**

Actual: SPILLS:
598 ft.

Focus Map:
6

Spill Number/Closed Date:	1305137 / 2013-08-12
Facility ID:	1305137
Facility Type:	ER
DER Facility ID:	440816
Site ID:	485692
DEC Region:	9
Spill Cause:	Deliberate
Spill Class:	D5
SWIS:	1564
Spill Date:	2013-07-15
Investigator:	SACALAND
Referred To:	NYSDEC - DIVISION OF WATER
Reported to Dept:	2013-08-12
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other

UNDERGROUND AUTOSOUND (Continued) **S113820057**

Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2013-08-12
Spill Record Last Update:	2013-08-12
Spiller Name:	ROTHOUSE, ERIC
Spiller Company:	UNDERGROUND AUTOSOUND
Spiller Address:	2980 SHERIDAN DR
Spiller Company:	999
Contact Name:	ROTHOUSE, ERIC
DEC Memo:	"8/12/13:RECEIVED NATIONAL RESPONSE CENTER (NRC) REPORT NUMBER 1056839. SENT SPILL REPORT AND NRC REPORT TO JEFF KONSELLA - NYSDEC DIV OF WATER. NO FURTHER WORK REQUIRED. NOTE TO FILE: DOES NOT REQUIRE MUNICIPAL OR PUBLIC NOTIFICATION NO PAPER FILE."
Remarks:	"Unknown amounts dumped into the shop drain. Impacts unk."

All Materials:

Site ID:	485692
Operable Unit ID:	1235350
Operable Unit:	01
Material ID:	2234562
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Site ID:	485692
Operable Unit ID:	1235350
Operable Unit:	01
Material ID:	2234565
Material Code:	0536A
Material Name:	degreaser
Case No.:	Not reported
Material FA:	Other
Quantity:	1.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Site ID:	485692
Operable Unit ID:	1235350
Operable Unit:	01
Material ID:	2234564
Material Code:	0055A
Material Name:	paint
Case No.:	Not reported
Material FA:	Other
Quantity:	1.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

UNDERGROUND AUTOSOUND (Continued) **S113820057**

Site ID:	485692
Operable Unit ID:	1235350
Operable Unit:	01
Material ID:	2234560
Material Code:	0021
Material Name:	transmission fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Site ID:	485692
Operable Unit ID:	1235350
Operable Unit:	01
Material ID:	2234561
Material Code:	0043A
Material Name:	antifreeze
Case No.:	Not reported
Material FA:	Other
Quantity:	1.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Site ID:	485692
Operable Unit ID:	1235350
Operable Unit:	01
Material ID:	2234563
Material Code:	0042A
Material Name:	xylene (mixed)
Case No.:	01330207
Material FA:	Hazardous Material
Quantity:	1.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

P138 **ROW** **NY Spills** **S106735842**
NE **MAIN AND KENMORE** **N/A**
< 1/8 **BUFFALO, NY**
0.033 mi.
172 ft. **Site 10 of 10 in cluster P**

Actual:
654 ft.

Focus Map:
8

SPILLS:

Spill Number/Closed Date:	0485256 / 2005-11-03
Facility ID:	0485256
Facility Type:	ER
DER Facility ID:	269837
Site ID:	334620
DEC Region:	9
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	1502
Spill Date:	2004-01-01
Investigator:	FXGALLEG

ROW (Continued) **S106735842**

Referred To:	Not reported
Reported to Dept:	2004-12-01
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-12-02
Spill Record Last Update:	2005-11-03
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	Not reported
Contact Name:	RONALD MANDELL , CONSULTANT
DEC Memo:	"12/2/04 FG SPOKE TO RONALD MANDELL, CONSULTANT FOR NYSDOT 8360247. HE SAID THE REMOVED SOIL AND COLLECTED EXCAVATION SAMPLES. THEY DISPOSED OF THE CONTAMINATED SOIL AS WELL. HE WILL SUBMIT THE REPORT. 12/21/04 RECD DISPOSAL RECEIPTS FOR EXCAVATED SOILS AND DISPOSAL/HAZ DETERMINATION ANALYTICAL. NO MAP OR EXCAVATION ANALYTICAL PROVIDED. PHONE REQUEST TO RON MANDELL ASKING FOR THE ADDITIONAL INFO. 1/5/05 FG SPOKE TO TRACEY WHEELER WITH NYSDOT. SHE SAID THE CITY OF BUFFALO OWNS THE PROPERTY EVEN THOUGH IT IS IN AMHERST. SHE SAID THE NYSDOT WILL COLLECT A SOIL SAMPLE FOR 8260 STARS ANALYSIS BECAUSE NONE WAS COLLECTED WHEN THE WORK WAS COMPLETED EVEN THOUGH OP TECH, NYSDEC'S CURRENT LOW BID CONTRACTOR COMPLETED THE SITE WORK. MS. WHEELER WILL LET US KNOW WHEN SITE WORK WILL START. 6/28/05 FG SPOKE TO TRACY WHEELER WITH NYSDOT. SHE SAID THAT THE BORINGS WERE COLLECTED AT THE SITE. CONTAMINATION WAS NOTED IN THE BORINGS WITH ODOR AND ELEVATED PID READINGS. SHE SAID THAT THE ANALYTICAL CAME BACK AND IS BELOW STARS. SHE WILL PROVIDE THE BORING LOGS AND ANALYTICAL. 7/22/05 TRACY WHEELER WITH NYSDOT CALLED AND SAID THAT SHE RECD THE DATA FROM THE RECENT SUBSURFACE INVESTIGATION. THE PID'S ARE HIGH BUT NOTHING EXCEEDS TAGMS. SHE WILL SUBMIT THE DATA TO THE CITY AND THEY WILL PROVIDE TO THE STATE. 8/15/05 TRACY WHEELER WITH NYSDOT CALLED. SHE SAID NYSDOT REMOVED SOME PETROLEUM CONTAMINATED SOIL FROM THE SITE WHILE INSTALLING A SEWER LINE ON SITE. THE CONTAMINATED SOIL WAS TRUCKED TO THE TONAWANDA LANDFILL. THE CITY WILL PROVIDE A COPY OF THE RECEIPT - MR. RON MANDELL, 836-0247. MR. JOHN BIDELL WITH THE CITY DPW WILL PROVIDE A COPY OF THE SUBSURFACE INVESTIGATION REPORT 851-4785. 10/26/05 FG DKK MEETING WITH MOBIL AND GES. NOTIFIED MOBIL THAT SOIL WAS REMOVED FROM THE FORMER MOBIL SITE BY NYSDOT WHILE ROAD WORK WAS BEING COMPLETED. 11/3/05 NYSDOT SUBMITTED DISPOSAL RECEIPTS FOR ADDITIONAL SOIL REMOVED FROM THE SITE WHILE INSTALLING A NEW SEWER LINE IN FRONT OF THE UNIVERSITY PLAZA ON MAIN. THEY REMOVED 400 YDS OF SOILS CONTAINING VOLATILE ORGANIC PID READINGS ABOVE 5PPM. THE SEWER HAS ALREADY BEEN INSTALLED AND THE ROAD REPLACED. NO ANALYTICAL EXCAVATION WAS PRESENTED. THE AREA OF THE FORMER MOBIL STATION AT THE INTERSECTION OF MAIN AND KENMORE HAD NO FURTHER WORK COMPLETED. THE PREVIOUS SPILL ASSOCIATED WITH THIS SITE IS 9207319. PETROLEUM CONTAMINATED SOIL WAS REMOVED AND DISPOSED OF. EXCAVATION SAMPLES WERE BELOW TAGM 4046 LEVELS BUT ABOVE STARS AND IN 1996, THE SITE WAS MADE INACTIVE. NO ADDITIONAL WORK ON THE FORMER MOBIL SITE WILL BE

ROW (Continued) **S106735842**

Remarks: COMPLETED. SPILLS WILL MAKE THE ENTIRE SITE INACTIVE DUE TO THE PRESENCE OF ELEVATED PID'S AT TEST PITS 1 AND 2 AND THE SAMPLE RESULTS SHOWING LUBE OIL PRESENT AT TEST PIT 2."
"Contamination found while doing road work, spill not called in by contractors, NYSDOT just now became aware of problem, the contractor reported to DOT that they disposed of an unknown quantity of contaminated soils. They reported it smelled like gasoline. There was a gasoline station on the corner. The impacted area is on the North East corner."

All Materials:

Site ID:	334620
Operable Unit ID:	1096746
Operable Unit:	01
Material ID:	576631
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	False

G139 **FIRESTONE** **NY LTANKS** **S100493950**
NNW **NIAGARA FALLS BLVD. MAPLE** **N/A**
< 1/8 **AMHERST, NY**
0.034 mi.
178 ft. **Site 2 of 3 in cluster G**

Actual:
583 ft.

Focus Map:
3

LTANKS:

Spill Number/Closed Date:	9206303 / 1992-10-02
Facility ID:	9206303
Site ID:	218987
Spill Date:	1992-08-04
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	1992-10-02
SWIS:	1522
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	1992-08-28
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1992-10-02
Spill Record Last Update:	1992-10-14
Spiller Name:	Not reported
Spiller Company:	BRIDGESTONE/FIRESTONE INC
Spiller Address:	1200 FIRESTONE PARKWAY
Spiller County:	001

FIRESTONE (Continued) **S100493950**

Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 9
DER Facility ID: 181128
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 10/02/92: SEE SPILL NO. 9206340 - DUPLICATE OF THIS SPILL (SPILL NO. 9206340 STILL ACTIVE AS OF 10/2/92). 10/02/92: SEE SPILL NO. 9206340 - DUPLICATE OF THIS SPILL (SPILL NO. 9206340 STILL ACTIVE AS OF 10/2/92; CLOSED THIS SPILL OUT 10/2/92). "
Remarks: "SEE SPILL NO. 9206340 - DUPLICATE OF THIS SPILL. SPILL NO. 9206340 STILL ACTIVE AS OF 10/2/92. CLOSED THIS SPILL OUT 10/2/92."

All Materials:
Site ID: 218987
Operable Unit ID: 969963
Operable Unit: 01
Material ID: 410474
Material Code: 0022
Material Name: waste oil/used oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Site ID: 218987
Operable Unit ID: 969963
Operable Unit: 01
Material ID: 410475
Material Code: 1101A
Material Name: hydraulic acid
Case No.: Not reported
Material FA: Other
Quantity: .00
Units: Not reported
Recovered: .00
Oxygenate: Not reported

G140 **FIRESTONE 955 NFB** **NY LTANKS** **S100493953**
NNW **NIAGARA FALLS BLVD MAPLE** **N/A**
< 1/8 **AMHERST, NY**
0.034 mi.
178 ft. **Site 3 of 3 in cluster G**

Actual:
583 ft.

Focus Map:
3

LTANKS:
Spill Number/Closed Date: 9206340 / 1993-01-19
Facility ID: 9206340
Site ID: 191032
Spill Date: 1992-08-04
Spill Cause: Tank Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: C3
Cleanup Ceased: 1993-01-19
SWIS: 1522
Investigator: RMCROSSE

FIRESTONE 955 NFB (Continued) **S100493953**

Referred To:	Not reported
Reported to Dept:	1992-08-28
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1992-09-02
Spill Record Last Update:	1993-02-01
Spiller Name:	Not reported
Spiller Company:	BRIDGESTONE/FIRESTONE INC
Spiller Address:	1200 FIRESTONE PARKWAY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	9
DER Facility ID:	159338
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 09/02/92: RMC/CASEY CHAMPION/PHONE WILL RUN TCLP RESULTS DUE 10/1/92. 09/02/92: RMC/CASEY CHAMPION/PHONE WILL RUN TCLP RESULTS DUE 10/1/92. SEE SPILL NO. 9206340 - DUPLICATE OF THIS SPILL. CLOSED SPILL NO.9206340OUT AS OF 10/2/92. 09/02/92: RMC/CASEY CHAMPION/PHONE WILL RUN TCLP RESULTS DUE 10/1/92. SEE SPILL NO. 9206303 - DUPLICATE OF THIS SPILL. CLOSED SPILL NO.9206303OUT AS OF 10/2/92. 11/16/92: RMC/CASEY CHAMPION/PHONE - RESAMPLED BELOW DETECTION ON TCLP, BUT DISPOSING BASED ON VISUAL. BFI APPROVAL SCHEDULED IN TWO WEEKS. WILLFAX TCLP RESULTS. DISPOSAL RECEIPT DUE 1/1/93. 01/19/93: RMC/RECEIVED CLOSURE REPORT EXCAVATION, DISPOSAL, DISPOSAL, AND LAB ANALYSIS OK. CLOSE OUT. "
Remarks:	"30 YDS SOIL IN PITS LINED W/ PLASTIC AT NFB. SEE SPILL NO. 9206303 - DUPLICATE OF THIS SPILL. CLOSED OUT SPILL NO. 9206303 AS OF 10/2/92."

All Materials:

Site ID:	191032
Operable Unit ID:	973586
Operable Unit:	01
Material ID:	410513
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Site ID:	191032
Operable Unit ID:	973586
Operable Unit:	01
Material ID:	410514
Material Code:	1101A
Material Name:	hydraulic acid
Case No.:	Not reported
Material FA:	Other

FIRESTONE 955 NFB (Continued) **S100493953**

Quantity: .00
Units: Not reported
Recovered: .00
Oxygenate: Not reported

141
North
< 1/8
0.034 mi.
180 ft.

COMMERCIAL DEVELOPMENT 4100 MAPLE RD **FINDS** **1008932578**
4080-4120 MAPLE RD **N/A**
AMHERST, NY 14221

Actual:
594 ft.

Focus Map:
4

FINDS:

Registry ID: 110023022851

Environmental Interest/Information System

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

AF142
West
< 1/8
0.035 mi.
183 ft.

MONRO MUFFLER BRAKE #56 **NY AST** **1000366035**
2980 SHERIDAN DR **RCRA NonGen / NLR** **NYD162544241**
TONAWANDA, NY 14150 **FINDS**
ECHO

Site 5 of 6 in cluster AF

Actual:
597 ft.

Focus Map:
6

AST:

Region: STATE
DEC Region: 9
Site Status: Active
Facility Id: 9-600273
Program Type: PBS
UTM X: 188233.94756
UTM Y: 4765791.89831
Expiration Date: 07/31/2021
Site Type: Other Wholesale/Retail Sales

Affiliation Records:

Site Id: 55133
Affiliation Type: Facility Owner
Company Name: MONRO MUFFLER BRAKE INC
Contact Type: DIRECTOR OF FACILITIES
Contact Name: THOMAS M. GIANNONE
Address1: 200 HOLLEDER PARKWAY
Address2: Not reported
City: ROCHESTER
State: NY
Zip Code: 14615-3808
Country Code: 001
Phone: (716) 647-6400
EMail: Not reported
Fax Number: Not reported

MONRO MUFFLER BRAKE #56 (Continued) **1000366035**

Modified By:	AESKALSK
Date Last Modified:	2016-05-23
Site Id:	55133
Affiliation Type:	Mail Contact
Company Name:	MONRO MUFFLER BRAKE INC
Contact Type:	Not reported
Contact Name:	ENV COMPLIANCE OFFICIAL
Address1:	200 HOLLEDER PARKWAY
Address2:	Not reported
City:	ROCHESTER
State:	NY
Zip Code:	14615-3808
Country Code:	001
Phone:	(716) 647-6400
EMail:	Not reported
Fax Number:	Not reported
Modified By:	LDGOMEZ
Date Last Modified:	2011-04-21
Site Id:	55133
Affiliation Type:	Facility Operator
Company Name:	MONRO MUFFLER BRAKE #56
Contact Type:	Not reported
Contact Name:	MONRO MUFFLER BRAKE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NY
Zip Code:	Not reported
Country Code:	001
Phone:	(716) 833-4000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KNGLASER
Date Last Modified:	2016-02-23
Site Id:	55133
Affiliation Type:	Emergency Contact
Company Name:	MONRO MUFFLER BRAKE INC
Contact Type:	Not reported
Contact Name:	TOM GIANNONE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(585) 647-6400
EMail:	Not reported
Fax Number:	Not reported
Modified By:	AESKALSK
Date Last Modified:	2016-11-28

Tank Info:

Tank Number:	001

MONRO MUFFLER BRAKE #56 (Continued) **1000366035**

Tank Id: 172126
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Equipment Records:
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None

Tank Location: 2
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 12/01/1989
Capacity Gallons: 275
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: AESKALSK
Last Modified: 04/14/2017
Material Name: waste oil/used oil

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: MONRO MUFFLER BRAKE #56
Facility address: 2980 SHERIDAN DR
TONAWANDA, NY 14150-9417
EPA ID: NYD162544241
Mailing address: PO BOX 22720
ROCHESTER, NY 14692
Contact: Not reported
Contact address: PO BOX 22720
ROCHESTER, NY 14692
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: MONRO MUFFLER BRAKE
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212

MONRO MUFFLER BRAKE #56 (Continued) **1000366035**

Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: MONRO MUFFLER BRAKE
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: MONRO MUFFLER BRAKE #56
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: MONRO MUFFLER BRAKE #56
Classification: Not a generator, verified

Date form received by agency: 04/07/1989
Site name: MONRO MUFFLER BRAKE #56
Classification: Small Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF

MONRO MUFFLER BRAKE #56 (Continued) **1000366035**

LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: X001
. Waste name: WASTE OILS

Violation Status: No violations found

FINDS:

Registry ID: 110004385433

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000366035
Registry ID: 110004385433
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004385433

---

143 **I/A/O 3 MALLARD CT** **NY Spills** **S109582650**
East **3 MALLARD CT** **N/A**
< 1/8 **AMHERST, NY**
0.036 mi.
188 ft.

Actual:
578 ft.

Focus Map:
2

SPILLS:
Spill Number/Closed Date: 0901545 / 2009-10-22
Facility ID: 0901545
Facility Type: ER
DER Facility ID: 362670
Site ID: 413540
DEC Region: 9
Spill Cause: Equipment Failure
Spill Class: C3
SWIS: 1522
Spill Date: 2009-05-07
Investigator: RJJONAK
Referred To: Not reported
Reported to Dept: 2009-05-07
CID: Not reported
Water Affected: Not reported
Spill Source: Private Dwelling
Spill Notifier: Other
Cleanup Ceased: Not reported

I/A/O 3 MALLARD CT (Continued) **S109582650**

Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-05-07
Spill Record Last Update:	2009-10-22
Spiller Name:	LISA MONTASANO
Spiller Company:	I/A/O 3 MALLARD CT
Spiller Address:	3 MALLARD CT
Spiller Company:	999
Contact Name:	LISA MONTASANO
DEC Memo:	"5/8/2009: RJJ TELECON LISA MONTESANO,NATIONAL GRID,SHE SAID THAT A PADMOUNT TRANSFORMER LEAKED OUT ~2 GAL OF TRANSFORMER OIL ON THE SOIL NEAR THE PAD...THEY HIRED OP-TECH ENVIRONMENTAL TO SCRAPE UP THE SMALL AFFECTED SOIL,CLEAN THE AREA UNDER THE TRANSFORMER,& DISPOSE ALL THE MATERIAL...THEY WILL ALSO TEST FOR ANY PCBS..LISA WILL SEND ME THE DISPOSAL RECEIPTS...RJJ AT SITE AT 1000...THE CLEAN UP IS ACCEPTABLE. 10/22/2009: RECEIVED THE DISPOSAL RECEIPTS FROM OP-TECH FOR THE ALL THE MATERIAL TAKEN TO THEIR HIGH ACRES LANDFILL & THE PBC ANALYSIS OF THE TRANSFORMER OIL,WHICH WAS ALL NON-DETECT FOR ANY PCBS...THE SPILL HAS BEEN CLEANED UP & PROPERLY DISPOSED OF...NO FURTHER ACTION NEEDED...SPILL CLOSED OUT."
Remarks:	"DUE TO A LEAKING TRANSFORMER ABOUT 2 GALLONS OF TRANSFORMER FLUID SPILLED TO SOIL. UNK IF IT CONTAINES PBCS CLEAN UP IS IN PROGRESS."

All Materials:

Site ID:	413540
Operable Unit ID:	1169964
Operable Unit:	01
Material ID:	2161670
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	2.00
Oxygenate:	Not reported

AG144 **KNOLL SERVICE STATION** **EDR Hist Auto** **1020490362**
West **2965 SHERIDAN DR** **N/A**
< 1/8 **TONAWANDA, NY 14150**
0.037 mi.
193 ft. **Site 1 of 3 in cluster AG**

Actual: EDR Hist Auto
600 ft.

Focus Map: **6**

Year:	Name:	Type:
1970	WALDOWSKI HENRY	Gasoline Service Stations
1982	KNOLL DANIEL A	Candy, Nut, And Confectionery Stores
1983	KNOLL DANIEL A	Gasoline Service Stations
1985	KNOLL DANIEL A	Gasoline Service Stations
1986	MOBILE	Gasoline Service Stations
1986	KNOLL DANIEL A	Gasoline Service Stations
1987	KNOLL DANIEL A	Gasoline Service Stations
1987	MOBILE	Gasoline Service Stations

KNOLL SERVICE STATION (Continued) **1020490362**

1988	KNOLL DANIEL A	Gasoline Service Stations
1988	MOBILE	Gasoline Service Stations
1989	KNOLL DANIEL A	Gasoline Service Stations, NEC
1989	REIMONDO JOHN	Gasoline Service Stations
1990	KNOLL DANIEL A	Gasoline Service Stations, NEC
1990	REIMONDO JOHN	Gasoline Service Stations
1991	REIMONDO JOHN	Gasoline Service Stations
1991	KNOLL DANIEL A	Gasoline Service Stations, NEC
1992	REIMONDO JOHN	Gasoline Service Stations
1992	KNOLL DANIEL A	Gasoline Service Stations, NEC
1993	KNOLL SERVICE STATION	Gasoline Service Stations, NEC
1994	KNOLL SERVICE STATION	Gasoline Service Stations, NEC
1995	KNOLL SERVICE STATION	Gasoline Service Stations, NEC
1996	KNOLL SERVICE STATION	Gasoline Service Stations, NEC
1997	KNOLL SERVICE STATION	Gasoline Service Stations, NEC
1998	KNOLL SERVICE STATION	Gasoline Service Stations, NEC
1999	KNOLL SERVICE STATION	Gasoline Service Stations, NEC
2000	KNOLL SERVICE STATION	Gasoline Service Stations, NEC
2001	KNOLL SERVICE STATION	Gasoline Service Stations, NEC
2002	KNOLL SERVICE STATION	Gasoline Service Stations, NEC
2003	KNOLLS MOBIL SERVICE STATION	Gasoline Service Stations
2004	KNOLLS MOBIL SERVICE STATION	Gasoline Service Stations
2011	KNOLLS MOBIL SVC STATION	Gasoline Service Stations

AG145 **MOBIL OIL CROP SS H4J** **RCRA-CESQG** **1000553468**
West **2965 SHERIDAN DR** **FINDS** **NYD986958890**
< 1/8 **TONAWANDA, NY 14150** **ECHO**
0.037 mi. **NY MANIFEST**
193 ft. **Site 2 of 3 in cluster AG**

Actual:
600 ft.

Focus Map:
6

RCRA-CESQG:

Date form received by agency:	01/01/2007
Facility name:	MOBIL OIL CROP SS H4J
Facility address:	2965 SHERIDAN DR TONAWANDA, NY 14150-9418
EPA ID:	NYD986958890
Mailing address:	GALLOWS RD - MKTG ENVIRON FAIRFAX, NY 22037
Contact:	Not reported
Contact address:	GALLOWS RD - MKTG ENVIRON FAIRFAX, NY 22037
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from

MOBIL OIL CROP SS H4J (Continued) **1000553468**

the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	MOBIL OIL CORP
Owner/operator address:	3225 GALLOWS RD
	FAIRFAX, VA 22037
Owner/operator country:	US
Owner/operator telephone:	703-849-3330
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	MOBIL OIL CORP
Owner/operator address:	3225 GALLOWS RD
	FAIRFAX, VA 22037
Owner/operator country:	US
Owner/operator telephone:	703-849-3330
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	01/01/2006
Site name:	MOBIL OIL CROP SS H4J
Classification:	Conditionally Exempt Small Quantity Generator

Date form received by agency:	07/08/1999
Site name:	MOBIL OIL CROP SS H4J
Classification:	Not a generator, verified

MOBIL OIL CROP SS H4J (Continued) **1000553468**

Date form received by agency: 04/10/1991
Site name: MOBIL OIL CROP SS H4J
Classification: Small Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

FINDS:

Registry ID: 110004470117

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000553468
Registry ID: 110004470117
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004470117

NY MANIFEST:
Country: USA
EPA ID: NYD986958890
Facility Status: Not reported
Location Address 1: 2965 SHERIDAN DRIVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: TONAWANDA
Location State: NY
Location Zip: 14150
Location Zip 4: 9418

NY MANIFEST:
EPAID: NYD986958890

MOBIL OIL CROP SS H4J (Continued) **1000553468**

Mailing Name:	EXXON MOBIL
Mailing Contact:	DOUG LIDDELL
Mailing Address 1:	2965 SHERIDAN DRIVE
Mailing Address 2:	Not reported
Mailing City:	TONAWANDA
Mailing State:	NY
Mailing Zip:	14150
Mailing Zip 4:	9418
Mailing Country:	USA
Mailing Phone:	9999999999

NY MANIFEST:

Document ID:	NYH1348623
Manifest Status:	Not reported
seq:	Not reported
Year:	2004
Trans1 State ID:	NYAC25373
Trans2 State ID:	Not reported
Generator Ship Date:	03/17/2004
Trans1 Recv Date:	03/17/2004
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/09/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986958890
Trans1 EPA ID:	NYD097644801
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD049836
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00400
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00

MOBIL OIL CROP SS H4J (Continued) **1000553468**

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AG146 **MOBIL OIL** **NY LTANKS** **S105141863**
West **2965 SHERIDAN DRIVE** **NY Spills** **N/A**
< 1/8 **TONAWANDA, NY**
0.037 mi.
193 ft. **Site 3 of 3 in cluster AG**

Actual:
600 ft.

Focus Map:
6

LTANKS:

Spill Number/Closed Date:	0605174 / 2007-11-30
Facility ID:	0605174
Site ID:	368295
Spill Date:	2006-08-03
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	1564
Investigator:	RJJONAK
Referred To:	Not reported
Reported to Dept:	2006-08-03
CID:	406
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2006-08-03
Spill Record Last Update:	2007-11-30
Spiller Name:	SHIMIKA BOWERS
Spiller Company:	EXXON MOBILE #11544
Spiller Address:	SHERIDAN DRIVE
Spiller County:	001
Spiller Contact:	SHIMIKA BOWERS
Spiller Phone:	(800) 997-7725
Spiller Extention:	2819
DEC Region:	9
DER Facility ID:	258151
DEC Memo:	"8/15/2006: RJJ TELECON STEVE LITTEN,GES,HE SAID THAT A DIESEL TANK FAILED A PRECISION TEST AND THE UST HAD 32' OF WATER IN IT...AFTER THEIR INVESTIGATION,THEY FOUND THE VENT-PIPE,WHICH IS NOT ALONGSIDE THE BUILDING,BROKE OFF AT THE GROUND...IT APPEARS THAT THIS IS WHERE THE WATER CAME IN FROM...GES WILL REPAIR/REPLACE THE VENT-PIPE,RE-TEST THE UST,THEN STEVE WILL SEND ME THE TEST RESULTS AND THEIR REPORT. 11/30/2007: THIS SPILL HAS BEEN REMEDIATED UNDER SPILL # 0105744(THE USTS HAVE ALL BEEN REMOVED)...REFER TO THAT SPILL # FOR ANY INFORMATION...THIS SPILL CLOSED OUT. ***** COMPUTER FILE ONLY *****"
Remarks:	"diesel tank failed the precision test. The site is decommissioned."

All TTF:

Facility ID:	0605174
Spill Number:	0605174
Spill Tank Test:	1550179
Site ID:	368295

MOBIL OIL (Continued) **S105141863**

Tank Number:	4
Tank Size:	6100
Material:	0008
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	18
Test Method 2:	Alert Model 1000 plus 1050 (Formerly Gilbarco Precision)
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	368295
Operable Unit ID:	1126177
Operable Unit:	01
Material ID:	2115698
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	9008391 / 1991-05-16
Facility ID:	9008391
Site ID:	320414
Spill Date:	1990-10-31
Spill Cause:	Tank Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Not reported
Cleanup Ceased:	1991-05-16
SWIS:	1564
Investigator:	MJHINTON
Referred To:	Not reported
Reported to Dept:	1990-10-31
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	1991-02-11
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1990-11-06
Spill Record Last Update:	1991-05-16
Spiller Name:	Not reported
Spiller Company:	MOBIL REFINING AND MARK
Spiller Address:	3225 GALLOWS ROAD
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported

MOBIL OIL (Continued) **S105141863**

Spiller Extention:	Not reported
DEC Region:	9
DER Facility ID:	258151
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MJH 11/06/90: LEAK DETECTOR TO BE TESTED ALONG WITH FILL PIPES. 12/20/90: MJH SENT LETTER 12/14/90 REQUESTING REPORT. 02/28/91: MJH SENT LETTER 02/11/91 REQUESTING REPORT. 05/16/91: FINAL TEST REPORT RECIEVED NO FURTHER ACTION NEEDED REFER TO SPILL NO 9012026 FOR FURTHER INFORMATION. "
Remarks:	"SHEEN DISCOVERED IN MANWAY PIT"

All Materials:

Site ID:	320414
Operable Unit ID:	945596
Operable Unit:	01
Material ID:	432223
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	9012026 / 1992-06-11
Facility ID:	9012026
Site ID:	320415
Spill Date:	1991-02-17
Spill Cause:	Tank Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	B3
Cleanup Ceased:	1992-06-11
SWIS:	1564
Investigator:	SORGI
Referred To:	Not reported
Reported to Dept:	1991-02-19
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	1991-02-19
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1991-02-20
Spill Record Last Update:	1992-11-05
Spiller Name:	Not reported
Spiller Company:	MOBIL OIL CORPORATION
Spiller Address:	675 BROOKS AVENUE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	9
DER Facility ID:	258151
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was

MOBIL OIL (Continued) **S105141863**

MJS 02/19/91: MJS SITE INSPECTION. PINHOLE FOUND IN PIPING - TO BE REPAIRED. CONTAMINATION STAGED ON SITE ON PLASTIC AND COVERED. TANK SYSTEM WILL BE TESTED AT COMPLETION OF WORK. 02/22/91: MJS TELECON WITH STEVE COOPER. SYSTEM WAS TESTED AND FAILED. HE THINKS AIR IS IN LINE. WILL SELL SOME PRODUCT TO PURGE AIR AND RETEST. 02/27/91: MJS SITE INSPECTION. SHEEN ON WATER IN EXCAVATION. TO BE LEFT OPEN SO PRODUCT CAN BE PADDED UP. CA BATT WILL WAIT FOR OK TO BACKFILL. STEVE COOPER SAID LINE WAS TESTED AND PASSED. 03/04/91: MJS RECEIVED LETTER AND LINE TEST RESULTS FROM MOBIL OIL. LINE TESTED TIGHT. ARRANGEMENTS BEING MADE FOR SAMPLING AND DISPOSAL OF CONTAMINATED SOIL. 03/05/91: MJS SITE INSPECTION. SHEEN IN EXCAVATION COMING FRON SATURATED SORBENT PADS THAT WERE LEFT IN HOLE BEFORE IT ICED OVER. 03/06/91: MJS TELECON WITH NIAGARA TANK AND PUMP. SAID THEY COULD BACKFILL AFTER PADDING UP REMAINING SHEEN. 10/29/91: MJS MEETING AT OFFICE WITH MOBIL. SOIL HAS BEEN DISPOSED OF. MOBIL WILL SEND RECEIPTS. 04/30/92: MJS MEETING WITH MOBIL(KEVIN SCHROEDER). EXPLAINED TO HIM THAT DEC HAS STILL NOT RECEIVED DISPOSAL RECEIPTS FOR THE SOIL. KEVIN WILL SEND RECEIPTS. 06/11/92: RECEIVED LETTER AND DISPOSAL INFO FROM MOBIL. "

Remarks: "FRP UST HAD A LINE LEAK. TANK OUT OF SERVICE. CA BATT TO REPAIR LINE. PADS USED IN SUBMERSIBLE PUMP AREA TO ABSORB PRODUCT. CONTAMINATION STAGED ON SITE ON PLASTIC AND COVERED."

All Materials:

Site ID:	320415
Operable Unit ID:	951914
Operable Unit:	01
Material ID:	428534
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	9705822 / 2000-02-15
Facility ID:	9705822
Site ID:	320416
Spill Date:	1997-08-13
Spill Cause:	Tank Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	1564
Investigator:	SORGI
Referred To:	Not reported
Reported to Dept:	1997-08-13
CID:	366
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	1997-08-14
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0

MOBIL OIL (Continued) **S105141863**

Date Entered In Computer:	1997-08-13
Spill Record Last Update:	2002-04-18
Spiller Name:	RICHARD CICCOTELLI
Spiller Company:	MOBIL OIL/BUSINESS RESOUR
Spiller Address:	464 DOUGHTY BLVD, 2ND FLR
Spiller County:	001
Spiller Contact:	JOHN REIMONDO JR
Spiller Phone:	(716) 835-6353
Spiller Extention:	Not reported
DEC Region:	9
DER Facility ID:	258151
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MJS 08/14/97: MJS TELECON TO TANKNOLOGY. MJS LEFT MESSAGE FOR MIKE LAMARRE (MOBIL). MJS TELECON WITH TRISH NEWDECK (GES). SHE STATED PROBLEM FOUND IN PIPING AND FUEL RELEASED TO TANK PIT AREA. THEY HAVE PUMPED APPROX 700 GALLONS OF FUEL/WATER. 08/14/97: MJS SITE INSPECTION, MET WITH JOHN REIMONDO (STATION MANAGER). CONCRETE PAD PARTIALLY REMOVED AND CORDONED OFF. FIFTEEN DRUMS ON SITE. MR REIMONDO STATED THAT THEY ARE BRINGING FRAC TANK TOMORROW TO CONTINUE PUMPING. 09/15/97: MJS TELECON TO JOHN REIMONDO FOR UPDATE. LEAK FOUND IN FIBERGLASS PIPING AND REPAIRED. OIL/WATER FROM DRUMS WAS TREATED VIA CARBON. 09/17/97: MJS RECEIVED REPORT FROM GES INC WITH EFFLUENT SAMPLE RESULTS. TWO 180-POUND CARBON DRUMS USED IN SERIES. 4820 GALLONS WATER TREATED TOTAL. NO COMPOUNDS DETECTED AFTER CARBON TREATMENT. 09/23/97: MJS SENT LETTER TO MOBIL REQUIRING SAMPLING OF TANK PIT MONITORING WELLS TO DETERMINE CONDITION OF GROUNDWATER. RESULTS DUE 11/1/97. 09/26/97: MJS RECEIVED MESSAGE FROM BRIAN CAREY THAT THEY WILL SAMPLE TANK PIT WELLS ON MON 9/29. 10/06/97: MJS TELECON WITH BRIAN CAREY. THEY WILL USE VACUUM TRUCK ON FRI 10/10 TO REMOVE WATER FROM TANK PIT PRIOR TO TAKING SAMPLES. WATER WILL BE TREATED AT MOBIL TERMINAL GW TREATMENT SYSTEM. MR CAREY WILL FORWARD LETTER TO THIS EFFECT. 10/10/97: MJS TELECON WITH MR CAREY. THEY REMOVED 5000 GALLONS OF WATER FROM TANK PIT AND DROPPED WATER LEVEL APPROX 1.5 FEET. THEY WILL REMOVE AN ADDITIONAL 5000 GALLONS LATER TODAY AND SAMPLE TANK PIT WELLS NEXT WEEK. MJS RECEIVED LETTER FROM MR CAREY. 10/22/97: MJS OFFICE MEETING WITH MOBIL AND GES. SAMPLES COLLECTED ON 10/15 AND RESULTS DUE BY END OF MONTH. REPORT DUE BY MID-NOVEMBER. IF RESULTS INDICATE CONTAMINATION THEY WILL REMOVE ADDITIONAL WATER FROM TANK PIT. 12/04/97: MJS TELECON FROM BRIAN CAREY. MOBIL CREW ON SITE PERFORMING TANK WORK. TOP OF TANKS UNCOVERED. WATER PUMPED FROM TANK PIT TO FRAC TANK. WATER HAS PETROLEUM ODOR BUT NO PRODUCT. MR CAREY REQUESTED APPROVAL TO TRANSPORT WATER TO MOBIL TERMINAL FOR TREATMENT AS BEFORE. MJS AGREED. REPORT DUE THIS MONTH. 12/15/97: MJS RECEIVED LETTER AND REPORT FROM MOBIL. TOTAL OF 8500 GALLONS OF WATER REMOVED FROM TANK PIT ON 10/10/99. TANK PIT WELLS SAMPLED ON 10/15, RESULTS INDICATE ELEVATED VOC CONCENTRATIONS (59,120 PPB AND 38,485 TOTAL STARS 8021 ANALYTES). ADDITIONAL DEWATERING ON 12/4 AND WATER STORED IN FRAC TANK PENDING TRANSPORTATION TO MOBIL TERMINAL FOR TREATMENT. LETTER STATES THAT MOBIL IS PREPARING A WORK PLAN FOR THIS SITE. 05/04/98: MJS TELECON WITH BRIAN CAREY. THEY PLAN TO UTILIZE A MOBILE TREATMENT UNIT (TRAILER) TO REMEDIATE TANK PIT AT VARIOUS TIMES THIS SEASON. THEY WILL BE ON SITE WITH EQUIPMENT MON 5/9. 07/16/98: MJS RECEIVED REPORT FOR JAN-JUNE 1998 FROM MOBIL. REMEDIATION TRAILER WITH GROUNDWATER TREATMENT SYSTEM OPERATED ON SITE ON MAY 11-13 AND JUNE 2-4. WATER TREATED VIA SERIES OF CARBON UNITS. INFLUENT, MIDDLE AND EFFLUENT SAMPLES OBTAINED DURING EACH EVENT. TOTAL OF 30,824 GALLONS

MOBIL OIL (Continued) **S105141863**

WATER REMOVED FROM TANK PIT DURING THE TWO EVENTS. TP-1 AND TP-2 SAMPLED ON 4/29 (PRIOR TO TREATMENT EVENTS). TOTAL 8021 STARS COMPOUNDS ARE 26,656 AND 20,302 PPB. REMEDIATION EVENT PLANNED FOR LATER THIS MONTH. 11/27/98: MJS RECEIVED REPORT FOR JUL-NOV 1998. REMEDIATION EVENTS TOOK PLACE ON 7/29 AND 11/6. 24,480 GALLONS WATER TREATED DURING THESE TWO EVENTS, 60,124 GALLONS TOTAL. TP-1 AND TP-2 SAMPLED ON 7/20. ALL THREE WELLS SAMPLED ON 10/12. ANALYSIS FOR BTEX+MTBE ONLY. TP-1 TP-2 TP-3 DATE BTEX/MTBE 2690/550 10309/690 NS 7/20/98 268/840 2110/1300 5930/960 12/12/98 705/5300 174/1100 NS 1/16/99 331/1300 38/420 526/670 4/29/99 257/NS 550/ NS NS/NS 7/13/99 663/950 183/850 423/750 10/27/99 03/01/99: MJS TELECON FROM MARC FALZONE, GES. HE WILL BE SENDING REPORT. 03/02/99: MJS RECEIVED REPORT FOR NOV 1998-JAN 1999. GROUNDWATER SAMPLING PERFORMED ON 1/16/99 - BTEX AND MTBE. SEE ABOVE FOR RESULTS. NEXT REMEDIATION EVENT SCHEDULED FOR MARCH 1999 AND NEXT SAMPLING SCHEDULED FOR DEC 1999. 06/17/99: MJS RECEIVED REPORT FOR FEB-APR 1999. REMEDIATION EVENT 4/30/99-5/3/99. TANK PIT WELL SAMPLING ON 4/29/99. SEE ABOVE FOR RESULTS. NEXT SAMPLING JULY 1999. 08/30/99: MJS RECEIVED MONITORING REPORT FOR MAY-JULY 1999. WELLS SAMPLED ON 7/13/99. SEE ABOVE FOR RESULTS. THEY PLAN TO PURSUE INACTIVE STATUS AFTER NEXT SAMPLING IN OCTOBER 1999. MJS SENT LETTER TO RP STATING THAT ALL THREE WELLS MUST BE SAMPLED AND THEY MUST BE ANALYZED FOR 8021+MTBE STARS LIST, NOT JUST BTEX. 11/09/99: MJS ANNUAL OFFICE MEETING WITH MOBIL AND GES. THEY SAMPLED GROUNDWATER IN LAST TWO WEEKS AND WILL FORWARD REPORT WITH RESULTS. SITE MAY BE MADE INACTIVE DEPENDENT ON RESULTS. 12/08/99: MJS RECEIVED QUARTERLY REPORT FROM MOBIL. ALL THREE TANK FIELD WELLS SAMPLED FOR STARS LIST. TOTAL VOC'S INCLUDING MTBE: TP-1: 2181 PPB TOTAL 8021+MTBE TP-2: 1064 PPB TP-3: 1691 PPB SEE ABOVE TABLE FOR BTEX/MTBE CONCENTRATIONS. 02/15/00: MJS REVIEWED FILE AND FOUND GROUNDWATER CONCENTRATIONS STABLE. BTEX AND MTBE BELOW 1 PPM FOR LAST FOUR QUARTERS. MJS DISCUSSED SITE WITH RNL. HE STATED LEVELS OK FOR INACTIVE STATUS. MJS SENT INACTIVE LETTER TO MOBIL OIL.
"

Remarks: "CALLER STATES A LEAK IN THE SYSTEM. PRODUCT IS AN OLD SPILL. CLEAN UP IS BEING ARRANGED."

All Materials:

Site ID:	320416
Operable Unit ID:	1051997
Operable Unit:	01
Material ID:	331442
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Spill Number/Closed Date:	0105744 / 2007-07-12
Facility ID:	0105744
Facility Type:	ER
DER Facility ID:	109167
Site ID:	126282

MOBIL OIL (Continued) **S105141863**

DEC Region:	9
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	1564
Spill Date:	2001-08-28
Investigator:	RJJONAK
Referred To:	Not reported
Reported to Dept:	2001-08-28
CID:	281
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	2002-02-11
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-08-28
Spill Record Last Update:	2007-11-08
Spiller Name:	MIKE BOYEA
Spiller Company:	EXXON MOBIL
Spiller Address:	2965 SHERIDAN DR
Spiller Company:	001
Contact Name:	RICHARD BENDER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RJJ 8/29/2001: RJJ TELECON DOUG LIDDELL,GES,HE SAID THAT THEY HAVE BEEN HIRED BY MOBIL TO INVESTIGATE THE SITE AND REMEDIATE IF NECCESARY...DOUG WILL KEEP ME INFORMED...DRAFTED AND SENT A 'RESPONSIBLE PARTY' LETTER TO MOBIL OIL. 10/11/2001: DOUG LIDDELL TELECON RJJ SAID THAT THEY HAVE BEEN AT THE SITE ALL WEEK INVESTIGATING THE PROBLEM AND HE WILL SEND ME A REPORT AND THEIR WORK PLAN IN ABOUT 2 MONTHS. 1/24/2002: RECEIVED THE PROPOSED WORK PLAN FROM GES,WHICH INCLUDES INSTALLING MONITORING WELLS,SOIL AND GROUNDWATER SAMPLING,AND DOCUMENTING ALL THE RESULTS...AFTER I REVIEWED THIS WORK PLAN,I AGREEDED WITH THEIR PLAN FOR INVESTIGATION. 2/6/2002: DAVID GERMERICO,GES,TELECON RJJ,SAID THAT THEY WILL BEGIN TAKING GEO-PROBE SOIL SAMPLES ON THE PROPERTY,ON 2/11/02. 2/1/2002: RJJ AT SITE AT 1000...GES HAS STARTED GEO-PROBE SAMPLING OF THE PROPERTY...THEY WILL BE ON SITE FOR 3 DAYS. 4/18/2002: RECEIVED THE SUBSURFACE INVESTIGATION REPORT FROM GES ON THE PROPERTY...IT INDICATED THAT BTEX WAS 441 PPB IN MW-1,AND THE SOIL NEAR MW-5 EXCEEDS OUR TAGA 4046 LEVELS...GES PLANS TO COMPLETE ADDITIONAL SOIL BORINGS NEAR MW-5,AND CONTINUE GROUNDWATER SAMPLING...GES WILL FORWARD THEIR WORKPLAN FOR MY REVIEW. 8/1/2002: RECEIVED THE SITE MONITORING REPORT FOR THE SECOND QUARTER OF 2002 FROM GES...IT INDICATES THAT BETX IN GROUNDWATER AT MW-1 WAS 7,127 PPB...A WORKPLAN FOR ADDITIONAL SOIL BORINGS NEAR MW-5 WILL BE SUBMITTED IN THE THRID QUARTER OF 2002...THE NEXT GROUNDWATER MONITORING AND SAMPLING EVENT IS PLANNED FOR SEPTEMBER 2002. 10/28/2002: RECEIVED THE SITE MONITORING REPORT FOR THE THIRD QUARTER OF 2002 FROM GES...IT INDICATES THAT BETX IN GROUNDWATER WAS 3,530 PPB IN MW-1,AND MTBE WAS 2.7 PPB IN MONITORING WELL MW-3...THEY WILL SUBMIT THE WORKPLAN FOR THE ADDITIONAL SOIL BORINGS IN THE FOURTH QUARTER OF 2002 PLANNED FOR DECEMBER 2002. 1/14/2003: DAVE GIANCO,GES,TELECON RJJ SAID THAT HE WILL HAVE THE WORKPLAN SOON. 1/31/2003: RECEIVED THE SITE MONITORING REPORT FROM GES,FOR THE FOURTH QUARTER OF 2002...IT INDICATES THAT

MOBIL OIL (Continued) **S105141863**

THE MAX. BETX WAS 2,282 PPB IN MW-1,AND THE MAX. MTBE WAS 24 PPB IN MW-1...THE NEXT GROUNDWATER MONITORING AND SAMPLING EVENT IS PLANNED FOR THE FIRST QUARTER OF 2003. 3/6/2003: RECEIVED THE SUPPLEMENTAL SUBSURFACE INVESTIGATION WORKPLAN,FROM GES, ON THE PROPERTY...SAC/DAN KING REVIEWED THIS AND SENT A LETTER WITH ADDITIONAL COMMENTS TO BOTH GES AND MOBIL...AT THIS TIME WE ARE AWAITING THEIR RESPONSE. 6/10/2003: RECEIVED THE RESPONSE FROM THE ABOVE LETTER FROM GES...THEY WILL INCLUDE BORING TO A DEPTH OF 8'...WORK WILL BEGIN IN THE THRID QUARTER OF 2003. 8/27/2003: RECEIVED THE SUPPLEMENTAL SUBSURFACE INVESTIGATION REPORT FROM GES,WHICH INCLUDES THEIR WORKPLAN FOR CONTINUING THEIR CONTAMINATED SOIL/GROUNDWATER INVESTIGATION...AFTER REVIEWING THIS PLAN,I AGREE WITH IT...DRAFTED AND SENT A LETTER AGREEING WITH THIS PLAN TO BOTH EXXON MOBIL AND GES. 10/7/2003: RECEIVED THE SITE MONITORING REPORT FROM GES FOR THE THRID QUARTER OF 2003...THE MAX. BETX CONCENTRATION IN GROUNDWATER WAS 3,148 PPB IN MW-1...THE MAX, MTBE CONC. IN GROUNDWATER WAS 41.9 PPB IN MW-5...THEY WILL CONTINUE WITH THEIR QUARTERLY GROUNDWATER AND SAMPLING,WITH THEIR NEXT EVENT PLANNED FOR THE FOURTH QUARTER OF 2003. 1/22/2004: RECEIVED THE SITE MONITORING REPORT FROM GES FOR THE FOURTH QUARTER OF 2003...THE MAX. BETX CONCENTRATION WAS 897 PPB IN MW-1...THE MAX. MTBE CONCENTRATION WAS 23.4 PPB IN MW-5...THEY WILL CONTINUE WITH QUARTERLY GROUNDWATER MONITORING AND SAMPLING. 4/6/2004: RECEIVED THE SITE MONITORING REPORT FROM GES FOR THE FIRST QUARTER OF 2004...THE MAX. BETX CONCENTRATION WAS 356.4 PPB IN TW-1...THE MAX. MTBE CONCENTRATION WAS 55.4 PPB ALSO IN TW-1...THEY WILL CONTINUE WITH QUARTERLY GROUNDWATER MONITORING/SAMPLING...THE NEXT EVENT IS SCHEDULED FOR THE SECOND QUARTER OF 2004. 6/28/2004: RECEIVED THE SITE MONITORING REPORT FROM GES FOR THE SECOND QUARTER OF 2004...SPH'S WERE NOT DETECTED IN ANY SAMPLED WELLS...THE MAX. BETX CONCENTRATION IN GROUNDWATER WAS 1,422.3 PPB IN MW-1...THE MAX. MTBE CONCENTRATION WAS 6.3 PPB IN MW-5...GES WILL CONTINUE WITH QUARTERLY GROUNDWATER MONITORING/SAMPLING...THE NEXT EVENT IS SCHEDULED FOR THE THIRD QUARTER OF 2004. 9/13/2004: RECEIVED THE SITE MONITORING REPORT FROM GES WHICH WAS COMPLETED ON 7/13/2004...SPH'S WERE NOT DETECTED IN ANY WELL...THE MAX. BETX CONCENTRATION IN GROUNDWATER WAS 2,531.9 PPB IN MW-1...THE MAX. MTBE CONCENTRATION WAS 9.1 PPB IN MW-5...GES WILL CONTINUE WITH QUARTERLY GROUNDWATER MONITORING AND SAMPLING...THE NEXT EVENT IS SCHEDULED FOR THE THRID QUARTER OF 2004. 11/23/2004: RECEIVED THE SITE MONITORING REPORT FROM GES WHICH WAS COMPLETED ON 10/7/2004...IT INDICATES THAT SPH WERE NOT DETECTED IN ANY MONITORING WELL,THE MAX. BETX CONCENTRATION IN GROUNDWATER WAS 25.3 PPB IN TW-1...THE MAX. MTBE CONCENTRATION WAS 6.3 PPB IN MW-5...GES WILL CONTINUE WITH QUARTERLY GROUNDWATER MONITORING/SAMPLING...THE NEXT SAMPLING EVENT IS PLANNED FOR THE FIRST QUARTER OF 2005. 2/7/2005: RECEIVED THE FIRST QUARTER SITE MONITORING REPORT FROM GES...THE MAX. BETX CONCENTRATION IN GROUNDWATER WAS 766 PPB IN MW-1...THE MAX. MTBE CONCENTRATION WAS 5.6 PPB IN MW-5...GES IS REQUESTING A 'CLOSURE' FOR THIS SITE...I WILL DISCUSS THIS WITH SAC. 5/24/2005: RECEIVED THE SITE MONITORING REPORT FROM GES FOR THE SAMPLING COMPLETED ON 4/6/2005...SPH WERE NOT DETECTED IN ANY WELL...THE MAX. BETX CONCENTRATION IN GROUNDWATER WAS 1,351.6 PPB IN MW-1...THE MAX. MTBE CONCENTRATION WAS 5.8 PPB IN MW-5...THE NEXT SAMPLING EVENT IS PLANNED FOR THE THIRD QUARTER OF 2005. 8/16/2005: RECEIVED THE SITE MONITORING REPORT FROM GES,FOR THE GROUNDWATER SAMPLING COMPLETED ON 7/5/2005...SPH WERE NOT DETECTED IN ANY WELL...THE MAX. BETX CONCENTRATION WAS 611.4 PPB IN MW-1...THE MAX. MTBE CONCENTRATION WAS 4.3 PPB IN MW-5...GES WILL CONTINUE WITH

MOBIL OIL (Continued) **S105141863**

QUARTERLY GROUNDWATER MONITORING & SAMPLING...AND THEY ARE REQUESTING THIS SITE BE 'RECLASSIFIED AS 'INACTIVE'...I WILL DISCUSS THIS WITH SAC. 10/26/2005: RJJ/DK/GES/EXXON MOBIL MEET AND DISCUSSED SITE...GES WILL DO ADDITIONAL INVESTIGATION ON THIS SITE AND CONTINUE WITH THEIR QUARTERLY SAMPLING...STEVE LITTEN,GES,WILL SEND ME THEIR WORKPLAN AND KEEP ME INFORMED. 12/2/2005: RECEIVED THE SITE MONITORING REPORT FROM GES,FOR THE GROUNDWATER SAMPLING COMPLETED ON 10/17/2005...SPH WERE NOT DETECTED IN ANY WELL...THE MAX. BETX CONCENTRATION WAS 168.32 PPB IN MW-1...THE MAX. MTBE CONCENTRATION WAS 5.66 PPB IN MW-5...GES WILL SUBMIT A WORKPLAN FOR ADDITIONAL SUBSURFACE INVESTIGATION THIS MONTH AND THEY WILL CONTINUE WITH QUARTERLY GROUNDWATER MONITORING AND SAMPLING...THE NEXT EVENT IS PLANNED FOR THE FIRST QUARTER OF 2006. 1/4/2006: RECEIVED THE SUPPLEMENTAL SUBSURFACE INVESTIGATION WORKPLAN FROM GES FOR THE ADDITIONAL INVESTIGATION IN THE VICINITY OF MW-5 AND THE NORTHERN DISPENSER ISLAND,PER OUR MEETING ON 10/26/2005...GES WILL SUBMIT THEIR RECOMMENDATIONS FOR ANY FURTHER ACTIONS AFTER THIS WORK IS COMPLETED. 2/23/2006: RECEIVED THE SITE MONITORING REPORT FROM GES FOR THE GROUNDWATER SAMPLING COMPLETED ON 1/5/2006...SPH WERE NOT DETECTED IN ANY WELL SAMPLED...THE MAX. BETX CONCENTRATION WAS 1,855.07 PPB IN MW-1...THE MAX. MTBE CONCENTRATION WAS 3.28 PPB IN MW-5...GES WILL CONTINUE WITH QUARTERLY GROUNDWATER MONITORING/SAMPLING...THE NEXT EVENT IS PLANNED FOR THE SECOND QUARTER OF 2006. 5/25/2006: RECEIVED THE SUPPLEMENTAL SUBSURFACE INVESTIGATION REPORT FROM GES,FOR THE WORK COMPLETED IN MARCH/APRIL 2006...VOC SOIL CONCENTRATIONS WERE STILL GREATER THAN OUR 'TAGM' VALUES IN SOIL BORINGS SB-4,5,6,7,8,&10...VOC GROUNDWATER CONCENTRATIONS WERE GREATER THAN OUR GROUNDWATER STANDARDS IN MW-1,5&TW-1...GES WILL SUBMIT A REMEDIAL ACTION PLAN IN THE FORTH QUARTER OF 2006 AND THEY WILL CONTINUE WITH QUARTERLY GROUNDWATER MONITORING/SAMPLING...THE NEXT EVENT IS SCHEDULED FOR THE SECOND QUARTER OF 2006. 9/1/2006: RECEIVED THE SITE MONITORING REPORT FROM GESFOR THE GROUNDWATER SAMPLING COMPLETED ON 7/18/2006...SPH WERE NOT DETECTED IN ANY WELL...THE MAX. BETX CONCENTRATION WAS 98.42 PPB IN MW-1...THE MAX. MTBE CONCENTRATION WAS 4.16 PPB IN TW-1...GES WILL CONTINUE WITH QUARTERLY GROUNDWATER MONITORING/SAMPLING...THE NEXT EVENT IS PLANNED FOR THE THIRD QUARTER OF 2006. 12/19/2006: RECEIVED THE SITE MONITORING REPORT FROM GES WHICH COVERS THE PERIOD FROM 7/19-10/31/2006...SPH WERE NOT DETECTED IN ANY WELL...THE MAX. BETX CONCENTRATION IN GROUNDWATER WAS 75.99 PPB IN MW-1...THE MAX. MTBE CONC. WAS 2.82 PPB AT MW-5...GES WILL CONTINUE WITH QUARTERLY GROUNDWATER MONITORING/SAMPLING...THE NEXT SAMPLING EVENT IS PLANNED FOR THE FIRST QUARTER OF 2007. 2/23/2007: RECEIVED THE 2007 FIRST QUARTER SITE MONITORING REPORT FROM GES,VIA E-MAIL...SPH WERE NOT DETECTED IN ANY WELL...THE MAX. BETX CONCENTRATION WAS 436.3 PPB AT MW-1...THE MAX. MTBE CONCENTRATION WAS 1.36 PPB AT TW-1...GES PLANS TO REMOVE THE USTS ON 3/12/2007 AND WILL CONTINUE WITH QUARTERLY GROUNDWATER MONITORING/SAMPLING...(THE RAP ALSO CONSISTS OF THE EXCAVATION OF ~3000 TONS OF PETROLEUM CONTAMINATED SOIL.) 3/14/2007: JEFF WALKER,GES,TELECON RJJ,HE SAID THAT THEY HAVE BEGUN TO REMOVE THE OLD WASTE OIL AND FUEL OIL USTS TODAY,THEN IN 2 WEEKS,THEY WILL REMOVE THE GASOLINE USTS,PER THE RAP. 3/19/2007: RJJ AT SITE AT 1330...GES,JEFF WALKER,HAS REMOVED THE WASTE OIL AND FUEL OIL USTS...THIS EXCAVATION IS ~20'X10'X10' AND APPEARS TO HAVE NO VISIBLE STAINING OR ANY PETROLUM ODORS...TODAY,THEY ARE REMOVING THE PIPING IN THE FRONT OF THE BUILDING...JEFF WILL KEEP ME INFORMED ON THEIR ACTIVITIES. 3/30/2007: RJJ AT SITE AT 1000...GES HAS ALREADY REMOVED THE 6000(SPECIAL UNLEADED),6000(SUPER UNLEADED),& 10000 GAL REGULAR

MOBIL OIL (Continued) **S105141863**

UNLEADED GASOLINE USTS AND THE 6000 GAL DIESEL FUEL UST...THE EXCAVATION ~ 75'X50'X12' AND APPEARS TO HAVE NO VISIBLE STAINING OR PETROLEUM ODORS...NEXT WEEK,GES WILL REMOVE THE ASSOCIATED PIPING...THEY ALSO TRANSPORTED ~900 TONS OF CONTAMINATED SOIL TO MODERN LANDFILL. 4/5/2007: RJJ AT SITE AT 1000...GES IS CONTINUING TO EXCAVATE THE CONTAMINATED SOIL ON SITE...THUS FAR,THEY HAVE DISPOSED ~2000 TONS OF SOIL...TODAY,THEY ARE EXCAVATING AROUND THE PUMP ISLAND CANAPYS...ALSO,ON THE NORTHSIDE OF THE EXCAVATION,NEAR THE SIDEWALK,THERE IS A GAS-LINE,SO THEY CAN NOT EXCAVATE ANY FURTHER IN THAT DIRECTION. 4/12/2007: RJJ AT SITE AT 1030...GES IS STILL CONTINUING EXCAVATING/DISPOSE THE PETROLEUM CONTAMINATED SOIL...TODAY,THEY ARE EXCAVATING TOWARD THE WESTSIDE OF THE PROPERTY...THUS FAR,THEY HAVE REMOVED/DISPOSED ~4700 TONS OF SOIL. 4/18/2007: RJJ AT SITE AT 1330...GES HAS FINISHED EXCAVATING AS MUCH/FAR ON THE PROPERTY AS THEY CAN,DUE TO MANY UTILITY LINES(GAS,WATER,ELECTRICAL),AND ARE NOW BACKFILLING THE SITE...ALL TOTAL,THEY HAVE EXCAVATED ~6000 TONS OF CONTAMINATED SOIL...IN A FEW AREAS,NEAR THE UTILITY LINES AND UP TO THE ISLAND CANAPY,THERE IS STILL SOME RESIDUE SOIL STAINING,HOWEVER,NO FURTHER SOIL REMOVAL IS POSSIBLE...GES WAS TAKEN ALL THE NECESSARY SOIL SAMPLES AND WILL SEND ME THEIR FINAL REPORT. 5/11/2007: RECEIVED THE TANK EXCAVATION ASSESSMENT REPORT FROM GES,WHICH INCLUDES THE DISPOSAL RECEIPTS FOR 5,526.44 TONS OF PETROLEUM IMPACTED SOIL TAKEN TO ENSOL...ALSO,A FEW FLOOR SAMPLES ARE HIGHER THAN OUR 'TAGM' LEVELS...I WILL DISCUSS THIS REPORT WITH GES...JEREMIAH SMITH,GES,TELECON RJJ,HE SAID THAT THERE IS ANOTHER REPORT WITH ADDITIONAL CONFIRMATORY SAMPLES THAT WILL BE SENT TO ME. 6/21/2007: RECEIVED A REPORT,VIA-E-MAIL,FROM GES,WHICH WILL ALSO BE SENT TO US,THROUGH THE MAIL....RECEIVED THE FINAL REPORT, IN THE MAIL,FROM GES,WITH ADDITIONAL ANALYTICAL DATA...GES IS REQUESTING AN 'INACTIVE' STATIS FOR THIS SITE...A FEW SOIL SAMPLES ARE STILL SLIGHTLY HIGHER THAN OUR 'TAGM' GUIDANCE VALUES,SO I WILL REVIEW THIS WITH SAC. 7/3/2007: RICHARD BENDER,OWNER OF PROPERTY,TELECON RJJ,HE ASKED ABOUT THE STATIS OF THIS SITE...I TOLD HIM THAT WE ARE REVIEWING THE FINAL REPORT AND I WILL NOTIFY HIM OF OUR DECISION. 7/12/2007: AFTER REVIEWING THE SPILL FILE,SAC SAID THAT WE CAN NOW MAKE THIS SITE 'INACTIVE'...DRAFTED AND SENT AN 'INACTIVE' LETTER TO EXXON MOBILE...NO FURTHER ACTION NEEDED...SPILL CLOSED OUT. 11/8/2007: RECEIVED A LETTER FROM GES EXPLAINING THAT THEY ABONDONED ON-SITE MONITORING WELLS TW-1,2,3,MW-2,3,&4 IN ACCORDANCE WITH THE NYSDEC MONITORING WELL DECOMMISSIONING POLICY...I WILL INCLUDE THIS LETTER IN THE SPILL FILE. "

Remarks: "DURING DISPENSER UPGRADE HISTORIC CONTAMINATION HAS BEEN DISCOVERED. AREA TO BE EXCAVATED AND RETESTED."

All Materials:

Site ID:	126282
Operable Unit ID:	842788
Operable Unit:	01
Material ID:	534197
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

MOBIL OIL (Continued) **S105141863**

Site ID:	126282
Operable Unit ID:	842788
Operable Unit:	01
Material ID:	2096932
Material Code:	1213A
Material Name:	MTBE (methyl-tert-butyl ether)
Case No.:	01634044
Material FA:	Hazardous Material
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Spill Number/Closed Date:	9007600 / 1991-03-04
Facility ID:	9007600
Facility Type:	ER
DER Facility ID:	258151
Site ID:	320413
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	1564
Spill Date:	1990-10-11
Investigator:	MJHINTON
Referred To:	Not reported
Reported to Dept:	1990-10-11
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Responsible Party
Cleanup Ceased:	1991-03-04
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1990-10-15
Spill Record Last Update:	1991-10-29
Spiller Name:	Not reported
Spiller Company:	MOBIL REFINING AND MARK
Spiller Address:	3225 GALLOWS ROAD
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MJH 12/07/90: MOBIL OIL TO DISPOSE OF CONTAMINATED SOIL. 12/20/90: MJH SENT LETTER 12/14/90 REQUESTING DISPOSAL RECIEPTS. 02/28/91: MJH SENT LETTER 02/28/91 REQUESTING DISPOSAL RECIEPTS. 03/04/91: DISPOSAL RECIEPTS RECIEVED NO FURTHER ACTION NEEDED. 09/29/95: This is additional information about material spilled from the translation of the old spill file: HYDRAULIC FLUID."
Remarks:	"SUSPECT BAD SEAL ON HYDRAULIC LIFT 5CY CONTAMINATED SOIL REMOVED AND STORED ON SITE FOR DISPOSAL"

All Materials:

Site ID:	320413
Operable Unit ID:	944936
Operable Unit:	01

MOBIL OIL (Continued) **S105141863**

Material ID:	431446
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

---

147 **BURLINGTON TRUCK ROLLOVER** **NY Spills** **S103829190**
East **I290 & NIAGARA FALLS** **N/A**
< 1/8 **AMHERST, NY**
0.038 mi.
200 ft.

Actual:
613 ft.

Focus Map:
8

SPILLS:

Spill Number/Closed Date:	9875466 / 1999-07-28
Facility ID:	9875466
Facility Type:	ER
DER Facility ID:	75673
Site ID:	81947
DEC Region:	9
Spill Cause:	Traffic Accident
Spill Class:	C3
SWIS:	1522
Spill Date:	1999-03-18
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	1999-03-18
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	1999-03-18
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-03-18
Spill Record Last Update:	1999-09-24
Spiller Name:	Not reported
Spiller Company:	BURLINGTON MOTOR CARRIERS
Spiller Address:	14611 WEST COMMERCE ROAD
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 03/18/99: SAC TELECON JIM ZYMANEK, AMHERST DISASTER COORDINATOR, ONE FUEL TANK WAS AFFECTED AND THEY SHUT OFF THE OTHER TANK USING THE CROSSOVER VALVE, FIRE DEPT. WAS ABLE TO CONTAIN SPILL USING ABSORBENTS AND SPEEDI-DRY, THEY ARE ABLE TO PLACE A BUCKET UNDERNEATH THE LEAK POINT AND TRANSFER FUEL INTO A 55 GALLON DRUM, THEY CANNOT RIGHT THE TRUCK UNTIL THE TRUCK IS UNLOADED OF ITS CONTENTS OF AUTOMOBILE BRAKE ROTORS, MR. ZYMANEK BELIEVES 25 GALLONS OF FUEL HAS BEEN SPILLED, THERE IS A SMALL AMOUNT OF STONE AND SOIL THAT IS AFFECTED BY THE SPILL, THE CLAIMS ADJUSTER FOR BURLINGTON MOTOR

BURLINGTON TRUCK ROLLOVER (Continued) **S103829190**

CARRIERS IS RON BEAN, HIS PHONE NUMBER IS (800)333-1262, BURLINGTON HIRED RUSINIAK'S SERVICE TO CLEANUP THE SPILL. 03/18/99: RMC SITE INSPECTIONV 1200, MET RUSNIAKS AND AMHERST POLICE, TRACTOR TRAILOR ROLLED OVER, CURRENTLY LEAKING ABOUT HALF GALLON PER MINUTE, CONTRACTOR WILL TRY TO COLLECT UNTIL TRACTOR CAN BE RIGHTED, 3.5 HOURS SINCE ACCIDENT HAPPENED, EST BETWEEN 40 AND 100 GALLONS LOST INTO ROADSIDE STONE, RMC TO CONTACT RUSINIAKS FOR PLAN 03/18/99: RMC TELECON TO BERNIE R. 1245, TO SUB CLEANUP TO NWI, RMC ADVISED TO HAVE THEM LOOK AT JOB FIRST AS TRAFFIC AND LOCATION OF SPILL VERY DIFFICULT, 03/18/99: RMC TELECON KEVIN MURPHY 1315, AMHERST PD, PD CONCERNED ABOUT TRAFFIC AND LOGISTICS OF CLEANUP, RMC ADVISED THAT NWI WAS TO BE SUBED BY TOWER, AND THAT THEY HAVE DONE MANY CLEANUPS LIKE THIS, RMC THEN CALLED NWI AND RELAYED AMHERST PDS CONCERNS, 03/18/99: RMC SITE INSPECTION, MET AMHERST POLICE AND NWI, EXCAVATION STARTED, APPEARS CONTAMINATION HAS NOT SPREAD VERY FAR, LEFT AFTER ONE 6 WHEEL DUMP LOAD WAS REMOVED, EXPECT ONE OR TWO TO GO, MATERIAL STAGED 500 FEET AWAY, 03/19/99: RMC TELECON WITH GREG WEBER OF NWI, REMOVED TWO LOADS, EXCAVATION 3 FEET DEEP AND VISUALLY CLEAR OF ANY CONTAMINATION, DISPOSAL DUE 5/30/99 07/09/99: RMC TELECON TO NWI, REQUESTED INFORMATION, DUE 7/15 07/28/99: RMC RECEIVED DISPOSAL RECEIPT, OK, CLOSE OUT "

Remarks: "TRUCK ROLLOVER ON THE 290. UNKNOWN AMOUNT SPILLED. "

All Materials:

Site ID:	81947
Operable Unit ID:	1078755
Operable Unit:	01
Material ID:	307108
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	100.00
Units:	G
Recovered:	100.00
Oxygenate:	Not reported

---

148 **SWEENEY'S GARAGE** **NY Spills** **S102177485**
East **PAIGE AT NIAGARA FALLS** **N/A**
< 1/8 **TONAWANDA, NY**
0.039 mi.
204 ft.

Actual:
606 ft.

Focus Map:
8

SPILLS:

Spill Number/Closed Date:	9006553 / 1990-09-24
Facility ID:	9006553
Facility Type:	ER
DER Facility ID:	149192
Site ID:	177550
DEC Region:	9
Spill Cause:	Deliberate
Spill Class:	Not reported
SWIS:	1564
Spill Date:	1990-09-01
Investigator:	COOKE
Referred To:	Not reported
Reported to Dept:	1990-09-13

SWEENEY'S GARAGE (Continued) **S102177485**

CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Citizen
Cleanup Ceased:	1990-09-24
Cleanup Meets Std:	True
Last Inspection:	1990-09-24
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1990-09-20
Spill Record Last Update:	1990-09-26
Spiller Name:	Not reported
Spiller Company:	PHIL BRIZELLI
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was JDC 09/24/90: JDC INSPECTED SITE AND FOUND NO SPILLAGE REQUIRING ANY CLEANUP. SPOKE W/ SHOP MECHANIC AND INFORMED HIM OF PROHIBITION OF SPILLS. SOME PETROLEUM STAINS WERE OBSERVED IN STREET - NO STORM SEWER. "
Remarks:	"DUMPING OIL INTO STREET BY AN UNKNOWN CITIZEN"

All Materials:

Site ID:	177550
Operable Unit ID:	947159
Operable Unit:	01
Material ID:	434006
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Site ID:	177550
Operable Unit ID:	947159
Operable Unit:	01
Material ID:	434007
Material Code:	0043A
Material Name:	antifreeze
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

149
West
< 1/8
0.039 mi.
206 ft.

WRIGHT DRUM
4 HAWTHORNE AVENUE
CHEEKTOWAGA, NY

NY Spills **S102178207**
N/A

Actual:
622 ft.

Focus Map:
8

SPILLS:

Spill Number/Closed Date:	9309436 / 1993-11-02
Facility ID:	9309436
Facility Type:	ER
DER Facility ID:	78133
Site ID:	85006
DEC Region:	9
Spill Cause:	Deliberate
Spill Class:	E6
SWIS:	1530
Spill Date:	1993-03-01
Investigator:	COOKE
Referred To:	Not reported
Reported to Dept:	1993-11-01
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Citizen
Cleanup Ceased:	1993-11-02
Cleanup Meets Std:	True
Last Inspection:	1993-11-02
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1993-11-04
Spill Record Last Update:	1993-11-05
Spiller Name:	Not reported
Spiller Company:	BARBARA & JIM WRIGHT
Spiller Address:	4 HAWTHORNE AVENUE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was JDC 11/02/93: JDC/SITE - INSPECTED AREA DESCRIBED BY CALLER AND COULD NOT LOCATE DRUM. NO FURTHER ACTION REQUIRED. "
Remarks:	"55-GAL. DRUM OF WASTE OIL ON LOT OWNED BY WRIGHT"

All Materials:

Site ID:	85006
Operable Unit ID:	990978
Operable Unit:	01
Material ID:	392093
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

150
NE
< 1/8
0.039 mi.
206 ft.

MCKAY HEATING PLANT
3545 MAIN ST.
BUFFALO, NY

NY Spills **S106127122**
N/A

Actual:
655 ft.

Focus Map:
8

SPILLS:

Spill Number/Closed Date:	0375429 / 2003-12-18
Facility ID:	0375429
Facility Type:	ER
DER Facility ID:	224827
Site ID:	276528
DEC Region:	9
Spill Cause:	Human Error
Spill Class:	E5
SWIS:	1502
Spill Date:	2003-09-05
Investigator:	SACALAND
Referred To:	Not reported
Reported to Dept:	2003-12-18
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-18
Spill Record Last Update:	2003-12-18
Spiller Name:	AL SWAVY
Spiller Company:	SUNY AT BUFFALO
Spiller Address:	220 WINSPEAR AVENUE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SAC 12/18/03:SAC TELECON AL SWAVY - SUNYAB, SPILL INVOLVED A SMALL AMOUNT OF MERCURY WHICH WAS CLEANED UP THE SAME DAY IT WAS SPILLED, AT TIME OF SPILL MR.SWAVY DID NOT BELIEVE IT SHOULD HAVE BEEN REPORTED BUT DECIDED TO DISCUSS W/SAC TODAY, HE IS NOT SURE IF GREATER THAN THE 1 LB. REPORTABLE QUANTITY AMOUNT WAS SPILLED, HE WILL SEND IN REPORT DOCUMENTING WHAT WAS DONE FOR THE CLEANUP. 12/18/03:SAC REVIEWED DATA BASE, SPILL WAS CALLED IN ON SEPT. 5, 2003, SPILL NUMBER 0375281, FURTHER FOLLOWUP TO BE DONE UNDER THAT SPILL SPILL NUMBER, CLOSE OUT THIS SPILL NUMBER. ********** COMPUTER FILE ONLY, NO PAPER FILE **********"
Remarks:	"CONTRACTOR DROPPED A TRANSMITTER WHICH CONTAINED MERCURY."

All Materials:

Site ID:	276528
Operable Unit ID:	882264
Operable Unit:	01
Material ID:	494616
Material Code:	0031A
Material Name:	mercury
Case No.:	07439976

MCKAY HEATING PLANT (Continued) **S106127122**

Material FA:	Hazardous Material
Quantity:	1.00
Units:	L
Recovered:	1.00
Oxygenate:	Not reported

AH151 **SOUTHLAND CORP. 7-ELEVEN** **NY LTANKS** **S101174483**
SW **MAIN STREET AT WINDERMERE** **N/A**
< 1/8 **BUFFALO, NY**
0.039 mi.
208 ft. **Site 1 of 8 in cluster AH**

Actual:
657 ft.

Focus Map:
8

LTANKS:

Spill Number/Closed Date:	8702468 / 1987-08-11
Facility ID:	8702468
Site ID:	123202
Spill Date:	1987-06-23
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Not reported
Cleanup Ceased:	1987-08-11
SWIS:	1502
Investigator:	PRINGLE
Referred To:	Not reported
Reported to Dept:	1987-06-23
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1987-06-29
Spill Record Last Update:	1987-08-12
Spiller Name:	Not reported
Spiller Company:	SOUTHLAND CORP.
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	9
DER Facility ID:	106797
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MNP / / : TELECON 06/23/87, TWO TANKS FAILED; TELECON 06/26/87, TANK FAILED AGAIN; TELECON 06/26/87, TANKS TO BE RETESTED BY 06/27/87 OR TO BE EMPTIED. / / : TELECON 06/29/87, TANKS TESTED TIGHT, RESULTS TO BE SENT. / / : 7/31/87 RECEIVED TANK TESTS;8/11/87 TELECON W/JENKINS, TESTS ON 6/26/87 INCONCLUSIVE, RETESTED TIGHT 6/27/87, PROBLEM IN PROD & VENT LINES. "
Remarks:	"TANKS FAILURE RATES -0.055 AND -0.083"

All TTF:

Facility ID:	8702468
Spill Number:	8702468
Spill Tank Test:	1531019

SOUTHLAND CORP. 7-ELEVEN (Continued) **S101174483**

Site ID:	123202
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	123202
Operable Unit ID:	906703
Operable Unit:	01
Material ID:	565273
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

---

152 **ZINNIS FRIENDLY SERVICE** **EDR Hist Auto** **1020264568**
NW **1346 NIAGARA FALLS BLVD** **N/A**
< 1/8 **TONAWANDA, NY 14150**
0.042 mi.
223 ft.

Actual: EDR Hist Auto
584 ft.

Focus Map:
6

Year:	Name:	Type:
1969	ZINNIS FRIENDLY SERVICE	Gasoline Service Stations
1970	ZINNIS FRIENDLY SERVICE	Gasoline Service Stations
1971	ZINNIS FRIENDLY SERVICE	Gasoline Service Stations
1972	ZINNIS FRIENDLY SERVICE	Gasoline Service Stations
1973	ZINNIS FRIENDLY SERVICE	Gasoline Service Stations
1974	ZINNIS FRIENDLY SERVICE	Gasoline Service Stations
1975	ZINNIS FRIENDLY SERVICE	Gasoline Service Stations
1976	ZINNIS FRIENDLY SERVICE	Gasoline Service Stations
1977	ZINNIS FRIENDLY SERVICE	Gasoline Service Stations
1978	ZINNIS FRIENDLY SERVICE	Gasoline Service Stations
1979	ZINNIS FRIENDLY SERVICE	Gasoline Service Stations
1980	ZINNIS FRIENDLY SERVICE	Gasoline Service Stations
1982	ZINNIS FRIENDLY SERVICE	Gasoline Service Stations
1983	ZINNIS FRIENDLY SERVICE	Gasoline Service Stations
1991	BAUER RADIATOR INC	Powertrain Components Repair Services
1992	BAUER RADIATOR INC	Powertrain Components Repair Services
1993	BAUER RADIATOR INC	Powertrain Components Repair Services
1994	BAUER RADIATOR INC	Powertrain Components Repair Services

ZINNIS FRIENDLY SERVICE (Continued) **1020264568**

2002	BAUER RADIATOR INC	Powertrain Components Repair Services
2003	BAUER RADIATOR INC	Powertrain Components Repair Services
2004	BAUER RADIATOR INC	Powertrain Components Repair Services
2005	BAUER RADIATOR INC	Powertrain Components Repair Services

---

AH153 **BASIL FORD** **NY Spills** **S102245128**
SW **MAIN STREET AT WINDEMERE** **N/A**
< 1/8 **BUFFALO, NY**
0.043 mi.
225 ft. **Site 2 of 8 in cluster AH**

Actual:
656 ft.

Focus Map:
8

SPILLS:

Spill Number/Closed Date:	9514248 / 1996-02-09
Facility ID:	9514248
Facility Type:	ER
DER Facility ID:	161706
Site ID:	194002
DEC Region:	9
Spill Cause:	Housekeeping
Spill Class:	C3
SWIS:	1502
Spill Date:	1996-02-07
Investigator:	SACALAND
Referred To:	Not reported
Reported to Dept:	1996-02-07
CID:	351
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	1996-02-09
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-02-08
Spill Record Last Update:	1996-02-14
Spiller Name:	Not reported
Spiller Company:	BASIL FORD
Spiller Address:	MAIN STREET
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SAC 2/7/96:SAC INSPECT,FOUND SHEEN COMING OFF BACK LOT,YELLOW DISCOLORED SNOW,OIL RAN DOWN STREET AND COLLECTED ON CAPEN BLVD. IN SNOW,NO ODORS,HAD OILY SLIPPERY FEEL. 2/8/96:SAC TELECON CHUCK BASIL/BASIL FORD,NOTIFYING HIM OF SPILL CHUCK SENT JIM WEHNER OF ENVIRONMENTAL SERVICES GROUP TO CLEANUP. 2/8/96:SAC TELECON JIM WEHNER,NOT MUCH CLEANUP NECESSARY,SNOW HAS MELTED AND SOME SHEEN REMAINS,JIM WILL PLACE BOOMN IN BACK,LOT ALONG FENCE TO PREVENT ANYMORE GETTING TO STREET AND PLACE SOME ABSORBENT DOWN.ABSORBENT WILL BE DISPOSED W/DEBRIS FROM SPILL NUMBER 9514250. 2/9/96:SAC INSPECT,CLEANUP HAS BEEN COMPLETED."
Remarks:	"sheen in driveway"

All Materials:

Site ID:	194002
Operable Unit ID:	1028787

BASIL FORD (Continued) **S102245128**

Operable Unit:	01
Material ID:	553666
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	10.00
Oxygenate:	Not reported

AH154 **FORMER BASIL FORD** **NY Spills** **S103569084**
SSW **MAIN & WINDEMERE AVENUE** **N/A**
< 1/8 **BUFFALO, NY**
0.044 mi.
231 ft. **Site 3 of 8 in cluster AH**

Actual:
654 ft.

Focus Map:
8

SPILLS:

Spill Number/Closed Date:	9514250 / 1996-03-21
Facility ID:	9514250
Facility Type:	ER
DER Facility ID:	178054
Site ID:	214917
DEC Region:	9
Spill Cause:	Other
Spill Class:	C3
SWIS:	1502
Spill Date:	1996-02-01
Investigator:	SACALAND
Referred To:	Not reported
Reported to Dept:	1996-02-06
CID:	351
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	1996-02-08
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-02-08
Spill Record Last Update:	1996-03-29
Spiller Name:	BASIL
Spiller Company:	BASIL FORD
Spiller Address:	1540 WALDEN AVENUE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SAC 2/6/95:SAC TELECON JIM WEHNER/ENVIRONMENTAL SERVICES GROUP,THEY HAVE REMOVED SOIL AND HAVE TAKEN SAMPLES FROM EXCAVATION, TREATMENT OPTION LETTER HAS BEEN SENT.SOIL FOUND DURING REMOVAL OF TANKS THAT WERE CLOSED IN PLACE BACK IN 1956. 3/21/96:RECEIVED ANALYTICAL RESULTS AND DISPOSAL RECEIPTS,ALL PARAMETERS WERE BELOW GUIDANCE VALUES."
Remarks:	"contaminated soil spill faxed from region 9 on 02/08/96"

FORMER BASIL FORD (Continued) **S103569084**

All Materials:

Site ID:	214917
Operable Unit ID:	1028791
Operable Unit:	01
Material ID:	354382
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AI155 **HERRSCHER'S EXPRESS MART** **ICIS 1011905876**
SE **4291 MAPLE ROAD** **FINDS N/A**
< 1/8 **AMHERST, NY 14226** **ECHO**
0.045 mi.
237 ft. **Site 1 of 4 in cluster AI**

Actual:
593 ft.

Focus Map:
7

ICIS:

Enforcement Action ID:	02-2012-7501
FRS ID:	110037232410
Action Name:	Amerimart Development Corp., et al.
Facility Name:	HERRSCHER'S EXPRESS MART
Facility Address:	4291 MAPLE ROAD AMHERST, NY 14226
Enforcement Action Type:	RCRA 9006 AO For Comp And/Or Pen (UST)
Facility County:	ERIE
Program System Acronym:	ICIS
Enforcement Action Forum Desc:	Administrative - Formal
EA Type Code:	9006
Facility SIC Code:	Not reported
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	42.99029
Longitude in Decimal Degrees:	-78.80398
Permit Type Desc:	Not reported
Program System Acronym:	2600024402
Facility NAICS Code:	Not reported
Tribal Land Code:	Not reported

Facility Name:	HERRSCHER'S EXPRESS MART
Address:	4291 MAPLE ROAD
Tribal Indicator:	N
Fed Facility:	Not reported
NAIC Code:	Not reported
SIC Code:	Not reported

FINDS:

Registry ID: 110064416421

Environmental Interest/Information System
ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when

HERRSCHER'S EXPRESS MART (Continued) **1011905876**

complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

Registry ID: 110037232410

Environmental Interest/Information System

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1011905876
Registry ID:	110037232410
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110037232410

AI156 **EZ MART** **NY LTANKS** **U003318408**
SE **4291 MAPLE RD** **NY UST** **N/A**
< 1/8 **AMHERST, NY 14226** **NY Spills**
0.045 mi.
237 ft. **Site 2 of 4 in cluster AI**

Actual:
593 ft.

Focus Map:
7

LTANKS:

Spill Number/Closed Date:	1110941 / 2013-06-28
Facility ID:	1110941
Site ID:	458804
Spill Date:	2011-12-08
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	1522
Investigator:	RJJONAK

EZ MART (Continued) **U003318408**

Referred To:	Not reported
Reported to Dept:	2011-12-08
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2011-12-08
Spill Record Last Update:	2013-06-28
Spiller Name:	MICHAEL GEIGER
Spiller Company:	MJG ENTERPRISES,INC.
Spiller Address:	14 COLONIAL DR.
Spiller County:	001
Spiller Contact:	TONY NASIADRA
Spiller Phone:	716-434-2885
Spiller Extention:	Not reported
DEC Region:	9
DER Facility ID:	53711
DEC Memo:	"12/8/2011: ED BEALE,REID PETROLEUM,TELECON RJJ,HE SAID THAT REID HAS BEEN HIRED BY THE STATION OWNER,MJG ENTERPRIZES INC.,TO INVESTIGATE/REPAIR THEIR 8K PREMIUM UNLEADED UST,WHICH HAD/HAS WATER DRIPPING INTO IT...REID HAS ALREADY EMPTIED THE UST,THEN TOMORROW,THEY WILL TRY TO FIND WHERE THE WATER MIGHT BE ENTERING FROM...IT MAY BE COMING FROM A LEAK IN THE FILL PORT...AFTER THEY FIND THE LEAK,THEY WILL TRY TO MAKE REPAIRS NEXT WEEK...FOR NOW,THE TANK IS OUT-OF-SERVICE...ED WILL KEEP ME INFORMED. 12/23/2011: RJJ TELECON ED BEALE,HE SAID THAT THEY USED THEIR CAMERA INSIDE THE UST AND DISCOVERED A FEW STRESS CRACKS BY THE FILL RISER...HE ALSO SAID THAT WATER IS STILL DRIPPING INTO IT,BUT IT IS STILL OUT-OF-SERVICE WITH NO PRODUCT IN IT...HE IS AWAITING MR. GEIGER'S DECISION ON WHAT TO DO NEXT. 1/11/12:SAC TELECON TED GINTHER - PRIME TIME SERVICES. THEY WERE CONTACTED BY JOHN BATTAGLIA OF ENSOL TO CHECK THE TANK. THEY OBSERVED THE 3 FT. X 3FT. CONCRETE SQUARE AROUND THE FILLPORT WAS LOOSE. THEY WERE ABLE TO ROCK IT BACK AND FORTH. MR. GINTHER SAID SITUATIONS LIKE THIS COULD CAUSE A SPLIT IN THE TANKTOP. HE SAID THIS WOULD ALSO CAUSE THE HIGHER RATE OF WATER INFILTRATION INTO THE TANK TO TAKE PLACE BECAUSE OF THE HIGH GW TABLE. 2/28/2012: HAL GEIGER TELECON RJJ,HE SAID THAT REID PETROLEUM WILL HIRE A SUB-CONTRACTOR TO REPAIR THE UST IN ABOUT 4-5 WEEKS...MR. GEIGER WILL NOTIFY ME WHEN THEY PLAN TO START. 10/11/2012: RJJ TELECON MR. GEIGER,HE SAID THAT THEY ARE IN THE PROCESS OF SELLING THIS PROPERTY TO REID PETROLEUM,WHICH MIGHT BE WITHIN 2 WEEKS,THEN REID WILL UPGRADE THE SITE WITH ALL NEW USTS...MR. GEIGER WILL KEEP ME INFORMED. 1/15/2013: HAL GEIGER TELECON RJJ,HE SAID THAT REID PETROLEUM WILL BE THE NEW OWNERS SOON,AND THEN REID WILL UPGRADE THE ENTIRE SITE...MR. GEIGER WILL HAVE REID CONTACT ME...TONY NASIDRA,NEW CONTACT AT REID PETROLEUM,TELECON RJJ,HE SAID THAT REID WILL BE THE NEW OWNERS SOON AND THAT THEY WILL INSTALL NEW USTS,THEN AT A LATER TIME,START UPGRADING THE STATION...TONY WILL KEEP ME INFORMED...ALSO,HE WILL CONTACT AS IN PBS FOR HER INPUT/ADVISE. 6/28/2013: STEVE WARREN,REID PETROLEUM,TELECON RJJ,HE SAID THAT THEY ARE IN PROCESS OF DOING A PHASE 2 ON THE PROPERTY AND HAVE ENCOUNTERED PETROLEUM CONTAMINATED SOIL IN THE SUBSURFACE AND HAVE JUST NOTIFIED OUR ALBANY DISPATCH AND OBTAINED A NEW SPILL # 1303372...ALSO,HE SAID THAT REID PLANS ON

EZ MART (Continued) **U003318408**

REMOVING ALL THE USTS,KNOCKING DOWN THE EXISTING BUILDING AND INSTALLING NEW USTS AND A NEW BUILDING NEXT SPRING...AT THAT TIME,THEY WILL REMEDIATE THE PROPERTY,SO I WILL CLOSE-OUT THIS SPILL AND ANY INFOMATION ON THIS SITE WILL NOW BE IN SPILL # 1303372...REFER TO THAT SPILL FOR ANY ADDITIONAL INFO...THIS SPILL CLOSED OUT. ***** NOTE,COMPUTER FILE ONLY ****"

Remarks: "8000 gal premium tank had water intrusion problem. Performed tank test and test failed. Tank emptied of fuel and water can be heard dripping into tank. Plan to excavate at lines to repair connections."

All TTF:

Facility ID:	1110941
Spill Number:	1110941
Spill Tank Test:	2491420
Site ID:	458804
Tank Number:	Not reported
Tank Size:	8000
Material:	2712
EPA UST:	True
UST:	True
Cause:	00
Source:	00
Test Method:	14
Test Method 2:	VacuTest
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	GPSUTTON
Last Modified Date:	Not reported

UST:

Id/Status:	9-472123 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	9
Expiration Date:	03/05/2023
UTM X:	189855.24388
UTM Y:	4766754.13183
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	54550
Affiliation Type:	Mail Contact
Company Name:	REID PETROLEUM
Contact Type:	Not reported
Contact Name:	ENVIRONMENTAL COMPLIANCE
Address1:	P.O. BOX 987
Address2:	100 WEST GENESEE STREET
City:	LOCKPORT
State:	NY
Zip Code:	14095
Country Code:	001
Phone:	(716) 512-4223
EMail:	JMANETI@REIDPETROLEUM.COM
Fax Number:	Not reported
Modified By:	PTDIEZ
Date Last Modified:	2017-08-30

EZ MART (Continued) **U003318408**

Site Id:	54550
Affiliation Type:	Facility Operator
Company Name:	CROSBYS
Contact Type:	Not reported
Contact Name:	JOSHUA MANETI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(716) 836-0156
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MJGRIFFI
Date Last Modified:	2017-08-18

Site Id:	54550
Affiliation Type:	Emergency Contact
Company Name:	HAWLEY DEVELOPMENT
Contact Type:	Not reported
Contact Name:	JOSHUA J. MANETI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(716) 512-4223
EMail:	Not reported
Fax Number:	Not reported
Modified By:	PTDIEZ
Date Last Modified:	2017-08-30

Site Id:	54550
Affiliation Type:	Facility Owner
Company Name:	HAWLEY DEVELOPMENT
Contact Type:	ENVIRONMENTAL AUDITOR II
Contact Name:	JOSHUA J. MANETI
Address1:	100 WEST GENESEE STREET
Address2:	Not reported
City:	LOCKPORT
State:	NY
Zip Code:	14095
Country Code:	001
Phone:	(800) 348-8400
EMail:	Not reported
Fax Number:	Not reported
Modified By:	VMKREUTZ
Date Last Modified:	2018-01-29

Tank Info:

Tank Number:	1
Tank ID:	168187
Tank Status:	Closed - Removed
Material Name:	Closed - Removed

EZ MART (Continued) **U003318408**

Capacity Gallons:	8000
Install Date:	12/01/1986
Date Tank Closed:	07/14/2014
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	03
Date Test:	11/01/1993
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	AESKALSK
Last Modified:	04/14/2017

Equipment Records:

H99 - Tank Leak Detection - Other
F02 - Pipe External Protection - Original Sacrificial Anode
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
B00 - Tank External Protection - None
J01 - Dispenser - Pressurized Dispenser
E00 - Piping Secondary Containment - None
K01 - Spill Prevention - Catch Basin
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I03 - Overfill - Automatic Shut-Off

Tank Number:	2
Tank ID:	168188
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	8000
Install Date:	12/01/1986
Date Tank Closed:	07/14/2014
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	03
Date Test:	11/01/1993
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	AESKALSK
Last Modified:	04/14/2017

Equipment Records:

H99 - Tank Leak Detection - Other
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
F02 - Pipe External Protection - Original Sacrificial Anode
K01 - Spill Prevention - Catch Basin
E00 - Piping Secondary Containment - None
G00 - Tank Secondary Containment - None

EZ MART (Continued) **U003318408**

C02 - Pipe Location - Underground/On-ground
J01 - Dispenser - Pressurized Dispenser
B00 - Tank External Protection - None
I03 - Overfill - Automatic Shut-Off
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number:	3
Tank ID:	168189
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	6000
Install Date:	09/01/1974
Date Tank Closed:	03/16/2005
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	20
Date Test:	01/01/1999
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	AESKALSK
Last Modified:	04/14/2017

Equipment Records:

F99 - Pipe External Protection - Other
F02 - Pipe External Protection - Original Sacrificial Anode
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
H04 - Tank Leak Detection - Groundwater Well
I03 - Overfill - Automatic Shut-Off
D01 - Pipe Type - Steel/Carbon Steel/Iron
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number:	4
Tank ID:	168190
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	2500
Install Date:	08/01/1986
Date Tank Closed:	07/14/2014
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported

EZ MART (Continued) **U003318408**

Pipe Model: Not reported
Modified By: AESKALSK
Last Modified: 04/14/2017

Equipment Records:

H99 - Tank Leak Detection - Other
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
F02 - Pipe External Protection - Original Sacrificial Anode
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
E00 - Piping Secondary Containment - None
K01 - Spill Prevention - Catch Basin
B00 - Tank External Protection - None
J01 - Dispenser - Pressurized Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I03 - Overfill - Automatic Shut-Off

Tank Number: 5
Tank ID: 254572
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 15000
Install Date: 10/17/2014
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: PTDIEZ
Last Modified: 08/28/2018

Equipment Records:

L07 - Piping Leak Detection - Pressurized Piping Leak Detector
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
C02 - Pipe Location - Underground/On-ground
J01 - Dispenser - Pressurized Dispenser
E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
A00 - Tank Internal Protection - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
D11 - Pipe Type - Flexible Piping

Tank Number: 6A
Tank ID: 254573
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 10000
Install Date: 10/17/2014
Date Tank Closed: Not reported

EZ MART (Continued) **U003318408**

Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	PTDIEZ
Last Modified:	08/28/2018

Equipment Records:

L07 - Piping Leak Detection - Pressurized Piping Leak Detector
B04 - Tank External Protection - Fiberglass
K01 - Spill Prevention - Catch Basin
E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
D11 - Pipe Type - Flexible Piping
G04 - Tank Secondary Containment - Double-Walled (Underground)
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
C02 - Pipe Location - Underground/On-ground

Tank Number:	6B
Tank ID:	254574
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	5000
Install Date:	10/17/2014
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	PTDIEZ
Last Modified:	08/28/2018

Equipment Records:

E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
C02 - Pipe Location - Underground/On-ground
B04 - Tank External Protection - Fiberglass
K01 - Spill Prevention - Catch Basin
D11 - Pipe Type - Flexible Piping
G04 - Tank Secondary Containment - Double-Walled (Underground)
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
L07 - Piping Leak Detection - Pressurized Piping Leak Detector

Tank Number: A

EZ MART (Continued) **U003318408**

Tank ID:	216698
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	6000
Install Date:	09/01/1974
Date Tank Closed:	03/01/1987
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	AESKALSK
Last Modified:	04/14/2017

Tank Number:	B
Tank ID:	216699
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	6000
Install Date:	09/01/1974
Date Tank Closed:	03/01/1987
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	AESKALSK
Last Modified:	04/14/2017

SPILLS:

Spill Number/Closed Date:	9600093 / 1996-04-03
Facility ID:	9600093
Facility Type:	ER
DER Facility ID:	157644
Site ID:	188796
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	D3
SWIS:	1522
Spill Date:	1996-04-02
Investigator:	COOKE
Referred To:	Not reported
Reported to Dept:	1996-04-02
CID:	312
Water Affected:	Not reported
Spill Source:	Commercial Vehicle

EZ MART (Continued) **U003318408**

Spill Notifier:	Responsible Party
Cleanup Ceased:	1996-04-03
Cleanup Meets Std:	True
Last Inspection:	1996-04-03
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-04-02
Spill Record Last Update:	1996-04-15
Spiller Name:	Not reported
Spiller Company:	CID
Spiller Address:	10860 OLEAN ROAD
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was JDC 4/3/96: JDC ON SITE AND MET W/ STORE OWNER MR HERRSCHER, SPILL AREA CLEANUP W/ CLAY SORB AND DISPOSED OF TO DUMPSTER. NO FURTHER ACTION REQUIRED."
Remarks:	"hyd. line broke on trash hauling truck - clay sorb used to collect spilled oil - contaminated material placed in refuse truck for disposal to c.i.d."

All Materials:

Site ID:	188796
Operable Unit ID:	1027786
Operable Unit:	01
Material ID:	353492
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	4.00
Units:	G
Recovered:	4.00
Oxygenate:	Not reported

Spill Number/Closed Date:	9811632 / 2007-06-13
Facility ID:	9811632
Facility Type:	ER
DER Facility ID:	159588
Site ID:	191332
DEC Region:	9
Spill Cause:	Housekeeping
Spill Class:	B3
SWIS:	1522
Spill Date:	1998-12-16
Investigator:	RJJONAK
Referred To:	Not reported
Reported to Dept:	1998-12-16
CID:	266
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	2005-03-21
Recommended Penalty:	False

EZ MART (Continued) **U003318408**

UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-12-16
Spill Record Last Update:	2007-06-13
Spiller Name:	KATHY HERRSCHER
Spiller Company:	HERRSCHER'S
Spiller Address:	4291 MAPLE ROAD
Spiller Company:	001
Contact Name:	HAROLD GEIGER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MF 02/12/99: AES AND RNL INSPECTION FOR PBS LEGAL REFERRAL, NEW LINE AND SPILL BUCKETS BEING INSTALLED BY REID PETROLEUM, ONE TANK HAD BEEN TAKING ON WATER, EXCAVATED DOWN TO TANK, TANK BEING EMPTIED, NATURE'S WAY TREATED CONTAMINATED WATER, AES AND RNL FOUND CONTAMINTED SOIL IN TANK EXCAVATION AND SHEEN ON WATER IN EXCAVATION, RNL TOLD REID ABOUT NEED FOR MONITORING WELLS TO INVESTIGATE SPILL 02/18/99: MJS TELECON FROM RUSS SAVAGE, NATURES WAY. WATER FROM TANK CARBON FILTERED AND SAMPLED. SAMPLE INDICATES MTBE CONCENTRATION AT 230 PPB. MJS ADVISED MR SAVAGE TO ADD CARBON DRUM AND DISCHARGE WITH CONFIRMATORY SAMPLE DURING MID DISCHARGE. MJS, RNL SITE INSPECT. NATURES WAY ON SITE CARBON FILTERING WATER AND DISCHARGING TO GROUND. SHALLOW MONITORING WELL INSTALLED BY TANK THAT WAS TAKING ON WATER. MET WITH KATHY HERRSCHER. REID PETROLEUM EXPOSING TANKS FOR TANK TOP WORK, DIESEL TANK EXPOSED FOR NEW LINE TO PUMP ISLANDS 06/11/01: MF T/C KATHY HERRSCHER, PETRO CHEMICAL FUNDING OWNS TANKS & PROPERTY, HAROLD GEIGER 874-7000. KATHY LEASES PROPERTY. T/C RUSS SAVAGE, NW, 3 LOADS OF CONTAMINATED SOIL WENT TO 317 E AMHERST OR CLYDE AVE FOR BIOTREATMENT. S/I KATHY NOT ON SITE. 06/13/01: MF T/C HAROLD GEIGER NO ANSWER. 06/15/01: MF LETTER TO RP, SITE INVESTIGATION PLAN BY 6/29/01. 07/02/01: MF NO RESPONSE LETTER, DUE 7/16/01. 07/11/01: MF T/C HAROLD GEIGER, SENTINAL DID A PHASE 2 APPX 3 MONTHS AGO. WAITING FOR PAPER WORK. HAROLD WILL SEND ME A COPY IN APPX 3 WEEKS. REID IS HOLDING A LAND CONTRACT. HAROLD SCHECTMAN SOLD THE LAND CONTRACT HE HELD FOR GEIGER TO REID. 07/30/01: MF T/C SENTINAL, LEFT MESSAGE. T/C HAROLD GEIGER, LEFT MESSAGE TO RETURN CALL. T/C MIKE MCCARTHY, REID 800-348-8400, HE HIRED SENTINAL TO DO PHASE 2. HE WILL GIVE A COPY AS SOON AS HE RECEIVES ONE. 08/29/01: MF T/C HAROLD GEIGER, NO ANSWER. T/C MIKE MCCARTHY, 583-4563 CELL #. JUST RECEIVED PHASE 2. HE WILL BE BACK IN THE OFFICE 9/2 & HE WILL THEN SEND IT TO ME. 09/04/01: MF RECEIVED 6/6/01 SVES PROPOSAL ALONG WITH 3/22/01 SOIL & 1 MW SAMPLE RESULTS. IN PPB BTEX SOIL P-3 BENZENE 66, XYLENES 4000, MTBE 270 P-4 MTBE 1600 P-5 BENZENE 680, ETHYLBENZENE 35000, TOLUENE 50000 XYLENES 360000, ISOPROPYLBENZENE 5600 n-PROPYLBENZENE 22000, 1,2,4 270000, 1,3,5 110000 WATER AT P-1 BENZENE 250, TOLUENE 240, o-XYLENE 2200 1,2,4 750, 1,3,5 460, MTBE 230 EXTENT OF THE CONTAMINATION NOT DEFINED. CONTRACTOR PROPOSES SVES AROUND PUMP ISLAND. SOIL CONDITIONS & DEPTH TO GW UNKNOWN. NO BORING LOGS. 09/10/01: MF LETTER TO RP, EXTENT OF SOIL & GW CONTAMINATION MUST BE DEFINED. WE ALSO REQUIRE BORING LOGS. SCHEDULE BY 9/28/01. 09/25/01: MF RECEIVED CC OF A LETTER FROM REID ATTY'S TO GEIGER. BASED ON SALE CONTRACT, GEIGER IS THE RP & THEN WANT HIM TO RESPOND TO THE DEC RE; INVESTIGATION & CLEAN UP. 01/25/02: MF T/C HAROLD GEIGER, NEED INVESTIGATION PLAN, SCHEDULE BY 2/15/02. THIS PLAN MUST DEFINE THE EXTENT OF THE GW & SOIL CONNTAMINATION. MUST INCLUDE BORING LOGS. ONCE INVESIGATION IS COMPLETE, REMEDIATION PLAN WILL BE REQUIRED. T/C MIKE MCCARTHY DISCUSSED THE DEC TAKING OVER INVESTIGATION. 02/19/02: MF T/C HAROLD GEIGER, HE SENT 6/6/01 REPORT AGAIN. NO ANSWER, NO MACHINE. ROE

EZ MART (Continued) **U003318408**

REQUEST TO REID & GEIGER, RESPONSE BY 3/15/02. 02/20/02: MF T/C HAROLD GEIGER, TOLD HIM ROE SENT & IF HE HIRES A CONTRACTOR TO DO THIS WORK BY THE END OF THIS WEEK WE WILL HOLD OFF. INVESTIGATION PLAN MUST DEFINE THE EXTENT OF THE GW & SOIL CONTAMINATION, PROVIDE A REMEDIATION PLAN WITH ACCEPTABLE SCHEDULES, BORING LOGS A MUST. 773-1677, 773-4777 HOME #'S. 03/12/02: MF T/C MIKE MCCARTHY, REID PET 800-348-8400. HE WILL SIGN & RETURN ROE. 03/13/02: MF RECEIVED COPY OF INVESTIGATION CONTRACT SIGNED BY RP. SENTINEL WILL DO INVESTIGATION. 03/25/02: MF RECEIVED SIGNED ROE FROM REID PETROLEUM. 05/20/02: MF T/C DON SEYMORE, SENTINAL, LEFT MESSAGE. 09/08/02: MF LETTER TO RP, REQUESTING PHASE 2 REPORT BY 9/20/02. 09/20/02: MF RECEIVED SITE REPORT. NO GW SAMPLES TAKEN. 13 SOIL SAMPLES TAKEN ALONG THE PRIMETER OF THE SITE. 2 COMPOUNDS A/T AT B2, XYLENES AT 2507 PPB & MTBE AT 1170 PPB. B2 IS BY THE TANK FIELD. SAMPLES TAKEN AT 2-5' 09/24/02: MF T/C JOHN BATTAGLIA, 570-1295 CELL. ENSOL, LEFT MESSAGE. 11/18/02: MF T/C JOHN BATTAGLIA, WILL RETURN CALL. 12/03/02: MF T/C JOHN, WAS TOLD BY GEIGER TO DO BORINGS ALONG THE PERIMETER OF SITE. REFUSAL AT 8'. CLAY AT 3'. 01/23/03: MF LETTER TO GEIGER REQUESTING SCHEDULE FOR SVS INSTALLATION BY 2/15/03. 02/21/03: MF STIP PROCESSED STARTED. 04/09/03: MF T/C HAROLD GEIGER, CLAIMED HE HAND DELIVERED SIGNED STIP APPX 2 WEEKS AGO. HE IS WAITING FOR HIS COPY BEFORE HE STARTS WORK. 04/10/03: MF RECEIVED SIGN COPY OF ORDER. 08/06/03: MF S/I/KATHY H, SYSTEM NOT INSTALLED. E-MAIL TO LEGAL REGARDING THIS. 08/18/03: MF RECEIVED REVISED REMEDIATION PLAN. THEY WANT TO EXTEND SVES & USE A ROTARY VENTILATOR IN PLACE OF A REGENERATIVE BLOWER. THEY ALSO WANT TO FILL A 5K UST IN PLACE. LETTER TO RP, EXTENT OF THE GW CONTAMINATION MUST BE DEFINED. 5K UST MUST BE REMOVED. THE USE OF A ROTORY VENTILATOR IS NOT ACCEPTABLE. WILL SYSTEM AFFECT B2. OK TO INSTALL 4 MW, SCHEDULE BY 8/29/03. RESPONSE TO COMMENTS BY 9/1/03. 09/05/03: MF T/C PETE, EM SOL, DISCUSSED SITE & LACK OF INFO. WANTS TO FILL UST IN PLACE. FOUNDATION FOR PUMP CANOPY IS NEXT TO THE FG LEAKING UST. THEY WANT TO TT THE TANK THAT THEY WANT TO FILL IN PLACE. THEN THEY WILL DISCUSS IT. 09/00/03: MF S/I/EM SOL, OUT OF SERVICE UST UNCOVERED. LOT OF CONTAMINATED WATER FLOWING IN FROM UNDER THE BLACKTOP. PUMPED INTO HOLDING TANK. ALSO SOIL BEING REMOVED & STOCKPILED ON SITE. 10/01/03: MF T/C PETE EM-SOL 285-3920 x215, THEY WANT TO FILL UST IN PLACE. LEFT MESSAGE. 10/08/03: MF T/C PETE, EM SOL. WANTS TO FILL TANK IN QUESTION IN PLACE. TOLD HIM WANT A PE TO WRITE A LETTER STATING UST CAN'T RESONABLE REMOVED. HE WILL FAX RESULTS OF WATER SAMPLING. 10/09/03: MF FAX LETTER FROM EM SOL: THE GW AROUND THE 6K UST WILL BE PUMPED DOWN & THE SOIL BENEATH THE TANK WILL BE SAMPLED. IF THIS TANK CAN BE REMOVED IT WILL BE OTHERWISE A LETTER FROM A PE WILL BE SENT STATING REASONS WHY UST CAN'T BE REMOVED. 11/15/03: MF LETTER FROM EM SOL, BRIAN SHIAH, PE. HE REQUIRES THAT THE UST CAN'T BE REMOVED. 11/28/03: MF E-MAIL TO EM SOL, STATING THAT THEIR PE STATED THE UST CAN'T BE REMOVED WITHOUT CONSIDERABE EXPENSE & DIFFICULTY. 07/06/04: MF T/C KATHY HERRSCHER, NO FURTHER ACTIVITY ON SITE. T/C HAROLD GEIGER, NO ANSWER. T/C PETE CARMINA, EM SOL, NOT HANDLING SITE T/C JOHN B, BLOWER UNIT IS IN, WILL START INSTALLATION 7/12/04. 07/19/04: MF S/I/KATHY H, NO ACTIVITY SINCE MY LAST VISIT. T/C HAROLD GEIGER, 874-9775, HE IS GOING TO A MEETING TODAY WITH EM SOL. HE EXPECTS WORK TO START NEXT WEEK. TOLD HIM A STIP WILL BE NECESSARY & WHAT TO EXPECT. 09/15/04: MF T/C HAROLD GEIGER, LFT MESSAGE TO CALL ME. T/C KATHY H, NO ACTIVITY. T/C PETE EM SOL, LEFT MESSAGE. 01/03/05: MF FILE TO PETER GRASSO, WANTS TO DRAFT VIOLATION LETTER. 01/13/05: MF T/C JOHN BATTAGLIA, EM SOL, CLAINED HAROLD TOLD HIM THAT HE IS

EZ MART (Continued) **U003318408**

WAITING FOR PAPER WORK FROM US BEFORE HE STARTS REMEDIATION. 02/03/05: MF S/I/KATHY H, NO ACTIVITY SINCE MY LAST VISIT. 02/07/05: MF T/C HAL GEIGER, 874-9775, TOLD HIM 2 YEARS ARE ALMOST UP & THEREFORE ANOTHER FORM OF REMEDIATION IS NECESSARY. AND THAT HE IS VIOLATION OF THE STIP. HE WILL HAVE EM SOL SEND ME THEIR NEW REMEDIATION PLAN BY THE END OF THE WEEK. 03/16/05 RMC/BOB LENHART, 870-7902/PHONE. FOUND SHEEN ON WATER AND STRONG ODORS IN SOIL WHILE STARTING TO REMOVE 6K UST. HOLE WILL BE LEFT OPEN FOR MF INSPECTION. 03/21/05: MF S/I/AL GEIGER, OWNER OF THE PROPERTY/TEG, BOB LENHARDT/KATHY HERRSHIRE, OPERATOR, RENTER. 6K FIBERGLASS UST REMOVED. I WAS TOLD THE BUNG ON TOP HAS A PROBLEM. I TOLD HAL TO HAVE ALL THE LINES REMOVED IF POSSIBLE. CONTAMINATED SOIL REMOVED & AREA TO BE SAMPLED. I TOLD THEM A SAMPLE OF GW NECESSARY. GW TO BE PUMPED TO BAKER TANK. I TOLD BOB PRE & POST WATER FILTERING SAMPLE MUST BE TAKEN & ANALYZED FOR STARS 8260 BEFORE ANY DISCHARGE CAN OCCOR. 04/10/05: MF RECEIVED TANK EXCAVATION SAMPLING RESULTS, STARS 8260, PPB TOTAL, SOIL. BOTTOM - BDL'S OF 22.5 MTBE - 892 EAST - BDL'S, MTBE - 12.2 SOUTH - 42893 + 1130 WEST - 3071, XYLENES > TAGM AT 1239 MTBE - 110 NORTH - 86 + 357 WATER PILOT - BDL'S CONTAMINATED WATER - 15325 + 2170 04/14/05: MF LETTER TO RP, SOIL REMEDIATION NECESSARY IN THE AREA OF THE SOUTH WALL & GW REMEDIATION ALSO NECESSARY. SCHEDULE BY 5/15/05. 05/13/05: MF REMEDIATION PROPOSAL FROM EM SOL. 4 BIOTREATMENTS. 01/27/06: MF T/C JOHN BATTAGLIA, 285-3920, LEFT MESSAGE. LETTER TO RP, OKING TREATMENT PROPOSAL. BUT NEED 8260 SAMPLING INSTEAD OF 8021. 02/13/06: MF LETTER FROM ENSOL. THEY GOT AUTHORIZATION FROM HAROLD GEIGER TO DO REMEDIATION. THEY EXPECT TO START THE MIDDLE OF 4/06. 4/4/2006: MF HAS RETIRED FROM DEC,SO RJJ IS NOW THE DEC SPILL INVESTIGATOR FOR THIS SITE. 5/15/2006: RJJ TELECON JOHN BATTAGLIA,HE SAID THAT THEY WILL BEGIN THE BIO-REMEDIATION ON THE PROPERTY IN ABOUT 2 WEEKS...MR. BATTAGLIA WILL KEEP ME INFORMED. 6/19/2006: JOHN BATTAGLIA TELECON RJJ,HE SAID THAT THEY HAD ENVIRONMENTAL SERVICE GROUP INJECT THE BIO-REMEDIATION AGENT 2 WEEKS AGO AND WILL RE-INJECT IN ABOUT 2 WEEKS FROM TODAY...JOHN WILL SEND ME THEIR REPORT AFTER ALL THE WORK HAS BEEN FINISHED. 10/6/2006: RECEIVED AN E-MAIL FROM KRISTAN PRICE,ENSOL,STATING THAT THEY HAVE RE-INJECTED THE BIOREMEDIATION INTO THE SUBSURFACE AND WILL INSTALL A NEW GROUNDWATER MONITORING WELL IN ABOUT 2 WEEKS,THEN TAKE A WATER SAMPLE,AS PER THE WORKPLAN. 11/6/2006: RECEIVED THE REPORT FROM ENSOL FOR THEIR WORK DONE ON THE PROPERTY,WHICH WAS,THE INSTALLATION OF A MONITORING WELL IN THE SOUTHWEST PROPERTY OF THE TANK FIELD,THEN SAMPLED...THE RESULTS OF THE ANALYTICAL TEST ARE STILL ABOVE OUR 'TAGM' LEVELS,I WILL DISCUSS THIS WITH ENSOL...RJJ TELECON KRISTIN PRICE,ENSOL,SHE SAID THAT THEY WILL RESAMPLE ALL THE WELLS IN THE TANK FIELD IN ABOUT 3-6 MONTHS(I SAID THAT THIS WOULD BE ACCEPTABLE)...KRISTIN WILL SEND ME A WORKPLAN. 11/17/2006: RECEIVED THE WORKPLAN FROM ENSOL,WHICH STATES THAT THEY WILL RESAMPLE THE WELL IN MAY 2007. 6/11/2007: RECEIVED THE ANALYTICAL RESULTS FROM THE MONITORING WELL IN THE TANK EXCAVATION AREA...THE RESULTS SHOW A SLIGHT INCREASE IN CONTAMINANTS STILL ABOVE OUR GUIDANCE VALUES...I WILL DISCUSS THIS WITH SAC/DK...AFTER REVIEWING THE ANALYTICAL RESULTS,SAC SAID THAT THE LAB SHOULD DILUTE THE SAMPLE AND ANALYZE AGAIN...I CALLED KRISTIN PRICE AND INFORMED HER. 6/13/2007: RECEIVED THE ANALYTICAL RESULTS FROM THE 'DILUTED' SAMPLE...THE RESULTS ARE STILL SLIGHTLY HIGH THAN OUR GROUNDWATER GUIDANCE VALUES,HOWEVER,AFTER REVIEWING THE SPILL FILE/RESULTS,SAC & DK SAID THAT WE CAN MAKE THIS SITE 'INACTIVE'...DRAFTED AND SENT AN 'INACTIVE' LETTER TO MR. GEIGER...NO FURTHER ACTION NEEDED...SPILL

EZ MART (Continued) **U003318408**

CLOSED OUT."

Remarks: "GASOLINE TANK HAD BEEN TAKING ON WATER. WHEN TANK WAS UNCOVERED, NOTIFIER DISCOVERED SOIL CONTAMINATION. GROUNDWATER CONTAMINATION IS LIKELY ALSO. FURTHER INVESTIGATION AND REMEDIATION PLAN TO FOLLOW. ***(FORMERLY MJS FILE)***"

All Materials:

Site ID:	191332
Operable Unit ID:	1068926
Operable Unit:	01
Material ID:	311916
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	8603239 / 1986-12-24
Facility ID:	8603239
Facility Type:	ER
DER Facility ID:	258504
Site ID:	320877
DEC Region:	9
Spill Cause:	Human Error
Spill Class:	Not reported
SWIS:	1522
Spill Date:	1986-08-09
Investigator:	PRINGLE
Referred To:	Not reported
Reported to Dept:	1986-08-11
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	1986-12-24
Cleanup Meets Std:	True
Last Inspection:	1986-08-21
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1986-08-22
Spill Record Last Update:	1986-12-30
Spiller Name:	Not reported
Spiller Company:	NORTH CAMP RV & MARINE
Spiller Address:	4291 MAPLE RD.
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MNP / / : SITE INSP. 8/21/86, NEW LINES & PUMS BEING INSTALLED BY HALES SERVICE & REPAIRS. / / : TELCON 08/15/86 MNP. / / : TELECON 9/2/86, MARSHALL TANK TO SEND VERIFICATION OF DISPOSAL OF WATER;NORTH CAMP RV TO MAINTAIN & SUBMIT INVENTORY RECORDS FOR NEXT 3 MOS. / / : LETTER 11/14/86, REPLY 11/24/86 - NG, VERIFICATION NOT RECEIVED. / / : RECEIVED TANK INVENTORY RECORDS 12/2/86;RECEIVED LETTER FROM

EZ MART (Continued) **U003318408**

MARSHALL TANK 12/8/86. / / : RECEIVED TANK INVENTORY RECORDS 12/2/86;RECEIVED LETTER FROM MARSHALL TANK 12/8/86;REVIEWED INVENTORY RECORDS 12/24/86, O.K. "

Remarks: "UNDERGROUND TANK PUNCTURED WHILE INSTALLING NEW LINES"

All Materials:

Site ID:	320877
Operable Unit ID:	900510
Operable Unit:	01
Material ID:	476068
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

AI157 **ERINS AUTOMOTIVE & TRNSP** **EDR Hist Auto** **1020206117**
SE **4291 MAPLE RD** **N/A**
< 1/8 **BUFFALO, NY 14226**
0.045 mi.
237 ft. **Site 3 of 4 in cluster AI**

Actual: EDR Hist Auto
593 ft.

Focus Map: **7**

Year:	Name:	Type:
1970	BUCKS SUNOCO	Gasoline Service Stations
1971	BUCKS SUNOCO	Gasoline Service Stations
1975	MIKES SUNOCO	Gasoline Service Stations
1976	MIKES SUNOCO	Gasoline Service Stations
1977	VAN INTERIOR IDEAS	Gasoline Service Stations
1978	J & J AUTO SERVICE	Gasoline Service Stations
1982	MIKES SUNOCO SERVICE	Gasoline Service Stations
1983	MIKES SUNOCO SERVICE	Gasoline Service Stations
1985	MIKES SUNOCO SERVICE	General Automotive Repair Shops
1985	NORTH CAMP R V & MARINE INC	Gasoline Service Stations
1986	MIKES SUNOCO SERVICE	General Automotive Repair Shops
1986	NORTH CAMP R V & MARINE INC	Machine Tools, Metal Cutting Type
1987	MIKES SUNOCO SERVICE	General Automotive Repair Shops
1987	NORTH CAMP R V & MARINE INC	Machine Tools, Metal Cutting Type
1988	MIKES SUNOCO SERVICE	General Automotive Repair Shops
1993	M B B ENTERPRISES INC	Gasoline Service Stations
1994	AMHERST AUTOMOTIVE INC	General Automotive Repair Shops
1995	AMHERST AUTOMOTIVE INC	General Automotive Repair Shops
1996	AMHERST AUTOMOTIVE INC	General Automotive Repair Shops
1996	HERSHERER KATHY	Gasoline Service Stations
1997	AMHERST AUTOMOTIVE INC	General Automotive Repair Shops
1997	HERSHERER KATHY	Gasoline Service Stations
1998	AMHERST AUTOMOTIVE INC	General Automotive Repair Shops
1998	HERSHERER KATHY	Gasoline Service Stations
1999	HERSHERER KATHY	Gasoline Service Stations
2000	HERSHERER KATHY	Gasoline Service Stations
2001	HERSHERER KATHY	Gasoline Service Stations
2002	HERSHERER KATHY	Gasoline Service Stations
2003	ERIN BILLS AUTO TRNSPT INC	General Automotive Repair Shops

ERINS AUTOMOTIVE & TRNSP (Continued) **1020206117**

2003	HERSHERER KATHY	Gasoline Service Stations
2004	ERINS AUTOMOTIVE & TRNSP	General Automotive Repair Shops
2004	ERIN BILLS AUTO TRNSPT INC	General Automotive Repair Shops
2004	HERSHERER KATHY	Gasoline Service Stations
2005	ERINS AUTOMOTIVE & TRNSP	General Automotive Repair Shops
2005	HERSHERER KATHY	Gasoline Service Stations
2005	ERIN BILLS AUTO TRNSPT INC	General Automotive Repair Shops
2006	ERIN BILLS AUTO TRNSPT INC	General Automotive Repair Shops
2006	HERSHERER KATHY	Gasoline Service Stations
2006	ERINS AUTOMOTIVE & TRNSP	General Automotive Repair Shops
2007	ERINS AUTOMOTIVE & TRNSP	General Automotive Repair Shops
2007	HERSHERER KATHY	Gasoline Service Stations
2007	ERIN BILLS AUTO TRNSPT INC	General Automotive Repair Shops
2008	ERIN BILLS AUTO TRNSPT INC	General Automotive Repair Shops
2008	HERSHERER KATHY	Gasoline Service Stations
2008	HERRSCHER SUNOCO	Gasoline Service Stations
2008	ERINS AUTOMOTIVE & TRNSP	General Automotive Repair Shops
2009	ERINS AUTOMOTIVE & TRNSP	General Automotive Repair Shops
2009	ERIN BILLS AUTO TRNSPT INC	General Automotive Repair Shops
2009	HERRSCHER SUNOCO	Gasoline Service Stations
2009	HERSHERER KATHY	Gasoline Service Stations
2010	ERIN BILLS AUTO TRNSPT INC	General Automotive Repair Shops
2010	ERINS AUTOMOTIVE & TRNSP	General Automotive Repair Shops
2010	HERRSCHER SUNOCO	Gasoline Service Stations
2010	HERSHERER KATHY	Gasoline Service Stations
2011	ERIN BILLS AUTO TRNSPT INC	General Automotive Repair Shops
2011	HERRSCHER SUNOCO	Gasoline Service Stations
2011	HERSHERER KATHY	Gasoline Service Stations
2011	ERINS AUTOMOTIVE & TRNSP	General Automotive Repair Shops
2012	ERINS AUTOMOTIVE & TRNSP	General Automotive Repair Shops
2012	HERSHERER KATHY	Gasoline Service Stations
2013	HERSHERER KATHY	Gasoline Service Stations
2013	ERINS AUTOMOTIVE & TRNSP	General Automotive Repair Shops
2014	HERSHERER KATHY	Gasoline Service Stations

AI158 **MAPLE SUNOCO** **NY Spills** **S113818482**
SE **4291 MAPLE RD** **N/A**
< 1/8 **AMHERST, NY 14226**
0.045 mi.
237 ft. **Site 4 of 4 in cluster AI**

Actual:
593 ft.

Focus Map:
7

SPILLS:

Spill Number/Closed Date:	1303372 / 2014-10-22
Facility ID:	1303372
Facility Type:	ER
DER Facility ID:	53711
Site ID:	483849
DEC Region:	9
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	1522
Spill Date:	2013-06-28
Investigator:	RJJONAK
Referred To:	Not reported
Reported to Dept:	2013-06-28
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility

MAPLE SUNOCO (Continued) **S113818482**

Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2013-06-28
Spill Record Last Update:	2014-10-22
Spiller Name:	STEVE WARREN
Spiller Company:	REID PETROLEUM
Spiller Address:	100 WEST GENESEE ST.
Spiller Company:	001
Contact Name:	STEVE WARREN
DEC Memo:	"6/28/2013: STEVE WARREN,REID PETROLEUM,HE SAID THAT THEY ARE IN THE PROCESS OF DOING A PHASE 2 AND HAVE ENCOUNTERED PETROLEUM CONTAMINATED SOIL IN THE SUBSURFACE...HE ALSO SAID THAT IN THE SPRING OF 2014,REID PLANS ON DEMOLISHING THE EXISTING BUILDINGS AND REMOVING/REPLACING THE USTS/PIPING...AT THAT TIME THEY WILL REMEDIATE THE ENTIRE SITE,SINCE THEY ARE NOW THE CURRENT PROPERTY OWNERS...STEVE WILL KEEP ME INFORMED AND SEND ME THE PHASE 2, WHEN COMPLETED. 11/7/2013: RECEIVED THE PHASE 2,VIA E-MAIL,FROM REID PETROLEUM WHICH INDICATES SUBSURFACE PETROLEUM CONTAMINATED SOIL & GROUNDWATER,IN A FEW AREAS ON THE PROPERTY,MAINLY NEAR THE PUMP ISLANDS & OLD UST FIELD...REID STILL HAS PLANS TO UPGRADE THIS SITE IN 2014...AT THAT TIME,THEY WILL REMOVE THIS CONTAMINATION. 7/8/2014: STEVE WARREN,REID PETROLEUM,TELECON RJJ,HE SAID THAT THEY HAVE STARTED TO DEMOLISH THE EXISTING BUILDING AND CANOPY,THEN THEY WILL REMOVE THE OLD USTS/PIPING,IN ~2 WEEKS...STEVE WILL KEEP ME UPDATED. 7/28/2014: RJJ AT SITE AT 1330...ALL THE EXISTING BUILDINGS AND CANOPY HAVE BEEN DEMOLISHED AND THE USTS HAVE BEEN REMOVED...AFTER THE ANALYTICAL RESULTS COME BACK,REID WITH THEIR CONTRACTOR,TODD CO.,WILL REMOVE/DISPOSE THE PETROLEUM CONTAMINATED SOIL,STILL UNDERGROUND. 8/25/14:RECEIVED MESSAGE FROM FG. ROB GILL - MATRIX CALLED AND SAID WORK TO START TOMORROW. HE ESTIMATES 4000 TONS TO BE REMOVED. 8/26/14:SAC INSPECT SITE. MET W/STEVE WARREN AND ROB GILL. THEY HAVE COMPLETED THE EXCAVATION ON ONE SIDE OF THE CANOPY AT THE EAST END OF THE PROPERTY. ON THE NORTHSIDE ALONG MAPLE ROAD, ONE SMALL AREA HAD SLIGHT ODORS AT THIS EASTERN END AND A PID METER READING OF 20 ppm BUT NO ADDITIONAL EXCAVATION COULD TAKE PLACE DUE TO PROXIMITY OF NATURAL GAS MAIN. THEY HAVE BEGUN TO EXCAVATE IN THE CENTER. OLD PIPING FOUND. BLACK STAINED SOIL WITH STRONG ODORS OBSERVED. MR. GILL SAID 39 TRUCKLOADS OF SOIL REMOVED TODAY. EXCAVATION WILL CONTINUE TOMORROW. 8/27/14:SAC INSPECT SITE. MET W/STEVE WARREN AND ROB GILL. EXCAVATION CONTINUING IN THE DISPENSER/CANOPY AREA WHERE THEY STOPPED YESTERDAY MOVING IN THE WEST DIRECTION. ODORS OBSERVED. 31 TRUCKLOADS WERE REMOVED TODAY. THEY ARE ALSO, BACKFILLING AT THE EASTERN PORTION OF THE EXCAVATION WHERE SOIL WAS REMOVED YESTERDAY. EXCAVATION CONTINUES TOMORROW. 8/28/14:SAC INSPECT SITE. MET W/ROB GILL. EXCAVATION IS AT ITS WESTERN EXTENT FOR THE DISPENSER AREA. UNKNOWN FIBERGLASS TANK FOUND THAT WAS FILLED IN WITH STONE. PRESENTLY LOADING SOIL OUT IN THE MIDDLE OF THE EXCAVATION. ODORS OBSERVED. ALSO CONTINUING TO BACKFILL EXCAVATION. ONCE THEY HAVE FINISHED THIS PART OF THE JOB, THEY WILL START IN THE BUILDING/FORMER TANK AREA. 31 TRUCKLOADS WERE REMOVED TODAY. 8/29/14:SAC INSPECT SITE. MET W/ROB GILL AND STEVE WARREN. EXCAVATION IN THE DISPENSER AREA HAS STOPPED AND THEY ARE REMOVING SOIL FROM THE

MAPLE SUNOCO (Continued) **S113818482**

FORMER TANK AREA. MR. GILL SAID ABANDONED TANK FOUND YESTERDAY WAS ACTUALLY NOT AN INTACT TANK BUT PIECES THAT WERE USED AS BACKFILL. THEY ARE ALSO CONTINUING TO BACKFILL THE DISPENSER AREA. 31 MORE TRUCKLOADS WERE REMOVED TODAY. 9/2/2014: RJJ AT SITE AT 1245...TODAY,TODD CO. IS CONTINUING TO BOTH,EXCAVATE AND BACKFILL THE SITE,WHILE ROB GILL(MATRIX) OBTAINS CONFIRMATORY SOIL SAMPLES...THUS FAR,THEY HAVE REMOVED OVER 3000 TONS OF PETROLEUM CONTAMINATED SOIL AND HAVE TRANSPORTED IT TO NOCO'S BIO-CELL IN TONAWANDA...THEY ARE ALSO TRANSPORTING THE WATER,FROM THE VARIOUS EXCAVATIONS, IN THE STAGED FRAC-TANK, OFF-SITE,SINCE THE TOWN OF AMHERST WILL NOT ALLOW THEM TO DISCHARGE IT INTO THEIR SEWER SYSTEM FOR ARSENIC EXCEEDENCE...THEY PLAN ON CONTINUING THIS ALL WEEK. 9/4/2014: RJJ AT SITE AT 1445...YESTERDAY,THEY UNCOVERED ANOTHER UST...IT APPEARS THAT THIS IS AN OLD WASTE OIL TANK...TODAY,THEY ARE PUMPING OUT THIS FULL UST,THEN THEY WILL REMOVE IT...ALSO,THEY ARE STILL CONTINUING TO EXACAVATE/BACKFILL...THUS FAR,THEY HAVE REMOVED ~4000 TONS AND HAVE ~1000 TONS MORE. 9/8/2014: RJJ AT SITE AT 1500...THE REMEDIATION IS CONTINUING...THUS FAR,THEY HAVE REMOVED ~4600 TONS OF SOIL AND STILL HAVE ANOTHER DAY OF EXCAVATING LEFT. 9/10/2014: RJJ AT SITE AT 1445...TODAY THEY ARE CONTINING EXCAVATING/BACKFILL THE SITE...THUS FAR,THEY HAVE REMOVED ~5400 TONS OF SOIL...YESTERDAY,THEY ENCOUNTERED ANOTHER 1K UST(#2 FUEL OIL),NEXT TO THE WASTE OIL TANK...TOMORROW THEY WILL PUMP THIS UST OUT,THEN REMOVE BOTH USTS AND ANY PETROLEUM CONTAMINATION THEY ENCOUNTER. 10/6/14:SAC TELECON STEVE WARREN. MR. WARREN SAID THE USTs THEY ARE GOING TO INSTALL ARE LARGER THAN WHAT THEY ESTIMATED SO THEY USED TOO MUCH PEA STONE TO BACKFILL THE EXCAVATION. THEY WILL REMOVE THE EXCESS PEA STONE AND BRING IT BACK TO THEIR YARD. IF THEY DETERMINE THEY REMOVED TOO MUCH, THEY WILL BRING IT BACK TO THE SITE FOR USE AROUND THE NEW USTs. THEY ALSO HAVE AREAS IN THEIR YARD THAT REQUIRE BACKFILLING SO THEY MAY USE IT THERE. 10/21/2014: RECEIVED THE FINAL REPORT FROM REID PETROLEUM,WHICH INCLUDES THE DISPOSAL RECEIPTS FOR 5599 .55 TONS OF PETROLEUM IMPACTED SOIL TAKEN TO THE TONAWANDA TERNIMAL & THE ANALYTICAL RESULTS FROM THE EXCAVATION(THEY OBTAINED 50 SOIL SAMPLES AND ONLY 1-MTBE RESULT,FROM THE FLOOR #7 SAMPLE,EXCEEDED OUR CP-51 GUIDANCE VALUES)...THEY ARE REQUESTING A CLOSURE STATUS...I WILL DISCUSS THIS WITH SAC...AFTER REVIEWING SPILL DATA,SAC SAID THAT WE CAN MAKE THIS SITE 'INACTIVE',SINCE THERE IS AN EXCEEDENCE OF OUR CP-51 VALUES...DRAFTED AND SENT AN 'INACTIVE' LETTER TO REID PETROLEUM...NO FURTHER ACTION NEEDED...SPILL CLOSED OUT."

Remarks: "Phase 2 investigation showed soil and groundwater contamination on site at out of service gas staion."

All Materials:

Site ID:	483849
Operable Unit ID:	1233547
Operable Unit:	01
Material ID:	2232456
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

AF159 **MOBIL OIL** **NY LTANKS** **S105054098**
West **SHERIDAN & NIAGARA FALLS** **N/A**
< 1/8 **TONAWANDA, NY**
0.046 mi.
245 ft. **Site 6 of 6 in cluster AF**

Actual:
599 ft.

Focus Map:
6

LTANKS:

Spill Number/Closed Date:	8908574 / 1990-10-15
Facility ID:	8908574
Site ID:	277625
Spill Date:	1989-11-29
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Not reported
Cleanup Ceased:	1990-10-15
SWIS:	1564
Investigator:	LYONS
Referred To:	Not reported
Reported to Dept:	1989-11-29
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	1990-05-08
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1989-11-30
Spill Record Last Update:	1991-03-04
Spiller Name:	Not reported
Spiller Company:	MOBIL OIL
Spiller Address:	3225 GALLOWS ROAD
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	9
DER Facility ID:	225661
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MEL 11/30/89: MEL RECIEVED SPILL. 12/26/89: MF SITE VISIT/L & O SERVICES. I COULDN'T CHECK THE SOIL REMOVED AS IT WAS FROZEN, HOWEVER L & O CLAIMED THE SOIL WAS CONTAMINATED. I DID CHECK THE SOIL IN THE WASTE OIL TANK EXCAVATION, ITS OK. 05/08/90: MEL TELCON WITH T.J. FARRELL. HE STATES THAT SOIL HAD BEEN TESTED AND PROPERLY DISPOSED OF. DISPOSAL RECIEPT TO FOLLOW. 10/15/90: MEL RECIEVED DISPOSAL RECIEPTS. NO FURTHER ACTION NECESSARY, RECOMMEND FILE BE CLOSED. 09/29/95: This is additional information about material spilled from the translation of the old spill file: -.136 LEAK RATE."
Remarks:	"SUSPECT A BROKEN VENT LINE. MOBIL TO PUMP TANK AND REMOVE."

All TTF:

Facility ID:	8908574
Spill Number:	8908574
Spill Tank Test:	1536493
Site ID:	277625
Tank Number:	Not reported
Tank Size:	0
Material:	0022
EPA UST:	Not reported
UST:	Not reported

MOBIL OIL (Continued) **S105054098**

Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	277625
Operable Unit ID:	933633
Operable Unit:	01
Material ID:	445309
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AJ160 **STATION 124** **NY MANIFEST** **S118708037**
East **48 ALMEDA DR** **N/A**
< 1/8 **AMHERST, NY 14226**
0.049 mi.
258 ft. **Site 1 of 2 in cluster AJ**

Actual:
592 ft.

Focus Map:
6

NY MANIFEST:

Country:	USA
EPA ID:	NYD980783351
Facility Status:	Not reported
Location Address 1:	78 ALMEDA DR
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	AMHERST
Location State:	NY
Location Zip:	14226
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD980783351
Mailing Name:	STATION 124
Mailing Contact:	L MONTESANO
Mailing Address 1:	144 KENSINGTON AVENUE
Mailing Address 2:	Not reported
Mailing City:	BUFFALO
Mailing State:	NY
Mailing Zip:	14214
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7168317209

NY MANIFEST:

STATION 124 (Continued) **S118708037**

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD986980753
Trans2 State ID:	NJD080631369
Generator Ship Date:	06/11/2018
Trans1 Recv Date:	06/11/2018
Trans2 Recv Date:	06/11/2018
TSD Site Recv Date:	06/22/2018
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD980783351
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	003045366FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	60
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	B007
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
1 additional NY MANIFEST: record(s) in the EDR Site Report.

AJ161 **STATION 124** **RCRA NonGen / NLR** **1000413629**
East **48 ALMEDA DR** **FINDS** **NYD980783351**
< 1/8 **AMHERST, NY 14226** **ECHO**
0.049 mi.
258 ft. **Site 2 of 2 in cluster AJ**

Actual:
592 ft.

Focus Map:
6

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	STATION 124
Facility address:	48 ALMEDA DR AMHERST, NY 14226-1151
EPA ID:	NYD980783351
Mailing address:	ERIE BLVD W SYRACUSE, NY 13202
Contact:	Not reported
Contact address:	ERIE BLVD W SYRACUSE, NY 13202
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	Not reported
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	Not reported
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No

STATION 124 (Continued) **1000413629**

On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: STATION 124
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: STATION 124
Classification: Not a generator, verified

Date form received by agency: 11/20/1984
Site name: STATION 124
Classification: Large Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: X002
. Waste name: POLYCHLORINATED BIPHENOLS (PCBs)

Violation Status: No violations found

FINDS:

Registry ID: 110004392648

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000413629
Registry ID: 110004392648
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004392648

AK162 **UNDERNEATH DISPENSER 3/4** **NY Spills** **S113916371**
NNW **1355 NIAGARA FALLS BLVD** **N/A**
< 1/8 **AMHERST, NY 14226**
0.050 mi.
264 ft. **Site 1 of 8 in cluster AK**

Actual:
583 ft.

Focus Map:
3

SPILLS:

Spill Number/Closed Date:	1306629 / 2014-01-08
Facility ID:	1306629
Facility Type:	ER
DER Facility ID:	52491
Site ID:	487257
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	1522
Spill Date:	2013-09-24
Investigator:	RJJONAK
Referred To:	Not reported
Reported to Dept:	2013-09-24
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2013-09-24
Spill Record Last Update:	2014-01-08
Spiller Name:	MICHAEL YOUNT
Spiller Company:	DELTA SONIC CAR WASH SYSTEMS,INC.
Spiller Address:	570 DELAWARE AVE.
Spiller Company:	001
Contact Name:	MIKE YOUNT
DEC Memo:	"9/24/2013: RJJ TELECON MIKE YOUNT,DELTA SONIC,HE SAID THAT ~3-5 GALS. OF GASOLINE LEAKED OUT,ALL UNDER THE DISPENSER,ALL CAPTURED IN THE CONTAINMENT SUMP,DUE TO A FAULTY FUEL LINE...DELTA SONIC WILL PUMP-OUT & CLEAN THE SUMP,THEN REPLACE THE FUEL LINE...FOR NOW,THE DISPENSER IS OUT-OF-SERVICE...ALL OF THE SPILL HAS BEEN RECOVERED...MIKE WILL KEEP ME INFORMED. 10/30/2013: MIKE YOUNT TELECON RJJ,HE SAID THAT TODAY,THEY HAVE STARTED TO UPGRADE THE ENTIRE SITE...THEY WILL REMOVE/REPLACE ALL THE USTS & PIPING,AND ALL THE DISPENSERS...MIKE WILL OBTAIN CONFIRMATORY SOIL SAMPLES FROM THE UST EXCAVATIONS AND HE WILL CALL ME IF THEY ENCOUNTER ANY PETROLEUM CONTAMINATED SOIL. 10/31/2013: RJJ AT SITE AT 0730...DELTA SONIC ARE CONTINUING TO REMOVE/REPLACE THE 6-USTS ON SITE(1-12K,15K,8K,25K,&7K GASOLINE USTS AND 1-4K DIESEL UST)AND THE ASSOCIATED PIPING...THEY HAVE STAGED A SMALL AMOUNT OF CONTAMINATED SOIL ON SITE,WHICH WILL BE DISPOSED OF...MIKE YOUNT WILL KEEP ME INFORMED. 11/7/2013: RJJ AT SITE AT 0915...DELTA SONIC HAS FINISHED EXCAVATING/REMOVING THE OLD USTS AND TODAY,THEY WILL BEGIN TO INSTALL 2 NEW USTS(1-30K & 1-26K)...THEY HAVE TRANSPORTED ~400 TONS OF PETROLEUM CONTAMINATED SOIL TO THE MODERN LANDFILL AND MIKE YOUNT HAS OBTAINED THEIR CONFIRMATORY SOIL SAMPLES FROM THE EXCAVATION...THE EXCAVATION APPEARS TO HAVE NO STAINED SOIL OR ANY ODORS OF ANY KIND...MIKE WILL SEND ME THEIR REPORT. 11/19/2013: RJJ AT SITE AT 1000...DELTA SONIC

UNDERNEATH DISPENSER 3/4 (Continued) **S113916371**

HAS ENCOUNTERED ADDITIONAL CONTAMINATED SOIL,WHERE THE NEW UTILITY LINES ARE BEING INSTALLED WHICH RUN INTO THE DISPENSERS...MIKE YOUNT HAS OBTAINED CONFIRMATORY SOIL SAMPLES,FROM THE TRENCH AND THE SOIL(~50 TONS),IS STAGED ON SITE AWAITING DISPOSAL...THE TRENCH NOW APPEARS TO HAVE NO VISIBLE STAINING OR ANY ODORS...MIKE WILL KEEP ME INFORMED. 1/6/2014: RECEIVED THE 'FINAL' CLOSURE REPORT FROM DELTA SONIC,WHICH INCLUDES THE DISPOSAL RECEIPTS FOR 507.3 TONS OF PETROLEUM CONTAMINTED SOIL TAKEN TO THE MODERN LANDFILL & THE CONFIRMATORY ANALYTICAL RESULTS FROM THE UST EXCAVATION AND PIPING TRENCHES...ALL THE RESULTS ARE ALL BELOW OUR CP-51 GUIDANCE VALUES...I WILL DISCUSS THIS WITH SAC. 1/8/2014: AFTER DISCUSSING SITE WITH SAC,HE SAID THAT WE CAN CLOSE-OUT THIS SPILL...DRAFTED & SENT A 'NO FURTHER ACTION' LETTER TO DELTA SONIC...SPILL CLOSED OUT."

Remarks: "Clean up underway. Line Failure"

All Materials:

Site ID:	487257
Operable Unit ID:	1236893
Operable Unit:	01
Material ID:	2236455
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	5.00
Oxygenate:	Not reported

AK163 **SPILL NUMBER 8504373** **NY Spills** **S117853664**
NNW **1355 NIAGARA FALLS BLVD** **N/A**
< 1/8 **AMHERST, NY**
0.050 mi.
264 ft. **Site 2 of 8 in cluster AK**

Actual:
583 ft.

Focus Map:
3

SPILLS:

Spill Number/Closed Date:	8504373 / 1986-03-08
Facility ID:	8504373
Facility Type:	ER
DER Facility ID:	245513
Site ID:	197383
DEC Region:	9
Spill Cause:	Unknown
Spill Class:	Not reported
SWIS:	1522
Spill Date:	1986-03-08
Investigator:	MJHINTON
Referred To:	Not reported
Reported to Dept:	Not reported
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	1986-03-08
Cleanup Meets Std:	True
Last Inspection:	1986-03-08
Recommended Penalty:	False

SPILL NUMBER 8504373 (Continued) **S117853664**

UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	Not reported
Spill Record Last Update:	2004-02-19
Spiller Name:	Not reported
Spiller Company:	KNOWN, SEE FILE
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MJH 2004/02/19 - Both Spill_Time and RCVD_Time were previously blank and replaced with 00:00 to fix a data translation problem... Bob Corcoran "
Remarks:	""

All Materials:

Site ID:	197383
Operable Unit ID:	897599
Operable Unit:	01
Material ID:	479963
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

AK164 **DELTA SONIC CAR WASH** **ECHO** **1016089373**
NNW **1355 NIAGARA FALLS BLVD** **N/A**
< 1/8 **AMHERST, NY 14226**
0.050 mi.
264 ft. **Site 3 of 8 in cluster AK**

Actual:
583 ft.

Focus Map:
3

ECHO:

Envid:	1016089373
Registry ID:	110004450460
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004450460

AK165 **DELTA SONIC CAR WASH SYSTEMS** **EDR Hist Auto** **1020515330**
NNW **1355 NIAGARA FALLS BLVD** **N/A**
< 1/8 **BUFFALO, NY 14226**
0.050 mi.
264 ft. **Site 4 of 8 in cluster AK**

Actual:
583 ft.

Focus Map:
3

EDR Hist Auto

Year:	Name:	Type:
1993	DELTA SONIC CAR WASH SYSTEMS	Gasoline Service Stations, NEC
1994	DELTA SONIC CAR WASH SYSTEMS	Gasoline Service Stations, NEC
1995	DELTA SONIC CAR WASH SYSTEMS	Gasoline Service Stations, NEC
1996	DELTA SONIC CAR WASH SYSTEMS	Gasoline Service Stations, NEC
1997	DELTA SONIC CAR WASH SYSTEMS	Gasoline Service Stations, NEC
1998	DELTA SONIC CAR WASH SYSTEMS	Gasoline Service Stations, NEC
1999	DELTA SONIC CAR WASH SYSTEMS	Gasoline Service Stations, NEC

DELTA SONIC CAR WASH SYSTEMS (Continued) **1020515330**

2000	DELTA SONIC CAR WASH SYSTEMS	Gasoline Service Stations, NEC
2001	DELTA SONIC CAR WASH SYSTEMS	Gasoline Service Stations, NEC
2002	DELTA SONIC CAR WASH SYSTEMS	Gasoline Service Stations, NEC
2003	DELTA SONIC CAR WASH SYSTEMS	Gasoline Service Stations, NEC
2004	DELTA SONIC CAR WASH SYSTEMS	Gasoline Service Stations, NEC
2005	DELTA SONIC CAR WASH SYSTEMS	Gasoline Service Stations, NEC
2006	DELTA SONIC CAR WASH SYSTEMS	Gasoline Service Stations, NEC
2007	DELTA-SNIC CARWASH SYSTEMS INC	Gasoline Service Stations, NEC
2008	DELTA-SNIC CARWASH SYSTEMS INC	Gasoline Service Stations, NEC
2009	DELTA-SNIC CARWASH SYSTEMS INC	Gasoline Service Stations, NEC
2010	DELTA-SNIC CARWASH SYSTEMS INC	Gasoline Service Stations, NEC
2011	DELTA-SNIC CARWASH SYSTEMS INC	Gasoline Service Stations, NEC
2012	DELTA-SNIC CARWASH SYSTEMS INC	Gasoline Service Stations, NEC
2013	DELTA-SNIC CARWASH SYSTEMS INC	Gasoline Service Stations, NEC
2014	DELTA-SNIC CARWASH SYSTEMS INC	Gasoline Service Stations, NEC

AK166 **DELTA SONIC CAR WASH- AMHERST** **NY AST** **U003317220**
NNW **1355 NIAGARA FALLS BLVD** **N/A**
< 1/8 **AMHERST, NY 14226**
0.050 mi.
264 ft. **Site 5 of 8 in cluster AK**

Actual:
583 ft.

Focus Map:
3

AST:

Region:	STATE
DEC Region:	9
Site Status:	Active
Facility Id:	9-225185
Program Type:	PBS
UTM X:	188471.41466
UTM Y:	4766938.76012
Expiration Date:	08/17/2022
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	53307
Affiliation Type:	Facility Owner
Company Name:	DELTA SONIC CAR WASH SYSTEM INC
Contact Type:	VP PURCHASING/FUEL
Contact Name:	DALE WITTLIEF
Address1:	570 DELAWARE AVE
Address2:	Not reported
City:	BUFFALO
State:	NY
Zip Code:	14202
Country Code:	001
Phone:	(716) 886-0931
EMail:	Not reported
Fax Number:	Not reported
Modified By:	AESKALSK
Date Last Modified:	2018-07-03

Site Id:	53307
Affiliation Type:	Mail Contact
Company Name:	DELTA SONIC CAR WASH SYSTEM INC
Contact Type:	Not reported
Contact Name:	DALE WITTLIEF
Address1:	570 DELAWARE AVE
Address2:	Not reported

DELTA SONIC CAR WASH- AMHERST (Continued) **U003317220**

City:	BUFFALO
State:	NY
Zip Code:	14202
Country Code:	001
Phone:	(716) 541-2343
EMail:	DALEWITTLIEF@DELTASONICCARWASH.COM
Fax Number:	Not reported
Modified By:	AESKALSK
Date Last Modified:	2018-07-03

Site Id:	53307
Affiliation Type:	Facility Operator
Company Name:	DELTA SONIC CAR WASH- AMHERST
Contact Type:	Not reported
Contact Name:	BRAD NATALIZIA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(716) 823-4050
EMail:	Not reported
Fax Number:	Not reported
Modified By:	AESKALSK
Date Last Modified:	2018-07-03

Site Id:	53307
Affiliation Type:	Emergency Contact
Company Name:	DELTA SONIC CAR WASH SYSTEM INC
Contact Type:	Not reported
Contact Name:	MATT HAGEMAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(716) 572-9784
EMail:	Not reported
Fax Number:	Not reported
Modified By:	PTDIEZ
Date Last Modified:	2018-02-01

Tank Info:

Tank Number:	010
Tank Id:	173597
Material Code:	0013
Common Name of Substance:	Lube Oil

Equipment Records:

G01 - Tank Secondary Containment - Diking (Aboveground)
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping

DELTA SONIC CAR WASH- AMHERST (Continued) **U003317220**

J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	07/01/1999
Capacity Gallons:	280
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	07/19/2007
Register:	True
Modified By:	LDGOMEZ
Last Modified:	04/14/2017
Material Name:	lube oil

Tank Number:	015
Tank Id:	174539
Material Code:	0013
Common Name of Substance:	Lube Oil

Equipment Records:

G01 - Tank Secondary Containment - Diking (Aboveground)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	07/01/1999
Capacity Gallons:	280
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	07/19/2007
Register:	True
Modified By:	LDGOMEZ
Last Modified:	04/14/2017
Material Name:	lube oil

Tank Number:	020
Tank Id:	173598
Material Code:	0013

DELTA SONIC CAR WASH- AMHERST (Continued) **U003317220**

Common Name of Substance: Lube Oil

Equipment Records:

H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
G01 - Tank Secondary Containment - Diking (Aboveground)

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 07/01/1999
Capacity Gallons: 280
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 07/19/2007
Register: True
Modified By: LDGOMEZ
Last Modified: 04/14/2017
Material Name: lube oil

Tank Number: 025
Tank Id: 174540
Material Code: 0013
Common Name of Substance: Lube Oil

Equipment Records:

L09 - Piping Leak Detection - Exempt Suction Piping
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
G01 - Tank Secondary Containment - Diking (Aboveground)

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 07/01/1999
Capacity Gallons: 280
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 07/19/2007
Register: True

DELTA SONIC CAR WASH- AMHERST (Continued) **U003317220**

Modified By:	LDGOMEZ
Last Modified:	04/14/2017
Material Name:	lube oil

Tank Number:	030
Tank Id:	173599
Material Code:	0013
Common Name of Substance:	Lube Oil

Equipment Records:

J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
G01 - Tank Secondary Containment - Diking (Aboveground)

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	07/01/1999
Capacity Gallons:	280
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	07/19/2007
Register:	True
Modified By:	LDGOMEZ
Last Modified:	04/14/2017
Material Name:	lube oil

Tank Number:	035
Tank Id:	174541
Material Code:	0013
Common Name of Substance:	Lube Oil

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G01 - Tank Secondary Containment - Diking (Aboveground)

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed

DELTA SONIC CAR WASH- AMHERST (Continued) **U003317220**

Pipe Model:	Not reported
Install Date:	07/01/1999
Capacity Gallons:	280
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	07/19/2007
Register:	True
Modified By:	LDGOMEZ
Last Modified:	04/14/2017
Material Name:	lube oil

Tank Number:	040
Tank Id:	173600
Material Code:	0013
Common Name of Substance:	Lube Oil

Equipment Records:

G01 - Tank Secondary Containment - Diking (Aboveground)
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	07/01/1999
Capacity Gallons:	560
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	07/19/2007
Register:	True
Modified By:	LDGOMEZ
Last Modified:	04/14/2017
Material Name:	lube oil

Tank Number:	050
Tank Id:	173601
Material Code:	0013
Common Name of Substance:	Lube Oil

Equipment Records:

H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating

DELTA SONIC CAR WASH- AMHERST (Continued) **U003317220**

D01 - Pipe Type - Steel/Carbon Steel/Iron
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
G01 - Tank Secondary Containment - Diking (Aboveground)

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	07/01/1999
Capacity Gallons:	900
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	07/19/2007
Register:	True
Modified By:	LDGOMEZ
Last Modified:	04/14/2017
Material Name:	lube oil

Tank Number:	060
Tank Id:	173602
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
G01 - Tank Secondary Containment - Diking (Aboveground)

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	07/01/1999
Capacity Gallons:	1170
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	07/19/2007
Register:	True
Modified By:	LDGOMEZ
Last Modified:	04/14/2017
Material Name:	waste oil/used oil

Tank Number:	070
Tank Id:	174542
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

DELTA SONIC CAR WASH- AMHERST (Continued) **U003317220**

Equipment Records:

C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G01 - Tank Secondary Containment - Diking (Aboveground)

Tank Location:	1
Tank Type:	Fiberglass Reinforced Plastic
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	07/01/1999
Capacity Gallons:	500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	07/19/2007
Register:	True
Modified By:	LDGOMEZ
Last Modified:	04/14/2017
Material Name:	waste oil/used oil

Tank Number:	10L
Tank Id:	217648
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

K01 - Spill Prevention - Catch Basin
I02 - Overfill - High Level Alarm
G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
D11 - Pipe Type - Flexible Piping
L00 - Piping Leak Detection - None
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Location:	2
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	06/01/2005
Capacity Gallons:	300
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported

DELTA SONIC CAR WASH- AMHERST (Continued) **U003317220**

Date Tank Closed: Not reported
Register: True
Modified By: SLZIEMBA
Last Modified: 04/14/2017
Material Name: waste oil/used oil

Tank Number: 11L
Tank Id: 217649
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)
C01 - Pipe Location - Aboveground
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)
H05 - Tank Leak Detection - In-Tank System (ATG)
L00 - Piping Leak Detection - None
D11 - Pipe Type - Flexible Piping

Tank Location: 2
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 06/01/2005
Capacity Gallons: 300
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: SLZIEMBA
Last Modified: 04/14/2017
Material Name: waste oil/used oil

Tank Number: 12L
Tank Id: 217650
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Equipment Records:

E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
D11 - Pipe Type - Flexible Piping

DELTA SONIC CAR WASH- AMHERST (Continued) **U003317220**

C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Location:	2
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	06/01/2005
Capacity Gallons:	300
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	SLZIEMBA
Last Modified:	04/14/2017
Material Name:	waste oil/used oil

Tank Number:	13L
Tank Id:	217651
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
D11 - Pipe Type - Flexible Piping
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Location:	2
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	06/01/2005
Capacity Gallons:	300
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	SLZIEMBA
Last Modified:	04/14/2017
Material Name:	waste oil/used oil

DELTA SONIC CAR WASH- AMHERST (Continued) **U003317220**

Tank Number: 14L
Tank Id: 217652
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Equipment Records:

J02 - Dispenser - Suction Dispenser
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
D11 - Pipe Type - Flexible Piping
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)
E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Location: 2
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 06/01/2005
Capacity Gallons: 300
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: SLZIEMBA
Last Modified: 04/14/2017
Material Name: waste oil/used oil

Tank Number: 15L
Tank Id: 217654
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Equipment Records:

I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
D11 - Pipe Type - Flexible Piping
H05 - Tank Leak Detection - In-Tank System (ATG)

DELTA SONIC CAR WASH- AMHERST (Continued) **U003317220**

Tank Location:	2
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	06/01/2005
Capacity Gallons:	300
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	SLZIEMBA
Last Modified:	04/14/2017
Material Name:	waste oil/used oil

Tank Number:	16L
Tank Id:	218441
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
H04 - Tank Leak Detection - Groundwater Well
E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	10/01/2005
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	SLZIEMBA
Last Modified:	04/14/2017
Material Name:	waste oil/used oil

Tank Number:	17L
Tank Id:	238274
Material Code:	0015
Common Name of Substance:	Motor Oil

DELTA SONIC CAR WASH- AMHERST (Continued) **U003317220**

Equipment Records:
E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None
H04 - Tank Leak Detection - Groundwater Well
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)
J03 - Dispenser - Gravity
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping

Tank Location:	3
Tank Type:	Plastic
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	06/15/2010
Capacity Gallons:	180
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	05/14/2013
Register:	True
Modified By:	aeskalsk
Last Modified:	04/14/2017
Material Name:	motor oil

Tank Number:	18L
Tank Id:	238275
Material Code:	0015
Common Name of Substance:	Motor Oil

Equipment Records:
E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
D11 - Pipe Type - Flexible Piping
H05 - Tank Leak Detection - In-Tank System (ATG)
J03 - Dispenser - Gravity

Tank Location:	3
Tank Type:	Plastic
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	06/15/2010
Capacity Gallons:	180
Tightness Test Method:	NN

DELTA SONIC CAR WASH- AMHERST (Continued) **U003317220**

Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	05/14/2013
Register:	True
Modified By:	aeskalsk
Last Modified:	04/14/2017
Material Name:	motor oil

Tank Number:	1L
Tank Id:	217639
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

H05 - Tank Leak Detection - In-Tank System (ATG)
C01 - Pipe Location - Aboveground
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D11 - Pipe Type - Flexible Piping
E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)

Tank Location:	2
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	10/01/2005
Capacity Gallons:	1100
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	SLZIEMBA
Last Modified:	04/14/2017
Material Name:	waste oil/used oil

Tank Number:	2L
Tank Id:	217640
Material Code:	0013
Common Name of Substance:	Lube Oil

Equipment Records:

J02 - Dispenser - Suction Dispenser
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating

DELTA SONIC CAR WASH- AMHERST (Continued) **U003317220**

G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
D11 - Pipe Type - Flexible Piping
E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None
H05 - Tank Leak Detection - In-Tank System (ATG)
L00 - Piping Leak Detection - None

Tank Location:	2
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	10/01/2005
Capacity Gallons:	850
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	SLZIEMBA
Last Modified:	04/14/2017
Material Name:	lube oil

Tank Number:	3L
Tank Id:	217641
Material Code:	0013
Common Name of Substance:	Lube Oil

Equipment Records:

I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)
D11 - Pipe Type - Flexible Piping
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Location:	2
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	10/01/2005
Capacity Gallons:	720
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	SLZIEMBA

DELTA SONIC CAR WASH- AMHERST (Continued) **U003317220**

Last Modified: 04/14/2017
Material Name: lube oil

Tank Number: 4L
Tank Id: 217642
Material Code: 0013
Common Name of Substance: Lube Oil

Equipment Records:

E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)
D11 - Pipe Type - Flexible Piping
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Location: 2
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 10/01/2005
Capacity Gallons: 325
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: SLZIEMBA
Last Modified: 04/14/2017
Material Name: lube oil

Tank Number: 5L
Tank Id: 217643
Material Code: 0013
Common Name of Substance: Lube Oil

Equipment Records:

F00 - Pipe External Protection - None
E04 - Piping Secondary Containment - Double walled UG
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
I02 - Overfill - High Level Alarm
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
J02 - Dispenser - Suction Dispenser
G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)

DELTA SONIC CAR WASH- AMHERST (Continued) **U003317220**

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D11 - Pipe Type - Flexible Piping
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Location:	2
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	10/01/2005
Capacity Gallons:	325
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	SLZIEMBA
Last Modified:	04/14/2017
Material Name:	lube oil

Tank Number:	6L
Tank Id:	217644
Material Code:	0013
Common Name of Substance:	Lube Oil

Equipment Records:

E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None
D11 - Pipe Type - Flexible Piping
J02 - Dispenser - Suction Dispenser
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Location:	2
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	10/01/2005
Capacity Gallons:	325
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	SLZIEMBA
Last Modified:	04/14/2017
Material Name:	lube oil

Tank Number:	7L

DELTA SONIC CAR WASH- AMHERST (Continued) **U003317220**

Tank Id: 217645
Material Code: 0013
Common Name of Substance: Lube Oil

Equipment Records:

E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)
D11 - Pipe Type - Flexible Piping
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Location: 2
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 10/01/2005
Capacity Gallons: 325
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: SLZIEMBA
Last Modified: 04/14/2017
Material Name: lube oil

Tank Number: 8L
Tank Id: 217646
Material Code: 0013
Common Name of Substance: Lube Oil

Equipment Records:

E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D11 - Pipe Type - Flexible Piping
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Location: 2

DELTA SONIC CAR WASH- AMHERST (Continued) **U003317220**

Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	10/01/2005
Capacity Gallons:	325
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	SLZIEMBA
Last Modified:	04/14/2017
Material Name:	lube oil

Tank Number:	9L
Tank Id:	217647
Material Code:	0013
Common Name of Substance:	Lube Oil

Equipment Records:

C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
D11 - Pipe Type - Flexible Piping
E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
J02 - Dispenser - Suction Dispenser
H05 - Tank Leak Detection - In-Tank System (ATG)
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)

Tank Location:	2
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	10/01/2005
Capacity Gallons:	325
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	SLZIEMBA
Last Modified:	04/14/2017
Material Name:	lube oil

AK167 **DELTA SONIC - BOULEVARD** **NY LTANKS** **1000447103**
NNW **1355 NIAGARA FALLS BLVD** **NY Spills** **NYD986907996**
< 1/8 **AMHERST, NY 14226** **RCRA NonGen / NLR**
0.050 mi. **US AIRS**
264 ft. **Site 6 of 8 in cluster AK** **FINDS**
NY MANIFEST

Actual:
583 ft.

Focus Map:
3

LTANKS:

Spill Number/Closed Date:	8703113 / 1987-08-05
Facility ID:	8703113
Site ID:	303871
Spill Date:	1987-07-16
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1987-08-05
SWIS:	1522
Investigator:	ROSS
Referred To:	Not reported
Reported to Dept:	1987-07-17
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1987-07-20
Spill Record Last Update:	2002-03-22
Spiller Name:	Not reported
Spiller Company:	DELTA SONIC
Spiller Address:	1355 NIAGARA FALLS BLVD
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	9
DER Facility ID:	245513
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was LQR / / : RNL TELECON 07/17/87, TANK TO BE ISOLATED, BELIEVE LEAK IN LINE, TANKS RELINED, WILL CALL BEFORE BACKFILLING. / / : LQR TELCON 07/30/87 TANK RETESTED TIGHT,RESULTS TO FOLLOW. / / : LQR TELCON 07/30/87 TANK RETESTED TIGHT,RESULTS TO FOLLOW;RESULTS REC. 08/05/87 COMPLT. "
Remarks:	"RELINED TANK FAILED TEST"

All TTF:

Facility ID:	8703113
Spill Number:	8703113
Spill Tank Test:	1531141
Site ID:	303871
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00

DELTA SONIC - BOULEVARD (Continued) **1000447103**

Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	303871
Operable Unit ID:	907135
Operable Unit:	01
Material ID:	469378
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	9204430 / 1992-12-10
Facility ID:	9204430
Site ID:	303872
Spill Date:	1992-07-15
Spill Cause:	Tank Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C3
Cleanup Ceased:	1992-11-12
SWIS:	1522
Investigator:	SACALAND
Referred To:	Not reported
Reported to Dept:	1992-07-15
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	1992-08-25
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1992-07-17
Spill Record Last Update:	2002-03-22
Spiller Name:	Not reported
Spiller Company:	DELTA SONIC CAR WASH
Spiller Address:	570 DELAWARE AVENUE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	9
DER Facility ID:	245513
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SAC 07/17/92: SAC INSPECT SITE,MET WITH BRUCE NATALIZIA OF DELTA SONIC AND GARY TOLLNER OF K&T PIPING,GROUNDWATER WAS CONTAMINATED,DISPOSAL LETTER DRAFTED. 07/29/92: 2ND TANK EXCAVATION BELOW SOIL GUIDANCE VALUES,CONTAMINATED SOIL TESTED

DELTA SONIC - BOULEVARD (Continued) **1000447103**

NON-HAZARDOUS,WATER TESTED HAZARDOUS FOR BENZENE.CONTAMINATED SOIL NEEDS DISPOSAL,1ST EXCAVATION NEEDS SAMPLING. 09/09/92: DISPOSAL RECEIPTS HAVE BEEN RECEIVED,WAITING FOR ANALYTICAL RESULTS FROM 1ST EXCAVATION. 11/12/92: ANALYTICAL RESULTS OF 1ST EXCAVATION HAVE NOT BEEN RECEIVED,EXCAVATION APPEARED TO GO DOWN TO CLEAN CLAY. 12/10/92: REC. RESULTS OF 1ST EXCAVATION, OK, CLOSEOUT. "

Remarks: "GROUNDWATER CONTAMINATION FOUND DURING TANK PULL."

All Materials:

Site ID:	303872
Operable Unit ID:	971821
Operable Unit:	01
Material ID:	412155
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Spill Number/Closed Date:	0514837 / 2006-06-22
Facility ID:	0514837
Facility Type:	ER
DER Facility ID:	245513
Site ID:	361654
DEC Region:	9
Spill Cause:	Housekeeping
Spill Class:	C3
SWIS:	1522
Spill Date:	2006-03-27
Investigator:	RJJONAK
Referred To:	Not reported
Reported to Dept:	2006-03-27
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-03-27
Spill Record Last Update:	2006-06-22
Spiller Name:	BILL PAZAMICKAS
Spiller Company:	DELTA SONIC CAR WASH
Spiller Address:	1355 NIAGARA FALLS BLVD
Spiller Company:	001
Contact Name:	DINO ZACK
DEC Memo:	"3/27/2006: RJJ AT SITE AT 1500...IN THEIR STORM WATER RETENTION POND THERE IS A SMALL AMOUNT OF OIL DRIPPING INTO THE POND FROM ONE OF THEIR DRAINAGE PIPES...IN THE POND THERE IS A SLIGHT PETROLEUM SHEEN

DELTA SONIC - BOULEVARD (Continued) **1000447103**

NEAR THIS PIPE...I TOLD DELTA SONIC TO PLACE AN ABSORBANT BOOM AROUND THIS PIPE, SOAK UP THE SHEEN WITH PADS, AND TO INVESTIGATE THE CAUSE...NONE OF THE PRODUCT LEFT THE POND,IT IS ALL CONTAINED THERE...I WILL CHECK ON POND TOMORROW. 3/28/2006: RJJ AT SITE AT 0930...BILL PAZAMICKAS,DELTA SONIC MANAGER(#832-4050),SAID THAT THEIR OIL/WATER SEPARATER PLUGGED UP,CAUSING A SMALL AMOUNT OF OIL TO BACK-UP INTO THIER SUMP(INSIDE THE BUILDING),WHICH THEN PUMPED OUT INTO THE RETENTION POND...DELTA SONIC PUMPED OUT AND CLEANED BOTH THE OIL/WATER SEPARATER AND THEIR SUMP,FLUSHED OUT ALL THE DRAINAGE LINES,AND PLACED ALL THE MATERIAL INTO DRUMS FOR DISPOSAL...IN THE RETENTION POND,THEY HAVE BOOMS AND ABSORBANT PADS TO CONTAIN AND ABSORB THE OIL SHEEN AND TO STOP THE SHEEN FROM LEAVING THE POND...ALL THE OIL,WHICH WAS <1 GAL,STAYED IN THE POND AND WILL BE CLEANED UP...BILL WILL SEND ME ALL THE DISPOSAL RECEIPTS. 3/29/2006: RJJ AT SITE AT 1300...DELTA SONIC PLACED ADDITIONAL PADS AND BOOMS IN THE RETENTION POND TO SOAK-UP THE SHEEN AND IT APPEARS TO HAVE WORKED...TODAY THE SHEEN IS GONE...THEY WILL LEAVE THE ABSORBANTS IN A FEW DAYS,THEN DISPOSE ALL THE MATERIAL. 6/22/2006: RECEIVED THE DISPOSAL RECEIPTS FOR THE 2-55 GAL DRUMS OF MATERIAL TAKEN TO SOLENTS & PETROLEUM SERVICES IN SYRACUSE FOR DISPOSAL...THE SPILL HAS BEEN CLEANED UP AND PROPERLY DISPOSED OF...NO FURTHER ACTION NEEDED...SPILL CLOSED OUT."

Remarks: "CALLER SAYS HE SEES OIL IN A RETENTION POND IN CENTER OF YARD: AND IT GOES INTO STORM SEWER"

All Materials:

Site ID:	361654
Operable Unit ID:	1119784
Operable Unit:	01
Material ID:	2109232
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

Spill Number/Closed Date:	0102552 / 2001-07-16
Facility ID:	0102552
Facility Type:	ER
DER Facility ID:	245513
Site ID:	303870
DEC Region:	9
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	1522
Spill Date:	2001-06-06
Investigator:	RJJONAK
Referred To:	Not reported
Reported to Dept:	2001-06-06
CID:	312
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported

DELTA SONIC - BOULEVARD (Continued) **1000447103**

Cleanup Meets Std:	True
Last Inspection:	2001-06-07
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-06-06
Spill Record Last Update:	2002-03-22
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	WAYNE FRY(MANAGER)
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RJJ 6/7/01:SAC INSPECT SITE, MET W/WAYNE FRY WHO IS THE MANAGER, SPILL WAS CLEANED UP, STAINED PAVEMENT WAS OBSERVED, SPILL DID OCCUR WHEN PRODUCT CAME UP THE OTHER FILL PORT, WAYNE BELIEVES THEY HAVE A SIPHON SYSTEM WITH 2 DIFFERNET SIZED TANKS THAT WERE CONNECTED AND THE EXTRA PRODUCT WENT OVER TO THE SMALLER TANK THAT WAS ALREADY FILLED AND PRODUCT WAS RELEASED. 6/7/2001: RJJ/AES SITE INSPECTION AT 1300...MEET WITH WAYNE FRY,MANAGER DELTA SONIC,HE SAID THAT HE WILL TALK WITH THE PERSON,WHO WAS THERE LAST NIGHT AND SEND ME THE REPORT...IT APPEARS THAT ABOUT 10 GAL OF FUEL WAS SPILLED,THAN ALL CLEANED UP. 6/15/2001: RECEIVED THE REPORT FROM THE MANAGER OF DELTA SONIC WHO WAS THERE AT THE SPILL,HE SAID THAT ABOUT 3 GAL OF FUEL SPILLED ON THE PAVEMENT FROM THE HOSE FROM THE DELIVERY TRUCK,WHEN HE DROPPED IT ON THE PAVEMENT,AND IT WAS ALL CLEANED UP...AES HAS DRAFTED A LETTER TO DELTA SONIC REQUESTING THE SPILL ALARM HISTORY AND OTHER PBS ISSUES TO BE ADDRESSED...I WILL WAIT FOR THAT REPORT. 7/16/2001: RECEIVED THE REPORT FROM DELTA SONIC WHICH STATES THAT THE OVERFILL ALARM WAS NOT ACTIVATED,THIS THAN MEANS THAT THE FUEL WAS SPILLED ON THE PAVEMENT FROM THE DELIVERYMAN'S HOSE,NOT FROM AN OVERFILL...I TELECON WAYNE FRY,MANAGER,AND ASKED HIM ABOUT THE CONTAMINATED SPEEDY-DRY?...HE SAID THAT THEY LET THE SPEEDY-DRY AIR OUT,THEN THEY RE-USED IT,SINCE IT WAS ONLY A SMALL AMOUNT...NO FURTHER ACTION NEEDED...SPILL CLOSED OUT."
Remarks:	"DRIVER WAS MAKING A DELIVERY TO THE GAS STATION AND NOTICED PRODUCT COMING FROM FILL CAP OF ANOTHER TANK - WAS CLEANED UP - GERALD PALUMBO ADVISED"

All Materials:

Site ID:	303870
Operable Unit ID:	839266
Operable Unit:	01
Material ID:	534669
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	G
Recovered:	3.00
Oxygenate:	Not reported

Spill Number/Closed Date:	9406720 / 1994-08-17
Facility ID:	9406720
Facility Type:	ER
DER Facility ID:	245513

DELTA SONIC - BOULEVARD (Continued) **1000447103**

Site ID:	303873
DEC Region:	9
Spill Cause:	Human Error
Spill Class:	C3
SWIS:	1522
Spill Date:	1994-08-17
Investigator:	SORGI
Referred To:	Not reported
Reported to Dept:	1994-08-17
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Tank Truck
Spill Notifier:	Affected Persons
Cleanup Ceased:	1994-08-17
Cleanup Meets Std:	True
Last Inspection:	1994-08-17
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1994-08-18
Spill Record Last Update:	2002-03-22
Spiller Name:	Not reported
Spiller Company:	PAL OIL
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MJS 08/17/94: MJS SITE INSPECT - MET W/ CHRIS HYDE. SORBENTS COLLECTED AND STORED BEHIND GATE FOR DUMPSTER. SMALL QUANTITY. NO RECEIPTS REQUIRED. MJS CLOSE FILE. "
Remarks:	"VALVE LEFT OPEN DURING DELIVERY"

All Materials:

Site ID:	303873
Operable Unit ID:	1001127
Operable Unit:	01
Material ID:	379753
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	15.00
Oxygenate:	Not reported

Spill Number/Closed Date:	9807773 / 1998-11-05
Facility ID:	9807773
Facility Type:	ER
DER Facility ID:	245513
Site ID:	303874
DEC Region:	9
Spill Cause:	Other
Spill Class:	C3
SWIS:	1522
Spill Date:	1998-09-24
Investigator:	SORGI

DELTA SONIC - BOULEVARD (Continued) **1000447103**

Referred To:	Not reported
Reported to Dept:	1998-09-25
CID:	384
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	1998-09-28
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-09-25
Spill Record Last Update:	2002-03-22
Spiller Name:	BRUCE NATALZIA
Spiller Company:	DELTA SONIC CORP
Spiller Address:	570 DELAWARE AVENUE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MJS 09/28/98: MJS TELCON TO BRUCE NATALIZIA(DELTA SONIC) AND LEFT MESSAGE FOR HIM TO CALL. 09/28/98: MJS SITE INSPECT. MET WITH MR NATALIZIA AND JOHN BUMPUS (ARROW CONTRACTING). THEY ARE INSTALLING DOUBLE-WALLED FIBERGLAS PIPING AND FOUND CONTAMINATED SOILS UNDER CONCRETE PAD IN DISPENSER/CANOPY AREA. THEY WILL STOCKPILE SOILS AND DISPOSE. HE WILL CALL WITH PROGRESS. 10/ /98: MJS TELECON WITH MR NATALIZIA. ALL CONTAMINATED SOIL STOCKPILED ON SITE AND COVERED PENDING DISPOSAL. 10/22/98: MJS TELECON WITH MR NATALIZIA. HE STATED THAT SOIL DISPOSED AND HE WILL FORWARD DOCUMENTATION. 11/05/98: RECEIVED DISPOSAL DOCUMENTATION.TOTAL 0F 359.37 TONS SOILS DISPOSED AT MODEL CITY LANDFILL(MODERN). NO FURTHER ACTION REQUIRED. MJS CLOSE FILE."
Remarks:	"CALLER STATED THEY WERE REPLACING LINES AT THE GASOLINE DISPENSERS AND FOUND SOIL CONTAMINATION. "

All Materials:

Site ID:	303874
Operable Unit ID:	1068964
Operable Unit:	01
Material ID:	315329
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	0900340 / 2009-04-10
Facility ID:	0900340
Facility Type:	ER
DER Facility ID:	361449
Site ID:	412268
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	D3

DELTA SONIC - BOULEVARD (Continued) **1000447103**

SWIS:	1522
Spill Date:	2009-04-09
Investigator:	RJJONAK
Referred To:	Not reported
Reported to Dept:	2009-04-09
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2009-04-09
Spill Record Last Update:	2009-04-10
Spiller Name:	Not reported
Spiller Company:	DELTA SONIC
Spiller Address:	570 DELAWARE AVENUE
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"4/9/2009: RJJ AT SITE AT 1300...DUE TO A PLUGGED FUEL FILTER,A SMALL AMOUNT OF GASOLINE,<.5 GAL,LEAKED OUT FROM THE NOZZLE,ALL ONTO THE CONCRETE PUMP ISLAND(THIS CAUSED A PRESSURE CHANGE WITHIN THE HOSE, WHICH CAUSED THIS PROBLEM)...DELTA SONIC PERSONNEL CLEANED UP THE SMALL SPILL WITH SPEEDI-DRY AND DISPOSED THE MATERIAL IN THEIR DUMPSTER...THEY HAVE PLACED THE DISPENSER OUT-OF-SERVICE,UNTIL THEY REPLACE THE FUEL FILTER,LATTER TODAY...NO FURTHER ACTION IS NEEDED...SPILL CLOSED OUT. ***** NOTE,COMPUTER FILE ONLY *****"
Remarks:	"CALLER ALLEDGES THAT PUMP NUMBER 14 AT THE GAS STATION HAS A FAULTY SHUT OFF MECHANISM THAT CAUSES GASOLINE TO LEAK OUT TO THE GROUND. HE SPOKE TO THE ATTNEDENT WHO SAID THEY ARE AWARE OF THE SITUATION AND THAT THEY ARE WATCHING IT."

All Materials:

Site ID:	412268
Operable Unit ID:	1168751
Operable Unit:	01
Material ID:	2160373
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

Spill Number/Closed Date:	0910621 / 2010-02-23
Facility ID:	0910621
Facility Type:	ER
DER Facility ID:	245513
Site ID:	423386
DEC Region:	9
Spill Cause:	Human Error
Spill Class:	C3

DELTA SONIC - BOULEVARD (Continued) **1000447103**

SWIS:	1522
Spill Date:	2009-12-29
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	2009-12-29
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	2009-12-29
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-12-29
Spill Record Last Update:	2010-02-23
Spiller Name:	SCOTT WILSON
Spiller Company:	OMNI DELTA SONIC
Spiller Address:	1355 NIAGARA FALLS BLVD
Spiller Company:	999
Contact Name:	SCOTT WILSON
DEC Memo:	"12/29/09 RMC/SCOTT WILSON/SITE. YESTERDAY SOMEONE WAS WORKING ON WASTE OIL BOILER. A BLEEDER VALVE WAS LEFT OPEN ALLOWING THE TOTAL CONTENTS OF THE TANK TO SLOWLY DRAIN TO THE FLOOR IN THE SUB BASEMENT UNDER THE OIL CHANGE AREA. THEY WERE ABLE TO RECOVER ABOUT 80 GALLONS OFF THE FLOOR IN LIQUID FORM. THAT WAS PUT INTO TWO DRUMS. RMC OKED THE REUSE BACK INTO THE FURNACE, SPEEDY DRY WAS USED TO CLEAN UP THE MAJORITY OF THE REMAINDER. THEN THE FLOOR WAS WASHED, THEY HAVE A 5 K O/W SEPERATOR. RMC REQUESTED THAT THE SEPERATOR BE CHECKED AND PUMPED IF NECESSARY THEY WILL REPORT BACK ON THAT. THE SPEEDY DRY WILL BE PICKED UP IN THEIR NORMAL SAFETY KLEEN RUNS. UPDATE 1/7/10. 0 02/23/10 RMC/FILE. LAST MONTH RECEIVED CALL FROM SCOTT WILSON THAT THE SPEEDY DRY WAS PICKED UP AND THE OW SEPERATOR WAS PUMPED DOWN AS REGULAR MAINTENANCE ITEM. NO FURTHER ACTION REQUIRED. CLOSE OUT"
Remarks:	"CONTAINED; ANYTHING LOST FEEDS INTO SEPERATOR.CLEAN UP COMPLETE"

All Materials:

Site ID:	423386
Operable Unit ID:	1179199
Operable Unit:	01
Material ID:	2172805
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	150.00
Units:	G
Recovered:	150.00
Oxygenate:	Not reported

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	DELTA SONIC - BOULEVARD
Facility address:	1355 NIAGARA FALLS BLVD AMHERST, NY 14226

DELTA SONIC - BOULEVARD (Continued) **1000447103**

EPA ID: NYD986907996
Mailing address: DELAWARE AVE
BUFFALO, NY 14202
Contact: BRUCE NATALIZIA
Contact address: DELAWARE AVE
BUFFALO, NY 14202
Contact country: US
Contact telephone: 716-886-0931
Contact email: Not reported
EPA Region: 02
Land type: Facility is not located on Indian land. Additional information is not known.
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: DELTA SONIC CAR WASH SYSTEMS INC
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: DELTA SONIC CAR WASH SYSTEMS INC
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No

DELTA SONIC - BOULEVARD (Continued) **1000447103**

Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: DELTA SONIC - BOULEVARD
Classification: Not a generator, verified

Date form received by agency: 07/23/1990
Site name: DELTA SONIC - BOULEVARD
Classification: Conditionally Exempt Small Quantity Generator

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Generators - Records/Reporting
Date violation determined: 04/30/1993
Date achieved compliance: 10/28/1993
Violation lead agency: State
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 10/28/1993
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: 600
Paid penalty amount: 600

Regulation violated: Not reported
Area of violation: Generators - Records/Reporting
Date violation determined: 04/30/1993
Date achieved compliance: 10/28/1993
Violation lead agency: State
Enforcement action: INITIAL 3008(A) COMPLIANCE
Enforcement action date: 08/04/1993
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: 1200
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 04/30/1993
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Generators - Records/Reporting
Date achieved compliance: 10/28/1993
Evaluation lead agency: State

US AIRS MINOR:
Envid: 1000447103
Region Code: 02
Programmatic ID: AIR 020000003602999967
Facility Registry ID: 110004450460
D and B Number: Not reported
Primary SIC Code: 5171
NAICS Code: 999999
Default Air Classification Code: MIN

DELTA SONIC - BOULEVARD (Continued) **1000447103**

Facility Type of Ownership Code: POF
Air CMS Category Code: Not reported
HPV Status: Not reported

FINDS:

Registry ID: 110004450460

Environmental Interest/Information System

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

AIR MINOR

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

NY MANIFEST:
Country: USA
EPA ID: NYD986907996
Facility Status: Not reported
Location Address 1: 1355 NIAGARA FALLS BLVD
Code: BP
Location Address 2: Not reported

DELTA SONIC - BOULEVARD (Continued) **1000447103**

Total Tanks:	Not reported
Location City:	AMHERST
Location State:	NY
Location Zip:	14226
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD986907996
Mailing Name:	DELTA SONIC CAR WASH
Mailing Contact:	MARK A LEWANDOWSKI
Mailing Address 1:	570 DELAWARE AVE
Mailing Address 2:	Not reported
Mailing City:	BUFFALO
Mailing State:	NY
Mailing Zip:	14202
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7168860931

NY MANIFEST:

Document ID:	PAC2631650
Manifest Status:	C
seq:	Not reported
Year:	1992
Trans1 State ID:	PAAH0331
Trans2 State ID:	Not reported
Generator Ship Date:	10/20/1992
Trans1 Recv Date:	10/20/1992
Trans2 Recv Date:	/ /
TSD Site Recv Date:	10/21/1992
Part A Recv Date:	/ /
Part B Recv Date:	11/10/1992
Generator EPA ID:	NYD986907996
Trans1 EPA ID:	NYD982792814
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD067098822
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00350
Units:	G - Gallons (liquids only)* (8.3 pounds)

DELTA SONIC - BOULEVARD (Continued) **1000447103**

Number of Containers:	007
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AK168 **DELTA SONIC** **NY Spills** **S118459621**
NNW **1355 NIAGRA FALLS BLVD** **N/A**
< 1/8 **AMHERST, NY 14228**
0.050 mi.
264 ft. **Site 7 of 8 in cluster AK**

Actual:
583 ft.

Focus Map:
3

SPILLS:

Spill Number/Closed Date:	1508488 / 2015-11-17
Facility ID:	1508488
Facility Type:	ER
DER Facility ID:	471413
Site ID:	517036
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	1522
Spill Date:	2015-11-16
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	2015-11-16
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2015-11-16
Spill Record Last Update:	2015-11-17
Spiller Name:	Not reported
Spiller Company:	DELTA SONIC
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	MIKE YOUNT
DEC Memo:	"11/17/15 RMC/MIKE YOUNT/PHONE. PERSON LIFT BROKE HYDRAULIC LINE. SMALL AMOUNT SPRAYED ABOUT THE PARKING LOT. SPILL WAS CLEANED UP WITH PADS AND SPEEDY DRY. NO SPILL ACTION REQUIRED. CLOSE OUT."
Remarks:	"spill to paved area and catch basin/clean up underway"

All Materials:

Site ID:	517036
Operable Unit ID:	1266142
Operable Unit:	01
Material ID:	2269995
Material Code:	0010
Material Name:	hydraulic oil

DELTA SONIC (Continued) **S118459621**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	G
Recovered:	3.00
Oxygenate:	Not reported

AK169 **DELTA SONIC CAR WASH- AMHERST** **NY UST** **U004062498**
NNW **1355 NIAGARA FALLS BLVD** **N/A**
< 1/8 **AMHERST, NY 14226**
0.050 mi.
264 ft. **Site 8 of 8 in cluster AK**

Actual:
583 ft.

Focus Map:
3

UST:

Id/Status:	9-225185 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	9
Expiration Date:	08/17/2022
UTM X:	188471.41466
UTM Y:	4766938.76012
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	53307
Affiliation Type:	Facility Owner
Company Name:	DELTA SONIC CAR WASH SYSTEM INC
Contact Type:	VP PURCHASING/FUEL
Contact Name:	DALE WITTLIEF
Address1:	570 DELAWARE AVE
Address2:	Not reported
City:	BUFFALO
State:	NY
Zip Code:	14202
Country Code:	001
Phone:	(716) 886-0931
EMail:	Not reported
Fax Number:	Not reported
Modified By:	AESKALSK
Date Last Modified:	2018-07-03

Site Id:	53307
Affiliation Type:	Mail Contact
Company Name:	DELTA SONIC CAR WASH SYSTEM INC
Contact Type:	Not reported
Contact Name:	DALE WITTLIEF
Address1:	570 DELAWARE AVE
Address2:	Not reported
City:	BUFFALO
State:	NY
Zip Code:	14202
Country Code:	001
Phone:	(716) 541-2343
EMail:	DALEWITTLIEF@DELTASONICCARWASH.COM
Fax Number:	Not reported
Modified By:	AESKALSK
Date Last Modified:	2018-07-03

DELTA SONIC CAR WASH- AMHERST (Continued) **U004062498**

Site Id:	53307
Affiliation Type:	Facility Operator
Company Name:	DELTA SONIC CAR WASH- AMHERST
Contact Type:	Not reported
Contact Name:	BRAD NATALIZIA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(716) 823-4050
EMail:	Not reported
Fax Number:	Not reported
Modified By:	AESKALSK
Date Last Modified:	2018-07-03

Site Id:	53307
Affiliation Type:	Emergency Contact
Company Name:	DELTA SONIC CAR WASH SYSTEM INC
Contact Type:	Not reported
Contact Name:	MATT HAGEMAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(716) 572-9784
EMail:	Not reported
Fax Number:	Not reported
Modified By:	PTDIEZ
Date Last Modified:	2018-02-01

Tank Info:

Tank Number:	001
Tank ID:	170484
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	12000
Install Date:	07/01/1992
Date Tank Closed:	10/14/2013
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	aeskalsk
Last Modified:	04/14/2017

Equipment Records:

DELTA SONIC CAR WASH- AMHERST (Continued) **U004062498**

K01 - Spill Prevention - Catch Basin
B02 - Tank External Protection - Original Sacrificial Anode
E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
C02 - Pipe Location - Underground/On-ground
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
D11 - Pipe Type - Flexible Piping
G04 - Tank Secondary Containment - Double-Walled (Underground)
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Number:	003
Tank ID:	170659
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	06/01/1984
Date Tank Closed:	10/14/2013
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	21
Date Test:	09/24/2009
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	aeskalsk
Last Modified:	04/14/2017

Equipment Records:

F00 - Pipe External Protection - None
H04 - Tank Leak Detection - Groundwater Well
J01 - Dispenser - Pressurized Dispenser
B02 - Tank External Protection - Original Sacrificial Anode
E04 - Piping Secondary Containment - Double walled UG
K01 - Spill Prevention - Catch Basin
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
I03 - Overfill - Automatic Shut-Off
A00 - Tank Internal Protection - None
D11 - Pipe Type - Flexible Piping
L07 - Piping Leak Detection - Pressurized Piping Leak Detector

Tank Number:	006
Tank ID:	180834
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	15000
Install Date:	11/01/2004
Date Tank Closed:	Not reported
Registered:	True

DELTA SONIC CAR WASH- AMHERST (Continued) **U004062498**

Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: PTDIEZ
Last Modified: 06/26/2018

Equipment Records:

B04 - Tank External Protection - Fiberglass
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
C02 - Pipe Location - Underground/On-ground
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
D11 - Pipe Type - Flexible Piping
G04 - Tank Secondary Containment - Double-Walled (Underground)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Number: 007
Tank ID: 250485
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 30000
Install Date: 11/07/2013
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: PTDIEZ
Last Modified: 06/26/2018

Equipment Records:

C02 - Pipe Location - Underground/On-ground
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
B04 - Tank External Protection - Fiberglass
I02 - Overfill - High Level Alarm

DELTA SONIC CAR WASH- AMHERST (Continued) **U004062498**

K01 - Spill Prevention - Catch Basin
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
D11 - Pipe Type - Flexible Piping
G04 - Tank Secondary Containment - Double-Walled (Underground)
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Number:	008A
Tank ID:	250487
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	8000
Install Date:	11/07/2013
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	PTDIEZ
Last Modified:	06/26/2018

Equipment Records:

J01 - Dispenser - Pressurized Dispenser
E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
C02 - Pipe Location - Underground/On-ground
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
A00 - Tank Internal Protection - None
D11 - Pipe Type - Flexible Piping
G04 - Tank Secondary Containment - Double-Walled (Underground)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Number:	008B
Tank ID:	250489
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	10000
Install Date:	11/07/2013
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	PTDIEZ
Last Modified:	06/26/2018

DELTA SONIC CAR WASH- AMHERST (Continued) **U004062498**

Equipment Records:

E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
C02 - Pipe Location - Underground/On-ground
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
B04 - Tank External Protection - Fiberglass
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
D11 - Pipe Type - Flexible Piping
G04 - Tank Secondary Containment - Double-Walled (Underground)
H05 - Tank Leak Detection - In-Tank System (ATG)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector

Tank Number:	008C
Tank ID:	250488
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	8000
Install Date:	11/07/2013
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	PTDIEZ
Last Modified:	06/26/2018

Equipment Records:

C02 - Pipe Location - Underground/On-ground
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
B04 - Tank External Protection - Fiberglass
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
H05 - Tank Leak Detection - In-Tank System (ATG)
D11 - Pipe Type - Flexible Piping
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number:	05
Tank ID:	180833
Tank Status:	In Service
Material Name:	In Service

DELTA SONIC CAR WASH- AMHERST (Continued) **U004062498**

Capacity Gallons:	25000
Install Date:	11/01/2004
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	aeskalsk
Last Modified:	04/14/2017

Equipment Records:

C02 - Pipe Location - Underground/On-ground
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
B04 - Tank External Protection - Fiberglass
D11 - Pipe Type - Flexible Piping
G04 - Tank Secondary Containment - Double-Walled (Underground)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
H05 - Tank Leak Detection - In-Tank System (ATG)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off

Tank Number:	1
Tank ID:	164231
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	06/01/1974
Date Tank Closed:	07/01/1992
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	02
Date Test:	12/01/1987
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel

DELTA SONIC CAR WASH- AMHERST (Continued) **U004062498**

F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
A01 - Tank Internal Protection - Epoxy Liner
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None

Tank Number: 2
Tank ID: 164232
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 10000
Install Date: 06/01/1981
Date Tank Closed: 07/01/1992
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None

Tank Number: 2A
Tank ID: 174177
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 8000
Install Date: 07/01/1992
Date Tank Closed: 10/14/2013
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: aeskalsk

DELTA SONIC CAR WASH- AMHERST (Continued) **U004062498**

Last Modified: 04/14/2017

Equipment Records:

J01 - Dispenser - Pressurized Dispenser
E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None
B02 - Tank External Protection - Original Sacrificial Anode
K01 - Spill Prevention - Catch Basin
C02 - Pipe Location - Underground/On-ground
I03 - Overfill - Automatic Shut-Off
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
D11 - Pipe Type - Flexible Piping
G04 - Tank Secondary Containment - Double-Walled (Underground)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Number: 2B
Tank ID: 174178
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 7000
Install Date: 07/01/1992
Date Tank Closed: 10/14/2013
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: aeskalsk
Last Modified: 04/14/2017

Equipment Records:

B02 - Tank External Protection - Original Sacrificial Anode
C02 - Pipe Location - Underground/On-ground
J02 - Dispenser - Suction Dispenser
E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
H05 - Tank Leak Detection - In-Tank System (ATG)
D11 - Pipe Type - Flexible Piping
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: 3
Tank ID: 164233
Tank Status: Closed - Removed
Material Name: Closed - Removed

DELTA SONIC CAR WASH- AMHERST (Continued) **U004062498**

Capacity Gallons:	4000
Install Date:	06/01/1974
Date Tank Closed:	07/01/1992
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	01
Date Test:	07/01/1987
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
A01 - Tank Internal Protection - Epoxy Liner
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number:	4
Tank ID:	164234
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	06/01/1984
Date Tank Closed:	10/14/2013
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	21
Date Test:	09/24/2009
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	aeskalsk
Last Modified:	04/14/2017

Equipment Records:

L07 - Piping Leak Detection - Pressurized Piping Leak Detector
B07 - Tank External Protection - Retrofitted Sacrificial Anode
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None
H04 - Tank Leak Detection - Groundwater Well
J01 - Dispenser - Pressurized Dispenser
A00 - Tank Internal Protection - None

DELTA SONIC CAR WASH- AMHERST (Continued) **U004062498**

B01 - Tank External Protection - Painted/Asphalt Coating
I03 - Overfill - Automatic Shut-Off
K01 - Spill Prevention - Catch Basin
D11 - Pipe Type - Flexible Piping

Tank Number:	5
Tank ID:	164235
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	06/01/1984
Date Tank Closed:	07/01/1992
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	2722
Common Name of Substance:	Kerosene [#1 Fuel Oil] (Resale/Redistribute)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
J01 - Dispenser - Pressurized Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None

Tank Number:	6
Tank ID:	164236
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	8000
Install Date:	06/01/1974
Date Tank Closed:	07/01/1992
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	02
Date Test:	11/01/1987
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

DELTA SONIC CAR WASH- AMHERST (Continued) **U004062498**

Equipment Records:

G00 - Tank Secondary Containment - None
A01 - Tank Internal Protection - Epoxy Liner
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser

Tank Number:	7
Tank ID:	164237
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	10000
Install Date:	06/01/1981
Date Tank Closed:	07/01/1992
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
A00 - Tank Internal Protection - None

Tank Number:	8
Tank ID:	164238
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	06/01/1974
Date Tank Closed:	07/01/1992
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

DELTA SONIC CAR WASH- AMHERST (Continued) **U004062498**

Tightness Test Method:	02
Date Test:	12/01/1987
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
A01 - Tank Internal Protection - Epoxy Liner
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
G00 - Tank Secondary Containment - None

170
West
< 1/8
0.053 mi.
282 ft.

Actual:
603 ft.

Focus Map:
8

WASTE OIL **NY Spills** **S102174537**
CHALMERS AND KETTERING **N/A**
TONAWANDA, NY

SPILLS:

Spill Number/Closed Date:	9201318 / 1992-05-08
Facility ID:	9201318
Facility Type:	ER
DER Facility ID:	81907
Site ID:	89678
DEC Region:	9
Spill Cause:	Deliberate
Spill Class:	D3
SWIS:	1564
Spill Date:	1992-05-03
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	1992-05-03
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Citizen
Cleanup Ceased:	1992-05-07
Cleanup Meets Std:	True
Last Inspection:	1992-05-07
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1992-05-08
Spill Record Last Update:	1992-11-05
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 05/07/92: RMC/SITE FOUND OIL IN DITCH AT STORM SEWER ENTRANCE, SENT WASTE OIL LETTER TO PEOPLE IN APTS. CLOSE OUT. "

WASTE OIL (Continued) **S102174537**

Remarks: "PEOPLE IN GREY HOUSE ON CORNOR BELIEVED TO BE DUMPING WASTE OIL BY THEIR HOUSE."

All Materials:

Site ID:	89678
Operable Unit ID:	968702
Operable Unit:	01
Material ID:	412642
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

171
NE
< 1/8
0.056 mi.
297 ft.

GOOD YEAR TIRE **FINDS** **1014811127**
200 JOHN JAMES AUDUBON PARKWAY **N/A**
AMHERST, NY 14228

Actual:
579 ft.

Focus Map:
2

FINDS:

Registry ID: 110042346397

Environmental Interest/Information System

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

AH172 **7- ELEVEN STORE #22491** **NY UST** **U003318313**
SSW **3488 MAIN STREET** **N/A**
< 1/8 **BUFFALO, NY 14214**
0.056 mi.
298 ft. **Site 4 of 8 in cluster AH**

Actual:
653 ft.

Focus Map:
8

UST:

Id/Status:	9-446904 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	9
Expiration Date:	N/A
UTM X:	188439.58413
UTM Y:	4763193.62299
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	54444
Affiliation Type:	Facility Owner
Company Name:	THE SOUTHLAND CORPORATION
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	8545 MAIN STREEET
Address2:	Not reported
City:	WILLIAMSVILLE
State:	NY
Zip Code:	14221
Country Code:	001
Phone:	(716) 633-1522
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	54444
Affiliation Type:	Mail Contact
Company Name:	THE SOUTHLAND CORPORATION
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	8545 MAIN STREEET
Address2:	Not reported
City:	WILLIAMSVILLE
State:	NY
Zip Code:	14221
Country Code:	001
Phone:	(716) 633-1522
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	54444
Affiliation Type:	Facility Operator
Company Name:	7- ELEVEN STORE #22491
Contact Type:	Not reported
Contact Name:	THE SOUTHLAND CORPORATION
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN

7- ELEVEN STORE #22491 (Continued) **U003318313**

Zip Code:	Not reported
Country Code:	001
Phone:	(716) 836-4982
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	54444
Affiliation Type:	Emergency Contact
Company Name:	THE SOUTHLAND CORPORATION
Contact Type:	Not reported
Contact Name:	BOB LASKER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(716) 688-7355
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	1
Tank ID:	167936
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	8000
Install Date:	04/01/1973
Date Tank Closed:	05/01/1993
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

Tightness Test Method:	01
Date Test:	09/01/1989
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser

7- ELEVEN STORE #22491 (Continued) **U003318313**

Tank Number:	2
Tank ID:	167938
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	8000
Install Date:	04/01/1973
Date Tank Closed:	06/01/1993
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	01
Date Test:	09/01/1989
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser

Tank Number:	3
Tank ID:	167937
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	8000
Install Date:	04/01/1973
Date Tank Closed:	03/01/1993
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	01
Date Test:	09/01/1989
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel

7- ELEVEN STORE #22491 (Continued) **U003318313**

F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
H00 - Tank Leak Detection - None
I00 - Overfill - None

AH173 **7-ELEVEN #22491** **RCRA NonGen / NLR** **1000281912**
SSW **3488 MAIN ST** **FINDS** **NYD986898534**
< 1/8 **BUFFALO, NY 14214** **ECHO**
0.056 mi. **NY MANIFEST**
298 ft. **Site 5 of 8 in cluster AH**

Actual:
653 ft.

Focus Map:
8

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	7-ELEVEN #22491
Facility address:	3488 MAIN ST BUFFALO, NY 14214-1337
EPA ID:	NYD986898534
Mailing address:	ROSCOMMON DR MIDDLETOWN, NY 06457
Contact:	Not reported
Contact address:	ROSCOMMON DR MIDDLETOWN, NY 06457
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	THE SOUTHLAND CORP
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	THE SOUTHLAND CORP
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

7-ELEVEN #22491 (Continued) **1000281912**

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: 7-ELEVEN #22491
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: 7-ELEVEN #22491
Classification: Not a generator, verified

Date form received by agency: 05/03/1990
Site name: 7-ELEVEN #22491
Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004445672

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000281912
Registry ID: 110004445672
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004445672

NY MANIFEST:
Country: USA
EPA ID: NYD986898534

7-ELEVEN #22491 (Continued) **1000281912**

Facility Status:	Not reported
Location Address 1:	3488 MAIN STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BUFFALO
Location State:	NY
Location Zip:	14214
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD986898534
Mailing Name:	SOUTHLAND CORPORATION 7 ELEVEN STORE
Mailing Contact:	JOHN SCHLIA
Mailing Address 1:	3488 MAIN STREET
Mailing Address 2:	Not reported
Mailing City:	BUFFALO
Mailing State:	NY
Mailing Zip:	14214
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7168364982

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	MNS000110924
Trans2 State ID:	Not reported
Generator Ship Date:	02/22/2018
Trans1 Recv Date:	02/22/2018
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/01/2018
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986898534
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	MID980615298
TSDF ID 2:	Not reported
Manifest Tracking Number:	011299952FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

7-ELEVEN #22491 (Continued) **1000281912**

Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	5
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	Not reported
Waste Code 1_2:	D007
Waste Code 1_3:	D010
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
16 additional NY MANIFEST: record(s) in the EDR Site Report.

AH174 **KENDALL REFG CO FILLING STA** **EDR Hist Auto** **1014539416**
SSW **3488 MAIN ST** **N/A**
< 1/8 **BUFFALO, NY**
0.056 mi.
298 ft. **Site 6 of 8 in cluster AH**

Actual: EDR Hist Auto
653 ft.

Focus Map:
8

Year:	Name:	Type:
1935	KENDALL REFG CO FILLING STA	GASOLINE AND OIL SERVICE STATIONS
1940	FOX KENDALL SERVICE STATION FIL	GASOLINE AND OIL SERVICE STATIONS
1946	BERCHOU ALBERT FILLING STA	GASOLINE AND OIL SERVICE STATIONS
1950	BERCHOU ALBERT GAS STA	GASOLINE STATIONS
1955	BERCHOU ALBERT GAS STA	GASOLINE STATIONS
1960	BERTS KENDALL SERV STA	GASOLINE STATIONS
1964	BERTS KENDALL SERVICE STATION	GASOLINE STATIONS
1969	BERTS KENDALL STATION	Gasoline Service Stations
1970	BERTS KENDALL SERVICE STATION	GASOLINE STATIONS
1970	BERTS KENDALL STATION	Gasoline Service Stations
1971	BERTS KENDALL STATION	Gasoline Service Stations
1972	BERTS KENDALL SERVICE	Gasoline Service Stations
1973	BERTS KENDALL SERVICE	Gasoline Service Stations
1974	BERTS KENDALL SERVICE	Gasoline Service Stations
1975	CHARGER GAS STATION	GASOLINE STATIONS
1975	BERTS KENDALL SERVICE	Gasoline Service Stations
1980	AMOCO SERV STA	GASOLINE STATIONS

AH175 **WALGREENS PARKING LOT** **NY Spills** **S118638204**
SSW **3488 MAIN STREET** **N/A**
< 1/8 **BUFFALO, NY**
0.056 mi.
298 ft. **Site 7 of 8 in cluster AH**

Actual: SPILLS:
653 ft.

Spill Number/Closed Date:	1601035 / 2016-05-02
Facility ID:	1601035
Facility Type:	ER

Focus Map:
8

WALGREENS PARKING LOT (Continued) **S118638204**

DER Facility ID:	95974
Site ID:	526339
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	1502
Spill Date:	2016-05-01
Investigator:	TDJOHNSO
Referred To:	Not reported
Reported to Dept:	2016-05-01
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Passenger Vehicle
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2016-05-01
Spill Record Last Update:	2016-05-02
Spiller Name:	KAMILAH WHITFIELD
Spiller Company:	UNKNOWN
Spiller Address:	3488 MAIN STREET
Spiller Company:	999
Contact Name:	KAMILAH WHITFIELD
DEC Memo:	"05/02/16 TDJ MINOR SPILL CLEANED BY FIRE DEPT. NO FURTHER ACTION FILE CLOSED TO ELECTRONIC ONLY"
Remarks:	"Spill was completely contained. Clean up is in complete."

All Materials:

Site ID:	526339
Operable Unit ID:	1275266
Operable Unit:	01
Material ID:	2279991
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

AH176 **7-ELEVEN STORE #22491** **NY Spills** **S102174996**
SSW **3488 MAIN STREET** **N/A**
< 1/8 **BUFFALO, NY**
0.056 mi.
298 ft. **Site 8 of 8 in cluster AH**

Actual:
653 ft.

Focus Map:
8

SPILLS:

Spill Number/Closed Date:	9211094 / 2000-11-03
Facility ID:	9211094
Facility Type:	ER
DER Facility ID:	95974
Site ID:	109271

7-ELEVEN STORE #22491 (Continued) **S102174996**

DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	1502
Spill Date:	1992-12-23
Investigator:	SORGI
Referred To:	Not reported
Reported to Dept:	1992-12-23
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1992-12-28
Spill Record Last Update:	2000-12-11
Spiller Name:	Not reported
Spiller Company:	SOUTHLAND CORPORATION
Spiller Address:	814 BAKER AVENUE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MJS 12/23/92: MJS TELECON GARY BLAIR OF SOUTHLAND CORP, SUBMERSIBLE PUMP LEAKED TOBACKFILL AROUND PUMP. SOUTHLAND CORP. MAY BE CLOSING THIS FACILITY; IF SO, PHASE I SUBSURFACE INVESTIGATION WILL BE DONE. 12/29/92: MJS SENT LETTER REQUESTING INCIDENT REPORT. 01/14/93: MJS TELECON GLENN GORAL OF CEA (CONSULTANT), HE SAID SOIL BORING TAKEN TWO WEEKS AGO FOR 8021. BEDROCK AT 9'. INFO FORWARDED REGARDING DEC LETTER OF 12/29/92. SAMPLE RESULTS WILL BE FORWARDED WHEN RECEIVED. PHASE I WILL BE DONE. 01/19/93: MJS RECEIVED LETTER FROM CEA. PHASE I STUDY BEING DONE & REPORT DUE APPROX. 2/1/93. FOUR SOIL BORINGS DONE. ANALYZED FOR EPA 8021 AND 418.1. NO EVIDENCE OF LARGE LEAK FOUND. 03/12/93: MJS RECEIVED SITE ASSESSMENT FROM CEA. FOUR SOIL BORINGS DONE. LOW-LEVEL CONTAMINATION FOUND IN BORING #4 (NAPHTHALENE AT 33 PPB AND 1,2,4 TRIMETHYLBENZENE AT 2.0 PPB). 03/24/93: MJS TELECON GLEN GORAL OF CEA, HE SAID SOUTHLAND CORP. HAS DECIDED TO END GASOLINE SALES AT THIS LOCATION. TANKS ARE PLANNED FOR REMOVAL IN MAY OF 1993, HE WILL BE FORWARDING A WORK SCHEDULE. 05/18/93: MJS SITE INSPECTION, MET PAUL DONNELLY, ONE TANK REMOVED. SOIL FROM TANK PIT IS CONTAMINATED. MORE EXCAVATION NECESSARY. SOIL STILL PLANNED FOR RECYCLING AT MILLER ASPHALT. ANOTHER TANK TO BE REMOVED TOMORROW. 05/19/93: MJS SITE INSPECTION, MET GLENN GORAL AND PAUL DONELLY, ALL TANKS REMOVED. CANNOT EXCAVATE TO CONTAMINATION LIMITS. MJS GAVE PERMISSION TO BACKFILL EXCAVATION WITH CONTAMINATED SOIL. INFORMED FURTHER WORK REQUIRED. 06/24/93: MJS RECEIVED REMEDIAL ACTION PLAN FROM CEA WITH ENGINEERING DRAWINGS. SVES WILL BE INSTALLED. 07/01/93: MJS RECEIVED RAP FROM FUGRO-MCCLELLAND. THEY ARE NOW HANDLING REMEDIATION AND ARE ADOPTING RAP OF CEA. MJS TELECON WITH BOB CATALDO. SVES WILL BE INSTALLED WEEK OF 07/19/93. 07/12/93: MJS RECEIVED REPORT FROM SOUTHLAND CORP WITH SAMPLE RESULTS OF CONTAMINATED SOIL. 07/20/93: MJS SITE INSPECTION, MET SAL BAZZANO OF FUGRO AND K & T PUMP. STARTING TO INSTALL VERTICAL AND HORIZONTAL PIPING. WORK ESTIMATED TO BE COMPLETE BY 07/22/93. PHOTOS TAKEN.

7-ELEVEN STORE #22491 (Continued) **S102174996**

08/02/93: MJS RECEIVED PROPOSAL FOR SOIL-VAPOR PILOT TEST REPORT FROM FUGRO. TEDLAR BAG SAMPLE TO BE OBTAINED AFTER EIGHT HOURS AND AFTER TWO WEEKS. 08/19/93: MJS SENT LETTER TO RP, REQUIREMENTS FOR VENT SYSTEM AND MONTHLY REPORTS. 10/18/93: MJS RECEIVED START-UP AND IMPLEMENTATION REPORT FROM FUGRO-EAST. SYSTEM STARTED ON 9/12, INITIAL BENZENE CONCENTRATION ABOVE 0.02 POUNDS/HOUR BUT DECREASED DURING TWO-WEEK PILOT TEST. CURRENT DISCHARGE RATE IS LESS THAN THE LIMIT. THEY WILL COLLECT VAPOR SAMPLES DURING MONTHS 2 AND 3 AND QUARTERLY THEREAFTER. GROUNDWATER SAMPLES COLLECTED ON 9/23. 11/05/93: MJS RECEIVED MONTHLY REPORT FROM FUGRO-EAST. DISCHARGE RATES REMAIN BELOW LIMITS. GROUNDWATER SAMPLE RESULTS ARE 23 PPM AND 53 PPM AT V-1, V-2. THEY WIL SAMPLE GROUNDWATER AGAIN IN 12/93. 12/--/93: MJS RECEIVED MONITORING REPORT FOR OCT/NOV 1993. EXTRACTION VAPORS RANGED 1-6 PPM ON PID METER. GW SAMPLING SCHEDULED FOR 12/93. 02/15/94: MJS RECEIVED MONITORING REPORT FOR DECEMBER 1993. RESULTS OF GROUNDWATER SAMPLING ARE 7 PPM AND 6 PPM FOR V-3 (FORMERLY V-1) AND V-4 (FORMERLY V-2), RESPECTIVELY.(BTEX+MTBE) 06/15/94: MJS RECEIVED MONITORING REPORT FOR JAN-MAR 1994. TEDLAR BAG SAMPLE OF VAPOR EFFLUENT SHOW CONCENTRATION ALL LESS THAN 1 PPM. 08/15/94: MJS RECEIVED MONITORING REPORT FOR APR-JUN 1994. GROUNDWATER SAMPLED IN JUNE 1994. BTEX+MTBE CONCENTRATIONS ARE 4 PPM AND 1.7 PPM FOR V-3 AND V-4, RESPECTIVELY. CONTINUING TO OPERATE SVE SYSTEM. 11/14/94: MJS RECEIVED MONITORING REPORT FOR JUL-SEP 1994. TEDLAR BAG SAMPLES COLLECTED IN EACH MONTH AND ALL VERY LOW-LEVEL RESULTS. GROUNDWATER RESULTS ARE 9.5 PPM FOR BOTH V-3 AND V-4. 01/30/95: MJS RECEIVED MONITORING REPORT FOR OCT-DEC 1994. GROUNDWATER RESULTS ARE 4.5 PPM AND 1.1 PPM FOR V-3 AND V-4, DECREASED FROM LAST ROUND. CONTINUING TO OPERATE SVE SYSTEM. 05/26/95: MJS RECEIVED MONITORING REPORT FOR JAN-MAR 1995. TEDLAR BAG EFFLUENT SAMPLES CONTINUE TO SHOW LOW-LEVEL CONCENTRATION. GROUNDWATER RESULTS ARE 2.9 PPM AND 1.1 PPM FOR V-3 AND V-4. THEY INSTALLED SOIL BORINGS ON ADJACENT PROPERTY TO THE NORTH AND WILL FORWARD RESULTS OF INVESTIGATION. 08/--/95: MJS RECEIVED PHASE 1 INVESTIGATION REPORT PERFORMED BY KAYVER GROUP. REPORT COVERS 3484, 3488 AND 3514 MAIN ST. REPORT PREPARED FOR H-H ACQUISITION CORP AND KEY BANK. 08/14/95: MJS RECEIVED MONITORING REPORT FOR APR-JUN 1995. 5 PPM BTEX+MTBE AT V-4. V-3 INACCESSIBLE. TWO BORINGS, B-5 AND B-6, INSTALLED ON ADJACENT PROPERTY. APPROX 14 PPM TOTAL 8260 ANALYTES DETECTED AT B-5. NO CONTAMINATION FOUND AT B-6. THEY SUGGEST SHUTDOWN OF SVE SYSTEM AND CYCLING DURING MONTHLY SITE VISITS. THEY WILL TURN SYSTEM ON AND SAMPLE EFFLUENT. IF SAMPLES SHOW SIGNIFICANT INCREASE FROM SYSTEM BEING TURNED OFF, THEY WILL RESTART SYSTEM AND RUN FULL TIME. MJS VERBALLY APPROVED SHUTDOWN. 11/13/95: MJS RECEIVED MONITORING REPORT FOR JUL-SEP 1995. EFFLUENT AIR SAMPLES EITHER NON-DETECT OR VERY LOW-LEVEL. GROUNDWATER SAMPLE RESULTS (BTEX+MTBE) ARE 6.9 PPM AND 6.6 PPM FOR V-3 AND V-4. 02/02/96: MJS RECEIVED MONITORING REPORT FOR OCT-DEC 1995. AIR EFFLUENT SAMPLE RESULTS ARE 191 PPB AND 339 PPB (BTEX ONLY) MTBE NON-DETECT. GROUNDWATER RESULTS ARE 2.5 PPM AND 2.9 PPM AT V-3 AND V-4 (BTEX+MTBE). THEY WILL CONTINUE TO CYCLE THE SVE SYSTEM. 03/01/96: MJS TELECON WITH BOB CATALDO OF FUGRO-EAST AND VERBALLY APPROVED DECOMMISIONING OF SVE SYSTEM. 03/04/96: MJS RECEIVED LETTER FROM FUGRO-EAST. THEY WILL REMOVE SYSTEM. GROUNDWATER SAMPLING SCHEDULED FOR MID-MARCH. THEY WILL BE INSTALLING ORC'S IN THE MONITORING WELLS. 03/04/96: MJS RECEIVED COPY OF LETTER FROM FUGRO EAST TO MYRON HUNT INC. DEMOLITION OF EXISTING BUILDING SCHEDULED FOR END OF APRIL 1996. EXCAVATION TO BEGIN AT THAT TIME FOR CONSTRUCTION OF A WALGREEN'S STORE. FUGRO TO BE ON SITE TO OVERSEE EXCAVATION OF

7-ELEVEN STORE #22491 (Continued) **S102174996**

SOILS AND INSURE PRESERVATION OF POINTS V-3 AND V-4. 04/10/96: MJS RECEIVED MONITORING REPORT FOR JAN-MAR 1996. SVE SYSTEM DISMANTLED. GROUNDWATER RESULTS FOR V-3 AND V-4 ARE 863 PPB AND 93 PPB (BTEX+MTBE), RESPECTIVELY. 05/17/96: MJS SENT LETTER TO THOMAS HAGNER STATING THAT MOBIL, SOUTHLAND AND NFTA ARE ALL CONSIDERED PRP'S FOR THE CONTAMINATION FOUND AT THE BUS LOOP. THE CURRENT PLANS ARE TO DEVELOP THE ENTIRE CORNER (7-11, FORMER MOBIL AND NFTA BUS LOOP) INTO A NEW WALGREEN'S SITE. 06/17/00: MJS LETTER TO MOBIL, SOUTHLAND AND NFTA STATING THEY ARE ALL CONSIDERED PRP'S AND REQUESTING INVESTIGATION OR DEC WILL PERFORM THE WORK. 06/ /00: MJS TELECON FROM SEAN IRWIN, HE IS PERFORMING SITE ASSESSMENT ON BEHALF OF MOBIL AT ADJACENT PROPERTY (NFTA BUS LOOP), CONTMINATION FOUND. RESULTS SUGGEST MIGRATION FROM SOUTHLAND PROPERTY. 07/19/96: MJS RECEIVED MONITORING REPORT FOR APR-JUN 1996. GROUNDWATER RESULTS FOR V-3 AND V-4 ARE 1490 PPB AND 1540 PPB, RESPECTIVELY (BTEX+MTBE). 07/30/96: MSJ SENT LETTER TO SOUTHLAND REQUESTING THEY REMEDIATE CONTAMINATED SOILS ON NFTA PROPERTY. 08/01/96: MJS RECEIVED COPY OF SITE ASSESSMENT PERFORMED BY KAYVER GROUP FROM MOBIL.(REPORT FILED UNDER SPILL #9207319 - MOBIL). REPORT SUGGESTS CONTAMINATION AT BUS LOOP MIGRATED FROM SOUTHLAND (7-ELEVEN) PROPERTY. COVER LETTER FROM MOBIL STATES THEY PLAN NO FURTHER INVESTIGATION. 08/05/00: MJS AND RNL ON SITE MEETING WITH FUGRO. AGREED THAT THEY WILL PERFORM TEST-PITTING TO DETERMINE EXTENT OF CONTAMINATION. 08/07/96: MJS SENT LETTER TO SOUTHLAND CONFIRMING OUR AGREEMENT AT SITE MEETING. 09/27/96: MJS SITE INSPECTION, MET WITH BOB PEDLEY (FUGRO). NATURES WAY DROPPED OFF 9000 GAL TANKER FOR HOLDING AND FILTERING CONTAMINATED WATER FROM EXCAVATION. 09/28/96: SATURDAY. MJS AND RNL SITE MEETING WITH HAGNER, HUNT, AND PEDLEY. RAINWATER IS COLLECTING IN PIT. RNL AGREED WATER MUST BE FILTERED. AGREED ON SAMPLING PLAN FOR EXCAVATION. CONTAMINATED SOIL REMAINS ON EAST SIDE OF EXCAVATION UNDER NEW ROAD AND CANNOT BE EXCAVATED DUE TO UTILITY LINES. RNL ASKED FOR TEST PITS ON EAST SIDE OF NEW ROAD TO DETERMINE IF CONTAMINATION CONTINUES ACROSS THE ROAD TOWARD MOBIL SITE. POSSIBLE SVE SPUR TO BE REQUIRED ON EAST SIDE OF NEW ROAD BY RETAINING WALL TO VENT REMAINING CONTAMINATED SOIL. 09/30/96: MJS SITE INSPECTION. THREE TEST PITS PERFORMED ON EAST SIDE OF NEW ROAD AS REQUESTED BY RNL. ONE TEST PIT (FURTHEST NORTH) SHOWED THIN LAYER (~2 INCHES) OF CONTAMINATED SOIL AT BEDROCK. OTHER TWO TEST PITS SHOWED NO CONTAMINATION. THUS, CONTAMINATION AT SOUTHLAND SITE DOES NOT RUN ACROSS ROAD AND TERMINATES SOMEWHERE IN MIDDLE OF ROAD. FUGRO AND NATURES WAY PUMPING CONTAMINATED WATER FROM EXCAVATION AND CONTINUING TO EXCAVATE SOIL. RNL SITE INSPECTION, MJS EXPLAINED FINDINGS OF TEST PITS AND UPDATED RNL ON SITE ACTIVITIES. 10/01/96: MJS SITE INSPECTION, MET BOB PEDLEY. HE IS OBTAINING POST-EXCAVATION SIDEWALL SAMPLES. RUSS SAVAGE (NWI) DROPPED OFF WELL SCREEN FOR PRECAUTIONARY SVE LEG. 10/02/96: MJS SITE INSPECTION, MET BOB PEDLEY. HE IS WAITING FOR RETAINING WALL CONSTRUCTION TO INSTALL SVE VENT PIPE. SOME SOIL STOCKPILED FROM EAST END OF EXCAVATION, REMOVED DURING TRENCHING FOR RETAINING WALL. 10/03/96: MJS SITE INSPECTION, MET BOB PEDLEY. HE INSTALLED SVE LEG NEXT TO RETAINING WALL. MJS TELECON WITH RUSS SAVAGE. SAMPLE RESULTS FOR FILTERED TANK PIT WATER ARE RECEIVED AND SHOW NO VIOLATIONS. HE WILL FAX COPY OF SAMPLE RESULTS. MJS INFORMED BOB PEDLEY AND NWI THAT FILTERED WATER CAN BE DISCHARGED TO SEWER. HE WILL BE LEAVING IN AM, PLANNED REMEDIATION COMPLETED. REMEDIATION REPORT SHALL BE FORWARDED TO DEC WITH SAMPLE RESULTS AND DISPOSAL DOCUMENTATION. 11/04/96: MJS RECEIVED CLOSURE REPORT FROM FUGRO EAST INC. SOIL SAMPLE RESULTS FROM ALONG EAST WALL OF EXCAVATION INDICATE SIGNIFICANT LEVELS OF

7-ELEVEN STORE #22491 (Continued) **S102174996**

CONTAMINATION REMAIN(~50 PPM TOTAL) AS EXPECTED. ALL OTHER SAMPLE RESULTS FROM WALLS OF EXCAVATION ARE NON-DETECT LEVELS. A TOTAL OF 2183 CUBIC YARDS OF SOIL WERE REMOVED FROM THE SITE AND DISPOSED AT LAKEVIEW LANDFILL. THE REPORT ESTIMATES REMAINING SOIL CONTAMINATION AT 30-40 CUBIC YARDS UNDERNEATH WALKWAY AND ROADWAY. 11/27/96: MJS AND RNL MEETING AT DEC OFFICE WITH TOM HAGNER. DEC CANNOT MAKE FILE INACTIVE AT THIS TIME DUE TO HIGH CONCENTRATIONS ONE ONE SAMPLE ALONG EAST WALL OF EXCAVATION. FURTHER WORK IS REQUIRED. SOUTHLAND CAN EITHER INSTALL PUMP ON SVE SPUR INSTALLED BY RETAINING WALL OR PERFORM RBCA STUDY TO ATTEMPT FULL CLOSURE. MJS TO SEND LETTER STATING ABOVE TO SOUTHLAND AND CONSULTANT (FUGRO). 12/04/96: MJS SENT LETTER TO RP, THEY MUST EITHER ACTIVATE SVE SYSTEM OR PERFORM RBCA STUDY. CC: TOM HAGNER, CHRIS MARIANO (FUGRO). RP TO RESPOND IN WRITING. 12/10/96: MJS TELECON FROM CHRIS MARIANO AND DISCUSSED LETTER OF 12/4. HE STATED THAT FUGRO WILL MOST LIKELY PERFORM RBCA STUDY FOR FILE CLOSURE, . MJS ADVISED MR MARIANO TO CONTACT FRANK PEDUTO (CENTRAL OFFICE) REGARDING CURRENT RBCA REQUIREMENTS AND GUIDELINES. 01/21/97: MJS RECEIVED LETTER FROM FUGRO-EAST. CHRIS MARIANO SPOKE WITH TOM PLESNARSKI REGARDING RBCA POLICY. RBCA INTERIM PROCEDURES ARE DUE OUT THIS MONTH FOR REVIEW BY AN ADVISORY COMMITTEE, OF WHICH FUGRO IS A MEMBER. IF OFFICIALLY IMPLEMENTED, FUGRO WILL PERFORM A RBCA STUDY FOR THIS SITE. 11/03/00: MJS REVIEW FILE. NO KNOWN WORK PERFORMED SINCE LAST ENTRY. RBCA POLICY NEVER IMPLEMENTED BY NYSDEC, RBCA STUDY NEVER PERFORMED. MJS REVIEW WORK PERFORMED DURING CLEANUP. TOTAL OF 2183 TONS SOIL DISPOSED. ELEVEN SOIL SAMPLES COLLECTED FROM WALLS OF EXCAVATION. NO FLOOR SAMPLE COLLECTED, FLOOR IS BEDROCK. ALL SAMPLE RESULTS OF EXCAVATION ARE EITHER NON-DETECT OR LOW-LEVEL EXCEPT FOR TWO OF FOUR SAMPLES COLLECTED ALONG EAST SIDEWALL (THESE SAMPLES ARE IDENTIFIED AS EASTWALL AND EWN) AND ARE SPACED APPROX TWENTY FEET APART. SAMPLES TO THE NORTH AND SOUTH ALONG THE SAME WALL ARE EITHER NON-DETECT OR LOW-LEVEL. FURTHER EXCAVATION OF THESE IMPACTED SOILS WAS INHIBITED BY UTILITIES AND A NEW ROADWAY CONTRUCTED ON THE SITE FOR AN NFTA BUS STOP. TEST PITS ON OTHER SIDE OF ROAD INDICATED ONLY THIN VENEER OF CONTAMINATION AT SOIL-BEDROCK INTERFACE AT ONE TEST PIT LOCATION ONLY. ANY REMAINING RESIDUAL CONTAMINATION (ESTIMATED AT A MAX OF 30-40 TONS) IS IN UTILITIES (WATER AND FIBER OPTIC) AND UNDER ROADWAY. MJS PERFORMED INFORMAL EXPOSURE ASSESSMENT USING AVAILABLE DATA AND INFORMATION: 1. SITE CHARACTERIZATION - ALL CONTAMINATION IDENTIFIED 2. SOURCE REMOVAL COMPLETE - 2183 TONS SOIL EXCAVATED AND REMOVED, CLEAN SAMPLE RESULTS EXCEPT FOR SMALL AREA ON EAST WALL. APPROX 30 TONS CONTAMINATED SOIL REMAIN IN UTILITIES. THIS REPRESENTS ONLY 1.3 PERCENT OF CONTAMINATED SOILS, 98.7 PERCENT OF CONTAMINATION REMOVED. 3. REMEDIATION - COST OF REMEDIATING REMAINING 30 TONS IN UTILITIES AND UNDER ROAD IS IMPRUDENT CONSIDERING 98.7 PERCENT REMOVAL AT THIS TIME. 4. EXPOSURE ASSESSMENT - NO DRINKING WATER WELLS IN AREA, PUBLIC WATER SUPPLY. ONLY POTENTIAL RECEPTOR IS CONSTRUCTION WORKER AND POTENTIAL PATHWAY IS SOIL VOLATILIZATION TO OUTDOORS. CONSIDERING BEDROCK IS AT APPROX 3' BGS, REMAINING CONTAMINATED SOILS ARE CONSIDERED SURFICIAL FOR PURPOSE OF EXPOSURE ASSESSMENT. MJS COMPARED SOIL SAMPLE RESULTS FROM EAST WALL TO THE VOLATILIZATION TO OUTDOORS COLUMN (SOIL) AND SURFICIAL SOIL COLUMN UNDER THE CONSTRUCTION WORKER RECEPTOR (LOOK-UP) TABLE. SOIL SAMPLE RESULTS ARE WELL WITH THE ALLOWABLE CONCENTRATION VALUES. MJS SUBMIT FILE TO RNL FOR REVIEW FOR INACTIVE STATUS."

Remarks: "PUMP FAILURE."

7-ELEVEN STORE #22491 (Continued) **S102174996**

All Materials:

Site ID:	109271
Operable Unit ID:	978052
Operable Unit:	01
Material ID:	404519
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AL177 **SUNY AT BUFFALO - NORTH CAMPUS** **NY AST** **U003107392**
NW **SERVICE BUILDING** **N/A**
< 1/8 **BUFFALO, NY 14215**
0.057 mi.
302 ft. **Site 1 of 2 in cluster AL**

Actual:
660 ft.

Focus Map:
8

AST:

Region:	STATE
DEC Region:	9
Site Status:	Active
Facility Id:	9-039403
Program Type:	PBS
UTM X:	188404.68550
UTM Y:	4762233.24036
Expiration Date:	05/07/2017
Site Type:	School

Affiliation Records:

Site Id:	52262
Affiliation Type:	Facility Owner
Company Name:	STATE UNIVERSITY OF NEW YORK
Contact Type:	DIRECTOR, EH&S SERVICES
Contact Name:	JOSEPH RAAB
Address1:	STATE UNIVERSITY CENTRAL OFFICE
Address2:	Not reported
City:	ALBANY
State:	NY
Zip Code:	12246
Country Code:	001
Phone:	(518) 473-4060
EMail:	Not reported
Fax Number:	Not reported
Modified By:	SLZIEMBA
Date Last Modified:	2015-07-16

Site Id:	52262
Affiliation Type:	Mail Contact
Company Name:	SUNY AT BUFFALO
Contact Type:	Not reported
Contact Name:	BRIAN FOTI
Address1:	ENVIRONMENT, HEALTH & SAFETY SERVICES
Address2:	220 WINSPEAR AVENUE
City:	BUFFALO

SUNY AT BUFFALO - NORTH CAMPUS (Continued) **U003107392**

State:	NY
Zip Code:	14215-1034
Country Code:	001
Phone:	(716) 829-3301
EMail:	BRIANF@BUFFALO.EDU
Fax Number:	Not reported
Modified By:	SLZIEMBA
Date Last Modified:	2015-07-16

Site Id:	52262
Affiliation Type:	Facility Operator
Company Name:	SUNY AT BUFFALO - NORTH CAMPUS
Contact Type:	Not reported
Contact Name:	TIMOTHY RITTLING
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(716) 645-5962
EMail:	Not reported
Fax Number:	Not reported
Modified By:	AYLAGATI
Date Last Modified:	2017-03-06

Site Id:	52262
Affiliation Type:	Emergency Contact
Company Name:	STATE UNIVERSITY OF NEW YORK
Contact Type:	Not reported
Contact Name:	UNIVERSITY POLICE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(716) 645-2222
EMail:	Not reported
Fax Number:	Not reported
Modified By:	SLZIEMBA
Date Last Modified:	2015-07-16

Tank Info:

Tank Number:	01DN
Tank Id:	215024
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
C01 - Pipe Location - Aboveground
A00 - Tank Internal Protection - None

SUNY AT BUFFALO - NORTH CAMPUS (Continued) **U003107392**

B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
G01 - Tank Secondary Containment - Diking (Aboveground)
L00 - Piping Leak Detection - None
J02 - Dispenser - Suction Dispenser

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	02/10/2006
Capacity Gallons:	50
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	BFGRABER
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	01N
Tank Id:	215023
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
L00 - Piping Leak Detection - None

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	02/17/2006
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	BFGRABER
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

SUNY AT BUFFALO - NORTH CAMPUS (Continued) **U003107392**

Tank Number: 02DN
Tank Id: 215026
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
E00 - Piping Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
L00 - Piping Leak Detection - None
G01 - Tank Secondary Containment - Diking (Aboveground)

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 02/10/2006
Capacity Gallons: 50
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: BFGRABER
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

Tank Number: 02N
Tank Id: 215025
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L00 - Piping Leak Detection - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service

SUNY AT BUFFALO - NORTH CAMPUS (Continued) **U003107392**

Pipe Model:	Not reported
Install Date:	02/10/2006
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	BFGRABER
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	03N
Tank Id:	215027
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
C03 - Pipe Location - Aboveground/Underground Combination
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
G01 - Tank Secondary Containment - Diking (Aboveground)
L00 - Piping Leak Detection - None

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	02/10/2006
Capacity Gallons:	50
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	BFGRABER
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	1
Tank Id:	161125
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron

SUNY AT BUFFALO - NORTH CAMPUS (Continued) **U003107392**

F01 - Pipe External Protection - Painted/Asphalt Coating
G10 - Tank Secondary Containment - Impervious Underlayment
C01 - Pipe Location - Aboveground
J02 - Dispenser - Suction Dispenser
I00 - Overfill - None
L09 - Piping Leak Detection - Exempt Suction Piping
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	12/01/1972
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	01/13/2006
Register:	True
Modified By:	AESKALSK
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	16
Tank Id:	161140
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
G10 - Tank Secondary Containment - Impervious Underlayment
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	12/01/1984
Capacity Gallons:	50
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	01/19/2006
Register:	True
Modified By:	AESKALSK
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	16N
Tank Id:	215028

SUNY AT BUFFALO - NORTH CAMPUS (Continued) **U003107392**

Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
G01 - Tank Secondary Containment - Diking (Aboveground)
L00 - Piping Leak Detection - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 02/06/2006
Capacity Gallons: 50
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: BFGRABER
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

Tank Number: 1D
Tank Id: 174417
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
G10 - Tank Secondary Containment - Impervious Underlayment
A00 - Tank Internal Protection - None
L09 - Piping Leak Detection - Exempt Suction Piping
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
J02 - Dispenser - Suction Dispenser
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 12/01/1972
Capacity Gallons: 10
Tightness Test Method: NN
Date Test: Not reported

SUNY AT BUFFALO - NORTH CAMPUS (Continued) **U003107392**

Next Test Date: Not reported
Date Tank Closed: 01/13/2006
Register: True
Modified By: AESKALSK
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

Tank Number: 2
Tank Id: 161126
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
G10 - Tank Secondary Containment - Impervious Underlayment
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 12/01/1978
Capacity Gallons: 275
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 01/10/2006
Register: True
Modified By: AESKALSK
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

Tank Number: 25
Tank Id: 161149
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
C01 - Pipe Location - Aboveground
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating

SUNY AT BUFFALO - NORTH CAMPUS (Continued) **U003107392**

G01 - Tank Secondary Containment - Diking (Aboveground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	12/01/1977
Capacity Gallons:	50
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	BFGRABER
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	2D
Tank Id:	174418
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
G10 - Tank Secondary Containment - Impervious Underlayment
J02 - Dispenser - Suction Dispenser
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
C01 - Pipe Location - Aboveground

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	12/01/1978
Capacity Gallons:	25
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	01/10/2006
Register:	True
Modified By:	AESKALSK
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	3
Tank Id:	161127
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

SUNY AT BUFFALO - NORTH CAMPUS (Continued) **U003107392**

J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
G10 - Tank Secondary Containment - Impervious Underlayment
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
C01 - Pipe Location - Aboveground
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	12/01/1973
Capacity Gallons:	50
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	01/19/2006
Register:	True
Modified By:	AESKALSK
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	38N
Tank Id:	215029
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
C01 - Pipe Location - Aboveground
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
G01 - Tank Secondary Containment - Diking (Aboveground)
L00 - Piping Leak Detection - None

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	02/07/2006
Capacity Gallons:	550
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	BFGRABER
Last Modified:	04/14/2017

SUNY AT BUFFALO - NORTH CAMPUS (Continued) **U003107392**

Material Name: #2 fuel oil (on-site consumption)

Tank Number: 39
Tank Id: 172064
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:
G10 - Tank Secondary Containment - Impervious Underlayment
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
I02 - Overfill - High Level Alarm
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
E00 - Piping Secondary Containment - None
F04 - Pipe External Protection - Fiberglass
J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
C01 - Pipe Location - Aboveground
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location: 3
Tank Type: Fiberglass Reinforced Plastic
Tank Status: In Service
Pipe Model: Not reported
Install Date: 09/01/1993
Capacity Gallons: 100
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: TJWALKER
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

Tank Number: 4
Tank Id: 161128
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
G10 - Tank Secondary Containment - Impervious Underlayment
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron

SUNY AT BUFFALO - NORTH CAMPUS (Continued) **U003107392**

Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 09/01/1973
Capacity Gallons: 55
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 03/02/2006
Register: True
Modified By: AESKALSK
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

Tank Number: 40
Tank Id: 172566
Material Code: 0009
Common Name of Substance: Gasoline

Equipment Records:

D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
K01 - Spill Prevention - Catch Basin
E04 - Piping Secondary Containment - Double walled UG
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
J02 - Dispenser - Suction Dispenser
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
B05 - Tank External Protection - Jacketed
G04 - Tank Secondary Containment - Double-Walled (Underground)
L02 - Piping Leak Detection - Interstitial - Manual Monitoring

Tank Location: 6
Tank Type: Fiberglass Reinforced Plastic
Tank Status: In Service
Pipe Model: Not reported
Install Date: 03/01/1997
Capacity Gallons: 4000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: BFGRABER
Last Modified: 04/14/2017
Material Name: gasoline

Tank Number: 41
Tank Id: 172567
Material Code: 0009
Common Name of Substance: Gasoline

Equipment Records:

D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
K01 - Spill Prevention - Catch Basin

SUNY AT BUFFALO - NORTH CAMPUS (Continued) **U003107392**

C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
J02 - Dispenser - Suction Dispenser
E04 - Piping Secondary Containment - Double walled UG
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
B05 - Tank External Protection - Jacketed
G04 - Tank Secondary Containment - Double-Walled (Underground)
L02 - Piping Leak Detection - Interstitial - Manual Monitoring

Tank Location:	6
Tank Type:	Fiberglass Reinforced Plastic
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	03/01/1997
Capacity Gallons:	4000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	BFGRABER
Last Modified:	04/14/2017
Material Name:	gasoline

Tank Number:	42
Tank Id:	172568
Material Code:	0009
Common Name of Substance:	Gasoline

Equipment Records:

L02 - Piping Leak Detection - Interstitial - Manual Monitoring
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
E04 - Piping Secondary Containment - Double walled UG
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
K01 - Spill Prevention - Catch Basin
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
J02 - Dispenser - Suction Dispenser
B05 - Tank External Protection - Jacketed
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Location:	6
Tank Type:	Fiberglass Reinforced Plastic
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	03/01/1997
Capacity Gallons:	4000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	BFGRABER
Last Modified:	04/14/2017

SUNY AT BUFFALO - NORTH CAMPUS (Continued) **U003107392**

Material Name: gasoline

Tank Number: 43
Tank Id: 172569
Material Code: 0008
Common Name of Substance: Diesel

Equipment Records:

D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
K01 - Spill Prevention - Catch Basin
E04 - Piping Secondary Containment - Double walled UG
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
J02 - Dispenser - Suction Dispenser
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
B05 - Tank External Protection - Jacketed
G04 - Tank Secondary Containment - Double-Walled (Underground)
L02 - Piping Leak Detection - Interstitial - Manual Monitoring

Tank Location: 6
Tank Type: Fiberglass Reinforced Plastic
Tank Status: In Service
Pipe Model: Not reported
Install Date: 03/01/1997
Capacity Gallons: 4000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: BFGRABER
Last Modified: 04/14/2017
Material Name: diesel

Tank Number: 44
Tank Id: 174420
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
I00 - Overfill - None
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
G01 - Tank Secondary Containment - Diking (Aboveground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location: 3

SUNY AT BUFFALO - NORTH CAMPUS (Continued) **U003107392**

Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	04/01/1999
Capacity Gallons:	500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	BFGRABER
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	44D
Tank Id:	179501
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

K00 - Spill Prevention - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
A00 - Tank Internal Protection - None
I00 - Overfill - None
E00 - Piping Secondary Containment - None
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
C01 - Pipe Location - Aboveground
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None

Tank Location:	2
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	04/01/1999
Capacity Gallons:	50
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	05/03/2006
Register:	True
Modified By:	AESKALSK
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	44DN
Tank Id:	215030
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

E00 - Piping Secondary Containment - None

SUNY AT BUFFALO - NORTH CAMPUS (Continued) **U003107392**

I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
G01 - Tank Secondary Containment - Diking (Aboveground)
L00 - Piping Leak Detection - None

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	03/02/2006
Capacity Gallons:	50
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	BFGRABER
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	45
Tank Id:	174421
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

G01 - Tank Secondary Containment - Diking (Aboveground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	03/01/1997
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	12/06/2003
Register:	True
Modified By:	AESKALSK
Last Modified:	04/14/2017
Material Name:	waste oil/used oil

SUNY AT BUFFALO - NORTH CAMPUS (Continued) **U003107392**

Tank Number: 46
Tank Id: 174422
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

E00 - Piping Secondary Containment - None
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
G04 - Tank Secondary Containment - Double-Walled (Underground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Tank Converted to Non-Regulated Use
Pipe Model: Not reported
Install Date: 12/01/2000
Capacity Gallons: 400
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 06/20/2007
Register: True
Modified By: LDGOMEZ
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

Tank Number: 47
Tank Id: 174423
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
G04 - Tank Secondary Containment - Double-Walled (Underground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported

SUNY AT BUFFALO - NORTH CAMPUS (Continued) **U003107392**

Install Date: 12/01/2000
Capacity Gallons: 400
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 06/20/2007
Register: True
Modified By: LDGOMEZ
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

Tank Number: 48
Tank Id: 174424
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
E00 - Piping Secondary Containment - None
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
G04 - Tank Secondary Containment - Double-Walled (Underground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 12/01/2000
Capacity Gallons: 400
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 06/20/2007
Register: True
Modified By: LDGOMEZ
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

Tank Number: 49
Tank Id: 174425
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
E00 - Piping Secondary Containment - None
K01 - Spill Prevention - Catch Basin

SUNY AT BUFFALO - NORTH CAMPUS (Continued) **U003107392**

L09 - Piping Leak Detection - Exempt Suction Piping
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	12/01/2000
Capacity Gallons:	400
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	11/11/2014
Register:	True
Modified By:	SLZIEMBA
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	4D
Tank Id:	174419
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
G10 - Tank Secondary Containment - Impervious Underlayment
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
C01 - Pipe Location - Aboveground
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	09/01/1973
Capacity Gallons:	10
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	03/05/2006
Register:	True
Modified By:	AESKALSK
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	5

SUNY AT BUFFALO - NORTH CAMPUS (Continued) **U003107392**

Tank Id: 161129
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

D01 - Pipe Type - Steel/Carbon Steel/Iron
G99 - Tank Secondary Containment - Other
A00 - Tank Internal Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 09/01/1974
Capacity Gallons: 250
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 09/01/2001
Register: True
Modified By: TRANSLAT
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

Tank Number: 50
Tank Id: 174426
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

F01 - Pipe External Protection - Painted/Asphalt Coating
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
G04 - Tank Secondary Containment - Double-Walled (Underground)
J02 - Dispenser - Suction Dispenser
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 12/01/2000
Capacity Gallons: 400
Tightness Test Method: NN
Date Test: Not reported

SUNY AT BUFFALO - NORTH CAMPUS (Continued) **U003107392**

Next Test Date: Not reported
Date Tank Closed: 06/20/2007
Register: True
Modified By: LDGOMEZ
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

Tank Number: 51
Tank Id: 174427
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
I03 - Overfill - Automatic Shut-Off
E00 - Piping Secondary Containment - None
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
G04 - Tank Secondary Containment - Double-Walled (Underground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 12/01/2000
Capacity Gallons: 400
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 06/20/2007
Register: True
Modified By: LDGOMEZ
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

Tank Number: 52
Tank Id: 174428
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron

SUNY AT BUFFALO - NORTH CAMPUS (Continued) **U003107392**

F01 - Pipe External Protection - Painted/Asphalt Coating
I03 - Overfill - Automatic Shut-Off
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	09/01/2001
Capacity Gallons:	400
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	06/20/2007
Register:	True
Modified By:	LDGOMEZ
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	53
Tank Id:	174429
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
E00 - Piping Secondary Containment - None
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
C03 - Pipe Location - Aboveground/Underground Combination
F04 - Pipe External Protection - Fiberglass
J02 - Dispenser - Suction Dispenser
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Location:	6
Tank Type:	Fiberglass Reinforced Plastic
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	10/01/2000
Capacity Gallons:	2500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	06/01/2007
Register:	True
Modified By:	SLZIEMBA
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	53D
Tank Id:	174430
Material Code:	0001

SUNY AT BUFFALO - NORTH CAMPUS (Continued) **U003107392**

Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
G10 - Tank Secondary Containment - Impervious Underlayment
L09 - Piping Leak Detection - Exempt Suction Piping
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location: 3
Tank Type: Stainless Steel Alloy
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 09/01/1974
Capacity Gallons: 25
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 02/24/2006
Register: True
Modified By: AESKALSK
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

Tank Number: 53DN
Tank Id: 215031
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

C01 - Pipe Location - Aboveground
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
G01 - Tank Secondary Containment - Diking (Aboveground)
L00 - Piping Leak Detection - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 02/17/2006
Capacity Gallons: 50
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported

SUNY AT BUFFALO - NORTH CAMPUS (Continued) **U003107392**

Date Tank Closed: Not reported
Register: True
Modified By: BFGRABER
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

Tank Number: 54
Tank Id: 174431
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
I03 - Overfill - Automatic Shut-Off
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
G04 - Tank Secondary Containment - Double-Walled (Underground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 09/01/2001
Capacity Gallons: 220
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: BFGRABER
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

Tank Number: 55D
Tank Id: 174433
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
G10 - Tank Secondary Containment - Impervious Underlayment
L09 - Piping Leak Detection - Exempt Suction Piping

SUNY AT BUFFALO - NORTH CAMPUS (Continued) **U003107392**

H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	09/01/1974
Capacity Gallons:	10
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	02/06/2006
Register:	True
Modified By:	AESKALSK
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	55DN
Tank Id:	215032
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
C01 - Pipe Location - Aboveground
G01 - Tank Secondary Containment - Diking (Aboveground)
L00 - Piping Leak Detection - None

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	03/10/2006
Capacity Gallons:	50
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	BFGRABER
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	56
Tank Id:	174434
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

SUNY AT BUFFALO - NORTH CAMPUS (Continued) **U003107392**

Equipment Records:
H99 - Tank Leak Detection - Other
F01 - Pipe External Protection - Painted/Asphalt Coating
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
C00 - Pipe Location - No Piping
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)
G04 - Tank Secondary Containment - Double-Walled (Underground)
D00 - Pipe Type - No Piping

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	09/01/2001
Capacity Gallons:	1500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	BFGRABER
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	57
Tank Id:	174435
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:
G04 - Tank Secondary Containment - Double-Walled (Underground)
H99 - Tank Leak Detection - Other
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
I03 - Overfill - Automatic Shut-Off
J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
C01 - Pipe Location - Aboveground

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	09/01/2001
Capacity Gallons:	400
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported

SUNY AT BUFFALO - NORTH CAMPUS (Continued) **U003107392**

Date Tank Closed: Not reported
Register: True
Modified By: BFGRABER
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

Tank Number: 58D
Tank Id: 174437
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
G10 - Tank Secondary Containment - Impervious Underlayment
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 07/01/1981
Capacity Gallons: 10
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 03/27/2006
Register: True
Modified By: AESKALSK
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

Tank Number: 58DN
Tank Id: 215033
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

C01 - Pipe Location - Aboveground
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
J02 - Dispenser - Suction Dispenser
G01 - Tank Secondary Containment - Diking (Aboveground)

SUNY AT BUFFALO - NORTH CAMPUS (Continued) **U003107392**

L00 - Piping Leak Detection - None

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	03/24/2006
Capacity Gallons:	50
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	BFGRABER
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	59
Tank Id:	174438
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

G01 - Tank Secondary Containment - Diking (Aboveground)
A01 - Tank Internal Protection - Epoxy Liner
E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
C03 - Pipe Location - Aboveground/Underground Combination
J02 - Dispenser - Suction Dispenser
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	09/01/2001
Capacity Gallons:	1000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	SLZIEMBA
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	59D
Tank Id:	174439
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

SUNY AT BUFFALO - NORTH CAMPUS (Continued) **U003107392**

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
G10 - Tank Secondary Containment - Impervious Underlayment
L09 - Piping Leak Detection - Exempt Suction Piping
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	07/01/1981
Capacity Gallons:	10
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	03/02/2006
Register:	True
Modified By:	AESKALSK
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)
Tank Number:	59DN
Tank Id:	215034
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
C01 - Pipe Location - Aboveground
J02 - Dispenser - Suction Dispenser
G01 - Tank Secondary Containment - Diking (Aboveground)
L00 - Piping Leak Detection - None

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	03/24/2006
Capacity Gallons:	50
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	BFGRABER

SUNY AT BUFFALO - NORTH CAMPUS (Continued) **U003107392**

Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

Tank Number: 60D
Tank Id: 174440
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:
E00 - Piping Secondary Containment - None
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
G10 - Tank Secondary Containment - Impervious Underlayment
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 10/01/1977
Capacity Gallons: 25
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: BFGRABER
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

Tank Number: 61
Tank Id: 174441
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
E00 - Piping Secondary Containment - None
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
I03 - Overfill - Automatic Shut-Off
G04 - Tank Secondary Containment - Double-Walled (Underground)
C01 - Pipe Location - Aboveground

SUNY AT BUFFALO - NORTH CAMPUS (Continued) **U003107392**

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	09/01/2001
Capacity Gallons:	400
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	BFGRABER
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	61D
Tank Id:	174442
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
G10 - Tank Secondary Containment - Impervious Underlayment
L09 - Piping Leak Detection - Exempt Suction Piping
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	07/01/1977
Capacity Gallons:	20
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	02/24/2006
Register:	True
Modified By:	AESKALSK
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	61DN
Tank Id:	215035
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

C01 - Pipe Location - Aboveground
A00 - Tank Internal Protection - None

SUNY AT BUFFALO - NORTH CAMPUS (Continued) **U003107392**

B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
F01 - Pipe External Protection - Painted/Asphalt Coating
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
G01 - Tank Secondary Containment - Diking (Aboveground)
L00 - Piping Leak Detection - None

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	02/10/2006
Capacity Gallons:	50
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	BFGRABER
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	62
Tank Id:	174443
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

I03 - Overfill - Automatic Shut-Off
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
E00 - Piping Secondary Containment - None
B04 - Tank External Protection - Fiberglass
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
G04 - Tank Secondary Containment - Double-Walled (Underground)
J02 - Dispenser - Suction Dispenser
C03 - Pipe Location - Aboveground/Underground Combination
F04 - Pipe External Protection - Fiberglass

Tank Location:	6
Tank Type:	Fiberglass Reinforced Plastic
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	09/01/2001
Capacity Gallons:	600
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	BFGRABER
Last Modified:	04/14/2017

SUNY AT BUFFALO - NORTH CAMPUS (Continued) **U003107392**

Material Name: #2 fuel oil (on-site consumption)

Tank Number: 62D
Tank Id: 174444
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
G10 - Tank Secondary Containment - Impervious Underlayment
L09 - Piping Leak Detection - Exempt Suction Piping
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 10/01/1981
Capacity Gallons: 25
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 02/06/2006
Register: True
Modified By: AESKALSK
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

Tank Number: 62DN
Tank Id: 215036
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
A00 - Tank Internal Protection - None
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
E00 - Piping Secondary Containment - None
C01 - Pipe Location - Aboveground
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None
G01 - Tank Secondary Containment - Diking (Aboveground)

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service

SUNY AT BUFFALO - NORTH CAMPUS (Continued) **U003107392**

Pipe Model:	Not reported
Install Date:	02/24/2006
Capacity Gallons:	50
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	BFGRABER
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	63
Tank Id:	174445
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

A03 - Tank Internal Protection - Fiberglass Liner (FRP)
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
E00 - Piping Secondary Containment - None
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
C03 - Pipe Location - Aboveground/Underground Combination
F04 - Pipe External Protection - Fiberglass
J02 - Dispenser - Suction Dispenser
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Location:	6
Tank Type:	Fiberglass Reinforced Plastic
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	09/01/2001
Capacity Gallons:	600
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	BFGRABER
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	63D
Tank Id:	174446
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
G10 - Tank Secondary Containment - Impervious Underlayment

SUNY AT BUFFALO - NORTH CAMPUS (Continued) **U003107392**

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
L09 - Piping Leak Detection - Exempt Suction Piping
J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	01/01/1985
Capacity Gallons:	10
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	02/06/2006
Register:	True
Modified By:	AESKALSK
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	63DN
Tank Id:	215037
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

C01 - Pipe Location - Aboveground
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
F01 - Pipe External Protection - Painted/Asphalt Coating
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
G01 - Tank Secondary Containment - Diking (Aboveground)
L00 - Piping Leak Detection - None

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	03/10/2006
Capacity Gallons:	50
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	BFGRABER
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

SUNY AT BUFFALO - NORTH CAMPUS (Continued) **U003107392**

Tank Number: 64D
Tank Id: 174447
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
G10 - Tank Secondary Containment - Impervious Underlayment
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 10/01/1990
Capacity Gallons: 50
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 12/29/2005
Register: True
Modified By: AESKALSK
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

Tank Number: 65
Tank Id: 174448
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

H99 - Tank Leak Detection - Other
I03 - Overfill - Automatic Shut-Off
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
B01 - Tank External Protection - Painted/Asphalt Coating
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
A01 - Tank Internal Protection - Epoxy Liner
C01 - Pipe Location - Aboveground
J02 - Dispenser - Suction Dispenser
G01 - Tank Secondary Containment - Diking (Aboveground)

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 09/01/2001
Capacity Gallons: 220

SUNY AT BUFFALO - NORTH CAMPUS (Continued) **U003107392**

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	BFGRABER
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	65D
Tank Id:	174449
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

E00 - Piping Secondary Containment - None
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
G10 - Tank Secondary Containment - Impervious Underlayment
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	02/01/1979
Capacity Gallons:	25
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	BFGRABER
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	66
Tank Id:	174450
Material Code:	0013
Common Name of Substance:	Lube Oil

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A01 - Tank Internal Protection - Epoxy Liner

SUNY AT BUFFALO - NORTH CAMPUS (Continued) **U003107392**

E00 - Piping Secondary Containment - None
D00 - Pipe Type - No Piping
G01 - Tank Secondary Containment - Diking (Aboveground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	09/01/2001
Capacity Gallons:	110
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	BFGRABER
Last Modified:	04/14/2017
Material Name:	lube oil

Tank Number:	67
Tank Id:	174451
Material Code:	0013
Common Name of Substance:	Lube Oil

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
A01 - Tank Internal Protection - Epoxy Liner
E00 - Piping Secondary Containment - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
D00 - Pipe Type - No Piping
G01 - Tank Secondary Containment - Diking (Aboveground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	09/01/2001
Capacity Gallons:	110
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	BFGRABER
Last Modified:	04/14/2017
Material Name:	lube oil

Tank Number:	68
Tank Id:	174452
Material Code:	0013
Common Name of Substance:	Lube Oil

SUNY AT BUFFALO - NORTH CAMPUS (Continued) **U003107392**

Equipment Records:
K00 - Spill Prevention - None
B01 - Tank External Protection - Painted/Asphalt Coating
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
A01 - Tank Internal Protection - Epoxy Liner
I04 - Overfill - Product Level Gauge (A/G)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
D00 - Pipe Type - No Piping
G01 - Tank Secondary Containment - Diking (Aboveground)

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	09/01/2001
Capacity Gallons:	500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	BFGRABER
Last Modified:	04/14/2017
Material Name:	lube oil

Tank Number:	69
Tank Id:	174453
Material Code:	0013
Common Name of Substance:	Lube Oil

Equipment Records:
I04 - Overfill - Product Level Gauge (A/G)
B01 - Tank External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A01 - Tank Internal Protection - Epoxy Liner
E00 - Piping Secondary Containment - None
D00 - Pipe Type - No Piping
G01 - Tank Secondary Containment - Diking (Aboveground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	09/01/2001
Capacity Gallons:	500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	BFGRABER
Last Modified:	04/14/2017

SUNY AT BUFFALO - NORTH CAMPUS (Continued) **U003107392**

Material Name: lube oil

Tank Number: 70
Tank Id: 174454
Material Code: 0013
Common Name of Substance: Lube Oil

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
A01 - Tank Internal Protection - Epoxy Liner
E00 - Piping Secondary Containment - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
D00 - Pipe Type - No Piping
G01 - Tank Secondary Containment - Diking (Aboveground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 09/01/2001
Capacity Gallons: 500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: BFGRABER
Last Modified: 04/14/2017
Material Name: lube oil

Tank Number: 71
Tank Id: 174455
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

I03 - Overfill - Automatic Shut-Off
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
A01 - Tank Internal Protection - Epoxy Liner
C01 - Pipe Location - Aboveground
G04 - Tank Secondary Containment - Double-Walled (Underground)
J02 - Dispenser - Suction Dispenser
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service

SUNY AT BUFFALO - NORTH CAMPUS (Continued) **U003107392**

Pipe Model: Not reported
Install Date: 09/01/2001
Capacity Gallons: 220
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: BFGRABER
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

Tank Number: 72D
Tank Id: 174457
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

L09 - Piping Leak Detection - Exempt Suction Piping
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
G10 - Tank Secondary Containment - Impervious Underlayment
J02 - Dispenser - Suction Dispenser
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 12/01/1975
Capacity Gallons: 25
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 03/27/2006
Register: True
Modified By: AESKALSK
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

Tank Number: 72DN
Tank Id: 215039
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None

SUNY AT BUFFALO - NORTH CAMPUS (Continued) **U003107392**

B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
C01 - Pipe Location - Aboveground
G01 - Tank Secondary Containment - Diking (Aboveground)
L00 - Piping Leak Detection - None

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	03/31/2006
Capacity Gallons:	50
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	BFGRABER
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	73
Tank Id:	179502
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None

Tank Location:	2
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	09/01/1993
Capacity Gallons:	150
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	AESKALSK
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

SUNY AT BUFFALO - NORTH CAMPUS (Continued) **U003107392**

Tank Number: 74
Tank Id: 179503
Material Code: 0008
Common Name of Substance: Diesel

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
K01 - Spill Prevention - Catch Basin
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
C00 - Pipe Location - No Piping
I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 06/16/1999
Capacity Gallons: 500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: TJWALKER
Last Modified: 04/14/2017
Material Name: diesel

Tank Number: 75
Tank Id: 179504
Material Code: 0009
Common Name of Substance: Gasoline

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
K01 - Spill Prevention - Catch Basin
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
C00 - Pipe Location - No Piping
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported

SUNY AT BUFFALO - NORTH CAMPUS (Continued) **U003107392**

Install Date: 06/16/1999
Capacity Gallons: 500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: TJWALKER
Last Modified: 04/14/2017
Material Name: gasoline

Tank Number: 76
Tank Id: 179497
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
D11 - Pipe Type - Flexible Piping
L00 - Piping Leak Detection - None

Tank Location: 2
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 03/04/2003
Capacity Gallons: 1850
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: AESKALSK
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

Tank Number: 77
Tank Id: 179499
Material Code: 0002
Common Name of Substance: #4 Fuel Oil (On-Site Consumption)

Equipment Records:

E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None

SUNY AT BUFFALO - NORTH CAMPUS (Continued) **U003107392**

B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
H02 - Tank Leak Detection - Interstitial - Manual Monitoring
C01 - Pipe Location - Aboveground
G01 - Tank Secondary Containment - Diking (Aboveground)
L00 - Piping Leak Detection - None

Tank Location:	2
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1995
Capacity Gallons:	1000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TJWALKER
Last Modified:	04/14/2017
Material Name:	waste oil/used oil

Tank Number:	77D
Tank Id:	179500
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
K01 - Spill Prevention - Catch Basin
C01 - Pipe Location - Aboveground
L00 - Piping Leak Detection - None

Tank Location:	2
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	02/11/1998
Capacity Gallons:	60
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	AESKALSK
Last Modified:	04/14/2017
Material Name:	waste oil/used oil

SUNY AT BUFFALO - NORTH CAMPUS (Continued) **U003107392**

Tank Number: 78
Tank Id: 215038
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
C01 - Pipe Location - Aboveground
G01 - Tank Secondary Containment - Diking (Aboveground)
L00 - Piping Leak Detection - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 02/17/2006
Capacity Gallons: 150
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: BFGRABER
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

Tank Number: 79
Tank Id: 215040
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

E00 - Piping Secondary Containment - None
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None

Tank Location: 2
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported

SUNY AT BUFFALO - NORTH CAMPUS (Continued) **U003107392**

Install Date:	06/06/2006
Capacity Gallons:	780
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	BFGRABER
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	80
Tank Id:	235876
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
K00 - Spill Prevention - None
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	06/20/2007
Capacity Gallons:	220
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	LDGOMEZ
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	81
Tank Id:	235877
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

D01 - Pipe Type - Steel/Carbon Steel/Iron

SUNY AT BUFFALO - NORTH CAMPUS (Continued) **U003107392**

G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
I02 - Overfill - High Level Alarm
E00 - Piping Secondary Containment - None
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
L00 - Piping Leak Detection - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 06/20/2007
Capacity Gallons: 220
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: LDGOMEZ
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

Tank Number: 82
Tank Id: 235878
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 06/20/2007
Capacity Gallons: 220
Tightness Test Method: NN
Date Test: Not reported

SUNY AT BUFFALO - NORTH CAMPUS (Continued) **U003107392**

Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	LDGOMEZ
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

178
West
< 1/8
0.062 mi.
329 ft.

LOUISE RING TANK
61 WREXHAM NORTH
TONAWANDA, NY

NY Spills **S104789602**
N/A

Actual:
587 ft.

Focus Map:
6

SPILLS:

Spill Number/Closed Date:	0075364 / 2000-12-20
Facility ID:	0075364
Facility Type:	ER
DER Facility ID:	66961
Site ID:	70586
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	1564
Spill Date:	1999-10-01
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	2000-09-13
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	2000-12-20
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-09-14
Spill Record Last Update:	2001-03-15
Spiller Name:	LOUISE RING
Spiller Company:	LOUISE RING
Spiller Address:	61 WREXHAM NORTH
Spiller Company:	001
Contact Name:	KARL SCHRODER SON IN LAW
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 09/13/00 RMC/DAN OLEARY, JOHN C., TOWN OF TONAWANDA/MRS RING/KARL SCHROEDER, SON IN LAW/SITE. NOCO INSTALLED NEW FUEL OIL FURNACE 10/99 DUE TO FUEL OIL ODORS IN HOME, ODORS CONTINUED, NOCO CHECKED 11/22/99 NOTED NO PROBLEM. MR. RING DIED IN 4/00. HEALTH CARE WORKERS NOTED STRONG FUEL IN HOME. NOCO WAS CALLED AGAIN FOUND NO PROBLEM, NOCO WAS CALLED ONCE MORE IN APRIL OR MAY, NOCO SUGGESTED THAT MRS RING PUT A FAN IN THE BASEMENT WINDOW. 8/00 NOCO AGAIN CHECKED UNIT, MRS RING COMPLAINED OF STRONG FUEL OIL ODORS IN HOME, NOCO NOTED NO PROBLEM. VERY STRONG FUEL ODORS IN BASEMENT, TANK IN BASEMENT EMPTY, WAS FILLED IN APRIL. NOTED LINE GOES FROM TANK UNDER CONCRETE FLOOR AND UP TO FURNACE. FUEL OIL NOTED IN FLOOR DRAIN. TOWN FOUND FUEL OIL IN LATERAL AND IN MAIN SEWER. VERY FEW HOMES SERVED BY THE SEWER SO THE FUEL OIL LINGERS. TOWN SHUT OFF VALVE ON TANK. REPAIR PERSON CALLED

LOUISE RING TANK (Continued) **S104789602**

TO INSTALL NEW LINE, 09/13/00 RMC/DAN O. AND JOHN C./MEETING. SINCE THIS HAS BEEN ONGOING FOR A YEAR, WE ARE GOING TO WAIT A WEEK OR TWO AND SEE IF DISCHARGE TO SEWERS STOPS. UPDATE 10/1 12/20/00 RMC/DAN OLEARY, TOWN OF TONAWANDA/MEETING. TOWN HAS CHECKED SEWERS SEVERAL TIMES, NO LONGER A PROBLEM ONCE THE LEAK WAS STOPPED, APPEARS THAT ALL OIL THAT WAS SPILLED WENT DIRECTLY INTO SANITARY SEWER, NO FURTHER ACTION REQUIRED. CLOSE OUT 01/05/01: RNL FILE REVIEW, RETURNED TO RMC FOR CLARIFICATION AND PUNCTUATION 03/14/01: RNL FILE REVIEW, RMC CLARIFIED AND/OR CORRECTED, OK TO FILE"

Remarks: "FUEL OIL IN SANITARY FROM FEED LINE LEAK "

All Materials:

Site ID:	70586
Operable Unit ID:	838223
Operable Unit:	01
Material ID:	538930
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AM179
ESE
< 1/8
0.062 mi.
329 ft.

FKQ CONFERENCE CENTER **FINDS** **1007809250**
2401 N FOREST RD **N/A**
AMHERST, NY 14226

Site 1 of 2 in cluster AM

Actual:
577 ft.

Focus Map:
5

FINDS:

Registry ID: 110019717895

Environmental Interest/Information System

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

180
South
< 1/8
0.066 mi.
349 ft.

ELMER SPAETH **NY Spills** **S102175584**
392 HOMECREST DRIVE **N/A**
AMHERST, NY

Actual:
596 ft.

Focus Map:
7

SPILLS:

Spill Number/Closed Date:	8602464 / 1987-02-20
Facility ID:	8602464
Facility Type:	ER
DER Facility ID:	142968
Site ID:	169910

ELMER SPAETH (Continued) **S102175584**

DEC Region:	9
Spill Cause:	Deliberate
Spill Class:	Not reported
SWIS:	1522
Spill Date:	1986-07-14
Investigator:	PRINGLE
Referred To:	Not reported
Reported to Dept:	1986-07-14
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Citizen
Cleanup Ceased:	1987-02-20
Cleanup Meets Std:	True
Last Inspection:	1987-02-20
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1986-07-17
Spill Record Last Update:	1988-08-11
Spiller Name:	Not reported
Spiller Company:	ELMER SPAETH
Spiller Address:	107 MACARTHUR DRIVE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MNP / / : SITE INSP. 7/15/86 BY MNP, SAMPLE TAKEN FROM WELL;SAMPLE TO E&E 7/15/86. / / : SITE INSP. 7/18/86 BY MNP, OWNER TO CLEANUP & SAMPLE;LETTER TO BE SENT. / / : SITE INSP. 7/18/86 BY MNP, OWNER TO CLEANUP & SAMPLE;SAMPLE (E&E) 07/15/86, RECEIVED _____. / / : LETTER 8/5/86, REPLY 8/18/86. / / : TELECON 8/12/86, SPILLER AGREED TO SAMPLE, WILL CALL WHEN RESULTS ARE RECEIVED. / / : SITE INSP. 8/21/86, WELL IS COVERED; HOLD FOR SAMPLING RESULTS. / / : RECEIVED SAMPLE RESULTS FROM BUFFALO TESTING LAB 9/12/86, INDICATING OIL & GREASE; RECEIVED SAMPLE RESULTS FROM E&E 9/16/86, 40% GASOLINE. / / : TELECON 9/17/86 W/SPAETH, WELL TO BE PUMPED OUT, PRODUCT CAN BE RECLAIMED, VERIFICATION OF REMOVAL & DISPOSAL REQUIRED. / / : LETTER 09/24/86 RECEIVED, VERIFICATION OK. / / : SAMPLE E&E 07/15/86, RECEIVED 08/23/86 - GASOLINE; SITE INSPECTION 11/06/86, SHEEN, PRODUCT REMOVED. / / : SAMPLE E&E 07/15/86, RECEIVED 08/23/86 - GASOLINE; SITE INSPECTION 11/06/86, SHEEN, PRODUCT REMOVED;NEEDS FINAL INSP. / / : SITE INSP. 11/06/86, SHEEN, PRODUCT REMOVED;SITE INSP. 2/20/87, SLIGHT SHEEN, DTW = 1.5';NO FURTHER CLEANUP NECESSARY. "
Remarks:	"DUMPING OIL IN ABANDONED WATER WELL"

All Materials:

Site ID:	169910
Operable Unit ID:	899178
Operable Unit:	01
Material ID:	478899
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00

ELMER SPAETH (Continued) **S102175584**

Oxygenate: Not reported

AN181 **ELLICOTT COMPLEX-FARGO** **NY Spills** **S102667840**
NNE **HALL AREA** **N/A**
< 1/8 **AMHERST, NY**
0.066 mi.
350 ft. **Site 1 of 4 in cluster AN**

Actual:
597 ft.

Focus Map:
4

SPILLS:

Spill Number/Closed Date:	9705442 / 2014-02-19
Facility ID:	9705442
Facility Type:	ER
DER Facility ID:	146836
Site ID:	174611
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	A3
SWIS:	1522
Spill Date:	1997-07-01
Investigator:	gmmay
Referred To:	Not reported
Reported to Dept:	1997-07-31
CID:	999
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	2001-08-27
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-08-05
Spill Record Last Update:	2014-02-19
Spiller Name:	GENE MONACELL, AL SWAVY
Spiller Company:	SUNY AT BUFFALO
Spiller Address:	MICHAEL HALL
Spiller Company:	999
Contact Name:	GORDIE LOVE
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SAC 08/04/97: SAC INSPECTS SITE WITH GENE MONACELL,UB-GENE DISCUSSED WHAT HAPPENED,APPEARS 20 YRS.AGO SPILL OCCURRED IN TRANSFORMER ROOM AND FLOOR WAS NOT SEALED,OIL GOT INTO HOLES WHERE GROUND WIRES RUN AND POSSIBLY THROUGH CRACKS IN THE FLOOR,SPILL WAS THEN CLEANED UP USING KEROSENE WHICH ALSO GOT UNDERNEATH FLOOR,ELECTRICIANS WERE PULLING WIRES THROUGH CONDUIT LAST MONTH, NOTICED THAT THE WIRES WERE WET WITH OIL,AT FIRST IT WAS BELIEVED IT WAS A DIESEL FUEL SPILL BECAUSE OF TANK UNDER LOADING DOCK,BUT ONE OF THE WORKERS NOTED THE ODORS WERE SIMILAR TO THE PCB OIL THAT WAS SPILLED SO SAMPLE WAS TAKEN,1ST RESULTS CAME BACK AT 6 % PCBs AT LAB WHICH WAS NOT CERTIFIED TO RUN PCBs,2ND TEST INDICATED 1.5 % PCBs,ELECTRICIAN REMOVED WIRE AND INSULATION BACK TO HIS HOME BECAUSE HE RECLAIMS THE WIRE,HE EXPRESSED HIS CONCERNS THAT HIS HOUSE MAY BE CONTAMINATED.RNL INSPECT SITE W/SAC AND GENE MONACELL,SOIL GAS SURVEY TO BE DONE TO HELP DETERMINE EXTENT,WILL CHECK UTILITY CORRIDORS ALSO.UB WILL ARRANGE TO BRING BACK CONTAMINATED MATERIAL,THEY WILL PRESENT WORKPLAN SOON. 08/05/97: SAC MET W/CAMERON O'CONNOR-NYSDOH AND

ELLICOTT COMPLEX-FARGO (Continued) **S102667840**

DISCUSSED SITUATION W/HIM. 08/05/97: SAC TELECON DEBBIE KASNIAK-NEIGHBOR OF ELECTRICIAN, SAC DISCUSSED SITE W/MS.KASNIAK AND TOLD HER HE WOULD CONTACT HEALTH DEPT.TO CONTACT HER TO ADDRESS ANY QUESTIONS SHE MAY HAVE. 08/06/97: SAC TELECON CAMERON O'CONNOR REGARDING MS.KASNIAK,SAC TELECON LEN BORCZYNSKI,UB AND TOLD HIM OF COMPLAINT BY MS.KASNIAK,MR.BORZYNSKI INDICATED HE WAS AWARE OF THE SITUATION AND THAY ARE IN THE PROCESS OF ARRANGING REMOVAL OF MATERIAL AS WELL AS CLEANING AND SAMPLING THE HOMES OF THE ELECTRICIAN AND HIS FATHER. 08/07/97: SAC TELECON LEN BORZYNSKI,UB WILL ISSUE PRESS RELEASE,HE WILL SEND COPY OF THE RELEASE,MEETING WILL BE HELD ON 8/11/97 TO DISCUSS SITE. 08/08/97: RECEIVED PRESS RELEASE. 08/11/97: SAC,CAMERON O'CONNOR-NYSDOH,LOU HENRY,LEN BORZYNSKI,GENE MONACELL-UB MEETING AT MICHAEL HALL-CHECK MEMO WRITTEN TO RNL. 08/21/97: SAC TELECON GENE MONACELL,LEVELS REMAIN AT ABOUT 40ug/100cm3 ON BLACKTOP AND SIDEWALKS,SPOKE W/PJB,PART 761 IS FEDERAL PROGRAM,STATE DOES NOT HAVE DELEGATION,CONTACTED DAVID GREENLAW,EPA TO UPDATE ON SITUATION,CALLED BACK GENE MONACELL, SINCE THEY ARE UNABLE TO CLEAN DOWN TO REQUIRED LEVELS,THEY WILL REMOVE BLACKTOP AND SIDEWALK. 08/29/97: SAC TELECON GENE MONACELL,ADDITIONAL ASPHALT AND SIDEWALK HAS BEEN REMOVED AND TESTING COMPLETE,ALL LEVELS ARE BELOW 10ug/100cm3,LEVELS WITHIN ROOMS W/CONDUITS COMING THROUGH THE FLOOR REMAINSLIGHTLY ABOVE THIS LEVEL,THEY HAVE CHANGED THE LOCKS AND HAVE SECURED ROOMS SO ONLY AUTHORIZED PERSONNEL MAY ENTER. UB IS PROVIDING GLOVES AND SHOE PROTECTION FOR ANYONE WHO ENTERS AREA. THEY WILL SUBMIT SURFACE CLEANUP REPORT NEXT WEEK AND HAVE HIRED URS-GREINER AS CONSULTANT FOR SUBFLOOR CLEANUP,THEY WILL VACUUM OUT THE CONDUITS TO SEE IF ANY RECOVERY TAKES PLACE HERE. 10/01/97: SAC TELECON LOU HENRY-UB,DO NOT HAVE REPORT YET,STILL ATTEMPTING TO OBTAIN IT FROM ADIRONDACK TESTING. 11/21/97: SAC TELECON GENE MONACELL,UB-THEY WILL BE SUBMITTING REPORT NEXT WEEK.ALSO WILL BE PUMPING OUT CONDUIT TO RECOVER ANY PRODUCT THAT MAY BE REMAINING. 12/05/97: HAVE NOT RECEIVED REPORT OR WORKPLAN,DRAFTED LETTER FOR RNL SIGNATURE INDICATING SEND IN REPORT BY 12/19/97 OR ELSE WILL BEGIN LEGAL ACTION. 12/17/97: RNL TELECON GENE MONACELL,SUNY-REPORT WILL BE OUT IN THE MAIL TOMORROW 12/22/97: RECEIVED CLEANUP REPORT. 03/12/99: RECEIVED MONTHLY PROGRESS REPORT FROM GENE MONACELL, SUNYAB - COVERING PERIOD FOR MONTH OF FEBRUARY, 674 GALS OF LIQUID WERE PUMPED INTO 55 GAL DRUMS, SAMPLES WERE TAKEN AND THE RESULTS INDICATE NON HAZ LEVELS OF PCBS PRESENT, WATER TO BE DISPOSED AS NON HAZ LIQUID, SORBENT SOCK PLACED INTO MW-3, MW-2 NEEDED TO BE PUMPED BECAUSE LIQUIDS RECOVERED FROM THE GROUNDWATER RECOVERY SYSTEM DID NOT COLLECT ANY PRODUCT DUE TO THE HIGH WATER LEVELS FROM THE AMOUNT OF PRECIPITATION, THEY WILL CONTINUE TO INSPECT THE SYSTEM DAILY TO ADJUST THE PUMP RATE. 04/21/99: RECEIVED MONTHLY PROGRESS REPORT FROM GENE MONACELL, SUNYAB, NO OBSERVED PRODUCT IN THE MONITORING WELLS & RESULTS INDICATE PCB LEVELS BELOW 10 ppb 05/28/99: RECEIVED MONTHLY PROGRESS REPORT FROM GENE MONACELL, SUNYAB - COVERING PERIOD OF 4/1/99 TO 4/30/99, 900 GAL OF WATER PUMPED FROM MW-2 INTO DRUMS AND TESTED FOR PCBs, RESULTS WERE LESS THAN 5 ppb OF PCBs AND WILL BE DISPOSED OF AS NON-HAZ WASTE, SORBENT SOCK IN MW-3 DOES NOT HAVE ANY PRODUCT SORBED ON TO IT SO IT WILL NOT BE REPLACED, REMOVAL OF TRANSFORMERS SCHEDULED FOR JUNE. 06/02/99: RNL RECEIVED FAXED COPY OF 5/25/99 MEETING MINUTES FROM GENE MONACELL ABOUT COORDINATION MEETING FOR PCB REMEDIAL CONTRACT & FERGUSON ELECTRIC CONTRACT. 06/08/99: RECEIVED MONTHLY PROGRESS REPORT FROM GENE MONACELL, SUNYAB - COVERING PERIOD OF 05/01/99 TO 05/31/99, 975 GALS OF WATER PUMPED FROM MW-2 & WILL BE TRANSFERRED TO HAZ WASTE STORAGE AREA, SAMPLE

ELLICOTT COMPLEX-FARGO (Continued) **S102667840**

TAKEN FOR ANALYSIS TO DETERMINE DISPOSAL STREAM, NO ADDITIONAL PRODUCT ABSORBED ON THE SOCK, & FINALIZED PLANS FOR THE REMOVAL OF THE EXISTING TRANSFORMERS AT THE SITE, WORK SCHEDULED TO BEGIN ON JUNE 14, 1999. 06/24/99: SAC TELECON GENE MONACELL, SUNYAB - THEY HAVE REMOVED FLOOR IN TRANSFORMER ROOM AND COMPLETED SOME OF THE EXCAVATION WORK, WILL MEET ON-SITE TOMORROW TO INSPECT AREA. 06/25/99: SAC MET WITH GENE MONACELL-SUNYAB, BOB NAJJAR & SCOTT MCCONE - URS, THEY HAVE REMOVED PART OF THE CONCRETE FLOORING AND NOTED STAINED SOIL WITH STANDING WATER, AN OIL SCUM WAS NOTED ON THE WATER, THEY ARE PROPOSING TO INSTALL A SUMP SYSTEM TO COLLECT AND DISPOSE OF THE WATER, THEY ARE RELUCTANT TO EXCAVATE MATERIAL BECAUSE IF THEY HAVE TO REMOVE THE FILL AND CONTINUE TO EXCAVATE THEN THEY BELIEVE THEY COULD COMPROMISE THE INTEGRITY OF THE BUILDING, THEY HAVE BEEN SAMPLING THE OUTSIDE WELLS WHICH DO NOT SHOW ANY MIGRATION HAS OCCURRED OUTSIDE OF THE BUILDING, THE REMOVED MATERIAL HAS BEEN PLACED INSIDE OF A LINED ROLLOFF. 06/25/99: SAC MET W/PJB REGARDING SITE AND PROPOSAL FOR A SYSTEM TO COLLECT AND DISPOSE OF THE WATER BASED ON STRUCTURAL CONCERNS, IT WAS AGREED THAT BEFORE THIS ALTERNATIVE IS ACCEPTED THAT A REPORT WRITTEN BY A P.E. CERTIFYING THAT EXCAVATION AND REMOVAL OF CONTAMINATED MATERIAL WILL COMPROMISE THE INTEGRITY OF THE BUILDING MUST BE SUBMITTED TO US. 06/28/99: SAC TELECON GENE MONACELL, UB - REGARDING 6/25 MEETING AND DISCUSSION OF SAC MEETING W/PJB, SAC INFORMED MR. MONACELL OF THE P.E. REPORT REQUIREMENT FOR A GW COLLECTION SYSTEM, MR. MONACELL STATED HE WOULD RATHER EXCAVATE MATERIAL IF POSSIBLE, IT WAS AGREED THAT SAC WOULD SEND LETTER TO MR. MONACELL WITH RECOMMENDATION TO EXCAVATE MATERIAL, THAT THE SPILL MUST BE CLEANED UP IN THE TRANSFORMER ROOM, THE GENERATOR ROOM, & THE SIDEWALK AREA OUTSIDE THESE 2 ROOMS. 07/15/99: RECEIVED MONTHLY PROGRESS FOR 6/1/99 - 6/30/99, SAMPLES FROM THE EXCAVATION ARE ABOVE 500 ppm OF PCBs 07/29/99: RNL, SAC HAD MEETING W/GENE MONACELL, MIKE DUPRE, LOU HENRY OF SUNYAB, & BOB NAJJAR - URS GREINER WOODWARD CLYDE, TO DISCUSS PROJECT, SUNYAB IS UNABLE TO DO THE WORK THIS SUMMER DUE TO TIME AND SPACE CRUNCH WITH TRANSFORMER CHANGEOUT PROJECT, NEED TO MAKE SURE ELECTRICITY IS BACK ON LINE BY THE TIME THE SCHOOL BEGINS FOR HEALTH AND SAFETY REASONS FOR THE STUDENTS, THEY REQUESTED DELAYING PROJECT UNTIL THE NEXT SUMMER, THEY WILL CONSIDER OPTIONS FOR THE WORK, THEY MAY PUT IN A SUMP AND PUMP AND TREAT WATER TO CONTAIN OIL IN THE MEANTIME, THEY WILL ALSO BE INCLUDING COSTS INTO NEXT YEAR'S CAPITAL BUDGET, THEY WILL ALSO SUBMIT A WORKPLAN AND TIMELINE FOR THE IMPLEMENTATION OF THE PLAN, THEY WILL KEEP DEC UPDATED AS TO THE PROGRESS OF THE WORK VIA MONTHLY REPORTS, RNL,SAC STRONGLY RECOMMENDED REMOVING THE FLOOR AND REMOVING THE CONTAMINATED MATERIAL UNDERNEATH THE FLOOR FOR DISPOSAL AND THAT WORK SHOULD BEGIN NEXT SUMMER, RNL,SAC AGREEABLE TO SUNYAB CLEANING UP ONE ROOM AT A TIME, DRAFTED LETTER BASED ON THESE ITEMS. 08/16/99: RECEIVED JULY MONTHLY REPORT, 900 GALLONS OF GROUNDWATER WERE PUMPED DURING JUNE AND NOW HAVE BEEN STORED, SUMP WILL BE INSTALLED AS TEMPORARY MEASURE UNTIL CLEANUP/REMOVAL WILL POSSIBLY BE DONE NEXT SUMMER, THEY WILL CUT ADDITIONAL SECTION OF FLOOR AND ROLLOFF HAS BEEN STAGED AT THE SITE, THEY WILL CONTINUE TO CHECK THE ABSORBENTS IN THE MONITORING WELLS AND DISPOSE WHERE NECESSARY. 09/13/99: RECEIVED AUGUST MONTHLY REPORT, 900 GALLONS OF GROUNDWATER WERE PUMPED INTO DRUMS FOR STORAGE AND DISPOSAL, SUMP WAS INSTALLED AND EXCAVATION WAS BACKFILLED AND CONCRETED OVER, TRANSFORMER ROOM DECONTAMINATED, 2 ROLLOFF BOXES TRANSPORTED FOR DISPOSAL TO CWM. 09/15/99: SAC TELECON SCOTT MCCONE, URS GREINER - MR. MCCONE SAID SUMP SYSTEM INSTALLATION HAS BEEN COMPLETED AND THEY HAVE COLLECTED

ELLICOTT COMPLEX-FARGO (Continued) **S102667840**

SOME PRODUCT FROM IT. 09/17/99: SAC TELECON GENE MONACELL, SUNYAB - SAC ASKED FOR CLARIFICATION OF LAST REPORT WHERE SYSTEM INSTALLATION WAS DONE IN RED JACKET HALL, MR. MONACELL SAID THAT FINAL COLLECTION AREA IS IN THE PORTER QUAD ACROSS FROM THE FARGO QUAD AND NOT THE RED JACKET QUAD AS WAS STATED IN THE REPORT. 05/02/00: SAC CALLED GENE MONACELL, MR. MONACELL WAS NOT IN OFFICE, LEFT MESSAGE FOR A CALLBACK. 05/02/00: SAC TELECON GENE MONACELL, THEY ARE HAVING A MEETING TODAY REGARDING REMEDIAL WORK, URS GREINER WAS AWARDED THE WORK AND SHOULD HAVE WORKPLAN IN-PLACE SOON, MR. MONACELL SAID HE WOULD CALL BACK W/INFO ON MEETING THIS WEEK. 06/01/00: SAC TELECON GENE MONACELL, SAC ASKED ABOUT THE STATUS OF THE CLEANUP, MR. MONACELL SAID THAT URS GREINER HAS BEEN RETAINED AND ARE STARTING TO PUT A PLAN TOGETHER BUT WORK MAY BE PUT OFF UNTIL THE DECEMBER BREAK, HE HAS NOT BEEN DIRECTLY INVOLVED W/THIS PROCESS AND WILL TALK TO LOU HENRY AND CALL SAC BACK. 07/20/00: SAC CALLED GENE MONACELL, MR. MONACELL WAS AWAY FROM HIS OFFICE, SAC LEFT MESSAGE FOR AN UPDATE ON THE STATUS OF THE WORK. 07/21/00: SAC TELECON GENE MONACELL, MR. MONACELL WILL ASK AGAIN TO SEE WHEN THE WORK WILL BEGIN, HE SAID HE BELIEVES THAT URS GREINER HAS BEEN RETAINED TO BID WORK OUT AND BELIEVES IT IS READY TO GO OUT FOR BID, BUT HE IS NO LONGER INVOLVED WITH THE PROJECT AND HAS NOT ATTENDED ANY MEETINGS REGARDING THE MATTER. 07/31/00: SAC TELECON GENE MONACELL, MR. MONACELL RECEIVED A MEMO FROM LOU HENRY INDICATING THE PROJECT HAS GONE OUT FOR BID AND THEY HOPE TO BEGIN WORK NEXT SUMMER. 12/18/00: SAC TELECON GENE MONACELL, URS-GREINER HAS WON THE BID ON THE PROJECT AS THE CONSULTANT AND THE BIDS HAVE GONE OUT FOR THE CONTRACTOR, THE WORK IS SCHEDULED TO BEGIN IN MAY OF 2001. 05/16/01: SAC TELECON GENE MONACELL, MR. MONACELL SAID THE WORK SHOULD BE STARTING VERY SOON, HE IS RETIRING IN A COUPLE OF WEEKS AND THE NEW PROJECT MANAGER FOR THE JOB IS AL SWAVY AND HE IS AT THE 829-3301 PHONE NUMBER. 05/21/01: SAC RECEIVED PHONE MESSAGE FROM AL SWAVY REGARDING THE SITE, WORK HAS BEGUN ON THE ELECTRICAL PORTION OF THE PROJECT. 05/30/01: SAC TELECON AL SWAVY, SAC REQUESTED WORKPLAN INCLUDING SCHEDULE OF THE WORK, MR. SWAVY SAID HE WILL TRY TO ARRANGE TO HAVE ONE SENT OUT. 06/18/01: SAC TELECON PAT FOOTE - INDUSTRIAL SITE SERVICES, THEY WILL BEGIN TO SAWCUT FLOOR IN TRANSFORMER ROOM EITHER TOMORROW OR THE NEXT DAY AND WILL BEGIN TO DO THE CLEANUP WORK, MR. FOOTE'S CELL PHONE NUMBER IS 583-2898 AND THE OFFICE PHONE NUMBER IS 775-1401. 06/22/01: SAC INSPECT SITE, MET WITH SCOTT MCCONE AND DAVE COFIELD, URS - TRANSFORMER ROOM FLOOR HAS BEEN BROKEN UP AND THEY HAVE BEGUN TO EXCAVATE THE MATERIAL BELOW THE FLOOR, THEY HAVE ALSO REMOVED THE CONCRETE BLOCK WALLS THAT SEPARATED THE THREE ROOMS, DUE TO THE PROXIMITY TO THE UTILITIES THEY WILL BE HAND DIGGING SOME OF THE SOIL, THEY WILL USE IMMUNO ASSAY TESTS TO FIELD SCREEN THE PCB LEVELS IN THE SOIL AFTER REMOVAL, THEY WILL THEN TAKE SAMPLES FOR LABORATORY ANALYSIS TO CONFIRM THE CLEANUP HAS BEEN COMPLETED, THE IMMUNO ASSAY TESTS WILL BE RUN AT THE CHEMICAL STORAGE BUILDING ON CAMPUS FOR QUICK TURNAROUND, WATER WAS FOUND IN A NEARBY ELECTRICAL VAULT WHICH WAS ANALYZED AND FOUND TO CONTAIN LOW LEVELS OF PCBs, THE WATER WAS CARBON TREATED AND STORED IN A BAKER TANK FOR ANALYSIS, THE TREATED WATER RESULTS WERE NON-DETECT AND THE WATER WAS PUMPED TO THE STORM SEWER, THE WORK IN THE 3 ROOMS SHOULD BE COMPLETED BY THE END OF NEXT WEEK AND THE REMOVAL TANK WILL BE COMPLETED AROUND THE END OF NEXT MONTH. 06/26/01: SAC INSPECT SITE, MET WITH PAT FOOTE OF ISS, THEY HAVE EXCAVATED IN TWO OF THE ROOMS DOWN TO WHAT APPEARS TO BE CLAY AND WERE WAITING FOR THE IMMUNO ASSAY FIELD TEST RESULTS TO SEE IF THEY NEEDED TO REMOVE THE ADDITIONAL MATERIAL FROM THESE AREAS, IF NO

ELLICOTT COMPLEX-FARGO (Continued) **S102667840**

FURTHER REMOVAL IS NECESSARY THEN THEY WILL REMOVE THE REMAINDER OF THE CONCRETE FLOOR AND REMOVE THE SOIL BENEATH THIS FLOORING, THEY WILL THEN PROCEED OUTSIDE OF THE 3 ROOMS IN THE PAVED AREA AT THE LOADING DOCK AND REMOVE THE CONTAMINATED MATERIAL FROM THIS AREA AND EVENTUALLY REMOVE THE CONCRETE AND TANK IN THE LOADING DOCK AREA. 06/26/01: SAC REVIEW FILE, NO WORK PLAN WAS SUBMITTED, SAC TELECON SCOTT MCCONE - URS, HE HAS MADE COPY OF THE WORKPLAN AND WILL GIVE SAC A COPY. 06/27/01: SAC INSPECT SITE, MET W/SCOTT MCCONE AND DAVE COFIELD, DIESEL HAS BEEN FOUND LEACHING INTO THE EXCAVATION FROM THE SOUTHEAST CORNER OF THE ROOM, THEY DUG A COUPLE OF TEST HOLES AND GROUNDWATER LEACHES UP WITH A SOME PRODUCT ON TOP OF IT, DIESEL HAS ACTED AS A SOLVENT WITH THE PCB OIL AND SO PCBs ARE BEING FOUND AT THIS LEVEL AS WELL, URS DOES NOT BELIEVE THEY CAN EXCAVATE ANY FURTHER THAN 7.5 TO 8 FEET WITHOUT COMPROMISING THE INTEGRITY OF THE BUILDING, THEY HAVE PROPOSED EXCAVATING AS FAR AS THEY CAN AND THEN SLOPE THE NATIVE SOIL BELOW THE FLOOR TOWARD THE LOADING DOCK AND INSTALL A SUMP TO COLLECT ANY ADDITIONAL PRODUCT THAT REMAINS IN THE SUBSURFACE, THEY WOULD POUR FLOWABLE FILL IN THE EXCAVATION AND INSTALL A CONCRETE FLOOR IN THE ROOM TO ENCAPSULATE AND PREVENT DIRECT CONTACT WITH THE PCBs, THERE WOULD ALSO BE SOME TYPE OF DEED RESTRICTION NOTIFICATION REGARDING THE SITE. 06/28/01: SAC RECEIVED LETTER WORKPLAN FOR THE PROPOSAL FROM BOB NAJJAR, SAC TELECON BOB NAJJAR, MR. NAJJAR STATES IN THE LETTER THAT IMMUNOASSAY TESTS INDICATE PRESENCE OF PCBs DOWN TO 7.5 FOOT DEPTH, MR. NAJJAR SAID THAT THIS INDICATES THAT THE LEVELS ARE ABOVE 5 ppm, THE SOIL SAMPLE RESULTS SHOULD BE RECEIVED AT LEAST WITHIN THE NEXT COUPLE OF DAYS, HOWEVER, SINCE ODORS REMAIN IN THIS AREA, HE BELIEVES THE RESULTS OF THE TEST COULD BE GREATER THAN 10 PPM, SAC NOTIFIED PJB OF THE PROJECT STATUS. 06/29/01: SAC INSPECT SITE, MET W/GORDIE LOVE - PROJECT MANAGER FROM SUNYAB AND DAVID COFIELD, THEY HAVE BROKEN THE CONCRETE ON THE LAST AREA OF THE ROOM THAT HAS NOT BEEN EXCAVATED, THE EXCAVATED AREA IS AT THE LIMIT OF ITS DEPTH WHICH IS BELIEVED TO BE ABOUT 8 FEET, LESS PRODUCT WAS OBSERVED IN THE CORNER THAN WAS THERE 2 DAYS AGO, THEY HAVE DONE ADDITIONAL SAMPLING IN THE AREA AND THE RESULTS SHOULD BE RECEIVED BY 7/3, SMALL AMOUNT OF WATER HAS COME INTO THE EXCAVATION BUT IT IS BELIEVED TO BE PERCHED GROUNDWATER, THEY WILL CONTINUE AS PLANNED AND EXCAVATE THE REMAINING SOIL BUT SLOPING THE GRADE SO COLLECTION WILL TAKE PLACE NEAR THE LOADING DOCK, THEY WILL ALSO BE REMOVING SOME OF THE SIDEWALK OUTSIDE OF THE ROOM AND POSSIBLY THE ROADWAY, SAC TELECON MATT FORCUCCI - NYSDOH, NOTIFYING HIM OF THE PRESENT STATUS. 07/03/01: RMC, SAC INSPECT SITE, MET WITH PAT FOOTE, THEY HAVE BEGUN TO EXCAVATE THE REMAINING AREA OF THE TRANSFORMER ROOM, THEY ANTICIPATE COMPLETING THE EXCAVATION THURSDAY 7/5 AND BEGIN BACKFILLING WITH STONE AND POURING THE FLOWABLE FILL ON FRIDAY 7/6. 07/03/01: RECEIVED WORKPLAN TO INSTALL AN 8 INCH WELL/SUMP, IT WILL BE DESIGNED SO A SUBMERSIBLE PUMP CAN BE INSTALLED WITH A DISCHARGE LINE AND ELECTRICAL CONDUIT LINE, BOTH LINES WILL BE CAPPED FOR THE TIME BEING, THE WELL WILL BE MONITORED TO SEE HOW MUCH PRODUCT WILL BE COLLECTED. 07/05/01: SAC TELECON CAMERON O'CONNOR - NOTIFYING HIM OF THE STATUS. 07/09/01: PJB, SAC INSPECT SITE, EXCAVATION INSIDE HAS BEEN COMPLETED, CRUSHED STONE AND GEOTEXTILE FABRIC HAVE BEEN PLACED INTO THE EXCAVATION, MET W/SCOTT MCCONE, REQUESTED MR. MCCONE TAKE TO SIDE SAMPLES FROM CLAY AREA BELOW THE CONCRETE CROSS BEAM/FOOTER ON THE SIDES WHERE THERE ARE TWO INNER WALLS, ONE WAS TAKEN NEAR THE CORNER WHERE THE FUEL WAS LEACHING IN, THEY WERE WAITING FOR THE FLOWABLE FILL TO BE DELIVERED SO THE AREA WILL BE FILLED BY THIS AFTERNOON, THE OTHER SIDE OF THE

ELLICOTT COMPLEX-FARGO (Continued) **S102667840**

INNER WALLS LEAD TO THE INTERIOR OF THE BUILDING WHICH WOULD MAKE ANY CLEANUP IN THESE AREAS VERY DIFFICULT, RECEIVED RESULTS FROM THE BOTTOM SAMPLING ON THE SIDE CLOSEST TO LOADING DOCK AND LOADING AREA, THE RESULTS WERE BELOW TAGM 4046 AND STARS GUIDANCE VALUES BUT THE PCB LEVELS ARE ELEVATED, PCB RESULTS ARE 1700 ppm FOR THE AREA NEAR THE LOADING DOCK AND FUEL OIL TANK AND 82 ppm FOR THE AREA NEAREST THE ROAD. 07/11/01: SAC TELECON SCOTT MCCONE, MR. MCCONE RECEIVED THE ADDITIONAL SAMPLES BOTTOM SAMPLES FARTHEST AWAY FROM THE LOADING DOCK AND THEY CAME BACK AT ABOUT 1000 ppm OF PCBs FOR THE SAMPLE NEAREST THE INNER WALL AND ABOUT 9 ppm OF PCBs NEAREST THE ROADWAY, THE VOLATILES AND SEMIVOLATILES WERE BELOW THE STARS GUIDANCE. 07/12/01: SAC INSPECT SITE W/CAMERON O'CONNOR, SHOWED MR. O'CONNOR AFFECTED AREA, SINCE THERE IS NO EXPOSURE PATHWAY MR. O'CONNOR IS NOT CONCERNED WITH THE SITE. 07/18/01: SAC TELECON PAT FOOTE, THEY HAVE SET THE RE-BAR IN THE TRANSFORMER ROOM AND WILL BE POURING THE CONCRETE FLOOR TOMORROW, THE LOADING DOCK WILL BE BROKEN UP AND THE TANK REMOVED THIS FRIDAY-7/20. 07/20/01: SAC INSPECT SITE AT ABOUT 1545, NO ONE ON SITE, TANK HAS BEEN REMOVED. 07/24/01: SAC INSPECT SITE, MET W/PAT FOOTE AND JOHN HENSON, THEY WERE IN THE PROCESS OF PUMPING OUT ELECTRICAL MANHOLE UPSTREAM FROM THE AREA TO PREVENT FURTHER WATER FROM ENTERING THE AFFECTED MANHOLE, THEY ARE CONTINUING TO EXCAVATE THE AREA IN THE LOADING DOCK, PER JOHN HENSON THERE WERE HOLES IN THE BOTTOM OF THE TANK, THERE ARE UTILITY LINES THAT RUN THROUGH THE AREA SO THEY WILL HAVE TO EXCAVATE CERTAIN AREAS BY HAND. 08/01/01: SAC INSPECT SITE, MET W/SCOTT MCCONE, THEY HAVE CONTINUED THE EXCAVATION IN THE ASPHALT LOADING AREA AND THE WORST AREA IS IN THE CORNER NEXT TO THE LOADING DOCK AND THE TRANSFORMER ROOM, THEY HAVE EXCAVATED ACROSS ALMOST THE LENGTH OF THE LOADING RACK SLOPED TO THE END WHERE THE SUMP WILL BE INSTALLED, RECEIVED ADDITIONAL SAMPLE RESULTS, THE WALL SAMPLES INSIDE OF THE TRANSFORMER ROOM WERE 13.6 ppm OF PCBs IN THE CORNER OF THE ROOM NEAREST THE LOADING DOCK AND 0.07 ppm OF PCBs AT THE WALL FARTHEST AWAY FROM THE LOADING DOCK, ALL OTHER PARAMETERS WERE BELOW TAGM 4046 GUIDANCE VALUES. 08/02/01: SAC TELECON SCOTT MCCONE, DISCUSSED 2ND SET OF RESULTS THAT WERE GIVEN TO SAC AT INSPECTION YESTERDAY, THESE WERE THE RESULTS FROM THE FILTERED WATER OUT OF THE ELECTRIC MANHOLE, THE WATER WAS FILTERED AND SAMPLED UNTIL THE RESULTS CAME BACK NON-DETECT. 08/08/01: SAC INSPECT SITE W/SCOTT MCCONE, EXCAVATION WAS COMPLETED AND LOADING AREA HAS BEEN BACKFILLED WITH FLOWABLE FILL, SUMP/WELL HAS BEEN SET, SIDEWALK HAS BEEN DAMAGED AND WILL BE REPLACED, RECEIVED COPY OF THE SAMPLE RESULTS FROM THE UST LOCATION AND THE LOADING DOCK AREA, FOR THE UST LOCATION THE RESULTS WERE BELOW STARS GUIDANCE VALUES AND TAGM 4046 GUIDANCE VALUES FOR THE TWO BOTTOM SAMPLES, THE PCB RESULTS WERE LESS THAN 1 ppm FOR BOTH SAMPLES, THE SAMPLES IN THE LOADING DOCK AREA ARE BELOW STARS GUIDANCE AND TAGM 4046 GUIDANCE FOR THE SW & NW QUADRANT SAMPLES AND BELOW 1 ppm PCBs, THE SE QUADRANT HAD LEVELS ABOVE STARS BUT NOT ABOVE TAGM 4046 VALUES, PCB RESULTS WERE AT 1.3 ppm, THE NE QUADRANT SAMPLE WAS NOT IN THE AREA WHERE THERE WAS STAINED SOIL PER MR. MCCONE, RESULTS WERE ABOVE STARS GUIDANCE BUT NOT ABOVE TAGM 4046 VALUES, THE PCB RESULTS WERE AT 3.0 ppm. 08/13/01: SAC TELECON SCOTT MCCONE, THEY ARE SCHEDULED TO REMOVE THE SIDEWALK AND THE CONTAMINATED SOIL UNDERNEATH THE SIDEWALK THIS WEEK, ANY REMOVAL OF THE ROADWAY WOULD TAKE PLACE EITHER DURING THANKSGIVING OR CHRISTMAS BREAKS. 08/17/01: SAC INSPECT SITE, MET W/PAT FOOTE, NO ADDITIONAL EXCAVATION HAS TAKEN PLACE, THEY ARE FINISHING UP THE TRANSFORMER ROOM AND WILL BE FINISHING THE LOADING AREA, ANY EXCAVATIO0N COULD TAKE PLACE IN THE MIDDLE OF NEXT WEEK. 08/27/01: SAC INSPECT SITE,

ELLICOTT COMPLEX-FARGO (Continued) **S102667840**

MET W/DAVE COFIELD AND PAT FOOTE, NEW SIDEWALK WAS POURED AND LOADING AREA WAS FILLED BACK IN WITH NEW ASPHALT TO BE POURED TODAY, PER MR. COFIELD THE EXCAVATION WAS 7 TO 8 FT DEEP IN THE SIDEWALK AREA, THE ELECTRICAL MANHOLE STILL IS GETTING LOW LEVELS TO ENTER INTO IT, THEY WILL CONTINUE TO MONITOR IT UNTIL THERE ARE NO DETECTIBLE LEVELS AND THEY EXCAVATE OUT INTO THE ROADWAY TO COMPLETE THE EXCAVATION WORK. 01/23/08: SAC R3EVIEW FILE. NO FINAL REPORT SUBMITTED FOR WORK COMPLETED. SAC TELECON AL SWAVY REQUESTING COPY. MR. SWAVY WILL CHECK FILES TO SEE IF THEY HAVE A COPY. 02/08/08: SAC TELECON AL SWAVY EARLIER IN THE WEEK. MR. SWASVY CONTACTED URS AND WAS ABLE TO GET WHAT APPEARS TO BE A FINAL REPORT FOR THE WORK. HE WILL SEND IN THE COPY. 02/15/11: SAC TELECON DAVE VASBINDER - SUNYAB. AL SWAVY HAS RETIRED. DISCUSSED THE REPORT THAT MR. SWAVY SENT TO SAC. REPORT WAS ONLY TEXT AND DID NOT HAVE THE DISPOSAL RECEIPTS OR THE ANALYTICAL RESULTS THAT WERE SUPPOSED TO BE IN THE APPENDICES. SAC TO SEND A COPY TO HIM. HE WILL MOST LIKELY DISCUSS W/BRIAN FOTI OF HIS DEPT. AND MR. FOTI WILL FOLLOW UP W/SAC. SAC SENT COPY OF REPORT TO MR. VASBINDER. 03/02/11: SAC TELECON BRIAN FOTI. MR. FOTI SAID HE DOES HAVE A FINAL REPORT REGARDING THE WORK THAT WAS COMPLETED. HE WILL CHECK WITH HIS SUPERVISOR REGARDING WHETHER TO SEND ONE OF THE COPIES THE UNIVERSITY HAS OR TO COPY IT AND SEND IT TO SAC. MR. FOTI SAID THAT HE ANTICIPATES SENDING OUT A COPY OF THE REPORT THIS WEEK. 03/04/11: RECEIVED REMEDIATION REPORT. 07/28/11: GPS REVEIWED FILE WITH SAC. AGREED TO REQUEST UB TO PERFORM ADDITIONAL ROUND OF GW ANALYSIS FROM ALL EXISTING MWS. CONDUCT SEPERATE ANALYSIS ON GW AND ALL SEPERATE PHASE MATERIAL, IF FOUND, FOR PCBS. LOOK AT SUMP INSTALLED IN LOADING DOCK TO DETERMINE IF IT IS COLLECTING PRODUCT AS DESIGNED BACK IN 2000. HAD FOLLOW-UP DISCUSSION WITH JIM HARRINGTON ON TSCA ISSUES PERTAINING TO SPILL. AGREE TO PROVIDE NEW DATA TO JIM SO HE CAN DISCUSS CONCEPTUAL PLAN WITH EPA. AGREED THERE IS PROBABLY NO CURRENT ROUTE OF EXPOSURE LEFT ALTHOUGH SOIL & GW STD EXCEEDED FOR PCBS IN 2000 DATA AND DON'T EXPECT CONDITIONS TO CHANGE WITH NEW DATA. FINAL CONCEPTUAL RA TO REQUIRE NFA AND DEED RESTRICTION. 07/29/11: SAC INSPECT SITE. MONITORING WELLS MW-2, MW-3, MW-4, AND SUMP STILL IN PLACE. 08/12/11: SAC CALLED BRIAN FOTI. LEFT MESSAGE FOR A CALL BACK. 09/01/11: SAC TELECON BRIAN FOTI. DISCUSSED HAVING MWS AND SUMP: GAUGED, EVACUATED, AND SAMPLED. MR. FOTI SAID THAT THEY USE FRONTIER AS THEIR CONSULTANT/CONTRACTOR AND THEY ARE SCHEDULED TO BE ON-SITE THE WEEK OF 9/26. HE WILL INCLUDE THIS WORK AS PART OF THEIR VISIT. SAC DRAFTED LETTER REQUESTING THE WORK BE COMPLETED. 01/26/12: MEETING WITH UB TO DISCUSS THIS SPILL AND DECIDE HOW TO MOVE FORWARD. UB PERSONNEL INDICATE THAT THEY PLAN ON REPLACING ALL UTILITIES UNDER THE ROADWAY IN 2013, AND RECOGNIZE THAT THE PRESENCE OF PCB CONTAMINATED SOIL IS AN ISSUE. GPS SUGGESTS THAT ADDITIONAL INVESTIGATION COULD BE COMPLETED THIS YEAR TO DETERMINE THE EXTENT OF THE CONTAMINATION, WITH REMEDIAL WORK COMPLETED WHEN THE UTILITIES ARE REPLACED. UB LIKES THIS IDEA AND BELIEVES THAT THE INVESTIGATION CAN BE COMPLETED IN TIME TO USE THE INFORMATION IN THE ROADWAY/UTILITIES DESIGN PHASE. THIS SPILL IS OFFICIALLY TRANSFERRED TO GMM DUE TO HIS EXPERIENCE WITH PCB OIL MIGRATION THROUGH SILTY CLAYS. 02/29/12: GPS MEETS WITH UB PERSONNEL AND UB'S CONSULTANT AT THE SITE. GMM UNAVAILABLE FOR THIS MEETING. WORK PLAN SUBMITTAL SCHEDULED FOR THE END OF MARCH 2012. 05/02/12: GMM E-MAIL TO BF AT UB INQUIRING ABOUT WORK PLAN SUBMITTAL. SUBMITTAL IS NOW 1 MONTH LATE, DELAYING THE SCHEDULED MAY 20, 2012 FIELD WORK START DATE. 06/07/12: UB SUBMITTS INVESTIGATION WORK PLAN VIA E-MAIL. 07/02/12: COMMENTS ON INVESTIGATION WORK PLAN SENT TO UB. 07/26/12: UB SUBMITTS REVISED

ELLICOTT COMPLEX-FARGO (Continued) **S102667840**

INVESTIGATION WORK PLAN VIA E-MAIL. 07/31/12: GMM REVIEWS REVISED INVESTIGATION WORK PLAN. NYSDEC COMMENTS FROM JULY 2, 2012 HAVE BEEN ADDRESSED, AND ONLY A FEW ADDITIONAL COMMENTS REMAIN. GMM E-MAILS UB WITH GENERAL ACCEPTANCE OF THE WORK PLAN, AND REQUESTS A COMPLETE COPY OF THE WORK PLAN IN PDF FORMAT THAT ADDRESSES THE ADDITIONAL COMMENTS. GMM ALSO LETS UB KNOW THAT FIELD WORK CAN BE SCHEDULED. 12/05/12: UB SUBMITS REPORT ENTITLED SUB-SURFACE INVESTIGATION REPORT, ELLICOTT COMPLEX/FARGO COMPLEX THAT DETAILS THE RESULTS OF THE INVESTIGATION. THE HORIZONTAL EXTENT OF CONTAMINATION WAS DELINEATED BUT NOT THE VERTICAL EXTENT. 12/10/12: GPS & GMM MEET WITH UB PERSONNEL AND THEIR CONSULTANT TO DISCUSS THE FINDINGS OF THE SUB-SURFACE INVESTIGATION REPORT AND THE NEED FOR FURTHER VERTICAL DELINEATION OF THE PCB CONTAMINATION. 02/14/13: UB SUBMITS REPORT ENTITLED MILLARD FILLMORE ACADEMIC CENTER TUNNEL PCB EXCAVATION REPORT THAT DETAILS THE RESULTS OF THE VERTICAL DELINEATION INVESTIGATION THE GENERAL PROCEDURE FOR COMPLETING SITE REMEDIATION. 04/22/13: APPROVAL OF THE MILLARD FILLMORE ACADEMIC CENTER TUNNEL PCB EXCAVATION REPORT SENT TO UB WITH A REQUEST TO SUBMIT ELECTRONIC COPY OF THE REPORT. 04/24/13: ELECTRONIC COPY OF MILLARD FILLMORE ACADEMIC CENTER TUNNEL PCB EXCAVATION REPORT RECEIVED FROM UB VIA E-MAIL. 06/17/13: EXCAVATION OF PCB CONTAMINATED SOIL BEGINS, AND IS COMPLETED JUNE 28, 2013. THE PRIMARY EXCAVATION MEASURED APPROXIMATELY 60 FEET BY 32 FEET, AND TERMINATED AT A DEPTH OF APPROXIMATELY 10 FEET BELOW GROUND SURFACE. APPROXIMATELY 711 SQUARE YARDS OF SOIL WAS EXCAVATED AND DISPOSED OF OFF-SITE. THE SECONDARY EXCAVATION WAS COMPLETED ON JUNE 20, 2013, AND WAS LOCATED WITHIN THE PRIMARY EXCAVATION. THIS EXCAVATION WAS TERMINATED AT A DEPTH OF APPROXIMATELY 16 FEET BELOW GROUND SURFACE. 12/05/13: UB SUBMITS REPORT ENTITLED PCB SPILL CLOSURE REPORT THAT PRESENTS THE RESULTS OF THE CONFIRMATORY SAMPLES COLLECTED FOLLOWING EXCAVATION ACTIVITIES. ALL CONFIRMATORY SAMPLES MET THE CP-51 SOIL GUIDANCE VALUE FOR PCBS OF 10 PPM. 01/24/14: COMMENTS ON THE PCB SPILL CLOSURE REPORT SENT TO UB VIA E-MAIL. 01/30/14: UB SUBMITS REVISED PCB SPILL CLOSURE REPORT . 02/19/14: APPROVAL OF THE PCB SPILL CLOSURE REPORT SENT TO UB. DUE TO THE PRESENCE OF PCB CONCENTRATIONS ABOVE 10 PPM AT THE FLOOR OF THE EXCAVATIONS COMPLETED IN 2001, THIS LETTER INDICATED THAT THE SPILL WOULD BE CLOSED BUT GIVEN AN INACTIVE STATUS."

Remarks: "HISTORIC SPILL - 20 YEARS AGO. ELECTRICIAN PULLING WIRES THROUGH CONDUIT, HAD OIL ON WIRES."

All Materials:

Site ID:	174611
Operable Unit ID:	1048851
Operable Unit:	01
Material ID:	334658
Material Code:	0012A
Material Name:	kerosene
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Site ID:	174611
Operable Unit ID:	1048851
Operable Unit:	01
Material ID:	334659

ELLICOTT COMPLEX-FARGO (Continued) **S102667840**

Material Code:	0017A
Material Name:	PCB oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AO182 **BASIL FORD** **NY LTANKS** **U003318278**
South **3484 MAIN STREET** **NY AST** **N/A**
< 1/8 **BUFFALO, NY**
0.066 mi.
350 ft. **Site 1 of 3 in cluster AO**

Actual:
654 ft.

Focus Map:
8

LTANKS:

Spill Number/Closed Date:	9501367 / 1995-11-17
Facility ID:	9501367
Site ID:	327438
Spill Date:	1995-04-06
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	1995-11-17
SWIS:	1502
Investigator:	FXGALLEG
Referred To:	Not reported
Reported to Dept:	1995-05-01
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	DEC
Last Inspection:	1995-10-05
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-05-03
Spill Record Last Update:	1999-10-08
Spiller Name:	Not reported
Spiller Company:	BASIL FORD INC.
Spiller Address:	3484 MAIN STREET
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	9
DER Facility ID:	263574
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was FG 05/03/95: SITE VISIT 5/3/95. 5 YDS CONTAM SOIL ON SITE WAITING FOR DISPOSAL. TOLD BASIL MORE SOIL MUST BE REMOVED DUE TO EXCEEDANCES. 500GAL WASTE OIL UST BEING REMOVED. OIL TO BE DISPOSED. 05/05/95: LTR SENT REQUESTING SOIL REMOVAL & RESAMPLING. WORK PLAN DUE BY 5/19/95. 06/08/95: ANALYSIS FROM EXCAV RECD. RESULTS ARE 8270 DIRECT. RESULTS ONLY SLIGHTLY EXCEED SOIL GUIDANCE STARS VALUES. SOIL DISPOSAL MUST TAKE PLACE. 08/18/95: SUBMITTED MANIFEST FOR DISPOSAL OF OIL FROM WASTE OIL TANK THAT WAS UNDERGROUND IN THE BLDG. ENVRL SVCE GRP EXCAVATED ADDL SOIL & RESAMPLED UST EXCAV OUTSIDE. WILL SUBMIT

BASIL FORD (Continued) **U003318278**

ANALYTICAL. 09/20/95: EXCAVA ANALYSIS FOR 8270 BELOW STARS. CONTAM SOIL TO BE DISPOSED 9/21/95. DISPOSAL RECPTS TO BE SUBMITTED. 10/5/95 SITE VISIT. SOIL GONE FROM SITE. 11/17/95 SOIL DISPOSAL RECPTS RECEIVED. SITE CAN BE CLOSED."

Remarks: "REMOVED 3 TANKS 4/6/95. ANALYTICAL REPORT OF SOILS INDICATES EXCEEDANCES OF STARS MEMO GUIDANCE."

All Materials:
Site ID: 327438
Operable Unit ID: 1015774
Operable Unit: 01
Material ID: 369974
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

AST:
Region: STATE
DEC Region: 9
Site Status: Unregulated/Closed
Facility Id: 9-444227
Program Type: PBS
UTM X: 188453.36582
UTM Y: 4763183.61896
Expiration Date: N/A
Site Type: Other Wholesale/Retail Sales

Affiliation Records:
Site Id: 54397
Affiliation Type: Facility Owner
Company Name: JOSEPH F. & SHIRLEY J. BASIL
Contact Type: Not reported
Contact Name: Not reported
Address1: 600 KLEIN RD.
Address2: Not reported
City: AMHERST
State: NY
Zip Code: 14221
Country Code: 001
Phone: (716) 688-7057
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 54397
Affiliation Type: Mail Contact
Company Name: BASIL FORD INC
Contact Type: Not reported
Contact Name: CHARLES J BASIL
Address1: 3484 MAIN STREET
Address2: Not reported

BASIL FORD (Continued) **U003318278**

City:	BUFFALO
State:	NY
Zip Code:	14221
Country Code:	001
Phone:	(716) 833-8140
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	54397
Affiliation Type:	Facility Operator
Company Name:	BASIL FORD INC.
Contact Type:	Not reported
Contact Name:	CHARLES J BASIL
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(716) 833-8140
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	54397
Affiliation Type:	Emergency Contact
Company Name:	JOSEPH F. & SHIRLEY J. BASIL
Contact Type:	Not reported
Contact Name:	CHARLES BASIL
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(716) 688-2699
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	6
Tank Id:	170881
Material Code:	0013
Common Name of Substance:	Lube Oil

Equipment Records:

J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

BASIL FORD (Continued) **U003318278**

I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
L09 - Piping Leak Detection - Exempt Suction Piping
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
G01 - Tank Secondary Containment - Diking (Aboveground)

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	02/01/1992
Capacity Gallons:	350
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	lube oil

AO183 **BASIL FORD INC.** **NY UST** **U004081614**
South **3484 MAIN STREET** **N/A**
< 1/8 **BUFFALO, NY 14214**
0.066 mi.
350 ft. **Site 2 of 3 in cluster AO**

Actual:
654 ft.

Focus Map:
8

UST:

Id/Status:	9-444227 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	9
Expiration Date:	N/A
UTM X:	188453.36582
UTM Y:	4763183.61896
Site Type:	Other Wholesale/Retail Sales

Affiliation Records:

Site Id:	54397
Affiliation Type:	Facility Owner
Company Name:	JOSEPH F. & SHIRLEY J. BASIL
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	600 KLEIN RD.
Address2:	Not reported
City:	AMHERST
State:	NY
Zip Code:	14221
Country Code:	001
Phone:	(716) 688-7057
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	54397
Affiliation Type:	Mail Contact
Company Name:	BASIL FORD INC

BASIL FORD INC. (Continued) **U004081614**

Contact Type:	Not reported
Contact Name:	CHARLES J BASIL
Address1:	3484 MAIN STREET
Address2:	Not reported
City:	BUFFALO
State:	NY
Zip Code:	14221
Country Code:	001
Phone:	(716) 833-8140
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	54397
Affiliation Type:	Facility Operator
Company Name:	BASIL FORD INC.
Contact Type:	Not reported
Contact Name:	CHARLES J BASIL
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(716) 833-8140
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	54397
Affiliation Type:	Emergency Contact
Company Name:	JOSEPH F. & SHIRLEY J. BASIL
Contact Type:	Not reported
Contact Name:	CHARLES BASIL
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(716) 688-2699
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	2
Tank ID:	167821
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	6000
Install Date:	01/01/1968
Date Tank Closed:	04/01/1995

BASIL FORD INC. (Continued) **U004081614**

Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0003
Common Name of Substance: #6 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None

Tank Number: 3
Tank ID: 167822
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 1000
Install Date: 01/01/1968
Date Tank Closed: 04/01/1995
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0000
Common Name of Substance: Empty

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None

Tank Number: 4

BASIL FORD INC. (Continued) **U004081614**

Tank ID:	167823
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	1000
Install Date:	01/01/1968
Date Tank Closed:	04/01/1995
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0000
Common Name of Substance:	Empty
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None

Tank Number:	5
Tank ID:	167824
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	1000
Install Date:	01/01/1968
Date Tank Closed:	04/01/1995
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0000
Common Name of Substance:	Empty
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B00 - Tank External Protection - None

BASIL FORD INC. (Continued) **U004081614**

I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None

AO184 **BASIL FORD** **RCRA-CESQG** **1000162004**
South **3484 MAIN ST** **FINDS** **NYD118786128**
< 1/8 **BUFFALO, NY 14214** **ECHO**
0.066 mi. **NY MANIFEST**
350 ft. **Site 3 of 3 in cluster AO**

Actual:
654 ft.

Focus Map:
8

RCRA-CESQG:

Date form received by agency:	01/01/2007
Facility name:	C BASIL FORD INC
Facility address:	3484 MAIN ST BUFFALO, NY 14214
EPA ID:	NYD118786128
Mailing address:	MAIN ST BUFFALO, NY 14214
Contact:	Not reported
Contact address:	MAIN ST BUFFALO, NY 14214
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	JOSEPH F BASIL
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	JOSEPH F BASIL
Owner/operator address:	NOT REQUIRED

BASIL FORD (Continued) **1000162004**

NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: C BASIL FORD INC
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 06/01/1996
Site name: C BASIL FORD INC
Classification: Large Quantity Generator

Date form received by agency: 10/29/1993
Site name: C BASIL FORD INC
Classification: Small Quantity Generator

Date form received by agency: 09/22/1986
Site name: C BASIL FORD INC
Classification: Large Quantity Generator

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLOROETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE, AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: U002

BASIL FORD (Continued) **1000162004**

. Waste name: ACETONE (I)

. Waste code: U239
. Waste name: BENZENE, DIMETHYL- (I,T)

Violation Status: No violations found

FINDS:

Registry ID: 110000875198

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000162004
Registry ID: 110000875198
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110000875198

NY MANIFEST:
Country: USA
EPA ID: NYD118786128
Facility Status: Not reported
Location Address 1: 3484 MAIN STREET
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BUFFALO
Location State: NY
Location Zip: 14225
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD118786128
Mailing Name: BASIL FORD INCORPOARTED
Mailing Contact: CHARLES BASIL
Mailing Address 1: 3484 MAIN STREET
Mailing Address 2: Not reported
Mailing City: BUFFALO
Mailing State: NY
Mailing Zip: 14225
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 7168338140

BASIL FORD (Continued) **1000162004**

NY MANIFEST:

Document ID:	NYG2662335
Manifest Status:	Not reported
seq:	01
Year:	2003
Trans1 State ID:	P207004IL
Trans2 State ID:	Not reported
Generator Ship Date:	03/04/2003
Trans1 Recv Date:	03/04/2003
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/11/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD118786128
Trans1 EPA ID:	NJD080631369
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD049836679
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F003 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AM185 **NY COOLING TOWERS** **S122987378**
ESE **2402 NORTH FOREST ROAD** **N/A**
< 1/8 **GETZVILLE, NY 14068**
0.067 mi.
352 ft. **Site 2 of 2 in cluster AM**

Actual:
577 ft.

Focus Map:
5

COOLING TOWERS:

Equipment Unique ID:	12736
Equipment Borough:	2402
Intended Use:	Air Conditioning

(Continued) **S122987378**

Manufacturer:	Evapco
Model:	LSWE43518
Cooling Capacity:	Not reported
Cooling Capacity Unit:	Not reported
Commissioned Date:	06/18/2018
Inspection Date:	09/10/2018
Date of Bacteriological Collection:	09/26/2018
Date of Legionella Collection:	09/10/2018
Last Legionella Result > 1,000 CFU/mL:	no
Latitude:	43.009853428
Longitude:	-78.77727683

AP186 **STATE UNIVERSTIY CONSTRUCTION FUND** **RCRA NonGen / NLR** **1000397720**
NW **SUNY AT BUFFALO 3435 MAIN ST** **NYD980780258**
< 1/8 **BUFFALO, NY 14214**
0.067 mi.
356 ft. **Site 1 of 12 in cluster AP**

Actual:
658 ft.

Focus Map:
8

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	STATE UNIVERSTIY CONSTRUCTION FUND
Facility address:	SUNY AT BUFFALO 3435 MAIN ST BUFFALO, NY 14214
EPA ID:	NYD980780258
Mailing address:	PO BOX 176 WILLIAMSVILLE, NY 14221
Contact:	FRED SMEADER
Contact address:	PO BOX 176 WILLIAMSVILLE, NY 14221
Contact country:	US
Contact telephone:	716-636-3083
Contact email:	Not reported
EPA Region:	02
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	Not reported
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	Not reported
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported

STATE UNIVERSTIY CONSTRUCTION FUND (Continued) **1000397720**

Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: STATE UNIVERSTIY CONSTRUCTION FUND
Classification: Not a generator, verified

Date form received by agency: 11/07/1984
Site name: STATE UNIVERSTIY CONSTRUCTION FUND
Classification: Not a generator, verified

. Waste code: X002
. Waste name: POLYCHLORINATED BIPHENOLS (PCBs)

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Generators - Manifest
Date violation determined: 05/02/1985
Date achieved compliance: 08/15/1985
Violation lead agency: State
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 05/02/1985
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 05/02/1985
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Generators - Manifest

STATE UNIVERSTIY CONSTRUCTION FUND (Continued) **1000397720**

Date achieved compliance: 08/15/1985
Evaluation lead agency: State

AN187 **SUNY AT BUFFALO** **NY LTANKS** **S102177169**
NNE **MILLERSPORT HIGHWAY 265** **NY Spills** **N/A**
< 1/8 **AMHERST, NY**
0.069 mi.
365 ft. **Site 2 of 4 in cluster AN**

Actual:
596 ft.

Focus Map:
4

LTANKS:

Spill Number/Closed Date:	9706838 / 2001-07-24
Facility ID:	9706838
Site ID:	257969
Spill Date:	1997-09-05
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	1522
Investigator:	SACALAND
Referred To:	Not reported
Reported to Dept:	1997-09-08
CID:	999
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	2001-07-24
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1997-09-09
Spill Record Last Update:	2001-07-24
Spiller Name:	GORDON A. LOVE
Spiller Company:	SUNY AT BUFFALO
Spiller Address:	119 JOHN BEANE CENTER
Spiller County:	001
Spiller Contact:	AL SWAVY
Spiller Phone:	(716) 829-3301
Spiller Extention:	Not reported
DEC Region:	9
DER Facility ID:	211221
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SAC 9/10/97:SAC TELECON GENE MONACELL-UB,TANK WILL BE EMPTIED,THEY ARE LOOKING TO CLOSE TANK DURING WINTER BREAK WHEN STUDENTS ARE HOME. 9/17/97:RECEIVED FAILING TANK TEST REPORT. 12/5/97:HAVE NOT RECEIVED WORKPLAN FOR TANK CLOSURE,DRAFTED LETTER REQUIRING PLAN BY 12/19/97. 5/25/99:SAC TELECON GENE MONACELL - SUNYAB, THEY INTEND TO REMOVE THE TANK OR CLOSE IN PLACE BUT WILL BORE THROUGH TO TAKE SAMPLES IF THE CLOSE IN PLACE OPTION IS CHOSEN, TANK HAS BEEN EMPTIED AND THEY ARE WAITING FOR FUNDING TO HANDLE ALL TANKS ON THE CAMPUS, ESTIMATE THAT WORK WILL BE GOING ON THIS SUMMER TO FALL, PROJECT WILL BE COMPLETED BY OGS,MR. MONACELL THINKS THAT THE TANK WAS OK BUT THAT THE PIPING LEAKED SINCE THROUGH THE INVENTORY RECORDS THEY DID NOT LOSE PRODUCT WHEN THE TANK WAS FILLED. 6/8/01:SAC TELECON BOB NAJJAR - URS/GREINER, THEY ARE ARRANGING FOR THE DISPOSAL OF THE CONTAMINATED SOIL FROM AROUND THE TANK BUT IT DID HAVE SOME PCBs IN THE SOIL SO IT WILL BE HANDLED APPROPRIATELY, TANK HAS NOT BEEN REMOVED, INDUSTRIAL SITE SERVICES IS THE CONTRACTOR HIRED TO DO THE REMOVAL AND BHAVESH KAMDAR IS THE CONTACT, AND GORDY LOVE IS THE PROJECT MANAGER FOR

SUNY AT BUFFALO (Continued) **S102177169**

SUNYAB, AL SWAVY AND LOU HENRY PROVIDE TECHNICAL GUIDANCE, HE WILL NOTIFY SAC WHEN TANK WILL BE REMOVED. 6/18/01:SAC TELECON PAT FOOTE - INDUSTRIAL SITE SERVICES, THEY ARE SCHEDULED TO REMOVE THE TANK IN ABOUT A MONTH'S TIME, THIS WILL BE AFTER THEY HAVE EXCAVATED THE PCB CONTAMINATED DIRT UNDER THE TRANSFORMER ROOM FLOORS. 7/18/01:SAC TELECON PAT FOOTE, MR. FOOTE SAID TANK IS SCHEDULED TO BE REMOVED THIS FRIDAY 7/20. 7/20/01:SAC INSPECT SITE, TANK HAS BEEN REMOVED. 7/24/01:SAC INSPECT SITE, MET W/JOHN HENSON AND PAT FOOTE - INDUSTRIAL SITE SERVICES, HOLES WERE OBSERVED IN THE BOTTOM OF TANK PER MR. HENSON, UTILITIES RUN THROUGH THE EXCAVATION SO CONTAMINATION WILL BE EXCAVATED BY HAND, SINCE THE PCB OIL SPILL (SPILL NUMBER 9705442) AND THIS SPILL ENCOMPASS THE SAME AREA AND THE REMEDIATIONS FOR BOTH HAVE MERGED TOGETHER, THEREFORE WE WILL CLOSE THIS SPILL AND FOLLOW UP UNDER SPILL NUMBER 9705442."

Remarks: "JOHN HAYNES 645-2752 WILL RETEST TANK. GENE MONTECELL. FARGO LOADING DOCK."

All TTF:

Facility ID:	9706838
Spill Number:	9706838
Spill Tank Test:	1545308
Site ID:	257969
Tank Number:	008
Tank Size:	500
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	257969
Operable Unit ID:	1050194
Operable Unit:	01
Material ID:	332425
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Spill Number/Closed Date:	9000336 / 1990-04-12
Facility ID:	9000336
Facility Type:	ER
DER Facility ID:	246675
Site ID:	305371

SUNY AT BUFFALO (Continued) **S102177169**

DEC Region:	9
Spill Cause:	Abandoned Drums
Spill Class:	Not reported
SWIS:	1522
Spill Date:	1990-04-10
Investigator:	COOKE
Referred To:	Not reported
Reported to Dept:	1990-04-10
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Fire Department
Cleanup Ceased:	1990-04-12
Cleanup Meets Std:	True
Last Inspection:	1990-04-11
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1990-04-10
Spill Record Last Update:	1990-04-20
Spiller Name:	Not reported
Spiller Company:	SUNY AT BUFFALO
Spiller Address:	MILLERSPORT HIGHWAY
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was JDC 04/11/90: JDC INSPECTED SITE W/ CALLER AND OBSERVED (3) DRUMS IN LAKE 10 FEET FROM SHORE, SUBMERGED. NO INDICATION OF A LEAK OR SPILL. WILL CONTACT UNOVERSITY OFFICIALS TO CONFIRM REMOVAL. 04/12/90: JDC RECEVIED CALL FROM MR G MONICELL, ENVIRO CHEM FOR UB. HE REPORTED DRUMS WERE EMPTY TRASH CANS MADE FROM OLD DRUMS. DRUMS WILL BE REMOVED BY MAINTENANCE. NO FURTHER ACTION WILL BE REQUIERD. "
Remarks:	"FOUR DRUMS FOUND WHEN CONTAINMENT POND PUMPED OUT"

All Materials:

Site ID:	305371
Operable Unit ID:	938680
Operable Unit:	01
Material ID:	438737
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AN188 **NYS UNIV. AT BUFFALO (N.)** **NY LTANKS** **S104513670**
NNE **301 MICHAEL HALL** **N/A**
< 1/8 **AMHERST, NY**
0.069 mi.
365 ft. **Site 3 of 4 in cluster AN**

Actual:
596 ft.

Focus Map:
4

LTANKS:

Spill Number/Closed Date:	9300882 / 1993-04-29
Facility ID:	9300882
Site ID:	308852
Spill Date:	1993-04-15
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	E6
Cleanup Ceased:	1993-04-29
SWIS:	1522
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	1993-04-15
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1993-04-20
Spill Record Last Update:	1994-01-06
Spiller Name:	Not reported
Spiller Company:	SUNY AT BUFFALO (NORTH)
Spiller Address:	306 MICHAEL HALL
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	9
DER Facility ID:	249425
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 04/28/93: MJS/JOHN CAMPBELL, OAKA/TELECON - MR. CAMPBELL INFORMS THAT TANKS ARE BEING RETESTED NOW AND LOOKS AS THOUGH TANKS WILL FAIL AGAIN. 04/29/93: RMC/RECEIVED FINAL TANK TEST RESULTS. TANKS PASSED ... CLOSE OUT. "
Remarks:	"THREE TANKS FAILED - EXCAVATE AND RETEST - INCONCLUSIVE OGS"

All TTF:

Facility ID:	9300882
Spill Number:	9300882
Spill Tank Test:	1541425
Site ID:	308852
Tank Number:	32
Tank Size:	0
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00

NYS UNIV. AT BUFFALO (N.) (Continued) **S104513670**

Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported
Facility ID:	9300882
Spill Number:	9300882
Spill Tank Test:	1541426
Site ID:	308852
Tank Number:	30
Tank Size:	0
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported
Facility ID:	9300882
Spill Number:	9300882
Spill Tank Test:	1541427
Site ID:	308852
Tank Number:	31
Tank Size:	0
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	308852
Operable Unit ID:	982635
Operable Unit:	01
Material ID:	567372
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

AN189 **SUNY AT BUFFALO-NORTH CAMPUS-ALUMNI ARENA POOL** **NY CBS UST** **S103941633**
NNE **THE JOHN BEANE CENTER-PHYSICAL PLANT** **NY CBS** **N/A**
< 1/8 **AMHERST, NY 14260**
0.069 mi.
365 ft. **Site 4 of 4 in cluster AN**

Actual:
596 ft.

Focus Map:
4

CBS:

CBS Number:	9-000276
Program Type:	CBS
Facility Status:	Unregulated/Closed
Expiration Date:	Not reported
Dec Region:	9
UTMX:	191192.49039
UTMY:	4767753.82074

AQ190 **COLDEN AUTO COLLISION INC** **EDR Hist Auto** **1020963993**
East **2131 EGGERT RD** **N/A**
< 1/8 **BUFFALO, NY 14226**
0.071 mi.
376 ft. **Site 1 of 5 in cluster AQ**

Actual:
597 ft.

Focus Map:
6

EDR Hist Auto

Year:	Name:	Type:
1985	OZTAN S & SONS INC	Automotive Repair Shops, NEC
1986	OZTAN S & SONS INC	Automotive Repair Shops, NEC
1987	OZTAN S & SONS INC	Automotive Repair Shops, NEC
1988	OZTAN S & SONS INC	Automotive Repair Shops, NEC
1989	OZTAN S & SONS INC	Automotive Transmission Repair Shops
1990	OZTAN S & SONS INC	Automotive Transmission Repair Shops
1992	COLDEN AUTO COLLISION INC	General Automotive Repair Shops
1993	COLDEN AUTO COLLISION INC	General Automotive Repair Shops
1994	COLDEN AUTO COLLISION INC	General Automotive Repair Shops
1995	COLDEN AUTO COLLISION INC	General Automotive Repair Shops
1996	COLDEN AUTO COLLISION INC	General Automotive Repair Shops
1997	COLDEN AUTO COLLISION INC	General Automotive Repair Shops
1998	COLDEN AUTO COLLISION INC	General Automotive Repair Shops
2000	MARTYS AUTO PRO CENTER	General Automotive Repair Shops
2001	GIOELI AUTOMOTIVE	General Automotive Repair Shops
2002	GIOELI AUTOMOTIVE	General Automotive Repair Shops
2009	AAA CAR CARE PLUS	Automotive Repair Shops, NEC
2010	AAA CAR CARE PLUS	Automotive Repair Shops, NEC
2011	AAA CAR CARE PLUS	Automotive Repair Shops, NEC
2012	AAA CAR CARE PLUS	Automotive Repair Shops, NEC
2013	AAA CAR CARE PLUS	Automotive Repair Shops, NEC
2014	AAA CAR CARE PLUS	Automotive Repair Shops, NEC

AQ191 **MARTY'S AUTOPRO CENTER** **RCRA NonGen / NLR** **1000555599**
East **2131 EGGERT RD** **FINDS** **NYD986981397**
< 1/8 **AMHERST, NY 14226** **ECHO**
0.071 mi. **NY MANIFEST**
376 ft. **Site 2 of 5 in cluster AQ**

Actual:
597 ft.

Focus Map:
6

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	AUTO PRO
Facility address:	2131 EGGERT RD AMHERST, NY 14226

MARTY'S AUTOPRO CENTER (Continued) **1000555599**

EPA ID: NYD986981397
Mailing address: EGGERT RD
AMHERST, NY 14226
Contact: MARTIN GREENBERG
Contact address: EGGERT RD
AMHERST, NY 14226
Contact country: US
Contact telephone: 716-833-0009
Contact email: Not reported
EPA Region: 02
Land type: Private
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: MARTIN GREENBERG
Owner/operator address: 2131 EGGERT RD
AMHERST, NY 14226
Owner/operator country: US
Owner/operator telephone: 716-833-0009
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

Owner/operator name: MARTIN GREENBERG
Owner/operator address: 2131 EGGERT RD
AMHERST, NY 14226
Owner/operator country: US
Owner/operator telephone: 716-833-0009
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

Owner/operator name: MARTIN GREENBERG
Owner/operator address: 2131 EGGERT RD
AMHERST, NY 14226
Owner/operator country: Not reported
Owner/operator telephone: 716-833-0009
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No

MARTY'S AUTOPRO CENTER (Continued) **1000555599**

Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: AUTO PRO
Classification: Not a generator, verified

Date form received by agency: 12/20/2002
Site name: AUTO PRO
Classification: Not a generator, verified

Date form received by agency: 04/30/2001
Site name: AUTO PRO
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

MARTY'S AUTOPRO CENTER (Continued) **1000555599**

Date form received by agency: 10/01/1991
Site name: AUTO PRO
Classification: Small Quantity Generator

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: LDR - General
Date violation determined: 07/26/1993
Date achieved compliance: 06/13/1995
Violation lead agency: EPA
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 08/18/1993
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Manifest
Date violation determined: 07/26/1993
Date achieved compliance: 06/13/1995
Violation lead agency: EPA
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 08/18/1993
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 10/06/1992
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Manifest
Date achieved compliance: 06/13/1995
Evaluation lead agency: EPA Contractor/Grantee

Evaluation date: 10/06/1992
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: LDR - General
Date achieved compliance: 06/13/1995
Evaluation lead agency: EPA Contractor/Grantee

FINDS:

Registry ID: 110004480197

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

MARTY'S AUTOPRO CENTER (Continued) **1000555599**

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000555599
Registry ID:	110004480197
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004480197

NY MANIFEST:

Country:	USA
EPA ID:	NYD986981397
Facility Status:	Not reported
Location Address 1:	2131 EGGERT ROAD
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	AMHERST
Location State:	NY
Location Zip:	14226
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD986981397
Mailing Name:	COLDEN AUTO COLLISION INCORPORATED
Mailing Contact:	COLDEN AUTO COLLISION INCORPORATED
Mailing Address 1:	PO BOX 127
Mailing Address 2:	Not reported
Mailing City:	KENMORE
Mailing State:	NY
Mailing Zip:	14217
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7168330009

NY MANIFEST:

Document ID:	NYG1905966
Manifest Status:	Not reported
seq:	01
Year:	2001
Trans1 State ID:	P207004IL
Trans2 State ID:	Not reported
Generator Ship Date:	04/23/2001
Trans1 Recv Date:	04/23/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/25/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986981397
Trans1 EPA ID:	NJD080631369
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD049836679

MARTY'S AUTOPRO CENTER (Continued) **1000555599**

TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F005 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AP192 **GAS FROM CAR AT UB** **NY Spills** **S104497692**
NW **SUNY AT BUFFALO** **N/A**
< 1/8 **AMHERST, NY**
0.073 mi.
384 ft. **Site 2 of 12 in cluster AP**

Actual:
658 ft.

Focus Map:
8

SPILLS:

Spill Number/Closed Date:	8806382 / 1988-10-31
Facility ID:	8806382
Facility Type:	ER
DER Facility ID:	232528
Site ID:	287055
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	1522
Spill Date:	1988-10-31
Investigator:	COOKE
Referred To:	Not reported
Reported to Dept:	1988-10-31
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Passenger Vehicle
Spill Notifier:	Fire Department
Cleanup Ceased:	1988-10-31
Cleanup Meets Std:	True
Last Inspection:	1988-10-31
Recommended Penalty:	False

GAS FROM CAR AT UB (Continued) **S104497692**

UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1988-10-31
Spill Record Last Update:	1988-11-04
Spiller Name:	Not reported
Spiller Company:	SANDRA MORLOCK
Spiller Address:	111 MACUMLY STREET
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was JDC 10/31/88: GETZVILLE FD AND UB STAFF APPLIED SPEEDY DRY TO AFFECTED AREA. DEBRIS COLLECTED AND DISPOSED OF TO CAMPUS TS & D FACILITY. NO FURTHER ACTION WILL BE REQUIRED. "
Remarks:	"GASOLINE TANK ON CAR LEAKING OUT FUEL TO PARKING LOT."

All Materials:

Site ID:	287055
Operable Unit ID:	921555
Operable Unit:	01
Material ID:	454727
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	9.00
Oxygenate:	Not reported

AP193 **SUNY AT BUFFALO** **NY Spills** **S103562203**
NW **ATCHISON HALL SUNYAB** **N/A**
< 1/8 **BUFFALO, NY**
0.073 mi.
384 ft. **Site 3 of 12 in cluster AP**

Actual:
658 ft.

Focus Map:
8

SPILLS:

Spill Number/Closed Date:	8803631 / 1988-10-26
Facility ID:	8803631
Facility Type:	ER
DER Facility ID:	220475
Site ID:	270837
DEC Region:	9
Spill Cause:	Other
Spill Class:	Not reported
SWIS:	1502
Spill Date:	1988-07-26
Investigator:	MXFRANKS
Referred To:	Not reported
Reported to Dept:	1988-07-26
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Fire Department
Cleanup Ceased:	1988-10-26
Cleanup Meets Std:	True
Last Inspection:	1988-07-26
Recommended Penalty:	False

SUNY AT BUFFALO (Continued) **S103562203**

UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1988-07-27
Spill Record Last Update:	1988-10-27
Spiller Name:	Not reported
Spiller Company:	SUNY AT BUFFALO
Spiller Address:	3435 MAIN STREET
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MF 07/26/88: MF & RNL SITE VISIT/GENE MONACELL, FIRE PUT OUT WITH DRY CHEMICALS, DEBRIS PLACED IN 55 GALLON DRUM, TO BE DISPOSED OF. NO RUNOFF GOT INTO SEWERS. 08/22/88: MF TELECON GENE MONACELL, HE CLAIMED HE IS WAITING FOR APPROVAL TO DISPOSE OF WASTE & HE WILL SEND ME A COPY OF DISPOSAL RECEIPT. 10/21/88: MF GENE TELECON, MATERIAL DISPOSED OF. HE WILL SEND RECEIPTS. 10/21/88: MF TELECON GENE MONACELL 10/20 & 10/21, NOT IN LEFT MESSAGE TO RETURN CALL. 10/26/88: MF RECEIVED COPY OF DISPOSAL RECEIPT. NO FUTHER ACYION NECESSARY. 09/29/95: This is additional information about material spilled from the translation of the old spill file: VARIOUS LAB CHEMICAL."
Remarks:	"CHEMISTRY BUILDING FIRE, F.D. CONCERNED ABOUT RUNOFF"

AP194 **SUNY AT BUFFALO** **NY Spills** **S102175865**
NW **MAIN STREET** **N/A**
< 1/8 **BUFFALO, NY**
0.073 mi.
384 ft. **Site 4 of 12 in cluster AP**

Actual:
658 ft.

Focus Map:
8

SPILLS:

Spill Number/Closed Date:	8706241 / 1987-10-23
Facility ID:	8706241
Facility Type:	ER
DER Facility ID:	282665
Site ID:	263237
DEC Region:	9
Spill Cause:	Human Error
Spill Class:	Not reported
SWIS:	1502
Spill Date:	1987-10-23
Investigator:	LEARY
Referred To:	Not reported
Reported to Dept:	1987-01-23
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Local Agency
Cleanup Ceased:	1987-10-23
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1987-10-29
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	SUNY AT BUFFALO
Spiller Address:	MAIN STREET
Spiller Company:	001

SUNY AT BUFFALO (Continued) **S102175865**

Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was RNL / / : RNL TELECON NYSDOH 10/23/87, DOH, W. OBRIEN, ON SCENE, CONTAINED WITHIN BUILDING, UNDER CONTROL, NO FURTHER SPILL UNIT INVOLVEMENT. "
Remarks: ""

All Materials:
Site ID: 263237
Operable Unit ID: 912276
Operable Unit: 01
Material ID: 465261
Material Code: 0064A
Material Name: unknown material
Case No.: Not reported
Material FA: Other
Quantity: .00
Units: L
Recovered: .00
Oxygenate: Not reported

---

195 East < 1/8 0.073 mi. 384 ft. **PADMOUNT TRANSFORMER #63** **NY Spills** **S108058170**
ALMEDA AVE **N/A**
AMHERST, NY

Actual: 593 ft.
Focus Map: 6

SPILLS:
Spill Number/Closed Date: 0603784 / 2006-09-26
Facility ID: 0603784
Facility Type: ER
DER Facility ID: 316618
Site ID: 366567
DEC Region: 9
Spill Cause: Equipment Failure
Spill Class: B3
SWIS: 1522
Spill Date: 2006-07-06
Investigator: RJJONAK
Referred To: Not reported
Reported to Dept: 2006-07-06
CID: 444
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2006-07-06
Spill Record Last Update: 2006-09-26
Spiller Name: LISA FREDERICKS
Spiller Company: PADMOUNT TRANSFORMER #63
Spiller Address: ALMEDA AVE
Spiller Company: 001

PADMOUNT TRANSFORMER #63 (Continued) **S108058170**

Contact Name: LISA FREDERICKS
DEC Memo: "7/17/06:SAC TELECON LISA FREDERICKS - NATIONAL GRID. MS. FREDERICKS SAID WORK TO START THIS FRIDAY, 7/21 AT 11:00 PM. THEY WILL SAMPLE THE TRANSMISSION FLUID DURING THE WORK FOR A PCB ANALYSIS. 7/21/2006: RJJ AT SITE AT 2300...DUE TO MANY TECHNICAL DIFFICULTIES,NATIONAL GRID HAS STOPPED THEIR PLAN TO REPLACE THE TRANSFORMER TODAY...LISA FREDRICKS WILL CALL US BACK,WHEN THEY WILL RESUME WORK,WHICH SHOULD BE SOME TIME NEXT WEEK...(I CHECKED INSIDE THE TRANSFORMER AND IT APPEARS THAT THERE IS/WAS ONLY A SMALL AMOUNT OF CONTAMINATED STONE AFFECTED.) 8/17/2006: LISA FREDRICKS TELECON RJJ,SHE SAID THAT THEY HAVE REPLACED THE TRANSFORMER AND REMOVED A SMALL AMOUNT OF CONTAMINATED STONE FROM THE PADMOUNT,WHICH THEY WILL DISPOSE...LISA WILL SEND ME THE DISPOSAL RECEIPTS. 9/26/2006: RECEIVED THE DISPOSAL RECEIPTS FOR THE MATERIAL TAKEN TO HIGH ACRES LANDFILL IN FAIRPORT,NY....THE SPILL HAS BEEN CLEANED UP AND PROPERLY DISPOSED OF...NO FURTHER ACTION NEEDED...SPILL CLOSED OUT."
Remarks: "OLD BUSHING FAILED: CONTAINED IN CONTAINMENT AREA: DOING CLEAN UP WHEN TRANSFORMER IS REPLACED, IN NEXT COUPLE OF DAYS:"

All Materials:
Site ID: 366567
Operable Unit ID: 1124503
Operable Unit: 01
Material ID: 2114001
Material Code: 0020A
Material Name: transformer oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G
Recovered: 1.00
Oxygenate: Not reported

AP196 **BUFFALO COLLEGE** **NY Spills** **S121100914**
NW **3435 MAIN ST AT MAIN CIRCLE AND HAYES RD** **N/A**
< 1/8 **BUFFALO, NY**
0.073 mi.
387 ft. **Site 5 of 12 in cluster AP**

Actual:
658 ft.

Focus Map:
8

SPILLS:
Spill Number/Closed Date: 1704127 / 2017-07-27
Facility ID: 1704127
Facility Type: ER
DER Facility ID: 508919
Site ID: 555346
DEC Region: 9
Spill Cause: Equipment Failure
Spill Class: Not reported
SWIS: 1502
Spill Date: 2017-07-26
Investigator: TDJOHNSO
Referred To: Not reported
Reported to Dept: 2017-07-26
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial Vehicle
Spill Notifier: Other

BUFFALO COLLEGE (Continued) **S121100914**

Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2017-07-26
Spill Record Last Update:	2017-07-27
Spiller Name:	Not reported
Spiller Company:	UNKNOWN BUS COMPANY
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	DISP SUSAN
DEC Memo:	"07/27/17 TDJ MINOR SPILL OF DIESEL FUEL CLEANED BY BFD. AND CITY STREETS DEPT. NO FURTHER ACTION FIE CLOSED TO ELECTRONIC ONLY"
Remarks:	"cleanup done"

All Materials:

Site ID:	555346
Operable Unit ID:	1303387
Operable Unit:	01
Material ID:	2309950
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	4.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

AP197 **SUNY AT BUFFALO - SOUTH CAMPUS, BAKER** **NY AIRS S121492725**
NW **3435 MAIN ST** **NY SPDES N/A**
< 1/8 **BUFFALO, NY 14214**
0.073 mi.
387 ft. **Site 6 of 12 in cluster AP**

Actual:
658 ft.

Focus Map:
8

AIRS:

Permit Type:	ASF
Permit Status:	Issued
Issue Date:	03/18/2015
Expiration Date:	03/17/2025
County Fips:	Not reported
DEC Id:	9140200680
Emission Unit Id:	Not reported
Process Id:	Not reported
Contaminant Name/cas:	Not reported
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	Not reported
Unit:	Not reported
Auth Type Code:	2
Latitude:	Not reported
Longitude:	Not reported

Permit Type:	ASF
Permit Status:	Expired

SUNY AT BUFFALO - SOUTH CAMPUS, BAKER (Continued) **S121492725**

Issue Date:	Not reported
Expiration Date:	12/30/2013
County Fips:	Not reported
DEC Id:	9140200680
Emission Unit Id:	Not reported
Process Id:	Not reported
Contaminant Name/cas:	Not reported
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	Not reported
Unit:	Not reported
Auth Type Code:	7
Latitude:	Not reported
Longitude:	Not reported

Permit Type:	ASF
Permit Status:	Expired
Issue Date:	10/22/2001
Expiration Date:	03/17/2015
County Fips:	Not reported
DEC Id:	9140200680
Emission Unit Id:	Not reported
Process Id:	Not reported
Contaminant Name/cas:	Not reported
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	Not reported
Unit:	Not reported
Auth Type Code:	7
Latitude:	Not reported
Longitude:	Not reported

Permit Type:	ASF
Permit Status:	Expired
Issue Date:	12/30/2013
Expiration Date:	Not reported
County Fips:	Not reported
DEC Id:	9140200680
Emission Unit Id:	Not reported
Process Id:	Not reported
Contaminant Name/cas:	Not reported
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	Not reported
Unit:	Not reported
Auth Type Code:	7
Latitude:	Not reported
Longitude:	Not reported

SPDES:

Permit Number:	NY0204218
State-Region:	9
Expiration Date:	08/31/2020
Current Major Minor Status:	Not reported
Primary Facility SIC Code:	9999
State Water Body Name:	Not reported

SUNY AT BUFFALO - SOUTH CAMPUS, BAKER (Continued) **S121492725**

Limit Set Status Flag:	Not reported
Total Actual Average Flow(MGD):	5.00000000
Total App Design Flow(MGD):	Not reported
UDF1:	Not reported
Lat/Long:	42.953232 / 78.8185938
DMR Cognizant Official:	LOUIS HENRY
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	Not reported
Non-Gov Permit Affiliation Type Desc:	Not reported
Non-Gov Permit Org Formal Name:	STATE UNIVERSITY OF NEW YORK
Non-Gov Permit Street Address:	STATE UNIVERSITY PLAZA
Non-Gov Permit Supplemental Location:	381 BROADWAY
Non-Gov Permit City:	ALBANY
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	12246
Non-Gov Facility Affiliation Type Desc:	Not reported
Non-Gov Facility Org Formal Name:	Not reported
Non-Gov Facility Street Address:	Not reported
Non-Gov Facility Supplemental Location:	Not reported
Non-Gov Facility City:	Not reported
Non-Gov Facility State Code:	Not reported
Non-Gov Facility Zip Code:	Not reported
State Water Body:	Not reported

AP198 **STATE UNIVERSITY OF NEW YORK SUNY BUFFALO** **PA MANIFEST** **S110049410**
NW **3435 MAIN ST** **N/A**
< 1/8 **BUFFALO, NY 14214**
0.073 mi.
387 ft. **Site 7 of 12 in cluster AP**

Actual:
658 ft.

Focus Map:
8

Manifest Details:

Year:	2009
Manifest Number:	005090037JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYD071475867
Generator Date:	09/29/2009
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	716-831-3301
TSD EPA Id:	PAD002390961
TSD Date:	Not reported
TSD Facility Name:	BETHLEHEM APPARATUS CO INC
TSD Facility Address:	890 FRONT ST
TSD Facility City:	HELLERTOWN
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D007
Container Number:	5
Container Type:	Metal drums, barrels, kegs
Waste Quantity:	1500
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

STATE UNIVERSITY OF NEW YORK SUNY BUFFALO (Continued) **S110049410**

Year:	2009
Manifest Number:	005090037JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYD071475867
Generator Date:	09/29/2009
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	716-831-3301
TSD EPA Id:	PAD002390961
TSD Date:	Not reported
TSD Facility Name:	BETHLEHEM APPARATUS CO INC
TSD Facility Address:	890 FRONT ST
TSD Facility City:	HELLERTOWN
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D006
Container Number:	5
Container Type:	Metal drums, barrels, kegs
Waste Quantity:	1500
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

Year:	2009
Manifest Number:	005090037JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYD071475867
Generator Date:	09/29/2009
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	716-831-3301
TSD EPA Id:	PAD002390961
TSD Date:	Not reported
TSD Facility Name:	BETHLEHEM APPARATUS CO INC
TSD Facility Address:	890 FRONT ST
TSD Facility City:	HELLERTOWN
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D004
Container Number:	5
Container Type:	Metal drums, barrels, kegs
Waste Quantity:	1500
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

Year:	2009
Manifest Number:	005090037JJK
Manifest Type:	TSD Copy

STATE UNIVERSITY OF NEW YORK SUNY BUFFALO (Continued) **S110049410**

Generator EPA Id:	NYD071475867
Generator Date:	09/29/2009
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	716-831-3301
TSD EPA Id:	PAD002390961
TSD Date:	Not reported
TSD Facility Name:	BETHLEHEM APPARATUS CO INC
TSD Facility Address:	890 FRONT ST
TSD Facility City:	HELLERTOWN
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D008
Container Number:	5
Container Type:	Metal drums, barrels, kegs
Waste Quantity:	1500
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

Year:	2008
Manifest Number:	005090023JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYD071475867
Generator Date:	10/02/2008
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	716-831-3301
TSD EPA Id:	PAD002390961
TSD Date:	Not reported
TSD Facility Name:	BETHLEHEM APPARATUS CO INC
TSD Facility Address:	890 FRONT STREET
TSD Facility City:	HELLERTOWN
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D007
Container Number:	8
Container Type:	Metal drums, barrels, kegs
Waste Quantity:	2800
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

Year:	2008
Manifest Number:	005090023JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYD071475867
Generator Date:	10/02/2008
Mailing Address:	Not reported

STATE UNIVERSITY OF NEW YORK SUNY BUFFALO (Continued) **S110049410**

Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	716-831-3301
TSD EPA Id:	PAD002390961
TSD Date:	Not reported
TSD Facility Name:	BETHLEHEM APPARATUS CO INC
TSD Facility Address:	890 FRONT STREET
TSD Facility City:	HELLERTOWN
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D004
Container Number:	8
Container Type:	Metal drums, barrels, kegs
Waste Quantity:	2800
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

Year:	2008
Manifest Number:	005090023JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYD071475867
Generator Date:	10/02/2008
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	716-831-3301
TSD EPA Id:	PAD002390961
TSD Date:	Not reported
TSD Facility Name:	BETHLEHEM APPARATUS CO INC
TSD Facility Address:	890 FRONT STREET
TSD Facility City:	HELLERTOWN
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D008
Container Number:	8
Container Type:	Metal drums, barrels, kegs
Waste Quantity:	2800
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

Year:	2008
Manifest Number:	005090023JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYD071475867
Generator Date:	10/02/2008
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	716-831-3301

STATE UNIVERSITY OF NEW YORK SUNY BUFFALO (Continued) **S110049410**

TSD EPA Id:	PAD002390961
TSD Date:	Not reported
TSD Facility Name:	BETHLEHEM APPARATUS CO INC
TSD Facility Address:	890 FRONT STREET
TSD Facility City:	HELLERTOWN
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D006
Container Number:	8
Container Type:	Metal drums, barrels, kegs
Waste Quantity:	2800
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

AP199 **SUNY AT BUFFALO - SOUTH CAMPUS, BAKER** **ICIS 1016106672**
NW **3435 MAIN STREET** **FINDS N/A**
< 1/8 **BUFFALO, NY 14214** **ECHO**
0.073 mi.
387 ft. **Site 8 of 12 in cluster AP**

Actual:
658 ft.

Focus Map:
8

ICIS:

Enforcement Action ID:	02-2005-0841
FRS ID:	110000880100
Action Name:	University at Buffalo
Facility Name:	SUNY AT BUFFALO - SOUTH CAMPUSNA BAKER
Facility Address:	3435 MAIN STREET BUFFALO, NY 14214-3001
Enforcement Action Type:	RCRA 3008A AO For Comp And/Or Penalty
Facility County:	ERIE
Program System Acronym:	RCRAINFO
Enforcement Action Forum Desc:	Administrative - Formal
EA Type Code:	3008A
Facility SIC Code:	Not reported
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	42.955965
Longitude in Decimal Degrees:	-78.820564
Permit Type Desc:	Not reported
Program System Acronym:	NYD071475867
Facility NAICS Code:	Not reported
Tribal Land Code:	Not reported

Enforcement Action ID:	02-000F000360290010300002
FRS ID:	110000880100
Action Name:	SUNY AT BUFFALO - SOUTH CAMPUS 360290010300002
Facility Name:	SUNY AT BUFFALO - SOUTH CAMPUS, BAKER
Facility Address:	3435 MAIN ST BUFFALO, NY 14214
Enforcement Action Type:	Notice of Violation
Facility County:	ERIE
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Informal
EA Type Code:	NOV
Facility SIC Code:	8221
Federal Facility ID:	Not reported

SUNY AT BUFFALO - SOUTH CAMPUS, BAKER (Continued) **1016106672**

Latitude in Decimal Degrees: 42.953233
Longitude in Decimal Degrees: 78.8185938
Permit Type Desc: Not reported
Program System Acronym: NY0000009140200680
Facility NAICS Code: 221112
Tribal Land Code: Not reported

Facility Name: SUNY AT BUFFALO - SOUTH CAMPUS
Address: 3435 MAIN STREET
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: SUNY AT BUFFALO - SOUTH CAMPUS
Address: 3435 MAIN STREET
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: SUNY AT BUFFALO - SOUTH CAMPUS
Address: 3435 MAIN STREET
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: SUNY AT BUFFALO - SOUTH CAMPUS
Address: 3435 MAIN STREET
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

FINDS:

Registry ID: 110000880100

Environmental Interest/Information System

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

AIR SYNTHETIC MINOR

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of

SUNY AT BUFFALO - SOUTH CAMPUS, BAKER (Continued) **1016106672**

events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016106672
Registry ID:	110000880100
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110000880100

AP200 **UNIVERSITY OF BUFFALO** **NY LTANKS** **S110243419**
NW **3435 MAIN STREET** **NY Spills** **N/A**
< 1/8 **BUFFALO, NY 14214**
0.073 mi.
387 ft. **Site 9 of 12 in cluster AP**

Actual:
658 ft.

Focus Map:
8

LTANKS:

Spill Number/Closed Date:	9004852 / 1993-12-23
Facility ID:	9004852
Site ID:	80791
Spill Date:	1990-07-31
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B3
Cleanup Ceased:	1993-12-23
SWIS:	1502
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	1990-08-01
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	1993-06-29
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1990-08-01
Spill Record Last Update:	1996-06-18
Spiller Name:	Not reported
Spiller Company:	NYS - SUNYAB
Spiller Address:	306 MICHAEL HALL
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	9

UNIVERSITY OF BUFFALO (Continued) **S110243419**

DER Facility ID: 74826
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 08/01/90: MF TELECON SPILLER, TANK TESTED & FAILED. EMPTIED, WILL BE REPLACED. 08/31/90: MF 8/31/90 LETTER FROM SPILLER. PROPOSAL FOR REMOVAL SENT OUT. WILL KEEP DEC INFORMED. 10/09/90: MF 10/9/90 LETTER FROM SPILLER. PROPOSAL FOR TANK REMOVAL SENT TO ALBANY. 02/13/91: MF LETTER TO SPILLER REQUESTING UPDATE BY 2/28/91. 03/04/91: MF 3/4/91 LETTER FROM SPILLER, REQUEST FOR FUNDS IS IN THE HANDS OF ALBANY. 07/29/91: MF 7/29/91 LETTER TO SPILLER REQUESTING UPDATE BY 8/30/91. 08/05/91: MF 8/2/91 LETTER FROM SPILLER, MONEY FOR PROJECT EXPECTED BY 10/91. 12/30/91: MF LETTER TO RP REQUESTING UPDATE BY 1/31/91. 02/11/92: REMINDER LETTER, RESPONSE DUE 2/28/92. 02/21/92: RECEIVED LETTER PROJECTING FUNDS AVIABLE FOR REMOVAL 7/1/92, REMOVAL AT THAT TIME. 07/09/92: RMC/RECEIVED LETTER WORK FUNDED THIS YEAR SCHEDUAL TO FOLLOW. CALL 9/1/92 IF SCHEDUAL NOT YET RECEIVED. 10/20/92: RMC/GENE M./ PHONE WILL UPDATE VIA LETTER, DUE 11/30/92. 01/15/93: RMC/LETTER REQUESTING CONTRACT AND SCHEDUAL DUE 02/19/93. 03/13/93: RMC/BOB EADICCO/PHONE TANK WILL BE REMOVED BY 05/30/93, CALL 04/15/93 FOR UPDATE. 03/13/93: RMC/BOB EADICCO/PHONE TANK WILL BE REMOVED BY 05/30/93, CALL 04/15/93 FOR UPDATE RECEIVED CONFIRMATION LETTER 03/17/93 CALL 4/15/93. 04/29/93: RMC/GENE MONOCELL/PHONE TANK WILL BE REMOVED BY 05/30/93, CALL 04/15/93 FOR UPDATE RECEIVED CONFIRMATION LETTER 03/17/93 CALL 4/15/93 PROJECT ON SCHEDULE FOR 5/30/93 REMOVAL. 06/15/93: RMC/RECEIVED PBS REMOVAL FORM, TO REMOVE 7/15/93. 06/29/93: RMC/SITE TANKS REMOVED WITH 200 YARDS CONTAMINATED SOIL. SAMPLES DUE 7/30/93. DISPOSAL DUE 8/15/93. 08/17/93: RMC/GENE MONACELL/PHONE RMC ADVISED NON HAZARDOUS BASED ON RESULTS SUBMITTED ON EXCAVATED SOIL WHICH IS TO BE LANDFILLED, CLEAN HOLE TEST DUE 9/15/93. 11/19/93: RMC/DISPOSAL SAMPLING LETTER, RESPONSE DUE 12/30/93. 12/23/93: RMC/FILE REVIEW, RECEIVED DISPOSAL RECEIPTS, OK, NO FURTHER SAMPLING WAS DONE PER EPS, INCOMPLETE,. "
Remarks: "TANK TAKING ON WATER, TANK EMPTIED."

All TTF:
Facility ID: 9004852
Spill Number: 9004852
Spill Tank Test: 1537380
Site ID: 80791
Tank Number: Not reported
Tank Size: 0
Material: 0009
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 80791
Operable Unit ID: 942536
Operable Unit: 01
Material ID: 435926

UNIVERSITY OF BUFFALO (Continued) **S110243419**

Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	9307528 / 1993-11-19
Facility ID:	9307528
Site ID:	80792
Spill Date:	1993-09-21
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	1993-11-03
SWIS:	1502
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	1993-09-21
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1993-09-23
Spill Record Last Update:	1994-01-11
Spiller Name:	Not reported
Spiller Company:	NYS UNIVERSITY OF BUFFALO
Spiller Address:	301 MICHAEL HALL
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	9
DER Facility ID:	74826
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 09/23/93: RMC/ RHODES/PHONE TO RETEST TANK, ALL TANK TEST RESULTS DUE 10/30/93. 11/19/93: RMC/RECEIVED RETEST, PASSED CLOSE OUT. "
Remarks:	"TANK TEST FAILURE."

All TTF:

Facility ID:	9307528
Spill Number:	9307528
Spill Tank Test:	1542012
Site ID:	80792
Tank Number:	Not reported
Tank Size:	0
Material:	0008
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported

UNIVERSITY OF BUFFALO (Continued) **S110243419**

Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	80792
Operable Unit ID:	986106
Operable Unit:	01
Material ID:	393787
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Spill Number/Closed Date:	1100485 / 2011-05-23
Facility ID:	1100485
Facility Type:	ER
DER Facility ID:	375172
Site ID:	447891
DEC Region:	9
Spill Cause:	Other
Spill Class:	Not reported
SWIS:	1502
Spill Date:	2011-04-13
Investigator:	TDJOHNSO
Referred To:	Not reported
Reported to Dept:	2011-04-14
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2011-04-14
Spill Record Last Update:	2011-05-23
Spiller Name:	TONY OSWALD
Spiller Company:	UNIVERSITY AT BUFFALO
Spiller Address:	3435 MAIN ST
Spiller Company:	999
Contact Name:	TONY OSWALD
DEC Memo:	"04/14/11 TDJ WHILE WORKING ON OLD SANITARY DRAIN LINE IN BASEMENT AT UNIVERSITY A CONTRACTOR FOUND A SMALL AMOUNT OF MERCURY IN THE BROKEN TILE. EPIC ENVIRONMENTAL WAS CONTACTED TO CLEAN AND DISPOSE OF SAME.

UNIVERSITY OF BUFFALO (Continued) **S110243419**

A MERVAC WAS USED TO SUCK UP LIQUID AND BROKEN DRAIN LINE WAS CONTAINED FOR DISPOSAL AS HAZARDOUS MATERIAL. NO ADDITIONAL MERCURY WAS ENCOUNTERED FROM LINE. 05/20/11 TDJ RECEIVED DISPOSAL RECEIPT FOR DRUMS OF MERCURY CONTAMINATED MATERIAL TAKEN TO CWM IN MODEL CITY. NO FURTHER ACTION FILE CLOSED"

Remarks: "Caller reporting a spill of 2 pounds of mercury. Clean up complete."

All Materials:

Site ID:	447891
Operable Unit ID:	1198137
Operable Unit:	01
Material ID:	2194384
Material Code:	0031A
Material Name:	mercury
Case No.:	07439976
Material FA:	Hazardous Material
Quantity:	2.00
Units:	L
Recovered:	Not reported
Oxygenate:	Not reported

Spill Number/Closed Date:	0711200 / 2009-01-23
Facility ID:	0711200
Facility Type:	ER
DER Facility ID:	74826
Site ID:	392627
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	1502
Spill Date:	2008-01-23
Investigator:	jfotto
Referred To:	Not reported
Reported to Dept:	2008-01-23
CID:	404
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-01-23
Spill Record Last Update:	2009-01-23
Spiller Name:	AL SWAVY
Spiller Company:	BIOMEDICAL EDUCATIONAL BU
Spiller Address:	3435 MAIN STREET
Spiller Company:	001
Contact Name:	AL SWAVY
DEC Memo:	"1/24/08 FG SPOKE TO AL SWAVY WITH UB - 829-3301. HE SAID THEY ARE INVESTIGATING THE SOURCE OF THE LEAK. THEY BELIEVE IT TO BE IN THE LIFT. THEY WILL DISCONNECT THE LINE TO THE HYDRAULIC TANK AND PRESSURE TEST TO ELIMINATE THE LINE AS A POSSIBILITY. THEY BELIEVE THE HYDRAULIC OIL IS IN THE STEEL SLEEVE. THEY WILL SEND SOMEONE IN TO CHECK ONCE CONDITIONS ARE SAFE. 01/29/08 JFO CALL FROM BRIAN FOTI.

UNIVERSITY OF BUFFALO (Continued) **S110243419**

ONLY SLIGHT CONTAMINATION. THEY WILL REMOVE AND DISPOSE IN REGULAR WASTE STREAM. HE WILL SEND IN HIS REPORT. 02/05/08 JFO CALL TO BRIAN F. LEFT MSG ON V-MAIL. NEED REPORT TO CLOSE. 03/13/08 JFO CALL TO BRIAN. NLEFT MSG ON V-MAIL. 04/07/08 JFO TELCON WITH BRIAN. HE WILL SEND THE REPORT TODAY. 01/22/09 JFO CALL TO AL SWAVY AND BRIAN FOTI. THEY WILL SEND THE REPORT VIA E-MAIL. 01/23/09 JFO REC'D THE REPORT. THE 7 PLACTIC BAGS OF CLEANUP MATERIAL WAS DISPOSED VIA REGULAR WASTE STREAM. NO FURTHER ACTION REQUIRED. CLOSED"

Remarks: "the hydraulic lift stopped working causing the hydraulic oil to be lost; it could possibly be in the line still or it could have leaked into a pit; they are going to investigate futher tomorrow; will call with updates"

All Materials:

Site ID:	392627
Operable Unit ID:	1149619
Operable Unit:	01
Material ID:	2140154
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	1207951 / 2013-04-04
Facility ID:	1207951
Facility Type:	ER
DER Facility ID:	425291
Site ID:	471011
DEC Region:	9
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	1502
Spill Date:	2012-10-01
Investigator:	TDJOHNSO
Referred To:	Not reported
Reported to Dept:	2012-10-31
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2012-10-31
Spill Record Last Update:	2013-04-15
Spiller Name:	Not reported
Spiller Company:	UNIVERSITY AT BUFFALO
Spiller Address:	3435 MAIN STREET
Spiller Company:	999
Contact Name:	Not reported

UNIVERSITY OF BUFFALO (Continued) **S110243419**

DEC Memo: "11/1/12 TDJ WENT TO LOCATION AND SPOKE WITH MATT HOLQUIST OF WATTS ENGINEERING (716)206-5140 WHO SHOWED ME THE AREA OF CONCERN. DURING THE RENOVATION PROJECT FOR THE 1800'S STRUCTURE THE CONCRETE FLOORING IS BEING CUT FOR NEW FOUNDATION WALLS. ONE AREA HAD A MUSTY ODOR OF POSSIBLE DIESEL OR SIMILAR OIL. SAMPLES WERE TAKEN AND ONE WAS FOUND TO CONTAIN LOW LEVEL DIESEL CONTAMINATION. WILL HAVE CONTRACTOR DIG THROUGH CINDER FILL IN TOP 2-5 UNDER CONCRETE WHERE THICK CLAY LAYER CONTAINED SPILL. SAMPLE WILL BE COLLECTED TO SHOW MATERIAL WAS REMOVED. CONTAMINATED DIRT IS BEING STAGED FOR DISPOSAL. 11/1/12 TDJ SPOKE WITH MIKE CARPENTER (315) 576-0982 WHO IS IN CHARGE OF ENVIRONMENTAL WORK ON SOIL SAMPLING. CONTAMINATION WAS FOUND IN THE CONFIRMATORY SAMPLES ABOVE CP-51 LIMITS. DISCUSSED THE ADDITIONAL SOIL REMOVAL AND RESAMPLING OF SOIL NEEDED TO CLOSE SPILL. 12/20/12 TDJ FURTHER EXCAVATION WORK BEGAN IN THE BASEMENT AREA WITH WORKERS HAND SHOVELING CONTAMINATED SOIL. HOLES DRILLED INTO THE CONCRETE AND SOIL GAS SAMPLING PERFORMED RECENTLY DEFINED THE AREA OF FURTHER REMEDIAL WORK. PID READINGS WILL DETERMINE THE SOIL REMOVAL FOLLOWED BY SAMPLING TO CONFIRM CP-51 SOIL GUIDANCE LIMITS ARE MET. SPOKE WITH MATT FORCUCCI OF THE NYS HEALTH DEPT.ABOUT POSSIBLE AIR MONITORING WHEN PROJECT IS COMPLETE. HE FEELS THAT AS LONG AS THERE HAS BEEN NO ODORS IN THE PAST AND WE ARE REMOVING THE SOURCE MATERIAL WHICH WILL BE COVERED BY CONCRETE WE SHOULD NOT NEED AN AIR MONITORING PROGRAM. 04/01/13 TDJ RECEIVED FINAL REPORT FOR ADDITIONAL SOIL REMOVAL,DISPOSAL AND CONFIRMATORY SAMPLING. RESULTS SHOW ALL CONTAMINANTS TESTED FOR WERE BELOW THE CP-51/ SOIL CLEANUP GUIDANCE LIMITS. NO ADDITIONAL WORK WILL BE PERFORMED IN THE BASEMENT AREA UNLESS WORK IN OTHER AREAS FINDS ADDITIONAL CONTAMINATION. NO FURTHER ACTION LETTER SENT TO STEVE DEMEO. NO FURTHER ACTION FILE CLOSED"

Remarks: "Soil with solvent odors found under concrete floor. Facility was cutting out a portion of a basement floor slab to put in a footer. Sample results also indicate contamination. Results will be e-mailed to RMC."

All Materials:

Site ID:	471011
Operable Unit ID:	1220870
Operable Unit:	01
Material ID:	2219497
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Spill Number/Closed Date:	0075177 / 2000-10-18
Facility ID:	0075177
Facility Type:	ER
DER Facility ID:	74826
Site ID:	80790
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	D3
SWIS:	1502
Spill Date:	2000-06-20

UNIVERSITY OF BUFFALO (Continued) **S110243419**

Investigator:	RJJONAK
Referred To:	Not reported
Reported to Dept:	2000-06-20
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	2000-06-20
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-06-20
Spill Record Last Update:	2000-10-23
Spiller Name:	GENE MONACELL
Spiller Company:	SUNY AT BUFFALO
Spiller Address:	3435 MAIN STREET
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RJJ 06/20/2000: RJJ SITE INVESTIGATION AT 1000...MEET WITH GENE MONACELL, MANAGER OF HAZARDOUS MATERIALS-UB, HE TOOK ME TO THE RIDING MOWER, WHICH HAD AN ELECTRICAL PROBLEM, WHICH CAUSED A FIRE, WHICH TOTALED THE MOWER...ABOUT THREE GALLONS OF HYDRAULIC OIL SPILLED UNDER THE MOWER, THEY SHUT-OFF THE FUEL TANK SO NO FUEL WAS SPILLED...THEY WILL DIG UP ABOUT AN AREA OF ABOUT 10'X10' AND DISPOSE OF THE SOIL AND SEND ME THE SOIL DISPOSAL RECEIPTS...THE BUFFALO FIRE DEPT. WAS AT THE SITE TO PUT OUT THE FIRE...NO ONE WAS HURT. 10/18/2000: RJJ RECEIVED THE REPORT FROM GENE MONACELL, WHICH INCLUDES THE SOIL DISPOSAL RECEIPTS, FROM THE UB CAMPUS...ALL THE RECEIPTS ARE IN ORDER...I CAN NOW CLOSE OUT THIS SPILL...NO FURTHER ACTION NEEDED."
Remarks:	"CALLER SAID THAT ABOUT 2 GAL OF HYDRAULIC OIL SPILLED ONTO THE LAWN OF THE UB CAMPUS FROM A RIDING MOWER....REQUEST D.E.C. RESPONCE."

All Materials:

Site ID:	80790
Operable Unit ID:	838003
Operable Unit:	01
Material ID:	538722
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	2.00
Oxygenate:	Not reported

Spill Number/Closed Date:	0913360 / 2010-03-22
Facility ID:	0913360
Facility Type:	ER
DER Facility ID:	375172
Site ID:	426298
DEC Region:	9
Spill Cause:	Unknown

UNIVERSITY OF BUFFALO (Continued) **S110243419**

Spill Class:	E6
SWIS:	1502
Spill Date:	2010-03-18
Investigator:	FXGALLEG
Referred To:	Not reported
Reported to Dept:	2010-03-18
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-03-18
Spill Record Last Update:	2010-03-22
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	SCOTT WAKEFIELD
DEC Memo:	"3/18/10 FG SITE INSPECTION. FOUND A TRAILER LABELED ASBESTOS THAT APPEARED TO BE LEAKING A SMALL AMOUNT OF WATER. COMPANY INFORMATION ON TRAILER, SERVICE TRANSPORT GROUP, NEW CASTLE DELAWARE. FG SPOKE TO OFFICER T. KOPACZ WITH THE UNIVERSITY POLICE 645-2224. HE GAVE ME THE FACILITIES PHONE NUMBER 829-2270. 3/20/10 FG CONTACTED THE UNIVERSITY HEALTH & SAFETY GROUP AND ARE WAITING FOR THEIR RETURN CALL 829-3301. TONY OSWALD OR AL SWAVE TO CALL BACK. FG SPOKE TO NANCY HUTCHISON WITH THE UNIVERSITY OF BUFFALO 829-2702. SHE SAID THE TRACTOR HAS BEEN SEALED OFF AND THE WATER CLEANED UP. NO FURTHER WORK IS REQUIRED. THE SITE IS CLOSED. ELECTRONIC FILE ONLY. "
Remarks:	"unknown information - generic nrc report - nrc #"

All Materials:

Site ID:	426298
Operable Unit ID:	1181985
Operable Unit:	01
Material ID:	2176125
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

AP201 **STATE UNIVERSITY OF NEW YORK AT BUFFALO S CAMPUS** **RCRA-LQG** **1000397714**
NW **3435 MAIN ST** **US AIRS** **NYD071475867**
< 1/8 **BUFFALO, NY 14215** **WI MANIFEST**
0.073 mi.
387 ft. **Site 10 of 12 in cluster AP**

Actual:
658 ft.

Focus Map:
8

RCRA-LQG:

Date form received by agency:	02/24/2016
Facility name:	STATE UNIVERSITY OF NEW YORK AT BUFFALO S CAMPUS
Facility address:	3435 MAIN ST BUFFALO, NY 14215
EPA ID:	NYD071475867
Mailing address:	WINSPEAR AVE BUFFALO, NY 14215
Contact:	ANTHONY OSWALD
Contact address:	WINSPEAR AVE BUFFALO, NY 14215
Contact country:	US
Contact telephone:	716-829-3301
Contact email:	ACOSWALD@BUFFALO.EDU
EPA Region:	02
Land type:	State
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	ANTHONY OSWALD
Owner/operator address:	MAIN ST BUFFALO, NY 14215
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	State
Owner/Operator Type:	Operator
Owner/Op start date:	12/01/2004
Owner/Op end date:	Not reported

Owner/operator name:	STATE UNIVERSITY OF NEW YORK AT BUFFALO
Owner/operator address:	MAIN ST BUFFALO, NY 14215
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	State

STATE UNIVERSITY OF NEW YORK AT BUFFALO S CAMPUS (Continued) **1000397714**

Owner/Operator Type: Owner
Owner/Op start date: 08/01/1980
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Universal Waste Summary:
Waste type: Batteries
Accumulated waste on-site: Yes
Generated waste on-site: Not reported

Waste type: Lamps
Accumulated waste on-site: Yes
Generated waste on-site: Not reported

Waste type: Thermostats
Accumulated waste on-site: Yes
Generated waste on-site: Not reported

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D003
. Waste name: A MATERIAL IS CONSIDERED TO BE A REACTIVE HAZARDOUS WASTE IF IT IS NORMALLY UNSTABLE, REACTS VIOLENTLY WITH WATER, GENERATES TOXIC GASES WHEN EXPOSED TO WATER OR CORROSIVE MATERIALS, OR IF IT IS CAPABLE OF

STATE UNIVERSITY OF NEW YORK AT BUFFALO S CAMPUS (Continued) **1000397714**

DETONATION OR EXPLOSION WHEN EXPOSED TO HEAT OR A FLAME. ONE EXAMPLE OF SUCH WASTE WOULD BY WASTE GUNPOWDER.

. Waste code: D004
. Waste name: ARSENIC

. Waste code: D005
. Waste name: BARIUM

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D010
. Waste name: SELENIUM

. Waste code: D018
. Waste name: BENZENE

. Waste code: D019
. Waste name: CARBON TETRACHLORIDE

. Waste code: D022
. Waste name: CHLOROFORM

. Waste code: D028
. Waste name: 1,2-DICHLOROETHANE

. Waste code: D029
. Waste name: 1,1-DICHLOROETHYLENE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLOROETHYLENE

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003

STATE UNIVERSITY OF NEW YORK AT BUFFALO S CAMPUS (Continued) 1000397714

. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: LABP
. Waste name: LAB PACK

. Waste code: P087
. Waste name: OSMIUM OXIDE OSO4, (T-4)-

Historical Generators:
Date form received by agency: 02/28/2014
Site name: SUNY AT BUFFALO SOUTH CAMPUS
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D003
. Waste name: A MATERIAL IS CONSIDERED TO BE A REACTIVE HAZARDOUS WASTE IF IT IS NORMALLY UNSTABLE, REACTS VIOLENTLY WITH WATER, GENERATES TOXIC GASES WHEN EXPOSED TO WATER OR CORROSIVE MATERIALS, OR IF IT IS CAPABLE OF DETONATION OR EXPLOSION WHEN EXPOSED TO HEAT OR A FLAME. ONE EXAMPLE OF SUCH WASTE WOULD BY WASTE GUNPOWDER.

. Waste code: D004

STATE UNIVERSITY OF NEW YORK AT BUFFALO S CAMPUS (Continued) **1000397714**

. Waste name: ARSENIC

. Waste code: D005
. Waste name: BARIUM

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D010
. Waste name: SELENIUM

. Waste code: D011
. Waste name: SILVER

. Waste code: D018
. Waste name: BENZENE

. Waste code: D022
. Waste name: CHLOROFORM

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLOROETHYLENE

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

STATE UNIVERSITY OF NEW YORK AT BUFFALO S CAMPUS (Continued) **1000397714**

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: LABP
. Waste name: LAB PACK

. Waste code: P012
. Waste name: ARSENIC OXIDE AS2O3

. Waste code: P030
. Waste name: CYANIDES (SOLUBLE CYANIDE SALTS), NOT OTHERWISE SPECIFIED

. Waste code: B004
. Waste name: B004

. Waste code: B007
. Waste name: B007

Date form received by agency: 03/06/2012
Site name: SUNY AT BUFFALO SOUTH CAMPUS
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D003
. Waste name: A MATERIAL IS CONSIDERED TO BE A REACTIVE HAZARDOUS WASTE IF IT IS NORMALLY UNSTABLE, REACTS VIOLENTLY WITH WATER, GENERATES TOXIC GASES WHEN EXPOSED TO WATER OR CORROSIVE MATERIALS, OR IF IT IS CAPABLE OF DETONATION OR EXPLOSION WHEN EXPOSED TO HEAT OR A FLAME. ONE EXAMPLE OF SUCH WASTE WOULD BY WASTE GUNPOWDER.

. Waste code: D004
. Waste name: ARSENIC

. Waste code: D005

STATE UNIVERSITY OF NEW YORK AT BUFFALO S CAMPUS (Continued) **1000397714**

. Waste name: BARIUM

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D011
. Waste name: SILVER

. Waste code: D018
. Waste name: BENZENE

. Waste code: D019
. Waste name: CARBON TETRACHLORIDE

. Waste code: D022
. Waste name: CHLOROFORM

. Waste code: D028
. Waste name: 1,2-DICHLOROETHANE

. Waste code: D029
. Waste name: 1,1-DICHLOROETHYLENE

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLOROETHYLENE

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT

STATE UNIVERSITY OF NEW YORK AT BUFFALO S CAMPUS (Continued) **1000397714**

NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: LABP
. Waste name: LAB PACK

. Waste code: P012
. Waste name: ARSENIC OXIDE AS2O3

. Waste code: P087
. Waste name: OSMIUM OXIDE OSO4, (T-4)-

. Waste code: P098
. Waste name: POTASSIUM CYANIDE

. Waste code: P106
. Waste name: SODIUM CYANIDE

. Waste code: U002
. Waste name: ACETONE (I)

Date form received by agency: 03/08/2010
Site name: STATE UNIVERSITY OF NEW YORK AT BUFFALO, SOUTH CAMPUS
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D003

STATE UNIVERSITY OF NEW YORK AT BUFFALO S CAMPUS (Continued) **1000397714**

. Waste name: A MATERIAL IS CONSIDERED TO BE A REACTIVE HAZARDOUS WASTE IF IT IS NORMALLY UNSTABLE, REACTS VIOLENTLY WITH WATER, GENERATES TOXIC GASES WHEN EXPOSED TO WATER OR CORROSIVE MATERIALS, OR IF IT IS CAPABLE OF DETONATION OR EXPLOSION WHEN EXPOSED TO HEAT OR A FLAME. ONE EXAMPLE OF SUCH WASTE WOULD BY WASTE GUNPOWDER.

. Waste code: D004
. Waste name: ARSENIC

. Waste code: D005
. Waste name: BARIUM

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D011
. Waste name: SILVER

. Waste code: D018
. Waste name: BENZENE

. Waste code: D021
. Waste name: CHLOROBENZENE

. Waste code: D022
. Waste name: CHLOROFORM

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: D038
. Waste name: PYRIDINE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLOROETHYLENE

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND

STATE UNIVERSITY OF NEW YORK AT BUFFALO S CAMPUS (Continued) **1000397714**

SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: LABP
. Waste name: LAB PACK

. Waste code: P030
. Waste name: CYANIDES (SOLUBLE CYANIDE SALTS), NOT OTHERWISE SPECIFIED

. Waste code: P042
. Waste name: 1,2-BENZENEDIOL, 4-[1-HYDROXY-2-(METHYLAMINO)ETHYL]-, (R)-

. Waste code: P087
. Waste name: OSMIUM OXIDE OSO4, (T-4)-

. Waste code: U002
. Waste name: ACETONE (I)

. Waste code: B004
. Waste name: B004

. Waste code: B007
. Waste name: B007

Date form received by agency: 01/31/2008
Site name: STATE UNIVERSITY OF NEW YORK AT BUFFALO
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

STATE UNIVERSITY OF NEW YORK AT BUFFALO S CAMPUS (Continued) **1000397714**

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D003
. Waste name: A MATERIAL IS CONSIDERED TO BE A REACTIVE HAZARDOUS WASTE IF IT IS NORMALLY UNSTABLE, REACTS VIOLENTLY WITH WATER, GENERATES TOXIC GASES WHEN EXPOSED TO WATER OR CORROSIVE MATERIALS, OR IF IT IS CAPABLE OF DETONATION OR EXPLOSION WHEN EXPOSED TO HEAT OR A FLAME. ONE EXAMPLE OF SUCH WASTE WOULD BY WASTE GUNPOWDER.

. Waste code: D004
. Waste name: ARSENIC

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D011
. Waste name: SILVER

. Waste code: D018
. Waste name: BENZENE

. Waste code: D022
. Waste name: CHLOROFORM

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLOROETHYLENE

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR

STATE UNIVERSITY OF NEW YORK AT BUFFALO S CAMPUS (Continued) **1000397714**

F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: LABP
. Waste name: LAB PACK

. Waste code: P030
. Waste name: CYANIDES (SOLUBLE CYANIDE SALTS), NOT OTHERWISE SPECIFIED

. Waste code: P042
. Waste name: 1,2-BENZENEDIOL, 4-[1-HYDROXY-2-(METHYLAMINO)ETHYL]-, (R)-

. Waste code: P048
. Waste name: 2,4-DINITROPHENOL

. Waste code: P087
. Waste name: OSMIUM OXIDE OSO4, (T-4)-

. Waste code: P098
. Waste name: POTASSIUM CYANIDE

. Waste code: P119
. Waste name: AMMONIUM VANADATE

. Waste code: U002
. Waste name: ACETONE (I)

. Waste code: U003
. Waste name: ACETONITRILE (I,T)

. Waste code: B007
. Waste name: B007

Date form received by agency: 01/01/2007
Site name: STATE UNIVERSITY OF NEW YORK AT BUFFALO
Classification: Large Quantity Generator

STATE UNIVERSITY OF NEW YORK AT BUFFALO S CAMPUS (Continued) **1000397714**

Date form received by agency: 02/16/2006
Site name: STATE UNIVERSITY OF NEW YORK AT BUFFALO
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D003
. Waste name: A MATERIAL IS CONSIDERED TO BE A REACTIVE HAZARDOUS WASTE IF IT IS NORMALLY UNSTABLE, REACTS VIOLENTLY WITH WATER, GENERATES TOXIC GASES WHEN EXPOSED TO WATER OR CORROSIVE MATERIALS, OR IF IT IS CAPABLE OF DETONATION OR EXPLOSION WHEN EXPOSED TO HEAT OR A FLAME. ONE EXAMPLE OF SUCH WASTE WOULD BY WASTE GUNPOWDER.

. Waste code: D004
. Waste name: ARSENIC

. Waste code: D005
. Waste name: BARIUM

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D010
. Waste name: SELENIUM

. Waste code: D011
. Waste name: SILVER

. Waste code: D018
. Waste name: BENZENE

. Waste code: D019

STATE UNIVERSITY OF NEW YORK AT BUFFALO S CAMPUS (Continued) **1000397714**

. Waste name: CARBON TETRACHLORIDE

. Waste code: D021
. Waste name: CHLOROBENZENE

. Waste code: D022
. Waste name: CHLOROFORM

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: D038
. Waste name: PYRIDINE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLOROETHYLENE

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: LABP
. Waste name: LAB PACK

. Waste code: P028
. Waste name: BENZENE, (CHLOROMETHYL)-

STATE UNIVERSITY OF NEW YORK AT BUFFALO S CAMPUS (Continued) **1000397714**

. Waste code: P030
. Waste name: CYANIDES (SOLUBLE CYANIDE SALTS), NOT OTHERWISE SPECIFIED

. Waste code: P077
. Waste name: BENZENAMINE, 4-NITRO-

. Waste code: P087
. Waste name: OSMIUM OXIDE OSO4, (T-4)-

. Waste code: P098
. Waste name: POTASSIUM CYANIDE

. Waste code: U001
. Waste name: ACETALDEHYDE (I)

. Waste code: U002
. Waste name: ACETONE (I)

. Waste code: U003
. Waste name: ACETONITRILE (I,T)

. Waste code: U007
. Waste name: ACRYLAMIDE

. Waste code: U009
. Waste name: ACRYLONITRILE

. Waste code: U012
. Waste name: ANILINE (I,T)

. Waste code: U029
. Waste name: METHANE, BROMO-

. Waste code: U044
. Waste name: CHLOROFORM

. Waste code: U068
. Waste name: METHANE, DIBROMO-

. Waste code: U077
. Waste name: ETHANE, 1,2-DICHLORO-

. Waste code: U080
. Waste name: METHANE, DICHLORO-

. Waste code: U108
. Waste name: 1,4-DIETHYLENEOXIDE

. Waste code: U122
. Waste name: FORMALDEHYDE

. Waste code: U123
. Waste name: FORMIC ACID (C,T)

. Waste code: U136
. Waste name: ARSINIC ACID, DIMETHYL-

STATE UNIVERSITY OF NEW YORK AT BUFFALO S CAMPUS (Continued) **1000397714**

. Waste code: U140
. Waste name: ISOBUTYL ALCOHOL (I,T)

. Waste code: U161
. Waste name: METHYL ISOBUTYL KETONE (I)

. Waste code: U169
. Waste name: BENZENE, NITRO-

. Waste code: U188
. Waste name: PHENOL

. Waste code: U196
. Waste name: PYRIDINE

. Waste code: U201
. Waste name: 1,3-BENZENEDIOL

. Waste code: U207
. Waste name: BENZENE, 1,2,4,5-TETRACHLORO-

. Waste code: U208
. Waste name: ETHANE, 1,1,1,2-TETRACHLORO-

. Waste code: U210
. Waste name: ETHENE, TETRACHLORO-

. Waste code: U211
. Waste name: CARBON TETRACHLORIDE

. Waste code: U220
. Waste name: BENZENE, METHYL-

. Waste code: U226
. Waste name: ETHANE, 1,1,1-TRICHLORO-

. Waste code: U228
. Waste name: ETHENE, TRICHLORO-

. Waste code: U239
. Waste name: BENZENE, DIMETHYL- (I,T)

. Waste code: U246
. Waste name: CYANOGEN BROMIDE (CN)BR

. Waste code: U404
. Waste name: ETHANAMINE, N,N-DIETHYL- (OR) TRIETHYLAMINE

Date form received by agency: 02/15/2006
Site name: STATE UNIVERSITY OF NEW YORK AT BUFFALO
Classification: Large Quantity Generator

Date form received by agency: 06/01/2004
Site name: STATE UNIVERSITY OF NEW YORK AT BUFFALO
Classification: Large Quantity Generator

. Waste code: D001

STATE UNIVERSITY OF NEW YORK AT BUFFALO S CAMPUS (Continued) **1000397714**

. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D003
. Waste name: A MATERIAL IS CONSIDERED TO BE A REACTIVE HAZARDOUS WASTE IF IT IS NORMALLY UNSTABLE, REACTS VIOLENTLY WITH WATER, GENERATES TOXIC GASES WHEN EXPOSED TO WATER OR CORROSIVE MATERIALS, OR IF IT IS CAPABLE OF DETONATION OR EXPLOSION WHEN EXPOSED TO HEAT OR A FLAME. ONE EXAMPLE OF SUCH WASTE WOULD BY WASTE GUNPOWDER.

. Waste code: D004
. Waste name: ARSENIC

. Waste code: D005
. Waste name: BARIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D011
. Waste name: SILVER

. Waste code: D022
. Waste name: CHLOROFORM

. Waste code: D026
. Waste name: CRESOL

. Waste code: D038
. Waste name: PYRIDINE

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING,

STATE UNIVERSITY OF NEW YORK AT BUFFALO S CAMPUS (Continued) **1000397714**

BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: P003
. Waste name: ACROLEIN

. Waste code: P028
. Waste name: BENZENE, (CHLOROMETHYL)-

. Waste code: P030
. Waste name: CYANIDES (SOLUBLE CYANIDE SALTS), NOT OTHERWISE SPECIFIED

. Waste code: P054
. Waste name: AZIRIDINE

. Waste code: P075
. Waste name: NICOTINE, & SALTS

. Waste code: P077
. Waste name: BENZENAMINE, 4-NITRO-

. Waste code: P087
. Waste name: OSMIUM OXIDE OSO4, (T-4)-

. Waste code: P098
. Waste name: POTASSIUM CYANIDE

. Waste code: P104
. Waste name: SILVER CYANIDE

. Waste code: P106
. Waste name: SODIUM CYANIDE

. Waste code: U002
. Waste name: ACETONE (I)

. Waste code: U007
. Waste name: ACRYLAMIDE

. Waste code: U012
. Waste name: ANILINE (I,T)

. Waste code: U021
. Waste name: BENZIDINE

. Waste code: U069

STATE UNIVERSITY OF NEW YORK AT BUFFALO S CAMPUS (Continued) **1000397714**

. Waste name: 1,2-BENZENEDICARBOXYLIC ACID, DIBUTYL ESTER

. Waste code: U102
. Waste name: 1,2-BENZENEDICARBOXYLIC ACID, DIMETHYL ESTER

. Waste code: U112
. Waste name: ACETIC ACID ETHYL ESTER (I)

. Waste code: U117
. Waste name: ETHANE, 1,1'-OXYBIS-(I)

. Waste code: U122
. Waste name: FORMALDEHYDE

. Waste code: U123
. Waste name: FORMIC ACID (C,T)

. Waste code: U133
. Waste name: HYDRAZINE (R,T)

. Waste code: U147
. Waste name: 2,5-FURANDIONE

. Waste code: U151
. Waste name: MERCURY

. Waste code: U162
. Waste name: METHYL METHACRYLATE (I,T)

. Waste code: U170
. Waste name: P-NITROPHENOL

. Waste code: U188
. Waste name: PHENOL

. Waste code: U190
. Waste name: 1,3-ISOBENZOFURANDIONE

. Waste code: U201
. Waste name: 1,3-BENZENEDIOL

. Waste code: U226
. Waste name: ETHANE, 1,1,1-TRICHLORO-

. Waste code: U238
. Waste name: CARBAMIC ACID, ETHYL ESTER

. Waste code: U246
. Waste name: CYANOGEN BROMIDE (CN)BR

. Waste code: U404
. Waste name: ETHANAMINE, N,N-DIETHYL- (OR) TRIETHYLAMINE

Date form received by agency: 02/28/2002
Site name: STATE UNIVERSITY OF NEW YORK AT BUFFALO
Classification: Large Quantity Generator

STATE UNIVERSITY OF NEW YORK AT BUFFALO S CAMPUS (Continued) **1000397714**

Date form received by agency: 01/01/2001
Site name: STATE UNIVERSITY OF NEW YORK @ BUFFALO
Classification: Large Quantity Generator

Date form received by agency: 01/22/1998
Site name: ST UNIVERSITY OF NY AT BUFFALO S CAMPUS
Classification: Large Quantity Generator

Date form received by agency: 02/21/1996
Site name: STATE UNIVERSITY OF NEW YORK AT BUFFALO
Classification: Large Quantity Generator

Date form received by agency: 03/24/1994
Site name: STATE UNIV OF NEW YORK AT BUFFALO
Classification: Large Quantity Generator

Date form received by agency: 02/26/1992
Site name: STATE UNIVERSITY OF NY
Classification: Large Quantity Generator

Date form received by agency: 03/01/1990
Site name: STATE UNIVERSITY OF N.Y. AT BUFFALO
Classification: Large Quantity Generator

Date form received by agency: 08/01/1980
Site name: STATE UNIVERSITY OF NY AT BUFFALO
Classification: Large Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Biennial Reports:

Last Biennial Reporting Year: 2017

Annual Waste Handled:
Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE

STATE UNIVERSITY OF NEW YORK AT BUFFALO S CAMPUS (Continued) **1000397714**

FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.
Amount (Lbs): 8370

Waste code: D002
Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.
Amount (Lbs): 4820

Waste code: D003
Waste name: A MATERIAL IS CONSIDERED TO BE A REACTIVE HAZARDOUS WASTE IF IT IS NORMALLY UNSTABLE, REACTS VIOLENTLY WITH WATER, GENERATES TOXIC GASES WHEN EXPOSED TO WATER OR CORROSIVE MATERIALS, OR IF IT IS CAPABLE OF DETONATION OR EXPLOSION WHEN EXPOSED TO HEAT OR A FLAME. ONE EXAMPLE OF SUCH WASTE WOULD BY WASTE GUNPOWDER.
Amount (Lbs): 4820

Waste code: D004
Waste name: ARSENIC
Amount (Lbs): 4820

Waste code: D005
Waste name: BARIUM
Amount (Lbs): 4820

Waste code: D006
Waste name: CADMIUM
Amount (Lbs): 4820

Waste code: D007
Waste name: CHROMIUM
Amount (Lbs): 4820

Waste code: D008
Waste name: LEAD
Amount (Lbs): 7095

Waste code: D009
Waste name: MERCURY
Amount (Lbs): 4820

Waste code: D010
Waste name: SELENIUM
Amount (Lbs): 4820

Waste code: D018
Waste name: BENZENE
Amount (Lbs): 1300

Waste code: D019

STATE UNIVERSITY OF NEW YORK AT BUFFALO S CAMPUS (Continued) **1000397714**

Waste name: CARBON TETRACHLORIDE
Amount (Lbs): 150

Waste code: D022
Waste name: CHLOROFORM
Amount (Lbs): 1450

Waste code: D028
Waste name: 1,2-DICHLOROETHANE
Amount (Lbs): 150

Waste code: D029
Waste name: 1,1-DICHLOROETHYLENE
Amount (Lbs): 150

Waste code: D039
Waste name: TETRACHLOROETHYLENE
Amount (Lbs): 1450

Waste code: D040
Waste name: TRICHLOROETHYLENE
Amount (Lbs): 1450

Waste code: F002
Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Amount (Lbs): 1450

Waste code: F003
Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Amount (Lbs): 1450

Waste code: F005
Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Amount (Lbs): 1450

STATE UNIVERSITY OF NEW YORK AT BUFFALO S CAMPUS (Continued) **1000397714**

Waste code: LABP
Waste name: LAB PACK
Amount (Lbs): 2

Waste code: P087
Waste name: OSMIUM OXIDE OSO4, (T-4)-
Amount (Lbs): 2

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 03/31/1989
Date achieved compliance: 06/23/1989
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/28/1989
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 08/17/2017
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 09/23/2014
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

Evaluation date: 10/13/2011
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 03/26/2008
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 09/24/1999
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 03/31/1989

STATE UNIVERSITY OF NEW YORK AT BUFFALO S CAMPUS (Continued) **1000397714**

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 06/23/1989
Evaluation lead agency: State

US AIRS (AFS):
Envid: 1000397714
Region Code: 02
County Code: NY029
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
D and B Number: Not reported
Facility Site Name: SUNY AT BUFFALO - SOUTH CAMPUS, BAKER
Primary SIC Code: 8221
NAICS Code: 611310
Default Air Classification Code: SMI
Facility Type of Ownership Code: Not reported
Air CMS Category Code: SMI
HPV Status: Not reported

US AIRS (AFS):
Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2002-09-27 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2002-09-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2007-08-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02

STATE UNIVERSITY OF NEW YORK AT BUFFALO S CAMPUS (Continued) **1000397714**

Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2007-09-04 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2012-09-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: New Source Performance Standards
Activity Date: 2002-09-27 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: New Source Performance Standards
Activity Date: 2002-09-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: New Source Performance Standards
Activity Date: 2007-08-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation

STATE UNIVERSITY OF NEW YORK AT BUFFALO S CAMPUS (Continued) **1000397714**

Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: New Source Performance Standards
Activity Date: 2007-09-04 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: New Source Performance Standards
Activity Date: 2012-09-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1977-01-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1979-08-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1980-12-10 00:00:00

STATE UNIVERSITY OF NEW YORK AT BUFFALO S CAMPUS (Continued) **1000397714**

Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1981-12-09 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1982-11-19 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1983-07-08 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1983-11-18 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR

STATE UNIVERSITY OF NEW YORK AT BUFFALO S CAMPUS (Continued) **1000397714**

Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1984-05-25 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1984-10-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1985-04-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1985-11-26 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1986-11-18 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02

STATE UNIVERSITY OF NEW YORK AT BUFFALO S CAMPUS (Continued) **1000397714**

Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1988-01-15 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1989-01-27 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1989-11-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1991-01-15 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1992-11-13 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation

STATE UNIVERSITY OF NEW YORK AT BUFFALO S CAMPUS (Continued) **1000397714**

Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1997-09-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1999-02-02 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2002-09-27 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2002-09-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2007-08-28 00:00:00

STATE UNIVERSITY OF NEW YORK AT BUFFALO S CAMPUS (Continued) **1000397714**

Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2007-09-04 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2012-09-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1979-03-14 00:00:00
Activity Status Date: 1979-03-14 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Envid: 1000397714
Region Code: 02
County Code: NY029
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
D and B Number: Not reported
Facility Site Name: SUNY AT BUFFALO - SOUTH CAMPUS, BAKER
Primary SIC Code: 8221
NAICS Code: 221112
Default Air Classification Code: SMI
Facility Type of Ownership Code: Not reported
Air CMS Category Code: SMI
HPV Status: Not reported

US AIRS (AFS):
Region Code: 02

STATE UNIVERSITY OF NEW YORK AT BUFFALO S CAMPUS (Continued) **1000397714**

Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2002-09-27 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2002-09-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2007-08-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2007-09-04 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2012-09-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation

STATE UNIVERSITY OF NEW YORK AT BUFFALO S CAMPUS (Continued) **1000397714**

Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: New Source Performance Standards
Activity Date: 2002-09-27 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: New Source Performance Standards
Activity Date: 2002-09-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: New Source Performance Standards
Activity Date: 2007-08-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: New Source Performance Standards
Activity Date: 2007-09-04 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: New Source Performance Standards
Activity Date: 2012-09-28 00:00:00

STATE UNIVERSITY OF NEW YORK AT BUFFALO S CAMPUS (Continued) **1000397714**

Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1977-01-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1979-08-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1980-12-10 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1981-12-09 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR

STATE UNIVERSITY OF NEW YORK AT BUFFALO S CAMPUS (Continued) **1000397714**

Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1982-11-19 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1983-07-08 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1983-11-18 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1984-05-25 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1984-10-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02

STATE UNIVERSITY OF NEW YORK AT BUFFALO S CAMPUS (Continued) **1000397714**

Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1985-04-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1985-11-26 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1986-11-18 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1988-01-15 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1989-01-27 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation

STATE UNIVERSITY OF NEW YORK AT BUFFALO S CAMPUS (Continued) **1000397714**

Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1989-11-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1991-01-15 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1992-11-13 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1997-09-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1999-02-02 00:00:00

STATE UNIVERSITY OF NEW YORK AT BUFFALO S CAMPUS (Continued) **1000397714**

Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2002-09-27 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2002-09-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2007-08-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2007-09-04 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009140200680
Facility Registry ID: 110000880100
Air Operating Status Code: OPR

STATE UNIVERSITY OF NEW YORK AT BUFFALO S CAMPUS (Continued) **1000397714**

Default Air Classification Code:	SMI
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	2012-09-28 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported
Region Code:	02
Programmatic ID:	AIR NY0000009140200680
Facility Registry ID:	110000880100
Air Operating Status Code:	OPR
Default Air Classification Code:	SMI
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	1979-03-14 00:00:00
Activity Status Date:	1979-03-14 00:00:00
Activity Group:	Enforcement Action
Activity Type:	Administrative - Informal
Activity Status:	Achieved

WI MANIFEST:

Year:	2004
EPA ID:	NYD071475867
FID:	0
ACT Code:	201
ACT Status:	A
ACT Code 1:	201
ACT Name:	HW Generator - Large
Contact Title:	Not reported
Contact Name:	Not reported
Contact Address:	Not reported
Contact City/State/Zip:	Not reported
Contact Telephone:	Not reported
Contact EMail Address:	Not reported

AP202 **UB - SOUTH CAMPUS** **NY Spills** **S108059213**
NW **MAIN** **N/A**
< 1/8 **BUFFALO, NY**
0.075 mi.
394 ft. **Site 11 of 12 in cluster AP**

Actual:
657 ft.

Focus Map:
8

SPILLS:

Spill Number/Closed Date:	0650660 / 2006-07-21
Facility ID:	0650660
Facility Type:	ER
DER Facility ID:	317446
Site ID:	367454
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	1502
Spill Date:	2006-07-20
Investigator:	RJJONAK
Referred To:	Not reported
Reported to Dept:	2006-07-20

UB - SOUTH CAMPUS (Continued) **S108059213**

CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-07-21
Spill Record Last Update:	2006-07-21
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	Not reported
Contact Name:	AL SWAVY
DEC Memo:	"7/21/2006: A HYDRAULIC HOSE BROKE ON ONE OF THEIR PIECES OF EQUIPMENT SPILLING ~ 1GAL OF HYDRAULIC OIL ON THE GROUND...MAINTENANCE PERSONNAL SPREAD SPEEDI DRY ON THE SPILL AND SCRAPED UP THE AFFECTED AREA AND DISPOSED THE MATERIAL IN THEIR DUMPSTER,SINCE IT WAS A SMALL SPILL...THE SPILL HAS BEEN CLEANED UP AND PROPERLY DISPOSED OF...NO FURTHER ACTION NEEDED...SPILL CLOSED OUT. ***** NOTE,COMPUTER FILE ONLY *****"
Remarks:	"Failled hydraulic hose. LT 1 gallon lost. Located in campus bone yard. Speedy dry applied. Spill clean-up complete."

All Materials:

Site ID:	367454
Operable Unit ID:	1125371
Operable Unit:	01
Material ID:	2114884
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	1.00
Oxygenate:	False

203
East
< 1/8
0.076 mi.
400 ft.

OIL DUMPING AT ALLENHURST **NY Spills** **S102177538**
441 ALLENHURST ROAD **N/A**
AMHERST, NY

Actual:
605 ft.

Focus Map:
8

SPILLS:

Spill Number/Closed Date:	9007944 / 1990-11-08
Facility ID:	9007944
Facility Type:	ER
DER Facility ID:	119264
Site ID:	139601
DEC Region:	9
Spill Cause:	Deliberate
Spill Class:	Not reported
SWIS:	1522

OIL DUMPING AT ALLENHURST (Continued) **S102177538**

Spill Date:	1990-10-20
Investigator:	PRINGLE
Referred To:	Not reported
Reported to Dept:	1990-10-20
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Citizen
Cleanup Ceased:	1990-11-08
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1990-10-23
Spill Record Last Update:	1990-12-04
Spiller Name:	Not reported
Spiller Company:	J. PIATT
Spiller Address:	ALLENHURST ROAD
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MNP 11/08/90: MNP REVIEW OF FILE, NO RESPONCE. "
Remarks:	"OIL DUMPED IN DRIVEWAY"

All Materials:

Site ID:	139601
Operable Unit ID:	948577
Operable Unit:	01
Material ID:	431776
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

204
West
< 1/8
0.076 mi.
402 ft.

Actual:
597 ft.

Focus Map:
6

CURTIS PARK U.P. CHURCH **NY UST** **U004272445**
748 WOODLAND DR **N/A**
KENMORE, NY 14223

UST:

Id/Status:	9-601738 / Unregistered
Program Type:	PBS
Region:	STATE
DEC Region:	9
Expiration Date:	N/A
UTM X:	Not reported
UTM Y:	Not reported
Site Type:	Religious Building (Church, Synagogue, Mosque, Temple, etc.)

Affiliation Records:

Site Id:	548800
Affiliation Type:	Facility Owner

CURTIS PARK U.P. CHURCH (Continued) **U004272445**

Company Name:	CURTIS PARK U.P. CHURCH
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	748 WOODLAND DR
Address2:	Not reported
City:	KENMORE
State:	NY
Zip Code:	14223
Country Code:	001
Phone:	(716) 834-3534
EMail:	Not reported
Fax Number:	Not reported
Modified By:	SRMCDONN
Date Last Modified:	2017-05-22

Site Id:	548800
Affiliation Type:	Mail Contact
Company Name:	CURTIS PARK U.P. CHURCH
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	748 WOODLAND DR
Address2:	Not reported
City:	KENMORE
State:	NY
Zip Code:	14223
Country Code:	001
Phone:	(716) 834-3534
EMail:	Not reported
Fax Number:	Not reported
Modified By:	SRMCDONN
Date Last Modified:	2017-05-22

Tank Info:

Tank Number:	1
Tank ID:	268398
Tank Status:	Unregistered
Material Name:	Unregistered
Capacity Gallons:	6800
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	SRMCDONN
Last Modified:	05/22/2017

205
NW
< 1/8
0.078 mi.
410 ft.

MORRIS AND REIMAN WRECKING
3900 RENSCH RD.
AMHERST, NY 14226

NY HSWDS **S108146696**
N/A

Actual:
601 ft.

Focus Map:
4

HSWDS:

Facility ID:	Not reported
Region:	9
Facility Status:	Unknown
Owner Type:	S
Owner:	NYSDOT
Owner Address:	Unknown
Owner Phone:	Unknown
Operator Type:	S
Operator:	Same
Operator:	Same
Operator Phone:	Same
EPA ID:	NYD980534770
Registry:	D
Registry Site ID:	915092
RCRA Permitted:	Unknown
Site Code:	Industrial Landfill
Owner City State:	Not reported
Operator City State:	Not reported
Quadrange:	Buffalo NE
Latitude:	42 59'26"N
Longitude:	78 47'57"W
Acres:	120.00
Operator Date:	1932
Close Date:	1972
Completed:	Phase 1
Active:	No
PCB's Disposed:	No
Pesticides Disposed:	No
Metals Disposed:	No
Asbestos Disposed:	No
Volatile Organic Compounds Disposed:	Yes
Semi Volatile Organic Compounds Disposed:	Yes
Analytical Info Exists for Air:	Not reported
Analytical Info Exists for Ground:	Groundwater
Analytical Info Exists for Surface:	Not reported
Analytical Info Exists for Sediments:	Not reported
Analytical Info Exists for Surface:	Not reported
Analytical Info Exists for Substance:	Soil
Analytical Info Exists for Waste:	Not reported
Analytical Info Exists for Leachate:	Not reported
Analytical Info Exists for EP Toxicity:	Not reported
Analytical Info Exists for TCLP:	Not reported
Threat to Environment/Public Health:	N
Surface Water Contamination:	Unknown
Surface Water Body Class:	Unknown
Groundwater Contamination:	Unknown
Groundwater Classification:	Unknown
Drinking Water Contamination:	Unknown
Drinking Water Supply is Active:	Unknown
Any Known Fish or Wildlife:	Unknown
Hazardous Exposure:	Unknown
Site Has Controlled Acess:	No

MORRIS AND REIMAN WRECKING (Continued) **S108146696**

Ambient Air Contamination:	No
Direct Contact:	Unknown
EPA Hazardous Ranking System Score:	0
Inventory:	F
Nefrap:	Not reported
Mailing:	Not reported
Tax Map No:	Not reported
Qualify:	0
Next Action:	Not reported
Agencies:	Not reported
Air:	Not reported
Building:	Not reported
Site Desc:	Not reported
Drink:	Not reported
Eptox:	Not reported
Fish:	Not reported
Ground:	Not reported
Ground Desc:	Not reported
Hazardous Threat:	Not reported
Haz Threat Desc:	Not reported
Leachate:	Not reported
Preparer:	Not reported
Sediment:	Not reported
Soil:	Not reported
Surface:	Not reported
Status:	Not reported
Surface Soil:	Not reported
Surface:	Not reported
TCLP:	Not reported
Waste:	Not reported

206
SW
< 1/8
0.078 mi.
411 ft.

HONEYWELL INC
251 JOHN JAMES AUDUBON PKWY
WEST AMHERST, NY 14228

RCRA NonGen / NLR **1001079787**
FINDS **NYR000014944**
ECHO
NY MANIFEST

Actual:
577 ft.

Focus Map:
2

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	HONEYWELL INC
Facility address:	251 JOHN JAMES AUDUBON PKWY WEST AMHERST, NY 14228
EPA ID:	NYR000014944
Mailing address:	N FRENCH RD SUITE 102 AMHERST, NY 14228-2090
Contact:	Not reported
Contact address:	N FRENCH RD SUITE 102 AMHERST, NY 14228-2090
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Land type:	Private
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

HONEYWELL INC (Continued) **1001079787**

Owner/operator name: J J GUMBERG CO
Owner/operator address: 1051 BRINTON RD
PITTSBURGH, PA 15221
Owner/operator country: US
Owner/operator telephone: 412-244-4068
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: J J GUMBERG CO
Owner/operator address: 1051 BRINTON RD
PITTSBURGH, PA 15221
Owner/operator country: US
Owner/operator telephone: 412-244-4068
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: HONEYWELL INC
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: HONEYWELL INC
Classification: Not a generator, verified

Date form received by agency: 10/13/1995
Site name: HONEYWELL INC
Classification: Large Quantity Generator

HONEYWELL INC (Continued) **1001079787**

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 08/28/1998
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110004519398

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1001079787
Registry ID: 110004519398
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004519398

NY MANIFEST:
Country: USA
EPA ID: NYR000014944
Facility Status: Not reported
Location Address 1: 251 JOHN JAMES AUDOIBON PKWY
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported

HONEYWELL INC (Continued) **1001079787**

Location City:	WEST AMHERST
Location State:	NY
Location Zip:	14228
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000014944
Mailing Name:	HONEYWELL
Mailing Contact:	D BROSIUS
Mailing Address 1:	100 METRO PARK
Mailing Address 2:	Not reported
Mailing City:	ROCHESTER
Mailing State:	NY
Mailing Zip:	14623
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7162724322

NY MANIFEST:

Document ID:	CTF0263167
Manifest Status:	C
seq:	Not reported
Year:	1995
Trans1 State ID:	NYPR1561
Trans2 State ID:	654310
Generator Ship Date:	10/19/1995
Trans1 Recv Date:	10/19/1995
Trans2 Recv Date:	10/24/1995
TSD Site Recv Date:	11/01/1995
Part A Recv Date:	10/27/1995
Part B Recv Date:	11/13/1995
Generator EPA ID:	NYR000014944
Trans1 EPA ID:	MAD039322250
Trans2 EPA ID:	MAD039322250
TSDF ID 1:	CTD000604488
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00035
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001

HONEYWELL INC (Continued) **1001079787**

Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00090
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AP207 **STATE UNIVERSTIY CONSTRUCTION FUND** **FINDS 1016199271**
NW **SUNY AT BUFFALO 3435 MAIN ST** **ECHO N/A**
< 1/8 **BUFFALO, NY 14214**
0.080 mi.
424 ft. **Site 12 of 12 in cluster AP**

Actual:
656 ft.

Focus Map:
8

FINDS:

Registry ID: 110004392416

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access
additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016199271
Registry ID:	110004392416
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004392416

AQ208 **TOTAL AUTOMOTIVE INC** **EDR Hist Auto** **1020135616**
East **2125 EGGERT RD** **N/A**
< 1/8 **BUFFALO, NY 14226**
0.084 mi.
445 ft. **Site 3 of 5 in cluster AQ**

Actual: EDR Hist Auto
597 ft.

Focus Map:
6

Year:	Name:	Type:
1972	NORTHTOWN AUTO WASH INC	Carwashes
1973	NORTHTOWN AUTO WASH INC	Carwashes
1974	NORTHTOWN AUTO WASH INC	Carwashes
1975	NORTHTOWN AUTO WASH INC	Carwashes
1988	GAS RITE	Carwashes
1989	GAS RITE	Carwashes
1990	GAS RITE	Carwashes
1991	GAS RITE	Carwashes
1992	GAS RITE	Carwashes
1993	GAS RITE	Carwashes
1994	GAS RITE	Carwashes
1999	BUFFALO DISC MUFFLER & BRAKE	Automotive Repair Shops, NEC
2000	BUFFALO DISC MUFFLER & BRAKE	Automotive Repair Shops, NEC
2001	TOTAL AUTOMOTIVE INC	Automotive Repair Shops, NEC
2002	TOTAL AUTOMOTIVE INC	Automotive Repair Shops, NEC
2003	TOTAL AUTOMOTIVE INC	Automotive Repair Shops, NEC
2004	TOTAL AUTOMOTIVE INC	Automotive Repair Shops, NEC
2005	TOTAL AUTOMOTIVE INC	Automotive Repair Shops, NEC
2006	TOTAL AUTOMOTIVE INC	Automotive Repair Shops, NEC
2007	TOTAL AUTOMOTIVE INC	Automotive Repair Shops, NEC
2008	TOTAL AUTOMOTIVE INC	Automotive Repair Shops, NEC
2009	TOTAL AUTOMOTIVE INC	Automotive Repair Shops, NEC
2010	TOTAL AUTOMOTIVE INC	Automotive Repair Shops, NEC
2011	TOTAL AUTOMOTIVE INC	Automotive Repair Shops, NEC
2012	TOTAL AUTOMOTIVE INC	Automotive Repair Shops, NEC
2013	TOTAL AUTOMOTIVE INC	Automotive Repair Shops, NEC
2014	TOTAL AUTOMOTIVE INC	Automotive Repair Shops, NEC

AQ209 **NORTHTOWN PLAZA CAR WASH** **NY UST** **U001327543**
East **2125 EGGERT RD** **N/A**
< 1/8 **AMHERST, NY 14226**
0.084 mi.
445 ft. **Site 4 of 5 in cluster AQ**

Actual: UST:
597 ft.

Focus Map:
6

Id/Status:	9-221295 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	9
Expiration Date:	N/A
UTM X:	188446.40592
UTM Y:	4765624.09299
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	52979
Affiliation Type:	Facility Owner
Company Name:	NORTH TOWN INC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	3097 SHERIDAN DR

NORTHTOWN PLAZA CAR WASH (Continued) **U001327543**

Address2:	Not reported
City:	AMHERST
State:	NY
Zip Code:	14226
Country Code:	001
Phone:	(716) 836-6603
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	52979
Affiliation Type:	Mail Contact
Company Name:	NORTH TOWN INC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	3097 SHERIDAN DR
Address2:	Not reported
City:	AMHERST
State:	NY
Zip Code:	14226
Country Code:	001
Phone:	(716) 836-6603
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	52979
Affiliation Type:	Facility Operator
Company Name:	NORTHTOWN PLAZA CAR WASH
Contact Type:	Not reported
Contact Name:	ORCHARD PARK CAR WASH INC
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(716) 833-1770
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	52979
Affiliation Type:	Emergency Contact
Company Name:	NORTH TOWN INC
Contact Type:	Not reported
Contact Name:	CHARLES MATTELIANO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(716) 832-2251

NORTHTOWN PLAZA CAR WASH (Continued) **U001327543**

EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Tank Info:

Tank Number: 1
Tank ID: 163327
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 8000
Install Date: Not reported
Date Tank Closed: 10/01/1995
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 05
Date Test: 10/01/1991
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
K01 - Spill Prevention - Catch Basin
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
A00 - Tank Internal Protection - None
G07 - Tank Secondary Containment - Excavation Liner

Tank Number: 2
Tank ID: 163328
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 8000
Install Date: Not reported
Date Tank Closed: 10/01/1995
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 05
Date Test: 10/01/1991
Next Test Date: Not reported
Pipe Model: Not reported

NORTHTOWN PLAZA CAR WASH (Continued) **U001327543**

Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

I00 - Overfill - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
A00 - Tank Internal Protection - None
G07 - Tank Secondary Containment - Excavation Liner
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Number: 3
Tank ID: 163329
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 8000
Install Date: Not reported
Date Tank Closed: 10/01/1995
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 05
Date Test: 10/01/1991
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H04 - Tank Leak Detection - Groundwater Well
J01 - Dispenser - Pressurized Dispenser
I00 - Overfill - None
K01 - Spill Prevention - Catch Basin

AQ210 **POLE 2109** **NY Spills** **S108295036**
East **2125 EGGERT RD** **N/A**
< 1/8 **AMHERST, NY**
0.084 mi.
445 ft. **Site 5 of 5 in cluster AQ**

Actual:
597 ft.

Focus Map:
6

SPILLS:
Spill Number/Closed Date: 0608552 / 2006-10-27
Facility ID: 0608552
Facility Type: ER
DER Facility ID: 321681
Site ID: 372550

POLE 2109 (Continued) **S108295036**

DEC Region:	9
Spill Cause:	Other
Spill Class:	C4
SWIS:	1522
Spill Date:	2006-10-26
Investigator:	RJJONAK
Referred To:	Not reported
Reported to Dept:	2006-10-26
CID:	410
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-10-26
Spill Record Last Update:	2006-10-27
Spiller Name:	LISA FREDERICKS
Spiller Company:	SOIL AND PAVEMENT / REAR
Spiller Address:	2125 EGGERT RD
Spiller Company:	001
Contact Name:	LISA FREDERICKS
DEC Memo:	"10/26/2006: THIS IS THE SAME SPILL AS SPILL# 0608071...REFER TO THAT SPILL FOR ANY INFORMATION...THIS SPILL CLOSED OUT. ***** NOTE,COMPUTER FILE ONLY *****"
Remarks:	"SPILL IS RESULT OF RECENT STORM: MATERIAL IS AT THE REAR OF A PARKING LOT AT THIS LOCATION / COMMERCIAL BUSINESS LOT: CLEAN UP CREW IN ROUTE:"

All Materials:

Site ID:	372550
Operable Unit ID:	1130288
Operable Unit:	01
Material ID:	2119961
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	0608071 / 2007-02-14
Facility ID:	0608071
Facility Type:	ER
DER Facility ID:	321681
Site ID:	371946
DEC Region:	9
Spill Cause:	Other
Spill Class:	C3
SWIS:	1522
Spill Date:	2006-10-15
Investigator:	RJJONAK

POLE 2109 (Continued) **S108295036**

Referred To:	Not reported
Reported to Dept:	2006-10-15
CID:	41
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-10-16
Spill Record Last Update:	2007-02-14
Spiller Name:	Not reported
Spiller Company:	NATL GRID
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	LISA FREDERICKS
DEC Memo:	"10/18/2006: RJJ AT SITE AT 0900...DUE TO THE SNOWSTORM,A 3-PHASE POLETOP TRANSFORMER FELL ON THE PARKING LOT,SPILLING ~20 GAL OF NON-PCB OIL ALL THE PAVEMENT...NATIONAL GRID HIRED OP-TECH TO CONTAIN,CLEAN UP,AND DISPOSE THE MATERIAL...NONE OF THE OIL REACHED ANY RECEIVERS OR SOIL,IT WAS ALL CONTAINED ON THE PAVEMENT...OP-TECH WILL SEND ME THE DISPOSAL RECEIPTS. 2/14/2007; RECEIVED THE FINAL REPORT FROM NATIONAL GRID,WHICH INCLUDES THE DISPOSAL RECEIPTS FOR 1-55 DRUM OF MATERIAL TAKEN TO OP-TECH'S WAVERLY LANDFILL...THE SPILL HAS BEEN CLEANED UP AND PROPERLY DISPOSED OF...NO FURTHER ACTION NEEDED...SPILL CLOSED OUT...(REFER TO SPILL # 0607997 FOR ANY INFORMATION)"
Remarks:	"STORM-RELATED - CREW ENROUTE"

All Materials:

Site ID:	371946
Operable Unit ID:	1129695
Operable Unit:	01
Material ID:	2119360
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	21.00
Units:	G
Recovered:	21.00
Oxygenate:	Not reported

AR211 **SEARS #1162** **RCRA-CESQG 1012186655**
East **1261 NIAGARA FALLS BLVD** **NY MANIFEST NYR000165175**
< 1/8 **AMHERST, NY 14226**
0.084 mi.
446 ft. **Site 1 of 3 in cluster AR**

Actual:
591 ft.

Focus Map:
6

RCRA-CESQG:

Date form received by agency:	05/21/2009
Facility name:	SEARS #1162
Facility address:	1261 NIAGARA FALLS BLVD AMHERST, NY 14226

SEARS #1162 (Continued) **1012186655**

EPA ID: NYR000165175
Mailing address: BEVERLY RD B5-348A
HOFFMAN ESTATES, IL 60179
Contact: DAWN A JESS
Contact address: BEVERLY RD B5-348A
HOFFMAN ESTATES, IL 60179
Contact country: US
Contact telephone: 847-286-8616
Telephone ext.: 68616
Contact email: DJESS1@SEARSHC.COM
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:
Owner/operator name: SEARS #1162
Owner/operator address: Not reported
Not reported
Owner/operator country: Not reported
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 08/19/2000
Owner/Op end date: Not reported

Owner/operator name: BOULEVARD MALL EXPANSION LLC
Owner/operator address: TERMINAL TOWER 50 PUBLIC SQUARE
CLEVELAND, OH 44113
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 08/16/2000
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No

SEARS #1162 (Continued) **1012186655**

Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYR000165175
Facility Status: Not reported
Location Address 1: 1261 NIAGARA FALLS BLVD
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: AMHERST
Location State: NY
Location Zip: 14226
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000165175
Mailing Name: SEARS #1162
Mailing Contact: SEARS #1162
Mailing Address 1: 1261 NIAGARA FALLS BLVD
Mailing Address 2: Not reported
Mailing City: AMHERST
Mailing State: NY
Mailing Zip: 14226
Mailing Zip 4: Not reported

SEARS #1162 (Continued) **1012186655**

Mailing Country: USA
Mailing Phone: 7164465100

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2017
Trans1 State ID: MNS000110924
Trans2 State ID: MID021087275
Generator Ship Date: 04/04/2017
Trans1 Recv Date: 04/04/2017
Trans2 Recv Date: 04/13/2017
TSD Site Recv Date: 04/18/2017
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000165175
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: MID980615298
TSDF ID 2: Not reported
Manifest Tracking Number: 009265844FLE
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H141
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 14
Units: P - Pounds
Number of Containers: 1
Container Type: BA - Burlap, plastic, paper bags
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1
Waste Code: Not reported
Waste Code 1_2: D001
Waste Code 1_3: Not reported
Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

Country: USA
EPA ID: NYR000209254
Facility Status: Not reported
Location Address 1: 1261 NIAGARA FALLS BLVD

SEARS #1162 (Continued) **1012186655**

Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	AMHERST
Location State:	NY
Location Zip:	14226
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000209254
Mailing Name:	BYE BYE BABY #3083
Mailing Contact:	BB&B C/O PSC ATTN: BB&B CSR
Mailing Address 1:	5151 SAN FELIPE
Mailing Address 2:	BYE 3083
Mailing City:	AMHERST
Mailing State:	NY
Mailing Zip:	14226
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	MNS000110924
Trans2 State ID:	Not reported
Generator Ship Date:	03/13/2018
Trans1 Recv Date:	03/13/2018
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/16/2018
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000209254
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	MID980615298
TSDF ID 2:	Not reported
Manifest Tracking Number:	001800280PSC
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

SEARS #1162 (Continued) **1012186655**

Quantity:	27
Units:	P - Pounds
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	D006
Waste Code 1_2:	D008
Waste Code 1_3:	D011
Waste Code 1_4:	D016
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
9 additional NY MANIFEST: record(s) in the EDR Site Report.

AR212 **BYE BYE BABY #3083** **RCRA-CESQG 1016678178**
East **1261 NIAGARA FALLS BLVD** **FINDS NYR000209254**
< 1/8 **AMHERST, NY 14226** **ECHO**
0.084 mi.
446 ft. **Site 2 of 3 in cluster AR**

Actual:
591 ft.

Focus Map:
6

RCRA-CESQG:

Date form received by agency:	04/21/2014
Facility name:	BYE BYE BABY #3083
Facility address:	1261 NIAGARA FALLS BLVD AMHERST, NY 14226
EPA ID:	NYR000209254
Mailing address:	SAN FELIPE ST SUITE 1100 HOUSTON, TX 77056
Contact:	CHRIS BAKER
Contact address:	SAN FELIPE ST SUITE 1100 HOUSTON, TX 77056
Contact country:	US
Contact telephone:	713-625-7015
Contact email:	CHRIS.BAKER@PSCNOW.COM
EPA Region:	02
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	BUY BUY BABY #3083
Owner/operator address:	Not reported

BYE BYE BABY #3083 (Continued) **1016678178**

Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 01/04/2011
Owner/Op end date: Not reported

Owner/operator name: BYE BYE BABY INC
Owner/operator address: LIBERTY AVE
UNION, NJ 07083
Owner/operator country: US
Owner/operator telephone: 908-855-4517
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/04/2011
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE

BYE BYE BABY #3083 (Continued) **1016678178**

DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D005
. Waste name: BARIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

Violation Status: No violations found

FINDS:

Registry ID: 110059662618

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016678178
Registry ID: 110059662618
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110059662618

AR213 **SEARS #1162** **FINDS** **1012107884**
East **1261 NIAGARA FALLS BLVD** **ECHO** **N/A**
< 1/8 **AMHERST, NY 14226**
0.084 mi.
446 ft. **Site 3 of 3 in cluster AR**

Actual:
591 ft.

FINDS:

Focus Map:
6

Registry ID: 110038898967

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

SEARS #1162 (Continued) **1012107884**

ECHO:
- Envid: 1012107884
- Registry ID: 110038898967
- DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110038898967

AS214 **SIDE OF ROAD** **NY Spills** **S108955761**
North **145 MAYER RD** **N/A**
< 1/8 **AMHERST, NY**
0.087 mi.
461 ft. **Site 1 of 2 in cluster AS**

Actual:
581 ft.

Focus Map:
3

SPILLS:
- Spill Number/Closed Date: 0707774 / 2007-10-16
- Facility ID: 0707774
- Facility Type: ER
- DER Facility ID: 338062
- Site ID: 388537
- DEC Region: 9
- Spill Cause: Equipment Failure
- Spill Class: D4
- SWIS: 1522
- Spill Date: 2007-10-15
- Investigator: rmcrosse
- Referred To: Not reported
- Reported to Dept: 2007-10-15
- CID: 408
- Water Affected: Not reported
- Spill Source: Commercial Vehicle
- Spill Notifier: Responsible Party
- Cleanup Ceased: Not reported
- Cleanup Meets Std: True
- Last Inspection: Not reported
- Recommended Penalty: False
- UST Trust: False
- Remediation Phase: 0
- Date Entered In Computer: 2007-10-15
- Spill Record Last Update: 2007-10-16
- Spiller Name: LISA MONTSANO
- Spiller Company: SIDE OF ROAD
- Spiller Address: 145 MAYER RD
- Spiller Company: 001
- Contact Name: LISA MONTSANO
- DEC Memo: "10/16/078 RMC/FILE. AFTER HOURS SPILL, REPORTED TO BE CLEANED UP BY PRP. MINOR INCIDENT, NO SPILLS ACTION REQUIRED. CLOSE OUT. NO PAPER FILE. "
- Remarks: "CLEAN UP PENDING COMPLETION OF POLE REPLACEMENT; POLE REPLACEMENT CREW WILL CLEAN IT;"

All Materials:
- Site ID: 388537
- Operable Unit ID: 1145706
- Operable Unit: 01
- Material ID: 2136035
- Material Code: 0010
- Material Name: hydraulic oil
- Case No.: Not reported
- Material FA: Petroleum
- Quantity: 1.00

SIDE OF ROAD (Continued) **S108955761**

Units: G
Recovered: .00
Oxygenate: Not reported

AL215 **BELL ATLANTIC** **NY MANIFEST** **1009234743**
NW **MAIN ST & CAPEN BLVD** **N/A**
< 1/8 **BUFFALO, NY 14217**
0.090 mi.
475 ft. **Site 2 of 2 in cluster AL**

Actual:
655 ft.

Focus Map:
8

NY MANIFEST:
Country: USA
EPA ID: NYP000941245
Facility Status: Not reported
Location Address 1: MAIN ST & CAPEN BLVD
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BUFFALO
Location State: NY
Location Zip: 14217
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP000941245
Mailing Name: BELL ATLANTIC
Mailing Contact: JOHNNY ELSBERRY
Mailing Address 1: 221 EAST 37TH ST
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10016
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2123287126

NY MANIFEST:
Document ID: NJA2826833
Manifest Status: Not reported
seq: 01
Year: 1998
Trans1 State ID: S50060
Trans2 State ID: Not reported
Generator Ship Date: 07/30/1998
Trans1 Recv Date: 07/30/1998
Trans2 Recv Date: 08/10/1998
TSD Site Recv Date: 08/11/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP000941245
Trans1 EPA ID: NYD980761191
Trans2 EPA ID: NYD980761191
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported

BELL ATLANTIC (Continued) **1009234743**

Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00400
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	008
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

---

216 **KEATING JOS P GAS STA** **EDR Hist Auto** **1014537404**
WNW **3384 MAIN ST** **N/A**
< 1/8 **BUFFALO, NY**
0.093 mi.
490 ft.

Actual: EDR Hist Auto
655 ft.

Focus Map:
8

Year:	Name:	Type:
1930	MEILER BROS FILL STA	GASOLINE AND OIL SERVICE STATIONS
1940	HEWETT HARRY FILLING STA	GASOLINE AND OIL SERVICE STATIONS
1946	KEATING JOS P FILLING STA	GASOLINE AND OIL SERVICE STATIONS
1950	KEATING JOS P GAS STA	GASOLINE STATIONS
1955	KEATING JOS P GAS STA	GASOLINE STATIONS

---

217 **RESIDENCE** **NY Spills** **S109062397**
South **405 HOMECREST DRIVE** **N/A**
< 1/8 **AMHERST, NY**
0.099 mi.
524 ft.

Actual: SPILLS:
594 ft.

Focus Map:
7

Spill Number/Closed Date:	0801231 / 2008-04-30
Facility ID:	0801231
Facility Type:	ER
DER Facility ID:	346566
Site ID:	397121
DEC Region:	9
Spill Cause:	Unknown
Spill Class:	D5

RESIDENCE (Continued) **S109062397**

SWIS:	1522
Spill Date:	2008-04-30
Investigator:	sacaland
Referred To:	DEC - DIV OF SOLID & HAZ. MATERIALS/PESTICIDES
Reported to Dept:	2008-04-30
CID:	404
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-04-30
Spill Record Last Update:	2008-04-30
Spiller Name:	Not reported
Spiller Company:	FUNK LAWN CARE
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	JIM SLATTERY
DEC Memo:	"4/30/08:SAC SPOKE TO GLENN REINHARDT AND BRAD BROWN - DEC DIVISION OF SOLID AND HAZARDOUS MATERIALS, BUREAU OF PESTICIDES. GAVE THEM COPY OF SPILL REPORT. THEY WILL FOLLOW UP ON COMPLAINT TOMORROW. NO FURTHER WORK REQUIRED BY SPILLS. COMPUTER FILE ONLY."
Remarks:	"occured last week; some type of chemical that was being sprayed his lawn had gotten onto the siding of his home causing it to start melting and ruining the siding; believes that the lawn care company is responsible but does not want to own up to it;"

All Materials:

Site ID:	397121
Operable Unit ID:	1154078
Operable Unit:	01
Material ID:	2144865
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

218
West
< 1/8
0.099 mi.
524 ft.

NEW OPPORTUNITIES COMM. H **NY Spills** **S108294322**
245 HAWTHORNE AVE **N/A**
TONAWANDA, NY

Actual:
607 ft.

Focus Map:
8

SPILLS:

Spill Number/Closed Date:	0607131 / 2007-01-19
Facility ID:	0607131
Facility Type:	ER
DER Facility ID:	320431
Site ID:	370617

NEW OPPORTUNITIES COMM. H (Continued) **S108294322**

DEC Region:	9
Spill Cause:	Other
Spill Class:	B3
SWIS:	1564
Spill Date:	2006-09-20
Investigator:	SACALAND
Referred To:	Not reported
Reported to Dept:	2006-09-21
CID:	410
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	2006-11-30
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-09-21
Spill Record Last Update:	2007-01-19
Spiller Name:	JUDY SCOTT
Spiller Company:	NEW OPPORTUNITIES COMM. H
Spiller Address:	1195 MAIN STREET
Spiller Company:	001
Contact Name:	JUDY SCOTT
DEC Memo:	"10/26/06:SAC TELECON DOUG REID - LCS, INC. MR. REID SAID THE WAS WAITING FOR A RESPONSE FROM DEC REGARDING THE PROJECT AFTER SENDING IN THE PHASE II REPORT SINCE WORK IS TO BEGIN TOMORROW. SAC TOLD MR. REID THAT THE PHASE II REPORT HAS NOT BEEN RECEIVED. MR. REID SAID HE WILL SEND REPORT TO SAC. 10/27/06:SAC RECEIVED MESSAGE FROM ANDY KUCSERIK - LCS, INC. THAT HE IS WORKING AT THE SITE AND WAS REQUESTING AN INSPECTION. 10/27/06:SAC INSPECT SITE. MET W/ANDY KUCSERIK. PER MR. KUCSERIK PROJECT BEGAN A MONTH AGO. DURING THE EXCAVATION, SOME CONTAMINATION WAS OBSERVED COMING INTO IT. THEY STOPPED THE EXCAVATION AND SAMPLES WERE TAKEN. THE SAMPLES RESULTS WERE INCLUDED IN THE REPORT. AS THEY EXCAVATED, THEY BEGAN TO HIT A DEEPER AREA OF CONTAMINATION AWAY FROM THE ORIGINAL EXCAVATION. THEY DUG A TEST PIT IN ONE DIRECTION AND NO CONTAMINATION WAS OBSERVERD BY MR. KUCSERIK. THEY WILL CONTINUE TO WORK IN THIS AREA UNTIL THE ODORS ARE NO LONGER OBSERVED. MR. KUCSERIK SAID HE REGISTERRED 30 ppm ON HIS PID METER. SAC OBSERVED PETROLEUM ODORS WHILE STANDING NEXT TO THE EXCAVATION. THERE WAS NO APPARENT STAINING. SOILS DID APPEAR CLAYEY. MR. KUCSERIK SAID THERE IS STILL A CONCRETE SLAB ON THE SITE UNDERNEATH THE SOIL WHICH IS PROBABLY THE BASEMENT FLOOR. THEY WILL BE REMOVING THIS ALSO. ANOTHER LCS EMPLOYEE TO BE ONSITE MONDAY 10/30 WHEN WORK CONTINUES. 10/30/06:RECEIVED REPORT ON LIMITED AND FOCUSED SUBSURFACE INVESTIGATION. SAMPLES RESULTS WERE ABOVE STARS GUIDANCE FOR A FEW PARAMETERS AND TAGM GUIDANCE EXCEEDED ONLY FOR TICs. AREA WAS ALREADY EXCAVATED. SAC TELECON DOUG REID - LCS. MR. REID SAID JEFF ROWLEY ON SITE TODAY AND ABOUT 7 TRUCKLOADS WERE REMOVED FOR DISPOSAL. HE BELIEVES EXCAVATION WILL BE COMPLETED AT THE END OF THE DAY. CONFIRMATORY SAMPLES WILL BE TAKEN. THE CONCRETE SLAB THAT IS STILL AT SITE WILL BE REMOVED BY DEVELOPER AND LCS WILL CHECK TO SEE IF ANY CONTAMINATION IS UNDERNEATH SLAB. 10/31/06:SAC INSPECT SITE. NO ONE AND NO EQUIPMENT AT SITE. EXCAVATION WAS EXTENDED FROM FRIDAY 10/27. 11/14/06:SAC TELECON MATT FORCUCCI - NYSDOH NOTIFYING HIM OF THE SITE. 11/14/06:SAC TELECON DOUG REID. MR. REID SAID THEY

NEW OPPORTUNITIES COMM. H (Continued) **S108294322**

EXCAVATED UNTIL NO ODORS AND LOW PID METER READINGS WERE FOUND ON SIDEWALL. THERE WERE STILL ODORS AND PID METER READINGS AT THE BOTTOM OF THE HOLE WHERE THE CONCRETE SLAB WAS. THEY WILL REMOVE MORE SOIL UNDER SLAB AFTER CONTRACTOR REMOVES IT. MR. REID WILL SEND IN THE SAMPLE RESULTS WITH A SITE DRAWING OF THE SAMPLE LOCATIONS. 11/28/06:SAC TELECON DOUG REID. THEY ARE SCHEDULED TO REMOVE THE SLAB AND CONTINUE THE EXCAVATION ON NOV. 30TH. 11/29/06:RECEIVED THE ANALYTICAL RESULTS FROM THE INITAL EXCAVATION. RESULTS BELOW TAGM 4046 GUIDANCE VALUES. 11/30/06:SAC INSPECT SITE. MET W/DENNIS SULLIVAN - LCS, INC. AFTER REMOVING THE CONCRETE SLAB, THEY REMOVED SOIL TO AN APPROXIMATE DEPTH OF 12 FT. CONTRACTOR CONTINUING TO EXCAVATE ON THE STREET SIDE OF EXCAVATION AS ADDITIONAL MATERIAL IS REQUIRED TO BE REMOVED FOR DISPOSAL. AFTER FINAL TRUCKLOAD WAS TAKEN OFF SITE TO TONAWANDA LANDFILL, A TOTAL OF 500 TONS HAD BEEN REMOVED FROM THE SITE. THEREFORE ANOTHER WASTE CHARACTERIZATION SAMPLE NEEDS TO BE TAKEN FOR ANY MORE DISPOSAL TO TAKE PLACE. MR. SULLIVAN WAS GOING TO TAKE THIS SAMPLE AND SAID A 3 DAY TURNAROUND TIME WOULD BE REQUESTED. SO THE EARLIEST THE EXCAVATION WOULD CONTINUE WOULD BE LATER NEXT WEEK. 12/7/06:SAC TELECON DOUG REID. WASTE CHARACTERIZATION SAMPLE RESULTS STILL HAVE NOT BEEN RECEIVED SO THERE HAS BEEN NO ADDITIONAL EXCAVATION. MR. REID ANTICIPATES WORK WILL BEGIN NEXT WEEK. 12/19/06:RECEIVED PHONE MESSAGE FROM DOUG REID THAT WORK IS CONTINUING TODAY. 12/19/06:SAC INSPECT SITE. NO ONE AT SITE. ADDITIONAL SOIL WAS REMOVED. SAC TELECON DOUG REID. MR. REID SAID AN ADDITIONAL 100 TONS OF SOIL WERE REMOVED. THEY BELIEVE THEY HAVE COMPLETED THE REMEDIATION. LCS PERSONNEL OBSERVED NO ODORS AND THEIR PID METER REGISTERRED 7 ppm AT THE COMPLETION OF THE EXCAVATION. CONFIRMATORY SAMPLES WERE TAKEN. 1/9/07:SAC TELECON DOUG REID. MR. REID SAID HE WILL HAVE CLOSURE REPORT DELIVERED TO DEC AND DOH. 1/10/07:RECEIVED SPILL CLOSURE REPORT. 1/17/07;SAC TELECON MATT FORCUCCI - NYSDOH. DISCUSSED CLOSURE REPORT. MR. FORCUCCI DID NOT EXPRESS CONCERNS W/THE SITE BASED ON THE SUBMITTED REPORT. 1/19/07:REVIEWED SPILL CLOSURE REPORT. REPORT INCLUDES DISPOSAL RECEIPTS AND CONFIRMATORY SAMPLE RESULTS. SOME RESULTS WERE ABOVE STARS GUIDANCE BUT BELOW TAGM GUIDANCE VALUES. NO FURTHER WORK REQUIRED. DRAFT CLOSURE LETTER. "

Remarks: "CALLER REPORTS BEING HIRED TO COLLECT SAMPLES OF SOIL, ANALYTICAL DATA RECEIVED YESTERDAY 9/20/2006 SHOWS CONTAMINATED SOIL: MATERIAL IS FUEL OIL: THE PROPERTY WAS FORMERLY A PRIVATE DWELLILNG, BUT IS NOW OWNED BY NEW OPPORTUNITIES COMMUNITY HOUSING DEVELOPMENT CORPORATION:"

All Materials:

Site ID:	370617
Operable Unit ID:	1128412
Operable Unit:	01
Material ID:	2118025
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

219
West
< 1/8
0.104 mi.
549 ft.

TRANSFORMER HIT BY LIGHTNING
205 DALTON DRIVE
KENMORE, NY

NY Spills **S108057767**
N/A

Actual:
599 ft.

Focus Map:
6

SPILLS:

Spill Number/Closed Date:	0603288 / 2007-01-09
Facility ID:	0603288
Facility Type:	ER
DER Facility ID:	316058
Site ID:	365967
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	1564
Spill Date:	2006-06-25
Investigator:	SACALAND
Referred To:	Not reported
Reported to Dept:	2006-06-25
CID:	41
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-06-26
Spill Record Last Update:	2007-01-09
Spiller Name:	LISA MONTESANO
Spiller Company:	NATIONAL GRID
Spiller Address:	144 KENSINGTON AVENUE
Spiller Company:	001
Contact Name:	LISA FREDERICKS
DEC Memo:	"6/26/06:SAC TELECON LISA FREDERICKS. MS. FREDERICKS SAID THAT THE TRANSFORMER WAS LABELED NON-PCB BUT THE MANUFACTERER'S CERTIFICATION PLATE WITH THE SERIAL NUMBER IS WHAT WAS STRUCK BY LIGHTNING CAUSING THE MARKINGS TO BE ILLEGIBLE. TO MAKE SURE THE TRANSFORMER IS NON-PCB THEY WILL SAMPLE AND ANALYZE THE TRANSFORMER OIL. 1/5/07:RECEIVED DISPOSAL RECEIPT. 1/9/07:RECEIVED ANALYTICAL RESULTS. RESULTS DOCUMENT OIL WAS NON-PCB. NO FURTHER WORK REQUIRED."
Remarks:	"ONE CUP - TRANSFORMER FAILURE DUE TO LIGHTNING STRIKE - CREW CLEANING UP AT THIS TIME "

All Materials:

Site ID:	365967
Operable Unit ID:	1123943
Operable Unit:	01
Material ID:	2113414
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AT220 **KWIK KLEEN INC BR SWEET KLEEN LNDRY CTTE & DRY CLN** **EDR Hist Cleaner** **1014535470**
NE **3584 MAIN ST** **N/A**
< 1/8 **BUFFALO, NY**
0.104 mi.
550 ft. **Site 1 of 2 in cluster AT**

Actual: EDR Hist Cleaner
653 ft.

Focus Map: Year: Name: Type:
8 1960 KWIK KLEEN INC BR SWEET KLEEN L CLEANERS AND DYERS

AU221 **WEGMANS #0082** **RCRA-CESQG** **1010329084**
South **675 ALBERTA DR** **NY MANIFEST** **NYR000147058**
< 1/8 **AMHERST, NY 14226**
0.107 mi.
563 ft. **Site 1 of 3 in cluster AU**

Actual: RCRA-CESQG:
588 ft.
Date form received by agency: 05/10/2007

Focus Map:
6

Facility name:	WEGMANS #0082
Facility address:	675 ALBERTA DR AMHERST, NY 14226
EPA ID:	NYR000147058
Mailing address:	BROOKS AVE ROCHESTER, NY 14624
Contact:	RALPH MERRITT
Contact address:	BROOKS AVE ROCHESTER, NY 14624
Contact country:	US
Contact telephone:	585-464-4642
Telephone ext.:	6184
Contact email:	Not reported
EPA Region:	02
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	WEGMANS
Owner/operator address:	BROOK AVE ROCHESTER, NY 14624
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private

WEGMANS #0082 (Continued) **1010329084**

Owner/Operator Type: Owner
Owner/Op start date: 08/28/1977
Owner/Op end date: Not reported

Owner/operator name: WEGMANS
Owner/operator address: Not reported
Not reported
Owner/operator country: Not reported
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 08/28/1977
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Historical Generators:
Date form received by agency: 05/09/2007
Site name: WEGMANS #0082
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYR000147058
Facility Status: Not reported
Location Address 1: 675 alberta dr
Code: BP
Location Address 2: Not reported

WEGMANS #0082 (Continued) **1010329084**

Total Tanks:	Not reported
Location City:	amherst
Location State:	NY
Location Zip:	14226
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000147058
Mailing Name:	wegmans #82
Mailing Contact:	wegmans #82
Mailing Address 1:	675 alberta dr
Mailing Address 2:	Not reported
Mailing City:	amherst
Mailing State:	NY
Mailing Zip:	14226
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7168316300

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2007
Trans1 State ID:	MID021087275
Trans2 State ID:	Not reported
Generator Ship Date:	08/21/2007
Trans1 Recv Date:	08/21/2007
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/28/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000147058
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	MID980615298
TSDF ID 2:	Not reported
Manifest Tracking Number:	003367308JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	15
Units:	P - Pounds

WEGMANS #0082 (Continued) **1010329084**

Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	D002
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AU222 **WEGMANS #0082** **FINDS** **1010437873**
South **675 ALBERTA DR** **ECHO** **N/A**
< 1/8 **AMHERST, NY 14226**
0.107 mi.
563 ft. **Site 2 of 3 in cluster AU**

Actual:
588 ft.

FINDS:

Focus Map:
6

Registry ID: 110031306664

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access
additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1010437873
Registry ID:	110031306664
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110031306664

AU223 **TRANSFORMER POLE 505** **NY Spills** **S117364161**
South **675 ALBERTA DR** **N/A**
< 1/8 **EGGERTSVILLE, NY 14226**
0.107 mi.
563 ft. **Site 3 of 3 in cluster AU**

Actual:
588 ft.

SPILLS:

Focus Map:
6

Spill Number/Closed Date:	1408152 / 2015-01-22
Facility ID:	1408152
Facility Type:	ER
DER Facility ID:	456681
Site ID:	501704
DEC Region:	9
Spill Cause:	Traffic Accident

TRANSFORMER POLE 505 (Continued) **S117364161**

Spill Class:	D3
SWIS:	1522
Spill Date:	2014-11-06
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	2014-11-06
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Transformer
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2014-11-06
Spill Record Last Update:	2015-01-22
Spiller Name:	LISA MONTESANO
Spiller Company:	NATIONAL GRID
Spiller Address:	144 KENSINGTON AVE
Spiller Company:	999
Contact Name:	LISA MONTESANO
DEC Memo:	"12/24/14 RMC/FILE. DISPOSAL DUE 1/30/15. 12/29/14 RMC/FILE. SENT EMAIL REQUESTING DISPOSAL RECEIPTS, DUE 1/31/15 01/22/15 RMC/FILE. RECEIVED DISPOSAL RECEIPTS FOR 9 DRUMS. CLOSE OUT."
Remarks:	"Spilled onto blacktop parking lot. Cleanup is pending."

All Materials:

Site ID:	501704
Operable Unit ID:	1251091
Operable Unit:	01
Material ID:	2252950
Material Code:	0016A
Material Name:	non PCB oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	15.00
Oxygenate:	Not reported

AV224 **PROPERTY** **NY UST** **U004138457**
NW **3945 RENSCH RD** **N/A**
< 1/8 **AMHERST, NY 14228**
0.108 mi.
568 ft. **Site 1 of 2 in cluster AV**

Actual:
598 ft.

Focus Map:
4

UST:

Id/Status:	9-601105 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	9
Expiration Date:	N/A
UTM X:	190107.05331
UTM Y:	4767564.64708
Site Type:	Private Residence

PROPERTY (Continued) **U004138457**

Affiliation Records:

Site Id:	416404
Affiliation Type:	Facility Owner
Company Name:	JOE SNYDER
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	3945 RENSCH RD
Address2:	Not reported
City:	AMHERST
State:	NY
Zip Code:	14228
Country Code:	001
Phone:	Not reported
EMail:	Not reported
Fax Number:	Not reported
Modified By:	aeskalsk
Date Last Modified:	2009-07-13

Tank Info:

Tank Number:	1
Tank ID:	229417
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	12000
Install Date:	Not reported
Date Tank Closed:	03/05/2009
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	aeskalsk
Last Modified:	04/14/2017

Tank Number:	2
Tank ID:	229418
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	5000
Install Date:	Not reported
Date Tank Closed:	03/05/2009
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported

PROPERTY (Continued) **U004138457**

Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	aeskalsk
Last Modified:	04/14/2017

Tank Number:	3
Tank ID:	229419
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	10000
Install Date:	Not reported
Date Tank Closed:	03/05/2009
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	aeskalsk
Last Modified:	04/14/2017

AV225 **ON PROPERTY** **NY Spills** **S109415932**
NW **3945 RENSCH ROAD** **N/A**
< 1/8 **AMHERST, NY 14228**
0.108 mi.
568 ft. **Site 2 of 2 in cluster AV**

Actual:
598 ft.

Focus Map:
4

SPILLS:

Spill Number/Closed Date:	0813038 / 2009-04-02
Facility ID:	0813038
Facility Type:	ER
DER Facility ID:	359938
Site ID:	410697
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	1522
Spill Date:	2009-03-04
Investigator:	RJJONAK
Referred To:	Not reported
Reported to Dept:	2009-03-04
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Tank Tester
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2009-03-04
Spill Record Last Update:	2009-04-02

ON PROPERTY (Continued) **S109415932**

Spiller Name: JOE SNYDER
Spiller Company: JOE SNYDER
Spiller Address: 3945 RENSCH ROAD
Spiller Company: 999
Contact Name: JOE SNYDER
DEC Memo: "3/5/2009: RJJ AT SITE AT 0900...AFI HAS BEEN HIRED BY THE PROPERTY OWNER,MR. JOE SNYDER,TO REMOVE 3-USTS...1-10000 GAL DIESEL FUEL TANK,1-12,000 GAL DIESEL FUEL TANK & 1-5000 GAL GASOLINE TANK...THE 10K UST IS IN THE FRONT OF THE PROPERTY AND 12K & 5K UST ARE NEXT TO EACH OTHER IN THE REAR OF THE PROPERTY...THE 10K UST HAD NO LEAKAGE OF ANY KIND AND THERE WAS NO PETROLEUM CONTAMINATED SOIL IN THE EXCAVATION...IN THE OTHER EXCAVATION,ONLY THE 5K GASOLINE TANK HAD A FEW HOLES AND THEY DID REMOVE ~30 TONS OF PETROLEUM CONTAMINATED SOIL,WHICH IS STAGED ON SITE,ON PLASTIC,AWAITING DISPOSAL...THE EXCVATAION ~50'X30'X12' AND APPEARS TO HAVE NO PETROLEUM STAINING OR ANY ODORS OF ANY KIND...AFI WILL OBTAIN 4-WALL & 1-FLOOR CONFIRMATORY SOIL SAMPLES AND ANALYZE THEM FOR 8260/8270 'STARS'...AFI WILL SEND ME THEIR REPORT. 4/2/2009: RECEIVED THE FINAL UST CLOSURE REPORT FROM AFI,WHICH INCLUDES THE DISPOSAL RECEIPTS FOR 24.14 TONS OF PETROLEUM CONTAMINATED SOIL TAKEN TO THE TOWN OF TONAWANDA LANDFILL & AND ALL THE CONFIRMATORY SOIL ANALYTICAL FROM THE EXCAVATION(ALL THE RESULTS ARE ALL BELOW OUR 'STARS' GUIDANCE VALUES)...THE 3-USTS HAVE BEEN REMOVED AND THE CONTAMINATED SOIL HAS BEEN DISPOSED OF...DRAFTED AND SENT A 'CLOSURE' LETTER TO 'RP'...NO FURTHER ACTION NEEDED...SPILL CLOSED OUT."
Remarks: "CALLER STATES THAT THEY ENCOUNTERED PETROLEUM CONTAMINATED SOIL WHILE REMOVING 1-10,000 GAL GASOLINE UST...AFI WILL TAKE CONFIRMATORY SOIL SAMPLES AND DISPOSE OF THIS SOIL."

All Materials:
Site ID: 410697
Operable Unit ID: 1167174
Operable Unit: 01
Material ID: 2158715
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: G
Recovered: Not reported
Oxygenate: Not reported

226
NNE
< 1/8
0.109 mi.
576 ft.

Actual:
584 ft.

Focus Map:
4

CRYSTAL KIMMONS **FINDS 1024012730**
605 NATURAL SCIENCE COMPLEX, UNIVERSITY **ECHO N/A**
BUFFALO, NY 14260

FINDS:

Registry ID: 110070107677

Environmental Interest/Information System
ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance

CRYSTAL KIMMONS (Continued) **1024012730**

information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1024012730
Registry ID:	110070107677
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110070107677

227
NNE
< 1/8
0.111 mi.
585 ft.

MOBIL S/S 08-HA1 **NY LTANKS** **U001327012**
3514 MAIN & KENMORE AVE **NY UST** **N/A**
BUFFALO, NY 14226

Actual:
647 ft.

Focus Map:
8

LTANKS:

Spill Number/Closed Date:	9207319 / 1996-12-04
Facility ID:	9207319
Site ID:	156910
Spill Date:	1992-09-18
Spill Cause:	Tank Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	1502
Investigator:	SORGI
Referred To:	Not reported
Reported to Dept:	1992-09-18
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	1996-10-04
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1992-09-24
Spill Record Last Update:	2000-12-08
Spiller Name:	MICHAEL LAMARRE
Spiller Company:	MOBIL BUSINESS RESOURCES
Spiller Address:	464 DOUGHTY BLVD
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported

MOBIL S/S 08-HA1 (Continued) **U001327012**

DEC Region: 9
DER Facility ID: 132753
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was
MJS 11/24/92: MJS MEETING WITH KEVIN SCHROEDER OF MOBIL, HE SAID MOBIL WILL BE INITIATING BAILING PROGRAM TO DETERMINE EXTENT OF CONTAMINATION. REPORT TO BE FORWARDED TO MJS. 03/12/93: MJS RECEIVED REPORT FROM MOBIL, MJS SENT LETTER TO MOBIL NFORMATING THEM THAT REMEDIATION WILL BE REQUIRED. PRODUCT CONTINUALLY FOUND IN MW-1 & MW-2. MOBIL WILL INSTALL SKIMMER PUMP TO TAKE OUT PRODUCT. 03/16/93: MJS AND RNL MEETING WITH KEVIN SCHROEDER, THREE MW NOW SHOWING THREE FEET OF GASOLINE (SMELLS FRESH). SKIMMER PUMP WILL BE INSTALLED NEXT WEEK. 05/27/93: MJS RECEIVED SITE MONITORING REPORT FOR DECEMBER '92 - MARCH '93. APPROX. 50 GALLONS OF GASOLINE REMOVED FROM B1MW, B2MW, B3MW DURING REPORTING PERIOD. B4MW SAMPLED 3/25/93. GROUNDWATER TECHNOLOGY (GTI), MOBIL'S CONTRACTOR, TO SUBMIT RAP. 07/19/93: MJS RECEIVED COPY OF PROPOSED RAP BY GTI. INCLUDES: SOIL GAS SURVEY, GROUNDWATER SAMPLING BETWEEN MOBIL AND 7/11 SITES, INSTALLATION OF SVE POINTS & RECOVERY WELLS, PILOT TESTING. 11/17/93: MJS RECEIVED MONITORING REPORT FOR APRIL-JUNE '93. AS OF NOV. 12, 70 GALLONS OF GASOLINE RECOVERED. SOIL GAS SURVEY, GW SAMPLING, SVE POINTS & PILOT TESTING COMPLETE PER RAP. REPORT TO FOLLOW. 12/20/93: MJS RECEIVED MONITORING REPORT FOR JULY-OCT. '93. EXISTING MW'S ARE ABANDONED AND NEW OVERBURDEN WELLS INSTALLED. SYSTEM STARTUP PENDING INSTALLATION OF A/G EQUIPMENT. 01/24/94: MJS RECEIVED SVE PILOT TESTING REPORT. RESULTS FAVORABLE. SOIL GAS SURVEY RESULTS INCLUDED; INDICATE CONTAMINANT PLUME CENTERING AROUND FORMER TANK PIT AREA. STARTUP PENDING RECEIPT OF EQUIPMENT. 02/08/94: MJS AND RNL MEETING WITH MOBIL. INVESTIGATION INDICATES SOURCE OF GASOLINE IS ON-SITE.
02/09/94: MJS TELECON WITH GTI. REMEDIAL SYSTEM WILL BE RUNNING WITHIN 1 MONTH. 03/07/94: MJS RECEIVED NOV 93 - JAN 94 MONITORING REPORT. 67.6 GALLONS OF GASOLINE RECOVERED TO DATE. 06/09/94: MJS RECEIVED FEB - APRIL 94 MONITORING REPORT. APPROX 68 GALLONS OF GASOLINE RECOVERED TO DATE. REMEDIAL SYSTEM NOT RUNNING YET.
09/09/94: MJS RECEIVED MAY - JUL 94 MONITORING REPORT. SAMPLED WELLS MW-03, MW-04, MW-05, RW-01. CONCENTRATION STABLE. SYSTEM NOT RUNNING YET. 12/21/94: MJS RECEIVED AUG-OCT 94 MONITORING REPORT. SAMPLED WELLS MW-03, MW-04, MW-05, RW-01. CONCENTRATIONS LOWER IN MW-03,04,05. RECEIVED SINGLE PHASE MOTOR, BLOWER, EQUIP. TREE-PHASE SENT BACK. 01/17/95: MJS RECEIVED LETTER AND SVES SAMPLE RESULTS FROM GTI. SYSTEM TURNED ON 11/23/94 AND SAMPLED ON 11/30/94, THEN TURNED OFF. BENZENE EMISSION RATE MUST BE LOWERED UNTIL STACK HEIGHT IS RAISED. 04/03/95: MJS RECEIVED REPORT FOR 11/94 - 1/95. SVES STARTED AND SAMPLED. GW SYSTEM SAMPLED. 06/16/95: MJS RECEIVED REPORT FOR 2/95 - 4/95. HIGH CONCENTRATIONS CONTINUE IN MW-05 AND RW-01.
07/15/96: MJS RECEIVED REPORT FROM MOBIL F0R DECEMBER 1995 TO APRIL 1996, SAMPLE RESULTS FROM 04/24/96 SHOWED 3635 PPB BTEX IN MW-04 AND 38080 PPB BTEX IN MW-05, MW-04 ND, SHEEN IN MW-01, MW-05, AND RW-01, RECOVERED 41.1 GALLONS OF GASOLINE VIA SPARGE AND SVES 09/19/96: MJS TELECON FROM MIKE TEELING (GTI). HE PROPOSES SOURCE REMOVAL (EXCAVATION) AT THIS TIME IN AN ATTEMPT TO CLOSE FILE. SYSTEM IS NOW INOPERABLE DUE TO SITE ACTIVITIES FOR WALGREENS CONSTRUCTION. MJS INFORMED THAT THIS IS ACCEPTABLE WITH SITE MONITORING LATER.
10/01/96: MJS SITE INSPECTION. MET WITH MIKE TEELING. GTI BEGINS EXCAVATING AT FORMER MOBIL SITE. PEA GRAVEL IS CLEAN. SOME CONTAMINATION FOUND ON BOTTOM OF TANK PIT AND ABOVE BEDROCK. GTI EXCAVATING AND DISPOSING OF CONTAMINATED SOILS/GRAVEL. FILTERING TANK PIT WATER VIA CARBON AND DISCHARGING TO SEWER UNDER EXISTING BSA

MOBIL S/S 08-HA1 (Continued) **U001327012**

PERMIT. 10/02/96: MJS SITE INSPECTION. GTI EXCAVATING SOIL. FOUND SOME FREE GASOLINE. FILTERING WATER TO SEWER. MET WITH MIKE TEELING AND DAN KEENE. WORK TO CONTINUE TOMORROW. 10/03/96: MJS SITE INSPECTION. MET WITH MIKE TEELING. EXCAVATION COMPLETED TO BEST OF ABILITY. SOME RESIDUAL CONTAMINATION LEFT. THREE MONITORING WELLS LEFT INTACT FOR POSSIBLE FUTURE MONITORING. POULTRY COMPOST PLACE IN OPEN EXCAVATION. THEY WILL BACKFILL EXCAVATION TOMORROW. 10/04/96: MJS SITE INSPECTION, 0900 HOURS, NO ACTIVITY AT THIS TIME. 11/03/96: MJS TELECON FROM MIKE TEELING (GTI). HE WILL FORWARD COPY OF SAMPLE RESULTS. LOW-LEVEL EXCEEDENCES FOUND. CONTRUCTION COMPANY FOR WALGREENS DESTROYED EXISTING MONITORING WELLS ON SITE. REPORT FORTHCOMING. 11/15/96: RECEIVED CLOSURE REPORT WITH SAMPLE RESULTS AND DISPOSAL DOCUMENTATION. 11/20/96: MJS REVIEW CLOSURE REPORT. 462 TONS OF SOIL/SAND/GRAVEL DISPOSED AT LAKEVIEW LANDFILL. FOUR MW'S LEFT INTACT ON SITE WERE DESTROYED BY CONTRUCTION ACTIVITIES. SAMPLES INDICATING SIGNIFICANT CONTAMINATION (MW04 SIDEWALL AND BOTTOM, AND TANK PIT SIDEWALL) WERE REANALYZED USING TCLP METHOD. ONLY LOW-LEVEL CONTAMINATION FOUND. (SEE TABLE 1 IN REPORT DATED 11/13/96). BASED ON SAMPLE RESULTS FILE CAN BE CLASSIFIED INACTIVE . 11/27/96: MJS AND RNL MEETING AT DEC OFFICE WITH TOM HAGNER. EXPLAINED THAT ANALYTICAL RESULTS ALLOW INACTIVE STATUS (NO FURTHER ACTION). HE OR MOBIL CAN PERFORM RBCA STUDY IF FULL CLOSURE IS REQUIRED. 12/04/96: MJS SENT INACTIVE LETTER TO TOM HAGNER, CC: MIKE TEELING(GTI). 12/06/96: MJS TELECON FROM MIKE TEELING (GTI). HIS CLIENT (MOBIL) HAS REQUESTED THAT INACTIVE LETTER BE ADDRESSED TO MIKE LAMARRE AT MOBIL SINCE THEY ARE THE RP. MJS AGREED AND DRAFTED LETTER TO MR LAMARRE, CC: MR TEELING."

Remarks: "GROUNDWATER TECHNOLOGY FOUND OIL IN MONITORING WELLS. SAME SITE AS CLOSED SPILL #8908630. ACTIVE SERVICE STATION ACROSS THE STREET (711 STORE)."

All Materials:

Site ID:	156910
Operable Unit ID:	974284
Operable Unit:	01
Material ID:	407960
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

UST:

Id/Status:	9-041610 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	9
Expiration Date:	N/A
UTM X:	188631.50241
UTM Y:	4763240.71713
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	52307

MOBIL S/S 08-HA1 (Continued) **U001327012**

Affiliation Type:	Facility Owner
Company Name:	MOBIL OIL CORP
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	3225 GALLOWS RD.
Address2:	Not reported
City:	FAIRFAX
State:	VA
Zip Code:	22037
Country Code:	001
Phone:	(703) 849-5862
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2004-12-14

Site Id:	52307
Affiliation Type:	Mail Contact
Company Name:	MOBIL OIL CORP
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	3225 GALLOWS RD.
Address2:	Not reported
City:	FAIRFAX
State:	VA
Zip Code:	22037
Country Code:	001
Phone:	(703) 849-5862
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2004-12-14

Site Id:	52307
Affiliation Type:	Facility Operator
Company Name:	MOBIL S/S 08-HA1
Contact Type:	Not reported
Contact Name:	C BLACKWELL
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(716) 837-8282
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	52307
Affiliation Type:	Emergency Contact
Company Name:	MOBIL OIL CORP
Contact Type:	Not reported
Contact Name:	C BLACKWELL
Address1:	Not reported
Address2:	Not reported

MOBIL S/S 08-HA1 (Continued) **U001327012**

City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(716) 837-8282
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	169270
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	8000
Install Date:	01/01/1970
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0009
Common Name of Substance:	Gasoline

Tightness Test Method:	01
Date Test:	12/01/1987
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	002
Tank ID:	169271
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	6000
Install Date:	01/01/1970
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0009
Common Name of Substance:	Gasoline

MOBIL S/S 08-HA1 (Continued) **U001327012**

Tightness Test Method: 01
Date Test: 12/01/1987
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None

Tank Number: 003
Tank ID: 169272
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 6000
Install Date: 01/01/1970
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 01
Date Test: 12/01/1987
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

228
ESE
< 1/8
0.111 mi.
586 ft.

CONFERENCE CENTER COMMONS
2390 FOREST ROAD
AMHERST, NY 14068

FINDS **1007457182**
ECHO **N/A**

Actual:
578 ft.

Focus Map:
5

FINDS:

Registry ID: 110017754759

Environmental Interest/Information System

US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1007457182
Registry ID:	110017754759
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110017754759

AS229
North
< 1/8
0.112 mi.
591 ft.

BOULEVARD TOWER APTS.
120 MEYER ROAD
AMHERST, NY

Site 2 of 2 in cluster AS

NY Spills **S102178599**
N/A

Actual:
580 ft.

Focus Map:
3

SPILLS:

Spill Number/Closed Date:	9402661 / 1995-05-20
Facility ID:	9402661
Facility Type:	ER
DER Facility ID:	221961
Site ID:	272753
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	1522
Spill Date:	1994-05-19
Investigator:	SORGI
Referred To:	Not reported
Reported to Dept:	1994-05-20
CID:	Not reported
Water Affected:	STORM SEWER
Spill Source:	Commercial/Industrial
Spill Notifier:	Citizen
Cleanup Ceased:	1995-05-20
Cleanup Meets Std:	True

BOULEVARD TOWER APTS. (Continued) **S102178599**

Last Inspection:	1994-05-20
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1994-05-24
Spill Record Last Update:	1995-06-06
Spiller Name:	Not reported
Spiller Company:	BOULEVARD TOWER APARTMENT
Spiller Address:	120 MEYER ROAD
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MJS 05/20/94: MJS SITE INSPECT - SPOKE W/ MANAGER. ELEVATOR REPAIR DONE CONTINUALLY AROUND COMPLEX. DRAIN TILES BEING INSTALLED BEHIND 120 MEYER. BLACK WATER BEING PUMPED FROM EXCAVATION. NO OIL DUMPED. 05/20/94: MJS INSPECT ELEVATOR SHAFT. OIL FOUND IN SUMP. EQUIPMENT JUST UPDATED TO PREVENT LEAKING SEALS DISCHARGING TO GROUND. MJS ASKED MANAGER TO HAVE OIL REMOVED AND CHECK ALL ELEVATOR SHAFTS. 05/18/95: MJS REVIEW FILE. MINOR PROBLEM. NO FURTHER FOLLOW-UP REQUIRED. MJS CLOSE FILE. 09/29/95: This is additional information about material spilled from the translation of the old spill file: HYDRAULIC FLUID."
Remarks:	"ELEVATOR UNDER REPAIR"

All Materials:

Site ID:	272753
Operable Unit ID:	999711
Operable Unit:	01
Material ID:	382839
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	9975361 / 2000-08-11
Facility ID:	9975361
Facility Type:	ER
DER Facility ID:	221961
Site ID:	272754
DEC Region:	9
Spill Cause:	Housekeeping
Spill Class:	C3
SWIS:	1522
Spill Date:	1999-08-01
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	1999-08-13
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True

BOULEVARD TOWER APTS. (Continued) **S102178599**

Last Inspection:	1999-09-01
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-08-16
Spill Record Last Update:	2004-02-11
Spiller Name:	GEORGIANA LAUZAU
Spiller Company:	BOULEVARD TOWER APTS.
Spiller Address:	120 MEYER ROAD
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 09/--/99: RMC SITE INSPECTION, FOUND ELEVATOR SHAFTS LEAK INTO SUMP, WHERE THE SUMP DISCHARGES IS UNKNOWN, RMC CONTACTED JIM ZYMANEK OF THE TOWN OF AMHERST, UPDATE 11/1 12/06/99: RMC TELECON TO ZYMANEK, NOT IN, LEFT MESSAGE TO CALL 12/24/99: RMC TELECON ZYMANEK, TOWN WILL ASSIST RP IN COMPLIANCE WITH SEWER USE ORDINANCE 01/12/00: RMC SENT LETTER TO BLVD TOWER, RESPONSE DUE 2/28/00 01/18/00: RMC TELECON FROM GEORGIANA LAUZAU, BOULEVARD TOWERS WILL WORK WITH TOWN TO RESOLVE, REPORT DUE 3/30/00 05/01/00: RMC RECEIVED LETTER ADVISING THAT LIFTS WERE REPAIRED, LETTER FROM ELEVATOR COMPANY ATTACHED, NO FURTHER ACTION REQUIRED, CLOSE OUT "
Remarks:	"CALLER CLAIMS THAT THERE IS A HYDRAULIC PUMP BURIED IN THE GARDEN IN FRONT OF THE APARTMENT COMPLEX OFFICE THAT DISCHARGES TO A STORM SEWER IN THE BACK OF THE COMPLEX."

All Materials:

Site ID:	272754
Operable Unit ID:	1091515
Operable Unit:	01
Material ID:	291883
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AW230 **BJ'S AMHERST GAS STATION** **NY UST** **U004194459**
East **3050 SHERIDAN DRIVE** **N/A**
< 1/8 **AMHERST, NY 14226**
0.118 mi.
624 ft. **Site 1 of 5 in cluster AW**

Actual:
597 ft.

Focus Map:
6

UST:

Id/Status:	9-601356 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	9
Expiration Date:	01/25/2023
UTM X:	188495.98113
UTM Y:	4765787.18320
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	478215

BJ'S AMHERST GAS STATION (Continued) **U004194459**

Affiliation Type:	Facility Owner
Company Name:	AMHERST II UE CLO UC
Contact Type:	MANAGER OF FUEL FACILITIES
Contact Name:	DIANE RAE
Address1:	210 RTE 4 EAST
Address2:	Not reported
City:	PARAMUS
State:	NJ
Zip Code:	07652
Country Code:	001
Phone:	(774) 512-7922
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TAMAMUN
Date Last Modified:	2017-11-27

Site Id:	478215
Affiliation Type:	Mail Contact
Company Name:	BJS WHOLESALE CLUB
Contact Type:	Not reported
Contact Name:	DIANE RAE
Address1:	25 RESEARCH DRIVE
Address2:	P.O. BOX 5230
City:	WESTBOROUGH
State:	MA
Zip Code:	01581
Country Code:	001
Phone:	(774) 512-6468
EMail:	DRAE@BJS.COM
Fax Number:	Not reported
Modified By:	AESKALSK
Date Last Modified:	2016-09-26

Site Id:	478215
Affiliation Type:	Facility Operator
Company Name:	BJS AMHERST GAS STATION
Contact Type:	Not reported
Contact Name:	GUILLERMO SALAMANCA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	Not reported
EMail:	Not reported
Fax Number:	Not reported
Modified By:	AESKALSK
Date Last Modified:	2016-09-26

Site Id:	478215
Affiliation Type:	Emergency Contact
Company Name:	AMHERST II UE CLO UC
Contact Type:	Not reported
Contact Name:	ANTHONY BABINE
Address1:	Not reported
Address2:	Not reported

BJ'S AMHERST GAS STATION (Continued) **U004194459**

City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(774) 512-6468
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TAMAMUN
Date Last Modified:	2017-11-27

Tank Info:

Tank Number:	001
Tank ID:	247046
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	20000
Install Date:	12/15/2012
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	00
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	aeskalsk
Last Modified:	04/14/2017

Equipment Records:

E04 - Piping Secondary Containment - Double walled UG
J01 - Dispenser - Pressurized Dispenser
F05 - Pipe External Protection - Jacketed
B04 - Tank External Protection - Fiberglass
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
C02 - Pipe Location - Underground/On-ground
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
D11 - Pipe Type - Flexible Piping
G04 - Tank Secondary Containment - Double-Walled (Underground)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector

Tank Number:	002
Tank ID:	247047
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	8000
Install Date:	12/15/2012
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground

BJ'S AMHERST GAS STATION (Continued) **U004194459**

Tank Type: Equivalent technology
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TAMAMUN
Last Modified: 11/27/2017

Equipment Records:

L00 - Piping Leak Detection - None
D11 - Pipe Type - Flexible Piping
G04 - Tank Secondary Containment - Double-Walled (Underground)
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
J00 - Dispenser - None
C00 - Pipe Location - No Piping
E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None
B04 - Tank External Protection - Fiberglass
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin

Tank Number: 003
Tank ID: 247048
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 12000
Install Date: 12/15/2012
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 00
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: aeskalsk
Last Modified: 04/14/2017

Equipment Records:

B04 - Tank External Protection - Fiberglass
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
E04 - Piping Secondary Containment - Double walled UG
J01 - Dispenser - Pressurized Dispenser
F05 - Pipe External Protection - Jacketed
D11 - Pipe Type - Flexible Piping
G04 - Tank Secondary Containment - Double-Walled (Underground)
C02 - Pipe Location - Underground/On-ground

BJ'S AMHERST GAS STATION (Continued) **U004194459**

L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
L07 - Piping Leak Detection - Pressurized Piping Leak Detector

---

231
East
< 1/8
0.119 mi.
630 ft.

ORKEN LAWNCARE
514 CAPEN BOULEVARD
AMHERST, NY

NY LTANKS **S100117734**
N/A

Actual:
603 ft.

Focus Map:
8

LTANKS:

Spill Number/Closed Date:	8901455 / 1989-05-13
Facility ID:	8901455
Site ID:	235456
Spill Date:	1989-05-13
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1989-05-13
SWIS:	1522
Investigator:	LEARY
Referred To:	Not reported
Reported to Dept:	1989-05-13
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Citizen
Last Inspection:	1989-05-13
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2003-12-02
Spiller Name:	Not reported
Spiller Company:	ORKEN LAWNCARE
Spiller Address:	77 ORISKENY STREET
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	9
DER Facility ID:	193938
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RNL 05/13/89: RNL SITE INSP. 05/13/89, SITE CLEANED UP BY SPILLER, MET MR. MALISZEWSKI ON SITE; RNL TELECON WITH ROBERT BACHMANN, ORKEN LAWNCARE, HE SAID HIS MAN LEFT SPILL BEFORE CLEANUP, SHOULD NOT HAD DONE SO. "
Remarks:	"SPILL FROM LAWNCARE COMPANY"

All Materials:

Site ID:	235456
Operable Unit ID:	928716
Operable Unit:	01
Material ID:	449202
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	.00

ORKEN LAWNCARE (Continued) **S100117734**

Units: G
Recovered: .00
Oxygenate: Not reported

232
East
< 1/8
0.120 mi.
631 ft.

BUFFALO SUB 124
78 ALMEDA DR.
AMHERST, NY 14223

NY Spills **S118704814**
N/A

Actual:
593 ft.

Focus Map:
6

SPILLS:

Spill Number/Closed Date:	1601748 / 2018-08-15
Facility ID:	1601748
Facility Type:	ER
DER Facility ID:	481302
Site ID:	527126
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	1522
Spill Date:	2016-05-20
Investigator:	SACALAND
Referred To:	Not reported
Reported to Dept:	2016-05-20
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Transformer
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2016-05-20
Spill Record Last Update:	2018-08-26
Spiller Name:	LISA MONTESANO
Spiller Company:	NATIONAL GRID
Spiller Address:	144 KENSINGTON AVE.
Spiller Company:	001
Contact Name:	LISA MONTESANO
DEC Memo:	"5/23/2016: RJJ TELECON LISA MONTESANO,NATIONAL GRID,SHE SAID THAT DUE TO AN EQUIPMENT PROBLEM AT THEIR SUB-STATION,~3 GALS OF TRANSFORMER OIL SPRAYED OUT ONTO THE SUBSTATION'S OTHER EQUIPMENT...NATIONAL GRID HAS HIRED OP-TECH ENVIRONMENTAL WHO WILL CLEAN-UP THIS SPILL WHEN THEY CAN TURN THE POWER OFF AT A LATER TIME...NONE OF THE OIL REACHED ANY WATERWAYS...LISA WILL KEEP ME INFORMED. 6/6/2016: LISA MONTESANO TELECON RJJ,SHE SAID THAT THERE ARE 3 DIFFERNT TRANSFORMERS AT THIS STATION...#1 TESTED 208 PPM PCBS...#2 TESTED 174 PPM PCBS... #3 TESTED 39 PPM PCBS,EVENTHOUGH THEY ARE LABLED NON-PCB...OP-TECH WILL NOW EXCAVATE 1' DEEPER AND 1' WIDER,IN ALL DIRECTIONS IN 3 DIFFERNT AREAS AND OBTAIN CONFIRMATORY PCB SOIL SAMPLES...LISA ALSO SAID THAT IT STILL APPEARS THAT ONLY 2-3 GALS OF TRANSFORMER OIL HAS LEAKED OUT...THEY ALSO PLAN ON RETROFITTING THESE TRANSFORMES,LATER THIS YEAR,WITH NEW NON-PCB TRANSFORMER OIL...LISA WILL KEEP ME INFORMED AND SEND ME THEIR REPORT. 10/20/2016: LISA MONTESANO TELECON RJJ,SHE SAID THAT THEY

BUFFALO SUB 124 (Continued) **S118704814**

HAVE SCRAPED-UP THE AFFECTED STONE FROM THE 3 TRANSFORMERS HOWEVER,TRANSFORMERS #1 & 2 STILL HAVE A SMALL DRIPPING OF OIL SO LISA WILL CONTACT NATIONAL GRID MANAGEMENT TO TRY TO ASCERTAIN FUNDS TO REMOVE THESE TRANSFORMERS,SCRAPE-UP ADDITIONAL STONE,EMPTY THE TRANSFORMER'S OIL AND REPLACE WITH NON-PCB OIL,THEN DISPOSE ALL THIS MATERIAL...IN THE MEAN TIME,THEY WILL MONITOR THIS AND USE ABSORBANTS TO COLLECT ANY LEAKING OIL...LISA WILL ALSO SEND ME THEIR REPORT THUS FAR,WHICH HAS DISPOSAL RECEIPTS AND THEIR REPORT. 9/5/17:SAC TELECON LISA MONTESANO. THEY HAVE NOT REPAIRED THE TRANSFORMERS. THEY CANNOT HAVE AN OUTAGE PRESENTLY TO DO THE REPAIRS. THEY STILL HAVE THE DRIP PANS AND ABSORBENT PADS IN PLACE TO CATCH THE PRODUCT THAT IS WEEPING. SHE BELIEVES THE REPAIRS WILL BE SCHEDULED SOON. 2/23/18:RECEIVED MESSAGE FROM LISA MONTESANO. SHE REQUESTED NATIONAL GRID PERSONNEL AND NRC(OP-TECH) MEET AND CONFIRM THE NEXT STEPS SINCE THEY HAVE NOT HAD THE OPPORTUNITY FOR AN OUTAGE. 3/13/18:SAC TELECON LISA MONTESANO. MS. MONTESANO SAID THAT THEY HAD A MEETING WITH NATIONAL GRID MANAGEMENT DISCUSSING THE NEXT STEPS. INSTEAD OF REPLACING ONE BANK THEY WILL BE REPLACING ALL 4 BANKS. THEY ARE IN DESIGN FOR THIS REPLACEMENT. THE REPLACEMENT MAY TAKE 2 TO 3 YEARS. THE LEAKS HAVE SUBSIDED BUT THEY WILL WRAP THE PIPING AS A PRECAUTION AND A PREVENTIVE MEASURE. THEY ARE ALSO GOING TO HAVE NRC(OP-TECH) INSPECT SITE TO SEE IF ADDITIONAL CLEANUP IS REQUIRED. IF SO, THEY WILL DO THE CLEANUP. 8/15/18:SAC TEELECON LISA MONTESANO. MS. MONTESANO SAID THAT CLEANUP HAS BEEN COMPLETED AND ALL ACCESSIBLE CONTAMINATED MATERIAL HAS BEEN REMOVED. ONCE THE TRANSFORMER ARE RETIRED IN THE FUTURE, THEY WILL BE REMOVED. ONCE THEY ARE REMOVED, NATIONAL GRID WILL BE ABLE TO SEE IF ANY CONTAMINATION WAS NOT ADDRESSED PREVIOUSLY. SHE WILL HAVE NRCC/OP-TECH SEND IN REPORT. RECEIVED SPILL CLOSURE REPORT INCLUDING MANIFEST AND SAMPLE RESULTS. RESULTS WERE NON-DETECT FOR PCBS. NO FURTHER WORK IS REQUIRED."

Remarks: "clean up is on going"

All Materials:

Site ID:	527126
Operable Unit ID:	1275993
Operable Unit:	01
Material ID:	2280791
Material Code:	0017A
Material Name:	PCB oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

AX233 **PRINTS CHARMING** **NY Spills** **S103562747**
West **SHERIDAN & EGGERT ROAD** **N/A**
< 1/8 **TONAWANDA, NY**
0.121 mi.
640 ft. **Site 1 of 4 in cluster AX**

Actual:
596 ft.

Focus Map:
6

SPILLS:

Spill Number/Closed Date:	9211378 / 1994-06-16
Facility ID:	9211378
Facility Type:	ER
DER Facility ID:	260719

PRINTS CHARMING (Continued) **S103562747**

Site ID:	323647
DEC Region:	9
Spill Cause:	Other
Spill Class:	B3
SWIS:	1564
Spill Date:	1993-01-04
Investigator:	SORGI
Referred To:	Not reported
Reported to Dept:	1993-01-04
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Citizen
Cleanup Ceased:	1994-06-16
Cleanup Meets Std:	True
Last Inspection:	1994-06-16
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1993-01-05
Spill Record Last Update:	1998-10-19
Spiller Name:	Not reported
Spiller Company:	ANTHONE FURNITURE
Spiller Address:	2880 SHERIDAN DRIVE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MJS 03/18/93: MJS/SITE - RECEIVED 2ND COMPLAINT. SPOKE W/MANAGER. HE HASN'T NOTICED ANY PETROLEUM ODORS EXCEPT FOR HEAVY PROPANE ODOR FROM FACILITY NEXT DOOR (CAMPING COUNTRY). 03/18/93: (CONT. FROM PREVIOUS 3/18/93 HISTORY) - MANAGER SAYS THAT UST'S WERE REMOVED APPROX. 10 YEARS AGO. 3 MW'S ON-SITE. SITE ASSESSMENT WITHIN LAST COUPLE OF YEARS. WILL CONTACT MR. ANTHONE FOR SITE ASSESS. 03/19/93: MJS/BOB ANTHONE/TELECON - HE WILL FORWARD THE PHASE I STUDY THAT WASDONE. 03/24/93: MJS SENT LETTER TO ANTHONE FURNITURE CO. LETTER WAS RETURNED AS NON-DELIVERABLE. 06/14/93: MJS/RUSS SAVAGE/SITE - NATURE'S WAY IS EXCAVATING CONTAMINATED SOIL FROM OLD TANK PIT AREA. TANKS WERE REMOVED IN 1982. 06/20/93: MJS/RUSS SAVAGE/BOB ANTHONE/SITE - EXCAVATING SOIL FROM PIPING TRENCHES. SOIL IS SPREAD ON PLASTIC. FUEL OIL TANK TO BE REMOVED; CONTAMINATED SOIL AROUND TANK. BLDG. TO BE CONVERTED TO NATURAL GAS. 09/24/93: MJS RECEIVED POST-EXCAVATION ANALYTICAL RESULTS. NO FURTHER EXCAVATION REQUIRED. 04/21/94: MJS REVIEW FILE. NO INTERIM OR FINAL SAMPLE RESULTS ON SOIL PILE. MJS TELECON TO RUSS SAVAGE. HE REPORTS THAT TREATMENT IS COMPLETE AND WILL FORWARD SAMPLE RESULTS. 06/16/94: RECEIVED SAMPLE RESULTS FROM RUSS SAVAGE. NOTHING FOUND IN SAMPLES TREATMENT COMPLETE. MJS CLOSE FILE. LETTER TO RP. MJS SITE INSPECT SOIL MADE INTO BURM AS REQUESTED BY RP. "
Remarks:	"CITIZEN SMELLING FUMES FROM OLD ABANDONED GAS STATION. CURRENTLY A PRINTS CHARMING LOCATION."

All Materials:

Site ID:	323647
Operable Unit ID:	975675
Operable Unit:	01
Material ID:	404784
Material Code:	0009
Material Name:	gasoline

PRINTS CHARMING (Continued) **S103562747**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

AX234 **HANCOCK FABRICS** **NY Spills** **S106382843**
West **EGGERT AND SHERIDAN** **N/A**
< 1/8 **TONAWANDA, NY**
0.121 mi.
640 ft. **Site 2 of 4 in cluster AX**

Actual:
596 ft.

Focus Map:
6

SPILLS:

Spill Number/Closed Date:	0375473 / 2004-02-17
Facility ID:	0375473
Facility Type:	ER
DER Facility ID:	59878
Site ID:	61606
DEC Region:	9
Spill Cause:	Unknown
Spill Class:	D4
SWIS:	1564
Spill Date:	2004-02-17
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	2004-02-17
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-02-17
Spill Record Last Update:	2004-02-17
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC "
Remarks:	"CALLER CLAIMS STRONG CHEMICAL ODOR IN AIR OF THE STORE. ODOR MADE HER THROAT SORE. Clerk told her it was from cleaning chemicals. spills referred to division of air and ECDOH. no spill action required, close as a spills issue. no paper file. "

All Materials:

Site ID:	61606
Operable Unit ID:	882289
Operable Unit:	01
Material ID:	494658
Material Code:	0064A

HANCOCK FABRICS (Continued) **S106382843**

Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

AY235 **UNIVERSITY OF BUFFALO** **NY Spills** **S102175935**
North **JARVIS HALL** **N/A**
< 1/8 **AMHERST, NY**
0.122 mi.
642 ft. **Site 1 of 16 in cluster AY**

Actual:
586 ft.

Focus Map:
4

SPILLS:

Spill Number/Closed Date:	8708045 / 1988-04-05
Facility ID:	8708045
Facility Type:	ER
DER Facility ID:	104958
Site ID:	120931
DEC Region:	9
Spill Cause:	Human Error
Spill Class:	Not reported
SWIS:	1522
Spill Date:	1987-12-16
Investigator:	COOKE
Referred To:	Not reported
Reported to Dept:	1987-12-16
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	1988-04-05
Cleanup Meets Std:	True
Last Inspection:	1987-12-16
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1987-12-17
Spill Record Last Update:	1988-04-07
Spiller Name:	Not reported
Spiller Company:	SUNY AT BUFFALO
Spiller Address:	307 MICHAEL HALL
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was JDC 04/05/88: JDC RECEIVED FINAL DISPOSAL VARIFICATION FOR WASTE LIQIUDS FROM GENE MONACELL, UB. NO FURTHER ACTION WILL BE REQUIRED FOR THIS CASE. "
Remarks:	"ANONYMOUS CALLER DESCRIBED OIL STAIN IN PARKING LOT TO STORM DRAIN NEAR NON PCB TRANSFORMERS/SWITCHES."

All Materials:

Site ID:	120931
Operable Unit ID:	912366
Operable Unit:	01
Material ID:	463442

UNIVERSITY OF BUFFALO (Continued) **S102175935**

Material Code:	0016A
Material Name:	non PCB oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	10.00
Oxygenate:	Not reported

AY236 **SUNYAB - COOKE HALL** **NY Spills** **S105057840**
North **PUTNAM WAY** **N/A**
< 1/8 **AMHERST, NY**
0.122 mi.
642 ft. **Site 2 of 16 in cluster AY**

Actual:
586 ft.

Focus Map:
4

SPILLS:

Spill Number/Closed Date:	0175123 / 2001-08-07
Facility ID:	0175123
Facility Type:	ER
DER Facility ID:	152828
Site ID:	182388
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	D3
SWIS:	1522
Spill Date:	2001-05-31
Investigator:	SACALAND
Referred To:	Not reported
Reported to Dept:	2001-05-31
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	2001-08-06
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-05-31
Spill Record Last Update:	2002-01-02
Spiller Name:	AL SWAVY
Spiller Company:	SUNYAB
Spiller Address:	220 WINSPEAR AVE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SAC 5/31/01:SAC TELECON AL SWAVY, SUNYAB - MR. SWAVY SAID SPILL AMOUNT OF OIL LEAKED FROM AROUND THE SOLENOID VALVE AND DRIPPED DOWN THE SIDES OF THE TANK, SPILL WENT TO THE FLOOR WHERE ABSORBENTS WERE APPLIED TO CONTAIN SPILL, ABSORBENTS WILL BE SWEPT UP AND PLACED IN UNIVERSITY'S BULK SHIPMENT FOR DISPOSAL, NO FURTHER WORK REQUIRED. 6/8/01:SAC TELECON AL SWAVY, THEY HAVE BEEN CALCULATING THE AMOUNT OF PRODUCT THAT HAD BEEN LOST AND THEY HAVE A DISCREPANCY OF 80 GALLONS, THE TANK IS CONNECTED TO OTHER TANKS SO IT MAY HAVE BACKED UP INTO THE PIPING, THEY WILL CONTINUE TO INVESTIGATE THE SITUATION AND CALL BACK WITH THE FINDINGS. 6/25/01:SAC TELECON AL SWAVY, THEY HAVE

SUNYAB - COOKE HALL (Continued) **S105057840**

INVESTIGATED WHERE THE ADDITIONAL OIL MIGHT HAVE GONE, THE TANK WAS IN THE BASEMENT OF A SEVEN STORY BUILDING, THE VENT PIPE FOR THE BUILDING WENT UP SEVEN STORIES, THERE WAS AN ADDITIONAL FILL PIPE THAT ALSO WENT UP SEVEN STORIES AND THIS PIPE WAS CONNECTED TO ANOTHER TANK'S FILL PORT AND THIS TANK WAS ALSO AT THE SEVENTH STORY, THEY BELIEVE THAT THE TANK WHEN THE TANK WAS FILLED THAT IT HAD 6 1/2 VOID IN IT AND IF THE OIL FILLED THE VENT PIPE AND THIS FILL PIPE IT WOULD ACCOUNT FOR 60 GALLONS OF OIL, THEY INSPECTED THE ROOF AND THERE WAS NO OIL OBSERVED ON THE ROOF, SINCE THEN THE TANK HAS BEEN REMOVED AND A NEW TANK IN PLACE WITH SAFEGUARDS AGAINST OVERFILLING. 8/6/01:SAC INSPECT SITE, MET W/AL SWAVY, AREA WAS CLEANED UP W/SOME STAINING ON FLOOR, SOME OF THE SPILLAGE WENT UNDER WALL AND INTO A LARGER ROOM THAT HAS A LARGE VENT IN THE CEILING AND ALLOWED LEAVES TO ENTER ROOM AND COLLECT ON THE FLOOR, THE LEAVES WERE AGAINST THE WALL AND WERE CONTAMINATED WITH THE FUEL OIL, SOME OIL WAS FOUND IN A STORM SEWER DRAIN IN THIS ROOM, THE DRAIN DOWNSTREAM WAS CHECKED BUT NO OIL FOUND IN THIS DRAIN, THE DRAINAGE CREEK INTO WHICH THE SEWER ENTERS DID NOT HAVE PRODUCT OR A SHEEN COMING IN, THERE WAS NO UNDERGROUND PIPING INVOLVED WITH THIS TANK SYSTEM SO POTENTIAL SPILLS WOULD BE ABOVE GROUND, IT IS STILL ESTIMATED THAT ABOUT 5 GALLONS WERE SPILLED, THE CONTAMINATED SPEEDI-DRY AND LEAVES WILL BE SHIPPED IN BULK, NO FURTHER WORK REQUIRED."

Remarks: "BELIEVE A FAILED SOLENOID VALVE CAUSE LEAK ON TOP OF A 275 GALLON ABOVEGROUND TANK INSIDE BUILDING."

All Materials:

Site ID:	182388
Operable Unit ID:	852763
Operable Unit:	01
Material ID:	524444
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	5.00
Oxygenate:	Not reported

AY237 **SUNYAB AMHERST TANK** **NY Spills** **S104951985**
North **MAPLE AND JOHN BEANE CTR** **N/A**
< 1/8 **AMHERST, NY**
0.122 mi.
642 ft. **Site 3 of 16 in cluster AY**

Actual:
586 ft.

Focus Map:
4

SPILLS:

Spill Number/Closed Date:	0075497 / 2001-02-23
Facility ID:	0075497
Facility Type:	ER
DER Facility ID:	209162
Site ID:	255359
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	1522
Spill Date:	2000-11-15
Investigator:	RJJONAK

SUNYAB AMHERST TANK (Continued) **S104951985**

Referred To:	Not reported
Reported to Dept:	2000-11-15
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	2000-11-16
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-11-15
Spill Record Last Update:	2004-02-19
Spiller Name:	GENE MONACELL
Spiller Company:	SUNYAB
Spiller Address:	MAPLE ROAD
Spiller Company:	001
Contact Name:	RON KNOX
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RJJ 2004/02/19 - Spill_Time was previously blank and replaced with RCVD_Time to fix a data translation problem... Bob Corcoran 11/16/2000: RJJ SITE INVESTIGATION AT 1500...MEET WITH RON KNOX, UILDINGS (UB), AND BILL PATTERSON, FROM GZA...UB HAS HIRED TYREE TO REMOVE ALL THEIR OLD UST'S ON THE COLLEGE, WITH GZA DOING ANY TECHNICAL WORK...THIS TANK IS A 275 GAL FUEL OIL TANK NEXT TO THE JOHN BEANE CENTER...THEY REMOVED THE TANK AND STAGED THE SOIL, ON PLASTIC...THE PIT AREA IS ABOUT 8'X8'X7' AND IS SURROUNDED WITH ALL CLAY...THE PIT LOOKS AND SMELLS CLEAN, THEY WILL SAMPLE THE SIDES AND THE FLOOR AND SEND ME ALL THE RESULTS. 12/15/2000: RJJ RECEIVED THE ANALYTICAL RESULTS FROM THE EXCAVATION...ALL THE RESULTS CAME BACK ND, EXCEPT THE NORTH WALL, WHICH HAS VERY HIGH SEMI LEVELS... RJJ TELECON MARTIN WESOLOWSKI, LIRO-KASSNER,INC., AND TOLD HIM THAT THEY WILL HAVE TO RESAMPLE THE NORTH WALL...I SUGGESTED THAT THEY SAMPLE USING THE TCLP METHOD, MARTIN AGREED...HE WILL KEEP ME INFORMED ON THEIR PROGRESS. 01/04/2001: MARTY WESOLOWSKI TELECON RJJ, SAID THAT THEY WILL RESAMPLE THE NORTH WALL TOMORROW AT 0830 AND ANALYZE IT FOR 8270. 01/17/2001: RJJ RECEIVED THE ANALYTICAL RESULTS FROM THE NORTH WALL RESAMPLING...ALL OF THE RESULTS ARE BELOW OUR 'TAGM' GUIDANCE VALUES...WHEN I RECEIVE THE SOIL DISPOSAL RECEIPTS, I WILL BE ABLE TO CLOSE OUT THIS SPILL. 02/23/2001: RECEIVED THE TANK CLOSURE REPORT FROM LIRO-KASSNER,INC., WHICH INCLUDES THE SOIL DISPOSAL RECEIPTS...ALL THE RECEIPTS ARE IN ORDER...I WILL DRAFT AND SEND A 'CLOSURE' LETTER TO THEM...NO FURTHER ACTION NEEDED...SPILL CLOSED OUT."
Remarks:	"285 GALLON FUEL OIL UST WAS REMOVED. CONTAMINATION WAS DISCOVERED. SEVERAL LOADS OF CONTAMINATION WERE REMOVED. TYREE IS THE CONTRACTOR WHO WILL BE COLLECTING EXCAVATION SAMPLES."

All Materials:

Site ID:	255359
Operable Unit ID:	836854
Operable Unit:	01
Material ID:	539068
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum

SUNYAB AMHERST TANK (Continued) **S104951985**

Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AY238 **TRUCK AT SUNY AMHERST** **NY Spills** **S104651406**
North **FRONTIER ROAD** **N/A**
< 1/8 **AMHERST, NY**
0.122 mi.
642 ft. **Site 4 of 16 in cluster AY**

Actual:
586 ft.

Focus Map:
4

SPILLS:

Spill Number/Closed Date:	9975668 / 2000-05-11
Facility ID:	9975668
Facility Type:	ER
DER Facility ID:	107008
Site ID:	123447
DEC Region:	9
Spill Cause:	Human Error
Spill Class:	C3
SWIS:	1522
Spill Date:	2000-02-03
Investigator:	SORGI
Referred To:	Not reported
Reported to Dept:	2000-02-03
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	2000-02-03
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-02-03
Spill Record Last Update:	2000-06-06
Spiller Name:	Not reported
Spiller Company:	ROSS HERBERT BROTHERS
Spiller Address:	80 RABBITT ROAD
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MJS 02/03/00: MJS PAGED BY KAB TO RESPOND. MJS SITE INSPECTION, MET WITH JIM ZYMANEK OF TOWN OF AMHERST AND GENE MONACELL AND MARSHALL BOLLES OF SUNYAB. DRIVER BROKE CROSSOVER LINE UNDER TRUCK. SPILLED APPROX 60 GALLONS DIESEL TO ROADWAY FOR NEW CONSTRUCTION. IMPACTED AREA IS APPROX 15' X 25'. GROUND IS FROZEN, LITTLE PENETRATION. SUNYAB HIRED MARCOR TO CLEAN SPILL AND THEY ARE DUE ON SITE AT 1300 HRS. THEY WILL SCRAPE AREA AND DRUM WASTE FOR DISPOSAL. MR MONACELL WILL CONTACT ME WHEN WORK COMPLETE. 05/05/00: MJS REVIEW FILE. NEED DISPOSAL DOCUMENTATION. LEFT MESSAGE TO FORWARD INFO FOR CLOSURE. 05/11/00: MJS RECEIVED LETTER REPORT AND DISPOSAL MANIFEST FROM GENE MONACELL. SEVEN DRUMS DEBRIS GENERATED AND DISPOSED AT CHEMTRON CORP. NO FURTHER ACTION REQUIRED. MJS CLOSE FILE. "
Remarks:	"TRACTOR TRAILER RIPPED OFF SADDLE TANK AT CONSTRUCTION SITE. TOWN OF AMHERST REQUESTING DEC ASSISTANCE."

TRUCK AT SUNY AMHERST (Continued) **S104651406**

All Materials:

Site ID:	123447
Operable Unit ID:	1093955
Operable Unit:	01
Material ID:	290208
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	60.00
Units:	G
Recovered:	60.00
Oxygenate:	Not reported

AY239 **UNIVERSITY OF BUFFALO** **NY LTANKS** **S105135293**
North **NORTH CAMPUS - BAIRD HALL** **N/A**
< 1/8 **AMHERST, NY**
0.122 mi.
642 ft. **Site 5 of 16 in cluster AY**

Actual:
586 ft.

Focus Map:
4

LTANKS:

Spill Number/Closed Date:	0104703 / 2003-01-30
Facility ID:	0104703
Site ID:	262404
Spill Date:	2001-08-01
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	1522
Investigator:	SACALAND
Referred To:	Not reported
Reported to Dept:	2001-08-01
CID:	270
Water Affected:	Not reported
Spill Notifier:	Affected Persons
Last Inspection:	2002-06-05
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2001-08-01
Spill Record Last Update:	2003-01-30
Spiller Name:	TED KRYGIER
Spiller Company:	UNIVERSITY OF BUFFALO
Spiller Address:	119 JOHN BEANE CENTER
Spiller County:	001
Spiller Contact:	CALLER
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	9
DER Facility ID:	214220
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SAC 8/2/01:SAC TELECON BOB GROCK - TYREE, THEY HAVE REMOVED ALL CONTAMINATED SOIL, THEY ARE TAKING SIDE SAMPLES, CONCRETE PAD WAS FOUND ON THE BOTTOM OF THE EXCAVATION SO A SAMPLE WAS TAKEN NEXT TO

UNIVERSITY OF BUFFALO (Continued) **S105135293**

THE PAD AS THE BOTTOM SAMPLE, SAC INSPECT SITE, ONLY WORKERS FROM TYREE WERE ON THE SITE, NO VISIBLE CONTAMINATION OBSERVED, GZA SAMPLED THE EXCAVATION, SAC SPOKE TO ONE OF THE WORKERS FROM TYREE, THE TANK DID HAVE HOLES ALONG THE SEAM AT THE END OF THE TANK, THEY REMOVED A COUPLE OF TRUCKLOADS OF SOIL WITH ODORS FOR DISPOSAL, THE CLAY SOIL CONTAINED THE LEAKAGE TO NEAR THE EXCAVATION, TYREE WAS ABOUT TO INSTALL A NEW TANK AT THE TIME OF THE INSPECTION. 11/7/01:RECEIVED TANK CLOSURE REPORT FROM GZA, TAGM 4046 GUIDANCE VALUES WERE EXCEEDED FOR TANK REMOVAL EXCAVATION BOTTOM SAMPLE AND FOR NUMEROUS SAMPLES ALONG THE PIPING LINE ESPECIALLY NEAR SAMPLE BHP-5 WHICH HAD THE HIGHEST VALUES. 11/26/01:SAC TELECON MARTIN WESOLOWSKI - LIRO-KASSNER, INC. NOTIFYING HIM ADDITIONAL WORK IS REQUIRED IN THE PIPING AREA, HE IS SCHEDULED TO PERFORM ADDITIONAL WORK ON 11/29/01 AND WILL SEE IF HE CAN ADDRESS THIS AREA ON THAT DAY. 11/26/01:DRAFTED LETTER TO TED KRYGIER - SUNYAB REGARDING FURTHER WORK BEING REQUIRED IN THE PIPING AREA, ALTHOUGH MR. WESOLOWSKI MAY ADDRESS SITE THIS WEEK REQUESTED WORKPLAN IN THE LETTER BY 12/17/01. 11/27/01:SAC SPOKE TO RJJ, LI-RO KASSNER IS ARRANGING FOR TYREE TO COME BACK TO THE SITE AND ADDRESS THE AREA OF CONCERN. 11/29/01:SAC TELECON MARTIN WESOLOWSKI REGARDING REQUEST FOR ADDITIONAL WORK, EITHER REMOVAL AND DISPOSAL IS REQUIRED OR ADDITONAL INVESTIGATION INCLUDING BORINGS, LOGS, AND ANALYSIS REQUIRED, MR. WESOLOWSKI WILL DISCUSS THE OPTIONS WITH THE UNIVERSITY. 12/7/01:SAC SPOKE TO RJJ, RJJ INSPECTED SITE, THERE IS AIR VENT PIPING FOR THE BUILDING DIRECTLY BELOW THE TANK PIPING AND THERE IS LIMITED SPACE IN BETWEEN THE BUILDINGS FOR EXCAVATION, THEY ARE GOING TO CUT A TRENCH ALONG THE PIPING AND TAKE 6 SAMPLES TO FURTHER INVESTIGATE THE AREA. 12/10/01:SAC SPOKE TO RJJ, BFG AND RJJ INSPECTED SITE BUT BY THE TIME THEY INSPECTED THE TRENCH HAD BEEN BACKFILLED, THE TRENCH WAS ABOUT A HUNDRED FEET LONG AND RUN THE LENGTH OF THE BUILDING AND WHERE THE NEW PIPE WAS INSTALLED. 2/20/02:RECEIVED REPORT OF ADDITIONAL SOIL REMOVAL FROM GZA, INC. DATED JANUARY 31, 2002, ONLY HALF OF THE LINE WAS EXCAVATED AND NOT IN THE AREA OF BHP-5 AND BHP-7, 4 SAMPLES TAKEN WHERE EXCAVATION WAS PERFORMED AND THE RESULTS WERE BQL, DRAFTED LETTER REQUIRING FURTHER WORK IN AREAS OF BHP-5 AND BHP-7, REQUEST WORKPLAN BY 4/1/02. 4/4/02:SAC TELECON MARTIN WESOLOWSKI, MR. WESOLOWSKI WILL BE SUBMITTING A WORKPLAN WHERE THEY WILL BE EXCAVATING THE AREA THAT REMAINS TO BE ADDRESSED AND ALSO SAMPLE THE AREA BUT THEY ARE WAITING FOR A REPLY ON THE JACOBS MANAGEMENT CENTER WORK SINCE THEY WANT TO MOBILIZE AT THE SAME TIME TO COMPLETE THIS WORK. 4/11/02:RECEIVED WORKPLAN FOR ADDITIONAL WORK NEXT TO BHP-5 & BHP-7. 4/15/02:SAC TELECON MARTIN WESOLOWSKI, WORKPLAN STATED EXCAVATION WOULD TAKE PLACE TO A DEPTH OF 3 FT, SAC ASKED HOW DEEP THE PIPING INVOLVED WITH THE TANK IS, MR. WESOLOWSKI SAID IT WAS ABOUT 1 FT. DEEP DUE TO THE AIR VENT DUCT PIPING BELOW THE THE TANK PIPING, SAC DRAFTED COMMENT LETTER ACCEPTING WORK PLAN W/AN ADDITIONAL SIDEWALL SAMPLE REQUIRED ALONG WITH THE PROPoSED BOTTOM SAMPLES. 5/31/02:RECEIVED NOTIFICATION THAT ADDITIONAL EXCAVATION WOULD TAKE PLACE ON 6/4/02. 6/4/02:SAC TELECON MARTIN WESOLOWSKI, MR. WESOLOWSKI SAID WORK WILL TAKE PLACE TOMORROW INSTEAD OF TODAY. 6/5/02:SAC INSPECT SITE, TRENCH HAS BEEN EXCAVATED, NO ONE ELSE ON SITE, NO STAINING OBSERVED, SAC DID NOT TAKE SAMPLE TO OBSERVE ODORS BUT NO ODORS WERE OBSERVED STANDING NEXT TO THE TRENCH, ON END OF TRENCH AT THE MIDDLE OF BUILDING THERE WAS A BLACK TAR/ASPHALT LIKE SUBSTANCE. 6/6/02:SAC TELECON MARTIN WESOLOWSKI, DISCUSSED THAT TRENCH HAD BEEN DUG, CLARIFIED REQUEST THAT EPA METHOD 8270 SHOULD BE RUN ON THE SAMPLE ALONG WITH A VOLATILE SCAN - NOT AN 8021 AND 8260

UNIVERSITY OF BUFFALO (Continued) **S105135293**

AS WAS NOTED IN COMMENT LETTER DATED 4/16/02. 7/1/02:RECEIVED CONFIRMATORY SAMPLE RESULTS FROM THE EXCAVATION, RESULTS WERE BELOW TAGM 4046 VALUES BUT NOT STARS MEMO #1 VALUES, NO FURTHER EXCAVATION IS REQUIRED, SAC TELECON MARTIN WESOLOWSKI, SOIL WAS MIXED WITH THE SOIL FROM THE JACOBS MANAGEMENT CENTER CLEANUP AND STILL NEEDS TO BE DISPOSED, ONCE THIS HAS BEEN COMPLETED SPILL WILL BE GIVEN NO FURTHER ACTION STATUS. 1/30/03:RECEIVED DISPOSAL RECEIPTS, NO FURTHER WORK REQUIRED, I LETTER DRAFTED."

Remarks: "contaminated soil discovered from tank removal"

All Materials:

Site ID:	262404
Operable Unit ID:	841457
Operable Unit:	01
Material ID:	533185
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AY240 **ALUMNI ARENA -SUNYAB** **NY LTANKS** **S103479202**
North **WEBSTER ROAD** **N/A**
< 1/8 **AMHERST, NY**
0.122 mi.
642 ft. **Site 6 of 16 in cluster AY**

Actual: **586 ft.**

Focus Map: **4**

LTANKS:

Spill Number/Closed Date:	9805985 / 1998-11-27
Facility ID:	9805985
Site ID:	108226
Spill Date:	1998-08-01
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	1522
Investigator:	SACALAND
Referred To:	Not reported
Reported to Dept:	1998-08-06
CID:	999
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	1998-11-03
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1998-08-13
Spill Record Last Update:	1998-12-03
Spiller Name:	GENE MONACELL
Spiller Company:	SUNYAB
Spiller Address:	MICHAEL HALL-3435 MAIN ST
Spiller County:	001

ALUMNI ARENA -SUNYAB (Continued) **S103479202**

Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	9
DER Facility ID:	95128
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SAC 8/17/98:SAC INSPECT,MET W/GENE MONACELL-SUNYAB,EXCAVATION WAS ALREADY FILLED IN, TANK WAS REMOVED & STILL ON-SITE,MR.MONACELL SHOWED TANK DID HAVE A HOLE,CONTAMINATED SOIL STAGED ON SITE,TANK SIZE WAS 550 GALLONS. 8/21/98:TREATMENT FORM LETTER DRAFTED. 9/24/98:RECEIVED ANALYTICAL RESULTS FROM THE TANK REMOVAL, STARS GUIDANCE VALUES EXCEEDED FOR EPA METHOD 8021, DRAFTED LETTER ALLOWING THE OPTION FOR RETESTING USING TCLP 8021 OR REMOVING MORE SOIL AND RETESTING, REQUIRE OPTION SELECTION BY 10/15/98. 10/13/98:RECEIVED LETTER AND SAC TELECON GENE MONACELL LAST WEEK, THEY WILL DIG UP ADDITIONAL CONTAMINATED SOIL AND RETEST SITE. 10/20/98:SAC TELECON GENE MONACELL, SUNYAB THEY HAVE REDUG THE TANK LOCATION UNTIL THEY HIT CONCRETE WHICH IS A VAULT FOR THE ELECTRICAL LINES, THEY HAVE TAKEN A SAMPLE OF THE BOTTOM AT THE BASE OF ALL FOUR SIDES OF THE EXCAVATION. 11/3/98:RNL, SAC INSPECT RE- EXCAVATED TANK SITE, NO CONTAMINATION OBSERVED, SOIL PILE NOTED NEXT TO THE EXCAVATION. 11/12/98:SAC TELECON GENE MONACELL, SUNYAB - HE HAS MAILED THE EXCAVATION RESULTS FOR THE TANK AREA, FROM CONVERSATION IT APPEARS THAT LEVELS ARE NOW BELOW STARS GUIDANCE VALUES, EXCAVATED SOIL HAS NOT YET BEEN DISPOSED BUT IT SHOULD GO TO MODERN LANDFILL. 11/13/98:RECEIVED ANALYTICAL RESULTS FROM THE RESAMPLING, RESULTS ARE BELOW STARS MEMO #1 PETROLEUM CONTAMINATED SOIL GUIDANCE VALUES, NEED DISPOSAL RECEIPTS TO CLOSE FILE. 11/27/98:RECEIVED DISPOSAL RECEIPTS."
	Not reported
Remarks:	"WATER FOUND IN DIESEL TANK FOR AN EMERGENCY GENERATOR "

All Materials:

Site ID:	108226
Operable Unit ID:	1067169
Operable Unit:	01
Material ID:	317161
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AY241 **SUNY BUFFALO NORTH CAMPUS** **NY Spills** **S105057386**
North **SERVICE CENTER RD** **N/A**
< 1/8 **BUFFALO, NY**
0.122 mi.
642 ft. **Site 7 of 16 in cluster AY**

Actual:
586 ft.

Focus Map:
4

SPILLS:

Spill Number/Closed Date:	0101732 / 2001-11-08
Facility ID:	0101732
Facility Type:	ER
DER Facility ID:	225276
Site ID:	277089

SUNY BUFFALO NORTH CAMPUS (Continued) **S105057386**

DEC Region:	9
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	1502
Spill Date:	2001-05-15
Investigator:	RJJONAK
Referred To:	Not reported
Reported to Dept:	2001-05-15
CID:	396
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	2001-05-24
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-05-15
Spill Record Last Update:	2001-11-08
Spiller Name:	SAME
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	ROBERT GROCK
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RJJ 5/24/2001: RJJ AT SITE AT 1000...TYREE REMOVED A TANK ON 5/15/2001 AND THE EXCAVATION PIT AREA IS ABOUT 25X10X8'...THEY WILL SEND ME THE ANALYTICAL RESULTS FROM THE WALL AND FLOOR SAMPLES...THE PIT LOOKS AND SMELLS CLEAN. 11/8/2001: RECEIVED THE FINAL UST CLOSURE REPORT FROM GZA,WHICH INCLUDES ALL THE SOIL DISPOSAL RECEIPTS AND THE ANALYTICAL RESULTS FROM THE EXCAVATION...ALL THE ANALYTICAL RESULTS ARE BELOW OUR 'STARS' GUIDANCE VALUES AND ALL THE PAPERWORK IS IN ORDER...NO FURTHER ACTION NEEDED...SPILL CLOSED OUT."
Remarks:	"TYREE ON SITE REMOVING A TANK...EXCAVATION INPROGREESS..CLEAN UP WILL BE DONE...HELM WAREHOUSE IS WHERE SPILL IS."

All Materials:

Site ID:	277089
Operable Unit ID:	840557
Operable Unit:	01
Material ID:	537439
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AY242 **SUNYAB-AMHERST** **NY Spills** **S102177532**
North **MILLERSPORT BUILDING 40** **N/A**
< 1/8 **AMHERST, NY**
0.122 mi.
642 ft. **Site 8 of 16 in cluster AY**

Actual:
586 ft.

Focus Map:
4

SPILLS:

Spill Number/Closed Date:	9007861 / 1990-10-25
Facility ID:	9007861
Facility Type:	ER
DER Facility ID:	124481
Site ID:	146156
DEC Region:	9
Spill Cause:	Deliberate
Spill Class:	Not reported
SWIS:	1522
Spill Date:	1990-10-18
Investigator:	MXFRANKS
Referred To:	Not reported
Reported to Dept:	1990-10-18
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	1990-10-15
Cleanup Meets Std:	True
Last Inspection:	1990-10-18
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1990-10-18
Spill Record Last Update:	1990-11-03
Spiller Name:	Not reported
Spiller Company:	MICHAEL HUGHES & SONS
Spiller Address:	540 BROAD STREET
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MF 10/15/90: MF RECEIVED OIL CHANGE LETTER FROM ALLEGED SPILLER. NO FUTHER ACTION NECESSARY. 10/18/90: MF SITE VISIT, NO SPILLAGE NOTED. UNION/NON-UNION PROBLEMS. "
Remarks:	"COMPLAINT OF WASTE OIL DUMPING AT A NON UNION CONSTRUCTION SITE."

All Materials:

Site ID:	146156
Operable Unit ID:	945107
Operable Unit:	01
Material ID:	431696
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

AY243 **UB CAMPUS** **NY Spills** **S102174848**
North **SKINNERSVILLE ROAD** **N/A**
< 1/8 **AMHERST, NY**
0.122 mi.
642 ft. **Site 9 of 16 in cluster AY**

Actual:
586 ft.

Focus Map:
4

SPILLS:

Spill Number/Closed Date:	9207489 / 1992-10-20
Facility ID:	9207489
Facility Type:	ER
DER Facility ID:	214965
Site ID:	263707
DEC Region:	9
Spill Cause:	Unknown
Spill Class:	C6
SWIS:	1522
Spill Date:	1992-09-28
Investigator:	SORGI
Referred To:	Not reported
Reported to Dept:	1992-09-28
CID:	Not reported
Water Affected:	ELLICOTT CREEK
Spill Source:	Unknown
Spill Notifier:	Citizen
Cleanup Ceased:	1992-09-28
Cleanup Meets Std:	True
Last Inspection:	1992-09-28
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1992-09-29
Spill Record Last Update:	1992-10-28
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MJS 10/20/92: MJS SITE INSPECT. NO OIL OR SHEEN NOTICED. TWO MEN FISHING FOR 2 HOURS AND HAVE NOTICED NOTHING. NO FURTHER ACTION TO BE TAKEN. MJS TO CLOSE FILE. "
Remarks:	"GAS OR OIL FLOWING FROM U.B. CAMPUS; FLOWS OFF THE CAMPUS. SHEEN NOTICED."

All Materials:

Site ID:	263707
Operable Unit ID:	971134
Operable Unit:	01
Material ID:	408127
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AY244 **BLUE BIRD BUS LINE** **NY Spills** **S102176377**
North **SUNY AMHERST CAMPUS** **N/A**
< 1/8 **AMHERST, NY**
0.122 mi.
642 ft. **Site 10 of 16 in cluster AY**

Actual:
586 ft.

Focus Map:
4

SPILLS:

Spill Number/Closed Date:	8805153 / 1988-09-21
Facility ID:	8805153
Facility Type:	ER
DER Facility ID:	127279
Site ID:	149662
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	1522
Spill Date:	1988-09-14
Investigator:	COOKE
Referred To:	Not reported
Reported to Dept:	1988-09-14
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Affected Persons
Cleanup Ceased:	1988-09-21
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1988-09-20
Spill Record Last Update:	1988-10-13
Spiller Name:	Not reported
Spiller Company:	BLUE BIRD BUS
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was JDC 09/20/88: SUNY PERSONEL APPLIED SPEEDY DRY AND SWEPT UP AFFECTED ROAD SURFACE.MR MONTICELL WILL BE FORWARDING INCIDENT REPORT. 09/21/88: JDC RECIEVED INCIDENT REPORT- RESPONSE ACTIONS IDENTIFIED IN LETTER SATISFACTORY. NO FURTHER ACTION WILL BE RQUIRED AT THIS TIME. "
Remarks:	"BUS FUEL TANK LEAKING OUT FUEL WHEN MAKING TURNS."

All Materials:

Site ID:	149662
Operable Unit ID:	920312
Operable Unit:	01
Material ID:	457062
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	6.00
Units:	G
Recovered:	5.00
Oxygenate:	Not reported

AY245 **JACOB'S MANAGEMENT CNTR** **NY LTANKS** **S105055040**
North **SUNY BUFFALO** **N/A**
< 1/8 **AMHERST, NY**
0.122 mi.
642 ft. **Site 11 of 16 in cluster AY**

Actual:
586 ft.

Focus Map:
4

LTANKS:

Spill Number/Closed Date:	0102567 / 2003-01-29
Facility ID:	0102567
Site ID:	235289
Spill Date:	2001-06-07
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	1522
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	2001-06-07
CID:	323
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	2002-07-02
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2001-06-07
Spill Record Last Update:	2003-01-30
Spiller Name:	ROBERT GROCK
Spiller Company:	JACOB'S MANAGEMENT CNTR
Spiller Address:	SUNY BUFFALO
Spiller County:	001
Spiller Contact:	ROBERT GROCK
Spiller Phone:	(518) 469-4310
Spiller Extention:	Not reported
DEC Region:	9
DER Facility ID:	193798
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 06/06/01 RMC/BOB GROCK, TYREE/PHONE, NO VISUAL CONTAMINATION FOUND, METER WAS MALFUNCTIONING, RMC ADVISED TO SAMPLE AND SEND IN RESULTS TO PBS FOR REVIEW, NO SOIL WAS STOCKPILED, NO SPILL ACTION REQUIRED, CLOSE OUT 01/17/02 RMC/FILE. RECEIVED REPORT ON SITE, IT APPEARS THAT 3 CU YARDS OF SOIL WAS REMOVED, POST EXCAVTION SAMPLES SHOWED SIGNIFICANT EXCEEDANCES OF TAGM, SENT TO SAC FOR REVIEW. \\ 01/18/02 RMC/FILE. LETTER REQUIRING FUTHER REMEDIATION. RESPONSE DUE 2/28/02 1/25/02 RMC/MARTIN W. 882-5476, REQUESTED NO FURTHER ACTION DUE TO UTILITIES PROBLEMS, RMC ADVISED NO, DEC AT LEAST WILL REQUIRED A SITE ASSESSMENT TO DETERMINE THE EXTENT, HE WILL SEND PLAN. DUE 2/28/02 02/14/02 RMC/FILE. RECEIVED AND RESPONDED TO LETTER FORM CONTRACTOR, PLAN DUE 2/28/02 03/14/02 RMC/FILE. RECEIVED REPORT. PLAN TO EXCAVATED WHERE HIGHEST ANALYITICAL READING WERE FOUND, CAN NOT PRACTICALLY GET TO AREAS 7,8,10, AND 15. REPORT DUE 5/30/02 06/03/01 RMC/FILE. RECEIVED FAX, ADDITIONAL EXCAVATION TO START 6/5/02 07/02/02 RMC/FILE. RP EXCAVATED FURTHER, KEVIN GLASIER WAS ON SITE FOR THE WORK, HE NOTED NO VISUAL CONTAMINATION. STOCKPILED SOIL FOR DISPOSAL. RMC RECIEVED NUMEROUS SETS OF SAMPLE RESULTS. NO EXCEEDANCES IN VOLS. SOME EXCEEDANCES IN SEMI VOLS. IN SEVERAL SAMPLES. RMC NOTED NO VISUAL CONTAMINATION NOTED, THAT THE RP

JACOB'S MANAGEMENT CNTR (Continued) **S105055040**

EXCAVATED TO THE LIMITS OF REASON, AND THAT THE SITE CONTINUES TO BE A PBS SITE. RMC RECOMMENDS SITE TO BE MADE INACTIVE PENDING DISPOSAL, DUE 8/30/02 12/02/02 RMC/FILE. LEFT MESSAGE REQUESTING DISPOSAL RECEIPTS. DUE 12/15/02 01/07/03 RMC/FILE. LEFT MESSAGE FOR MARTIN WELOLOWSKI REQUESTING DISPOSAL RECEIPTS DUE 1/30/03 01/10/03 RMC/MARTING WESOLOWSKI/PHONE. MATERIAL DISPOSED OF, RECEIPTS DUE 1/31/03 01/29/03 RMC/FILE RECEIVED DISPOSAL RECEIPTS FOR CONTAMINATED SOIL REMOVED, OK, LETTER. INACTIVE."

Remarks: "WHILE REMOVIGN A TANK, CONTAMINATED SOIL WAS DISCOVERED. SOIL IS BEING STOCKPILED. "

All Materials:

Site ID:	235289
Operable Unit ID:	841267
Operable Unit:	01
Material ID:	534683
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AY246 **SUNY BUFFALO** **NY LTANKS** **S105054933**
North **TALBERT HALL** **N/A**
< 1/8 **AMHERST, NY**
0.122 mi.
642 ft. **Site 12 of 16 in cluster AY**

Actual: **586 ft.**

Focus Map: **4**

LTANKS:

Spill Number/Closed Date:	0102018 / 2002-02-19
Facility ID:	0102018
Site ID:	245095
Spill Date:	2001-05-22
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	1522
Investigator:	RJJONAK
Referred To:	Not reported
Reported to Dept:	2001-05-22
CID:	396
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	2001-05-22
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-05-22
Spill Record Last Update:	2002-02-19
Spiller Name:	SAME
Spiller Company:	SAME
Spiller Address:	Not reported

SUNY BUFFALO (Continued) **S105054933**

Spiller County:	001
Spiller Contact:	DICK CLEMENTS
Spiller Phone:	(518) 786-3200
Spiller Extention:	204
DEC Region:	9
DER Facility ID:	201333
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RJJ 5/22/2001: RJJ TELECON BOB GROCK,TYREE,HE SAID THAT THEY REMOVED A 500 GAL DIESEL TANK AND ENCOUNTERED CONTAMINATED SOIL...THEY WILL BE REMEDIATING THE SITE...TYREE SUB-CONTRACTED GZA TO DO THE TANK CLEANING AND SOIL SAMPLING...BOB WILL SEND ME THE REPORT...RJJ AT SITE AT 1500...MEET WITH BOB GROCK...THE EXCAVATION IS ABOUT 8'X6'X8' AND LOOKS AND SMELLS CLEAN...THEY ARE STARTING TO BACKFILL...BOB WILL SEND ME THE REPORT. 2/19/2002: RECEIVED THE UST CLOSURE REPORT FROM GZA,WHICH INCLUDES ALL THE SOIL DISPOSAL RECEIPTS AND ANALYTICAL DATA...ALL THE ANALYTICAL RESULTS ARE BELOW OUR 'STARS' GUIDANCE VALUES...THE 500 GAL DIESEL FUEL TANK HAS BEEN REMOVED AND PROPERLY DISPOSED OF,AND THE CONTAMINATED SOIL HAS BEEN DISPOSED OF...DRAFTED AND SENT A 'CLOSURE' LETTER...NO FURTHER ACTION NEEDED...SPILL CLOSED OUT."
Remarks:	"tank was being removed and soil cont. was found...clean up will be started."

All Materials:

Site ID:	245095
Operable Unit ID:	840831
Operable Unit:	01
Material ID:	537709
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AY247 **PORTER QUAD - ELLICOTT** **NY LTANKS** **S104877523**
North **JOHN JAMES AUDUBON PRKWAY** **N/A**
< 1/8 **AMHERST, NY**
0.122 mi.
642 ft. **Site 13 of 16 in cluster AY**

Actual:
586 ft.

Focus Map:
4

LTANKS:

Spill Number/Closed Date:	0075540 / 2001-10-01
Facility ID:	0075540
Site ID:	197080
Spill Date:	2000-12-01
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	1522
Investigator:	RJJONAK
Referred To:	Not reported
Reported to Dept:	2000-12-28
CID:	Not reported

PORTER QUAD - ELLICOTT (Continued) **S104877523**

Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	2001-01-23
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-12-28
Spill Record Last Update:	2002-12-04
Spiller Name:	THEODORE KRIEGER
Spiller Company:	SUNYAB
Spiller Address:	MILLERSPORT & MAPLE
Spiller County:	001
Spiller Contact:	RON KNOX
Spiller Phone:	(716) 912-2799
Spiller Extention:	Not reported
DEC Region:	9
DER Facility ID:	164049
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RJJ 1/12/2001: RECEIVED THE ANALYTICAL RESULTS FROM CHRIS BORON OF GZA...THE RESULTS INDICATE HIGH LEVELS OF CONTAMINATION,ABOVE TAGA 4046 GUILDANCE LEVELS,WHICH WILL HAVE TO BE REMEDIATED. 1/23/2001: MARTIN WESOLOWSKI,LIRO-KASSNER,INC.# 759-0887,TELECON RJJ AND ASKED ME MY ADVICE ON THIS SITE...I TOLD HIM THAT DUE TO THE HIGH LEVELS OF CONTAMINATION,EITHER IN-SITU,OR SOIL REMOVAL WILL HAVE TO BE DONE,EVENTHOUGH THE TANK IS UNDER A LOADING DOCK...MARTIN WILL TALK WITH THE CAMPUS AND KEEP ME INFORMED...THE WORK MAY HAVE TO WAIT UNTIL SUMMER,SINCE THE LOADING DOCK IS CONSTANTLY USED. 4/17/2001: RECEIVED A SUPPLEMENTAL REPORT FROM LIRO-KASSNER,MARTIN WESOLOWSKI,ON THE PORTER-QUAD UST,AND DISCUSSED THE RESULTS WITH RNL...THE SOIL BORINGS INDICATE THAT THE CONTAMINATION DID NOT TRAVEL PAST THE TANK AREA,SO THEY WILL CLOSE THE TANK IN-PLACE,SINCE THE LEVELS ARE WITHIN EXPOSURE ASSESSMENT LEVELS...MARTIN WILL CONTACT ME WHEN THEY PLAN ON DOING THIS. 5/7/2001: RJJ DRAFTED AND SENT A LETTER TO LIRO-KASSNER APPROVING THEIR WORK PLAN FOR PORTER-QUAD. 9/28/2001: RECEIVED THE FINAL CLOSURE UST REPORT FROM GZA...THEY CLOSED THE 500 GAL. DIESEL FUEL TANK IN-PLACE ON 8/20/2001...ALL THE PAPERWORK IS IN ORDER...DRAFTED AND SENT AN 'INACTIVE' LETTER TO LIRO-KASSNER...NO FURTHER ACTION NEEDED...SPILL CLOSED OUT."
Remarks:	"CONTAMINATION FOUND WHILE DOING A GEOPROBE SITE ASSESSMENT AROUND THE 550 GALLON TANK, TANK TO BE REMOVED IN THE SUMMER WHEN SCHOOL IS OUT, 3 GEOPROBES INSTALLED, ONE BORING HAD CONTAMINATION AT 7 TO 12 FEET."

All Materials:

Site ID:	197080
Operable Unit ID:	836904
Operable Unit:	01
Material ID:	539118
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AY248 **STATE UNIV BUFFALO NORTH** **NY LTANKS** **S104950858**
North **LOCKWOOD LIBRARY** **N/A**
< 1/8 **AMHERST, NY**
0.122 mi.
642 ft. **Site 14 of 16 in cluster AY**

Actual:
586 ft.

Focus Map:
4

LTANKS:

Spill Number/Closed Date:	0011535 / 2002-02-19
Facility ID:	0011535
Site ID:	290318
Spill Date:	2001-01-25
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	1522
Investigator:	RJJONAK
Referred To:	Not reported
Reported to Dept:	2001-01-25
CID:	323
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	2001-12-07
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2001-01-25
Spill Record Last Update:	2002-02-19
Spiller Name:	GENE MONTICELL
Spiller Company:	STATE UNIV BUFFALO NORTH
Spiller Address:	LOCKWOOD LIBRARY
Spiller County:	001
Spiller Contact:	ROBERT GROCK
Spiller Phone:	(518) 469-4310
Spiller Extention:	Not reported
DEC Region:	9
DER Facility ID:	235083
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RJJ 1/24/2001: RJJ AT SITE AT 1100...TYREE HAS REMOVED THE UST IN FRONT OF THE LOCKWOOD LIBARY AND THE EXCAVATION LOOKS AND SMELLS CLEAN...THEY WILL TAKE WALL/FLOOR SAMPLES AND ALSO SOIL SAMPLES UNDER THE PIPING AND SEND ME THE RESULTS. 11/13/2001: RECEIVED THE UST CLOSURE REPORT FROM GZA...ALL THE ANALYTICAL RESULTS ARE BELOW OUR GUIDANCE LEVELS EXCEPT FOR LOCKWOOD PIPE #4 WHICH GREATLY EXCEEDS OUR TAGA 4046 LEVELS...I TELECON CHRIS BORON,GZA,AND EXPLAINED THAT MORE REMEDIATION WILL BE NEEDED AT THAT LOCATION...HE SAID THAT HE WILL CALL MARTIN WESLOWSKI,LIRO-KASSNER,AND DISCUSS THIS WITH HIM AND CALL ME BACK. 11/14/2001: MARTIN WESLOWSKI TELECON RJJ,HE SAID THAT THEY WILL RE-EXCAVATE THE AREA AT LOCKWOOD PIPE #4 AND RESAMPLE,SINCE THE ANALYTICAL RESULTS WERE HIGHER THAN OUR TAGA GUIDANCE LEVELS. 11/21/2001: MARTIN WESLOWSKI TELECON RJJ,SAID THAT THEY WILL BEGIN 11/29/01 TO REMOVE THE ADDITIONAL CONTAMINATED SOIL AND RESAMPLE,AND SEND ME THE RESULTS. 12/7/2001: RJJ AT SITE AT 0800...MEET WITH MARTIN WESLOWSKI,THEY ARE RE-EXCAVATING THE AREA WHERE THE FUEL PORT WAS,AND WILL SAMPLE THE BOTTOM,WHICH CAME BACK HIGHER THAN OUR TAGA LEVELS...THE EXCAVATION AREA IS ONLY ABOUT 3'X3'X3' DEEP...MARTIN WILL SEND ME THE RESULTS. 2/19/2002: RECEIVED THE ADDITIONAL SOIL REMOVAL REPORT FROM GZA,WHICH INCLUDES THE CONTAMINTED SOIL DISPOSAL

STATE UNIV BUFFALO NORTH (Continued) **S104950858**

RECEIPTS...ALL THE ANALYTICAL RESULTS ARE NOW ALL BELOW OUR 'STARS' GUIDANCE VALUES...DRAFTED AND SENT A 'CLOSURE' LETTER...NO FURTHER ACTION NEEDED...SPILL CLOSED OUT."

Remarks: "UNDERGROUND TANK WAS REMOVED DURING EXCAVATION AND WAS FOUND TO BE LEAKING. SOIL IS STOCKPILED. NORTH SIDE OF LOCKWOOD LIBRARY MECHANICAL ROOM."

All Materials:

Site ID:	290318
Operable Unit ID:	833583
Operable Unit:	01
Material ID:	541844
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AY249 **SUNY AT BUFFALO** **NY Spills** **S106007370**
North **FRONTIER ST** **N/A**
< 1/8 **AMHERST, NY**
0.122 mi.
642 ft. **Site 15 of 16 in cluster AY**

Actual:
586 ft.

Focus Map:
4

SPILLS:

Spill Number/Closed Date:	0206015 / 2002-09-11
Facility ID:	0206015
Facility Type:	ER
DER Facility ID:	133924
Site ID:	158489
DEC Region:	9
Spill Cause:	Deliberate
Spill Class:	E5
SWIS:	1522
Spill Date:	2002-09-11
Investigator:	SACALAND
Referred To:	Not reported
Reported to Dept:	2002-09-11
CID:	390
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-09-11
Spill Record Last Update:	2002-09-11
Spiller Name:	UNK
Spiller Company:	SUNY AT BUFFALO
Spiller Address:	FRONTIER ST
Spiller Company:	001

SUNY AT BUFFALO (Continued) **S106007370**

Contact Name: UNK
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was SAC 9/11/02:GAP - DUTY OFFICER REFERRED SPILL TO DIV OF WATER, NO FURTHER ACTION REQUIRED BY SPILLS."
Remarks: "JANITORS ARE DUMPING USED CLEANING SUPPLIES INTO SANITARY SEWER."

All Materials:
Site ID: 158489
Operable Unit ID: 858500
Operable Unit: 01
Material ID: 516631
Material Code: 0045A
Material Name: cleaning chemicals/products
Case No.: Not reported
Material FA: Other
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

AY250 **NYS SUNY CAMPUS** **NY Spills** **S105140936**
North **JARVIS HALL** **N/A**
< 1/8 **AMHERST, NY**
0.122 mi.
642 ft. **Site 16 of 16 in cluster AY**

Actual:
586 ft.

Focus Map:
4

SPILLS:
Spill Number/Closed Date: 0104381 / 2002-02-19
Facility ID: 0104381
Facility Type: ER
DER Facility ID: 104958
Site ID: 120930
DEC Region: 9
Spill Cause: Unknown
Spill Class: C3
SWIS: 1522
Spill Date: 2001-07-24
Investigator: SACALAND
Referred To: Not reported
Reported to Dept: 2001-07-24
CID: 282
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: 2001-07-26
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2001-07-24
Spill Record Last Update: 2002-02-19
Spiller Name: TED KRYGIER
Spiller Company: SUNY AT BUFFALO
Spiller Address: 119 JOHN BEANE CENTER
Spiller Company: 001
Contact Name: BOB GROCK

NYS SUNY CAMPUS (Continued) **S105140936**

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was SAC 7/24/01:SAC INSPECT SITE, FOUND AREA WHERE TANK WAS LOCATED NEXT TO JARVIS HALL, WATER IN EXCAVATION HAS WHAT APPEARS TO BE A SCUM, PRODUCT LAYER, ODORS ALSO APPARENT, TIME OF INSPECTION WAS AROUND 1800 HRS SO THERE WAS NO ONE AROUND AT THAT TIME. 7/25/01:SAC INSPECT SITE, MET W/BOB GROCK - THE TYREE ORGANIZATION AND RAY LAPORT - GZA, PER MR. GROCK AND MR. LAPORT THE TANK SIZE WAS 500 GALLONS AND IT DID NOT HAVE ANY HOLES IN IT AND THE PIPING WAS WRAPPED SO THERE WAS NO LEAK IN THE LINES, IT WAS A SMALL EXCAVATION, THEY BELIEVE THE CONTAMINATION WAS FROM OVERFILLS, THEY ALSO BELIEVE THE GROUNDWATER IS PERCHED BECAUSE OF THE CLAY IN THE AREA BUT PEASTONE WAS USED TO BACKFILL AROUND THE TANK CAUSING A BATHTUB EFFECT, THE WERE WAITING FOR A VACUUM TRUCK TO COME ON THE SCENE TO REMOVE THE CONTAMINATED WATER, THEY WILL CLEAN OUT THE HOLE AND THEN SAMPLE IT, THEY DO NOT BELIEVE THE CONTAMINATION IS EXTENSIVE. 7/25/01:SAC TELECON RAY LAPORT, PER MR. LAPORT THEY HAVE DUG AS MUCH AS THEY CAN AND THE PEA GRAVEL HAS BEGUN TO FALL INTO THE EXCAVATION, THERE IS A CONCRETE PAD THERE AND THAT ALSO CANNOT BE REMOVED SINCE IT ALSO CAUSE A PROBLEM WITH THE BUILDING FOUNDATION, HE PROPOSED TO SAMPLE THE SIDES OF THE EXCAVATION, SAC SAID HE MUST ALSO SAMPLE THE BOTTOM OF THE EXCAVATION BY INSTALLING A BORING BENEATH THE DEPTH OF THE CONCRETE PAD, SAC RECEIVED A PHONE CALL FROM JEFF TENNISON OF THE UNIVERSITY AND DISCUSSED THE SITUATION WITH HIM. 7/26/01:SAC INSPECT SITE, MET W/MARTIN WESOLOWSKI AND RON KNOX FROM LIRO-KASSNER, INC., EXCAVATION HAD ABOUT 1.5 TO 2 FT OF WATER IN IT, SHEEN WAS OBSERVED, NO ODORS OBSERVED, SIDE SAMLES HAV BEEN TAKEN, THEY WILL PUMP WATER OUT AND ATTEMPT TO GRAB A SAMPLE FROM THE BOTTOM, IF THEY ARE UNABLE TO COMPLETE THIS WORK THEY WILL USE A GEOPROBE TO INSTALL BORINGS. 2/19/02:RECEIVED TANK CLOSURE REPORT COMPLETE W/DISPOSAL RECEIPTS FOR SOIL AND GW, CONFIRMATORY SOIL SAMPLES BELOW TAGM 4046 GUIDANCE VALUES, ONE SAMPLE ABOVE STARS GUIDANCE VALUES, WATER SAMPLE THAT WAS PUMPED OUT EXCEEDED GW STANDARDS, NO FURTHER WORK REQQUIRED BY SPILLS. "

Remarks: "THEY REMOVED A TANK AND FOUND CONTAMINATED SOIL AND WATER. THEY ARE ON THE SCENE NOW. "

All Materials:

Site ID:	120930
Operable Unit ID:	841016
Operable Unit:	01
Material ID:	532876
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AX251 **PRINTS CHARMING** **NY UST** **U004272437**
West **2900 SHERIDAN DR** **N/A**
1/8-1/4 **TONAWANDA, NY 14150**
0.126 mi.
664 ft. **Site 3 of 4 in cluster AX**

Actual:
595 ft.

Focus Map:
6

UST:

Id/Status:	9-601730 / Unregistered
Program Type:	PBS
Region:	STATE
DEC Region:	9
Expiration Date:	N/A
UTM X:	Not reported
UTM Y:	Not reported
Site Type:	Other

Affiliation Records:

Site Id:	548787
Affiliation Type:	Facility Owner
Company Name:	ROBERT ANTHONE
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	2900 SHERIDAN
Address2:	Not reported
City:	TONAWANDA
State:	NY
Zip Code:	14150
Country Code:	001
Phone:	(716) 875-0750
EMail:	Not reported
Fax Number:	Not reported
Modified By:	SRMCDONN
Date Last Modified:	2017-05-22

Site Id:	548787
Affiliation Type:	Mail Contact
Company Name:	ROBERT ANTHONE
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	2900 SHERIDAN
Address2:	Not reported
City:	TONAWANDA
State:	NY
Zip Code:	14150
Country Code:	001
Phone:	(716) 875-0750
EMail:	Not reported
Fax Number:	Not reported
Modified By:	SRMCDONN
Date Last Modified:	2017-05-22

Tank Info:

Tank Number:	1
Tank ID:	268378
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	1000
Install Date:	Not reported

PRINTS CHARMING (Continued) **U004272437**

Date Tank Closed:	11/09/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	SRMCDONN
Last Modified:	05/22/2017

AX252 **PRINTS CHARMING - TANK** **NY LTANKS** **S101341677**
West **2900 SHERIDAN DRIVE** **N/A**
1/8-1/4 **TONAWANDA, NY**
0.126 mi.
664 ft. **Site 4 of 4 in cluster AX**

Actual: **595 ft.**
Focus Map: **6**

LTANKS:

Spill Number/Closed Date:	9410986 / 1994-12-20
Facility ID:	9410986
Site ID:	227982
Spill Date:	1994-11-10
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	1994-12-20
SWIS:	1564
Investigator:	SORGI
Referred To:	Not reported
Reported to Dept:	1994-11-10
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	1994-11-10
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1994-11-17
Spill Record Last Update:	1994-12-28
Spiller Name:	Not reported
Spiller Company:	ROBERT ANTHONE
Spiller Address:	2880 SHERIDAN DRIVE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	9
DER Facility ID:	188046
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MJS 11/10/94: MJS SITE INSPECT. CONTAMINATED SOIL STOCKPILED ON PLASTIC. SAMPLES TAKEN BY CONTRACTOR. SOIL PLANNED FOR DISPOSAL. 12/09/94: RECEIVED EXCAVATION SAMPLE RESULTS FROM NATURES WAY. NO EXCEEDENCES OF GUIDANCE VALUES. NEED DISPOSAL RECEIPTS FOR SOIL FOR CLOSURE OF FILE. LETTER TO RP. 12/15/94: MJS TELECON W/ RUSS SAVAGE. SOIL SCHEDULED FOR PICKUP ON 12/16/94. MR SAVAGE WILL FORWARD DISPOSAL DOCUMENTATION WHEN RECEIVED. 12/20/94: MJS RECEIVED FAX OF DISPOSAL RECEIPT FROM NATURES WAY. 20.34 TONS DISPOSED AT LAKEVIEW.

PRINTS CHARMING - TANK (Continued) **S101341677**

NO FURTHER ACTION REQUIRED. MJS CLOSE FILE. "
Remarks: "CONTAMINATED SOIL FOUND DURING TANK REMOVAL."

All Materials:
Site ID: 227982
Operable Unit ID: 1004898
Operable Unit: 01
Material ID: 376850
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Not reported
Recovered: .00
Oxygenate: Not reported

AW253 **BJS WHOLESALE CLUB #213** **RCRA-CESQG** **1015747266**
East **3056 SHERIDAN DR** **NYR000197376**
1/8-1/4 **AMHERST, NY 14226**
0.127 mi.
671 ft. **Site 2 of 5 in cluster AW**

Actual:
597 ft.

Focus Map:
6

RCRA-CESQG:
Date form received by agency: 02/26/2013
Facility name: BJS WHOLESALE CLUB #213
Facility address: 3056 SHERIDAN DR
AMHERST, NY 14226
EPA ID: NYR000197376
Mailing address: RESEARCH DR
WESTBOROUGH, MA 01581
Contact: BILL E PETERS
Contact address: RESEARCH DR
WESTBOROUGH, MA 01581
Contact country: US
Contact telephone: 774-512-7400
Contact email: BPETERS@BJS.COM
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:
Owner/operator name: AMHERST II VF LLC C/O VORNADO REALTY
Owner/operator address: RTE 4 EAST

BJS WHOLESALE CLUB #213 (Continued) **1015747266**

PARAMUS, NJ 07652
Owner/operator country: US
Owner/operator telephone: 212-894-7000
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 02/01/2011
Owner/Op end date: Not reported

Owner/operator name: BJS WHOLESALE CLUB
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 08/11/2013
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE

BJS WHOLESALE CLUB #213 (Continued) **1015747266**

DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLOROETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE, AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: P001
. Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

. Waste code: P075
. Waste name: NICOTINE, & SALTS

. Waste code: U002
. Waste name: ACETONE (I)

. Waste code: U279
. Waste name: CARBARYL (OR) 1-NAPHTHALENOL, METHYLCARBAMATE

Historical Generators:
Date form received by agency: 09/27/2012
Site name: BJS WHOLESALE CLUB #213
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D008
. Waste name: LEAD

BJS WHOLESALE CLUB #213 (Continued) **1015747266**

. Waste code: D009
. Waste name: MERCURY

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLOROETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE, AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: P001
. Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

. Waste code: P075
. Waste name: NICOTINE, & SALTS

. Waste code: U002
. Waste name: ACETONE (I)

. Waste code: U279
. Waste name: CARBARYL (OR) 1-NAPHTHALENOL, METHYLCARBAMATE

Violation Status: No violations found

AW254 **BJS WHOLESALE CLUB #213** **NY MANIFEST** **S117742203**
East **3056 SHERIDAN DR** **N/A**
1/8-1/4 **AMHERST, NY 14226**
0.127 mi.
671 ft. **Site 3 of 5 in cluster AW**

Actual:
597 ft.

Focus Map:
6

NY MANIFEST:
Country: USA
EPA ID: NYR000197376
Facility Status: Not reported
Location Address 1: 3056 SHERIDAN DR
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: AMHERST
Location State: NY
Location Zip: 14226
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000197376
Mailing Name: BJS WHOLESALE CLUB #213
Mailing Contact: BILL PETERS
Mailing Address 1: 25 RESEARCH DR
Mailing Address 2: PO BOX 5233
Mailing City: WESTBOROUGH
Mailing State: MA
Mailing Zip: 01581
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

BJS WHOLESALE CLUB #213 (Continued) **S117742203**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	MAD039322250
Trans2 State ID:	Not reported
Generator Ship Date:	05/31/2018
Trans1 Recv Date:	05/31/2018
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/13/2018
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000197376
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NCD000648451
TSDF ID 2:	Not reported
Manifest Tracking Number:	011835585FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1
Units:	P - Pounds
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	D001
Waste Code 1_2:	D005
Waste Code 1_3:	D007
Waste Code 1_4:	D016
Waste Code 1_5:	D018
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
4 additional NY MANIFEST: record(s) in the EDR Site Report.

AW255 **BJ'S WHOLESALE CLUB #213** **NY AST** **A100380529**
East **3056 SHERIDAN DRIVE** **N/A**
1/8-1/4 **AMHERST, NY 14226**
0.127 mi.
671 ft. **Site 4 of 5 in cluster AW**

Actual:
597 ft.

Focus Map:
6

AST:

Region:	STATE
DEC Region:	9
Site Status:	Unregulated/Closed
Facility Id:	9-601364
Program Type:	PBS
UTM X:	188554.04844
UTM Y:	4765863.99310
Expiration Date:	N/A
Site Type:	Other Wholesale/Retail Sales

Affiliation Records:

Site Id:	482155
Affiliation Type:	Facility Owner
Company Name:	AMHERST 11 VFLLC, C/O VORNADO REALTY TRUST
Contact Type:	ENVIRONMENTAL MANAGER
Contact Name:	JASON MYERS
Address1:	210 ROUTE 4 EAST
Address2:	Not reported
City:	PARAMUS
State:	NJ
Zip Code:	07652
Country Code:	001
Phone:	(201) 587-1000 2079
EMail:	Not reported
Fax Number:	Not reported
Modified By:	SLZIEMBA
Date Last Modified:	2013-05-21

Site Id:	482155
Affiliation Type:	Mail Contact
Company Name:	BJS WHOLESALE CLUB
Contact Type:	Not reported
Contact Name:	DAVID TERIBURY
Address1:	3056 SHERIDAN DRIVE
Address2:	Not reported
City:	AMHERST
State:	NY
Zip Code:	14226
Country Code:	001
Phone:	(716) 833-3130
EMail:	Not reported
Fax Number:	Not reported
Modified By:	SLZIEMBA
Date Last Modified:	2013-05-21

Site Id:	482155
Affiliation Type:	Facility Operator
Company Name:	BJS WHOLESALE CLUB #213
Contact Type:	Not reported
Contact Name:	DENNIS WOOD
Address1:	Not reported
Address2:	Not reported
City:	Not reported

BJ'S WHOLESALE CLUB #213 (Continued) **A100380529**

State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(716) 833-3130
EMail:	Not reported
Fax Number:	Not reported
Modified By:	SLZIEMBA
Date Last Modified:	2013-05-21

Site Id:	482155
Affiliation Type:	Emergency Contact
Company Name:	AMHERST 11 VFLLC, C/O VORNADO REALTY TRUST
Contact Type:	Not reported
Contact Name:	3E COMPANY, INC.
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(800) 451-8346
EMail:	Not reported
Fax Number:	Not reported
Modified By:	SLZIEMBA
Date Last Modified:	2013-05-21

Tank Info:

Tank Number:	1
Tank Id:	248342

Equipment Records:

D00 - Pipe Type - No Piping
J03 - Dispenser - Gravity
L00 - Piping Leak Detection - None
E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
K00 - Spill Prevention - None
G12 - Tank Secondary Containment - Double-Walled (AG only)

Tank Location:	2
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	04/15/2013
Capacity Gallons:	706
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	SLZIEMBA
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

BJ'S WHOLESALE CLUB #213 (Continued) **A100380529**

Tank Number: 2
Tank Id: 248343

Equipment Records:

G12 - Tank Secondary Containment - Double-Walled (AG only)
K00 - Spill Prevention - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
B01 - Tank External Protection - Painted/Asphalt Coating
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I02 - Overfill - High Level Alarm
E00 - Piping Secondary Containment - None
J03 - Dispenser - Gravity
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping

Tank Location: 2
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 04/15/2013
Capacity Gallons: 707
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: SLZIEMBA
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

AW256 **BJS WHOLESALE CLUB #213** **FINDS 1015999257**
East **3056 SHERIDAN DR** **ECHO N/A**
1/8-1/4 **AMHERST, NY 14226**
0.127 mi.
671 ft. **Site 5 of 5 in cluster AW**

Actual:
597 ft.

FINDS:

Focus Map:
6

Registry ID: 110046537048

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1015999257
Registry ID: 110046537048
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110046537048

257
West
1/8-1/4
0.129 mi.
682 ft.

JOE CONTINO RESIDENCE
142 DALTON DRIVE
TONAWANDA, NY

NY LTANKS

S100495130
N/A

Actual:
599 ft.

Focus Map:
6

LTANKS:

Spill Number/Closed Date:	9301533 / 1993-12-28
Facility ID:	9301533
Site ID:	140721
Spill Date:	1993-04-13
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	1993-12-28
SWIS:	1564
Investigator:	SORGI
Referred To:	Not reported
Reported to Dept:	1993-04-29
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	1993-08-26
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1993-05-04
Spill Record Last Update:	1993-12-30
Spiller Name:	Not reported
Spiller Company:	JOE CONTINO
Spiller Address:	142 DALTON DRIVE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	9
DER Facility ID:	120174
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MJS 05/14/93: MJS/ANDY KUSCERIK, DAY ENV./TELECON - HE IS WORKING FOR INSURANCE CO. ODORS IN HOUSE ARE HEAVY. INSURANCE CO. HASN'T STARTED CLEANUP YET. SET UP MEETING W/JOE CONTINO FOR 5/17/93 AT 0500 HRS. 05/17/93: MJS/JOE CONTINO/SITE - PETROLEUM ODOR PRESENT IN HOME. 275-GAL. TANK IN CRAWL SPACE. GRAVEL & TANK PETROLEUM SATURATED. SHEEN IN SUMP. NO METER READINGS TAKEN (0800 HRS.). 05/17/93: MJS/ANDY KUSCEREK/TELECON - HE HAS NOT CONTACTED INSURANCE CO. YET. MJS INFORMED THAT MOST IMPORTANT ISSUE WAS VAPORS IN HOUSE. ADVISED THAT CRAWL SPACE MUST BE VENTED. WILL GET BACK TO ME. 05/20/93: MJS/ANDY KUSCERIK/TELECON - WORK PLAN IS APPROVED BY INSURANCE CO. MR. KUSCERIK WILL INSTALL VACCUUM SYSTEM. SATURDAY, 5/22/93. 05/20/93: MJS/ANDY KUSCEREK/TELECON - WORK PLAN HAS BEEN APPROVED BY INSURANCE COMPANY. MR. KUSCERIK WILL INSTALL VACCUUM SYSTEM ON SAT., 5/22/93. 05/22/93: MJS/JOE CONTINO/ANDY KUSCERIK/SITE - VENT SYSTEM IS INSTALLED. EFFLUENT APPROX. 100 PPM ON P.I.D. MR. KUSCERIK WILL MONITOR EFFLUENT FREQUENTLY. 05/22/93: MJS/JOE CONTINO/ANDY KUSCERIK/SITE - VENT SYSTEM INSTALLED. MR. KUSCERIK WILL MONITOR EFFLUENT FREQUENTLY. 05/22/93: MJS/JOE CONTINO/TELECON - P.I.D. READINGS HAVE DECREASED SIGNIFICANTLY (APPROX. 10 PPM). VAPORS IN HOUSE HAVE ALSO DECREASED. 05/25/93: MJS/JOE CONTION/TELECON - P.I.D.

JOE CONTINO RESIDENCE (Continued) **S100495130**

READINGS HAVE DECREASED SIGNIFICANTLY (APPROX. 10 PPM). VAPORS IN HOUSE HAVE ALSO DECREASED. 06/10/93: MJS RECEIVED WORK PROPOSAL FROM ANDY KUSIERIK. HE IS CURRENTLY OBTAINING BIDS. 06/10/93: MJS RECEIVED WORK PROPOSAL FROM ANDY KUSCERIK. HE IS CURRENTLY OBTAINING BIDS. 06/18/93: MJS/ANDY KUSCERIK/TELECON - MR. CONTINO IS GOING TO HIRE CONTRACTORS AN WILL BE REIMBURSED BY INSURANCE COMPANY. MJS/JOE CONTINO/TELECON NO ODORS IN HOUSE. 06/18/93: MJS/ANDY KUSCERIK/TELECON - MR. CONTINO IS GOING TO HIRE CONTRACTORS AND WILL BE REIMBURSED BY INSURANCE CO. MJS/JOE CONTINO/TELECON - NO ODORS IN HOUSE. 06/25/93: MJS SENT LETTER TO INSURANCE COMPANY AND REVIEWED WORK PLAN. PLAN IS SATISFACTORY. 07/10/93: COPY OF LETTER SENT TO MR. CONTINO RETURNED DUE TO WRONG ZIP CODE. MJS/ANDY KUSCERIK/TELECON - WORK TO BEGIN ON TUES. 7/6/93. NORSEMEN ENVIRONMENTAL FROM YOUNGSTOWN IS SUBCONTRACTOR. 07/12/93: MJS/ANDY KUSCERIK/TELECON - WORK COMPLETE. TANK AND CONTAMINATED SOIL HAVE BEEN REMOVED. MR. KUSCERIK IS SUBMITTING A SAMPLE TODAY FOR 24-HOUR TURNAROUND. 07/13/93: MJS/ANDY KUCSERIK/SITE - ROLLOFF BOX IN DRIVEWAY. APPROX. 15 TONS OF SOIL EXCAVATED. EXCAVATION BELOW DRAIN TILES. WATER COLLECTS WHEN IT RAINS. ANDY PROPOSES TO FILL EXCAVATION W/ MUD MAT . 07/14/93: MJS/ANDY KUCSERIK/TELECON - HE WILL WAIT FOR 72-HOUR TURNAROUND ON SAMPLES BEFORE FILLING EXCAVATION. 07/15/93: MJS/ANDY KUCSERIK/TELECON - SAMPLE RESULTS DUE AFTERNOON OF 7/16/93. IF RESULTS OKAY, HE WILL DO SLURRY ON 7/17/93 IN A.M. HE WILL ALSO SEND LETTER AS ADDENDUM TO ORIGINAL PLAN. 07/19/93: MJS/MR. CONTINO/TELECON - SAMPLE RESULTS IN; NO VIOLATIONS FOUND. MJS/ANDY KUCSERIK/TELECON - ONLY PARAMETER NAPTHALENE AT 3 PPB. BACFILLING W/SLURRY TO BEGIN 7/20/93 IN A.M. 07/20/93: MJS/ANDY KUCSERIK/SITE - RECEIVED COPY OF ANALYTICAL RESULTS. BACKFILLING CRAWL SPACE W/SLURRY. ROLLOFF BOX WILL BE MOVED IN APPROX. 1 WEEK. VAPOR EXTRACTION FAN IS DISASSEMBLED. 07/22/93: MJS RECEIVED LETTER FROM MR. KUCSERIK SUMMARIZING THE CLEANUP. STILL NEED ANALYTICAL & RECEIPTS FOR CONTAMINATED SOIL AND ANALYTICAL & RECEIPTS FOR CONTAMINATED WATER TO CLOSE FILE. 07/28/93: MJS/ANDY KUCSERIK/TELECON - HE INFORMS THAT MR. CONTINO IS AGAIN COMPLAINING OF VAPORS IN HOUSE. REQUESTS ON-SITE MEETING. MEETING SET FOR MON., 8/2/93 AT 1330 HRS. ON-SITE. 08/02/93: MJS/RNL/ANDY KUCSERIK/JOE CONTINO/SITE - DRAIN TILES WILL BE WASHED OR STEAM-CLEANED AND VENTING FAN LEFT IN PLACE FOR SUMMER. ROLLOFF IS MOVED OFF-SITE FOR DISPOSAL. 08/04/93: MJS/ANDY KUCSERIK/TELECON - ASKED HIM TO INFORM ME OF WORK DATE WHEN KNOWN. 08/06/93: MJS RECEIVED LETTER FROM MR. KUCSERIK CONFIRMING OUR MEETING ON 8/2/93. DRAIN TILES WILL BE PRESSURE RINSED. 08/12/93: MJS TELECON W/MR. KUCSERIK. DRAIN TILES WASHED 8/11/93. 08/13/93: MJS/ANDY KUCSERIK/SITE - NO FUEL OIL ODOR IN HOME. SLIGHT SHEEN IN SUMP AND DRAIN TILES. RECEIVED REPORT FROM MR. KUCSERIK. 08/18/93: MJS/JOE CONTINO/TELECON - HE REQUESTS LETTER OF SATISFACTORY CLEANUP. 08/19/93: MJS SENT LETTER OF SATISFACTORY CLEANUP TO MR. CONTINO. 08/23/93: MJS TELECON FROM MR CONTINO. HE INFORMS THAT PETROLEUM ODORS VERY STRONG AFTER HEAVY RAINS. ALSO, PETROLEUM IN DRAIN TILE. 08/26/93: MJS SITE MEETING W/ MR CONTINO AND MR KUCSERIK. OIL IN DRAIN TILE. DRAIN TILES NOT WORKING PROPERLY. 10/04/93: MJS/MR. KUCSERIK/TELECON - MR. CONTINO CONTACTED THE TOWN, BUT COULD NOT GET ANY GOOD INFORMATION. MR. KUCSERIK HAS RECEIVED NO NEW COMPLAINTS FROM MR. CONTINO. 10/07/93: MJS/MR. KUCSERIK/TELECON - MR. KUCSERIK SPOKE W/MR. CONTINO AND HAS HAD NO PROBLEMS SINCE LAST MEETING. MJS INFORMED MR. KUCSERIK THAT NO FURTHER WORK WOULD BE REQUIRED AT THIS TIME. 10/12/93: MJS RECEIVED UPDATE REPORT FROM MR. KUCSERIK. 12/28/93: MJS REVIEWED FILE. NO RECENT COMPLAINTS FROM MR. CONTINO.

JOE CONTINO RESIDENCE (Continued) **S100495130**

Remarks: NO FURTHER ACTION REQUIRED. MJS TO CLOSE FILE. " "ODOR & SOIL CONTAMINATION IN CRAWL SPACE UNDER HOUSE. ABANDONED TANK."

All Materials:

Site ID:	140721
Operable Unit ID:	980089
Operable Unit:	01
Material ID:	398706
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

AT258 **PARKHILL & HART LNDRY INC BR** **EDR Hist Cleaner** **1014536487**
NE **3586 MAIN ST** **N/A**
1/8-1/4 **BUFFALO, NY**
0.130 mi.
684 ft. **Site 2 of 2 in cluster AT**

Actual: EDR Hist Cleaner
651 ft.

Focus Map: **8**

Year:	Name:	Type:
1964	PARKHILL & HART LNDRY INC BR	LAUNDRIES

AZ259 **BAUGHMAN MAGIC SEAL** **RCRA NonGen / NLR** **1018158893**
North **44 MEYER RD** **NYR000219659**
1/8-1/4 **AMHERST, NY 14226**
0.131 mi.
690 ft. **Site 1 of 3 in cluster AZ**

Actual: RCRA NonGen / NLR:
581 ft.

Date form received by agency:	04/18/2017
Facility name:	BAUGHMAN MAGIC SEAL
Facility address:	44 MEYER RD AMHERST, NY 14226
EPA ID:	NYR000219659
Mailing address:	MEYER RD AMHERST, NY 14226
Contact:	CHRISTINE A MARTINECK
Contact address:	MEYER RD AMHERST, NY 14226
Contact country:	US
Contact telephone:	716-836-8880
Contact email:	CHRISSYM@BAUGHMANMAGICSEAL.COM
EPA Region:	02
Land type:	Private
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Focus Map: **3**

Owner/Operator Summary:

BAUGHMAN MAGIC SEAL (Continued) **1018158893**

Owner/operator name:	DONALD H BAUGHMAN
Owner/operator address:	Not reported
	Not reported
Owner/operator country:	Not reported
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	10/03/2007
Owner/Op end date:	Not reported

Owner/operator name:	DONALD H BAUGHMAN
Owner/operator address:	Not reported
	Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	10/03/2007
Owner/Op end date:	Not reported

Owner/operator name:	DONALD H BAUGHMAN
Owner/operator address:	MEYER RD
	AMHERST, NY 14226
Owner/operator country:	US
Owner/operator telephone:	716-836-8880
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	10/03/2007
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code: D001

BAUGHMAN MAGIC SEAL (Continued) **1018158893**

. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Historical Generators:
Date form received by agency: 06/08/2015
Site name: BAUGHMAN MAGIC SEAL
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 09/15/2017
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

AZ260 **BAUGHMAN MAGIC SEAL** **NY MANIFEST** **S118260222**
North **44 MEYER RD** **N/A**
1/8-1/4 **AMHERST, NY 14226**
0.131 mi.
690 ft. **Site 2 of 3 in cluster AZ**

Actual:
581 ft.

Focus Map:
3

NY MANIFEST:
Country: USA
EPA ID: NYR000219659
Facility Status: Not reported
Location Address 1: 44 MEYER RD
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: AMHERST
Location State: NY
Location Zip: 14226
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000219659
Mailing Name: BAUGHMAN MAGIC SEAL
Mailing Contact: BAUGHMAN MAGIC SEAL
Mailing Address 1: 44 MEYER RD
Mailing Address 2: Not reported
Mailing City: AMHERST
Mailing State: NY

BAUGHMAN MAGIC SEAL (Continued) **S118260222**

Mailing Zip:	14226
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7168688880

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NYD986903904
Trans2 State ID:	Not reported
Generator Ship Date:	06/29/2015
Trans1 Recv Date:	06/29/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/02/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000219659
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD066060609
TSDF ID 2:	Not reported
Manifest Tracking Number:	006690217FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	800
Units:	P - Pounds
Number of Containers:	2
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	D001
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

BAUGHMAN MAGIC SEAL (Continued) **S118260222**

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AZ261 **BAUGHMAN MAGIC SEAL** **FINDS** **1018124105**
North **44 MEYER RD** **ECHO** **N/A**
1/8-1/4 **AMHERST, NY 14226**
0.131 mi.
690 ft. **Site 3 of 3 in cluster AZ**

Actual:
581 ft.

FINDS:

Focus Map:
3

Registry ID: 110064675178

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access
additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1018124105
Registry ID: 110064675178
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110064675178

---

262 **RENSCH ROAD RESEARCH PARK** **FINDS** **1007810500**
NW **4080 RENSCH ROAD** **N/A**
1/8-1/4 **AMHERST, NY 14228**
0.141 mi.
742 ft.

Actual:
596 ft.

FINDS:

Focus Map:
4

Registry ID: 110019730380

Environmental Interest/Information System
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access
additional FINDS: detail in the EDR Site Report.

263
North
1/8-1/4
0.141 mi.
747 ft.

TRUCK AT LASERTRON PARKIN
5101 NORTH BAILEY/MAPLE
AMHERST, NY

NY Spills **S103273154**
N/A

Actual:
584 ft.

Focus Map:
4

SPILLS:

Spill Number/Closed Date:	9713482 / 1998-03-31
Facility ID:	9713482
Facility Type:	ER
DER Facility ID:	206648
Site ID:	252173
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	D3
SWIS:	1522
Spill Date:	1998-03-05
Investigator:	SORGI
Referred To:	Not reported
Reported to Dept:	1998-03-05
CID:	999
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	1998-03-05
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-03-05
Spill Record Last Update:	1998-04-10
Spiller Name:	Not reported
Spiller Company:	UNKNOWN TRUCK
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MJS 03/05/98: MJS SITE INSPECT. COULD NOT LOCATE SPILL. 03/31/98: MJS TELECON WITH JIM ZYMANEK(TOWN OF AMHERST). TRACTOR TRAILER LEAKED ENGINE TO ASPHALT AND STORM SEWER. TOWN SUPPLIED SORBENTS AND DRIVER CLEANED SPILL HIMSELF. NO DISPOSAL RECEIPTS REQUIRED. NO FURTHER ACTION REQUIRED. MJS CLOSE FILE."
Remarks:	"TRUCK LEAKED ENGINE OIL TO SEWER."

All Materials:

Site ID:	252173
Operable Unit ID:	1056342
Operable Unit:	01
Material ID:	324499
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	5.00
Oxygenate:	Not reported

264
WNW
1/8-1/4
0.149 mi.
785 ft.

OLD MAN PRECISION AUTOMOTIVE
4200 RENSH RD
AMHERST, NY 14228

EDR Hist Auto **1014539312**
N/A

Actual:
582 ft.

EDR Hist Auto

Focus Map:
4

Year:	Name:	Type:
1996	OLD MAN PRECISION AUTOMOTIVE	Automotive Transmission Repair Shops
1997	OLD MAN PRECISION AUTOMOTIVE	Automotive Transmission Repair Shops
1998	OLD MAN ENGINEERING AUTO	AUTOMOBILE REPAIRING & SERVICE
1998	OLD MAN PRECISION AUTOMOTIVE	Automotive Transmission Repair Shops
1999	OLD MAN PRECISION AUTOMOTIVE	Automotive Transmission Repair Shops
2000	OLD MAN PRECISION AUTOMOTIVE	Automotive Transmission Repair Shops
2001	OLD MAN PRECISION AUTOMOTIVE	Automotive Transmission Repair Shops
2002	OLD MAN PRECISION AUTOMOTIVE	Automotive Transmission Repair Shops
2003	OLD MAN PRECISION AUTOMOTIVE	Automotive Transmission Repair Shops
2008	OLD MAN ENGINEERING	General Automotive Repair Shops
2009	OLD MAN ENGINEERING	General Automotive Repair Shops
2010	OLD MAN ENGINEERING	General Automotive Repair Shops

BA265
NNW
1/8-1/4
0.153 mi.
810 ft.

PITZ DAVID & PHILIP
1435 NIAGARA FLS BD
BUFFALO, NY 14226

Site 1 of 3 in cluster BA

EDR Hist Auto **1021780060**
N/A

Actual:
581 ft.

EDR Hist Auto

Focus Map:
3

Year:	Name:	Type:
1971	PITZ DAVID & PHILIP	Gasoline Service Stations
1974	CARUANA V M INC	Gasoline Service Stations
1975	CARUANA V M INC	Gasoline Service Stations

BA266
NNW
1/8-1/4
0.153 mi.
810 ft.

STS CAR SERVICE
1435 NIAGARA FALLS BLVD
AMHERST, NY

Site 2 of 3 in cluster BA

NY LTANKS **S100176881**
N/A

Actual:
581 ft.

LTANKS:

Focus Map:
3

Spill Number/Closed Date:	9611396 / 1997-12-26
Facility ID:	9611396
Site ID:	115595
Spill Date:	1996-12-16
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	1522
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	1996-12-16
CID:	211
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	1997-12-01

STS CAR SERVICE (Continued) **S100176881**

Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1996-12-16
Spill Record Last Update:	1999-11-30
Spiller Name:	KENNITH MOSS/HORNSTEIN
Spiller Company:	RAYMOUR AND FLANIGAN FRUN
Spiller Address:	7248 MORGAN ROAD POB 220
Spiller County:	001
Spiller Contact:	LEN KWIECIEN
Spiller Phone:	(716) 833-3400
Spiller Extention:	Not reported
DEC Region:	9
DER Facility ID:	107110
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 12/17/96 RMC/LEN KWIECIEN/SITE, SOIL STOCKPILED ON PLASTIC, TWO LOADS SOIL FROM PHASE II WORK, REPORT DUE 1/30/97 12/31/96 RMC/MIKE SAVIOLA, C&H, 315-472-6980/PHONE, REPORTS TO BE AVAILABLE 2/28/97 03/20/97 RMC/HORNSTEIN/MEETING, REMEDIATION REQUIRED BASED ON PHASE I AND II, LETTER SENT, RESPONSE DUE 4/16/97. 04/18/97: MJS TELECON WITH MIKE SAVIOLA. THEY ARE PERFORMING BORINGS AND WELL INSTALLATIONS ON 4/18 AND 4/21. 04/29/97 RMC/SABIOLA/PHONE, WORK COMPLETE, REPORT TO FOLLOW, DUE 5/15/97 04/29/97 RMC/MIKE SAVIOLA/PHONE, WENT OVER MW ANALYSIS, SIGNIFICANT EXCEEDANCES, PLAN TO SUBMIT REMEDIATION PLAN FOR REVIEW, UPDATE 5/30/97 05/12/97 RMC/HORNSTEIN/CUDNEY C&H/PHONE, WENT OVER POSSIBLE REMEDIATION APPROACHES IF RAYMOUR AND FLANAGAN DO BUY THE PROPERTY. UPDATE 7/30/97 07/21/97 RMC/FILE RECEIVED WORK PLAN, PLAN TO EXCAVATE CONTAMINATED SOILS, SAMPLE EXCAVATION, THEN TEST SHALLOW GW AGAIN, CALL DUE 8/15/97 8/5/97: SAC TELECON BRIAN MCCRAE,C&H ENGINEERS,HE SPOKE WITH KEN KELLER AND WORK SHOULD BEGIN THIS THURSDAY AND EXTEND INTO THE MIDDLE OF NEXT WEEK AT THE LATEST, THEY WILL NOTIFY US ONCE ALL SOIL HAS BEEN REMOVED. 08/12/97 RMC/C&H/SITE, EXCAVATION STARTED, REMOVED 1000 TONS TO DATE, ENGINEEER CONCERNED ABOUT VEIN OF SUSPECT MATERIAL ON EAST AND WEST SIDEWALL, RMC ADVISED TO SAMPLE FOR STARS COMPLIANCE, 2 BOTTOM TWO EAST AND TWO WEST SIDEWALL,(GRAB/COMP), SAMPLING WILL BE DONE ON CONTINUED EXCAVATION TO THE NORTH WHEN COMPLETE, 08/13/97 RMC/KELLER/C&H/SITE, AGAIN WENT OVER SAMPLING, TO REINSPECT 08/15/97 RMC/SITE, EXCAVATION COMPLETED, 3000 TONS REMOVED, SAMPLES TAKEN, POTENTIAL FAILURE DUE TO NUSIANCE SOILS, DUE 9/30/97 08/21/97 RMC/FILE RECEIVED SAMPLE RESULTS, NUMEROUS EXCEEDANCES IN AREA OF NUSIANCE IMPACTS, ABOUT 2 FOOT VEIN 5 FEET DEEP IN FRONT OF BUILDING, FURTHER WORK REQUIRED 08/21/97 RMC/BRIAN MCRAE/PHONE, TO CONTINUE EXCAVATION, TO REMOVE 5 FOOT NON CONTAMINATED OVERBURDEN AND USE AS BACKFILL THEN REMOVE PETROLEUM IMPACTED SOILS TO LANDFILL, UPDATE 8/30 09/19/97 RMC/FILE, WORK COMPLETE ON EXCAVATION, NEED SAMPLE RESULTS AND GW MONITORING REPORT FOR CLOSURE DETERMINATION, DUE 9/30 10/22/97 RMC/BRIAN MCRAE/PHONE, ADDITIONAL 1100 TONS REMOVED AFTER BUILDING RAZED, REPORT TO FOLLOW, DUE 10/30 11/06/97 RMC/FILE RECEIVED REPORT. 5000 TONS SOIL REMOVED, MINOR EXCEEDANCES IN SOIL CONTINUE IN WEST WALL AT PROPERTY LINE, NEED GW ANALYSIS FOR MW 1 AND 4 FOR STATUS DETERMINATION. 11/12/97 RMC/BRIAN MCRAE/PHONE, RMC REQUESTED MW 1 AND MW 4 BE SAMPLED, HE AGREED, RESULTS DUE 12/30/97 11/26/97 RMC/MACRAE/PHONE, MW 1,3,4 WILL BE REINSTALLED DUE TO DAMAGE DONE DURING CONSTRUCTION, RESULTS DUE 12/30/97 11/26/97 RMC/BOB/SUSTAKOWSKI, MM BANK, 841-5491/PHONE,BANK CONCERNED THAT WEST

STS CAR SERVICE (Continued) **S100176881**

WALL RESAMPLE NOT DONE IN IMMEDIATE AREA WHERE CONTAMINATION CONTINUED ALONG NIAGARA FALLS BLVD., RMC ADVISED THAT STATE WAS AWARE OF SOIL REMAINING WITH NUSIANCE CHARACTERISTICS BUT THAT THE REMOVAL OF 5000 TONS OF SOIL COUPLED WITH THE GW DATE WILL BE SUFFICIENT FOR STATUS DETERMINATION, RMC ADVISED DEC WOULD NOT REQUIRED TNE ROAD TO BE DUG UP OR THE UTILITIES BE REMOVED, BUT FUTURE ROAD OR UTILITY PROJECTS COULD REQUIRE THE PROPERTY OWNER TO HAVE TO REMOVE MORE SOIL, REPORT DUE 12/30/97 12/26/97 RMC/FILE RECEIVED GW REPORT, ONLY MINOR EXCEEDANCES OF THE SOIL AND GROUNDWATER EXIST, COULD NOT CHASE CONTAMINATION ANY FURTHER WEST DUE TO UTILITIES AND PROXIMITY TO NIAGARA FALLS BLVD, HOWEVER CONTAMINATION REMAING APPEARED TO BE MINOR, RP REMOVED OVER 4000 TONS OF IMPACTED SOIL, NO FURTHER ACTION REQUIRED AT THIS TIME, INACTIVE."

Remarks: "CONTAMINATED SOIL AND GROUNDWATER DISCOVERED DURING PHASE 2 PIO 250-300 SHEEN ON WATER - SERVICE STATION UNTIL LATE 70'S - SAMPLING 8021 & 8270"

All Materials:

Site ID:	115595
Operable Unit ID:	1039424
Operable Unit:	01
Material ID:	343594
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	9107450 / 1992-03-24
Facility ID:	9107450
Site ID:	123585
Spill Date:	1991-10-10
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1992-03-24
SWIS:	1522
Investigator:	COOKE
Referred To:	Not reported
Reported to Dept:	1991-10-10
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	1991-10-10
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1991-10-11
Spill Record Last Update:	1992-04-02
Spiller Name:	Not reported
Spiller Company:	STS CAR SERVICE
Spiller Address:	1435 NIAGARA FALLS BLVD
Spiller County:	001

STS CAR SERVICE (Continued) **S100176881**

Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	9
DER Facility ID:	107110
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was JDC 10/10/91: TANK REMOVED SOIL BEING STAGED FOR DISPOSAL. 01/24/92: JDC INSPECTED SITE AND FOUND SOIL REMOVED FROM SITE. WILL CLOSE UPON CONFIRMATION OF DISPOSAL BY RECIEPT. 03/24/92: JDC INSPECTED FILE AND FOUND WORK COMPLETED SATISFACTORY. NO FURTHER WORK REQUIRED. "
Remarks:	"TANK LEAK"

All Materials:

Site ID:	123585
Operable Unit ID:	957912
Operable Unit:	01
Material ID:	419655
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BA267 **STS CAR SVC CTR** **RCRA NonGen / NLR** **1000554237**
NNW **1435 NIAGARA FALLS BLVD** **FINDS** **NYD986966976**
1/8-1/4 **BUFFALO, NY 14228** **ECHO**
0.153 mi. **NY MANIFEST**
810 ft. **Site 3 of 3 in cluster BA**

Actual:
581 ft.

Focus Map:
3

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	STS CAR SVC CTR
Facility address:	1435 NIAGARA FALLS BLVD BUFFALO, NY 14228-2701
EPA ID:	NYD986966976
Mailing address:	NIAGARA FALLS BLVD TONAWANDA, NY 14228
Contact:	Not reported
Contact address:	NIAGARA FALLS BLVD TONAWANDA, NY 14228
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	S T S BUFFALO INC
Owner/operator address:	UNKNOWN UNKNOWN, NY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212

STS CAR SVC CTR (Continued) **1000554237**

Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: S T S BUFFALO INC
Owner/operator address: UNKNOWN
UNKNOWN, NY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: STS CAR SVC CTR
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: STS CAR SVC CTR
Classification: Not a generator, verified

Date form received by agency: 08/07/1991
Site name: STS CAR SVC CTR
Classification: Small Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF

STS CAR SVC CTR (Continued) **1000554237**

LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 04/06/1993
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA Contractor/Grantee

FINDS:

Registry ID: 110004474382

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000554237
Registry ID: 110004474382
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004474382

NY MANIFEST:
Country: USA
EPA ID: NYD986966976
Facility Status: Not reported
Location Address 1: 1435 NIAGARA FALLS BLVD
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: AMHERST
Location State: NY
Location Zip: 14228
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD986966976
Mailing Name: STS CAR SERVICE CENTER
Mailing Contact: STS CAR SERVICE CENTER

STS CAR SVC CTR (Continued) **1000554237**

Mailing Address 1:	1435 NIAGARA FALLS BLVD
Mailing Address 2:	Not reported
Mailing City:	AMHERST
Mailing State:	NY
Mailing Zip:	14228
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7168333400

NY MANIFEST:

Document ID:	NJA1887955
Manifest Status:	C
seq:	Not reported
Year:	1995
Trans1 State ID:	50060
Trans2 State ID:	S50060
Generator Ship Date:	01/12/1995
Trans1 Recv Date:	01/12/1995
Trans2 Recv Date:	01/17/1995
TSD Site Recv Date:	01/18/1995
Part A Recv Date:	03/23/1995
Part B Recv Date:	02/06/1995
Generator EPA ID:	NYD986966976
Trans1 EPA ID:	NYD980761191
Trans2 EPA ID:	NYD980761191
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D039 - TETRACHLOROETHYLENE 0.73 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00250
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	005
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

268
East
1/8-1/4
0.154 mi.
812 ft.

JACK HANNON
190 MARGARET RD
AMHERST, NY

NY Spills **S106699514**
N/A

Actual:
598 ft.

Focus Map:
6

SPILLS:

Spill Number/Closed Date:	0475296 / 2004-09-23
Facility ID:	0475296
Facility Type:	ER
DER Facility ID:	152199
Site ID:	181495
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	D5
SWIS:	1522
Spill Date:	2004-09-01
Investigator:	RJJONAK
Referred To:	Not reported
Reported to Dept:	2004-09-22
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Passenger Vehicle
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-09-22
Spill Record Last Update:	2004-09-23
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RJJ 9/23/2004: I REFERED THIS SPILL TO THE DIV. OF LAW ENFORCEMENT...THEY WILL FOLLOW-UP ON THIS COMPLAINT...NO FURTHER ACTION NEEDED BY SPILLS...SPILL CLOSED OUT. ***** NOTE,COMPUTER FILE ONLY *****"
Remarks:	"CALLER REPORTING THAT A VEHICLE HAS BEEN LEAKING OIL FOR WEEKS AT THIS ADDRESS. THE VEHICLE IS A PURPLE DODGE MINIVAN WITH LICENSE BWC2284."

All Materials:

Site ID:	181495
Operable Unit ID:	891390
Operable Unit:	01
Material ID:	486283
Material Code:	0015
Material Name:	motor oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

269 NNW 1/8-1/4 0.158 mi. 836 ft. | **OLD BURGER KING**
1420 NIAGARA FALLS BLD
TONAWANDA, NY | **NY Spills** | **S106007155**
N/A

Actual: 582 ft.

Focus Map: 3

SPILLS:

Spill Number/Closed Date:	0275298 / 2002-11-27
Facility ID:	0275298
Facility Type:	ER
DER Facility ID:	221669
Site ID:	272355
DEC Region:	9
Spill Cause:	Other
Spill Class:	B3
SWIS:	1564
Spill Date:	2002-09-04
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	2002-09-04
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	2002-10-01
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-09-04
Spill Record Last Update:	2003-01-08
Spiller Name:	GLEN KAUFFMAN
Spiller Company:	FORS FAMILY PARTNERSHIP
Spiller Address:	5820 MAIN ST SUITE 201
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 09/04/02 RMC/SCOTT O./SITE. FOUND LARGE AMOUNT OF OLD PIPING, UST AND SOME CONTAMINATION. PLAN ON REMOVING EQUIPMENT AND DIGGING TO CLEAN. 09/05/02 RMC/SCOTT O./PHONE. RMC ADVISED STANDARD TO MEET IS REMOVE CONTAMINATION THAT CAN BE SEEN AND SMELT. THEN TEST. 11/27/02 RMC/FILE. REVIEWED REPORT RECEIVED 10/17/02. EXCAVATED ALL PETROLEUM CONTAMINATION TO THE EXTENT POSSIBLE. KEVIN GLASIER OBSERVED WORK FOR THE DEC. NUISANCE CHARACTERISTICS NOTED NEAR WATERLINE. ALL ANALYITICAL MET TAGM. 773 TONS OF IMPACTED SOILS REMOVED. NO FURTHER ACTION REQUIRED, LETTER INACTIVE. "
Remarks:	"CONTAMINATION FOUND DURING TEST PIT WORK, "

All Materials:

Site ID:	272355
Operable Unit ID:	868040
Operable Unit:	01
Material ID:	507660
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G

OLD BURGER KING (Continued) **S106007155**

Recovered: .00
Oxygenate: Not reported

---

270 East 1/8-1/4 0.160 mi. 845 ft. **RESIDENTIAL**
151 CAPEN BLVD
AMHERST, NY

NY Spills **S121463443**
N/A

Actual: 618 ft.

Focus Map: 8

SPILLS:

Spill Number/Closed Date:	1709075 / 2018-01-03
Facility ID:	1709075
Facility Type:	ER
DER Facility ID:	519013
Site ID:	565512
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	1522
Spill Date:	2018-01-02
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	2018-01-02
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2018-01-02
Spill Record Last Update:	2018-01-03
Spiller Name:	Not reported
Spiller Company:	UMESH SNAH
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	DON YOTT
DEC Memo:	"01/03/18 RMC/DON YOTT/PHONE. SMALL SPILL TO CONCRETE. CLEAN UP COMPLETED. NO SPILL ACTION REQUIRED. CLOSE OUT."
Remarks:	"The spill was over concrete . The cleanup is pending."

All Materials:

Site ID:	565512
Operable Unit ID:	1313447
Operable Unit:	01
Material ID:	2320885
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

BB271 **BENDERSON DEVELOPEMENT** **NY Spills** **S121463669**
NE **3608 MAIN STREET** **N/A**
1/8-1/4 **AMHERST, NY**
0.161 mi.
850 ft. **Site 1 of 4 in cluster BB**

Actual:
650 ft.

Focus Map:
8

SPILLS:

Spill Number/Closed Date:	1709316 / 2018-02-26
Facility ID:	1709316
Facility Type:	ER
DER Facility ID:	519224
Site ID:	565758
DEC Region:	9
Spill Cause:	Other
Spill Class:	B3
SWIS:	1522
Spill Date:	2018-01-11
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	2018-01-11
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2018-01-11
Spill Record Last Update:	2018-06-27
Spiller Name:	Not reported
Spiller Company:	BENDERSON DEVELOPMENT
Spiller Address:	584 DELAWARE AVE
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"01/17/18 RMC/TODD HARRIS, ESG 425-6985/PHONE. EXCAVATING TODAY. 01/17/18 RMC/FILE. INSPECTED SITE DURING THE UST AND SOIL EXCAVATION. SMALL AREA TO WORK DUE TO ROADS, BUILDINGS AND UTILITIES. SIDEWALL STILL HAD PETROLEUM ODORS AFTER EXCAVATION WAS COMPLETED. 02/26/18 RMC/FILE. REVIEWED ESG REPORT DATED 2/2/18. UST, 38 TONS IMPACTED SOIL,AND 505 GALLONS LIQUID CONTAMINATED MATERIAL DISPOSED OF. 5 POST EXCAVATION SAMPLES COLLECTED. SITE TO BE MADE INACTIVE DUE TO PETROLEUM TYPE ODORS AND MINOR CP51 VOC AND SVOC EXCEEDANCES IN THE POST EXCAVATION SAMPLES. LETTER INACTIVE."
Remarks:	"Found contamination while pulling what was thought to be a 500 gallon UST. Actual size is 1000 gallon. Believed to be fuel oil due to the smell and the feed and supply lines. To close the hole and excavate next week. Will call for inspection."

All Materials:

Site ID:	565758
Operable Unit ID:	1313695
Operable Unit:	01
Material ID:	2321168
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum

BENDERSON DEVELOPEMENT (Continued) **S121463669**

Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

BC272 **NIAGARA MOHAWK - LYNDALE** **NY Spills** **S102179588**
West **123 LYNDALE AVENUE** **N/A**
1/8-1/4 **BUFFALO, NY**
0.162 mi.
855 ft. **Site 1 of 2 in cluster BC**

Actual:
616 ft.

Focus Map:
8

SPILLS:

Spill Number/Closed Date:	9505191 / 1995-09-07
Facility ID:	9505191
Facility Type:	ER
DER Facility ID:	209395
Site ID:	255660
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	1502
Spill Date:	1995-07-27
Investigator:	SACALAND
Referred To:	Not reported
Reported to Dept:	1995-07-28
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	1995-09-07
Cleanup Meets Std:	True
Last Inspection:	1995-07-28
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1995-07-30
Spill Record Last Update:	1995-09-08
Spiller Name:	Not reported
Spiller Company:	NIAGARA MOHAWK
Spiller Address:	144 KENSINGTON AVENUE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SAC 07/28/95: SAC INSPECT SITE,SHRUBS,DIRT AND FENCE REMOVED,LETTER TO BE SENT ASKING FOR ANALYTICAL RESULTS. 08/01/95: FG SITE VISIT 8/1/95. TRANSFORMER ON POLE IN BACKYARD HAD LEAKED. TRANSFORMER WAS REPAIRED & SOIL REMOVED. HOMEOWNER WANTS FENCE & LAWN REPAIRED. 08/02/95: ED CHANDLER W/NIMO SAID SOIL HAS 95PPM PCB'S. EXCAV SAMPLE TO BE COLLECTED. RESULTS & DISPOSAL RECPT TO BE SUBMITTED TO OFFICE BY FRANK GRABOWSKI. 08/30/95: SAC TELCON FRANK GRABOWSKI/NI-MO,NI-MO'S CLAIM DEPT.IS DEALING W/MR & MRS.BRACKETT,NO CONFIRMATORY SAMPLE TAKEN BECAUSE <1 LB OF PCBS WERE SPILLED&SAMPLING IS NOT REQUIRED PER 40CFR PART 761. 09/07/95: RECEIVED DISPOSAL RECEIPTS AND SAMPLE RESULTS. "
Remarks:	"POLE MOUNTED TRANSFORMER BOTTOM DETERIORATED AND LEAKED"

All Materials:

NIAGARA MOHAWK - LYNDALE (Continued) **S102179588**

Site ID:	255660
Operable Unit ID:	1016174
Operable Unit:	01
Material ID:	363186
Material Code:	0017A
Material Name:	PCB oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	8.00
Units:	G
Recovered:	8.00
Oxygenate:	Not reported

BC273 **ERNS** **95301753**
West **123 LYNDALE AVE** **N/A**
1/8-1/4 **BUFFALO, NY**
0.162 mi.
855 ft. **Site 2 of 2 in cluster BC**

Actual:
616 ft.

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

Focus Map:
8

---

274 **NOCO ENERGY** **NY Spills** **S103272302**
West **82 TREADWELL ROAD** **N/A**
1/8-1/4 **TONAWANDA, NY**
0.162 mi.
856 ft.

Actual:
590 ft.

SPILLS:

Focus Map:
6

Spill Number/Closed Date:	9010521 / 1991-02-13
Facility ID:	9010521
Facility Type:	ER
DER Facility ID:	190338
Site ID:	230969
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	1564
Spill Date:	1990-12-31
Investigator:	MXFRANKS
Referred To:	Not reported
Reported to Dept:	1990-12-31
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Tank Truck
Spill Notifier:	Local Agency
Cleanup Ceased:	1991-02-13
Cleanup Meets Std:	True
Last Inspection:	1990-12-31
Recommended Penalty:	False
UST Trust:	False

NOCO ENERGY (Continued) **S103272302**

Remediation Phase:	0
Date Entered In Computer:	1990-12-31
Spill Record Last Update:	1996-01-03
Spiller Name:	Not reported
Spiller Company:	NOCO ENERGY
Spiller Address:	700 GRAND ISLAND
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MF 12/31/90: MF 12/31/90 SITE VISIT, MORE CLEAN UP NEEDED. TELECON SPILLER, THEY WILL GET SOMEONE OUT IMMEDIATELY. 02/13/91: MF 2/13/91 LETTER FROM NOCO. DEBRIS FROM THIS SPILL < 200 LBS. WILL BE DISPOSED OF WITH DEBRIS FROM SPILL # 9011062. NO FUTHER ACTION NECESSARY. "
Remarks:	"HOSE BLEW DURING DELIVERY"

All Materials:

Site ID:	230969
Operable Unit ID:	950830
Operable Unit:	01
Material ID:	430671
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	30.00
Units:	G
Recovered:	30.00
Oxygenate:	Not reported

275
WSW
1/8-1/4
0.163 mi.
862 ft.

KADIMAH SCHOOL OF BUFFALO **FINDS** **1007762985**
2675 NORTH FOREST RD **N/A**
AMHERST, NY 14068

Actual:
577 ft.

Focus Map:
2

FINDS:

Registry ID: 110019254064

Environmental Interest/Information System
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

276
East
1/8-1/4
0.164 mi.
868 ft.

BJ'S WHOLESALE CLUB
3080 SHERIDAN DR
AMHERST, NY 14226

NY Spills **S117852520**
N/A

Actual:
597 ft.

Focus Map:
6

SPILLS:

Spill Number/Closed Date:	1500888 / 2015-07-14
Facility ID:	1500888
Facility Type:	ER
DER Facility ID:	461817
Site ID:	507061
DEC Region:	9
Spill Cause:	Unknown
Spill Class:	D3
SWIS:	1522
Spill Date:	2015-04-25
Investigator:	SACALAND
Referred To:	Not reported
Reported to Dept:	2015-04-25
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2015-04-25
Spill Record Last Update:	2015-07-14
Spiller Name:	DON GUAY
Spiller Company:	ARG TRUCKING
Spiller Address:	369 BOSTWICK ROAD
Spiller Company:	001
Contact Name:	DONALD GUAY
DEC Memo:	"4/25/15:SAC TELECON DON GUAY - ARG. MR. GUAY SAID THE SPILL WAS BELIEVED TO BE 5 GALLONS BUT SOME DID MAKE IT INTO A STORM DRAIN. THEY HAVE CONTACTED EP&S OF VERMONT WITH A VACUUM TRUCK TO CLEAN OUT THE CATCH BASIN. SAC NOTIFIED DOMINIC CREAMER - TOWN OF AMHERST REGARDING THE SPILL. SAC TELECON GREG BLACK - ARG AND RON HUNTINGTON - SP&S PF VERMONT. THEY REMOVED THE PRODUCT AND SEDIMENT IN THE CATCHBASIN. THEY ALSO PUT BOOM IN THE THE CATCH BASIN AND THE DOWNSTREAM CATCH BASIN. NO PID WAS USED TO SCREEN CATCH BASIN. SAC INSPECT SITE. SAW SPILL AREA AND FOUND BOOM INSTALLED THE CATCH BASIN . USED PID METER TO SCREEN NSIDE THE CATCH BASIN. MEASURED READING ON THE PID METER. NOTICED ODORS WHEN CLOSELY EXAMINING THE GRATE. SAC CALLED GREG BLACK AND LEFT MESSAGE REGARDING RESULTS OF INSPECTION. SAC TELECON GREG BLACK. DISCUSSED INSPECTION RESULTS. MR. BLACK WILL CONTACT GREG WEBER - EP&S OF VERMONT TO FURTHER CLEAN UP THE CATCH BASIN. SAC TELECON GREG WEBER. DISCUSSED THE RESULTS OF THE INSPECTION. MR. WEBER WILL SEND A CREW TO FLUSH OUT CATCH BASIN AND CAPTURE RINSE. HE INTENDS TO HAVE A PID METER ON-SITE TO SCREEN THE BASIN AFTER THE CLEAN UP. SAC TELECON GREG WEBER. MR. WEBER SAID HE WAS ON-SITE WITH RON HUNTINGTON. THEY FLUSHED LINE ON BOTH SIDES AND REPLACED THE INSTALLED BOOMS. PID METER READINGS WERE AS LOW AS 3 PPM IN LINE. 5/21/15:SAC TELECON GREG WEBER. MR. WEBER SAID THAT JOHNNY ELSBERRY FROM HIS OFFICE INSPECTED SITE AND CHECKED CATCH BASINS. NO

BJ'S WHOLESALE CLUB (Continued) **S117852520**

SHEEN OBSERVED AND PID METER READINGS WERE NOT ABOVE 2 ppm. HE REQUESTED REMOVING THE BOOM IN PLACE IN THE BASINS. SAC TOLD MR. WEBER THERE WERE NO OBJECTIONS TO REMOVING THE BOOM. 7/14/15:RECEIVED DISPOSAL RECEIPTS. NO FURTHER WORK IS REQUIRED."

Remarks: "cleanup in progress"

All Materials:

Site ID:	507061
Operable Unit ID:	1256398
Operable Unit:	01
Material ID:	2259290
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

277
WSW
1/8-1/4
0.165 mi.
871 ft.

JEWISH COMMUNITY CENTER OF BUF **FINDS 1010030330**
2640 NORTH FOREST ROAD **ECHO N/A**
GETZVILLE, NY 14068

Actual:
575 ft.

Focus Map:
2

FINDS:

Registry ID: 110028138628

Environmental Interest/Information System

US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1010030330
Registry ID:	110028138628
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110028138628

BB278 **BLACKWELL PLAZA SERVICE GAS STA** **EDR Hist Auto** **1014538390**
NE **3614 MAIN ST** **N/A**
1/8-1/4 **BUFFALO, NY 14214**
0.169 mi.
893 ft. **Site 2 of 4 in cluster BB**

Actual: EDR Hist Auto
652 ft.

Focus Map: Year: Name: Type:
8 1975 BLACKWELL PLAZA SERVICE GAS STA GASOLINE STATIONS

BD279 **ADVANCE AUTO PARTS #4646** **RCRA-SQG** **1024090896**
West **2907 SHERIDAN DR** **NYR000234690**
1/8-1/4 **TONAWANDA, NY 14150**
0.172 mi.
910 ft. **Site 1 of 2 in cluster BD**

Actual: RCRA-SQG:
595 ft.

Focus Map: Date form received by agency: 11/30/2017
6 Facility name: ADVANCE AUTO PARTS #4646
Facility address: 2907 SHERIDAN DR
TONAWANDA, NY 14150
EPA ID: NYR000234690
Mailing address: AIRPORT RD
ROANOKE, VA 24012
Contact: MICAH S THOMPSON
Contact address: AIRPORT RD
ROANOKE, VA 24012
Contact country: US
Contact telephone: 540-561-8492
Contact email: MICAH.THOMPSON@ADVANCE-AUTO.COM
EPA Region: 02
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: GENERAL PARTS DISTRIBUTION LLC
Owner/operator address: E MILLBROOK RD
RALEIGH, NC 27604
Owner/operator country: US
Owner/operator telephone: 919-573-3000
Owner/operator email: MICAH.THOMPSON@ADVANCE-AUTO.COM
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 05/28/2013
Owner/Op end date: Not reported

Owner/operator name: THE CALLAHAN LLC
Owner/operator address: SYMPHONY CIR
ORCHARD PARK, NY 14127
Owner/operator country: US
Owner/operator telephone: 718-675-0678
Owner/operator email: JMCDONNELL@CUSTOMCARPETCENTERS.COM

ADVANCE AUTO PARTS #4646 (Continued) **1024090896**

Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/01/2000
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D005
. Waste name: BARIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003

ADVANCE AUTO PARTS #4646 (Continued) **1024090896**

. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

BD280
West
1/8-1/4
0.172 mi.
910 ft.

ADVANCE AUTO PARTS #4646 **FINDS 1024084693**
2907 SHERIDAN DR **ECHO N/A**
TONAWANDA, NY 14150

Site 2 of 2 in cluster BD

Actual:
595 ft.

Focus Map:
6

FINDS:

Registry ID: 110070205816

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1024084693
Registry ID: 110070205816
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110070205816

BE281 **SAVERS STORE #1217** **RCRA-CESQG** **1000292053**
West **2309 EGGERT RD** **FINDS** **NYD981139850**
1/8-1/4 **TONAWANDA, NY 14150** **ECHO**
0.176 mi.
927 ft. **Site 1 of 2 in cluster BE**

Actual:
594 ft.

Focus Map:
6

RCRA-CESQG:

Date form received by agency:	10/29/2014
Facility name:	SAVERS STORE #1217
Facility address:	2309 EGGERT RD TONAWANDA, NY 14150
EPA ID:	NYD981139850
Mailing address:	SOUTHEAST 6TH ST, SUITE 220 BELLEVUE, WA 98004
Contact:	RANDY RAINES
Contact address:	SOUTHEAST 6TH ST, SUITE 220 BELLEVUE, WA 98004
Contact country:	US
Contact telephone:	615-773-8600
Contact email:	RRCSAVES@COMCAST.NET
EPA Region:	02
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	SAVERS STORE #1217
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	06/09/2014
Owner/Op end date:	Not reported

Owner/operator name:	TVI INCORPORATED
Owner/operator address:	LAKE WASHINGTON BLVD SE BELLEVUE, NY 14219
Owner/operator country:	US
Owner/operator telephone:	716-833-2391
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported

SAVERS STORE #1217 (Continued) **1000292053**

Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 06/09/2014
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D005
. Waste name: BARIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D016
. Waste name: 2,4-D

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

SAVERS STORE #1217 (Continued) **1000292053**

Historical Generators:
Date form received by agency: 01/01/2007
Site name: BELLS SUPERMARKET
Classification: Not a generator, verified

Date form received by agency: 01/01/2006
Site name: BELLS SUPERMARKET
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: BELLS SUPERMARKET
Classification: Not a generator, verified

Date form received by agency: 10/31/1985
Site name: BELLS SUPERMARKET
Classification: Large Quantity Generator

. Waste code: X002
. Waste name: POLYCHLORINATED BIPHENOLS (PCBs)

Violation Status: No violations found

FINDS:

Registry ID: 110004400826

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000292053
Registry ID: 110004400826
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004400826

BE282 **SAVERS #1217** **NY MANIFEST** **S117562542**
West **2309 EGGERT RD** **N/A**
1/8-1/4 **TONAWANDA, NY 14150**
0.176 mi.
927 ft. **Site 2 of 2 in cluster BE**

Actual:
594 ft.

Focus Map:
6

NY MANIFEST:
Country: USA
EPA ID: NYD981139850
Facility Status: Not reported
Location Address 1: 2309 EGGERT RD
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported

SAVERS #1217 (Continued) **S117562542**

Location City:	TONAWANDA
Location State:	NY
Location Zip:	14150
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD981139850
Mailing Name:	SAVERS #1217
Mailing Contact:	SAVERS #1217
Mailing Address 1:	2309 EGGERT RD
Mailing Address 2:	Not reported
Mailing City:	TONAWANDA
Mailing State:	NY
Mailing Zip:	14150
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7168332391

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	MNS000110924
Trans2 State ID:	MIK126399684
Generator Ship Date:	05/07/2018
Trans1 Recv Date:	05/07/2018
Trans2 Recv Date:	05/16/2018
TSD Site Recv Date:	05/21/2018
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD981139850
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	MID980615298
TSDF ID 2:	Not reported
Manifest Tracking Number:	001854949PSC
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	43
Units:	P - Pounds
Number of Containers:	1

SAVERS #1217 (Continued) **S117562542**

Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	D001
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
17 additional NY MANIFEST: record(s) in the EDR Site Report.

---

283 **DOUG AL AUTOMOTIVE AUTO RPR** **EDR Hist Auto** **1014537705**
WSW **252 KENMORE AVE** **N/A**
1/8-1/4 **BUFFALO, NY 14223**
0.177 mi.
933 ft.

Actual:
620 ft.

EDR Hist Auto

Focus Map:
8

Year:	Name:	Type:
1985	DOUG AL AUTOMOTIVE INC GAS STA	GASOLINE STATIONS
1985	DOUG-AL AUTOMOTIVE INC	General Automotive Repair Shops
1986	DOUG-AL AUTOMOTIVE INC	General Automotive Repair Shops
1987	DOUG-AL AUTOMOTIVE INC	General Automotive Repair Shops
1988	DOUG-AL AUTOMOTIVE INC	General Automotive Repair Shops
1989	DOUG-AL AUTOMOTIVE INC	General Automotive Repair Shops
1990	DOUG-AL AUTOMOTIVE INC	General Automotive Repair Shops
1991	DOUG-AL AUTOMOTIVE INC	General Automotive Repair Shops
1992	DOUG AL AUTOMOTIVE INC GAS STA	GASOLINE STATIONS
1992	DOUG-AL AUTOMOTIVE INC	General Automotive Repair Shops
1993	DOUG-AL AUTOMOTIVE INC	General Automotive Repair Shops
1994	DOUG-AL AUTOMOTIVE INC	General Automotive Repair Shops
1995	DOUG-AL AUTOMOTIVE INC	General Automotive Repair Shops
1996	DOUG-AL AUTOMOTIVE INC	General Automotive Repair Shops
1997	DOUG-AL AUTOMOTIVE INC	General Automotive Repair Shops
1998	DOUG AL AUTOMOTIVE AUTO RPR	AUTOMOBILE REPAIRING & SERVICE
1998	DOUG-AL AUTOMOTIVE INC	General Automotive Repair Shops
1999	DOUG-AL AUTOMOTIVE INC	General Automotive Repair Shops
2000	DOUG-AL AUTOMOTIVE INC	General Automotive Repair Shops
2001	DOUG-AL AUTOMOTIVE INC	General Automotive Repair Shops
2002	DOUG-AL AUTOMOTIVE INC	General Automotive Repair Shops
2003	DOUG-AL AUTOMOTIVE INC	General Automotive Repair Shops
2004	DOUG AL AUTOMOTIVE INC	General Automotive Repair Shops
2005	DOUG AL AUTOMOTIVE INC	General Automotive Repair Shops
2006	DOUG AL AUTOMOTIVE INC	General Automotive Repair Shops
2007	DOUG AL AUTOMOTIVE INC	General Automotive Repair Shops
2008	DOUG AL AUTOMOTIVE INC	General Automotive Repair Shops
2009	DOUG AL AUTOMOTIVE INC	General Automotive Repair Shops
2010	DOUG AL AUTOMOTIVE INC	General Automotive Repair Shops
2011	DOUG AL AUTOMOTIVE INC	General Automotive Repair Shops
2012	DOUG AL AUTOMOTIVE INC	Automotive Glass Replacement Shops
2013	DOUG AL AUTOMOTIVE INC	Road, Airport, And Parking Lot Maintenance Services
2014	DOUG AL AUTOMOTIVE INC	Automotive Glass Replacement Shops

284
West
1/8-1/4
0.178 mi.
938 ft.

SEPTIC TANK FAILURE
4140 RENSCH ROAD
AMHERST, NY

NY Spills **S103569438**
N/A

Actual:
589 ft.

Focus Map:
4

SPILLS:

Spill Number/Closed Date:	9602794 / 1996-05-30
Facility ID:	9602794
Facility Type:	ER
DER Facility ID:	206899
Site ID:	252578
DEC Region:	9
Spill Cause:	Other
Spill Class:	D5
SWIS:	1522
Spill Date:	1996-05-25
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	1996-05-28
CID:	211
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-05-28
Spill Record Last Update:	1996-05-31
Spiller Name:	Not reported
Spiller Company:	UNKNOWN CONTRACTOR
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	DANIEL HULL
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 5/28/96:RMC GAVE COPY OF REPORT TO DIV.OF WATER AND REFERRED SPILL TO THEM."
Remarks:	"caller reports contractor installed septic system and it is now leaking raw sewage on callers property - caller wants dec rep to call contractor to have him fix problem"

All Materials:

Site ID:	252578
Operable Unit ID:	1034108
Operable Unit:	01
Material ID:	349033
Material Code:	0062A
Material Name:	raw sewage
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

285 West 1/8-1/4 0.178 mi. 941 ft. — **TANK AT LINDKE RESIDENCE**, **25 QUAKER RIDGE**, **TONAWANDA, NY** — **NY Spills** — **S102561409** / **N/A**

Actual: 592 ft.

Focus Map: 6

SPILLS:

Spill Number/Closed Date:	9614121 / 1997-04-29
Facility ID:	9614121
Facility Type:	ER
DER Facility ID:	59152
Site ID:	60628
DEC Region:	9
Spill Cause:	Human Error
Spill Class:	C3
SWIS:	1564
Spill Date:	1997-03-04
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	1997-03-04
CID:	282
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	1997-04-01
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-03-04
Spill Record Last Update:	1997-04-29
Spiller Name:	Not reported
Spiller Company:	NOCO ENERGY
Spiller Address:	700 GRAND ISLAND BLVD
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 03/04/97 RMC/DICK ELLMAN,NOCO/PHONE NOCO SPILLED ABOUT 20 GALLONS TO BASEMENT FROM OVERFILL, NOCO CLEANING UP, RMC CALLED THE OWNER, NO ANSWER, 03/05/97 RMC/FILE LEFT MESSAGE ON HOMEOWNERS MACHINE, CALL DUE 3/6/97 03/07/97 RMC/CYNTHIA LINDKE/SITE SPILL IN BASEMENT VISUALLY CLEAN, SPILL INITIALL COVERED A 5 BY 10 FOOT AREA, NOCO HAS HIRED ENVIRO CARE TO DEODORIZE AREA AND HOME AS ODORS STILL DETECTABLE, RMC TO CALL NEXT WEEK TO SEE IF HOME OWNER IS SATISFIED, CALL 03/10/97 03/19/97 RMC/LINDKE/PHONE SOME OIL STILL OUTSIDE ON HOUSE, 03/19/97 RMC/GARY ROESCH/PHONE NOCO TO CLEAN UP, INSPECT 4/1/97 04/28/97 RMC/FILE RMC INSPECTED SITE TWICE AND FOUND CLEANUP TO BE COMPLETE, NO FURTHER ACTION REQUIRED, NOCO TOOK CONTAMINATED MATERIALS BACK TO FACILITY FOR BIOTREATING, CLOSE OUT "
Remarks:	"DELIVERY ERROR 249.1 YESTERDAY 22.6 TODAY SPRAYED INTO CELLAR NOCO CLEANING UP "

All Materials:

Site ID:	60628
Operable Unit ID:	1041681
Operable Unit:	01
Material ID:	339230
Material Code:	0001A
Material Name:	#2 fuel oil

TANK AT LINDKE RESIDENCE (Continued) **S102561409**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	20.00
Oxygenate:	Not reported

286
SSW
1/8-1/4
0.180 mi.
952 ft.

BASEMENT
8 RADCLIFFE RD.
BUFFALO, NY

NY Spills **S112809410**
N/A

Actual:
634 ft.

Focus Map:
8

SPILLS:

Spill Number/Closed Date:	1214739 / 2013-01-28
Facility ID:	1214739
Facility Type:	ER
DER Facility ID:	433302
Site ID:	478005
DEC Region:	9
Spill Cause:	Unknown
Spill Class:	Not reported
SWIS:	1502
Spill Date:	2013-01-18
Investigator:	TDJOHNSO
Referred To:	Not reported
Reported to Dept:	2013-01-18
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2013-01-18
Spill Record Last Update:	2013-01-28
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	Not reported
Contact Name:	ART BAJ
DEC Memo:	"01/18/13 TDJ MET BUFFALO HAZ MAT AT RESIDENCE HERE DURING A CLEANOUT OF DECEASED RELATIVES HOUSE THE WORKERS FOUND A CONTAINER CONTAINING LIQUID MERCURY. THEY CONTACTED THE FIRE DEPARTMENT NOT KNOWING WHAT TO DO WITH IT. THE MERCURY WAS FOUND IN A CLOSET AND I WAS TOLD THAT THE RELATIVE WORKED ON CLOCKS AND RECIEVED MERCURY WITH EACH PURCHASE. EXTRA MERCURY WAS SENT ALOT DUE TO DAMAGE TO THE PACKAGING. THE RELATIVES WILL EITHER CONTACT A RECYCLING FIRM FOR REMOVAL OR SEE IF THE HOUSEHOLD HAZARDOUS WASTE WILL TAKE. OTHER HOUSEHOLD CHEMICAL WILL BE BOXED FOR THE SAME WASTE COLLECTION DAY FOR THE COUNTY RESIDENTS. NO SPILLAGE HAD TO BE DEALT WITH. WILL STAY IN CONTACT WITH THE RELATIVE ON MOVEMENT OF MATERIALS. 01/28/13 TDJ CONTACTED ART BAJ WHO IS THE RELATIVE IN CHARGE OF HOUSE CLEANOUT. HE STATED THAT HE CONTACTED HOUSEHOLD HAXARDOUS WASTE COLLECTION BUREAU WHO

BASEMENT (Continued) **S112809410**

STATED THAT THEY CAN TAKE THE MERCURY AT THEIR COLLECTION POINT IN JUNE 2013. HE HAS MERCURY CONTAINED AND IN SAFE LOCATION UNTIL DISPOSAL DATE. OTHER CHEMICALS WERE IN SMALL AMOUNTS AND WILL ALSO BE TAKEN TO DISPOSAL SITE IF OTHER MEANS ARE NOT AVAILABLE. NO FURTHER ACTION FILE CLOSED TO ELECTRONIC ONLY"

Remarks: "CALLER STATES THAT THE FIRE DEPT. FOUND A CONTAINER OF MERCURY(WHICH DID NOT LEAK) & SOME CAUSTIC CONTAINERS,WHICH DID LEAK...REQUESTING DEC RESPONSE."

All Materials:

Site ID:	478005
Operable Unit ID:	1227788
Operable Unit:	01
Material ID:	2225330
Material Code:	0031A
Material Name:	mercury
Case No.:	07439976
Material FA:	Hazardous Material
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

BB287 **EDDIES ASHLAND SERVICE** **EDR Hist Auto** **1014537223**
NE **3620 MAIN ST** **N/A**
1/8-1/4 **BUFFALO, NY 14226**
0.184 mi.
970 ft. **Site 3 of 4 in cluster BB**

Actual: EDR Hist Auto
653 ft.

Focus Map:
8

Year:	Name:	Type:
1955	FRONTIER SERV STA	GASOLINE STATIONS
1960	ASHLAND SERV GAS STA	GASOLINE STATIONS
1964	GORDONS SERVICE GAS STA	GASOLINE STATIONS
1969	EDDIES ASHLAND SERVICE	Gasoline Service Stations
1970	EDDIES ASHLAND SERVICE	Gasoline Service Stations
1972	GENTILE LENNY	Gasoline Service Stations

---

288 **UNION CONCRETE CO.** **NY Spills** **S108957525**
WNW **451 MEYERS RD** **N/A**
1/8-1/4 **WEST SENECA, NY**
0.186 mi.
981 ft.

Actual: SPILLS:
595 ft.

Focus Map:
4

Spill Number/Closed Date:	0751095 / 2008-01-30
Facility ID:	0751095
Facility Type:	ER
DER Facility ID:	339329
Site ID:	389743
DEC Region:	9
Spill Cause:	Housekeeping
Spill Class:	C3
SWIS:	1568
Spill Date:	2007-11-09

UNION CONCRETE CO. (Continued) **S108957525**

Investigator:	rjjonak
Referred To:	Not reported
Reported to Dept:	2007-11-09
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2007-11-13
Spill Record Last Update:	2008-01-30
Spiller Name:	ROBERT HILL
Spiller Company:	UNION CONCRETE CO.
Spiller Address:	451 MEYERS RD
Spiller Company:	999
Contact Name:	ROBERT HILL
DEC Memo:	"11/9/2007: RJJ/ECO WILSON AT SITE AT 1515...IN THE REAR OF THE PROPERTY,WHERE THEY STAGE THEIR SCRAP METAL & CRUSHED OIL FILTERS,THERE ARE A FEW SMALL AREAS OF STAINED SOIL FROM THE OIL FILTERS...ALSO,THERE IS A DRIPPING DIESEL FUEL TANK,(THE VALVE WAS NOT SHUT-OFF COMPLETELY)WITH SECONDARY CONTAINMENT,WHICH HAS SPILL OUT ~5 GAL OF DIESEL FUEL ON THE STONE DRIVEWAY...MR. ROBERT HILL,OWNER UNION CONCRETE,SAID THAT THEY WILL SCRAPE UP ALL THE AFFECTED AREAS AND DISPOSE THE MATERIAL AT A LANDFILL...NONE OF THE MOTOR OIL OR DIESEL FUEL REACHED ANY WATERWAYS,IT IS ALL ON THEIR STONE DRIVEWAY...MR. HILL WILL SEND ME THE DISPOSAL RECEIPTS. 11/13/2007: RJJ AT SITE AT 1100...UNION CONCRETE HAS SCRAPED UP ALL THE AFFECTED STAINED SOIL AND PLACED THE MATERIAL INTO 2-55 GAL DRUMS WHICH ARE STAGED ON SITE,AWAITING DISPOSAL. 1/30/2008: RECEIVED THE SPILL INCIDENT REPORT AND DISPOSAL RECEIPTS FROM UCC,ROBERT HILL...THE MATERIAL WAS TAKEN TO THE CHAUTAUQUA COUNTY LANDFILL FOR DISPOSAL...THE SPILL HAS BEEN CLEANED UP AND PROPERLY DISPOSED OF...NO FURTHER ACTION NEEDED...SPILL CLOSED OUT."
Remarks:	"CALLER STATES THAT THERE IS OIL ON THE GROUND ON THIS PROPERTY."

All Materials:

Site ID:	389743
Operable Unit ID:	1146876
Operable Unit:	01
Material ID:	2137267
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	5.00
Oxygenate:	False

BF289 **NY COOLING TOWERS** **S121989028**
SE **300 CORPORATE PKWY** **N/A**
1/8-1/4 **AMHERST, NY 14226**
0.187 mi.
985 ft. **Site 1 of 2 in cluster BF**

Actual:
592 ft.

Focus Map:
7

COOLING TOWERS:

Equipment Unique ID:	1035
Equipment Borough:	300
Intended Use:	Air Conditioning
Manufacturer:	BAC
Model:	VLT-126-MCX
Cooling Capacity:	114
Cooling Capacity Unit:	Tonnage
Commissioned Date:	01/01/1997
Inspection Date:	07/19/2018
Date of Bacteriological Collection:	08/15/2018
Date of Legionella Collection:	08/15/2018
Last Legionella Result > 1,000 CFU/mL:	no
Latitude:	42.988820034
Longitude:	-78.80039347

BF290 **NY COOLING TOWERS** **S121989038**
SE **300 CORPORATE PKWY** **N/A**
1/8-1/4 **AMHERST, NY 14226**
0.187 mi.
985 ft. **Site 2 of 2 in cluster BF**

Actual:
592 ft.

Focus Map:
7

COOLING TOWERS:

Equipment Unique ID:	1036
Equipment Borough:	300
Intended Use:	Air Conditioning
Manufacturer:	BAC
Model:	VLT-126-MCX
Cooling Capacity:	114
Cooling Capacity Unit:	Tonnage
Commissioned Date:	01/01/1997
Inspection Date:	07/19/2018
Date of Bacteriological Collection:	08/15/2018
Date of Legionella Collection:	08/15/2018
Last Legionella Result > 1,000 CFU/mL:	no
Latitude:	42.988820034
Longitude:	-78.80039347

---

291 **ERNS** **9053110**
West **95 TREADWELL AVE** **N/A**
1/8-1/4 **TONAWANDA, NY**
0.189 mi.
996 ft.

Actual:
590 ft.

Focus Map:
6

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

BB292 **FRONTIER OIL CO BR GAS STA** **EDR Hist Auto** **1014537753**
NE **3624 MAIN ST** **N/A**
1/8-1/4 **BUFFALO, NY**
0.191 mi.
1008 ft. **Site 4 of 4 in cluster BB**

Actual: EDR Hist Auto
653 ft.

Focus Map: Year: Name: Type:
8 1950 FRONTIER OIL CO BR GAS STA GASOLINE STATIONS

BG293 **NORTHTOWN ONE HOUR CLEANERS*** **EDR Hist Cleaner** **1020051156**
East **3075 SHERIDAN DR** **N/A**
1/8-1/4 **BUFFALO, NY 14226**
0.192 mi.
1012 ft. **Site 1 of 9 in cluster BG**

Actual: EDR Hist Cleaner
598 ft.

Focus Map: Year: Name: Type:
6 1970 NORTHTOWN ONE HOUR CLEANERS* Drycleaning Plants, Except Rugs
1971 NORTHTOWN ONE HOUR CLEANERS* Drycleaning Plants, Except Rugs
1972 NORTHTOWN ONE HOUR CLEANERS* Drycleaning Plants, Except Rugs

---

BG294 **GI-RO DRY CLEANERS** **ICIS** **1017783261**
East **3077 SHERIDAN DR?NORTHTOWN PLA** **US AIRS** **N/A**
1/8-1/4 **AMHERST, NY 14226**
0.192 mi.
1015 ft. **Site 2 of 9 in cluster BG**

Actual: ICIS:
598 ft.

Focus Map:
6

Enforcement Action ID:	NY000A0000914220028600316
FRS ID:	110004355705
Action Name:	GI-RO DRY CLEANERS 36029R044700316
Facility Name:	GI-RO DRY CLEANERS
Facility Address:	3077 SHERIDAN DR?NORTHTOWN PLA AMHERST, NY 142261910
Enforcement Action Type:	Notice of Violation
Facility County:	ERIE
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Informal
EA Type Code:	NOV
Facility SIC Code:	7216
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	42.980531
Longitude in Decimal Degrees:	-78.819571
Permit Type Desc:	Not reported
Program System Acronym:	NY0000009142200286
Facility NAICS Code:	812320
Tribal Land Code:	Not reported

Enforcement Action ID:	NY000A0000914220028600309
FRS ID:	110004355705
Action Name:	GI-RO DRY CLEANERS 36029R044700309
Facility Name:	GI-RO DRY CLEANERS
Facility Address:	3077 SHERIDAN DR?NORTHTOWN PLA AMHERST, NY 142261910
Enforcement Action Type:	Notice of Violation

GI-RO DRY CLEANERS (Continued) **1017783261**

Facility County:	ERIE
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Informal
EA Type Code:	NOV
Facility SIC Code:	7216
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	42.980531
Longitude in Decimal Degrees:	-78.819571
Permit Type Desc:	Not reported
Program System Acronym:	NY0000009142200286
Facility NAICS Code:	812320
Tribal Land Code:	Not reported

US AIRS MINOR:

Envid:	1017783261
Region Code:	02
Programmatic ID:	AIR NY0000009142200286
Facility Registry ID:	110004355705
D and B Number:	Not reported
Primary SIC Code:	7216
NAICS Code:	812320
Default Air Classification Code:	MIN
Facility Type of Ownership Code:	POF
Air CMS Category Code:	Not reported
HPV Status:	Not reported

US AIRS MINOR:

Region Code:	02
Programmatic ID:	AIR NY0000009142200286
Facility Registry ID:	110004355705
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	MACT Standards (40 CFR Part 63)
Activity Date:	1999-11-17 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported

Region Code:	02
Programmatic ID:	AIR NY0000009142200286
Facility Registry ID:	110004355705
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	MACT Standards (40 CFR Part 63)
Activity Date:	2000-01-24 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported

Region Code:	02
Programmatic ID:	AIR NY0000009142200286
Facility Registry ID:	110004355705
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN

GI-RO DRY CLEANERS (Continued) **1017783261**

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2000-04-20 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009142200286
Facility Registry ID: 110004355705
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2000-05-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009142200286
Facility Registry ID: 110004355705
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2000-06-12 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009142200286
Facility Registry ID: 110004355705
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2000-07-10 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000009142200286
Facility Registry ID: 110004355705
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2000-04-18 00:00:00
Activity Status Date: 2000-04-18 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 02
Programmatic ID: AIR NY0000009142200286

GI-RO DRY CLEANERS (Continued) **1017783261**

Facility Registry ID:	110004355705
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	MACT Standards (40 CFR Part 63)
Activity Date:	2005-03-21 00:00:00
Activity Status Date:	2005-03-21 00:00:00
Activity Group:	Enforcement Action
Activity Type:	Administrative - Informal
Activity Status:	Achieved

BG295 **JOSEPHS SERVICES** **EDR Hist Cleaner** **1018669165**
East **3077 SHERIDAN DRIVE** **N/A**
1/8-1/4 **BUFFALO, NY 14226**
0.192 mi.
1015 ft. **Site 3 of 9 in cluster BG**

Actual: EDR Hist Cleaner
598 ft.

Focus Map:
6

Year:	Name:	Type:
1973	NORTHTOWN ONE HOUR CLEANERS*	Drycleaning Plants, Except Rugs
1974	NORTHTOWN ONE HOUR CLEANERS*	Drycleaning Plants, Except Rugs
1975	NORTHTOWN ONE HOUR CLEANERS*	Drycleaning Plants, Except Rugs
1976	NORTHTOWN OE HR CS IC	Drycleaning Plants, Except Rugs
1977	NORTHTOWN ONE HOUR CLRS INC	Drycleaning Plants, Except Rugs
1978	NORTHTOWN ONE HR CLRS INC	Drycleaning Plants, Except Rugs
1979	NORTHTOWN ONE HR CLRS INC	Drycleaning Plants, Except Rugs
1980	NORTHTOWN ONE HR CLRS INC	Drycleaning Plants, Except Rugs
1982	NORTHTOWN ONE HR CLRS INC	Drycleaning Plants, Except Rugs
1983	NORTHTOWN ONE HR CLRS INC	Drycleaning Plants, Except Rugs
1985	NORTHTOWN ONE HR CLRS INC	Drycleaning Plants, Except Rugs
1986	JOSEPHS SERVICES	Garment Pressing And Cleaners' Agents
1986	NORTHTOWN ONE HOUR CLEANERS*	Drycleaning Plants, Except Rugs
1987	NORTHTOWN ONE HOUR CLEANERS*	Drycleaning Plants, Except Rugs
1987	JOSEPHS SERVICES	Garment Pressing And Cleaners' Agents
1988	NORTHTOWN ONE HOUR CLEANERS	Drycleaning Plants, Except Rugs
1988	JOSEPHS SERVICES	Garment Pressing And Cleaners' Agents
1989	NORTHTOWN ONE HOUR CLEANERS	Drycleaning Plants, Except Rugs
1989	JOSEPHS SERVICES	Garment Pressing And Cleaners' Agents
1990	JOSEPHS SERVICES	Garment Pressing And Cleaners' Agents
1990	NORTHTOWN ONE HOUR CLEANERS	Drycleaning Plants, Except Rugs
1991	NORTHTOWN ONE HOUR CLEANERS	Drycleaning Plants, Except Rugs
1991	JOSEPHS SERVICES	Garment Pressing And Cleaners' Agents
1992	JOSEPHS SERVICES	Garment Pressing And Cleaners' Agents
1992	NORTHTOWN ONE HOUR CLEANERS	Drycleaning Plants, Except Rugs
1993	NORTHTOWN ONE HOUR CLEANERS	Drycleaning Plants, Except Rugs
1993	JOSEPHS SERVICES	Garment Pressing And Cleaners' Agents
1994	JOSEPHS SERVICES	Garment Pressing And Cleaners' Agents
1994	NORTHTOWN ONE HOUR CLEANERS	Drycleaning Plants, Except Rugs
1995	JOSEPHS SERVICES	Garment Pressing And Cleaners' Agents
1996	NORTHTOWN ONE HOUR CLEANERS	Drycleaning Plants, Except Rugs
1997	NORTHTOWN ONE HOUR CLEANERS	Drycleaning Plants, Except Rugs

BG296 **GI-RO/NORTHTOWN CLEANING CENTER** **NY DRYCLEANERS** **S110246693**
East **3077 SHERIDAN DRIVE,EGGRTSV** **N/A**
1/8-1/4 **AMHERST, NY 14226**
0.192 mi.
1015 ft. **Site 4 of 9 in cluster BG**

Actual:
598 ft.

Focus Map:
6

DRYCLEANERS:

Facility ID:	9-1422-00286
Phone Number:	716-835-6764
Region:	Not reported
Registration Effective Date:	N/A
Inspection Date:	01MAY15
Install Date:	99/01
Drop Shop:	Y
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

BG297 **NORTHTOWN ONE HOUR CLEANERS INC** **RCRA NonGen / NLR** **1000410246**
East **3077 SHERIDAN DR** **FINDS** **NYD045166667**
1/8-1/4 **EGGERTSVILLE, NY 14226** **ECHO**
0.192 mi. **NY MANIFEST**
1015 ft. **Site 5 of 9 in cluster BG**

Actual:
598 ft.

Focus Map:
6

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	NORTHTOWN ONE HOUR CLEANERS INC
Facility address:	3077 SHERIDAN DR EGGERTSVILLE, NY 14226
EPA ID:	NYD045166667
Mailing address:	SHERIDAN DR EGGERTSVILLE, NY 14226
Contact:	Not reported
Contact address:	SHERIDAN DR EGGERTSVILLE, NY 14226
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	Not reported
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	Not reported
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999

NORTHTOWN ONE HOUR CLEANERS INC (Continued) **1000410246**

Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: NORTHTOWN ONE HOUR CLEANERS INC
Classification: Not a generator, verified

Date form received by agency: 07/14/1999
Site name: NORTHTOWN ONE HOUR CLEANERS INC
Classification: Small Quantity Generator

Date form received by agency: 07/02/1985
Site name: NORTHTOWN ONE HOUR CLEANERS INC
Classification: Large Quantity Generator

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

FINDS:

Registry ID: 110004355705

NORTHTOWN ONE HOUR CLEANERS INC (Continued) **1000410246**

Environmental Interest/Information System

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

AIR MINOR

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000410246
Registry ID:	110004355705
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004355705

NY MANIFEST:

Country:	USA
EPA ID:	NYD045166667
Facility Status:	Not reported
Location Address 1:	3077 SHERIDANDRIVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	EGGERTSVILLE
Location State:	NY
Location Zip:	14226
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD045166667
Mailing Name:	NORTHTOWN ONE HOUR CLEANER
Mailing Contact:	NORTHTOWN ONE HOUR CLEANER
Mailing Address 1:	3077 SHERIDAN DRIVE
Mailing Address 2:	Not reported
Mailing City:	EGGERTSVILLE
Mailing State:	NY
Mailing Zip:	14226

NORTHTOWN ONE HOUR CLEANERS INC (Continued) **1000410246**

Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7168368884

NY MANIFEST:

Document ID:	NYC5187464
Manifest Status:	Not reported
seq:	01
Year:	1999
Trans1 State ID:	NYNA1635
Trans2 State ID:	Not reported
Generator Ship Date:	07/23/1999
Trans1 Recv Date:	07/23/1999
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/23/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD045166667
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00225
Units:	P - Pounds
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

298
NE
1/8-1/4
0.195 mi.
1028 ft.

BOULEVARD INN & SUITES
3612 MAIN ST.
AMHERST, NY 14226

NY Spills **S109208422**
N/A

Actual:
648 ft.

Focus Map:
8

SPILLS:

Spill Number/Closed Date:	0890608 / 2008-11-05
Facility ID:	0890608
Facility Type:	ER
DER Facility ID:	350326
Site ID:	401060
DEC Region:	9
Spill Cause:	Deliberate
Spill Class:	C3
SWIS:	1522
Spill Date:	2008-07-11
Investigator:	rjjonak
Referred To:	Not reported
Reported to Dept:	2008-07-11
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-07-11
Spill Record Last Update:	2008-11-05
Spiller Name:	TONY TRUSSO
Spiller Company:	BOULEVARD INN & SUITES
Spiller Address:	140 NORTH ST.
Spiller Company:	001
Contact Name:	TONY TRUSSO
DEC Memo:	"7/11/2008: RJJ/JOHN RICHTER(TOWN OF AMHERST ENGINEERING DEPT.) AT SITE AT 1330...BEHIND THE BOULEVARD INN SOMEONE HAS DUMPED AN UNKNOWN AMOUNT OF WHAT APPEARS TO BE USED MOTOR OIL...IT IS ALL ALONG THE FENCE LINE UP TO 26 CALLODINE AVE. AND SOME BEHIND THE INN ON SPRINGVILLE AVE...WE SPOKE TO THE MANAGER OF THE INN(NORA MANGAS)AND SHE SAID THAT SHE WILL CONTACT THE OWNER OF THE PROPERTY,TONY TRUSSO,AND HAVE HIM CONTACT ME...SINCE IT APPEARS THAT THIS OIL HAS BEEN HERE A LONG TIME AND IT HAS SOCKED INTO THE LEAVES/DIRT,I TOLD HER THAT THIS CAN BE CLEANED UP NEXT WEEK. 7/21/2008: TONY TRUSSO TELECON RJJ,HE SAID THAT THEY HAVE SCRAPED UP THE SMALL AFFECTED AREA AND PLACED THE MATERIAL INTO 2 BAGS,WHICH HE WILL DISPOSE AT A LANDFILL...RJJ AT SITE AT 1400...THE AREA HAS BEEN SCRAPED UP,HOWEVER,THERE IS STILL CONTAMINATED SOIL ALONG THE FENCE...I TELECON TONY TRUSSO AND LEFT A MESSAGE THAT ADDTIONAL SOIL NEEDS TO BE REMOVED. 7/22/2008: RJJ AT SITE AT 1400...BOULEVARD INN PERSONNEL HAVE FINISHED SCRAPING UP ALL THE PETROLEUM CONTAMINATED SOIL...THE SMALL AREA(~6'X2'X.5')NOW APPEARS TO HAVE NO STAINED SOIL OR ANY PETROLEUM ODORS...THEY HAVE STAGED ALL THE EXCAVATED SOIL(~.25 TONS)ON SITE AND WILL DISPOSE IT AT A LANDFILL...TONY TRUSSO WILL SEND ME THE DISPOSAL RECEIPTS. 10/3/2008: TONY TRUSSO TELECON RJJ,HE SAID THAT GREEN ENVIRONMENTAL HAS PICKED UP THE CONTAMINATED SOIL AND WILL DISPOSE IT AT A LANDILL,THEN TONY WILL SEND ME THE DISPOSAL

BOULEVARD INN & SUITES (Continued) **S109208422**

RECEIPTS. 11/5/2008: RECEIVED THE DISPOSAL RECEIPTS FROM GREEN ENVIRONMENTAL FOR THE 40 LBS. OF CONTAMINATED SOIL TAKEN TO MODERN LANDFILL...THE SPILL HAS BEEN CLEANED UP AND PROPERLY DISPOSED OF...NO FURTHER ACTION NEEDED...SPILL CLOSED OUT."

Remarks: "CALLER STATES THAT SOMEONE WAS DUMPED WASTE OIL ALONG A FENCE NEXT TO 26 CALLODINE AVE."

All Materials:

Site ID:	401060
Operable Unit ID:	1157864
Operable Unit:	01
Material ID:	2148901
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

299
WSW
1/8-1/4
0.195 mi.
1030 ft.

HOUSE
2699 NORTH FOREST ROAD
AMHERST, NY

NY Spills **S106969091**
N/A

Actual:
579 ft.

Focus Map:
2

SPILLS:

Spill Number/Closed Date:	0550518 / 2005-06-28
Facility ID:	0550518
Facility Type:	ER
DER Facility ID:	294564
Site ID:	348203
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	1522
Spill Date:	2005-06-24
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	2005-06-24
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	2005-06-28
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-06-24
Spill Record Last Update:	2005-06-28
Spiller Name:	Not reported
Spiller Company:	MENORAH CAMPUS
Spiller Address:	2700 NORTH FOREST
Spiller Company:	001

HOUSE (Continued) **S106969091**

Contact Name: GARY CLUNIE
DEC Memo: "06/24/05 RMC/GARY CLUNIE, CLOVER CONSTRUCTION, LINE GOT BROKEN OFF AST IN BASEMENT ABOUT A WEEK AGO. NO ELECTRIC IN HOUSE SO SUMP PUMP DID NOT RUN. HE THINK MOST HAS BEEN RECOVERED, HE HAS PEOPLE CLEANING UP RESIDUALS NOW MODERN WILL TAKE IN SITE DUMPSTER. RMC TO INSPECT. 06/24/05 RMC/SITE. HOUSE READY FOR BURNING AND DEMOLITION, FUEL OIL AST IN BASEMENT HAD LINE LEAK, TOTAL CONTENTS LOST. BASEMENT HAD SIX FEET OF WATER IN IT A WEEK AGO, FD PUMPED OUT. OIL FOUND IN BASEMENT THE NEXT DAY. ELMWOOD PUMPED OUT 1300 GALLONS OF OIL/WATER TODAY. HALF OT 1 INCH OIL NOW ON SURFACE OF THE SUMP. UNKNOWN IF IT RAN OFF FLOOR OR IF IT IS COMING FROM PERIMETER DRAIN. RMC GAVE BOOMS AND PADS TO REMOVE. OIL OFF SUMP. TO TALK WITH CLOONIE MONDAY, 06/27/05 RMC/CLOONIE/PHONE. HE THINKS IT WAS JUST RESIDUAL ON THE FLOOR THAT RAN INTO THE SUMP. HE SAYS NO SHEEN REMAINS. RMC TO REINSPECT. 06/28/05 RMC/SITE. INSPECTED SUMP. NO ODOR NO SHEEN REMAINS, NOTHING ON PADS IN SUMP. NO FURTHER ACTION REQUIRED, ADVISED CLOVER CONSTRUCTION THAT THEY CAN PROCEED WITH DEMOLITION AS PLANNED. CLOSE OUT. "
Remarks: "CALLER CALLED TO THE SITE TO TAKE CARE OF SHEEN IN THE BASEMENT. FOUND PRODUCT IN CELLAR FROM BROKEN FUEL OIL LINE. REMOVED 1300 GALLONS. POWER IS OFF TO THE HOUSE SO SUMP WAS NOT PUMPING OUT. TANK IS IN THE CELLAR AND EMPTY."

All Materials:
Site ID: 348203
Operable Unit ID: 1105861
Operable Unit: 01
Material ID: 1968356
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: G
Recovered: Not reported
Oxygenate: False

BH300 **BLUE STAR DRY CLEANER** **EDR Hist Cleaner** **1019940944**
NNW **1436 NIAGARA FALLS BLVD** **N/A**
1/8-1/4 **TONAWANDA, NY 14150**
0.196 mi.
1037 ft. **Site 1 of 2 in cluster BH**

Actual: EDR Hist Cleaner
581 ft.

Focus Map: Year: Name: Type:
3 1971 BLUE STAR DRY CLEANER Drycleaning Plants, Except Rugs
1972 BLUE STAR DRY CLEANER Drycleaning Plants, Except Rugs
1973 BLUE STAR DRY CLEANER Drycleaning Plants, Except Rugs
1974 BLUE STAR DRY CLEANER Drycleaning Plants, Except Rugs
1975 BLUE STAR DRY CLEANER Drycleaning Plants, Except Rugs

BH301 **COLD PARTS CLEANER** **NY Spills** **S102174767**
NNW **1435 NIAGARA FALLS BLVD** **N/A**
1/8-1/4 **TONAWANDA, NY**
0.196 mi.
1037 ft. **Site 2 of 2 in cluster BH**

Actual:
581 ft.

Focus Map:
3

SPILLS:

Spill Number/Closed Date:	9205916 / 1992-08-24
Facility ID:	9205916
Facility Type:	ER
DER Facility ID:	279858
Site ID:	123586
DEC Region:	9
Spill Cause:	Human Error
Spill Class:	C3
SWIS:	1564
Spill Date:	1992-08-21
Investigator:	SACALAND
Referred To:	Not reported
Reported to Dept:	1992-08-21
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	1992-08-24
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1992-09-02
Spill Record Last Update:	2013-09-23
Spiller Name:	Not reported
Spiller Company:	SAFETY KLEEN
Spiller Address:	41 NORTH GATES AVENUE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SAC 09/02/92: SAC - 8/22/92 TELCON W/ RAYMOND DOE OF S T S. SPILL WAS CLEANED UP.SAFETY KLEEN TO PICK UP BUCKET. NO FURTHER ACTION REQUIRED AT THIS TIME. "
Remarks:	"EMPLOYEE KNOCKED OVER PAIL OF CLEANER ON FLOOR OF GARAGE. CONTAINED AND DRUMMED; WILL PICK UP 8/24/92 A.M."

All Materials:

Site ID:	123586
Operable Unit ID:	973200
Operable Unit:	01
Material ID:	410109
Material Code:	0809A
Material Name:	cold parts cleaner
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

Site ID:	123586
Operable Unit ID:	973200

COLD PARTS CLEANER (Continued) **S102174767**

Operable Unit:	01
Material ID:	410108
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BG302 **NORTHTOWN INC** **RCRA NonGen / NLR** **1001029105**
East **3097 SHERIDAN DR** **FINDS** **NYR000013375**
1/8-1/4 **AMHERST, NY 14226** **ECHO**
0.197 mi. **NY MANIFEST**
1042 ft. **Site 6 of 9 in cluster BG**

Actual:
598 ft.

Focus Map:
6

RCRA NonGen / NLR:

Date form received by agency:	04/18/2017
Facility name:	NORTHTOWN INC
Facility address:	3097 SHERIDAN DR AMHERST, NY 14226
EPA ID:	NYR000013375
Mailing address:	BOYLSTON ST CHESTNUT HILL, MA 02467
Contact:	DAVE YORK
Contact address:	BOYLSTON ST CHESTNUT HILL, MA 02467
Contact country:	US
Contact telephone:	617-232-8900
Contact email:	DAVE.YORK@WSDEVELOPMENT.COM
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	NORTHTOWN PROPERTY OWNER LLC
Owner/operator address:	BOYLSTON ST CHESTNUT HILL, MA 02467
Owner/operator country:	US
Owner/operator telephone:	617-232-8900
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	05/15/2015
Owner/Op end date:	Not reported

Owner/operator name:	NORTHTOWN PROPERTY OWNER LLC
Owner/operator address:	Not reported Not reported
Owner/operator country:	Not reported
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported

NORTHTOWN INC (Continued) **1001029105**

Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 05/15/2015
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Historical Generators:
Date form received by agency: 06/17/2016
Site name: NORTHTOWN INC
Classification: Large Quantity Generator

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Date form received by agency: 01/01/2007
Site name: NORTHTOWN INC
Classification: Not a generator, verified

Date form received by agency: 01/01/2006
Site name: NORTHTOWN INC

NORTHTOWN INC (Continued) **1001029105**

Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: NORTHTOWN INC
Classification: Not a generator, verified

Date form received by agency: 05/23/1996
Site name: NORTHTOWN, INC.
Classification: Large Quantity Generator

Date form received by agency: 09/18/1995
Site name: NORTHTOWN INC
Classification: Small Quantity Generator

. Waste code: B004
. Waste name: B004

Violation Status: No violations found

FINDS:

Registry ID: 110000882386

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1001029105
Registry ID: 110000882386
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110000882386

NY MANIFEST:
Country: USA
EPA ID: NYR000013375
Facility Status: Not reported
Location Address 1: 3097 SHERIDAN DRIVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: AMHERST
Location State: NY
Location Zip: 14226
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000013375
Mailing Name: NORTHTOWN PROPERTY OWNER LLC
Mailing Contact: ANDREW MANNING

NORTHTOWN INC (Continued) **1001029105**

Mailing Address 1:	33 BOYLSTON ST
Mailing Address 2:	Not reported
Mailing City:	CHESTNUT HILL
Mailing State:	MA
Mailing Zip:	02467
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	6172328900

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2016
Trans1 State ID:	NYD986903904
Trans2 State ID:	Not reported
Generator Ship Date:	08/17/2016
Trans1 Recv Date:	08/17/2016
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/18/2016
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000013375
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	MID000724831
TSDF ID 2:	Not reported
Manifest Tracking Number:	008906527FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1890
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	F002
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

NORTHTOWN INC (Continued) **1001029105**

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

BG303 **NORTHTOWN INC.** **NY ENG CONTROLS** **S116555295**
East **3097 SHERIDAN DRIVE** **NY INST CONTROL** **N/A**
1/8-1/4 **AMHERST, NY 14226** **NY BROWNFIELDS**
0.197 mi. **NY Spills**
1042 ft. **Site 7 of 9 in cluster BG**

Actual: **598 ft.**

Focus Map: **6**

ENG CONTROLS:

Site Code:	502175
HW Code:	C915292
Control Code:	13
Control Type:	ENG
Date Record Added:	09/09/2016
Date Rec Updated:	01/09/2017
Updated By:	TLRIDNER
Site Description:	Location: The site is located in the Northtown Plaza in a suburban area in the Town of Amherst. Sheridan Avenue borders the site to the north, other Northtown Plaza buildings then Bailey Avenue to the east, Niagara Falls Boulevard to the west and Eggert Road to the south. Site Features: The site consists of three Areas of Interest (AOIs) comprising 1.424 acres of an approximately 14.022 acre parcel of land on which the Northtown Plaza is located. Currently the Northtown Plaza is occupied by six commercial buildings, most containing multiple tenant spaces. Current Zoning and Land Use: The site is zoned for commercial use and is currently used as a commercial-retail plaza. The area is primarily used as a shopping district, with major retailers located within 1/2 mile. Residential properties are located on the side streets surrounding the site. Past Use of the Site: The plaza was developed between the mid-1950s and mid-1980s, when it reached a configuration similar to what exists today. The current parcel was originally 23 separate parcels. Prior to development of the shopping center, the 23 parcels were agricultural land with no physical improvements. Construction of the first buildings commenced in 1952. Site Geology and Hydrogeology: The topography in the vicinity of the site is generally flat. The site is located between the Niagara and Onondaga Escarpments which act as major surface and groundwater divides. Site soils generally consist of a thin layer of fill material, sand, gravel, silt and clay mixed with some anthropogenic material. This overlays native soils comprised of fine grained silts and clays with varying amounts of sand and gravel. Bedrock, located more than 58 feet below ground surface (bgs), is of upper Silurian age and composed of sequences of shale, dolostone, salt and gypsum. Groundwater is first encountered at depths of 53 to 57 feet bgs. However, once the water bearing zone is encountered, water levels rise to 6 to 8 feet bgs, indicating the overlying silts and clays have formed a confined aquifer. Water level measurements collected from three monitoring wells depict a slight southern groundwater flow direction. This site has an Site Management Plan (SMP) dated November 28, 2016. All post remedial activity is directed by the SMP.
Env Problem:	AOI 1 is 0.152 acres and includes portions of tenant spaces 21 and 22 and formerly included an abandoned fuel oil underground storage tank (UST). Tenant spaces 21 and 22 are currently vacant and will remain so until the building in which they are housed is demolished. AOI 2 is 0.048 acres and formerly included an abandoned fuel oil UST. AOI 3 is 1.272 acres and includes AOI 2 and tenant spaces 7 through 14.

NORTHTOWN INC. (Continued) **S116555295**

Tenant spaces 10 through 14 are currently vacant and will remain so until the building in which they are housed is demolished pending the expiration of the remaining tenant space lease agreements. Tenant space 14 was the location of a former dry cleaner facility which used tetrachloroethene (PCE) and is believed to have been the source of the PCE contamination found in AOI 3. The subsequent dry cleaner facility, which occupied the now vacant space, was used as a pick-up/drop off location for clothes that were dry cleaned at another facility which used PCE. Prior to IRMs: Soil was analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs) and pesticides. Groundwater was analyzed for VOCs, metals and pesticides. Based upon the investigations conducted to date, the primary contaminants of concern include tetrachloroethene (PCE), trichloroethene (TCE), cis-1, 2- dichloroethene (DCE) and petroleum products. SOIL The detected concentrations of VOCs in soil were below their commercial soil cleanup objectives (CSCO) with the exception of tetrachloroethene (PCE) which was found as high as 1,100 parts per million (ppm). The PCE was detected in and around the dry cleaner unit. The detected concentrations of PCE exceeded its unrestricted soil cleanup objective (USCO) in 19 samples, all within the area of AOI 3. CSCOs were exceeded in four of the sample locations. Two of the four locations that exceeded CSOCs (SP-47 and SP-56) also exceeded the industrial SCO. No other VOCs were detected exceeding their respective CSCOs in the other 79 soil samples collected. No soil contamination is known or suspected to be present off-site with the exception of one sample location which exceeded USCOs but was below Residential SCOs for benzene and xylene. A total of 28 soil samples were selected for analysis of semi-volatile organic compounds (SVOCs). SVOCs were detected in 3 of the samples however all concentrations were below the unrestricted SCOs. A total of 4 samples were selected for analysis of Target Analyte List (TAL) metals and pesticides. The concentration of metals were below CSCOs and pesticides were not detected. A total of 12 samples were selected for analysis of polychlorinated biphenyls (PCBs). PCBs were not detected. Visual/olfactory evidence of petroleum contamination was encountered in the vicinity of both the southern heating oil UST (AOI 1) and western heating oil UST (AOI 2) however the laboratory results did not exceed USCOs. One off-site sample location exceeded USCOs but was below Residential SCOs for benzene and xylene. GROUNDWATER Three deep groundwater monitoring wells, screened from 45 to 58 feet bgs, were sampled for VOCs, TAL metals and pesticides. A total of six VOCs were detected at concentrations ranging from 0.46 to 8.5 parts per billion (ppb) however all were below their applicable groundwater standards. The concentration of metals were below groundwater standards with the exception of magnesium and sodium, both naturally occurring minerals. Pesticides were not detected. Five of six shallow monitoring wells, screened from 5 to 20 feet below ground surface (bgs), were sampled for chlorinated volatile organic compounds (CVOCs). These wells were screened in a low permeability silty clay till. Saturated soils indicating shallow perched groundwater were not encountered and only five of the six wells produced sufficient pore water to sample. CVOCs were detected above the Department s Class GA criteria in only two of the wells and was limited to the immediate vicinity of the most highly impacted soils within AOI 3. PCE concentrations in the two wells ranged from 21,700 to 31,900 ppb. The contaminated pore water was removed during the PCE hot spot soil excavation. SOIL VAPOR,

NORTHTOWN INC. (Continued) **S116555295**

SUB-SLAB VAPOR, and INDOOR AIR A total of 29 air, sub-slab and soil vapor samples were collected and sent for VOC laboratory analysis. PCE, trichloroethene (TCE) and cis-1, 2-dichloroethene were detected in both sub-slab soil vapor and indoor air samples. PCE was the only compound to exceed DOH air guidelines and ranged from 60 to 70 ug/m3 in two indoor air samples inside AOI 3 tenant spaces 13 and 14. PCE concentrations ranged from 230 to 6,400 ug/m3 in three sub-slab vapor samples from beneath AOI 3 tenant spaces 13 and 14 and beneath the building located off-site directly west of AOI 3 (tenant space 1).
The sub-slab vapor and indoor air sample results from the remaining AOI 3 tenant spaces 7 through 12 were within DOH air guidelines. PCE was the only compound detected in the 2 soil vapor samples collected and ranged from 5.4 to 8.5 ug/m3. Post IRMs: At the completion of the UST and PCE hot spot excavations, 29 post excavation soil samples were collected to confirm that the remedial actions successfully achieved soil cleanup objectives for commercial use. All post excavation soil sample results met commercial SCOs. No contamination exceeding CSCOs is known or suspected to be present beneath the on-site buildings. Based on visual and olfactory observations as well as organic vapor meter readings, all soils exhibiting nuisance characteristics were removed. In December 2015, at the completion of the SSDS installations, post-installation vacuum monitoring of the sub-slab soil vapor was completed and confirmed that the SSDSs were operating as intended. In February 2016 post-installation indoor air sampling was performed for analysis of CVOCs at the now vacant tenant space 14 within AOI 3 and at tenant space 1, the now vacant building located off-site directly west of AOI 3. Post-installation indoor air sample results for PCE at tenant space 14 increased from 60 to 150 ug/m3 however, because the SSDS was operational with confirmed adequate depressurization of the sub-slab, the result was attributed to off-gassing from clothes dry-cleaned at another facility and routinely brought to the tenant space for pickup by customers at the time of the sampling. Post-installation indoor air sample results for PCE at tenant space 1 increased from less than 1.0 to 2.7 ug/m3 but remained below DOH air guidelines. The building which comprises tenant space 1 is currently vacant and slated for demolition.

Health Problem: Direct contact with contaminants in the soil is unlikely because the majority of the site is covered with buildings and pavement. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Sub-slab depressurization systems (systems that ventilate/remove the air beneath the building) have been installed in one on-site tenant space and one off-site building to prevent the indoor air quality from being affected by the contamination in soil vapor beneath the buildings. Other tenant spaces in the on-site building have the potential for soil vapor intrusion to affect indoor air quality, however the tenant spaces are currently unoccupied. Therefore, inhalation of site-contaminants in indoor air of these vacant tenant spaces does not represent a current concern. Soil vapor intrusion concerns are limited to the on-site building and one off-site structure as indicated above.

NORTHTOWN INC. (Continued) **S116555295**

Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2014-11-21 11:20:00
Record Upd:	2016-12-02 11:02:00
Updated By:	TEDIEFFE
Own Op:	Applicant/Requestor
Sub Type:	P03
Owner Name:	Jeffrey C. Curely
Owner Company:	Northtown Property Owner LLC
Owner Address:	33 Boylston Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Chestnut Hill, MA 02467
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Roseanne Butler-Smith
Owner Company:	Audubon Branch Library
Owner Address:	350 John J. Audubon Parkway
Owner Addr2:	Not reported
Owner City,St,Zip:	Amherst, NY 14228
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	E
Owner Name:	Jeffrey C. Curley
Owner Company:	Northtown Property Owner LLC
Owner Address:	33 Boylston Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Chestnut Hill, MA 02467
Owner Country:	United States of America
HW Code:	C915292
Waste Type:	cis-1,2-Dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C915292
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C915292
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C915292
Waste Type:	petroleum products
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C915292
Waste Type:	TRICHLOROETHENE (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	C915292-03-15

NORTHTOWN INC. (Continued) **S116555295**

Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2016-11-28 15:13:00
Record Updated: 2016-11-28 15:13:00
Updated By: TEDIEFFE
Crossref ID: 107/3178
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2016-11-29 09:42:00
Record Updated: 2016-11-29 09:42:00
Updated By: TEDIEFFE
Crossref ID: May 15, 2015
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2016-11-29 10:17:00
Record Updated: 2016-11-29 10:17:00
Updated By: TEDIEFFE
Crossref ID: Book 11305 Page 7751
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2016-11-29 09:42:00
Record Updated: 2016-12-08 09:59:00
Updated By: TEDIEFFE
Crossref ID: C915292
Cross Ref Type Code: 22
Cross Ref Type: BCP Site ID
Record Added Date: 2016-11-29 09:18:00
Record Updated: 2016-11-29 09:18:00
Updated By: TEDIEFFE

INST CONTROL:
Site Code: 502175
Control Name: Monitoring Plan
HW Code: C915292
Control Code: 31
Control Type: INST
Dt record added: 09/09/2016
Dt rec updated: 01/09/2017
Updated By: TLRIDNER
Site Code: 502175
Site Description: Location: The site is located in the Northtown Plaza in a suburban area in the Town of Amherst. Sheridan Avenue borders the site to the north, other Northtown Plaza buildings then Bailey Avenue to the east, Niagara Falls Boulevard to the west and Eggert Road to the south. Site Features: The site consists of three Areas of Interest (AOIs) comprising 1.424 acres of an approximately 14.022 acre parcel of land on which the Northtown Plaza is located. Currently the Northtown Plaza is occupied by six commercial buildings, most containing multiple tenant spaces. Current Zoning and Land Use: The site is zoned for commercial use and is currently used as a commercial-retail plaza. The area is primarily used as a shopping district, with major retailers located within 1/2 mile. Residential properties are located on the side streets surrounding the site. Past Use of the Site: The plaza was developed between the mid-1950s and mid-1980s, when it reached a configuration similar to what exists today. The current parcel was originally 23 separate parcels. Prior to development of the shopping center, the 23 parcels were

NORTHTOWN INC. (Continued) **S116555295**

agricultural land with no physical improvements. Construction of the first buildings commenced in 1952. Site Geology and Hydrogeology: The topography in the vicinity of the site is generally flat. The site is located between the Niagara and Onondaga Escarpments which act as major surface and groundwater divides. Site soils generally consist of a thin layer of fill material, sand, gravel, silt and clay mixed with some anthropogenic material. This overlays native soils comprised of fine grained silts and clays with varying amounts of sand and gravel. Bedrock, located more than 58 feet below ground surface (bgs), is of upper Silurian age and composed of sequences of shale, dolostone, salt and gypsum. Groundwater is first encountered at depths of 53 to 57 feet bgs. However, once the water bearing zone is encountered, water levels rise to 6 to 8 feet bgs, indicating the overlying silts and clays have formed a confined aquifer. Water level measurements collected from three monitoring wells depict a slight southern groundwater flow direction. This site has an Site Management Plan (SMP) dated November 28, 2016. All post remedial activity is directed by the SMP.

Env Problem: AOI 1 is 0.152 acres and includes portions of tenant spaces 21 and 22 and formerly included an abandoned fuel oil underground storage tank (UST). Tenant spaces 21 and 22 are currently vacant and will remain so until the building in which they are housed is demolished. AOI 2 is 0.048 acres and formerly included an abandoned fuel oil UST. AOI 3 is 1.272 acres and includes AOI 2 and tenant spaces 7 through 14. Tenant spaces 10 through 14 are currently vacant and will remain so until the building in which they are housed is demolished pending the expiration of the remaining tenant space lease agreements. Tenant space 14 was the location of a former dry cleaner facility which used tetrachloroethene (PCE) and is believed to have been the source of the PCE contamination found in AOI 3. The subsequent dry cleaner facility, which occupied the now vacant space, was used as a pick-up/drop off location for clothes that were dry cleaned at another facility which used PCE. Prior to IRMs: Soil was analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs) and pesticides. Groundwater was analyzed for VOCs, metals and pesticides. Based upon the investigations conducted to date, the primary contaminants of concern include tetrachloroethene (PCE), trichloroethene (TCE), cis-1, 2- dichloroethene (DCE) and petroleum products. SOIL The detected concentrations of VOCs in soil were below their commercial soil cleanup objectives (CSCO) with the exception of tetrachloroethene (PCE) which was found as high as 1,100 parts per million (ppm). The PCE was detected in and around the dry cleaner unit. The detected concentrations of PCE exceeded its unrestricted soil cleanup objective (USCO) in 19 samples, all within the area of AOI 3. CSCOs were exceeded in four of the sample locations. Two of the four locations that exceeded CSOCs (SP-47 and SP-56) also exceeded the industrial SCO. No other VOCs were detected exceeding their respective CSCOs in the other 79 soil samples collected. No soil contamination is known or suspected to be present off-site with the exception of one sample location which exceeded USCOs but was below Residential SCOs for benzene and xylene. A total of 28 soil samples were selected for analysis of semi-volatile organic compounds (SVOCs). SVOCs were detected in 3 of the samples however all concentrations were below the unrestricted SCOs. A total of 4 samples were selected for analysis of Target Analyte List (TAL) metals and pesticides. The concentration of metals were below CSCOs and

NORTHTOWN INC. (Continued) **S116555295**

pesticides were not detected. A total of 12 samples were selected for analysis of polychlorinated biphenyls (PCBs). PCBs were not detected. Visual/olfactory evidence of petroleum contamination was encountered in the vicinity of both the southern heating oil UST (AOI 1) and western heating oil UST (AOI 2) however the laboratory results did not exceed USCOs. One off-site sample location exceeded USCOs but was below Residential SCOs for benzene and xylene. GROUNDWATER Three deep groundwater monitoring wells, screened from 45 to 58 feet bgs, were sampled for VOCs, TAL metals and pesticides. A total of six VOCs were detected at concentrations ranging from 0.46 to 8.5 parts per billion (ppb) however all were below their applicable groundwater standards. The concentration of metals were below groundwater standards with the exception of magnesium and sodium, both naturally occurring minerals. Pesticides were not detected. Five of six shallow monitoring wells, screened from 5 to 20 feet below ground surface (bgs), were sampled for chlorinated volatile organic compounds (CVOCs). These wells were screened in a low permeability silty clay till. Saturated soils indicating shallow perched groundwater were not encountered and only five of the six wells produced sufficient pore water to sample. CVOCs were detected above the Department s Class GA criteria in only two of the wells and was limited to the immediate vicinity of the most highly impacted soils within AOI 3. PCE concentrations in the two wells ranged from 21,700 to 31,900 ppb. The contaminated pore water was removed during the PCE hot spot soil excavation. SOIL VAPOR, SUB-SLAB VAPOR, and INDOOR AIR A total of 29 air, sub-slab and soil vapor samples were collected and sent for VOC laboratory analysis. PCE, trichloroethene (TCE) and cis-1, 2-dichloroethene were detected in both sub-slab soil vapor and indoor air samples. PCE was the only compound to exceed DOH air guidelines and ranged from 60 to 70 ug/m3 in two indoor air samples inside AOI 3 tenant spaces 13 and 14. PCE concentrations ranged from 230 to 6,400 ug/m3 in three sub-slab vapor samples from beneath AOI 3 tenant spaces 13 and 14 and beneath the building located off-site directly west of AOI 3 (tenant space 1). The sub-slab vapor and indoor air sample results from the remaining AOI 3 tenant spaces 7 through 12 were within DOH air guidelines. PCE was the only compound detected in the 2 soil vapor samples collected and ranged from 5.4 to 8.5 ug/m3. Post IRMs: At the completion of the UST and PCE hot spot excavations, 29 post excavation soil samples were collected to confirm that the remedial actions successfully achieved soil cleanup objectives for commercial use. All post excavation soil sample results met commercial SCOs. No contamination exceeding CSCOs is known or suspected to be present beneath the on-site buildings. Based on visual and olfactory observations as well as organic vapor meter readings, all soils exhibiting nuisance characteristics were removed. In December 2015, at the completion of the SSDS installations, post-installation vacuum monitoring of the sub-slab soil vapor was completed and confirmed that the SSDSs were operating as intended. In February 2016 post-installation indoor air sampling was performed for analysis of CVOCs at the now vacant tenant space 14 within AOI 3 and at tenant space 1, the now vacant building located off-site directly west of AOI 3. Post-installation indoor air sample results for PCE at tenant space 14 increased from 60 to 150 ug/m3 however, because the SSDS was operational with confirmed adequate depressurization of the sub-slab, the result was attributed to off-gassing from clothes dry-cleaned at another facility and routinely brought to the tenant space for pickup by customers at the time of the sampling. Post-installation indoor air sample results for

NORTHTOWN INC. (Continued) **S116555295**

PCE at tenant space 1 increased from less than 1.0 to 2.7 ug/m3 but remained below DOH air guidelines. The building which comprises tenant space 1 is currently vacant and slated for demolition.

Health Problem: Direct contact with contaminants in the soil is unlikely because the majority of the site is covered with buildings and pavement. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Sub-slab depressurization systems (systems that ventilate/remove the air beneath the building) have been installed in one on-site tenant space and one off-site building to prevent the indoor air quality from being affected by the contamination in soil vapor beneath the buildings. Other tenant spaces in the on-site building have the potential for soil vapor intrusion to affect indoor air quality, however the tenant spaces are currently unoccupied. Therefore, inhalation of site-contaminants in indoor air of these vacant tenant spaces does not represent a current concern. Soil vapor intrusion concerns are limited to the on-site building and one off-site structure as indicated above.

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2014-11-21 11:20:00
Record Upd: 2016-12-02 11:02:00
Updated By: TEDIEFFE
Own Op: Applicant/Requestor
Sub Type: P03
Owner Name: Jeffrey C. Curely
Owner Company: Northtown Property Owner LLC
Owner Address: 33 Boylston Street
Owner Addr2: Not reported
Owner City,St,Zip: Chestnut Hill, MA 02467
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Roseanne Butler-Smith
Owner Company: Audubon Branch Library
Owner Address: 350 John J. Audubon Parkway
Owner Addr2: Not reported
Owner City,St,Zip: Amherst, NY 14228
Owner Country: United States of America
Own Op: Owner
Sub Type: E
Owner Name: Jeffrey C. Curley
Owner Company: Northtown Property Owner LLC
Owner Address: 33 Boylston Street

NORTHTOWN INC. (Continued) **S116555295**

Owner Addr2: Not reported
Owner City,St,Zip: Chestnut Hill, MA 02467
Owner Country: United States of America
HW Code: C915292
Waste Type: cis-1,2-Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C915292
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C915292
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C915292
Waste Type: petroleum products
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C915292
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C915292-03-15
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2016-11-28 15:13:00
Record Updated: 2016-11-28 15:13:00
Updated By: TEDIEFFE
Crossref ID: 107/3178
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2016-11-29 09:42:00
Record Updated: 2016-11-29 09:42:00
Updated By: TEDIEFFE
Crossref ID: May 15, 2015
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2016-11-29 10:17:00
Record Updated: 2016-11-29 10:17:00
Updated By: TEDIEFFE
Crossref ID: Book 11305 Page 7751
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2016-11-29 09:42:00
Record Updated: 2016-12-08 09:59:00
Updated By: TEDIEFFE
Crossref ID: C915292
Cross Ref Type Code: 22
Cross Ref Type: BCP Site ID
Record Added Date: 2016-11-29 09:18:00
Record Updated: 2016-11-29 09:18:00
Updated By: TEDIEFFE

Site Code: 502175
Control Name: Landuse Restriction
HW Code: C915292

NORTHTOWN INC. (Continued) **S116555295**

Control Code: 25
Control Type: INST
Dt record added: 09/09/2016
Dt rec updated: 01/09/2017
Updated By: TLRIDNER
Site Code: 502175
Site Description: Location: The site is located in the Northtown Plaza in a suburban area in the Town of Amherst. Sheridan Avenue borders the site to the north, other Northtown Plaza buildings then Bailey Avenue to the east, Niagara Falls Boulevard to the west and Eggert Road to the south. Site Features: The site consists of three Areas of Interest (AOIs) comprising 1.424 acres of an approximately 14.022 acre parcel of land on which the Northtown Plaza is located. Currently the Northtown Plaza is occupied by six commercial buildings, most containing multiple tenant spaces. Current Zoning and Land Use: The site is zoned for commercial use and is currently used as a commercial-retail plaza. The area is primarily used as a shopping district, with major retailers located within 1/2 mile. Residential properties are located on the side streets surrounding the site. Past Use of the Site: The plaza was developed between the mid-1950s and mid-1980s, when it reached a configuration similar to what exists today. The current parcel was originally 23 separate parcels. Prior to development of the shopping center, the 23 parcels were agricultural land with no physical improvements. Construction of the first buildings commenced in 1952. Site Geology and Hydrogeology: The topography in the vicinity of the site is generally flat. The site is located between the Niagara and Onondaga Escarpments which act as major surface and groundwater divides. Site soils generally consist of a thin layer of fill material, sand, gravel, silt and clay mixed with some anthropogenic material. This overlays native soils comprised of fine grained silts and clays with varying amounts of sand and gravel. Bedrock, located more than 58 feet below ground surface (bgs), is of upper Silurian age and composed of sequences of shale, dolostone, salt and gypsum. Groundwater is first encountered at depths of 53 to 57 feet bgs. However, once the water bearing zone is encountered, water levels rise to 6 to 8 feet bgs, indicating the overlying silts and clays have formed a confined aquifer. Water level measurements collected from three monitoring wells depict a slight southern groundwater flow direction. This site has an Site Management Plan (SMP) dated November 28, 2016. All post remedial activity is directed by the SMP.
Env Problem: AOI 1 is 0.152 acres and includes portions of tenant spaces 21 and 22 and formerly included an abandoned fuel oil underground storage tank (UST). Tenant spaces 21 and 22 are currently vacant and will remain so until the building in which they are housed is demolished. AOI 2 is 0.048 acres and formerly included an abandoned fuel oil UST. AOI 3 is 1.272 acres and includes AOI 2 and tenant spaces 7 through 14. Tenant spaces 10 through 14 are currently vacant and will remain so until the building in which they are housed is demolished pending the expiration of the remaining tenant space lease agreements. Tenant space 14 was the location of a former dry cleaner facility which used tetrachloroethene (PCE) and is believed to have been the source of the PCE contamination found in AOI 3. The subsequent dry cleaner facility, which occupied the now vacant space, was used as a pick-up/drop off location for clothes that were dry cleaned at another facility which used PCE. Prior to IRMs: Soil was analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds

NORTHTOWN INC. (Continued) **S116555295**

(SVOCs), metals, polychlorinated biphenyls (PCBs) and pesticides. Groundwater was analyzed for VOCs, metals and pesticides. Based upon the investigations conducted to date, the primary contaminants of concern include tetrachloroethene (PCE), trichloroethene (TCE), cis-1, 2- dichloroethene (DCE) and petroleum products. SOIL The detected concentrations of VOCs in soil were below their commercial soil cleanup objectives (CSCO) with the exception of tetrachloroethene (PCE) which was found as high as 1,100 parts per million (ppm). The PCE was detected in and around the dry cleaner unit. The detected concentrations of PCE exceeded its unrestricted soil cleanup objective (USCO) in 19 samples, all within the area of AOI 3. CSCOs were exceeded in four of the sample locations. Two of the four locations that exceeded CSOCs (SP-47 and SP-56) also exceeded the industrial SCO. No other VOCs were detected exceeding their respective CSCOs in the other 79 soil samples collected. No soil contamination is known or suspected to be present off-site with the exception of one sample location which exceeded USCOs but was below Residential SCOs for benzene and xylene. A total of 28 soil samples were selected for analysis of semi-volatile organic compounds (SVOCs). SVOCs were detected in 3 of the samples however all concentrations were below the unrestricted SCOs. A total of 4 samples were selected for analysis of Target Analyte List (TAL) metals and pesticides. The concentration of metals were below CSCOs and pesticides were not detected. A total of 12 samples were selected for analysis of polychlorinated biphenyls (PCBs). PCBs were not detected. Visual/olfactory evidence of petroleum contamination was encountered in the vicinity of both the southern heating oil UST (AOI 1) and western heating oil UST (AOI 2) however the laboratory results did not exceed USCOs. One off-site sample location exceeded USCOs but was below Residential SCOs for benzene and xylene. GROUNDWATER Three deep groundwater monitoring wells, screened from 45 to 58 feet bgs, were sampled for VOCs, TAL metals and pesticides. A total of six VOCs were detected at concentrations ranging from 0.46 to 8.5 parts per billion (ppb) however all were below their applicable groundwater standards. The concentration of metals were below groundwater standards with the exception of magnesium and sodium, both naturally occurring minerals. Pesticides were not detected. Five of six shallow monitoring wells, screened from 5 to 20 feet below ground surface (bgs), were sampled for chlorinated volatile organic compounds (CVOCs). These wells were screened in a low permeability silty clay till. Saturated soils indicating shallow perched groundwater were not encountered and only five of the six wells produced sufficient pore water to sample. CVOCs were detected above the Department s Class GA criteria in only two of the wells and was limited to the immediate vicinity of the most highly impacted soils within AOI 3. PCE concentrations in the two wells ranged from 21,700 to 31,900 ppb. The contaminated pore water was removed during the PCE hot spot soil excavation. SOIL VAPOR, SUB-SLAB VAPOR, and INDOOR AIR A total of 29 air, sub-slab and soil vapor samples were collected and sent for VOC laboratory analysis. PCE, trichloroethene (TCE) and cis-1, 2-dichloroethene were detected in both sub-slab soil vapor and indoor air samples. PCE was the only compound to exceed DOH air guidelines and ranged from 60 to 70 ug/m3 in two indoor air samples inside AOI 3 tenant spaces 13 and 14. PCE concentrations ranged from 230 to 6,400 ug/m3 in three sub-slab vapor samples from beneath AOI 3 tenant spaces 13 and 14 and beneath the building located off-site directly west of AOI 3 (tenant space 1). The sub-slab vapor and indoor air sample results from the remaining

NORTHTOWN INC. (Continued) **S116555295**

AOI 3 tenant spaces 7 through 12 were within DOH air guidelines. PCE was the only compound detected in the 2 soil vapor samples collected and ranged from 5.4 to 8.5 ug/m3. Post IRMs: At the completion of the UST and PCE hot spot excavations, 29 post excavation soil samples were collected to confirm that the remedial actions successfully achieved soil cleanup objectives for commercial use. All post excavation soil sample results met commercial SCOs. No contamination exceeding CSCOs is known or suspected to be present beneath the on-site buildings. Based on visual and olfactory observations as well as organic vapor meter readings, all soils exhibiting nuisance characteristics were removed. In December 2015, at the completion of the SSDS installations, post-installation vacuum monitoring of the sub-slab soil vapor was completed and confirmed that the SSDSs were operating as intended. In February 2016 post-installation indoor air sampling was performed for analysis of CVOCs at the now vacant tenant space 14 within AOI 3 and at tenant space 1, the now vacant building located off-site directly west of AOI 3. Post-installation indoor air sample results for PCE at tenant space 14 increased from 60 to 150 ug/m3 however, because the SSDS was operational with confirmed adequate depressurization of the sub-slab, the result was attributed to off-gassing from clothes dry-cleaned at another facility and routinely brought to the tenant space for pickup by customers at the time of the sampling. Post-installation indoor air sample results for PCE at tenant space 1 increased from less than 1.0 to 2.7 ug/m3 but remained below DOH air guidelines. The building which comprises tenant space 1 is currently vacant and slated for demolition.

Health Problem: Direct contact with contaminants in the soil is unlikely because the majority of the site is covered with buildings and pavement. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Sub-slab depressurization systems (systems that ventilate/remove the air beneath the building) have been installed in one on-site tenant space and one off-site building to prevent the indoor air quality from being affected by the contamination in soil vapor beneath the buildings. Other tenant spaces in the on-site building have the potential for soil vapor intrusion to affect indoor air quality, however the tenant spaces are currently unoccupied. Therefore, inhalation of site-contaminants in indoor air of these vacant tenant spaces does not represent a current concern. Soil vapor intrusion concerns are limited to the on-site building and one off-site structure as indicated above.

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2014-11-21 11:20:00

NORTHTOWN INC. (Continued) **S116555295**

Record Upd: 2016-12-02 11:02:00
Updated By: TEDIEFFE
Own Op: Applicant/Requestor
Sub Type: P03
Owner Name: Jeffrey C. Curely
Owner Company: Northtown Property Owner LLC
Owner Address: 33 Boylston Street
Owner Addr2: Not reported
Owner City,St,Zip: Chestnut Hill, MA 02467
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Roseanne Butler-Smith
Owner Company: Audubon Branch Library
Owner Address: 350 John J. Audubon Parkway
Owner Addr2: Not reported
Owner City,St,Zip: Amherst, NY 14228
Owner Country: United States of America
Own Op: Owner
Sub Type: E
Owner Name: Jeffrey C. Curley
Owner Company: Northtown Property Owner LLC
Owner Address: 33 Boylston Street
Owner Addr2: Not reported
Owner City,St,Zip: Chestnut Hill, MA 02467
Owner Country: United States of America
HW Code: C915292
Waste Type: cis-1,2-Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C915292
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C915292
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C915292
Waste Type: petroleum products
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C915292
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C915292-03-15
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2016-11-28 15:13:00
Record Updated: 2016-11-28 15:13:00
Updated By: TEDIEFFE
Crossref ID: 107/3178
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2016-11-29 09:42:00
Record Updated: 2016-11-29 09:42:00

NORTHTOWN INC. (Continued) **S116555295**

Updated By: TEDIEFFE
Crossref ID: May 15, 2015
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2016-11-29 10:17:00
Record Updated: 2016-11-29 10:17:00
Updated By: TEDIEFFE
Crossref ID: Book 11305 Page 7751
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2016-11-29 09:42:00
Record Updated: 2016-12-08 09:59:00
Updated By: TEDIEFFE
Crossref ID: C915292
Cross Ref Type Code: 22
Cross Ref Type: BCP Site ID
Record Added Date: 2016-11-29 09:18:00
Record Updated: 2016-11-29 09:18:00
Updated By: TEDIEFFE

Site Code: 502175
Control Name: O&M Plan
HW Code: C915292
Control Code: 33
Control Type: INST
Dt record added: 09/09/2016
Dt rec updated: 01/09/2017
Updated By: TLRIDNER
Site Code: 502175
Site Description: Location: The site is located in the Northtown Plaza in a suburban area in the Town of Amherst. Sheridan Avenue borders the site to the north, other Northtown Plaza buildings then Bailey Avenue to the east, Niagara Falls Boulevard to the west and Eggert Road to the south. Site Features: The site consists of three Areas of Interest (AOIs) comprising 1.424 acres of an approximately 14.022 acre parcel of land on which the Northtown Plaza is located. Currently the Northtown Plaza is occupied by six commercial buildings, most containing multiple tenant spaces. Current Zoning and Land Use: The site is zoned for commercial use and is currently used as a commercial-retail plaza. The area is primarily used as a shopping district, with major retailers located within 1/2 mile. Residential properties are located on the side streets surrounding the site. Past Use of the Site: The plaza was developed between the mid-1950s and mid-1980s, when it reached a configuration similar to what exists today. The current parcel was originally 23 separate parcels. Prior to development of the shopping center, the 23 parcels were agricultural land with no physical improvements. Construction of the first buildings commenced in 1952. Site Geology and Hydrogeology: The topography in the vicinity of the site is generally flat. The site is located between the Niagara and Onondaga Escarpments which act as major surface and groundwater divides. Site soils generally consist of a thin layer of fill material, sand, gravel, silt and clay mixed with some anthropogenic material. This overlays native soils comprised of fine grained silts and clays with varying amounts of sand and gravel. Bedrock, located more than 58 feet below ground surface (bgs), is of upper Silurian age and composed of sequences of shale, dolostone, salt and gypsum. Groundwater is first encountered

NORTHTOWN INC. (Continued) **S116555295**

at depths of 53 to 57 feet bgs. However, once the water bearing zone is encountered, water levels rise to 6 to 8 feet bgs, indicating the overlying silts and clays have formed a confined aquifer. Water level measurements collected from three monitoring wells depict a slight southern groundwater flow direction. This site has an Site Management Plan (SMP) dated November 28, 2016. All post remedial activity is directed by the SMP.

Env Problem: AOI 1 is 0.152 acres and includes portions of tenant spaces 21 and 22 and formerly included an abandoned fuel oil underground storage tank (UST). Tenant spaces 21 and 22 are currently vacant and will remain so until the building in which they are housed is demolished. AOI 2 is 0.048 acres and formerly included an abandoned fuel oil UST. AOI 3 is 1.272 acres and includes AOI 2 and tenant spaces 7 through 14. Tenant spaces 10 through 14 are currently vacant and will remain so until the building in which they are housed is demolished pending the expiration of the remaining tenant space lease agreements. Tenant space 14 was the location of a former dry cleaner facility which used tetrachloroethene (PCE) and is believed to have been the source of the PCE contamination found in AOI 3. The subsequent dry cleaner facility, which occupied the now vacant space, was used as a pick-up/drop off location for clothes that were dry cleaned at another facility which used PCE. Prior to IRMs: Soil was analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs) and pesticides. Groundwater was analyzed for VOCs, metals and pesticides. Based upon the investigations conducted to date, the primary contaminants of concern include tetrachloroethene (PCE), trichloroethene (TCE), cis-1, 2- dichloroethene (DCE) and petroleum products. SOIL The detected concentrations of VOCs in soil were below their commercial soil cleanup objectives (CSCO) with the exception of tetrachloroethene (PCE) which was found as high as 1,100 parts per million (ppm). The PCE was detected in and around the dry cleaner unit. The detected concentrations of PCE exceeded its unrestricted soil cleanup objective (USCO) in 19 samples, all within the area of AOI 3. CSCOs were exceeded in four of the sample locations. Two of the four locations that exceeded CSOCs (SP-47 and SP-56) also exceeded the industrial SCO. No other VOCs were detected exceeding their respective CSCOs in the other 79 soil samples collected. No soil contamination is known or suspected to be present off-site with the exception of one sample location which exceeded USCOs but was below Residential SCOs for benzene and xylene. A total of 28 soil samples were selected for analysis of semi-volatile organic compounds (SVOCs). SVOCs were detected in 3 of the samples however all concentrations were below the unrestricted SCOs. A total of 4 samples were selected for analysis of Target Analyte List (TAL) metals and pesticides. The concentration of metals were below CSCOs and pesticides were not detected. A total of 12 samples were selected for analysis of polychlorinated biphenyls (PCBs). PCBs were not detected. Visual/olfactory evidence of petroleum contamination was encountered in the vicinity of both the southern heating oil UST (AOI 1) and western heating oil UST (AOI 2) however the laboratory results did not exceed USCOs. One off-site sample location exceeded USCOs but was below Residential SCOs for benzene and xylene. GROUNDWATER Three deep groundwater monitoring wells, screened from 45 to 58 feet bgs, were sampled for VOCs, TAL metals and pesticides. A total of six VOCs were detected at concentrations ranging from 0.46 to 8.5 parts per billion (ppb) however all were below their applicable groundwater standards.

NORTHTOWN INC. (Continued) **S116555295**

The concentration of metals were below groundwater standards with the exception of magnesium and sodium, both naturally occurring minerals. Pesticides were not detected. Five of six shallow monitoring wells, screened from 5 to 20 feet below ground surface (bgs), were sampled for chlorinated volatile organic compounds (CVOCs). These wells were screened in a low permeability silty clay till. Saturated soils indicating shallow perched groundwater were not encountered and only five of the six wells produced sufficient pore water to sample. CVOCs were detected above the Department s Class GA criteria in only two of the wells and was limited to the immediate vicinity of the most highly impacted soils within AOI 3. PCE concentrations in the two wells ranged from 21,700 to 31,900 ppb. The contaminated pore water was removed during the PCE hot spot soil excavation. SOIL VAPOR, SUB-SLAB VAPOR, and INDOOR AIR A total of 29 air, sub-slab and soil vapor samples were collected and sent for VOC laboratory analysis. PCE, trichloroethene (TCE) and cis-1, 2-dichloroethene were detected in both sub-slab soil vapor and indoor air samples. PCE was the only compound to exceed DOH air guidelines and ranged from 60 to 70 ug/m3 in two indoor air samples inside AOI 3 tenant spaces 13 and 14. PCE concentrations ranged from 230 to 6,400 ug/m3 in three sub-slab vapor samples from beneath AOI 3 tenant spaces 13 and 14 and beneath the building located off-site directly west of AOI 3 (tenant space 1). The sub-slab vapor and indoor air sample results from the remaining AOI 3 tenant spaces 7 through 12 were within DOH air guidelines. PCE was the only compound detected in the 2 soil vapor samples collected and ranged from 5.4 to 8.5 ug/m3. Post IRMs: At the completion of the UST and PCE hot spot excavations, 29 post excavation soil samples were collected to confirm that the remedial actions successfully achieved soil cleanup objectives for commercial use. All post excavation soil sample results met commercial SCOs. No contamination exceeding CSCOs is known or suspected to be present beneath the on-site buildings. Based on visual and olfactory observations as well as organic vapor meter readings, all soils exhibiting nuisance characteristics were removed. In December 2015, at the completion of the SSDS installations, post-installation vacuum monitoring of the sub-slab soil vapor was completed and confirmed that the SSDSs were operating as intended. In February 2016 post-installation indoor air sampling was performed for analysis of CVOCs at the now vacant tenant space 14 within AOI 3 and at tenant space 1, the now vacant building located off-site directly west of AOI 3. Post-installation indoor air sample results for PCE at tenant space 14 increased from 60 to 150 ug/m3 however, because the SSDS was operational with confirmed adequate depressurization of the sub-slab, the result was attributed to off-gassing from clothes dry-cleaned at another facility and routinely brought to the tenant space for pickup by customers at the time of the sampling. Post-installation indoor air sample results for PCE at tenant space 1 increased from less than 1.0 to 2.7 ug/m3 but remained below DOH air guidelines. The building which comprises tenant space 1 is currently vacant and slated for demolition.

Health Problem: Direct contact with contaminants in the soil is unlikely because the majority of the site is covered with buildings and pavement. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air

NORTHTOWN INC. (Continued) **S116555295**

quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Sub-slab depressurization systems (systems that ventilate/remove the air beneath the building) have been installed in one on-site tenant space and one off-site building to prevent the indoor air quality from being affected by the contamination in soil vapor beneath the buildings. Other tenant spaces in the on-site building have the potential for soil vapor intrusion to affect indoor air quality, however the tenant spaces are currently unoccupied. Therefore, inhalation of site-contaminants in indoor air of these vacant tenant spaces does not represent a current concern. Soil vapor intrusion concerns are limited to the on-site building and one off-site structure as indicated above.

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2014-11-21 11:20:00
Record Upd: 2016-12-02 11:02:00
Updated By: TEDIEFFE
Own Op: Applicant/Requestor
Sub Type: P03
Owner Name: Jeffrey C. Curely
Owner Company: Northtown Property Owner LLC
Owner Address: 33 Boylston Street
Owner Addr2: Not reported
Owner City,St,Zip: Chestnut Hill, MA 02467
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Roseanne Butler-Smith
Owner Company: Audubon Branch Library
Owner Address: 350 John J. Audubon Parkway
Owner Addr2: Not reported
Owner City,St,Zip: Amherst, NY 14228
Owner Country: United States of America
Own Op: Owner
Sub Type: E
Owner Name: Jeffrey C. Curley
Owner Company: Northtown Property Owner LLC
Owner Address: 33 Boylston Street
Owner Addr2: Not reported
Owner City,St,Zip: Chestnut Hill, MA 02467
Owner Country: United States of America
HW Code: C915292
Waste Type: cis-1,2-Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C915292
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported

NORTHTOWN INC. (Continued) **S116555295**

HW Code: C915292
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C915292
Waste Type: petroleum products
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C915292
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C915292-03-15
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2016-11-28 15:13:00
Record Updated: 2016-11-28 15:13:00
Updated By: TEDIEFFE
Crossref ID: 107/3178
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2016-11-29 09:42:00
Record Updated: 2016-11-29 09:42:00
Updated By: TEDIEFFE
Crossref ID: May 15, 2015
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2016-11-29 10:17:00
Record Updated: 2016-11-29 10:17:00
Updated By: TEDIEFFE
Crossref ID: Book 11305 Page 7751
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2016-11-29 09:42:00
Record Updated: 2016-12-08 09:59:00
Updated By: TEDIEFFE
Crossref ID: C915292
Cross Ref Type Code: 22
Cross Ref Type: BCP Site ID
Record Added Date: 2016-11-29 09:18:00
Record Updated: 2016-11-29 09:18:00
Updated By: TEDIEFFE

Site Code: 502175
Control Name: Environmental Easement
HW Code: C915292
Control Code: J
Control Type: INST
Dt record added: 09/09/2016
Dt rec updated: 01/09/2017
Updated By: TLRIDNER
Site Code: 502175
Site Description: Location: The site is located in the Northtown Plaza in a suburban area in the Town of Amherst. Sheridan Avenue borders the site to the north, other Northtown Plaza buildings then Bailey Avenue to the east, Niagara Falls Boulevard to the west and Eggert Road to the south. Site Features: The site consists of three Areas of Interest

NORTHTOWN INC. (Continued) **S116555295**

(AOIs) comprising 1.424 acres of an approximately 14.022 acre parcel of land on which the Northtown Plaza is located. Currently the Northtown Plaza is occupied by six commercial buildings, most containing multiple tenant spaces. Current Zoning and Land Use: The site is zoned for commercial use and is currently used as a commercial-retail plaza. The area is primarily used as a shopping district, with major retailers located within 1/2 mile. Residential properties are located on the side streets surrounding the site. Past Use of the Site: The plaza was developed between the mid-1950s and mid-1980s, when it reached a configuration similar to what exists today. The current parcel was originally 23 separate parcels. Prior to development of the shopping center, the 23 parcels were agricultural land with no physical improvements. Construction of the first buildings commenced in 1952. Site Geology and Hydrogeology: The topography in the vicinity of the site is generally flat. The site is located between the Niagara and Onondaga Escarpments which act as major surface and groundwater divides. Site soils generally consist of a thin layer of fill material, sand, gravel, silt and clay mixed with some anthropogenic material. This overlays native soils comprised of fine grained silts and clays with varying amounts of sand and gravel. Bedrock, located more than 58 feet below ground surface (bgs), is of upper Silurian age and composed of sequences of shale, dolostone, salt and gypsum. Groundwater is first encountered at depths of 53 to 57 feet bgs. However, once the water bearing zone is encountered, water levels rise to 6 to 8 feet bgs, indicating the overlying silts and clays have formed a confined aquifer. Water level measurements collected from three monitoring wells depict a slight southern groundwater flow direction. This site has an Site Management Plan (SMP) dated November 28, 2016. All post remedial activity is directed by the SMP.

Env Problem: AOI 1 is 0.152 acres and includes portions of tenant spaces 21 and 22 and formerly included an abandoned fuel oil underground storage tank (UST). Tenant spaces 21 and 22 are currently vacant and will remain so until the building in which they are housed is demolished. AOI 2 is 0.048 acres and formerly included an abandoned fuel oil UST. AOI 3 is 1.272 acres and includes AOI 2 and tenant spaces 7 through 14. Tenant spaces 10 through 14 are currently vacant and will remain so until the building in which they are housed is demolished pending the expiration of the remaining tenant space lease agreements. Tenant space 14 was the location of a former dry cleaner facility which used tetrachloroethene (PCE) and is believed to have been the source of the PCE contamination found in AOI 3. The subsequent dry cleaner facility, which occupied the now vacant space, was used as a pick-up/drop off location for clothes that were dry cleaned at another facility which used PCE. Prior to IRMs: Soil was analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs) and pesticides. Groundwater was analyzed for VOCs, metals and pesticides. Based upon the investigations conducted to date, the primary contaminants of concern include tetrachloroethene (PCE), trichloroethene (TCE), cis-1, 2- dichloroethene (DCE) and petroleum products. SOIL The detected concentrations of VOCs in soil were below their commercial soil cleanup objectives (CSCO) with the exception of tetrachloroethene (PCE) which was found as high as 1,100 parts per million (ppm). The PCE was detected in and around the dry cleaner unit. The detected concentrations of PCE exceeded its unrestricted soil cleanup objective (USCO) in 19 samples, all within the area of

NORTHTOWN INC. (Continued) **S116555295**

AOI 3. CSCOs were exceeded in four of the sample locations. Two of the four locations that exceeded CSOCs (SP-47 and SP-56) also exceeded the industrial SCO. No other VOCs were detected exceeding their respective CSCOs in the other 79 soil samples collected. No soil contamination is known or suspected to be present off-site with the exception of one sample location which exceeded USCOs but was below Residential SCOs for benzene and xylene. A total of 28 soil samples were selected for analysis of semi-volatile organic compounds (SVOCs). SVOCs were detected in 3 of the samples however all concentrations were below the unrestricted SCOs. A total of 4 samples were selected for analysis of Target Analyte List (TAL) metals and pesticides. The concentration of metals were below CSCOs and pesticides were not detected. A total of 12 samples were selected for analysis of polychlorinated biphenyls (PCBs). PCBs were not detected. Visual/olfactory evidence of petroleum contamination was encountered in the vicinity of both the southern heating oil UST (AOI 1) and western heating oil UST (AOI 2) however the laboratory results did not exceed USCOs. One off-site sample location exceeded USCOs but was below Residential SCOs for benzene and xylene. GROUNDWATER Three deep groundwater monitoring wells, screened from 45 to 58 feet bgs, were sampled for VOCs, TAL metals and pesticides. A total of six VOCs were detected at concentrations ranging from 0.46 to 8.5 parts per billion (ppb) however all were below their applicable groundwater standards. The concentration of metals were below groundwater standards with the exception of magnesium and sodium, both naturally occurring minerals. Pesticides were not detected. Five of six shallow monitoring wells, screened from 5 to 20 feet below ground surface (bgs), were sampled for chlorinated volatile organic compounds (CVOCs). These wells were screened in a low permeability silty clay till. Saturated soils indicating shallow perched groundwater were not encountered and only five of the six wells produced sufficient pore water to sample. CVOCs were detected above the Department s Class GA criteria in only two of the wells and was limited to the immediate vicinity of the most highly impacted soils within AOI 3. PCE concentrations in the two wells ranged from 21,700 to 31,900 ppb. The contaminated pore water was removed during the PCE hot spot soil excavation. SOIL VAPOR, SUB-SLAB VAPOR, and INDOOR AIR A total of 29 air, sub-slab and soil vapor samples were collected and sent for VOC laboratory analysis. PCE, trichloroethene (TCE) and cis-1, 2-dichloroethene were detected in both sub-slab soil vapor and indoor air samples. PCE was the only compound to exceed DOH air guidelines and ranged from 60 to 70 ug/m3 in two indoor air samples inside AOI 3 tenant spaces 13 and 14. PCE concentrations ranged from 230 to 6,400 ug/m3 in three sub-slab vapor samples from beneath AOI 3 tenant spaces 13 and 14 and beneath the building located off-site directly west of AOI 3 (tenant space 1). The sub-slab vapor and indoor air sample results from the remaining AOI 3 tenant spaces 7 through 12 were within DOH air guidelines. PCE was the only compound detected in the 2 soil vapor samples collected and ranged from 5.4 to 8.5 ug/m3. Post IRMs: At the completion of the UST and PCE hot spot excavations, 29 post excavation soil samples were collected to confirm that the remedial actions successfully achieved soil cleanup objectives for commercial use. All post excavation soil sample results met commercial SCOs. No contamination exceeding CSCOs is known or suspected to be present beneath the on-site buildings. Based on visual and olfactory observations as well as organic vapor meter readings, all soils exhibiting nuisance characteristics were removed. In December 2015, at the completion of

NORTHTOWN INC. (Continued) **S116555295**

the SSDS installations, post-installation vacuum monitoring of the sub-slab soil vapor was completed and confirmed that the SSDSs were operating as intended. In February 2016 post-installation indoor air sampling was performed for analysis of CVOCs at the now vacant tenant space 14 within AOI 3 and at tenant space 1, the now vacant building located off-site directly west of AOI 3. Post-installation indoor air sample results for PCE at tenant space 14 increased from 60 to 150 ug/m3 however, because the SSDS was operational with confirmed adequate depressurization of the sub-slab, the result was attributed to off-gassing from clothes dry-cleaned at another facility and routinely brought to the tenant space for pickup by customers at the time of the sampling. Post-installation indoor air sample results for PCE at tenant space 1 increased from less than 1.0 to 2.7 ug/m3 but remained below DOH air guidelines. The building which comprises tenant space 1 is currently vacant and slated for demolition.

Health Problem: Direct contact with contaminants in the soil is unlikely because the majority of the site is covered with buildings and pavement. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Sub-slab depressurization systems (systems that ventilate/remove the air beneath the building) have been installed in one on-site tenant space and one off-site building to prevent the indoor air quality from being affected by the contamination in soil vapor beneath the buildings. Other tenant spaces in the on-site building have the potential for soil vapor intrusion to affect indoor air quality, however the tenant spaces are currently unoccupied. Therefore, inhalation of site-contaminants in indoor air of these vacant tenant spaces does not represent a current concern. Soil vapor intrusion concerns are limited to the on-site building and one off-site structure as indicated above.

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2014-11-21 11:20:00
Record Upd: 2016-12-02 11:02:00
Updated By: TEDIEFFE
Own Op: Applicant/Requestor
Sub Type: P03
Owner Name: Jeffrey C. Curely
Owner Company: Northtown Property Owner LLC
Owner Address: 33 Boylston Street
Owner Addr2: Not reported
Owner City,St,Zip: Chestnut Hill, MA 02467
Owner Country: United States of America
Own Op: Document Repository

NORTHTOWN INC. (Continued) **S116555295**

Sub Type: NNN
Owner Name: Roseanne Butler-Smith
Owner Company: Audubon Branch Library
Owner Address: 350 John J. Audubon Parkway
Owner Addr2: Not reported
Owner City,St,Zip: Amherst, NY 14228
Owner Country: United States of America
Own Op: Owner
Sub Type: E
Owner Name: Jeffrey C. Curley
Owner Company: Northtown Property Owner LLC
Owner Address: 33 Boylston Street
Owner Addr2: Not reported
Owner City,St,Zip: Chestnut Hill, MA 02467
Owner Country: United States of America
HW Code: C915292
Waste Type: cis-1,2-Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C915292
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C915292
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C915292
Waste Type: petroleum products
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C915292
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C915292-03-15
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2016-11-28 15:13:00
Record Updated: 2016-11-28 15:13:00
Updated By: TEDIEFFE
Crossref ID: 107/3178
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2016-11-29 09:42:00
Record Updated: 2016-11-29 09:42:00
Updated By: TEDIEFFE
Crossref ID: May 15, 2015
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2016-11-29 10:17:00
Record Updated: 2016-11-29 10:17:00
Updated By: TEDIEFFE
Crossref ID: Book 11305 Page 7751
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2016-11-29 09:42:00

NORTHTOWN INC. (Continued) **S116555295**

Record Updated: 2016-12-08 09:59:00
Updated By: TEDIEFFE
Crossref ID: C915292
Cross Ref Type Code: 22
Cross Ref Type: BCP Site ID
Record Added Date: 2016-11-29 09:18:00
Record Updated: 2016-11-29 09:18:00
Updated By: TEDIEFFE

Site Code: 502175
Control Name: IC/EC Plan
HW Code: C915292
Control Code: 34
Control Type: INST
Dt record added: 09/09/2016
Dt rec updated: 01/09/2017
Updated By: TLRIDNER
Site Code: 502175
Site Description: Location: The site is located in the Northtown Plaza in a suburban area in the Town of Amherst. Sheridan Avenue borders the site to the north, other Northtown Plaza buildings then Bailey Avenue to the east, Niagara Falls Boulevard to the west and Eggert Road to the south. Site Features: The site consists of three Areas of Interest (AOIs) comprising 1.424 acres of an approximately 14.022 acre parcel of land on which the Northtown Plaza is located. Currently the Northtown Plaza is occupied by six commercial buildings, most containing multiple tenant spaces. Current Zoning and Land Use: The site is zoned for commercial use and is currently used as a commercial-retail plaza. The area is primarily used as a shopping district, with major retailers located within 1/2 mile. Residential properties are located on the side streets surrounding the site. Past Use of the Site: The plaza was developed between the mid-1950s and mid-1980s, when it reached a configuration similar to what exists today. The current parcel was originally 23 separate parcels. Prior to development of the shopping center, the 23 parcels were agricultural land with no physical improvements. Construction of the first buildings commenced in 1952. Site Geology and Hydrogeology: The topography in the vicinity of the site is generally flat. The site is located between the Niagara and Onondaga Escarpments which act as major surface and groundwater divides. Site soils generally consist of a thin layer of fill material, sand, gravel, silt and clay mixed with some anthropogenic material. This overlays native soils comprised of fine grained silts and clays with varying amounts of sand and gravel. Bedrock, located more than 58 feet below ground surface (bgs), is of upper Silurian age and composed of sequences of shale, dolostone, salt and gypsum. Groundwater is first encountered at depths of 53 to 57 feet bgs. However, once the water bearing zone is encountered, water levels rise to 6 to 8 feet bgs, indicating the overlying silts and clays have formed a confined aquifer. Water level measurements collected from three monitoring wells depict a slight southern groundwater flow direction. This site has an Site Management Plan (SMP) dated November 28, 2016. All post remedial activity is directed by the SMP.
Env Problem: AOI 1 is 0.152 acres and includes portions of tenant spaces 21 and 22 and formerly included an abandoned fuel oil underground storage tank (UST). Tenant spaces 21 and 22 are currently vacant and will remain so until the building in which they are housed is demolished. AOI 2

NORTHTOWN INC. (Continued) **S116555295**

is 0.048 acres and formerly included an abandoned fuel oil UST. AOI 3 is 1.272 acres and includes AOI 2 and tenant spaces 7 through 14. Tenant spaces 10 through 14 are currently vacant and will remain so until the building in which they are housed is demolished pending the expiration of the remaining tenant space lease agreements. Tenant space 14 was the location of a former dry cleaner facility which used tetrachloroethene (PCE) and is believed to have been the source of the PCE contamination found in AOI 3. The subsequent dry cleaner facility, which occupied the now vacant space, was used as a pick-up/drop off location for clothes that were dry cleaned at another facility which used PCE. Prior to IRMs: Soil was analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs) and pesticides. Groundwater was analyzed for VOCs, metals and pesticides. Based upon the investigations conducted to date, the primary contaminants of concern include tetrachloroethene (PCE), trichloroethene (TCE), cis-1, 2- dichloroethene (DCE) and petroleum products. SOIL The detected concentrations of VOCs in soil were below their commercial soil cleanup objectives (CSCO) with the exception of tetrachloroethene (PCE) which was found as high as 1,100 parts per million (ppm). The PCE was detected in and around the dry cleaner unit. The detected concentrations of PCE exceeded its unrestricted soil cleanup objective (USCO) in 19 samples, all within the area of AOI 3. CSCOs were exceeded in four of the sample locations. Two of the four locations that exceeded CSOCs (SP-47 and SP-56) also exceeded the industrial SCO. No other VOCs were detected exceeding their respective CSCOs in the other 79 soil samples collected. No soil contamination is known or suspected to be present off-site with the exception of one sample location which exceeded USCOs but was below Residential SCOs for benzene and xylene. A total of 28 soil samples were selected for analysis of semi-volatile organic compounds (SVOCs). SVOCs were detected in 3 of the samples however all concentrations were below the unrestricted SCOs. A total of 4 samples were selected for analysis of Target Analyte List (TAL) metals and pesticides. The concentration of metals were below CSCOs and pesticides were not detected. A total of 12 samples were selected for analysis of polychlorinated biphenyls (PCBs). PCBs were not detected. Visual/olfactory evidence of petroleum contamination was encountered in the vicinity of both the southern heating oil UST (AOI 1) and western heating oil UST (AOI 2) however the laboratory results did not exceed USCOs. One off-site sample location exceeded USCOs but was below Residential SCOs for benzene and xylene. GROUNDWATER Three deep groundwater monitoring wells, screened from 45 to 58 feet bgs, were sampled for VOCs, TAL metals and pesticides. A total of six VOCs were detected at concentrations ranging from 0.46 to 8.5 parts per billion (ppb) however all were below their applicable groundwater standards. The concentration of metals were below groundwater standards with the exception of magnesium and sodium, both naturally occurring minerals. Pesticides were not detected. Five of six shallow monitoring wells, screened from 5 to 20 feet below ground surface (bgs), were sampled for chlorinated volatile organic compounds (CVOCs). These wells were screened in a low permeability silty clay till. Saturated soils indicating shallow perched groundwater were not encountered and only five of the six wells produced sufficient pore water to sample. CVOCs were detected above the Department s Class GA criteria in only two of the wells and was limited to the immediate vicinity of the most highly impacted soils within AOI 3. PCE concentrations in the two

NORTHTOWN INC. (Continued) **S116555295**

wells ranged from 21,700 to 31,900 ppb. The contaminated pore water was removed during the PCE hot spot soil excavation. SOIL VAPOR, SUB-SLAB VAPOR, and INDOOR AIR A total of 29 air, sub-slab and soil vapor samples were collected and sent for VOC laboratory analysis. PCE, trichloroethene (TCE) and cis-1, 2-dichloroethene were detected in both sub-slab soil vapor and indoor air samples. PCE was the only compound to exceed DOH air guidelines and ranged from 60 to 70 ug/m3 in two indoor air samples inside AOI 3 tenant spaces 13 and 14. PCE concentrations ranged from 230 to 6,400 ug/m3 in three sub-slab vapor samples from beneath AOI 3 tenant spaces 13 and 14 and beneath the building located off-site directly west of AOI 3 (tenant space 1). The sub-slab vapor and indoor air sample results from the remaining AOI 3 tenant spaces 7 through 12 were within DOH air guidelines. PCE was the only compound detected in the 2 soil vapor samples collected and ranged from 5.4 to 8.5 ug/m3. Post IRMs: At the completion of the UST and PCE hot spot excavations, 29 post excavation soil samples were collected to confirm that the remedial actions successfully achieved soil cleanup objectives for commercial use. All post excavation soil sample results met commercial SCOs. No contamination exceeding CSCOs is known or suspected to be present beneath the on-site buildings. Based on visual and olfactory observations as well as organic vapor meter readings, all soils exhibiting nuisance characteristics were removed. In December 2015, at the completion of the SSDS installations, post-installation vacuum monitoring of the sub-slab soil vapor was completed and confirmed that the SSDSs were operating as intended. In February 2016 post-installation indoor air sampling was performed for analysis of CVOCs at the now vacant tenant space 14 within AOI 3 and at tenant space 1, the now vacant building located off-site directly west of AOI 3. Post-installation indoor air sample results for PCE at tenant space 14 increased from 60 to 150 ug/m3 however, because the SSDS was operational with confirmed adequate depressurization of the sub-slab, the result was attributed to off-gassing from clothes dry-cleaned at another facility and routinely brought to the tenant space for pickup by customers at the time of the sampling. Post-installation indoor air sample results for PCE at tenant space 1 increased from less than 1.0 to 2.7 ug/m3 but remained below DOH air guidelines. The building which comprises tenant space 1 is currently vacant and slated for demolition.

Health Problem: Direct contact with contaminants in the soil is unlikely because the majority of the site is covered with buildings and pavement. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Sub-slab depressurization systems (systems that ventilate/remove the air beneath the building) have been installed in one on-site tenant space and one off-site building to prevent the indoor air quality from being affected by the contamination in soil vapor beneath the buildings. Other tenant spaces in the on-site building have the potential for soil vapor intrusion to affect indoor air quality, however the tenant spaces are currently unoccupied. Therefore, inhalation of site-contaminants in indoor air of these vacant tenant spaces does not represent a current

NORTHTOWN INC. (Continued) **S116555295**

concern. Soil vapor intrusion concerns are limited to the on-site building and one off-site structure as indicated above.

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2014-11-21 11:20:00
Record Upd: 2016-12-02 11:02:00
Updated By: TEDIEFFE
Own Op: Applicant/Requestor
Sub Type: P03
Owner Name: Jeffrey C. Curely
Owner Company: Northtown Property Owner LLC
Owner Address: 33 Boylston Street
Owner Addr2: Not reported
Owner City,St,Zip: Chestnut Hill, MA 02467
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Roseanne Butler-Smith
Owner Company: Audubon Branch Library
Owner Address: 350 John J. Audubon Parkway
Owner Addr2: Not reported
Owner City,St,Zip: Amherst, NY 14228
Owner Country: United States of America
Own Op: Owner
Sub Type: E
Owner Name: Jeffrey C. Curley
Owner Company: Northtown Property Owner LLC
Owner Address: 33 Boylston Street
Owner Addr2: Not reported
Owner City,St,Zip: Chestnut Hill, MA 02467
Owner Country: United States of America
HW Code: C915292
Waste Type: cis-1,2-Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C915292
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C915292
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C915292
Waste Type: petroleum products
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C915292
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN

NORTHTOWN INC. (Continued) **S116555295**

Waste Code: Not reported
Crossref ID: C915292-03-15
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2016-11-28 15:13:00
Record Updated: 2016-11-28 15:13:00
Updated By: TEDIEFFE
Crossref ID: 107/3178
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2016-11-29 09:42:00
Record Updated: 2016-11-29 09:42:00
Updated By: TEDIEFFE
Crossref ID: May 15, 2015
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2016-11-29 10:17:00
Record Updated: 2016-11-29 10:17:00
Updated By: TEDIEFFE
Crossref ID: Book 11305 Page 7751
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2016-11-29 09:42:00
Record Updated: 2016-12-08 09:59:00
Updated By: TEDIEFFE
Crossref ID: C915292
Cross Ref Type Code: 22
Cross Ref Type: BCP Site ID
Record Added Date: 2016-11-29 09:18:00
Record Updated: 2016-11-29 09:18:00
Updated By: TEDIEFFE

Site Code: 502175
Control Name: Site Management Plan
HW Code: C915292
Control Code: 32
Control Type: INST
Dt record added: 09/09/2016
Dt rec updated: 01/09/2017
Updated By: TLRIDNER
Site Code: 502175
Site Description: Location: The site is located in the Northtown Plaza in a suburban area in the Town of Amherst. Sheridan Avenue borders the site to the north, other Northtown Plaza buildings then Bailey Avenue to the east, Niagara Falls Boulevard to the west and Eggert Road to the south. Site Features: The site consists of three Areas of Interest (AOIs) comprising 1.424 acres of an approximately 14.022 acre parcel of land on which the Northtown Plaza is located. Currently the Northtown Plaza is occupied by six commercial buildings, most containing multiple tenant spaces. Current Zoning and Land Use: The site is zoned for commercial use and is currently used as a commercial-retail plaza. The area is primarily used as a shopping district, with major retailers located within 1/2 mile. Residential properties are located on the side streets surrounding the site. Past Use of the Site: The plaza was developed between the mid-1950s and mid-1980s, when it reached a configuration similar to what exists today. The current parcel was originally 23 separate parcels. Prior

NORTHTOWN INC. (Continued) **S116555295**

to development of the shopping center, the 23 parcels were agricultural land with no physical improvements. Construction of the first buildings commenced in 1952. Site Geology and Hydrogeology: The topography in the vicinity of the site is generally flat. The site is located between the Niagara and Onondaga Escarpments which act as major surface and groundwater divides. Site soils generally consist of a thin layer of fill material, sand, gravel, silt and clay mixed with some anthropogenic material. This overlays native soils comprised of fine grained silts and clays with varying amounts of sand and gravel. Bedrock, located more than 58 feet below ground surface (bgs), is of upper Silurian age and composed of sequences of shale, dolostone, salt and gypsum. Groundwater is first encountered at depths of 53 to 57 feet bgs. However, once the water bearing zone is encountered, water levels rise to 6 to 8 feet bgs, indicating the overlying silts and clays have formed a confined aquifer. Water level measurements collected from three monitoring wells depict a slight southern groundwater flow direction. This site has an Site Management Plan (SMP) dated November 28, 2016. All post remedial activity is directed by the SMP.

Env Problem: AOI 1 is 0.152 acres and includes portions of tenant spaces 21 and 22 and formerly included an abandoned fuel oil underground storage tank (UST). Tenant spaces 21 and 22 are currently vacant and will remain so until the building in which they are housed is demolished. AOI 2 is 0.048 acres and formerly included an abandoned fuel oil UST. AOI 3 is 1.272 acres and includes AOI 2 and tenant spaces 7 through 14. Tenant spaces 10 through 14 are currently vacant and will remain so until the building in which they are housed is demolished pending the expiration of the remaining tenant space lease agreements. Tenant space 14 was the location of a former dry cleaner facility which used tetrachloroethene (PCE) and is believed to have been the source of the PCE contamination found in AOI 3. The subsequent dry cleaner facility, which occupied the now vacant space, was used as a pick-up/drop off location for clothes that were dry cleaned at another facility which used PCE. Prior to IRMs: Soil was analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs) and pesticides. Groundwater was analyzed for VOCs, metals and pesticides. Based upon the investigations conducted to date, the primary contaminants of concern include tetrachloroethene (PCE), trichloroethene (TCE), cis-1, 2- dichloroethene (DCE) and petroleum products. SOIL The detected concentrations of VOCs in soil were below their commercial soil cleanup objectives (CSCO) with the exception of tetrachloroethene (PCE) which was found as high as 1,100 parts per million (ppm). The PCE was detected in and around the dry cleaner unit. The detected concentrations of PCE exceeded its unrestricted soil cleanup objective (USCO) in 19 samples, all within the area of AOI 3. CSCOs were exceeded in four of the sample locations. Two of the four locations that exceeded CSOCs (SP-47 and SP-56) also exceeded the industrial SCO. No other VOCs were detected exceeding their respective CSCOs in the other 79 soil samples collected. No soil contamination is known or suspected to be present off-site with the exception of one sample location which exceeded USCOs but was below Residential SCOs for benzene and xylene. A total of 28 soil samples were selected for analysis of semi-volatile organic compounds (SVOCs). SVOCs were detected in 3 of the samples however all concentrations were below the unrestricted SCOs. A total of 4 samples were selected for analysis of Target Analyte List (TAL) metals and

NORTHTOWN INC. (Continued) **S116555295**

pesticides. The concentration of metals were below CSCOs and pesticides were not detected. A total of 12 samples were selected for analysis of polychlorinated biphenyls (PCBs). PCBs were not detected. Visual/olfactory evidence of petroleum contamination was encountered in the vicinity of both the southern heating oil UST (AOI 1) and western heating oil UST (AOI 2) however the laboratory results did not exceed USCOs. One off-site sample location exceeded USCOs but was below Residential SCOs for benzene and xylene. GROUNDWATER Three deep groundwater monitoring wells, screened from 45 to 58 feet bgs, were sampled for VOCs, TAL metals and pesticides. A total of six VOCs were detected at concentrations ranging from 0.46 to 8.5 parts per billion (ppb) however all were below their applicable groundwater standards. The concentration of metals were below groundwater standards with the exception of magnesium and sodium, both naturally occurring minerals. Pesticides were not detected. Five of six shallow monitoring wells, screened from 5 to 20 feet below ground surface (bgs), were sampled for chlorinated volatile organic compounds (CVOCs). These wells were screened in a low permeability silty clay till. Saturated soils indicating shallow perched groundwater were not encountered and only five of the six wells produced sufficient pore water to sample. CVOCs were detected above the Department s Class GA criteria in only two of the wells and was limited to the immediate vicinity of the most highly impacted soils within AOI 3. PCE concentrations in the two wells ranged from 21,700 to 31,900 ppb. The contaminated pore water was removed during the PCE hot spot soil excavation. SOIL VAPOR, SUB-SLAB VAPOR, and INDOOR AIR A total of 29 air, sub-slab and soil vapor samples were collected and sent for VOC laboratory analysis. PCE, trichloroethene (TCE) and cis-1, 2-dichloroethene were detected in both sub-slab soil vapor and indoor air samples. PCE was the only compound to exceed DOH air guidelines and ranged from 60 to 70 ug/m3 in two indoor air samples inside AOI 3 tenant spaces 13 and 14. PCE concentrations ranged from 230 to 6,400 ug/m3 in three sub-slab vapor samples from beneath AOI 3 tenant spaces 13 and 14 and beneath the building located off-site directly west of AOI 3 (tenant space 1). The sub-slab vapor and indoor air sample results from the remaining AOI 3 tenant spaces 7 through 12 were within DOH air guidelines. PCE was the only compound detected in the 2 soil vapor samples collected and ranged from 5.4 to 8.5 ug/m3. Post IRMs: At the completion of the UST and PCE hot spot excavations, 29 post excavation soil samples were collected to confirm that the remedial actions successfully achieved soil cleanup objectives for commercial use. All post excavation soil sample results met commercial SCOs. No contamination exceeding CSCOs is known or suspected to be present beneath the on-site buildings. Based on visual and olfactory observations as well as organic vapor meter readings, all soils exhibiting nuisance characteristics were removed. In December 2015, at the completion of the SSDS installations, post-installation vacuum monitoring of the sub-slab soil vapor was completed and confirmed that the SSDSs were operating as intended. In February 2016 post-installation indoor air sampling was performed for analysis of CVOCs at the now vacant tenant space 14 within AOI 3 and at tenant space 1, the now vacant building located off-site directly west of AOI 3. Post-installation indoor air sample results for PCE at tenant space 14 increased from 60 to 150 ug/m3 however, because the SSDS was operational with confirmed adequate depressurization of the sub-slab, the result was attributed to off-gassing from clothes dry-cleaned at another facility and routinely brought to the tenant space for pickup by customers at the

NORTHTOWN INC. (Continued) **S116555295**

time of the sampling. Post-installation indoor air sample results for PCE at tenant space 1 increased from less than 1.0 to 2.7 ug/m3 but remained below DOH air guidelines. The building which comprises tenant space 1 is currently vacant and slated for demolition.

Health Problem: Direct contact with contaminants in the soil is unlikely because the majority of the site is covered with buildings and pavement. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Sub-slab depressurization systems (systems that ventilate/remove the air beneath the building) have been installed in one on-site tenant space and one off-site building to prevent the indoor air quality from being affected by the contamination in soil vapor beneath the buildings. Other tenant spaces in the on-site building have the potential for soil vapor intrusion to affect indoor air quality, however the tenant spaces are currently unoccupied. Therefore, inhalation of site-contaminants in indoor air of these vacant tenant spaces does not represent a current concern. Soil vapor intrusion concerns are limited to the on-site building and one off-site structure as indicated above.

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2014-11-21 11:20:00
Record Upd: 2016-12-02 11:02:00
Updated By: TEDIEFFE
Own Op: Applicant/Requestor
Sub Type: P03
Owner Name: Jeffrey C. Curely
Owner Company: Northtown Property Owner LLC
Owner Address: 33 Boylston Street
Owner Addr2: Not reported
Owner City,St,Zip: Chestnut Hill, MA 02467
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Roseanne Butler-Smith
Owner Company: Audubon Branch Library
Owner Address: 350 John J. Audubon Parkway
Owner Addr2: Not reported
Owner City,St,Zip: Amherst, NY 14228
Owner Country: United States of America
Own Op: Owner
Sub Type: E
Owner Name: Jeffrey C. Curley
Owner Company: Northtown Property Owner LLC

NORTHTOWN INC. (Continued) **S116555295**

Owner Address: 33 Boylston Street
Owner Addr2: Not reported
Owner City,St,Zip: Chestnut Hill, MA 02467
Owner Country: United States of America
HW Code: C915292
Waste Type: cis-1,2-Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C915292
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C915292
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C915292
Waste Type: petroleum products
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C915292
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C915292-03-15
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2016-11-28 15:13:00
Record Updated: 2016-11-28 15:13:00
Updated By: TEDIEFFE
Crossref ID: 107/3178
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2016-11-29 09:42:00
Record Updated: 2016-11-29 09:42:00
Updated By: TEDIEFFE
Crossref ID: May 15, 2015
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2016-11-29 10:17:00
Record Updated: 2016-11-29 10:17:00
Updated By: TEDIEFFE
Crossref ID: Book 11305 Page 7751
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2016-11-29 09:42:00
Record Updated: 2016-12-08 09:59:00
Updated By: TEDIEFFE
Crossref ID: C915292
Cross Ref Type Code: 22
Cross Ref Type: BCP Site ID
Record Added Date: 2016-11-29 09:18:00
Record Updated: 2016-11-29 09:18:00
Updated By: TEDIEFFE

Site Code: 502175
Control Name: Ground Water Use Restriction

NORTHTOWN INC. (Continued) **S116555295**

HW Code: C915292
Control Code: 08
Control Type: INST
Dt record added: 09/09/2016
Dt rec updated: 01/09/2017
Updated By: TLRIDNER
Site Code: 502175
Site Description: Location: The site is located in the Northtown Plaza in a suburban area in the Town of Amherst. Sheridan Avenue borders the site to the north, other Northtown Plaza buildings then Bailey Avenue to the east, Niagara Falls Boulevard to the west and Eggert Road to the south. Site Features: The site consists of three Areas of Interest (AOIs) comprising 1.424 acres of an approximately 14.022 acre parcel of land on which the Northtown Plaza is located. Currently the Northtown Plaza is occupied by six commercial buildings, most containing multiple tenant spaces. Current Zoning and Land Use: The site is zoned for commercial use and is currently used as a commercial-retail plaza. The area is primarily used as a shopping district, with major retailers located within 1/2 mile. Residential properties are located on the side streets surrounding the site. Past Use of the Site: The plaza was developed between the mid-1950s and mid-1980s, when it reached a configuration similar to what exists today. The current parcel was originally 23 separate parcels. Prior to development of the shopping center, the 23 parcels were agricultural land with no physical improvements. Construction of the first buildings commenced in 1952. Site Geology and Hydrogeology: The topography in the vicinity of the site is generally flat. The site is located between the Niagara and Onondaga Escarpments which act as major surface and groundwater divides. Site soils generally consist of a thin layer of fill material, sand, gravel, silt and clay mixed with some anthropogenic material. This overlays native soils comprised of fine grained silts and clays with varying amounts of sand and gravel. Bedrock, located more than 58 feet below ground surface (bgs), is of upper Silurian age and composed of sequences of shale, dolostone, salt and gypsum. Groundwater is first encountered at depths of 53 to 57 feet bgs. However, once the water bearing zone is encountered, water levels rise to 6 to 8 feet bgs, indicating the overlying silts and clays have formed a confined aquifer. Water level measurements collected from three monitoring wells depict a slight southern groundwater flow direction. This site has an Site Management Plan (SMP) dated November 28, 2016. All post remedial activity is directed by the SMP.
Env Problem: AOI 1 is 0.152 acres and includes portions of tenant spaces 21 and 22 and formerly included an abandoned fuel oil underground storage tank (UST). Tenant spaces 21 and 22 are currently vacant and will remain so until the building in which they are housed is demolished. AOI 2 is 0.048 acres and formerly included an abandoned fuel oil UST. AOI 3 is 1.272 acres and includes AOI 2 and tenant spaces 7 through 14. Tenant spaces 10 through 14 are currently vacant and will remain so until the building in which they are housed is demolished pending the expiration of the remaining tenant space lease agreements. Tenant space 14 was the location of a former dry cleaner facility which used tetrachloroethene (PCE) and is believed to have been the source of the PCE contamination found in AOI 3. The subsequent dry cleaner facility, which occupied the now vacant space, was used as a pick-up/drop off location for clothes that were dry cleaned at another facility which used PCE. Prior to IRMs: Soil was analyzed for

NORTHTOWN INC. (Continued) **S116555295**

volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs) and pesticides. Groundwater was analyzed for VOCs, metals and pesticides. Based upon the investigations conducted to date, the primary contaminants of concern include tetrachloroethene (PCE), trichloroethene (TCE), cis-1, 2- dichloroethene (DCE) and petroleum products. SOIL The detected concentrations of VOCs in soil were below their commercial soil cleanup objectives (CSCO) with the exception of tetrachloroethene (PCE) which was found as high as 1,100 parts per million (ppm). The PCE was detected in and around the dry cleaner unit. The detected concentrations of PCE exceeded its unrestricted soil cleanup objective (USCO) in 19 samples, all within the area of AOI 3. CSCOs were exceeded in four of the sample locations. Two of the four locations that exceeded CSOCs (SP-47 and SP-56) also exceeded the industrial SCO. No other VOCs were detected exceeding their respective CSCOs in the other 79 soil samples collected. No soil contamination is known or suspected to be present off-site with the exception of one sample location which exceeded USCOs but was below Residential SCOs for benzene and xylene. A total of 28 soil samples were selected for analysis of semi-volatile organic compounds (SVOCs). SVOCs were detected in 3 of the samples however all concentrations were below the unrestricted SCOs. A total of 4 samples were selected for analysis of Target Analyte List (TAL) metals and pesticides. The concentration of metals were below CSCOs and pesticides were not detected. A total of 12 samples were selected for analysis of polychlorinated biphenyls (PCBs). PCBs were not detected. Visual/olfactory evidence of petroleum contamination was encountered in the vicinity of both the southern heating oil UST (AOI 1) and western heating oil UST (AOI 2) however the laboratory results did not exceed USCOs. One off-site sample location exceeded USCOs but was below Residential SCOs for benzene and xylene. GROUNDWATER Three deep groundwater monitoring wells, screened from 45 to 58 feet bgs, were sampled for VOCs, TAL metals and pesticides. A total of six VOCs were detected at concentrations ranging from 0.46 to 8.5 parts per billion (ppb) however all were below their applicable groundwater standards. The concentration of metals were below groundwater standards with the exception of magnesium and sodium, both naturally occurring minerals. Pesticides were not detected. Five of six shallow monitoring wells, screened from 5 to 20 feet below ground surface (bgs), were sampled for chlorinated volatile organic compounds (CVOCs). These wells were screened in a low permeability silty clay till. Saturated soils indicating shallow perched groundwater were not encountered and only five of the six wells produced sufficient pore water to sample. CVOCs were detected above the Department s Class GA criteria in only two of the wells and was limited to the immediate vicinity of the most highly impacted soils within AOI 3. PCE concentrations in the two wells ranged from 21,700 to 31,900 ppb. The contaminated pore water was removed during the PCE hot spot soil excavation. SOIL VAPOR, SUB-SLAB VAPOR, and INDOOR AIR A total of 29 air, sub-slab and soil vapor samples were collected and sent for VOC laboratory analysis. PCE, trichloroethene (TCE) and cis-1, 2-dichloroethene were detected in both sub-slab soil vapor and indoor air samples. PCE was the only compound to exceed DOH air guidelines and ranged from 60 to 70 ug/m3 in two indoor air samples inside AOI 3 tenant spaces 13 and 14. PCE concentrations ranged from 230 to 6,400 ug/m3 in three sub-slab vapor samples from beneath AOI 3 tenant spaces 13 and 14 and beneath the building located off-site directly west of AOI 3 (tenant space 1).

NORTHTOWN INC. (Continued) **S116555295**

The sub-slab vapor and indoor air sample results from the remaining AOI 3 tenant spaces 7 through 12 were within DOH air guidelines. PCE was the only compound detected in the 2 soil vapor samples collected and ranged from 5.4 to 8.5 ug/m3. Post IRMs: At the completion of the UST and PCE hot spot excavations, 29 post excavation soil samples were collected to confirm that the remedial actions successfully achieved soil cleanup objectives for commercial use. All post excavation soil sample results met commercial SCOs. No contamination exceeding CSCOs is known or suspected to be present beneath the on-site buildings. Based on visual and olfactory observations as well as organic vapor meter readings, all soils exhibiting nuisance characteristics were removed. In December 2015, at the completion of the SSDS installations, post-installation vacuum monitoring of the sub-slab soil vapor was completed and confirmed that the SSDSs were operating as intended. In February 2016 post-installation indoor air sampling was performed for analysis of CVOCs at the now vacant tenant space 14 within AOI 3 and at tenant space 1, the now vacant building located off-site directly west of AOI 3. Post-installation indoor air sample results for PCE at tenant space 14 increased from 60 to 150 ug/m3 however, because the SSDS was operational with confirmed adequate depressurization of the sub-slab, the result was attributed to off-gassing from clothes dry-cleaned at another facility and routinely brought to the tenant space for pickup by customers at the time of the sampling. Post-installation indoor air sample results for PCE at tenant space 1 increased from less than 1.0 to 2.7 ug/m3 but remained below DOH air guidelines. The building which comprises tenant space 1 is currently vacant and slated for demolition.

Health Problem: Direct contact with contaminants in the soil is unlikely because the majority of the site is covered with buildings and pavement. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Sub-slab depressurization systems (systems that ventilate/remove the air beneath the building) have been installed in one on-site tenant space and one off-site building to prevent the indoor air quality from being affected by the contamination in soil vapor beneath the buildings. Other tenant spaces in the on-site building have the potential for soil vapor intrusion to affect indoor air quality, however the tenant spaces are currently unoccupied. Therefore, inhalation of site-contaminants in indoor air of these vacant tenant spaces does not represent a current concern. Soil vapor intrusion concerns are limited to the on-site building and one off-site structure as indicated above.

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported

NORTHTOWN INC. (Continued) **S116555295**

Record Add: 2014-11-21 11:20:00
Record Upd: 2016-12-02 11:02:00
Updated By: TEDIEFFE
Own Op: Applicant/Requestor
Sub Type: P03
Owner Name: Jeffrey C. Curely
Owner Company: Northtown Property Owner LLC
Owner Address: 33 Boylston Street
Owner Addr2: Not reported
Owner City,St,Zip: Chestnut Hill, MA 02467
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Roseanne Butler-Smith
Owner Company: Audubon Branch Library
Owner Address: 350 John J. Audubon Parkway
Owner Addr2: Not reported
Owner City,St,Zip: Amherst, NY 14228
Owner Country: United States of America
Own Op: Owner
Sub Type: E
Owner Name: Jeffrey C. Curley
Owner Company: Northtown Property Owner LLC
Owner Address: 33 Boylston Street
Owner Addr2: Not reported
Owner City,St,Zip: Chestnut Hill, MA 02467
Owner Country: United States of America
HW Code: C915292
Waste Type: cis-1,2-Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C915292
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C915292
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C915292
Waste Type: petroleum products
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C915292
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C915292-03-15
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2016-11-28 15:13:00
Record Updated: 2016-11-28 15:13:00
Updated By: TEDIEFFE
Crossref ID: 107/3178
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2016-11-29 09:42:00

NORTHTOWN INC. (Continued) **S116555295**

Record Updated: 2016-11-29 09:42:00
Updated By: TEDIEFFE
Crossref ID: May 15, 2015
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2016-11-29 10:17:00
Record Updated: 2016-11-29 10:17:00
Updated By: TEDIEFFE
Crossref ID: Book 11305 Page 7751
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2016-11-29 09:42:00
Record Updated: 2016-12-08 09:59:00
Updated By: TEDIEFFE
Crossref ID: C915292
Cross Ref Type Code: 22
Cross Ref Type: BCP Site ID
Record Added Date: 2016-11-29 09:18:00
Record Updated: 2016-11-29 09:18:00
Updated By: TEDIEFFE

BROWNFIELDS:

Program:	BCP
Site Code:	502175
Acres:	1.424
HW Code:	C915292
SWIS:	1522
Town:	Amherst
Record Added Date:	11/21/2014
Record Updated Date:	01/09/2018
Update By:	BXPUTZIG
Site Description:	Location: The site is located in the Northtown Plaza in a suburban area in the Town of Amherst. Sheridan Avenue borders the site to the north, other Northtown Plaza buildings then Bailey Avenue to the east, Niagara Falls Boulevard to the west and Eggert Road to the south. Site Features: The site consists of three Areas of Interest (AOIs) comprising 1.424 acres of an approximately 14.022 acre parcel of land on which the Northtown Plaza is located. Currently the Northtown Plaza is occupied by six commercial buildings, most containing multiple tenant spaces. Current Zoning and Land Use: The site is zoned for commercial use and is currently used as a commercial-retail plaza. The area is primarily used as a shopping district, with major retailers located within 1/2 mile. Residential properties are located on the side streets surrounding the site. Past Use of the Site: The plaza was developed between the mid-1950s and mid-1980s, when it reached a configuration similar to what exists today. The current parcel was originally 23 separate parcels. Prior to development of the shopping center, the 23 parcels were agricultural land with no physical improvements. Construction of the first buildings commenced in 1952. Site Geology and Hydrogeology: The topography in the vicinity of the site is generally flat. The site is located between the Niagara and Onondaga Escarpments which act as major surface and groundwater divides. Site soils generally consist of a thin layer of fill material, sand, gravel, silt and clay mixed with some anthropogenic material. This overlays native soils comprised of fine grained silts and clays with varying amounts of sand and gravel. Bedrock, located more than 58 feet below ground

NORTHTOWN INC. (Continued) **S116555295**

surface (bgs), is of upper Silurian age and composed of sequences of shale, dolostone, salt and gypsum. Groundwater is first encountered at depths of 53 to 57 feet bgs. However, once the water bearing zone is encountered, water levels rise to 6 to 8 feet bgs, indicating the overlying silts and clays have formed a confined aquifer. Water level measurements collected from three monitoring wells depict a slight southern groundwater flow direction. This site has an Site Management Plan (SMP) dated November 28, 2016. All post remedial activity is directed by the SMP.

Env Problem: AOI 1 is 0.152 acres and includes portions of tenant spaces 21 and 22 and formerly included an abandoned fuel oil underground storage tank (UST). Tenant spaces 21 and 22 are currently vacant and will remain so until the building in which they are housed is demolished. AOI 2 is 0.048 acres and formerly included an abandoned fuel oil UST. AOI 3 is 1.272 acres and includes AOI 2 and tenant spaces 7 through 14. Tenant spaces 10 through 14 are currently vacant and will remain so until the building in which they are housed is demolished pending the expiration of the remaining tenant space lease agreements. Tenant space 14 was the location of a former dry cleaner facility which used tetrachloroethene (PCE) and is believed to have been the source of the PCE contamination found in AOI 3. The subsequent dry cleaner facility, which occupied the now vacant space, was used as a pick-up/drop off location for clothes that were dry cleaned at another facility which used PCE. Prior to IRMs: Soil was analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs) and pesticides. Groundwater was analyzed for VOCs, metals and pesticides. Based upon the investigations conducted to date, the primary contaminants of concern include tetrachloroethene (PCE), trichloroethene (TCE), cis-1, 2- dichloroethene (DCE) and petroleum products. SOIL The detected concentrations of VOCs in soil were below their commercial soil cleanup objectives (CSCO) with the exception of tetrachloroethene (PCE) which was found as high as 1,100 parts per million (ppm). The PCE was detected in and around the dry cleaner unit. The detected concentrations of PCE exceeded its unrestricted soil cleanup objective (USCO) in 19 samples, all within the area of AOI 3. CSCOs were exceeded in four of the sample locations. Two of the four locations that exceeded CSOCs (SP-47 and SP-56) also exceeded the industrial SCO. No other VOCs were detected exceeding their respective CSCOs in the other 79 soil samples collected. No soil contamination is known or suspected to be present off-site with the exception of one sample location which exceeded USCOs but was below Residential SCOs for benzene and xylene. A total of 28 soil samples were selected for analysis of semi-volatile organic compounds (SVOCs). SVOCs were detected in 3 of the samples however all concentrations were below the unrestricted SCOs. A total of 4 samples were selected for analysis of Target Analyte List (TAL) metals and pesticides. The concentration of metals were below CSCOs and pesticides were not detected. A total of 12 samples were selected for analysis of polychlorinated biphenyls (PCBs). PCBs were not detected. Visual/olfactory evidence of petroleum contamination was encountered in the vicinity of both the southern heating oil UST (AOI 1) and western heating oil UST (AOI 2) however the laboratory results did not exceed USCOs. One off-site sample location exceeded USCOs but was below Residential SCOs for benzene and xylene. GROUNDWATER Three deep groundwater monitoring wells, screened from 45 to 58 feet bgs, were sampled for VOCs, TAL metals and pesticides. A total of six VOCs were

NORTHTOWN INC. (Continued) **S116555295**

detected at concentrations ranging from 0.46 to 8.5 parts per billion (ppb) however all were below their applicable groundwater standards. The concentration of metals were below groundwater standards with the exception of magnesium and sodium, both naturally occurring minerals. Pesticides were not detected. Five of six shallow monitoring wells, screened from 5 to 20 feet below ground surface (bgs), were sampled for chlorinated volatile organic compounds (CVOCs). These wells were screened in a low permeability silty clay till. Saturated soils indicating shallow perched groundwater were not encountered and only five of the six wells produced sufficient pore water to sample. CVOCs were detected above the Department s Class GA criteria in only two of the wells and was limited to the immediate vicinity of the most highly impacted soils within AOI 3. PCE concentrations in the two wells ranged from 21,700 to 31,900 ppb. The contaminated pore water was removed during the PCE hot spot soil excavation. SOIL VAPOR, SUB-SLAB VAPOR, and INDOOR AIR A total of 29 air, sub-slab and soil vapor samples were collected and sent for VOC laboratory analysis. PCE, trichloroethene (TCE) and cis-1, 2-dichloroethene were detected in both sub-slab soil vapor and indoor air samples. PCE was the only compound to exceed DOH air guidelines and ranged from 60 to 70 ug/m3 in two indoor air samples inside AOI 3 tenant spaces 13 and 14. PCE concentrations ranged from 230 to 6,400 ug/m3 in three sub-slab vapor samples from beneath AOI 3 tenant spaces 13 and 14 and beneath the building located off-site directly west of AOI 3 (tenant space 1). The sub-slab vapor and indoor air sample results from the remaining AOI 3 tenant spaces 7 through 12 were within DOH air guidelines. PCE was the only compound detected in the 2 soil vapor samples collected and ranged from 5.4 to 8.5 ug/m3. Post IRMs: At the completion of the UST and PCE hot spot excavations, 29 post excavation soil samples were collected to confirm that the remedial actions successfully achieved soil cleanup objectives for commercial use. All post excavation soil sample results met commercial SCOs. No contamination exceeding CSCOs is known or suspected to be present beneath the on-site buildings. Based on visual and olfactory observations as well as organic vapor meter readings, all soils exhibiting nuisance characteristics were removed. In December 2015, at the completion of the SSDS installations, post-installation vacuum monitoring of the sub-slab soil vapor was completed and confirmed that the SSDSs were operating as intended. In February 2016 post-installation indoor air sampling was performed for analysis of CVOCs at the now vacant tenant space 14 within AOI 3 and at tenant space 1, the now vacant building located off-site directly west of AOI 3. Post-installation indoor air sample results for PCE at tenant space 14 increased from 60 to 150 ug/m3 however, because the SSDS was operational with confirmed adequate depressurization of the sub-slab, the result was attributed to off-gassing from clothes dry-cleaned at another facility and routinely brought to the tenant space for pickup by customers at the time of the sampling. Post-installation indoor air sample results for PCE at tenant space 1 increased from less than 1.0 to 2.7 ug/m3 but remained below DOH air guidelines. The building which comprises tenant space 1 is currently vacant and slated for demolition.

Health Problem: Direct contact with contaminants in the soil is unlikely because the majority of the site is covered with buildings and pavement. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater or soil may move into

NORTHTOWN INC. (Continued) **S116555295**

the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Sub-slab depressurization systems (systems that ventilate/remove the air beneath the building) have been installed in one on-site tenant space and one off-site building to prevent the indoor air quality from being affected by the contamination in soil vapor beneath the buildings. Other tenant spaces in the on-site building have the potential for soil vapor intrusion to affect indoor air quality, however the tenant spaces are currently unoccupied. Therefore, inhalation of site-contaminants in indoor air of these vacant tenant spaces does not represent a current concern. Soil vapor intrusion concerns are limited to the on-site building and one off-site structure as indicated above.

Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2014-11-21 11:20:00
Record Upd:	2016-12-02 11:02:00
Updated By:	TEDIEFFE
Own Op:	Applicant/Requestor
Sub Type:	P03
Owner Name:	Jeffrey C. Curely
Owner Company:	Northtown Property Owner LLC
Owner Address:	33 Boylston Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Chestnut Hill, MA 02467
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Roseanne Butler-Smith
Owner Company:	Audubon Branch Library
Owner Address:	350 John J. Audubon Parkway
Owner Addr2:	Not reported
Owner City,St,Zip:	Amherst, NY 14228
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	E
Owner Name:	Jeffrey C. Curley
Owner Company:	Northtown Property Owner LLC
Owner Address:	33 Boylston Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Chestnut Hill, MA 02467
Owner Country:	United States of America
HW Code:	C915292
Waste Type:	cis-1,2-Dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C915292
Waste Type:	TETRACHLOROETHYLENE (PCE)

NORTHTOWN INC. (Continued) **S116555295**

Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C915292
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C915292
Waste Type:	petroleum products
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C915292
Waste Type:	TRICHLOROETHENE (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	C915292-03-15
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2016-11-28 15:13:00
Record Updated:	2016-11-28 15:13:00
Updated By:	TEDIEFFE
Crossref ID:	107/3178
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2016-11-29 09:42:00
Record Updated:	2016-11-29 09:42:00
Updated By:	TEDIEFFE
Crossref ID:	May 15, 2015
Cross Ref Type Code:	26
Cross Ref Type:	Agreement/Consent Order Date
Record Added Date:	2016-11-29 10:17:00
Record Updated:	2016-11-29 10:17:00
Updated By:	TEDIEFFE
Crossref ID:	Book 11305 Page 7751
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2016-11-29 09:42:00
Record Updated:	2016-12-08 09:59:00
Updated By:	TEDIEFFE
Crossref ID:	C915292
Cross Ref Type Code:	22
Cross Ref Type:	BCP Site ID
Record Added Date:	2016-11-29 09:18:00
Record Updated:	2016-11-29 09:18:00
Updated By:	TEDIEFFE

SPILLS:

Spill Number/Closed Date:	1401409 / 2015-02-20
Facility ID:	1401409
Facility Type:	ER
DER Facility ID:	449613
Site ID:	494691
DEC Region:	9
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	1522
Spill Date:	2014-05-09
Investigator:	SACALAND

NORTHTOWN INC. (Continued) **S116555295**

Referred To:	Not reported
Reported to Dept:	2014-05-09
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2014-05-09
Spill Record Last Update:	2015-02-20
Spiller Name:	JONATHAN LUTHER
Spiller Company:	NORTHTOWN, INC.
Spiller Address:	3097 SHERIDAN DRIVE
Spiller Company:	001
Contact Name:	CHRIS BORON
DEC Memo:	"5/16/14:SAC TELECON CHRIS BORON - GZA. MR. BORON SAID THERE WERE 2 USTS FOUND IN TWO ENTIRELY DIFFERENT LOCATIONS AT THE SITE AND BOTH WERE FOUND TO HAVE PETROLEUM CONTAMINATION IN THOSE LOCATIONS. THEY ARE FINISHING UP THE PHASE II WORK. MR. BORON ESTIMATES HE COULD SUBMIT THE PHASE II REPORT IN A MONTH. 8/7/14:SAC TELECON MIKE KRESS - GZA. MR. KRESS SAID THAT CHRIS BORON NO LONGER WORKS FOR GZA. HE WILL GIVE MESSAGE TO NEW GZA CONTACT PERSON REGARDING STATUS OF PHASE II REPORT. 8/8/14:SAC CALLED JONATHAN LUTHER - NORTHTOWN, INC. REGARDING PHASE II REPORT STATUS. LEFT MESSAGE FOR A CALL BACK. SAC TELECON JIM RICKERT - GZA. MR. RICKERT IS THE NEW PROJECT MANAGER FOR THE SITE. THEY ARE STILL WORKING ON THE REPORT. GZA IS WORKING FOR THE BUYER. THEY WANT TO SCHEDULE A MEETING BECAUSE PURCHASER IS CONSIDERING ENTERING THE BROWNFIELD OR VOLUNTARY CLEAN UP PROGRAM. THEY WILL CONTACT GPS NEXT WEEK TO SCHEDULE THE MEETING. 8/19/14:SAC SPOKE TO GPS. MR. RICKERT CONTACTED GPS AND SET UP MEETING FOR NEXT WEEK. 2/20/15:SAC SPOKE TO GPS. SITE WILL BE A BROWNFIELD SITE. OK TO CLOSEOUT SPILL. NO FURTHER ACTION REQUIRED BY SPILLS."
Remarks:	"phase 2 investigation found contamination, tank in place"

All Materials:

Site ID:	494691
Operable Unit ID:	1244202
Operable Unit:	01
Material ID:	2244990
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

BG304 **NORTHTOWN PLAZA** **NY UST** **U004047776**
East **3097 SHERIDAN DR** **N/A**
1/8-1/4 **AMHERST, NY 14226**
0.197 mi.
1042 ft. **Site 8 of 9 in cluster BG**

Actual:
598 ft.

Focus Map:
6

UST:

Id/Status:	9-600735 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	9
Expiration Date:	N/A
UTM X:	188722.82066
UTM Y:	4765688.18252
Site Type:	Other

Affiliation Records:

Site Id:	337658
Affiliation Type:	Facility Owner
Company Name:	NORTHTOWN PROPERTY OWNER LLC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	33 BOYLSTON STREET
Address2:	Not reported
City:	CHESTNUT HILL
State:	MA
Zip Code:	02467
Country Code:	001
Phone:	(617) 232-8900
EMail:	Not reported
Fax Number:	Not reported
Modified By:	AESKALSK
Date Last Modified:	2016-08-29

Site Id:	337658
Affiliation Type:	Mail Contact
Company Name:	NORTHTOWN PLAZA
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	3097 SHERIDAN DR
Address2:	Not reported
City:	AMHERST
State:	NY
Zip Code:	14226
Country Code:	001
Phone:	Not reported
EMail:	Not reported
Fax Number:	Not reported
Modified By:	AESKALSK
Date Last Modified:	2005-02-16

Site Id:	337658
Affiliation Type:	Facility Operator
Company Name:	NORTHTOWN PLAZA
Contact Type:	Not reported
Contact Name:	NONE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN

NORTHTOWN PLAZA (Continued) **U004047776**

Zip Code:	Not reported
Country Code:	001
Phone:	Not reported
EMail:	Not reported
Fax Number:	Not reported
Modified By:	AESKALSK
Date Last Modified:	2016-08-29

Tank Info:

Tank Number:	1
Tank ID:	182043
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	8000
Install Date:	Not reported
Date Tank Closed:	10/25/1995
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	AESKALSK
Last Modified:	04/14/2017

Tank Number:	2
Tank ID:	182044
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	8000
Install Date:	Not reported
Date Tank Closed:	10/25/1995
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	AESKALSK
Last Modified:	04/14/2017

Tank Number:	3
Tank ID:	182045
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	8000

NORTHTOWN PLAZA (Continued) **U004047776**

Install Date:	Not reported
Date Tank Closed:	10/25/1995
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	AESKALSK
Last Modified:	04/14/2017

Tank Number:	4
Tank ID:	263018
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	2000
Install Date:	Not reported
Date Tank Closed:	12/07/2015
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	AESKALSK
Last Modified:	04/14/2017

Equipment Records:

L00 - Piping Leak Detection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
J00 - Dispenser - None

Tank Number:	5
Tank ID:	263019
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	500
Install Date:	Not reported
Date Tank Closed:	12/09/2015
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel

NORTHTOWN PLAZA (Continued) **U004047776**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: AESKALSK
Last Modified: 04/14/2017

Equipment Records:

K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
L00 - Piping Leak Detection - None
J00 - Dispenser - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
E00 - Piping Secondary Containment - None

---

305 West 1/8-1/4 0.201 mi. 1060 ft.

Actual: 594 ft.

Focus Map: 6

WORLD AUTO PAINTING & COLLISION
2880 SHERIDAN DR
TONAWANDA, NY 14150

RCRA NonGen / NLR **1000278152**
FINDS **NYD121947063**
ECHO
NY MANIFEST

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: WORLD AUTO PAINTING & COLLISION
Facility address: 2880 SHERIDAN DR
TONAWANDA, NY 14150-9419
EPA ID: NYD121947063
Mailing address: SHERIDAN DR
TONAWANDA, NY 14150
Contact: Not reported
Contact address: SHERIDAN DR
TONAWANDA, NY 14150
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: BOB DUPREE
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

WORLD AUTO PAINTING & COLLISION (Continued) **1000278152**

Owner/operator name: BOB DUPREE
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: WORLD AUTO PAINTING & COLLISION
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: WORLD AUTO PAINTING & COLLISION
Classification: Not a generator, verified

Date form received by agency: 05/13/1986
Site name: WORLD AUTO PAINTING & COLLISION
Classification: Small Quantity Generator

. Waste code: NONE
. Waste name: None

Violation Status: No violations found

FINDS:

Registry ID: 110004381874

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA

WORLD AUTO PAINTING & COLLISION (Continued) **1000278152**

program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000278152
Registry ID:	110004381874
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004381874

NY MANIFEST:

Country:	USA
EPA ID:	NYD121947063
Facility Status:	Not reported
Location Address 1:	2880 SHERIDAN DRIVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	TONAWANDA
Location State:	NY
Location Zip:	14150
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD121947063
Mailing Name:	WORLD AUTO PAINTING & COLLISION
Mailing Contact:	WORLD AUTO PAINTING & COLLISION
Mailing Address 1:	2880 SHERIDAN DRIVE
Mailing Address 2:	Not reported
Mailing City:	TONAWANDA
Mailing State:	NY
Mailing Zip:	14150
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7168367150

NY MANIFEST:

Document ID:	NYA3571661
Manifest Status:	C
seq:	Not reported
Year:	1987
Trans1 State ID:	NYSDECVA0
Trans2 State ID:	Not reported
Generator Ship Date:	06/26/1987
Trans1 Recv Date:	06/26/1987
Trans2 Recv Date:	/ /
TSD Site Recv Date:	06/30/1987
Part A Recv Date:	06/29/1987
Part B Recv Date:	07/07/1987
Generator EPA ID:	NYD121947063
Trans1 EPA ID:	VAD980831580
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD043815703
TSDF ID 2:	Not reported

WORLD AUTO PAINTING & COLLISION (Continued) **1000278152**

Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F003 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00140
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	086

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

---

306 ESE 1/8-1/4 0.206 mi. 1090 ft. **UNITED CEREBRAL PALSY**
2360 NORTH FOREST
AMHERST, NY

NY Spills **S106008386** **N/A**

Actual: 582 ft.

Focus Map: 5

SPILLS:

Spill Number/Closed Date:	0207321 / 2002-11-26
Facility ID:	0207321
Facility Type:	ER
DER Facility ID:	152367
Site ID:	181709
DEC Region:	9
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	1522
Spill Date:	2002-10-15
Investigator:	RJJONAK
Referred To:	Not reported
Reported to Dept:	2002-10-15
CID:	211
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	2002-11-06
Recommended Penalty:	False
UST Trust:	False

UNITED CEREBRAL PALSY (Continued) **S106008386**

Remediation Phase:	0
Date Entered In Computer:	2002-10-15
Spill Record Last Update:	2002-11-27
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	CHRISTOPHER DOW
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RJJ 10/16/2002: RJJ TELECON CHRIS DOW,UNITED CEREBRAL PALSY,HE SAID THAT A PHASE 2 WAS DONE ON THE PROPERTY AND PETROLEUM CONTAMINATION WAS DISCOVERED...THEY WILL HIRE AN ENVIRONMENTAL FIRM TO REMEDIATE...CHRIS WILL SEND ME THE PHASE 2 AND KEEP ME INFORMED ON THEIR ACTIVITY...DRAFTED AND SENT A 'RP' LETTER. 11/1/2002: RJJ AT SITE WITH MARK WILDER,C&W,THEY HAVE BEEN HIRED BY UNITED CEREBRAL PALSEY TO REMEDIATE THE PETROLEUM CONTAMINATION,WHICH IS MAINLY BENEATH THE OLD MAINTANENCE BUILDING,NEAR THE WESTERN SIDE OF THE PROPERTY...MARK ALSO GAVE ME A COPY OF THE PHASE 2,WHICH GZA HAD DONE...WORK WILL BEGIN 11/4/2002...THEY ESTIMATE ABOUT 800 TONS OF CONTAMINATED SOIL NEEDS TO BE REMOVED AND DISPOSED OF. 11/4/2002: RJJ AT SITE AT 1000...C&W HAS REMOVED 1-1000 GAL GASOLINE TANK,WHICH WAS FULL OF FUEL,AND VACCED UP THE FUEL...THEY ARE EXCAVATING AN AREA ABOUT 30'X10'X6-8' AND STAGING THE CONTAMINATED SOIL ON PLASTIC,ON SITE...MOST OF THE CONTAMINATION APPEARS TO BE AROUND THE OLD PIPING AT THE FORMER PUMP ISLANDS...C&W WILL TAKE WALL/FLOOR SAMPLES AND SEND ME THEIR REPORT. 11/6/2002: RJJ AT SITE AT 1000...C&W HAS FINISHED EXCAVATING THE CONTAMINATION AND TOOK WALL/FLOOR SAMPLES...THE PIT AREA IS ABOUT 40'X20'X8'...UNITED CEREBRAL PALSEY HAS STARTED TO BACKFILL THE EXCAVATION,SINCE THEY ARE CONVINCED THEY HAVE DUG-TO-CLEAN...ABOUT 1000 TONS OF CONTAMINATED SOIL IS STAGED ON SITE,AWAITING FOR DISPOSAL. 11/26/2002: RECEIVED THE CLOSURE REPORT FROM C&W,WHICH INCLUDES THE SOIL DISPOSAL RECEIPTS FOR 1,447.24 TONS OF CONTAMINATED SOIL DISPOSED AT THE TONAWADA LANDFILL...THE CONFIRMATORY SOIL ANALYTICAL RESULTS ARE ALL BELOW OUR 'STARS' GUIDANCE VALUES...DRAFTED AND SENT A 'CLOSURE' LETTER TO UNITED CEREBRAL PALSY...NO FURTHER ACTION NEEDED...SPILL CLOSED OUT."
Remarks:	"SPILL FOUND DURING CONSTRUCTION PROJECT - APPEARS TO BE HISTORICAL SPILL"

All Materials:

Site ID:	181709
Operable Unit ID:	858928
Operable Unit:	01
Material ID:	517917
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BG307 **NORTHTOWN TEXACO SERVICE** **EDR Hist Auto** **1020290652**
East **3120 SHERIDAN DR** **N/A**
1/8-1/4 **BUFFALO, NY 14226**
0.210 mi.
1107 ft. **Site 9 of 9 in cluster BG**

Actual: EDR Hist Auto
597 ft.

Focus Map:
6

Year:	Name:	Type:
1973	NORTHTOWN TEXACO SERVICE	Gasoline Service Stations
1974	NORTHTOWN TEXACO SERVICE	Gasoline Service Stations
1975	NORTHTOWN TEXACO SERVICE	Gasoline Service Stations
1976	NORTHTOWN TEXACO SERVICE	Gasoline Service Stations
1977	NORTHTOWN TEXACO SERVICE	Gasoline Service Stations
1978	NORTHTOWN TEXACO SERVICE	Gasoline Service Stations
1979	NORTHTOWN TEXACO SERVICE	Gasoline Service Stations

---

308 **JOAN MILLEY TANK** **NY LTANKS** **S102234147**
West **45 CONANT STREET** **N/A**
1/8-1/4 **TONAWANDA, NY**
0.210 mi.
1110 ft.

Actual: LTANKS:
599 ft.

Focus Map:
8

Spill Number/Closed Date:	9601286 / 1996-05-01
Facility ID:	9601286
Site ID:	238945
Spill Date:	1996-04-01
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	1564
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	1996-04-24
CID:	266
Water Affected:	Not reported
Spill Notifier:	Citizen
Last Inspection:	1996-04-30
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-04-25
Spill Record Last Update:	1996-05-06
Spiller Name:	Not reported
Spiller Company:	JOAN MILLEY
Spiller Address:	45 CONANT STREET
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	(716) 835-4127
Spiller Extention:	Not reported
DEC Region:	9
DER Facility ID:	196665
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 04/30/96 RMC/MILLEY/SITE FUEL OIL TANK IN CRAWL SPACE, SUMP PUMP WITH IN 2 FEET OF TANK STONE STAINED IMMEDIATELY AROUND TANK, NO ODOR, DUG INTO SOIL AND FILL SEVERAL INCHES, NO ODOR OR VISUAL CONTAMINATION UNDERNEATH, NO ODOR OR SHEEN ON SUMP, DISCOLORATION

JOAN MILLEY TANK (Continued) **S102234147**

APPEARS TO BE FROM VERY OLD AND VERY MINOR SPILL YEARS AGO, NO SPILL ACTION REQUIRED, TANK BEING REMOVED BY LICENCED PLUMBER DURING VISIT. 05/01/96 RMC/GUARINO, PROSPECTIVE BUYER/PHONE RMC ADVISED OF FINDINGS AND GAVE NUMBER OF NYSDOH IF CONCERNED ABOUT ANY HEALTH IMPACTS, NO FURTHER ACTION REQUIRED, CLOSE OUT "

Remarks: "WHILE INSPECTING HOME FOR CLOSING OF SALE AGREEMENT, PERSPECTIVE BUYERS (MR. & MRS. GUARDINO) DISCOVERED A LEAKING ABANDONED FUEL OIL TANK IN CRAWL SPACE BENEATH THE HOUSE."

All Materials:

Site ID:	238945
Operable Unit ID:	1028921
Operable Unit:	01
Material ID:	351098
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

---

309 West 1/8-1/4 0.212 mi. 1120 ft.

Actual: 599 ft.

Focus Map: 8

FURMAN RESIDENCE
99 CONANT AVENUE
TONAWANDA, NY

NY LTANKS **S100879290**
N/A

LTANKS:

Spill Number/Closed Date:	9313777 / 1996-05-28
Facility ID:	9313777
Site ID:	194382
Spill Date:	1994-02-22
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	1564
Investigator:	SORGI
Referred To:	Not reported
Reported to Dept:	1994-02-22
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1994-02-24
Spill Record Last Update:	1996-07-22
Spiller Name:	Not reported
Spiller Company:	NORMAN FURMAN
Spiller Address:	99 CONANT AVENUE
Spiller County:	001
Spiller Contact:	Not reported

FURMAN RESIDENCE (Continued) **S100879290**

Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 9
DER Facility ID: 161986
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was MJS 02/22/94: MJS/SITE - TANK LAYS FLAT ON SIDE IN SMALL CRAWL SPACE. PRODUCT IS PUDDLED IN IMMEDIATE AREA (6' X 10'). GRAVEL APPEARS SATURATED. 02/22/94: MJS/MRS. MILLER (DAUGHTER)/TELECON -INFORMED HER THAT SPILL MUST BE CLEANED UP. SHE WILL CALL THE FURMAN'S INSURANCE COMPANY ON 2/23/94. SHE STATES THAT ODOR HAS BEEN PRESENT FOR MONTHS. 02/22/94: MJS/JIM VREELAND, EP & S/SITE - INSURANCE REP. VISITED HOME TODAY. FEELS THAT CURRENT POLICY DOESN'T COVER INCIDENT. 02/28/94: MJS/JIM VREELAND, DAVE COULTER, EP & S/SITE - WORK TO BEGIN 3/1/94. EP & S WILL USE MINI VAC TRUCK TO REMOVE PRODUCT & WATER. SVE BLOWER WILL BE USED TO MITIGATE VAPORS FROM RESIDUAL CONTAMINATION. 03/01/94: MJS/DAVE COULTER/SITE - FREE LIQUIDS ARE VACCED OUT. EP & S DIGGING DEPRESSION IN CENTER OF CRAWLSPACE. WILL USE BIO T MAX ON OILY GRAVEL AND FLUSH TO SUMP W/WATER. TANK TO BE DISPOSED OF. 03/01/94: MJS/SKIP EVANS/TELECON - OBTAINED PERMISSION TO DECANT WATER FROM VAC TRUCK TO SANITARY SEWER. MJS/ROGER HAAS (TON. SEWER)/TELECON - HE WILL SEND TOWN EMPLOYEE TO SPILL SITE TO LOCATE MANHOLE. 03/01/94: MJS/TOWN EMPLOYEE/SITE - HE WILL MARK OFF SANITARY MANHOLE ON CHOLMERS ST. FOR DECANTING OF WATER. EP & S WILL RINSE GRAVEL W/WATER AND COLLECT LIQUIDS FROM DEPRESSION. 03/02/94: MJS/SITE - EP & S ON-SITE INSTALLING STEPS AND VENT SYSTEM. DECANTING WILL TAKE PLACE IN P.M. 03/15/94: REJECTED PAY-PACK FROM EPS. MR COULTER CANNOT BE BILLED AS A GOELOGIST. 05/16/94: RECEIVED ADJUSTED PAY-PACK FROM EPS. MJS REVIEW FILE. NEED FINAL INSPECTION FOR CLOSURE OF FILE. 05/18/94: RESPONSIBILITY LETTER TO RP. 03/ /96: MJS TELECON WITH AG'S OFFICE. THEY ARE LOOKING AT OLD FILES FOR REIMBURSEMENT. THEY REQUEST FILE BE CLOSED IF POSSIBLE. 05/28/96: MJS REVIEW FILE. NO FURTHER ACTION REQUIRED. MJS CLOSE FILE. 12/05/96: MJS TELECON FROM SHARON SCHMIDT(AG'S OFFICE). SHE NEEDS COPY OF FINAL ISR...MJS FAXED COPY TO S. SCHMIDT."
Remarks: "A/G TANK IN CRAWL SPACE LEAKING HOME HEATING OIL."

All Materials:
Site ID: 194382
Operable Unit ID: 992228
Operable Unit: 01
Material ID: 389147
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

310
North
1/8-1/4
0.214 mi.
1128 ft.

GOVERNORS HALL AT UNIV OF BUFFALO
WHITE AND HADLEY RD
BUFFALO, NY

NY Spills **S122480414**
N/A

Actual:
582 ft.

Focus Map:
4

SPILLS:

Spill Number/Closed Date:	1803562 / 2018-07-02
Facility ID:	1803562
Facility Type:	ER
DER Facility ID:	525272
Site ID:	572221
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	1502
Spill Date:	2018-07-02
Investigator:	FXGALLEG
Referred To:	Not reported
Reported to Dept:	2018-07-02
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2018-07-02
Spill Record Last Update:	2018-07-02
Spiller Name:	Not reported
Spiller Company:	UNKNOWN - FROM RENTAL MACHINE
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	JOSH BLASKO
DEC Memo:	"7/2/18 The 4 gallons of diesel fuel spilled has been cleaned up and is disposed through the Oneida Co who is an abatement company. No further action is necessary. Closed."
Remarks:	"cleanup in progress"

All Materials:

Site ID:	572221
Operable Unit ID:	1320036
Operable Unit:	01
Material ID:	2328063
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	4.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

311
East
1/8-1/4
0.215 mi.
1134 ft.

NATIONAL FUEL GAS CO REG STA AM RM 60D
104 LONGMEADOW AVE
AMHERST, NY 14226

RCRA NonGen / NLR
FINDS
ECHO

1000274224
NYD982791014

Actual:
601 ft.

Focus Map:
6

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	NATIONAL FUEL GAS CO REG STA AM RM 60D
Facility address:	104 LONGMEADOW AVE AMHERST, NY 14226
EPA ID:	NYD982791014
Mailing address:	MILITARY RD TONAWANDA, NY 14150
Contact:	RICHARD FIORELLA
Contact address:	MILITARY RD TONAWANDA, NY 14150
Contact country:	US
Contact telephone:	716-692-6660
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	NATIONA FUEL GAS CO
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	NATIONA FUEL GAS CO
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No

NATIONAL FUEL GAS CO REG STA AM RM 60D (Continued) **1000274224**

On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: NATIONAL FUEL GAS CO REG STA AM RM 60D
Classification: Not a generator, verified

Date form received by agency: 10/20/1989
Site name: NATIONAL FUEL GAS CO REG STA AM RM 60D
Classification: Not a generator, verified

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: X002
. Waste name: POLYCHLORINATED BIPHENOLS (PCBs)

Violation Status: No violations found

FINDS:

Registry ID: 110004433649

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000274224
Registry ID: 110004433649
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004433649

312
East
1/8-1/4
0.216 mi.
1139 ft.

NATIONAL GRID TRANSFORMER
38 PARTRIDGE RUN
AMHERST, NY

NY LTANKS **S116156747**
N/A

Actual:
582 ft.

Focus Map:
2

LTANKS:

Spill Number/Closed Date:	1308736 / 2014-05-02
Facility ID:	1308736
Site ID:	489491
Spill Date:	2013-11-28
Spill Cause:	Tank Test Failure
Spill Source:	Transformer
Spill Class:	D3
Cleanup Ceased:	Not reported
SWIS:	1522
Investigator:	SACALAND
Referred To:	Not reported
Reported to Dept:	2013-11-28
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2013-11-28
Spill Record Last Update:	2014-05-02
Spiller Name:	LISA MONTESANO
Spiller Company:	NATIONAL GRID
Spiller Address:	144 KENSINGTON AVENUE
Spiller County:	999
Spiller Contact:	LISA MONTESANO
Spiller Phone:	(716) 831-7309
Spiller Extention:	Not reported
DEC Region:	9
DER Facility ID:	444591
DEC Memo:	"11/29/13:SAC TELECON LISA MONTESANO - NATIONAL GRID. MS. MONTESANO SAID THEY ARE GOING TO ANALYZE THE PRODUCT FOR PCB CONCENTRATION. SMALL AMOUNT OF PRODUCT GOT ONTO THE WATER BELOW THE PAD. 4/15/14:RECEIVED COPY OF THE ANALYTICAL RESULTS FOR THE PRODUCT AND THE NON-HAZARDOUS WASTE MANIFEST FOR THE DISPOSAL OF THE CONTAMINATED MATERIAL. THE RESULTS WERE NON-DETECT FOR PCBs. 5/2/14:SAC REVIEW FILE. CLEAN UP COMPLETED AND ALL DOCUMENTATION HAS BEEN RECEIVED. NO FURTHER WORK IS REQUIRED. NO PAPER FILE."
Remarks:	"transformer run over by private vehicle, c/u pending"

All Materials:

Site ID:	489491
Operable Unit ID:	1239069
Operable Unit:	01
Material ID:	2239036
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.25
Units:	G
Recovered:	Not reported

NATIONAL GRID TRANSFORMER (Continued) **S116156747**

Oxygenate: Not reported

BI313 **AMHERST CSD - WINDERMERE BLVD ELEMENTARY SCHOOL** **FINDS** **1017400802**
East **291 WINDERMERE BLVD** **ECHO** **N/A**
1/8-1/4 **AMHERST, NY 14226**
0.218 mi.
1150 ft. **Site 1 of 3 in cluster BI**

Actual:
608 ft.

Focus Map:
8

FINDS:

Registry ID: 110063000782

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid: 1017400802
Registry ID: 110063000782
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110063000782

BI314 **WINDERMERE BLVD SCHOOL** **NY LTANKS** **U003317493**
East **291 WINDERMERE BLVD** **NY UST** **N/A**
1/8-1/4 **AMHERST, NY 14226**
0.218 mi.
1150 ft. **Site 2 of 3 in cluster BI**

Actual:
608 ft.

Focus Map:
8

LTANKS:

Spill Number/Closed Date: 9100547 / 1992-03-23
Facility ID: 9100547
Site ID: 235642
Spill Date: 1991-04-15
Spill Cause: Tank Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: Not reported
Cleanup Ceased: 1992-03-23
SWIS: 1522
Investigator: SORGI
Referred To: Not reported
Reported to Dept: 1991-04-15
CID: Not reported
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: 1992-05-02
Recommended Penalty: False
Meets Standard: True
UST Involvement: False

WINDERMERE BLVD SCHOOL (Continued) **U003317493**

Remediation Phase:	0
Date Entered In Computer:	1991-04-15
Spill Record Last Update:	1992-03-23
Spiller Name:	Not reported
Spiller Company:	AMHERST CENTRAL SCHOOL
Spiller Address:	55 KINGS HIGHWAY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	9
DER Facility ID:	194092
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MJS 04/12/91: INVESTIGATION FOUND CRACKED STEEL VENT PIPE BELOW GRADE. HAVE EXCAVATED AND REPLACED PIPE. WILL EXCAVATE AND DISPOSE OF CONTAMINATED SOIL. HAVE CLEANED BASEMENT WITH SPEEDY DRY. 04/16/91: MJS SITE INSPECTION. OIL SEEPED INTO AULT ADJACENT TO TANK. GOT INTO SUMP IN BASEMENT. SCHOOL TO GET STEAM WASHER TO CLEAN SUMP AND AND PUMP ROOM. SCHOOL TO DECIDE WHETHER TANK TO BE REMOVED OR FILLED. 04/19/91: MJS SITE INSPECTION. SUMP IN BASEMENT HAS BEEN CLEANED AND IS FREE OF OIL-PUMP ROOM ALSO CLEANED. MORE CONTAMINATED SOIL FOUND IN EXCAVATION. ELMWOOD TANK TO PUMP OUT EXC AND DIG OUT SOIL. 04/24/91: MJS TELECON WITH JAMES GRUSKA. TANK TO BE TEMPORARILY CLOSED UNTIL DECISION IS MADE BY SCHOOL BOARD. JOB HAS TO BE BID. 04/26/91: LETTER TO JAMES GRUSKA. 05/02/91: MJS SITE INSPECTION. EVERYTHING HAS BEEN CLEANED UP. GAVE O.K. TO BACKFILL EXCAVATION. SAMPLING HAS BEEN DONE. WAITING FOR RESULTS AND DISPOSAL OF SOIL. 05/07/91: MJS RECEIVED INCIDENT REPORT AND SCHEMATIC OF TANK SYSTEM FROM JAMES GRUSKA. 03/17/92: DISPOSAL RECEIPT LETTER TO MR GRUSKA. 03/18/92: MJS TELECON WITH JAMES GRUSKA. HE HAS RECEIVED LETTER AND WILL FORWARD ANALYTICAL RESULTS AND DISPOSAL MANIFEST. 03/23/92: RECEIVED DISPOSAL PAPERWORK FOR CONTAMINATED SOIL. NO FURTHER WORK NECESSARY. FILE TO BE CLOSED. "
Remarks:	"OIL SEEPED INTO BASEMENT THROUGH VAULT WINDOW WITH RAINWATER RUNOFF ONTO CONCRETE FLOOR WITH DRAINS AND SUMP PUMP. SUMP PUMP MAY HAVE DISCHARGE TO SEWER."

All Materials:

Site ID:	235642
Operable Unit ID:	951549
Operable Unit:	01
Material ID:	426734
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

UST:

Id/Status:	9-385778 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	9

WINDERMERE BLVD SCHOOL (Continued) **U003317493**

Expiration Date: N/A
UTM X: 188619.36220
UTM Y: 4764012.48586
Site Type: School

Affiliation Records:

Site Id: 53677
Affiliation Type: Facility Owner
Company Name: AMHERST CENTRAL SCHOOLS
Contact Type: Not reported
Contact Name: Not reported
Address1: 55 KINGS HIGHWAY
Address2: Not reported
City: AMHERST
State: NY
Zip Code: 14226
Country Code: 001
Phone: (716) 836-3000
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 53677
Affiliation Type: Mail Contact
Company Name: AMHERST CENTRAL SCHOOLS
Contact Type: Not reported
Contact Name: JAMES R. GRUSZKA
Address1: 4301 MAIN STREET
Address2: Not reported
City: AMHERST
State: NY
Zip Code: 14226
Country Code: 001
Phone: (716) 836-3000
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 53677
Affiliation Type: Facility Operator
Company Name: WINDERMERE BLVD SCHOOL
Contact Type: Not reported
Contact Name: MARK MOYNIHAN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (716) 836-3000
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 53677

WINDERMERE BLVD SCHOOL (Continued) **U003317493**

Affiliation Type:	Emergency Contact
Company Name:	AMHERST CENTRAL SCHOOLS
Contact Type:	Not reported
Contact Name:	JAMES R. GRUSZKA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(716) 626-0344
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	003
Tank ID:	169659
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	15000
Install Date:	12/01/1986
Date Tank Closed:	07/21/2000
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

G99 - Tank Secondary Containment - Other
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I04 - Overfill - Product Level Gauge (A/G)
F06 - Pipe External Protection - Wrapped
C02 - Pipe Location - Underground/On-ground
H04 - Tank Leak Detection - Groundwater Well
B02 - Tank External Protection - Original Sacrificial Anode

BI315 **AMHERST CSD - WINDERMERE BLVD ELEMENTARY SCHOOL** **RCRA-CESQG** **1016974961**
East **291 WINDERMERE BLVD** **NYR000214213**
1/8-1/4 **AMHERST, NY 14226**
0.218 mi.
1150 ft. **Site 3 of 3 in cluster BI**

Actual:
608 ft.

Focus Map:
8

RCRA-CESQG:

Date form received by agency:	10/22/2014
Facility name:	AMHERST CSD - WINDERMERE BLVD ELEMENTARY SCHOOL
Facility address:	291 WINDERMERE BLVD AMHERST, NY 14226
EPA ID:	NYR000214213
Mailing address:	WINDERMERE BLVD AMHERST, NY 14226
Contact:	MICHAEL A TOMCZAK
Contact address:	WINDERMERE BLVD AMHERST, NY 14226
Contact country:	US
Contact telephone:	716-362-8151
Contact email:	MTOMCZAK@AMHERSTSCHOOLS.ORG
EPA Region:	02
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	AMHERST CENTRAL SCHOOLS
Owner/operator address:	KINGS HWY AMHERST, NY 14226
Owner/operator country:	US
Owner/operator telephone:	716-362-3000
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Municipal
Owner/Operator Type:	Owner
Owner/Op start date:	08/22/1960
Owner/Op end date:	Not reported
Owner/operator name:	MICHAEL TOMCZAK
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported

AMHERST CSD - WINDERMERE BLVD ELEMENTARY SCHOOL (Continued) **1016974961**

Legal status: Municipal
Owner/Operator Type: Operator
Owner/Op start date: 10/01/2008
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: B005
. Waste name: B005

Violation Status: No violations found

316
West
1/8-1/4
0.218 mi.
1150 ft.

NATIONAL GRID POLE 2328R
2352 EGGERT RD
TONAWANDA, NY 14150

NY Spills **S122877470**
N/A

Actual:
594 ft.

Focus Map:
6

SPILLS:
Spill Number/Closed Date: 1806439 / Not Reported
Facility ID: 1806439
Facility Type: ER
DER Facility ID: 530032
Site ID: 577166
DEC Region: 9
Spill Cause: Equipment Failure
Spill Class: D4
SWIS: 1564
Spill Date: 2018-09-14
Investigator: SACALAND
Referred To: Not reported
Reported to Dept: 2018-09-14
CID: Not reported
Water Affected: Not reported
Spill Source: Transformer
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: Not reported
UST Trust: False
Remediation Phase: 1
Date Entered In Computer: 2018-09-14

NATIONAL GRID POLE 2328R (Continued) **S122877470**

Spill Record Last Update:	2018-09-17
Spiller Name:	LISA MONTESANO
Spiller Company:	NATIONAL GRID
Spiller Address:	144 KENSINGTON AVENUE
Spiller Company:	999
Contact Name:	LISA MONTESANO
DEC Memo:	"9/15/18:RECEIVED MESSAGE FROM LISA MONTESANO - NATIONAL GRID. MS. MONTESANO SAID THE INITIAL REPORT FROM THE SITE IS THE PRODUCT IS NON-PCB. THEY WILL BE FOLLOWING UP ON MONDAY, 9/17."
Remarks:	"c/u pending"

All Materials:

Site ID:	577166
Operable Unit ID:	1324942
Operable Unit:	01
Material ID:	2333449
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

BJ317 **BALL PUMP STATION** **NY LTANKS S100494398**
NNW **SWEET HOME ROAD** **NY Spills N/A**
1/8-1/4 **AMHERST, NY**
0.218 mi.
1151 ft. **Site 1 of 12 in cluster BJ**

Actual:
580 ft.

Focus Map:
4

LTANKS:

Spill Number/Closed Date:	9209938 / 1993-02-03
Facility ID:	9209938
Site ID:	149088
Spill Date:	1992-11-20
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	D4
Cleanup Ceased:	1993-02-03
SWIS:	1522
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	1992-11-24
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1992-11-27
Spill Record Last Update:	1993-02-08
Spiller Name:	Not reported
Spiller Company:	ERIE COUNTY WATER AUTHOR.
Spiller Address:	ELLICOTT SQUARE BLDG.

BALL PUMP STATION (Continued) **S100494398**

Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 9
DER Facility ID: 58607
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 11/25/92: RMC/PATRICK MARTIN/PHONE - TANK NOT YET REMOVED; PROJECT BELOW FOUNDATION. BORING B-12 OVER GUIDANCE. PLAN TO RETEST ON TCLP BASIS. 02/03/93: RMC/REVIEWED SAMPLE RESULTS, OK TANK FILLED WITH SAND....CLOSE OUT. "
Remarks: "SOIL CONTAMINATION."

All Materials:
Site ID: 149088
Operable Unit ID: 976428
Operable Unit: 01
Material ID: 406965
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Not reported
Recovered: .00
Oxygenate: Not reported

SPILLS:
Spill Number/Closed Date: 0375269 / 2003-11-03
Facility ID: 0375269
Facility Type: ER
DER Facility ID: 58607
Site ID: 149087
DEC Region: 9
Spill Cause: Equipment Failure
Spill Class: C3
SWIS: 1522
Spill Date: 2003-08-26
Investigator: RJJONAK
Referred To: Not reported
Reported to Dept: 2003-08-26
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial Vehicle
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: 2003-08-26
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2003-08-26
Spill Record Last Update: 2003-11-03
Spiller Name: MIKE
Spiller Company: COMMERCIAL SUPPLY
Spiller Address: 1300 PERRY STREET

BALL PUMP STATION (Continued) **S100494398**

Spiller Company: 001
Contact Name: MIKE
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was RJJ 8/26/2003: RJJ AT SITE AT 1300...A COMMERCIAL SUPPLY TRUCK BROKE A HYDRAULIC HOSE,SPILLING ABOUT 10 GAL OF HYDRAULIC OIL ALL ON THE BLACKTOP DRIVEWAY,IN FRONT OF SWEETHOME HIGH SCHOOL...THEY SPREAD SPEEDY-DRY AND PLACED ABSORBANT BOOMS TO CONTAIN THE OIL...NONE OF THE OIL REACHED ANY RECEIVERS...COMMERCIAL SUPPLY CO. WILL HIRE AN ENVIRONMENTAL FIRM AND HAVE THE MATERIAL DISPOSED OF AND SEND ME THE RECEIPTS. 10/8/2003: MIKE,COMMERCIAL SUPPLY,TELECON RJJ,SAID THAT OP-TECH HAS PICKED UP THE DRUM AND WILL SEND ME THE DISPOSAL RECEIPTS. 11/3/2003: RECEIVED A COPY OF THE DISPOSAL RECEIPTS FOR THE 2 DRUMS OF MATERIAL PICKED UP BY OP-TECH AND TAKEN TO CYCLE CHEM FOR DISPOSAL...THE SPILL HAS BEEN CLEANED UP AND PROPERLY DISPOSED OF...NO FURTHER ACTION NEEDED...SPILL CLOSED OUT."
Remarks: "HYDRAULIC LINE RUPTURED ON BOOM TRUCK SPILLING HYDRAULIC OIL TO BLACKTOP. PUTTING CLEANUP DEBRIS IN RUBBERMAID TRASH CANS."

All Materials:
Site ID: 149087
Operable Unit ID: 882186
Operable Unit: 01
Material ID: 494464
Material Code: 0010
Material Name: hydraulic oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 10.00
Units: G
Recovered: 10.00
Oxygenate: Not reported

BJ318 **AMHERST CUSTOM CHEMICALS INC** **RCRA NonGen / NLR** **1007371358**
NNW **1576 SWEET HOME RD - 2ND FLOOR** **NYR000124230**
1/8-1/4 **AMHERST, NY 14228**
0.219 mi.
1154 ft. **Site 2 of 12 in cluster BJ**

Actual: **580 ft.**

Focus Map: **4**

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: AMHERST CUSTOM CHEMICALS INC
Facility address: 1576 SWEET HOME RD - 2ND FLOOR
BAIRD RESEARCH PARK
AMHERST, NY 14228
EPA ID: NYR000124230
Mailing address: SWEET HOME RD - 2ND FLOOR
BAIRD RESEARCH PARK
AMHERST, NY 14228
Contact: DELONG ZHANG
Contact address: SWEET HOME RD - 2ND FLOOR BAIRD RESEARCH PARK
AMHERST, NY 14228
Contact country: US
Contact telephone: 716-774-8198
Contact email: DELONG_ZHANG@YAHOO.COM
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

AMHERST CUSTOM CHEMICALS INC (Continued) **1007371358**

Owner/Operator Summary:
Owner/operator name: NO NAME FOUND
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 08/01/1988
Owner/Op end date: Not reported

Owner/operator name: UNIVERSITY AT BUFFALO FOUNDATION INC
Owner/operator address: PO BOX 900 - CTR FOR TOMORROW UNIVERSITY OF BUFFALO
NEW YORK, NY 14226
Owner/operator country: US
Owner/operator telephone: 716-774-8198
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 08/01/1988
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: AMHERST CUSTOM CHEMICALS INC
Classification: Not a generator, verified

Date form received by agency: 03/08/2004
Site name: AMHERST CUSTOM CHEMICALS INC
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS

AMHERST CUSTOM CHEMICALS INC (Continued) **1007371358**

CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D003
. Waste name: A MATERIAL IS CONSIDERED TO BE A REACTIVE HAZARDOUS WASTE IF IT IS NORMALLY UNSTABLE, REACTS VIOLENTLY WITH WATER, GENERATES TOXIC GASES WHEN EXPOSED TO WATER OR CORROSIVE MATERIALS, OR IF IT IS CAPABLE OF DETONATION OR EXPLOSION WHEN EXPOSED TO HEAT OR A FLAME. ONE EXAMPLE OF SUCH WASTE WOULD BY WASTE GUNPOWDER.

. Waste code: D004
. Waste name: ARSENIC

. Waste code: D005
. Waste name: BARIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D011
. Waste name: SILVER

. Waste code: D019
. Waste name: CARBON TETRACHLORIDE

. Waste code: D021
. Waste name: CHLOROBENZENE

. Waste code: D022
. Waste name: CHLOROFORM

. Waste code: D036
. Waste name: NITROBENZENE

. Waste code: D038
. Waste name: PYRIDINE

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING:

AMHERST CUSTOM CHEMICALS INC (Continued) **1007371358**

TETRACHLOROETHYLENE, TRICHLOROETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE, AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F004
. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: CRESOLS AND CRESYLIC ACID, AND NITROBENZENE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

BJ319 **ONY BIOTECH** **FINDS** **1007814954**
NNW **1576 SWEET HOME ROAD** **ECHO** **N/A**
1/8-1/4 **AMHERST, NY 14228**
0.219 mi.
1154 ft. **Site 3 of 12 in cluster BJ**

Actual:
580 ft.

FINDS:

Focus Map:
4

Registry ID: 110019775037

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid: 1007814954
Registry ID: 110019775037
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110019775037

BJ320 **AMHERST CUSTOM CHEMICALS INC** **FINDS** **1007457671**
NNW **1576 SWEET HOME RD - 2ND FLOOR** **ECHO** **N/A**
1/8-1/4 **AMHERST, NY 14228**
0.219 mi.
1154 ft. **Site 4 of 12 in cluster BJ**

Actual:
580 ft.

FINDS:

Focus Map:
4

Registry ID: 110017776450

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid: 1007457671
Registry ID: 110017776450
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110017776450

BJ321 **NY COOLING TOWERS** **S121997912**
NNW **1576 SWEET HOME ROAD** **N/A**
1/8-1/4 **AMHERST, NY 14228**
0.219 mi.
1154 ft. **Site 5 of 12 in cluster BJ**

Actual: **580 ft.**

Focus Map: **4**

COOLING TOWERS:

Equipment Unique ID:	8488
Equipment Borough:	1576
Intended Use:	Other
Manufacturer:	BAC
Model:	VFL-722-MR
Cooling Capacity:	133
Cooling Capacity Unit:	Tonnage
Commissioned Date:	01/04/1999
Inspection Date:	05/08/2018
Date of Bacteriological Collection:	10/24/2017
Date of Legionella Collection:	05/08/2018
Last Legionella Result > 1,000 CFU/mL:	no
Latitude:	43.003302929
Longitude:	-78.798840599

BJ322 **FERRIC CONTRAST INC** **RCRA-CESQG** **1004762876**
NNW **1576 SWEET HOME RD ROOM 224** **FINDS** **NYR000101360**
1/8-1/4 **AMHERST, NY 14228** **NY MANIFEST**
0.219 mi.
1154 ft. **Site 6 of 12 in cluster BJ**

Actual: **580 ft.**

Focus Map: **4**

RCRA-CESQG:

Date form received by agency:	02/06/2018
Facility name:	FERRIC CONTRAST INC
Facility address:	1576 SWEET HOME RD ROOM 224 AMHERST, NY 14228
EPA ID:	NYR000101360
Mailing address:	SWEET HOME RD ROOM 224 AMHERST, NY 14228
Contact:	BRADFORD M LA SALLE
Contact address:	SWEET HOME RD ROOM 224 AMHERST, NY 14228
Contact country:	US
Contact telephone:	716-380-3170
Contact email:	BRADFORDLASALLE@FERRIC-CONTRAST.COM
EPA Region:	02
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

FERRIC CONTRAST INC (Continued) **1004762876**

Owner/Operator Summary:

Owner/operator name:	UB FOUNDATION INCUBATOR INC
Owner/operator address:	PO BOX 900
	BUFFALO, NY 14226
Owner/operator country:	US
Owner/operator telephone:	716-645-3011
Owner/operator email:	EDWARDSCHNEIDE@BUFFALO.EDU
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	State
Owner/Operator Type:	Owner
Owner/Op start date:	01/15/1982
Owner/Op end date:	Not reported

Owner/operator name:	AETHLON MEDICAL INC
Owner/operator address:	7825 FAY AVE ST 200
	LA JOLLA, CA 92037
Owner/operator country:	US
Owner/operator telephone:	858-456-5777
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	01/01/2001
Owner/Op end date:	Not reported

Owner/operator name:	AETHLON MEDICAL INC
Owner/operator address:	7825 FAY AVE ST 200
	LA JOLLA, CA 92037
Owner/operator country:	US
Owner/operator telephone:	858-456-5777
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	01/01/2001
Owner/Op end date:	Not reported

Owner/operator name:	FERRIC CONTRAST INC
Owner/operator address:	SWEET HOME RD ROOM 224
	AMHERST, NY 14228
Owner/operator country:	US
Owner/operator telephone:	716-630-3170
Owner/operator email:	BRADFORDLASALLE@FERRICCONTRAST.COM
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	02/01/2018
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No

FERRIC CONTRAST INC (Continued) **1004762876**

Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code: D022
. Waste name: CHLOROFORM

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: U002
. Waste name: ACETONE (I)

. Waste code: U003
. Waste name: ACETONITRILE (I,T)

. Waste code: U044
. Waste name: CHLOROFORM

. Waste code: U080
. Waste name: METHANE, DICHLORO-

. Waste code: U117
. Waste name: ETHANE, 1,1'-OXYBIS-(I)

. Waste code: U123
. Waste name: FORMIC ACID (C,T)

. Waste code: U154
. Waste name: METHANOL (I)

. Waste code: U213
. Waste name: FURAN, TETRAHYDRO-(I)

. Waste code: U220
. Waste name: BENZENE, METHYL-

FERRIC CONTRAST INC (Continued) **1004762876**

Historical Generators:
Date form received by agency: 01/01/2007
Site name: HEMEX INC
Classification: Not a generator, verified

Date form received by agency: 01/01/2006
Site name: HEMEX INC
Classification: Not a generator, verified

Date form received by agency: 10/02/2001
Site name: HEMEX INC
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D003
. Waste name: A MATERIAL IS CONSIDERED TO BE A REACTIVE HAZARDOUS WASTE IF IT IS NORMALLY UNSTABLE, REACTS VIOLENTLY WITH WATER, GENERATES TOXIC GASES WHEN EXPOSED TO WATER OR CORROSIVE MATERIALS, OR IF IT IS CAPABLE OF DETONATION OR EXPLOSION WHEN EXPOSED TO HEAT OR A FLAME. ONE EXAMPLE OF SUCH WASTE WOULD BY WASTE GUNPOWDER.

Violation Status: No violations found

FINDS:

Registry ID: 110012253211

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FERRIC CONTRAST INC (Continued) **1004762876**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

NY MANIFEST:

Country:	USA
EPA ID:	NYR000101360
Facility Status:	Not reported
Location Address 1:	1576 SWEET HOME RD
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	AMHERST
Location State:	NY
Location Zip:	14228
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000101360
Mailing Name:	HEMEX
Mailing Contact:	N/S
Mailing Address 1:	1576 SWEET HOME RD
Mailing Address 2:	Not reported
Mailing City:	BUFFALO
Mailing State:	NY
Mailing Zip:	14228
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7166362568

NY MANIFEST:

Document ID:	ARA1224623
Manifest Status:	Not reported
seq:	01
Year:	2001
Trans1 State ID:	H245
Trans2 State ID:	Not reported
Generator Ship Date:	11/15/2001
Trans1 Recv Date:	11/15/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/24/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000101360
Trans1 EPA ID:	NYD980769947
Trans2 EPA ID:	Not reported
TSDF ID 1:	ARD069748192
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported

FERRIC CONTRAST INC (Continued) **1004762876**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F003 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00040
Units:	P - Pounds
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00020
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00020
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00020
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00

Country:	USA
EPA ID:	NY0000075754
Facility Status:	Not reported
Location Address 1:	1576 SWEET HOME RD
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported

FERRIC CONTRAST INC (Continued) **1004762876**

Location City:	BUFFALO
Location State:	NY
Location Zip:	14228
Location Zip 4:	2710

NY MANIFEST:

EPAID:	NY0000075754
Mailing Name:	ONYBIOTECH
Mailing Contact:	WILLIAM FERGUSON
Mailing Address 1:	1576 SWEET HOME RD
Mailing Address 2:	Not reported
Mailing City:	BUFFALO
Mailing State:	NY
Mailing Zip:	14228
Mailing Zip 4:	2710
Mailing Country:	USA
Mailing Phone:	7164283115

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD097644801
Trans2 State ID:	NYD097644801
Generator Ship Date:	03/29/2018
Trans1 Recv Date:	03/29/2018
Trans2 Recv Date:	04/02/2018
TSD Site Recv Date:	04/03/2018
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000075754
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	MID980991566
TSDF ID 2:	Not reported
Manifest Tracking Number:	017625536JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	15
Units:	P - Pounds
Number of Containers:	1

FERRIC CONTRAST INC (Continued) **1004762876**

Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D001
Waste Code 1_2:	D002
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
18 additional NY MANIFEST: record(s) in the EDR Site Report.

BJ323 **UNIVERSITY AT BUFFALO TECHNOLOGY INCUB** **RCRA NonGen / NLR** **1004762828**
NNW **1576 SWEET HOME RD** **FINDS** **NYR000100883**
1/8-1/4 **AMHERST, NY 14228** **ECHO**
0.219 mi.
1154 ft. **Site 7 of 12 in cluster BJ**

Actual:
580 ft.

Focus Map:
4

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	UNIVERSITY AT BUFFALO TECHNOLOGY INCUB
Facility address:	1576 SWEET HOME RD AMHERST, NY 14228
EPA ID:	NYR000100883
Mailing address:	SWEET HOME RD AMHERST, NY 14228
Contact:	KENNETH TARBOX
Contact address:	SWEET HOME RD AMHERST, NY 14228
Contact country:	US
Contact telephone:	716-636-3626
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	UNIVERSITY BUFFALO FOUND INCUBATOR
Owner/operator address:	PO BOX 900 BUFFALO, NY 14226
Owner/operator country:	US
Owner/operator telephone:	716-645-3013
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	01/01/2001
Owner/Op end date:	Not reported

Owner/operator name:	UNIVERSITY BUFFALO FOUND INCUBATOR
Owner/operator address:	PO BOX 900 BUFFALO, NY 14226
Owner/operator country:	US
Owner/operator telephone:	716-645-3013

UNIVERSITY AT BUFFALO TECHNOLOGY INCUB (Continued) **1004762828**

Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: UNIVERSITY AT BUFFALO TECHNOLOGY INCUB
Classification: Not a generator, verified

Date form received by agency: 09/06/2001
Site name: UNIVERSITY AT BUFFALO TECHNOLOGY INCUB
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D003
. Waste name: A MATERIAL IS CONSIDERED TO BE A REACTIVE HAZARDOUS WASTE IF IT IS NORMALLY UNSTABLE, REACTS VIOLENTLY WITH WATER, GENERATES TOXIC GASES WHEN EXPOSED TO WATER OR CORROSIVE MATERIALS, OR IF IT IS CAPABLE OF

UNIVERSITY AT BUFFALO TECHNOLOGY INCUB (Continued) **1004762828**

DETONATION OR EXPLOSION WHEN EXPOSED TO HEAT OR A FLAME. ONE EXAMPLE OF SUCH WASTE WOULD BY WASTE GUNPOWDER.

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D011
. Waste name: SILVER

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

FINDS:

Registry ID: 110012241911

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

UNIVERSITY AT BUFFALO TECHNOLOGY INCUB (Continued) **1004762828**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
- Envid: 1004762828
- Registry ID: 110012241911
- DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110012241911

BJ324 **FERRIC CONTRAST INC** **ECHO** **1024115290**
NNW **1576 SWEET HOME RD ROOM 224** **N/A**
1/8-1/4 **AMHERST, NY 14228**
0.219 mi.
1154 ft. **Site 8 of 12 in cluster BJ**

Actual:
580 ft.

Focus Map:
4

ECHO:
- Envid: 1024115290
- Registry ID: 110012253211
- DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110012253211

BJ325 **LASER PHOTONICS TECHNOLOGY INC** **RCRA NonGen / NLR** **1004760658**
NNW **1576 SWEET HOME RD ROOM 221** **FINDS** **NYR000054650**
1/8-1/4 **AMHERST, NY 14228** **ECHO**
0.219 mi. **NY MANIFEST**
1154 ft. **Site 9 of 12 in cluster BJ**

Actual:
580 ft.

Focus Map:
4

RCRA NonGen / NLR:
- Date form received by agency: 01/01/2007
- Facility name: LASER PHOTONICS TECHNOLOGY INC
- Facility address: 1576 SWEET HOME RD ROOM 221
AMHERST, NY 14228
- EPA ID: NYR000054650
- Mailing address: SWEET HOME RD ROOM 221
AMHERST, NY 14228
- Contact: MARTIN CASSTEVENS
- Contact address: SWEET HOME RD ROOM 221
AMHERST, NY 14228
- Contact country: US
- Contact telephone: 716-688-8251
- Contact email: Not reported
- EPA Region: 02
- Land type: Private
- Classification: Non-Generator
- Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
- Owner/operator name: PARAS N PRASAD
- Owner/operator address: 51 WATER RD
AMHERST, NY 14221
- Owner/operator country: US
- Owner/operator telephone: 716-839-9514
- Owner/operator email: Not reported
- Owner/operator fax: Not reported
- Owner/operator extension: Not reported
- Legal status: Private

LASER PHOTONICS TECHNOLOGY INC (Continued) **1004760658**

Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: PARAS N PRASAD
Owner/operator address: 51 WATER RD
AMHERST, NY 14221
Owner/operator country: US
Owner/operator telephone: 716-839-9514
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: LASER PHOTONICS TECHNOLOGY INC
Classification: Not a generator, verified

Date form received by agency: 05/08/1998
Site name: LASER PHOTONICS TECHNOLOGY INC
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT

LASER PHOTONICS TECHNOLOGY INC (Continued) **1004760658**

MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 03/23/2011
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110004543101

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004760658
Registry ID: 110004543101
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004543101

NY MANIFEST:
Country: USA
EPA ID: NYR000054650
Facility Status: Not reported
Location Address 1: 1576 SWEET HOME RD
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: AMHERST
Location State: NY
Location Zip: 14228
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000054650
Mailing Name: LASER PHOTONICS TECHNOLOGY INC
Mailing Contact: MARTIN CASSTEVENS
Mailing Address 1: 1576 SWEET HOME RD
Mailing Address 2: Not reported

LASER PHOTONICS TECHNOLOGY INC (Continued) **1004760658**

Mailing City:	AMHERST
Mailing State:	NY
Mailing Zip:	14228
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7166888251

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2011
Trans1 State ID:	MI0000263871
Trans2 State ID:	MI0000263871
Generator Ship Date:	08/24/2011
Trans1 Recv Date:	08/24/2011
Trans2 Recv Date:	09/02/2011
TSD Site Recv Date:	09/15/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000054650
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD048415665
TSDF ID 2:	Not reported
Manifest Tracking Number:	006758307JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Waste Code:	U138
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

LASER PHOTONICS TECHNOLOGY INC (Continued) **1004760658**

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

BJ326 **DIMIEN LLC** **RCRA-CESQG** **1000458422**
NNW **1576 SWEET HOME RD SUITE 222** **FINDS** **NYD986938140**
1/8-1/4 **AMHERST, NY 14228** **ECHO**
0.219 mi.
1154 ft. **Site 10 of 12 in cluster BJ**

Actual:
580 ft.

Focus Map:
4

RCRA-CESQG:

Date form received by agency:	05/05/2014
Facility name:	DIMIEN LLC
Facility address:	1576 SWEET HOME RD SUITE 222 AMHERST, NY 14228
EPA ID:	NYD986938140
Mailing address:	SWEET HOME RD SUITE 230A AMHERST, NY 14228
Contact:	BRIAN J SCHULTZ
Contact address:	SWEET HOME RD SUITE 230A AMHERST, NY 14228
Contact country:	US
Contact telephone:	585-260-1030
Contact email:	BSCHULTZ@DIMIEN.COM
EPA Region:	02
Land type:	State
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	UNIVERSITY BUFFALO FOUNDATION INCUBATOR
Owner/operator address:	PO BOX 900 BUFFALO, NY 14226
Owner/operator country:	US
Owner/operator telephone:	716-645-3013
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	State
Owner/Operator Type:	Owner
Owner/Op start date:	11/19/1997
Owner/Op end date:	Not reported
Owner/operator name:	DIMIEN LLC
Owner/operator address:	Not reported

DIMIEN LLC (Continued) **1000458422**

Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 05/01/2014
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: P120
. Waste name: VANADIUM OXIDE V2O5

. Waste code: U002
. Waste name: ACETONE (I)

. Waste code: U154
. Waste name: METHANOL (I)

Historical Generators:
Date form received by agency: 01/01/2007
Site name: RECRA ENVIRONMENTAL INC
Classification: Not a generator, verified

Date form received by agency: 01/01/2006
Site name: RECRA ENVIRONMENTAL INC

DIMIEN LLC (Continued) **1000458422**

Classification: Not a generator, verified

Date form received by agency: 03/22/1995
Site name: RECRA ENVIRONMENTAL INC
Classification: Unverified

. Waste code: NONE
. Waste name: None

Date form received by agency: 01/29/1991
Site name: RECRA ENVIRONMENTAL INC
Classification: Small Quantity Generator

. Waste code: NONE
. Waste name: None

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 10/05/1995
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110004459504

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000458422
Registry ID: 110004459504
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004459504

BJ327 **ONY INC** **NY AIRS** **S121492786**
NNW **1576 SWEET HOME ROAD** **N/A**
1/8-1/4 **AMHERST, NY 14228**
0.219 mi.
1154 ft. **Site 11 of 12 in cluster BJ**

Actual:
580 ft.

Focus Map:
4

AIRS:
Permit Type: AFR
Permit Status: Issued
Issue Date: 05/04/1999
Expiration Date: Not reported

ONY INC (Continued) **S121492786**

County Fips:	Not reported
DEC Id:	9142200207
Emission Unit Id:	Not reported
Process Id:	Not reported
Contaminant Name/cas:	Not reported
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	Not reported
Unit:	Not reported
Auth Type Code:	2
Latitude:	Not reported
Longitude:	Not reported

BJ328 **SQUIRREL FREE INCORPORATED** **FINDS** **1004567795**
NNW **1576 SWEET HOME ROAD** **N/A**
1/8-1/4 **AMHERST, NY 14228**
0.219 mi.
1154 ft. **Site 12 of 12 in cluster BJ**

Actual:
580 ft.

FINDS:

Focus Map:
4

Registry ID: 110011484429

Environmental Interest/Information System
NCDB (National Compliance Data Base) supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act (TSCA). The system tracks inspections in regions and states with cooperative agreements, enforcement actions, and settlements.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

---

329 **HOUSE** **NY Spills** **S108765231**
East **381 WINDERMERE** **N/A**
1/8-1/4 **AMHERST, NY**
0.220 mi.
1161 ft.

Actual:
607 ft.

SPILLS:

Focus Map:
8

Spill Number/Closed Date:	0750834 / 2007-09-12
Facility ID:	0750834
Facility Type:	ER
DER Facility ID:	336469
Site ID:	387060
DEC Region:	9
Spill Cause:	Deliberate
Spill Class:	D4
SWIS:	1522
Spill Date:	2007-09-01
Investigator:	rmcrosse
Referred To:	DOH DOW
Reported to Dept:	2007-09-11
CID:	Not reported
Water Affected:	Not reported

HOUSE (Continued) **S108765231**

Spill Source:	Private Dwelling
Spill Notifier:	Federal Government
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2007-09-11
Spill Record Last Update:	2007-09-12
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	Not reported
Contact Name:	Not reported
DEC Memo:	"09/11/07. RMC/AL FERRI,831-1161/PHONE. HAS 8 YEAR OLD SON. HE CLAIMS HAS SON WAS SICK FOR TWO WEEKS THIS SUMMER WITH STOMACH AILMENTS. HE CLAIMS NEIGHBOR IS DRAINING WATER OUT OF THE BASEMENT. AL FROM TOWN OF AMHERST IS THE PLUMBING INSPECTOR 631-7145. MR. FERRI CLAIMS THE SEWER WAS RUNNING OUT OF THE BASEMENT BY THE SUMP PUMP. HE STATED THAT HE NEVER SMELLED ANY ODOR OR NOTED ANY SOLIDS. THE DOH WAS THERE TODAY. HE DOES NOT KNOW WHO OR IF IT WAS THE STATE OR COUNTY DOH. HE WAS NOTIFIED TODAY BY AL, THE AMHERST PLUMBING INSPECTOR, THAT THE SEWER PROBLEM HAD BEEN REPAIRED. RMC GAVE HIM THE NUMBER FOR NYSDOH IN BUFFALO. 09/12/07 RMC/FILE. PROVIDED COPY OF THE REPORT TO DOW. NO DEC ACTION REQUIRED. CLOSE OUT. NO PAPER FILE. "
Remarks:	"Al Ferri contacted EPA claiming that his neighbor is dumping chemicals and it is making his son sick, he claims he has called Amherst Officials and DOH and no one will help. His number is 832-1161"

All Materials:

Site ID:	387060
Operable Unit ID:	1144280
Operable Unit:	01
Material ID:	2134576
Material Code:	0062A
Material Name:	raw sewage
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	False

330
WSW
1/8-1/4
0.221 mi.
1167 ft.

174 UNIVERSITY AVENUE
BUFFALO, NY

ERNS **2011967914**
N/A

Actual:
624 ft.

Focus Map:
8

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

331
East
1/8-1/4
0.228 mi.
1203 ft.

COMPUSOURCE SYSTEMS, INC.
110 JOHN MUIR DRIVE
AMHERST, NY 14228

NY AST **U004046428**
N/A

Actual:
578 ft.

Focus Map:
5

AST:

Region:	STATE
DEC Region:	9
Site Status:	Unregulated/Closed
Facility Id:	9-506362
Program Type:	PBS
UTM X:	192344.90646
UTM Y:	4769024.41072
Expiration Date:	N/A
Site Type:	Other

Affiliation Records:

Site Id:	54817
Affiliation Type:	Facility Owner
Company Name:	GARY L. GONZALES
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	5123 EAST RIVER ROAD
Address2:	Not reported
City:	GRAND ISLAND
State:	NY
Zip Code:	14072
Country Code:	001
Phone:	(716) 773-5203
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	54817
Affiliation Type:	Mail Contact
Company Name:	COMPUSOURCE SYSTEMS, INC.
Contact Type:	Not reported
Contact Name:	GARY L. GONZALES
Address1:	110 JOHN MUIR DRIVE
Address2:	Not reported
City:	AMHERST
State:	NY
Zip Code:	14228
Country Code:	001
Phone:	(716) 636-3700
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	54817
Affiliation Type:	Facility Operator
Company Name:	COMPUSOURCE SYSTEMS, INC.
Contact Type:	Not reported
Contact Name:	GARY GONZALES
Address1:	Not reported
Address2:	Not reported
City:	Not reported

COMPUSOURCE SYSTEMS, INC. (Continued) **U004046428**

State: NN
Zip Code: Not reported
Country Code: 001
Phone: (716) 636-3700
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 54817
Affiliation Type: Emergency Contact
Company Name: GARY L. GONZALES
Contact Type: Not reported
Contact Name: GARY GONZALES
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (716) 773-5203
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Tank Info:

Tank Number: 1
Tank Id: 169003
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
H99 - Tank Leak Detection - Other
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 07/01/1989
Capacity Gallons: 2400
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 01/01/1998
Register: True
Modified By: TRANSLAT
Last Modified: 04/14/2017

COMPUSOURCE SYSTEMS, INC. (Continued) **U004046428**

Material Name: #2 fuel oil (on-site consumption)

332
WNW
1/8-1/4
0.229 mi.
1209 ft.

MEL OTT BALL FIELD
MEYER ROAD
AMHERST, NY

NY Spills **S102174555**
N/A

Actual:
594 ft.

Focus Map:
4

SPILLS:

Spill Number/Closed Date:	9201608 / 1992-05-21
Facility ID:	9201608
Facility Type:	ER
DER Facility ID:	176219
Site ID:	212706
DEC Region:	9
Spill Cause:	Human Error
Spill Class:	D3
SWIS:	1522
Spill Date:	1992-05-09
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	1992-05-09
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Passenger Vehicle
Spill Notifier:	Local Agency
Cleanup Ceased:	1992-05-21
Cleanup Meets Std:	True
Last Inspection:	1992-05-21
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1992-05-12
Spill Record Last Update:	1992-11-05
Spiller Name:	Not reported
Spiller Company:	SWEET HOME SCHOOL DISTRIC
Spiller Address:	1901 SWEET HOME ROAD
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 05/09/92: RMC/ZYMANCK/PHONE SPILL CONTAINED TO A SMALL AREA OF GRAVEL LOT. LOOK AT MONDAY. 05/11/92: RMC/SITE SPILL CONTAINED TO A 7'*4' AREA OF LOOSE GRAVEL LOT. STRONG ODOR TO GRAVEL TO DEPTH OF 8 . NEED TO REMOVE OR REMEDIATE SOIL IN PLACE. 05/15/92: RMC/RAY KELLERHER PRESIDENT MEL OTT/+ LATTER COORER SCHOOL/PHONE ADVISED OF CLEAN UP REQUIRMENTS WILL ARRANGE, LETTER SENT. 05/21/92: RMC/ROGER SCHOOL/SITE SITE EXCAVATED BY HAND, DISPOSAL BY DOUBLE BAG, FILLED WITH STONE, CLOSE OUT. "
Remarks:	"CAR BACKED OVER OBJECT PUNCTURING GAS TANK IN GRAVEL LOT"

All Materials:

Site ID:	212706
Operable Unit ID:	965688
Operable Unit:	01
Material ID:	412906
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported

MEL OTT BALL FIELD (Continued) **S102174555**

Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

---

333 West 1/8-1/4 0.231 mi. 1219 ft.

WASTE OIL IN YARD
224 UNIVERSITY AVENUE
TONAWANDA, NY

NY Spills **S102178555**
N/A

Actual: 619 ft.

Focus Map: 8

SPILLS:

Spill Number/Closed Date:	9401679 / 1994-05-06
Facility ID:	9401679
Facility Type:	ER
DER Facility ID:	225331
Site ID:	277197
DEC Region:	9
Spill Cause:	Deliberate
Spill Class:	D6
SWIS:	1564
Spill Date:	1994-05-03
Investigator:	COOKE
Referred To:	Not reported
Reported to Dept:	1994-05-04
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Affected Persons
Cleanup Ceased:	1994-05-06
Cleanup Meets Std:	True
Last Inspection:	1994-05-05
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1994-05-05
Spill Record Last Update:	1994-05-19
Spiller Name:	Not reported
Spiller Company:	A-1 PRINTING
Spiller Address:	299 KENMORE AVENUE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was JDC 05/05/94: JDC/SITE - MINOR OIL SPILLAGE NOTED AT CURB. APPROX. 1 GAL. INTO LAWN AREA. WILL SEND WASTE OIL PROHIBITION LETTER TO SUSPECTED R.P. 05/06/94: JDC CALLED A-1 PAINTING AND GOT NO ANSWER. NO CLEANUP NECESSARY; NO FURTHER ACTION REQUIRED. "
Remarks:	"WASTE OIL DUMPED IN YARD BY RESIDENT AT 299 KENMORE AVENUE."

All Materials:

Site ID:	277197
Operable Unit ID:	995365
Operable Unit:	01
Material ID:	385427
Material Code:	0022
Material Name:	waste oil/used oil

WASTE OIL IN YARD (Continued) **S102178555**

Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G
Recovered: .00
Oxygenate: Not reported

334
NE
1/8-1/4
0.231 mi.
1221 ft.

Actual:
651 ft.

Focus Map:
9

3640 MAIN ST
AMHERST, NY

ERNS **2000543620**
N/A

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

335
WSW
1/8-1/4
0.233 mi.
1228 ft.

Actual:
667 ft.

Focus Map:
8

NYSDOT BIN 1001590
MAIN ST OVER NY RT 198
BUFFALO, NY 14203

FINDS **1016252355**
ECHO **N/A**

FINDS:

Registry ID: 110008066172

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid: 1016252355
Registry ID: 110008066172
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110008066172

BK336 **DICKS SPORTING GOODS #11** **RCRA-CESQG** **1018159319**
North **281 MEYER RD** **FINDS** **NYR000224246**
1/8-1/4 **AMHERST, NY 14226** **ECHO**
0.239 mi.
1264 ft. **Site 1 of 2 in cluster BK**

Actual:
583 ft.

Focus Map:
4

RCRA-CESQG:

Date form received by agency:	11/06/2015
Facility name:	DICKS SPORTING GOODS #11
Facility address:	281 MEYER RD AMHERST, NY 14226
EPA ID:	NYR000224246
Mailing address:	SAN FELIPE ST SUITE 1000 HOUSTON, TX 77056
Contact:	ASHLEY CAMPBELL
Contact address:	SAN FELIPE ST SUITE 1000 HOUSTON, TX 77056
Contact country:	US
Contact telephone:	713-985-5472
Contact email:	ASHLEY.CAMPBELL@STERICYCLE.COM
EPA Region:	02
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	SPIRIT DK AMHERST NY LLC
Owner/operator address:	N PERIMETER DR SUITE 210 SCOTTSDALE, AZ 85260
Owner/operator country:	US
Owner/operator telephone:	480-606-0821
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	07/17/2013
Owner/Op end date:	Not reported

Owner/operator name:	DICKS SPORTING GOODS #11
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported

DICKS SPORTING GOODS #11 (Continued) **1018159319**

Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 01/14/1993
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D005
. Waste name: BARIUM

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D016
. Waste name: 2,4-D

DICKS SPORTING GOODS #11 (Continued) **1018159319**

. Waste code: D018
. Waste name: BENZENE

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

Violation Status: No violations found

FINDS:

Registry ID: 110067044576

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1018159319
Registry ID: 110067044576
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110067044576

BK337 **DICKS SPORTING GOODS #11** **NY MANIFEST** **S118563961**
North **281 MEYER RD** **N/A**
1/8-1/4 **AMHERST, NY 14226**
0.239 mi.
1264 ft. **Site 2 of 2 in cluster BK**

Actual:
583 ft.

Focus Map:
4

NY MANIFEST:
Country: USA
EPA ID: NYR000224246
Facility Status: Not reported
Location Address 1: 281 MEYER RD
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: AMHERST
Location State: NY
Location Zip: 14226
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000224246
Mailing Name: DICKS SPORTING GOODS #11
Mailing Contact: DICKS SPORTING GOODS #11
Mailing Address 1: 281 MEYER RD
Mailing Address 2: Not reported
Mailing City: AMHERST
Mailing State: NY
Mailing Zip: 14226
Mailing Zip 4: Not reported

DICKS SPORTING GOODS #11 (Continued) **S118563961**

Mailing Country:	USA
Mailing Phone:	7168334761

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2016
Trans1 State ID:	MID021087275
Trans2 State ID:	Not reported
Generator Ship Date:	03/16/2016
Trans1 Recv Date:	03/16/2016
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/23/2016
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000224246
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	MID980615298
TSDF ID 2:	Not reported
Manifest Tracking Number:	001237410PSC
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	14
Units:	P - Pounds
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	D009
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

338
West
1/8-1/4
0.243 mi.
1285 ft.

NOCO TRUCK
216 NORTH WREXHAM
TONAWANDA, NY

NY Spills **S104508648**
N/A

Actual:
585 ft.

Focus Map:
6

SPILLS:

Spill Number/Closed Date:	9975577 / 1999-12-13
Facility ID:	9975577
Facility Type:	ER
DER Facility ID:	149113
Site ID:	177453
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	D3
SWIS:	1564
Spill Date:	1999-12-10
Investigator:	SORGI
Referred To:	Not reported
Reported to Dept:	1999-12-10
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Tank Truck
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	1999-12-13
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-12-10
Spill Record Last Update:	2000-01-20
Spiller Name:	ART MUELLER
Spiller Company:	NOCO ENERGY CORP
Spiller Address:	2440 SHERIDAN DRIVE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MJS 12/10/99: MJS TOOK REPORT FROM MR YOUNT. HE STATED THAT SPILL OCCURRED AS DRIVER TAKING HOSE BACK TO TRUCK AFTER DELIVERY COMPLETE. HOSE SPLIT AND FUEL SPILLED ON DRIVEWAY ONLY. NO SOILS IMPACTED. SPILL CLEANED WITH SPEEDI DRI AND DEBRIS TAKEN TO TERMINAL FOR DISPOSAL. 12/13/99: MJS SITE INSPECTION, CLEANUP COMPLETE, STAIN ON DRIVEWAY. MINOR SPILL. NO FURTHER ACTION REQUIRED. MJS CLOSE FILE."
Remarks:	"DELIVERY HOSE SPLIT AT END OF DELIVERY. APPROX ONE QUART FUEL SPILLED TO DRIVEWAY."

All Materials:

Site ID:	177453
Operable Unit ID:	1093903
Operable Unit:	01
Material ID:	290108
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

339
North
1/8-1/4
0.245 mi.
1294 ft.

NATIONAL GRID
311 MEYER RD
AMHERST, NY 14226

NY Spills **S117851790**
N/A

Actual:
585 ft.

Focus Map:
4

SPILLS:

Spill Number/Closed Date:	1500074 / 2015-07-13
Facility ID:	1500074
Facility Type:	ER
DER Facility ID:	460997
Site ID:	506207
DEC Region:	9
Spill Cause:	Traffic Accident
Spill Class:	C3
SWIS:	1522
Spill Date:	2015-04-03
Investigator:	RJJONAK
Referred To:	Not reported
Reported to Dept:	2015-04-03
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Transformer
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2015-04-03
Spill Record Last Update:	2015-07-13
Spiller Name:	LISA MONTESANO
Spiller Company:	NATIONAL GRID
Spiller Address:	144 KENSINGTON AVE.
Spiller Company:	001
Contact Name:	LISA MONTESANO
DEC Memo:	"4/3/2015: RJJ AT SITE AT 1045...BEHIND DICK'S SPORTING GOODS STORE(ON MAPLE RD.) AND BEHIND 311 MEYER RD.,A WASTE MANAGEMENT TRUCK CAUGHT A LOW HANGING UTILITY WIRE,CAUSING 4 POLES TO FALL(THIS WAS THE ONLY POLE WITH A TRANSFORMER)...THE ONE BEHIND DICK'S HAD A 30 GAL. NON-PCB TRANSFORMER,WHICH FELL,HALF-WAY, INTO A DUMPSTER...~15 GALS. OF TRANSFORMER OIL LEAKED OUT ONTO THE ASPHALT PARKING LOT AND A SMALL AMOUNT(less than 1 GAL),MIGRATED INTO THE NEARBY STORM CATCH BASIN...THE OTHER 15 GALS. WAS SPILLED INTO THIS DUMPSTER AND IS CONTAINED THERE...NATIONAL GRID PERSONNEL HAVE SPREAD SPEEDI-DRY/ABSORBANTS ON THIS SPILL AND HAVE CONTAINED IT...THEY ALSO PLACED ABSORBANTS IN THE STORM RECEIVER TO COLLECT THE OIL THERE...LISA MONTESANO,NATIONAL GRID,HAS ALSO HIRED OP-TECH ENVIRONMENTAL TO REMEDIATE,AFTER THEIR CREWS INSTALL NEW POLES/WIRES,LATER TODAY...OP-TECH WILL PICK-UP ALL THE IMPACTED SPEEDI DRY,CLEAN THE STORM SEWER,AND DISPOSE ALL THIS MATERIAL...LISA WILL KEEP ME INFORMED. 4/6/2015: RJJ AT SITE AT 0800...OP-TECH ENVIRONMENTAL HAS CLEANED-UP ALL THE SPEEDI-DRY,CLEANED THE STORM SEWER,AND PICKED-UP ALL THE MATERIAL,WHICH WILL BE DISPOSED OF...THE CLEAN-UP IS ACCEPTABLE...LISA WILL SEND ME THE DISPOSAL RECEIPTS...ALSO,NATIONAL GRID HAS INSTALLED A NEW POLE/TRANSFORMER. 7/13/2015: RECEIVED THE DISPOSAL RECEIPTS FOR THE 30 DRUMS & 5 CONTAINERS OF SPILL MATERIAL TAKEN TO COVANTA ENERGY...THE SPILL HAS

NATIONAL GRID (Continued) **S117851790**

BEEN CLEANED-UP & PROPERLY DISPOSED OF...NO FURTHER ACTION NEEDED...SPILL CLOSED OUT."
Remarks: "mva accident caused loss , c/u in progress"

All Materials:
Site ID: 506207
Operable Unit ID: 1255536
Operable Unit: 01
Material ID: 2258291
Material Code: 0020A
Material Name: transformer oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 30.00
Units: G
Recovered: 30.00
Oxygenate: Not reported

---

340 NNE 1/8-1/4 0.245 mi. 1294 ft.
Actual: 618 ft.
Focus Map: 8

PRINCETON HOUSING ASSOCIATES
165 PRINCETON AVE
AMHERST, NY 14226

RCRA NonGen / NLR **1000308228**
FINDS **NYD038630554**
ECHO
NY MANIFEST

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: PRINCETON HOUSING ASSOCIATES
Facility address: 165 PRINCETON AVE
AMHERST, NY 14226
EPA ID: NYD038630554
Mailing address: PRINCETON AVE
AMHERST, NY 14226
Contact: Not reported
Contact address: PRINCETON AVE
AMHERST, NY 14226
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: PRINCETON HOUSING ASSOCIATES
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: PRINCETON HOUSING ASSOCIATES

PRINCETON HOUSING ASSOCIATES (Continued) **1000308228**

Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: PRINCETON HOUSING ASSOCIATES
Classification: Not a generator, verified

Date form received by agency: 04/03/1995
Site name: PRINCETON HOUSING ASSOCIATES
Classification: Unverified

. Waste code: NONE
. Waste name: None

Date form received by agency: 03/17/1989
Site name: PRINCETON HOUSING ASSOCIATES
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: U240
. Waste name: ACETIC ACID, (2,4-DICHLOROPHENOXY)-, SALTS & ESTERS

PRINCETON HOUSING ASSOCIATES (Continued) **1000308228**

Violation Status: No violations found

FINDS:

Registry ID: 110004353404

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000308228
Registry ID:	110004353404
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004353404

NY MANIFEST:

Country:	USA
EPA ID:	NYD038630554
Facility Status:	Not reported
Location Address 1:	PRINCETON HOUSING ASSOCIATES
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	165 PRINCETON AVE AMHERST
Location State:	NY
Location Zip:	14226
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD038630554
Mailing Name:	M J PETERSON
Mailing Contact:	M J PETERSON
Mailing Address 1:	PRINCTON HOUSING ASSOCIATES
Mailing Address 2:	Not reported
Mailing City:	165 PRINCETON AVE-AMHERST
Mailing State:	NY
Mailing Zip:	14226
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7166881231

NY MANIFEST:

Document ID:	NYA7873956
Manifest Status:	K
seq:	Not reported
Year:	1989
Trans1 State ID:	AK6980NY
Trans2 State ID:	Not reported
Generator Ship Date:	04/14/1989

PRINCETON HOUSING ASSOCIATES (Continued) **1000308228**

Trans1 Recv Date:	04/14/1989
Trans2 Recv Date:	/ /
TSD Site Recv Date:	05/15/1989
Part A Recv Date:	06/06/1989
Part B Recv Date:	05/19/1989
Generator EPA ID:	NYD038630554
Trans1 EPA ID:	ILD099202681
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD049836679
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

341
East
1/8-1/4
0.245 mi.
1295 ft.

GRAND ISLAND SLS SV INC
190 MEADOW LEA
BUFFALO, NY 14226

EDR Hist Auto **1020911416**
N/A

Actual:
601 ft.

Focus Map:
6

EDR Hist Auto

Year:	Name:	Type:
1978	GRAND ISLAND SLS SV INC	Petroleum Products, NEC

342
SW
1/8-1/4
0.246 mi.
1301 ft.

SEAN MAGIERSKI RESIDENCE
73 MONTROSE AVE
BUFFALO, NY

NY Spills **S118952935**
N/A

Actual:
628 ft.

Focus Map:
8

SPILLS:

Spill Number/Closed Date:	1607324 / 2016-10-26
Facility ID:	1607324
Facility Type:	ER
DER Facility ID:	488940
Site ID:	534966
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	1502
Spill Date:	2016-10-26
Investigator:	FXGALLEG
Referred To:	Not reported
Reported to Dept:	2016-10-26
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2016-10-26
Spill Record Last Update:	2016-10-27
Spiller Name:	DON YOTT
Spiller Company:	SEAN MAGIERSKI RESIDENCE
Spiller Address:	73 MONTROSE AVE
Spiller Company:	999
Contact Name:	DON YOTT
DEC Memo:	"10/26/16 FG SPOKE TO DON YOTT WITH NOCO. HE SAID THE SPILL WAS LESS THAN 1 GALLON AND HAD BEEN CLEANED UP. THE WASTE WAS BROUGHT TO THE NOCO TERMINAL FOR DISPOSAL. NO FURTHER WORK IS REQUIRED. CLOSE."
Remarks:	"while moving the tank loss occurred to dirt and stone basement dirt floor. Oil has entered the sump, he does not believe that it has been released due to lack of rain"

All Materials:

Site ID:	534966
Operable Unit ID:	1283674
Operable Unit:	01
Material ID:	2289062

SEAN MAGIERSKI RESIDENCE (Continued) **S118952935**

Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

BL343 **NY COOLING TOWERS** **S122436381**
ESE **2350 N FOREST RD** **N/A**
1/8-1/4 **BUFFALO, NY 14068**
0.248 mi.
1307 ft. **Site 1 of 2 in cluster BL**

Actual:
585 ft.

Focus Map:
5

COOLING TOWERS:

Equipment Unique ID:	12336
Equipment Borough:	2350
Intended Use:	Air Conditioning
Manufacturer:	BAC
Model:	F1343-N
Cooling Capacity:	100
Cooling Capacity Unit:	Tonnage
Commissioned Date:	05/18/2017
Inspection Date:	08/09/2018
Date of Bacteriological Collection:	08/09/2018
Date of Legionella Collection:	08/09/2018
Last Legionella Result > 1,000 CFU/mL:	no
Latitude:	43.008570447
Longitude:	-78.774953948

BL344 **ELLICOTT CREEK FLOOD CONTROL PROJECT** **FINDS** **1007755637**
ESE **2350 NORTH FOREST ROAD** **N/A**
1/8-1/4 **GETZVILLE, NY 14068**
0.248 mi.
1307 ft. **Site 2 of 2 in cluster BL**

Actual:
585 ft.

Focus Map:
5

FINDS:

Registry ID: 110019180394

Environmental Interest/Information System

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

345
NNW
1/8-1/4
0.248 mi.
1312 ft.

ONY BIOTECH
1576 SWEET HOME RD N & S WINGS BAIRD RESEARCH PARK
AMHERST, NY 14228

RCRA-SQG **1000871607**
NY0000075754

Actual:
580 ft.

Focus Map:
4

RCRA-SQG:

Date form received by agency:	01/29/2018
Facility name:	ONY BIOTECH
Facility address:	1576 SWEET HOME RD N & S WINGS BAIRD RESEARCH PARK AMHERST, NY 14228
EPA ID:	NY0000075754
Mailing address:	SWEET HOME RD N & S WINGS BAIRD RESEARCH PARK AMHERST, NY 14228
Contact:	WALTER W KELLER
Contact address:	SWEET HOME RD N & S WINGS BAIRD RESEARCH PARK AMHERST, NY 14228
Contact country:	US
Contact telephone:	716-531-3540
Contact email:	WKELLER@ONYBIOTECH.COM
EPA Region:	02
Land type:	Private
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	ONY INC
Owner/operator address:	1576 SWEET HOME RD AMHERST, NY 14228
Owner/operator country:	US
Owner/operator telephone:	800-274-4669
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	ONY INC
Owner/operator address:	1576 SWEET HOME RD AMHERST, NY 14228
Owner/operator country:	US
Owner/operator telephone:	800-274-4669
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	ONY BIOTECH
Owner/operator address:	SWEET HOME RD N & S WINGS BAIRD RESEARCH PARK AMHERST, NY 14228

ONY BIOTECH (Continued) **1000871607**

Owner/operator country: US
Owner/operator telephone: 877-274-4669
Owner/operator email: Not reported
Owner/operator fax: 716-636-3942
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 10/10/2017
Owner/Op end date: Not reported

Owner/operator name: ONY BIOTECH
Owner/operator address: SWEET HOME RD N & S WINGS BAIRD RESEARCH PARK
AMHERST, NY 14228
Owner/operator country: US
Owner/operator telephone: 877-274-4669
Owner/operator email: Not reported
Owner/operator fax: 716-636-3942
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 10/10/2017
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

ONY BIOTECH (Continued) **1000871607**

. Waste code: D009
. Waste name: MERCURY

. Waste code: D011
. Waste name: SILVER

. Waste code: D022
. Waste name: CHLOROFORM

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: P105
. Waste name: SODIUM AZIDE

. Waste code: U044
. Waste name: CHLOROFORM

. Waste code: U154
. Waste name: METHANOL (I)

. Waste code: B
. Waste name: B

. Waste code: T
. Waste name: T

Historical Generators:
Date form received by agency: 01/01/2007
Site name: ONY INC
Classification: Small Quantity Generator

Date form received by agency: 01/01/2006
Site name: ONY INC
Classification: Small Quantity Generator

Date form received by agency: 11/03/1993
Site name: ONY INC
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D022
. Waste name: CHLOROFORM

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND

ONY BIOTECH (Continued) **1000871607**

1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

Evaluation Action Summary:

Evaluation date: 05/05/2015
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 11/29/2012
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 05/06/2010
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 09/17/2008
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 08/30/2006
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 01/24/2003
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

ONY BIOTECH (Continued) **1000871607**

Evaluation date: 08/07/1998
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

---

346 **WHITE CRYSTALLINE MATERIA** **NY Spills** **S102179466**
West **674 HARRISON STREET** **N/A**
1/8-1/4 **TONAWANDA, NY**
0.250 mi.
1318 ft.

Actual:
597 ft.

Focus Map:
6

SPILLS:
Spill Number/Closed Date: 9502446 / 2000-12-13
Facility ID: 9502446
Facility Type: ER
DER Facility ID: 233074
Site ID: 287702
DEC Region: 9
Spill Cause: Unknown
Spill Class: D5
SWIS: 1564
Spill Date: 1995-05-01
Investigator: RJJONAK
Referred To: Not reported
Reported to Dept: 1995-05-25
CID: Not reported
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Citizen
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1995-05-31
Spill Record Last Update: 2001-01-08
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller Company: 999
Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was RJJ 05/31/95: MJS CHECKED WITH DAN KING. GLEN MAY IS HANDLING PROJECT AND WILL INSPECT. 12/12/2000: RJJ IS TAKING OVER THIS SPILL FROM MJS, WHO HAS LEFT DEC. 12/13/2000: RJJ CHECKED WITH BOTH DAN KING AND GLENN MAY, AND THEY BOTH HAD NO INVOLVEMENT/KNOWLEDGE OF THIS...SINCE WE HAVE HAD NO FURTHER CALLS ON THIS IN OVER FIVE 5 YEARS, NO FURTHER ACTION NEEDED...SPILL CLOSED OUT."
Remarks: "DISTRESSED AND DEAD VEGETATION. WHITE CRYSTALLINE MATERIAL FOUND IN SOIL REMOVED FROM BASEMENT. CLAIMS HIGH CANCER RATE IN NEIGHBORHOOD. CLAIMS NIAGARA MOHAWK DUMPED DRUMS IN AREA LONG AGO."

All Materials:
Site ID: 287702
Operable Unit ID: 1013505
Operable Unit: 01
Material ID: 367498

WHITE CRYSTALLINE MATERIA (Continued) **S102179466**

Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Count: 233 records

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
AMHERST	1003863920	MORRIS & REIMANN	RENSCH RD	14226	SEMS-ARCHIVE
AMHERST	1017788046	NYSDOT BIN 1074391	I-990 SB	14068	RCRA-LQG
AMHERST	1017788047	NYSDOT BIN 1074392	I-990 NB	14068	RCRA-LQG
AMHERST	1000705540	NYSDOT BIN 1045070	I-290 RAMP	14226	RCRA-LQG
AMHERST	1018281138	NYS THRUWAY AUTH BIN 5511950	FOREST RD OVER I-90 MP 420.12	14226	RCRA-LQG, FINDS, ECHO
AMHERST	1018281139	NYS THRUWAY AUTH BIN 5511960	I-290 EB RAMP TO I-90 EB	14226	RCRA-LQG, FINDS, ECHO
AMHERST	1010566161	NYSDOT BIN 1071880	I-990 1.7 MI N OF INTER WITH	14228	RCRA-LQG
AMHERST	1010566162	NYSDOT BIN 1072631	I-990 OVER NYS RTE 952T SITE 1	14228	RCRA-LQG
AMHERST	1010566163	NYSDOT BIN 1072632	I-990 OVER NYS RTE 952T SITE 2	14228	RCRA-LQG
AMHERST	1004759009	MOBIL OIL CORP SS #HDX	SW TRANSIT RD & MAIN ST	14226	RCRA-CESQG, NY MANIFEST
AMHERST	93192550		SHERIDAN DR NEAR	14226	ERNS
AMHERST	89113685		STATE UNIV OF NY, AMHERST CAMPUS COOK HALL COOKE, 4TH FLOOR		ERNS
AMHERST	2009917453		I-290 AT MAIN STREET EXIT		ERNS
AMHERST	S113916948	RIDGE LEA CAMPUS	RIDGE LEE ROAD	14228	NY SHWS
AMHERST	S113917023	MORRIS AND REIMAN WRECKING	OFF RENSCH ROAD		NY SHWS
AMHERST	S118953637	ERIE COMM COLLEGE	MAIN STREET		NY LTANKS
AMHERST	S118953644	ERIE COMMUNITY COLLEGE	MAIN STREET		NY LTANKS
AMHERST	S121988541	ATLANTIC 0363-9176	800O MAIN ST. AT TRANSIT		NY LTANKS
AMHERST	S121988550	ATLANTIC 0363-9176	800 MAIN ST. AT TRANSIT		NY LTANKS
AMHERST	U004182990	PUMP HOUSE	I-990	14228	NY UST
AMHERST	S118707387	JEWETTE & NOONAN TRANSPORTATION INC	I-290 WB AT EXIT 5	14221	NY Spills
AMHERST	S123160071	ROADWAY & DRAINAGE	NORTH FOREST RD & REIST ST	14221	NY Spills
AMHERST	S117852901	ROADWAY	MAPLE RD AND COUNTRY PARKWAY	14221	NY Spills
AMHERST	S118260937	I290 AT MAIN STREET	I290 AT MAIN STREET	14226	NY Spills
AMHERST	S111457743	IN CREEK	MAPLE AT ELLICOTT CREEK	14226	NY Spills
AMHERST	S122877178	ROADWAY	SHERIDAN DR @ BUCKEYE	14226	NY Spills
AMHERST	S118951927	ROADWAY	MAPLE RD/MAPLE VIEW	14226	NY Spills
AMHERST	S113819685	TONAWANDA TANK ROADSIDE	SHERIDAN AND MILITARY	14226	NY Spills
AMHERST	S113915935	TRACTOR TRAILER ROLL OVER	I-990 SOUTH TO I-290 EASTBOUND RAMP	14226	NY Spills
AMHERST	S117535169	BEFORE MILLERSPORT HGWY EXIT	I-290 EASTBOUND	14226	NY Spills
AMHERST	S117394088	POLE TOP TRANSFORMERS	1876 NIAGARA FALLS BLVD.	14223	NY Spills
AMHERST	S121101264	BIESER CREEK	FLINT RD	14228	NY Spills
AMHERST	S106720508	CRUDE OIL	SHERATON DRIVE NEAR I-290		NY Spills
AMHERST	S108057344	NATIONAL GRID	4330 SWEET HOME ROAD		NY Spills
AMHERST	S122479409	I-290 ON RAMP @ MAIN ST	I-290 EASTBOUND		NY Spills
AMHERST	S118952882	UST IN ROAD ROW	EGGERT AT NIAGARA FALLS BLVE		NY Spills
AMHERST	S108295616	INSIDE SALT BARN	SWEET HOME ROAD		NY Spills
AMHERST	S102176033	NATIONAL FUEL GAS	MAIN STREET		NY Spills
AMHERST	S102177464	GARDNER TRUCK	FLINT ROAD		NY Spills
AMHERST	S102178038	DELMARCO ROOFING	SHERIDAN DRIVE		NY Spills
AMHERST	S103573603	NIAGARA MOHAWK POLE 17R	SHERIDAN DRIVE		NY Spills
AMHERST	S103938162	TAR-LIKE SUBSTANCE	SHERIDAN & MAPLE		NY Spills

Count: 233 records

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
AMHERST	S109063789	IN FRONT OF ROBO MINI MART	727 MAPLE & NORTH FOREST		NY Spills
AMHERST	S105056660	SHEEN IN ELLICOTT CREEK	NORTH FOREST		NY Spills
AMHERST	S109942985	I-290 E/B EXIT RAMP 7C	I-290 E/B EXIT RAMP 7C		NY Spills
AMHERST	S113817689	ROADSIDE CULVERT	MAIN ST (NEAR GETZVILLE RD)		NY Spills
AMHERST	S110750958	POLE 542	BILL ST / SHERIDAN DR		NY Spills
AMHERST	S110751156	I-990 MM 1004	I-990		NY Spills
AMHERST	S117853536	SPILL NUMBER 8502954	NIAGARA FALLS BLVD.		NY Spills
AMHERST	S117853663	SPILL NUMBER 8504357	MAPLE AT FORREST		NY Spills
AMHERST	S117853678	SPILL NUMBER 8504541	I290-E NEAR SHERIDAN		NY Spills
AMHERST	S117853697	SPILL NUMBER 8504732	NIAGARA FALLS BOUL.		NY Spills
AMHERST	1000705505	NYS THRUWAY AUTH	INTERCHANGE 50 I-290 RAMP	14226	RCRA NonGen / NLR
AMHERST	1001090104	NYSDOT BIN 1045040	CR 192 MAPLE RD BRIDGE OVER	14228	RCRA NonGen / NLR, NY MANIFEST
AMHERST	1001482762	NYSDOT BIN 1-07260-1	I290 SB BRG OVER SWEET HOME RD	14228	RCRA NonGen / NLR, NY MANIFEST
AMHERST	1001482764	NYSDOT BIN 1-07260-2	I290 NB BRG OVER SWEET HOME RD	14228	RCRA NonGen / NLR, NY MANIFEST
AMHERST	1023197989	NORTH FOREST MULTI FAMILY HOUSE	2371NA 2383NA 2391 & 2405 N FOREST RD	14221	FINDS
AMHERST	1007812023	PATEL PROPERTY	136 & 150 MAPLE RD	14221	FINDS
AMHERST	1017764722	NYSDOT BIN 1074391	I-990 SB	14068	FINDS, ECHO
AMHERST	1017764723	NYSDOT BIN 1074392	I-990 NB	14068	FINDS, ECHO
AMHERST	1007764631	SHERIDAN MEADOWS CORPORATE	7100-7200 SHERIDAN DRIVE	14226	FINDS
AMHERST	1008203917	BALL PUMP STATION AND TANKS	SWEET HOME RD	14226	FINDS, ECHO
AMHERST	1017744521	LOCKWOOD VILLAS	2493 & 2497 SWEET HOME RD	14226	FINDS
AMHERST	1023648115	TOWN DITCH 5 CULVERT EXTENSION AT FLINT RD	FLINT RD	14226	FINDS
AMHERST	1016367422	SWEET HOME RD CULVERT OVER TRIBUTARY TO ELLICOTT CRK	SWEET HOME RD AT OF HILTON BLVD	14226	FINDS
AMHERST	1016199951	NYS THRUWAY AUTH	INTERCHANGE 50 I-290 RAMP	14226	FINDS, ECHO
AMHERST	1008938778	UNIVERSITY COMMONS	4180 & 4200 RENSCH RD	14228	FINDS
AMHERST	1016311553	S ELLICOTT CREEK RD	S ELLICOTT CRK RD BETWEEN NIAGARA FALLS BLVD &	14228	FINDS
AMHERST	1017378373	E ROBINSON RD BRIDGE OVER TOWN DITCH #2 BIN 3367970	E ROBINSON RD BETWEEN NIAGARA FALLS BLVD & SUNDRID	14228	FINDS
AMHERST	1010492393	NYSDOT BIN 1071880	I-990 1.7 MI N OF INTER WITH	14228	FINDS, ECHO
AMHERST	1010492394	NYSDOT BIN 1072631	I-990 OVER NYS RTE 952T	14228	FINDS, ECHO
AMHERST	1010492395	NYSDOT BIN 1072632	I-990 OVER NYS RTE 952T	14228	FINDS, ECHO
AMHERST	S119079211	NYSDOT BIN 1074392	I-990 NB	14068	NY MANIFEST
AMHERST	S119079210	NYSDOT BIN 1074391	I-990 SB OVER N FRENCH RD	14068	NY MANIFEST
AMHERST	S122482677	NYSDOT	OD RAMP OVER RTE I-290	14226	NY MANIFEST
AMHERST	S122482656	NEW YORK STATE THRUWAY AUTHORITY	INTERCHANGE 50 I-290 RAMP	14226	NY MANIFEST
AMHERST	S119079235	NYS THRUWAY AUTH BIN 5511950	FOREST RD OVER I-90 MP 420.12	14226	NY MANIFEST
BUFFALO	2015105276		FRONTIER RAILYARD		ERNS
BUFFALO	2014093872		FRONTIER RAILYARD		ERNS
BUFFALO	2015105875		FRONTIER YARD		ERNS
BUFFALO	2015106054		FRONTIER YARD		ERNS
BUFFALO	2016139643		FRONTIER RAILYARD		ERNS
BUFFALO	2016140928		FRONTIER YARD		ERNS
BUFFALO	2015136623		BAILEY AVE		ERNS
BUFFALO	2014077297		FRONTIER YARD		ERNS
BUFFALO	92130245		MAIN ST		ERNS
BUFFALO	875444		MAIN DOCK		ERNS

Count: 233 records

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
BUFFALO	99471406		FRONTIER SWITCHING YARD		ERNS
BUFFALO	2018214391		FRONTIER RAILYARD		ERNS
BUFFALO	2000542938		2580 KENMORE AVE		ERNS
BUFFALO	2001589831		LEE STREET		ERNS
BUFFALO	2006809917		MAIN AND DIVISION ST		ERNS
BUFFALO	2011996122		RAIL YARD FRONTIER		ERNS
BUFFALO	S113916928	TIMES BEACH	FURHMANN BOULEVARD		NY SHWS
BUFFALO	S113917117	NEW BUFFALO INDUSTRIAL PARK	SOUTH OGDEN, DINGENS, BAILEY		NY SHWS
BUFFALO	S113922159	MAIN-LASALLE REVITALIZATION PROJECT	MAIN-LASALLE STREET	14214	NY VCP
BUFFALO	92100823		BROADWAY & BAILEY INTERSECTION		HMIRS
BUFFALO	92090164		CONRAIL FRONTIER YD		HMIRS
BUFFALO	92090165		CONRAIL FRONTIER YA		HMIRS
BUFFALO	94070105		FRONTIER YARD		HMIRS
BUFFALO	2004071245		BAILEY STREET		HMIRS
BUFFALO	2005701482	CSX FRONTIER YARD - MP-QC 434	CSX FRONTIER YARD - MP-QC 434		HMIRS
BUFFALO	2005702201	1836 BROADWAY/FRONTIER YARD	1836 BROADWAY/FRONTIER YARD		HMIRS
BUFFALO	2007445765	1836 BROADWAY/QC 434/FRONTIER	1836 BROADWAY/QC 434/FRONTIER		HMIRS
BUFFALO	S121979111	NYSDOT PROJECT/TANK	MAIN ST & HUMBOLDT PKWY		NY Spills
BUFFALO	S111011122	TRANSFORMER 178 @ DELEWARE PARK	MAIN WALKING LOOP		NY Spills
BUFFALO	S106967813	NIMO VAULT	MAIN STREET		NY Spills
BUFFALO	S111835932	INTERSECTION - VAULT # 23-11	MAIN AND SENECA		NY Spills
BUFFALO	S121464269	CSX TRANSPORTATION	MM QC 437.0 NEAR WILLIAM ST AT BAILEY AVE		NY Spills
BUFFALO	S118704812	UNDERGROUND	377 MAIN STREET		NY Spills
BUFFALO	S118706835	ON THE BUFFALO RIVER	OPPOSITE NEW SOLAR CITY SITE		NY Spills
BUFFALO	S112226922	AUTOTECH 3	361 FOREST AVE		NY Spills
BUFFALO	S118952364	SHEEN IN BUFFALO RIVER	BAILEY AVE BRIDGE		NY Spills
BUFFALO	S108295177	BUFFALO CEMENT COMPANY	MAIN STREET POLE # 242		NY Spills
BUFFALO	S102174179	AMERICANA	MAIN STREET		NY Spills
BUFFALO	S102175840	OIL DUMPING INTO SEWER	EGGERT ROAD		NY Spills
BUFFALO	S102175981	WEISS TRANSPORT CO	FURMANN BOULEVARD		NY Spills
BUFFALO	S102177787	VICTOR'S MOTORS	MAIN STREET		NY Spills
BUFFALO	S102178481	POLE 304	BAILEY AV		NY Spills
BUFFALO	S102667773	NFTA BUS	MAIN STREET NEAR PARKSIDE		NY Spills
BUFFALO	S103562301	BAD GASOLINE	MAIN STREET		NY Spills
BUFFALO	S109415800	MEMORIAL AUD	MAIN STREET		NY Spills
BUFFALO	S109060755	ROADWAY	BAILEY AVE/ WILLIAMS ST		NY Spills
BUFFALO	S121986141	FREEZER QUEEN	975 FURHMAN BOULEVARD		NY Spills
BUFFALO	S116553930	INTERSECTION	MAIN ST/LASALLE ST		NY Spills
BUFFALO	S116555053	NAT GRID RIGHT AWAY	OHIO ST/MOORE ST/MIAMI ST		NY Spills
BUFFALO	S120702450	VAULT	241 NORTH FOREST		NY Spills
BUFFALO	S109826562	MEMORIAL AUDITORIUM	MAIN ST		NY Spills
BUFFALO	S113818203	CITY OF BUFFALO SANITATION TRUCK	BAILEY		NY Spills
BUFFALO	S117268696	TRUCK	SWAN STREET /MAIN AND WASHINGTON		NY Spills
BUFFALO	S121099055	ROADWAY	BAILEY AVE 69 DINGENS ST INTERSECTION		NY Spills
BUFFALO	S121101222	COMMERCIAL	888 MAIN ST		NY Spills
BUFFALO	S110307956	ROADSIDE	MAIN AND WEST WINDSPEAR		NY Spills
BUFFALO	S117653756	PIKE CO	130 MAIN ST		NY Spills

Count: 233 records

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
BUFFALO	S117364000	CANALSIDE	130 MAIN ST		NY Spills
BUFFALO	S117364001	WITH IN A PIPE CASE	130 MAIN STREET		NY Spills
BUFFALO	S106009855	SKYWAY ROAD SPILL	SOUTH OF CITY SHIP CANAL		NY Spills
BUFFALO	S110539865	GRANT AUTOMOTIVE	BROADWAY AND BAILEY		NY Spills
BUFFALO	S110539966	IN STREET & PARKING LOT	MAIN ST. @ CHIPPIWA		NY Spills
BUFFALO	S117853657	SPILL NUMBER 8504242	1421 MAIN & GLENWOOD		NY Spills
BUFFALO	S117852107	VAULT #10-82	MAIN STREET AND SENECA STREET		NY Spills
BUFFALO	1014395329	NIAGARA MOHAWK A NATIONAL GRID CO	MAIN ST 7 JEWETT PKWY	14214	RCRA NonGen / NLR, NY MANIFEST
BUFFALO	1016323267	BUFFALO STATE CAMPUS NORTH HOUSING	HADLEY ROAD	14260	FINDS
BUFFALO	S109584695	NIAGARA MOHAWK POWER CORPORATION	MAIN ST		NY MANIFEST
CHEEKTOWAGA	1000232829	NIAGARA MOHAWK STATION 157	EGGERT RD	14223	RCRA NonGen / NLR
ERIE COUNTY	S120701569	SUNOCO STATION	2977 NIAGARA FALLS BLVE		NY Spills
GETZVILLE	S113406053	BIKE PATH OVER ELLICOTT CREEK	NORTH FOREST & AUDUBON	14221	NY Spills
KENMORE	2013049966		SHERIDAN DRIVE		ERNS
KENMORE	S122480382	KENMORE WEST HS	33 HIGHLAND AVE		NY Spills
KENNMORE	S122480545	NATION GRID POLE # 109R	109 NIAGARA FALLS BLVD	14150	NY Spills
TONAWANDA	1003863645	DUNLOP SITE 2	SHERIDAN DR	14150	SEMS-ARCHIVE
TONAWANDA	1001028632	NYS DOT BIN 1044970	TWO MILE CREEK RD I-290	14150	RCRA-LQG
TONAWANDA	1001233136	NYSDOT BIN 1044950	I-290 BRG OVER I-190	14150	RCRA-SQG, NJ MANIFEST, NY MANIFEST
TONAWANDA	1007112581	ERIE CO PARKS ELLICOTT CREEK	NIAGARA FALLS BLVD & ELLICOTT	14150	RCRA-CESQG, NY MANIFEST
TONAWANDA	92135052		KENMORE AVE	14150	ERNS
TONAWANDA	2015105421		KENMORE RAIL YARD		ERNS
TONAWANDA	9038932		I-290		ERNS
TONAWANDA	97399804		I-290 OVERPASS AT		ERNS
TONAWANDA	S113917112	SHANCO PLASTICS AND CHEMICALS	WALES AVENUE AND KENMORE AVENUE	14150	NY SHWS
TONAWANDA	S100118409	AUTO TANK LEAK	MAIN ST.		NY LTANKS
TONAWANDA	U004272432	CAMPING COUNTRY	SHERIDAN & EGGERT RD	14150	NY UST
TONAWANDA	U004272434	EARLE M. JORGENSEN COMPANY	1275 SHERIDAN DRIVE	14150	NY UST
TONAWANDA	U004272435	SHERIDAN MANOR APARTMENTS	1430 SHERIDAN DR	14150	NY UST
TONAWANDA	96090044		MAIN ST		HMIRS
TONAWANDA	S106722347	NORTHEAST SIDE OF FILMORE	TWIN CITY MEMORIAL HIGHWA	14150	NY Spills
TONAWANDA	S117654349	CSX YARD	300 RIVERVIEW BOULEVARD	14150	NY Spills
TONAWANDA	S114560310	VACANT LOT	945 KENMORE AVENUE	14150	NY Spills
TONAWANDA	S121984588	MODERN @ANDERSON FROZEN CUSTARD	2235 SHERIDAN DRIVE	14150	NY Spills
TONAWANDA	S112809929	DUPONT/INDECK	SHERIDAN	14150	NY Spills
TONAWANDA	S109205286	LI WASTE	KENMORE AVE	14150	NY Spills
TONAWANDA	S121985860	CSX RAIL YARD	KENMORE YARD MILE POST QDN10.1	14150	NY Spills
TONAWANDA	S116554412	ROADWAY	KENMORE AVE AND MILITARY RD	14150	NY Spills
TONAWANDA	S120700424	ROADSIDE	SHERIDAN DRIVE AT COOPER	14150	NY Spills
TONAWANDA	S117393416	PARKING LOT, ROAD SHOULDER, & LOADING DOCK	2750, 2760, & 2770 KENMORE AVE	14150	NY Spills
TONAWANDA	S117363192	METH LAB AT CORNER OF	MILITARY/SHERIDAN DR	14150	NY Spills
TONAWANDA	S118637964	BENDERSON DEVELOPMENT	3220 SHERIDAN DRIVE	14150	NY Spills
TONAWANDA	S117975574	PAVEMENT	2279 SHERIDAN DRIVE	14150	NY Spills
TONAWANDA	S117362171	ON ROADWAY M&M TOWING	FORD AVE/BTWN HAWTHORNE AVE SOUTHEAST CORNER	14223	NY Spills
TONAWANDA	S106736339	ST. JOHNS ST./BYRON/KLAUD	CROSS ST. KENMORE AVE.		NY Spills
TONAWANDA	S109208503	EXPERT PAINT	707 KENMORE AVENUE @STARIN		NY Spills

Count: 233 records

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
TONAWANDA	S122478720	FUEL IN FILL SUMP	1310 SHERIDAN DR		NY Spills
TONAWANDA	S112148481	POLE 1945R1	1945 SHERIDAN DR		NY Spills
TONAWANDA	S102175978	ROBERT BROSKIN	KENMORE AVENUE		NY Spills
TONAWANDA	S102176798	RED DYE IN 2 MILE CREEK	SHERIDAN PARKSIDE		NY Spills
TONAWANDA	S102680401	BOAT SUNK IN ERIE CANAL	ERIE CANAL AT MAIN STREET		NY Spills
TONAWANDA	S103562422	M.L YOUNG MOTOR EXPRESS	TWIN CITY MEMEROIL HWY		NY Spills
TONAWANDA	S109063259	BETWEEN	SHERIDAN DR& 375 RIVER RD		NY Spills
TONAWANDA	S109061226	N-SIDE BETWEEN KENMORE & I190	SHERIDAN DRIVE		NY Spills
TONAWANDA	S106014002	OIL IN DITCH	SAWYER BTW KENMORE & RIVR		NY Spills
TONAWANDA	S117853573	SPILL NUMBER 8503435	633 MOORE AVE.		NY Spills
TONAWANDA	S117853621	SPILL NUMBER 8503946	KENMORE & KLAUDER		NY Spills
TONAWANDA	S117853668	SPILL NUMBER 8504485	2221 KENMORE AVE.		NY Spills
TONAWANDA	1000432567	SERVICE STATION	MAIN ST	14150	RCRA NonGen / NLR
TONAWANDA	1000432570	SERVICE STATION	BAILEY LOCATION	14150	RCRA NonGen / NLR
TONAWANDA	1000432572	SERVICE STATION	NIAGARA FALLS BLVD LOCATION	14150	RCRA NonGen / NLR
TONAWANDA	1000432574	SERVICE STATION	MAPLE RD LOCATION	14150	RCRA NonGen / NLR
TONAWANDA	1014957331	NIAGARA MOHAWK A NATIONAL GRID CO	2272 KENMORE AVE	14150	RCRA NonGen / NLR, NY MANIFEST
TONAWANDA	1000693862	NYS THRUWAY AUTH	THRUWAY OVER SHERIDAN DR	14150	RCRA NonGen / NLR
TONAWANDA	1000693864	NYS THRUWAY AUTH	THRUWAY OVER SHERIDAN DR	14150	RCRA NonGen / NLR
TONAWANDA	1001028634	NYSDOT BIN 1044991 D256665	WB I-290 BRIDGE OVER CONRAIL	14150	RCRA NonGen / NLR
TONAWANDA	1001028635	NYSDOT BIN 1044992 D256665	EB I-290 BRIDGE OVER CONRAIL	14150	RCRA NonGen / NLR, NY MANIFEST
TONAWANDA	1014957357	NIAGARA MOHAWK A NATIONAL GRID CO	KENMORE AVE & SHERIDAN AVE	14150	RCRA NonGen / NLR, NY MANIFEST
TONAWANDA	1014628208		AAM TONAWANDA FORGE 2390 KENMORE	14150	PCB TRANSFORMER
TONAWANDA	1023369359	TONAWANDA RAILS TO TRAILS	BETWEEN KENMORE AVE & E NIAGARA ST	14150	FINDS
TONAWANDA	1016253103	NYS THRUWAY AUTH	THRUWAY OVER SHERIDAN DR	14150	FINDS, ECHO
TONAWANDA	S122376038	E I DUPONT YERKES PLANT	SHERIDAN DR AT RIVER RD		NY AIRS
TONAWANDA	S122482860	NYSDOT - BIN 1045022 D256665	EB I-290 BRG OVER COLVIN BLVD	14150	NY MANIFEST
TONAWANDA	S118954062	NYSDOT	I-290 NIAGARA FALLS BLVD	14150	NY MANIFEST
TONAWANDA	S118954158	NYSDOT BIN 1045032 D256665	EB I-290 BRG OVER PARKER BLVD	14150	NY MANIFEST
TONAWANDA	S119078351	NYSDOT BIN 1045031 D 256665	WB I-290 BRG OVER PARKER BLVD	14150	NY MANIFEST
TONAWANDA	S108934051	TOWN OF TONAWANDA WASTE TREATMENT PLANT	FOOT OF SHERIDAN DRIVE	14150	NY MANIFEST
TONAWANDA	S120678641	NYS DOT BIN 1044980	E PARK DR I-290	14150	NJ MANIFEST
TONAWANDA	S121446767	NYSDOT - BIN 1044980 D 2566665	E PARK DR BRG OVER RTE I-290	14150	NY MANIFEST
TONAWANDA	1009234888	US BULK TRANSPORT	I-290 & I-190	14150	NY MANIFEST
TONAWANDA	1009233273	NYNEX	N FALLS BLVD/ROCHELLE PKY	14150	NY MANIFEST
TONAWANDA	1009234254	NYSDEC REGION 9	SHERIDAN AND ODWIN	14150	NY MANIFEST
TONAWANDA	S117563176	NYSDOT	RTE I-290 OVER RTE I-190	14150	NY MANIFEST
TONAWANDA	S117563350	NEW YORK STATE THRUWAY AUTHORITY	THRUWAY OVER SHERIDAN DR	14150	NY MANIFEST
TONAWANDA	S117563351	NEW YORK STATE THRUWAY AUTHORITY	THRUWAY OVER SHERIDAN DR	14150	NY MANIFEST
TONAWANDA	S108933481	CSX TRANSPORTATION	300 RIVERVIEW KENMORE YARD		NY MANIFEST
TONWANDA	S121446768	NYSDOT - BIN 1044991	WB I-290 BRIDGE OVER CONRAIL	14150	NY MANIFEST
WHEATFIELD	S122482331	FORMER BELL AEROSPACE	9812 NIAGARA FALLS BLVD	14150	NY MANIFEST
WHEATFIELD	S116736427	BELL AEROSPACE TEXTRON	9812 NIAGARA FALLS BLVD	14150	PA MANIFEST
WILLIAMS VILLE	S118261106	ESTATE OF LORENZO TERUEL	5939 - 5951 MAIN STREET	14228	NY Spills
WILLIAMSVILLE	94050891		I-90 & I-290		HMIRS
WILLIAMSVILLE	S118636166	POLE 5189	MAIN STREET/LAFAYETTE STREET	14221	NY Spills
WILLIAMSVILLE	S121984671	NATIONAL GRID POLE 5320R	ON MAIN ST BEHIND 14 N LONG ST	14221	NY Spills

Count: 233 records

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
WILLIAMSVILLE	S109583297	AUDUBON GOLF COURSE	MAPLE ROAD	14221	NY Spills
WILLIAMSVILLE	S102178757	GRAVEL AND OIL ON ROAD	NORTH FOREST		NY Spills
WILLIAMSVILLE	S109061584	SOUTH OF MAPLE RD	OFF OF NORTH FOREST RD		NY Spills
WILLIAMSVILLE	S110490193	SUNOCO STATION	MAIN & TRANSIT		NY Spills
WILLIAMSVILLE	S118464355	ISKALO DEVELOPMENT CORP	5870-5872 MAIN ST	14221	NY MANIFEST
WILLIAMSVILLE	S117563045	EXXON MOBIL OIL CORP C/O GES INC	5300 MAIN ST & UNION RD	14221	NY MANIFEST

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 11/14/2018
Date Data Arrived at EDR: 11/27/2018
Date Made Active in Reports: 12/07/2018
Number of Days to Update: 10

Source: EPA
Telephone: N/A
Last EDR Contact: 12/28/2018
Next Scheduled EDR Contact: 04/15/2019
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 3
Telephone 215-814-5418

EPA Region 4
Telephone 404-562-8033

EPA Region 5
Telephone 312-886-6686

EPA Region 10
Telephone 206-553-8665

EPA Region 6
Telephone: 214-655-6659

EPA Region 7
Telephone: 913-551-7247

EPA Region 8
Telephone: 303-312-6774

EPA Region 9
Telephone: 415-947-4246

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 11/14/2018
Date Data Arrived at EDR: 11/27/2018
Date Made Active in Reports: 12/07/2018
Number of Days to Update: 10

Source: EPA
Telephone: N/A
Last EDR Contact: 12/28/2018
Next Scheduled EDR Contact: 04/15/2019
Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991
Date Data Arrived at EDR: 02/02/1994
Date Made Active in Reports: 03/30/1994
Number of Days to Update: 56

Source: EPA
Telephone: 202-564-4267
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Delisted NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 11/14/2018
Date Data Arrived at EDR: 11/27/2018
Date Made Active in Reports: 12/07/2018
Number of Days to Update: 10

Source: EPA
Telephone: N/A
Last EDR Contact: 12/28/2018
Next Scheduled EDR Contact: 04/15/2019
Data Release Frequency: Quarterly

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 11/07/2016
Date Data Arrived at EDR: 01/05/2017
Date Made Active in Reports: 04/07/2017
Number of Days to Update: 92

Source: Environmental Protection Agency
Telephone: 703-603-8704
Last EDR Contact: 01/04/2019
Next Scheduled EDR Contact: 04/15/2019
Data Release Frequency: Varies

SEMS: Superfund Enterprise Management System

SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly know as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the National Priorities List (NPL) and the sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 11/14/2018
Date Data Arrived at EDR: 11/27/2018
Date Made Active in Reports: 12/07/2018
Number of Days to Update: 10

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 12/28/2018
Next Scheduled EDR Contact: 01/28/2019
Data Release Frequency: Quarterly

SEMS-ARCHIVE: Superfund Enterprise Management System Archive

SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

Date of Government Version: 11/14/2018
Date Data Arrived at EDR: 11/28/2018
Date Made Active in Reports: 12/07/2018
Number of Days to Update: 9

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 12/28/2018
Next Scheduled EDR Contact: 01/28/2019
Data Release Frequency: Quarterly

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 03/01/2018
Date Data Arrived at EDR: 03/28/2018
Date Made Active in Reports: 06/22/2018
Number of Days to Update: 86

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 12/03/2018
Next Scheduled EDR Contact: 04/08/2019
Data Release Frequency: Quarterly

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 03/01/2018
Date Data Arrived at EDR: 03/28/2018
Date Made Active in Reports: 06/22/2018
Number of Days to Update: 86

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 12/03/2018
Next Scheduled EDR Contact: 04/08/2019
Data Release Frequency: Quarterly

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 03/01/2018
Date Data Arrived at EDR: 03/28/2018
Date Made Active in Reports: 06/22/2018
Number of Days to Update: 86

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 12/03/2018
Next Scheduled EDR Contact: 04/08/2019
Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 03/01/2018
Date Data Arrived at EDR: 03/28/2018
Date Made Active in Reports: 06/22/2018
Number of Days to Update: 86

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 12/03/2018
Next Scheduled EDR Contact: 04/08/2019
Data Release Frequency: Quarterly

RCRA-CESQG: RCRA - Conditionally Exempt Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 03/01/2018
Date Data Arrived at EDR: 03/28/2018
Date Made Active in Reports: 06/22/2018
Number of Days to Update: 86

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 12/03/2018
Next Scheduled EDR Contact: 04/08/2019
Data Release Frequency: Quarterly

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 10/17/2018
Date Data Arrived at EDR: 10/25/2018
Date Made Active in Reports: 12/07/2018
Number of Days to Update: 43

Source: Department of the Navy
Telephone: 843-820-7326
Last EDR Contact: 10/15/2018
Next Scheduled EDR Contact: 02/25/2019
Data Release Frequency: Varies

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 07/31/2018
Date Data Arrived at EDR: 08/28/2018
Date Made Active in Reports: 09/14/2018
Number of Days to Update: 17

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 11/28/2018
Next Scheduled EDR Contact: 03/11/2019
Data Release Frequency: Varies

US INST CONTROL: Sites with Institutional Controls

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 07/31/2018
Date Data Arrived at EDR: 08/28/2018
Date Made Active in Reports: 09/14/2018
Number of Days to Update: 17

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 11/28/2018
Next Scheduled EDR Contact: 03/11/2019
Data Release Frequency: Varies

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 09/24/2018
Date Data Arrived at EDR: 09/25/2018
Date Made Active in Reports: 11/09/2018
Number of Days to Update: 45

Source: National Response Center, United States Coast Guard
Telephone: 202-267-2180
Last EDR Contact: 01/08/2019
Next Scheduled EDR Contact: 04/08/2019
Data Release Frequency: Quarterly

STANDARD ENVIRONMENTAL RECORDS

State- and tribal - equivalent CERCLIS

NY SHWS: Inactive Hazardous Waste Disposal Sites in New York State

Referred to as the State Superfund Program, the Inactive Hazardous Waste Disposal Site Remedial Program is the cleanup program for inactive hazardous waste sites and now includes hazardous substance sites

Date of Government Version: 11/12/2018
Date Data Arrived at EDR: 11/14/2018
Date Made Active in Reports: 12/19/2018
Number of Days to Update: 35

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 11/14/2018
Next Scheduled EDR Contact: 02/25/2019
Data Release Frequency: Annually

State and tribal landfill and/or solid waste disposal site lists

NY SWF/LF: Facility Register

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 09/30/2018
Date Data Arrived at EDR: 10/03/2018
Date Made Active in Reports: 11/07/2018
Number of Days to Update: 35

Source: Department of Environmental Conservation
Telephone: 518-457-2051
Last EDR Contact: 01/04/2019
Next Scheduled EDR Contact: 04/15/2019
Data Release Frequency: Quarterly

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land
A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 04/13/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63
Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 10/26/2018
Next Scheduled EDR Contact: 02/04/2019
Data Release Frequency: Varies

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land
A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 04/13/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63
Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 10/26/2018
Next Scheduled EDR Contact: 02/04/2019
Data Release Frequency: Varies

INDIAN LUST R5: Leaking Underground Storage Tanks on Indian Land
A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 04/13/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63
Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 10/26/2018
Next Scheduled EDR Contact: 02/04/2019
Data Release Frequency: Varies

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land
A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 04/13/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63
Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 10/26/2018
Next Scheduled EDR Contact: 02/04/2019
Data Release Frequency: Varies

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land
A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 04/13/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63
Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 10/26/2018
Next Scheduled EDR Contact: 02/04/2019
Data Release Frequency: Varies

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land
A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 04/13/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63
Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 10/26/2018
Next Scheduled EDR Contact: 02/04/2019
Data Release Frequency: Varies

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land
A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 04/13/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63
Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 10/26/2018
Next Scheduled EDR Contact: 02/04/2019
Data Release Frequency: Varies

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land
A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 04/13/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63
Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 10/26/2018
Next Scheduled EDR Contact: 02/04/2019
Data Release Frequency: Varies

State and tribal leaking storage tank lists

NY LTANKS: Spills Information Database
Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills.

Date of Government Version: 11/12/2018
Date Data Arrived at EDR: 11/14/2018
Date Made Active in Reports: 12/20/2018
Number of Days to Update: 36
Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 11/14/2018
Next Scheduled EDR Contact: 02/25/2019
Data Release Frequency: Varies

NY HIST LTANKS: Listing of Leaking Storage Tanks
A listing of leaking underground and aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills. In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY LTANKS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6
Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

FEMA UST: Underground Storage Tank Listing
A listing of all FEMA owned underground storage tanks.

Date of Government Version: 05/15/2017
Date Data Arrived at EDR: 05/30/2017
Date Made Active in Reports: 10/13/2017
Number of Days to Update: 136
Source: FEMA
Telephone: 202-646-5797
Last EDR Contact: 01/08/2019
Next Scheduled EDR Contact: 04/22/2019
Data Release Frequency: Varies

State and tribal registered storage tank lists

NY UST: Petroleum Bulk Storage (PBS) Database
Facilities that have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons.

Date of Government Version: 09/25/2018
Date Data Arrived at EDR: 09/26/2018
Date Made Active in Reports: 10/12/2018
Number of Days to Update: 16
Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 12/26/2018
Next Scheduled EDR Contact: 04/08/2019
Data Release Frequency: No Update Planned

NY CBS UST: Chemical Bulk Storage Database
Facilities that store regulated hazardous substances in underground tanks of any size

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30
Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 10/24/2005
Next Scheduled EDR Contact: 01/23/2006
Data Release Frequency: No Update Planned

NY MOSF UST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

NY MOSF: Major Oil Storage Facility Site Listing

These facilities may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 09/25/2018
Date Data Arrived at EDR: 09/26/2018
Date Made Active in Reports: 10/12/2018
Number of Days to Update: 16

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 12/26/2018
Next Scheduled EDR Contact: 04/08/2019
Data Release Frequency: Quarterly

NY CBS: Chemical Bulk Storage Site Listing

These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

Date of Government Version: 09/25/2018
Date Data Arrived at EDR: 09/26/2018
Date Made Active in Reports: 10/12/2018
Number of Days to Update: 16

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 12/26/2018
Next Scheduled EDR Contact: 04/08/2019
Data Release Frequency: Quarterly

NY AST: Petroleum Bulk Storage

Registered Aboveground Storage Tanks.

Date of Government Version: 09/25/2018
Date Data Arrived at EDR: 09/26/2018
Date Made Active in Reports: 10/12/2018
Number of Days to Update: 16

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 12/26/2018
Next Scheduled EDR Contact: 04/08/2019
Data Release Frequency: No Update Planned

NY CBS AST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

NY MOSF AST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

INDIAN UST R7: Underground Storage Tanks on Indian Land

Date of Government Version: 04/06/2016
Date Data Arrived at EDR: 03/02/2017
Date Made Active in Reports: 04/07/2017
Number of Days to Update: 36

Source: N/A
Telephone: N/A
Last EDR Contact: 10/26/2018
Next Scheduled EDR Contact: 02/04/2019
Data Release Frequency: Varies

INDIAN UST R5: Underground Storage Tanks on Indian Land

Date of Government Version: 04/06/2016
Date Data Arrived at EDR: 03/02/2017
Date Made Active in Reports: 04/07/2017
Number of Days to Update: 36

Source: N/A
Telephone: N/A
Last EDR Contact: 10/26/2018
Next Scheduled EDR Contact: 02/04/2019
Data Release Frequency: Varies

INDIAN UST R6: Underground Storage Tanks on Indian Land

Date of Government Version: 04/06/2016
Date Data Arrived at EDR: 03/02/2017
Date Made Active in Reports: 04/07/2017
Number of Days to Update: 36

Source: N/A
Telephone: N/A
Last EDR Contact: 10/26/2018
Next Scheduled EDR Contact: 02/04/2019
Data Release Frequency: Varies

INDIAN UST R1: Underground Storage Tanks on Indian Land

Date of Government Version: 04/06/2016
Date Data Arrived at EDR: 03/02/2017
Date Made Active in Reports: 04/07/2017
Number of Days to Update: 36

Source: N/A
Telephone: N/A
Last EDR Contact: 10/26/2018
Next Scheduled EDR Contact: 02/04/2019
Data Release Frequency: Varies

INDIAN UST R4: Underground Storage Tanks on Indian Land

Date of Government Version: 04/06/2016
Date Data Arrived at EDR: 03/02/2017
Date Made Active in Reports: 04/07/2017
Number of Days to Update: 36

Source: N/A
Telephone: N/A
Last EDR Contact: 10/26/2018
Next Scheduled EDR Contact: 02/04/2019
Data Release Frequency: Varies

INDIAN UST R10: Underground Storage Tanks on Indian Land

Date of Government Version: 04/06/2016
Date Data Arrived at EDR: 03/02/2017
Date Made Active in Reports: 04/07/2017
Number of Days to Update: 36

Source: N/A
Telephone: N/A
Last EDR Contact: 10/26/2018
Next Scheduled EDR Contact: 02/04/2019
Data Release Frequency: Varies

INDIAN UST R9: Underground Storage Tanks on Indian Land

Date of Government Version: 04/06/2016
Date Data Arrived at EDR: 03/02/2017
Date Made Active in Reports: 04/07/2017
Number of Days to Update: 36

Source: N/A
Telephone: N/A
Last EDR Contact: 10/26/2018
Next Scheduled EDR Contact: 02/04/2019
Data Release Frequency: Varies

INDIAN UST R8: Underground Storage Tanks on Indian Land

Date of Government Version: 04/06/2016
Date Data Arrived at EDR: 03/02/2017
Date Made Active in Reports: 04/07/2017
Number of Days to Update: 36

Source: N/A
Telephone: N/A
Last EDR Contact: 10/26/2018
Next Scheduled EDR Contact: 02/04/2019
Data Release Frequency: Varies

NY TANKS: Storage Tank Faciliy Listing

This database contains records of facilities that are or have been regulated under Bulk Storage Program. Tank information for these facilities may not be releasable by the state agency.

Date of Government Version: 09/25/2018
Date Data Arrived at EDR: 09/26/2018
Date Made Active in Reports: 10/12/2018
Number of Days to Update: 16

Source: Department of Environmental Conservation
Telephone: 518-402-9543
Last EDR Contact: 12/26/2018
Next Scheduled EDR Contact: 04/08/2019
Data Release Frequency: Quarterly

State and tribal institutional control / engineering control registries

NY RES DECL: Restrictive Declarations Listing

A restrictive declaration is a covenant running with the land which binds the present and future owners of the property. As a condition of certain special permits, the City Planning Commission may require an applicant to sign and record a restrictive declaration that places specified conditions on the future use and development of the property. Certain restrictive declarations are indicated by a D on zoning maps.

Date of Government Version: 11/18/2010
Date Data Arrived at EDR: 06/30/2014
Date Made Active in Reports: 07/21/2014
Number of Days to Update: 21

Source: NYC Department of City Planning
Telephone: 212-720-3401
Last EDR Contact: 12/21/2018
Next Scheduled EDR Contact: 04/01/2019
Data Release Frequency: Varies

NY ENV RES DECL: Environmental Restrictive Declarations

The Environmental Restrictive Declarations (ERD) listed were recorded in connection with a zoning action against the noted Tax Blocks and Tax Lots, or portion thereof, and are available in the property records on file at the Office of the City Register for Bronx, Kings, New York and Queens counties or at the Richmond County Clerk's office. They contain environmental requirements with respect to hazardous materials, air quality and/or noise in accordance with Section 11-15 of this Resolution.

Date of Government Version: 05/15/2018
Date Data Arrived at EDR: 06/26/2018
Date Made Active in Reports: 08/07/2018
Number of Days to Update: 42

Source: New York City Department of City Planning
Telephone: 212-720-3300
Last EDR Contact: 12/17/2018
Next Scheduled EDR Contact: 04/01/2019
Data Release Frequency: Varies

NY ENG CONTROLS: Registry of Engineering Controls

Environmental Remediation sites that have engineering controls in place.

Date of Government Version: 11/12/2018
Date Data Arrived at EDR: 11/14/2018
Date Made Active in Reports: 12/19/2018
Number of Days to Update: 35

Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 11/14/2018
Next Scheduled EDR Contact: 02/25/2019
Data Release Frequency: Quarterly

NY INST CONTROL: Registry of Institutional Controls

Environmental Remediation sites that have institutional controls in place.

Date of Government Version: 11/12/2018
Date Data Arrived at EDR: 11/14/2018
Date Made Active in Reports: 12/19/2018
Number of Days to Update: 35

Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 11/14/2018
Next Scheduled EDR Contact: 02/25/2019
Data Release Frequency: Quarterly

State and tribal voluntary cleanup sites

NY VCP NYC: Voluntary Cleanup Program Listing NYC

New York City voluntary cleanup program sites.

Date of Government Version: 03/26/2018
Date Data Arrived at EDR: 03/29/2018
Date Made Active in Reports: 05/14/2018
Number of Days to Update: 46

Source: New York City Office of Environmental Protection
Telephone: 212-788-8841
Last EDR Contact: 12/14/2018
Next Scheduled EDR Contact: 04/01/2019
Data Release Frequency: Varies

INDIAN VCP R1: Voluntary Cleanup Priority Lisitng

A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27

Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 04/20/2009
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: Varies

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng

A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27

Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 04/20/2009
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: Varies

NY VCP: Voluntary Cleanup Agreements

New York established its Voluntary Cleanup Program (VCP) to address the environmental, legal and financial barriers that often hinder the redevelopment and reuse of contaminated properties. The Voluntary Cleanup Program was developed to enhance private sector cleanup of brownfields by enabling parties to remediate sites using private rather than public funds and to reduce the development pressures on "greenfield" sites.

Date of Government Version: 11/12/2018
Date Data Arrived at EDR: 11/14/2018
Date Made Active in Reports: 12/19/2018
Number of Days to Update: 35

Source: Department of Environmental Conservation
Telephone: 518-402-9711
Last EDR Contact: 11/14/2018
Next Scheduled EDR Contact: 02/25/2019
Data Release Frequency: Semi-Annually

State and tribal Brownfields sites

NY BROWNFIELDS: Brownfields Site List

A Brownfield is any real property where redevelopment or re-use may be complicated by the presence or potential presence of a hazardous waste, petroleum, pollutant, or contaminant.

Date of Government Version: 11/12/2018
Date Data Arrived at EDR: 11/14/2018
Date Made Active in Reports: 12/19/2018
Number of Days to Update: 35

Source: Department of Environmental Conservation
Telephone: 518-402-9764
Last EDR Contact: 11/14/2018
Next Scheduled EDR Contact: 02/25/2019
Data Release Frequency: Semi-Annually

NY ERP: Environmental Restoration Program Listing

In an effort to spur the cleanup and redevelopment of brownfields, New Yorkers approved a $200 million Environmental Restoration or Brownfields Fund as part of the $1.75 billion Clean Water/Clean Air Bond Act of 1996 (1996 Bond Act). Enhancements to the program were enacted on October 7, 2003. Under the Environmental Restoration Program, the State provides grants to municipalities to reimburse up to 90 percent of on-site eligible costs and 100% of off-site eligible costs for site investigation and remediation activities. Once remediated, the property may then be reused for commercial, industrial, residential or public use.

Date of Government Version: 11/12/2018
Date Data Arrived at EDR: 11/14/2018
Date Made Active in Reports: 12/19/2018
Number of Days to Update: 35

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 11/14/2018
Next Scheduled EDR Contact: 02/25/2019
Data Release Frequency: Quarterly

US BROWNFIELDS: A Listing of Brownfields Sites

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 09/18/2018
Date Data Arrived at EDR: 09/18/2018
Date Made Active in Reports: 11/09/2018
Number of Days to Update: 52

Source: Environmental Protection Agency
Telephone: 202-566-2777
Last EDR Contact: 12/18/2018
Next Scheduled EDR Contact: 04/01/2019
Data Release Frequency: Semi-Annually

ADDITIONAL ENVIRONMENTAL RECORDS

Local Lists of Landfill / Solid Waste Disposal Sites

NY SWTIRE: Registered Waste Tire Storage & Facility List

A listing of facilities registered to accept waste tires.

Date of Government Version: 02/27/2018
Date Data Arrived at EDR: 04/06/2018
Date Made Active in Reports: 06/08/2018
Number of Days to Update: 63

Source: Department of Environmental Conservation
Telephone: 518-402-8694
Last EDR Contact: 12/07/2018
Next Scheduled EDR Contact: 03/25/2019
Data Release Frequency: No Update Planned

NY SWRCY: Registered Recycling Facility List

A listing of recycling facilities.

Date of Government Version: 09/30/2018
Date Data Arrived at EDR: 10/03/2018
Date Made Active in Reports: 11/07/2018
Number of Days to Update: 35

Source: Department of Environmental Conservation
Telephone: 518-402-8705
Last EDR Contact: 01/04/2019
Next Scheduled EDR Contact: 04/15/2019
Data Release Frequency: Quarterly

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands

Location of open dumps on Indian land.

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52

Source: Environmental Protection Agency
Telephone: 703-308-8245
Last EDR Contact: 10/25/2018
Next Scheduled EDR Contact: 02/11/2019
Data Release Frequency: Varies

ODI: Open Dump Inventory

An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985
Date Data Arrived at EDR: 08/09/2004
Date Made Active in Reports: 09/17/2004
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 800-424-9346
Last EDR Contact: 06/09/2004
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations

A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 137

Source: EPA, Region 9
Telephone: 415-947-4219
Last EDR Contact: 10/22/2018
Next Scheduled EDR Contact: 02/04/2019
Data Release Frequency: No Update Planned

IHS OPEN DUMPS: Open Dumps on Indian Land

A listing of all open dumps located on Indian Land in the United States.

Date of Government Version: 04/01/2014
Date Data Arrived at EDR: 08/06/2014
Date Made Active in Reports: 01/29/2015
Number of Days to Update: 176

Source: Department of Health & Human Serivces, Indian Health Service
Telephone: 301-443-1452
Last EDR Contact: 11/02/2018
Next Scheduled EDR Contact: 02/11/2019
Data Release Frequency: Varies

US HIST CDL: National Clandestine Laboratory Register

A listing of clandestine drug lab locations that have been removed from the DEAs National Clandestine Laboratory Register.

Date of Government Version: 09/21/2018
Date Data Arrived at EDR: 09/21/2018
Date Made Active in Reports: 11/09/2018
Number of Days to Update: 49

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 11/26/2018
Next Scheduled EDR Contact: 03/11/2019
Data Release Frequency: No Update Planned

Local Lists of Hazardous waste / Contaminated Sites

NY DEL SHWS: Delisted Registry Sites

A database listing of sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites.

Date of Government Version: 11/12/2018
Date Data Arrived at EDR: 11/14/2018
Date Made Active in Reports: 12/19/2018
Number of Days to Update: 35

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 11/14/2018
Next Scheduled EDR Contact: 02/25/2019
Data Release Frequency: Quarterly

US CDL: Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 09/21/2018
Date Data Arrived at EDR: 09/21/2018
Date Made Active in Reports: 11/09/2018
Number of Days to Update: 49

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 11/26/2018
Next Scheduled EDR Contact: 03/11/2019
Data Release Frequency: Quarterly

Local Lists of Registered Storage Tanks

NY HIST UST: Historical Petroleum Bulk Storage Database

These facilities have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. It is no longer updated due to the sensitive nature of the information involved. See UST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: Varies

NY HIST AST: Historical Petroleum Bulk Storage Database

These facilities have petroleum storage capabilities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. No longer updated due to the sensitive nature of the information involved. See AST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: No Update Planned

Local Land Records

NY LIENS: Spill Liens Information

Lien information from the Oil Spill Fund.

Date of Government Version: 11/06/2018
Date Data Arrived at EDR: 11/07/2018
Date Made Active in Reports: 12/19/2018
Number of Days to Update: 42

Source: Office of the State Comptroller
Telephone: 518-474-9034
Last EDR Contact: 11/05/2018
Next Scheduled EDR Contact: 02/18/2019
Data Release Frequency: Quarterly

LIENS 2: CERCLA Lien Information

A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 08/13/2018
Date Data Arrived at EDR: 10/04/2018
Date Made Active in Reports: 11/16/2018
Number of Days to Update: 43

Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 12/28/2018
Next Scheduled EDR Contact: 02/04/2019
Data Release Frequency: Semi-Annually

HMIRS: Hazardous Materials Information Reporting System

Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 03/26/2018
Date Data Arrived at EDR: 03/27/2018
Date Made Active in Reports: 06/08/2018
Number of Days to Update: 73

Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 01/08/2019
Next Scheduled EDR Contact: 04/08/2019
Data Release Frequency: Quarterly

Records of Emergency Release Reports

NY SPILLS: Spills Information Database

Data collected on spills reported to NYSDEC as required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

Date of Government Version: 11/12/2018
Date Data Arrived at EDR: 11/14/2018
Date Made Active in Reports: 12/20/2018
Number of Days to Update: 36

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 11/14/2018
Next Scheduled EDR Contact: 02/25/2019
Data Release Frequency: Varies

NY HIST SPILLS: SPILLS Database

This database contains records of chemical and petroleum spill incidents. Under State law, petroleum and hazardous chemical spills that can impact the waters of the state must be reported by the spiller (and, in some cases, by anyone who has knowledge of the spills). In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY SPILLS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

NY SPILLS 90: SPILLS90 data from FirstSearch

Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.

Date of Government Version: 12/14/2012
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 02/12/2013
Number of Days to Update: 40

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

NY SPILLS 80: SPILLS80 data from FirstSearch

Spills 80 includes those spill and release records available from FirstSearch databases prior to 1990. Typically, they may include chemical, oil and/or hazardous substance spills recorded before 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 80.

Date of Government Version: 11/02/2010
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 03/07/2013
Number of Days to Update: 63

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

RCRA NonGen / NLR: RCRA - Non Generators / No Longer Regulated

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 03/01/2018
Date Data Arrived at EDR: 03/28/2018
Date Made Active in Reports: 06/22/2018
Number of Days to Update: 86

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 12/03/2018
Next Scheduled EDR Contact: 04/08/2019
Data Release Frequency: Quarterly

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 01/31/2015
Date Data Arrived at EDR: 07/08/2015
Date Made Active in Reports: 10/13/2015
Number of Days to Update: 97

Source: U.S. Army Corps of Engineers
Telephone: 202-528-4285
Last EDR Contact: 11/19/2018
Next Scheduled EDR Contact: 03/04/2019
Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 11/10/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 62

Source: USGS
Telephone: 888-275-8747
Last EDR Contact: 10/12/2018
Next Scheduled EDR Contact: 01/21/2019
Data Release Frequency: Semi-Annually

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 02/06/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 339

Source: U.S. Geological Survey
Telephone: 888-275-8747
Last EDR Contact: 10/12/2018
Next Scheduled EDR Contact: 01/21/2019
Data Release Frequency: N/A

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 01/01/2017
Date Data Arrived at EDR: 02/03/2017
Date Made Active in Reports: 04/07/2017
Number of Days to Update: 63

Source: Environmental Protection Agency
Telephone: 615-532-8599
Last EDR Contact: 11/16/2018
Next Scheduled EDR Contact: 02/25/2019
Data Release Frequency: Varies

US FIN ASSUR: Financial Assurance Information

All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 08/31/2018
Date Data Arrived at EDR: 09/25/2018
Date Made Active in Reports: 11/09/2018
Number of Days to Update: 45

Source: Environmental Protection Agency
Telephone: 202-566-1917
Last EDR Contact: 12/21/2018
Next Scheduled EDR Contact: 04/08/2019
Data Release Frequency: Quarterly

EPA WATCH LIST: EPA WATCH LIST

EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

Date of Government Version: 08/30/2013
Date Data Arrived at EDR: 03/21/2014
Date Made Active in Reports: 06/17/2014
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 617-520-3000
Last EDR Contact: 11/05/2018
Next Scheduled EDR Contact: 02/18/2019
Data Release Frequency: Quarterly

2020 COR ACTION: 2020 Corrective Action Program List

The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 09/30/2017
Date Data Arrived at EDR: 05/08/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 73

Source: Environmental Protection Agency
Telephone: 703-308-4044
Last EDR Contact: 11/09/2018
Next Scheduled EDR Contact: 02/18/2019
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2016
Date Data Arrived at EDR: 06/21/2017
Date Made Active in Reports: 01/05/2018
Number of Days to Update: 198

Source: EPA
Telephone: 202-260-5521
Last EDR Contact: 12/21/2018
Next Scheduled EDR Contact: 04/01/2019
Data Release Frequency: Every 4 Years

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2016
Date Data Arrived at EDR: 01/10/2018
Date Made Active in Reports: 01/12/2018
Number of Days to Update: 2

Source: EPA
Telephone: 202-566-0250
Last EDR Contact: 11/16/2018
Next Scheduled EDR Contact: 03/04/2019
Data Release Frequency: Annually

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 12/31/2009
Date Data Arrived at EDR: 12/10/2010
Date Made Active in Reports: 02/25/2011
Number of Days to Update: 77

Source: EPA
Telephone: 202-564-4203
Last EDR Contact: 10/24/2018
Next Scheduled EDR Contact: 02/04/2019
Data Release Frequency: Annually

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 08/13/2018
Date Data Arrived at EDR: 10/04/2018
Date Made Active in Reports: 11/16/2018
Number of Days to Update: 43

Source: EPA
Telephone: 703-416-0223
Last EDR Contact: 12/28/2018
Next Scheduled EDR Contact: 03/18/2019
Data Release Frequency: Annually

RMP: Risk Management Plans

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 08/01/2018
Date Data Arrived at EDR: 08/22/2018
Date Made Active in Reports: 10/05/2018
Number of Days to Update: 44

Source: Environmental Protection Agency
Telephone: 202-564-8600
Last EDR Contact: 10/23/2018
Next Scheduled EDR Contact: 02/04/2019
Data Release Frequency: Varies

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995
Date Data Arrived at EDR: 07/03/1995
Date Made Active in Reports: 08/07/1995
Number of Days to Update: 35

Source: EPA
Telephone: 202-564-4104
Last EDR Contact: 06/02/2008
Next Scheduled EDR Contact: 09/01/2008
Data Release Frequency: No Update Planned

PRP: Potentially Responsible Parties

A listing of verified Potentially Responsible Parties

Date of Government Version: 08/13/2018
Date Data Arrived at EDR: 10/04/2018
Date Made Active in Reports: 11/09/2018
Number of Days to Update: 36

Source: EPA
Telephone: 202-564-6023
Last EDR Contact: 12/28/2018
Next Scheduled EDR Contact: 02/18/2019
Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 09/14/2018
Date Data Arrived at EDR: 10/11/2018
Date Made Active in Reports: 12/07/2018
Number of Days to Update: 57

Source: EPA
Telephone: 202-566-0500
Last EDR Contact: 10/11/2018
Next Scheduled EDR Contact: 01/21/2019
Data Release Frequency: Annually

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 11/18/2016
Date Data Arrived at EDR: 11/23/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 79

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 01/07/2019
Next Scheduled EDR Contact: 04/22/2019
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: Quarterly

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: Quarterly

MLTS: Material Licensing Tracking System
MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 08/30/2016
Date Data Arrived at EDR: 09/08/2016
Date Made Active in Reports: 10/21/2016
Number of Days to Update: 43
Source: Nuclear Regulatory Commission
Telephone: 301-415-7169
Last EDR Contact: 10/11/2018
Next Scheduled EDR Contact: 02/04/2019
Data Release Frequency: Quarterly

COAL ASH DOE: Steam-Electric Plant Operation Data
A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 08/07/2009
Date Made Active in Reports: 10/22/2009
Number of Days to Update: 76
Source: Department of Energy
Telephone: 202-586-8719
Last EDR Contact: 12/05/2018
Next Scheduled EDR Contact: 03/18/2019
Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List
A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 07/01/2014
Date Data Arrived at EDR: 09/10/2014
Date Made Active in Reports: 10/20/2014
Number of Days to Update: 40
Source: Environmental Protection Agency
Telephone: N/A
Last EDR Contact: 12/03/2018
Next Scheduled EDR Contact: 03/18/2019
Data Release Frequency: Varies

PCB TRANSFORMER: PCB Transformer Registration Database
The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 05/24/2017
Date Data Arrived at EDR: 11/30/2017
Date Made Active in Reports: 12/15/2017
Number of Days to Update: 15
Source: Environmental Protection Agency
Telephone: 202-566-0517
Last EDR Contact: 10/26/2018
Next Scheduled EDR Contact: 02/04/2019
Data Release Frequency: Varies

RADINFO: Radiation Information Database

The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 10/02/2018
Date Data Arrived at EDR: 10/03/2018
Date Made Active in Reports: 11/09/2018
Number of Days to Update: 37

Source: Environmental Protection Agency
Telephone: 202-343-9775
Last EDR Contact: 01/03/2019
Next Scheduled EDR Contact: 04/15/2019
Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing

A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing

A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

DOT OPS: Incident and Accident Data

Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 07/31/2012
Date Data Arrived at EDR: 08/07/2012
Date Made Active in Reports: 09/18/2012
Number of Days to Update: 42

Source: Department of Transporation, Office of Pipeline Safety
Telephone: 202-366-4595
Last EDR Contact: 10/30/2018
Next Scheduled EDR Contact: 02/11/2019
Data Release Frequency: Varies

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 09/30/2018
Date Data Arrived at EDR: 10/12/2018
Date Made Active in Reports: 12/07/2018
Number of Days to Update: 56

Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 01/07/2019
Next Scheduled EDR Contact: 04/22/2019
Data Release Frequency: Varies

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2015
Date Data Arrived at EDR: 02/22/2017
Date Made Active in Reports: 09/28/2017
Number of Days to Update: 218
Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 11/21/2018
Next Scheduled EDR Contact: 03/04/2019
Data Release Frequency: Biennially

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 07/14/2015
Date Made Active in Reports: 01/10/2017
Number of Days to Update: 546
Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 01/07/2019
Next Scheduled EDR Contact: 04/22/2019
Data Release Frequency: Semi-Annually

FUSRAP: Formerly Utilized Sites Remedial Action Program

DOE established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations.

Date of Government Version: 08/08/2017
Date Data Arrived at EDR: 09/11/2018
Date Made Active in Reports: 09/14/2018
Number of Days to Update: 3
Source: Department of Energy
Telephone: 202-586-3559
Last EDR Contact: 11/01/2018
Next Scheduled EDR Contact: 02/18/2019
Data Release Frequency: Varies

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 06/23/2017
Date Data Arrived at EDR: 10/11/2017
Date Made Active in Reports: 11/03/2017
Number of Days to Update: 23
Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 12/14/2018
Next Scheduled EDR Contact: 03/04/2019
Data Release Frequency: Varies

LEAD SMELTER 1: Lead Smelter Sites

A listing of former lead smelter site locations.

Date of Government Version: 08/13/2018
Date Data Arrived at EDR: 10/04/2018
Date Made Active in Reports: 11/16/2018
Number of Days to Update: 43
Source: Environmental Protection Agency
Telephone: 703-603-8787
Last EDR Contact: 12/28/2018
Next Scheduled EDR Contact: 04/15/2019
Data Release Frequency: Varies

LEAD SMELTER 2: Lead Smelter Sites

A listing of former lead smelter site locations.

Date of Government Version: 08/13/2018
Date Data Arrived at EDR: 10/04/2018
Date Made Active in Reports: 11/16/2018
Number of Days to Update: 43
Source: Environmental Protection Agency
Telephone: 703-603-8787
Last EDR Contact: 12/28/2018
Next Scheduled EDR Contact: 04/15/2019
Data Release Frequency: Varies

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem

Date of Government Version: 10/27/2009
Date Data Arrived at EDR: 11/10/2009
Date Made Active in Reports: 12/08/2009
Number of Days to Update: 28
Source: N/A
Telephone: N/A
Last EDR Contact: 11/12/1996
Next Scheduled EDR Contact: N/A
Data Release Frequency: Annually

US AIRS MINOR: Aerometric Information Retrieval System Facility Subsystem

Date of Government Version: 10/27/2009
Date Data Arrived at EDR: 11/10/2009
Date Made Active in Reports: 12/08/2009
Number of Days to Update: 28

Source: N/A
Telephone: N/A
Last EDR Contact: 11/12/1996
Next Scheduled EDR Contact: N/A
Data Release Frequency: Annually

US MINES: Active Mines & Mineral Plants Database Listing

Active Mines and Mineral Processing Plant operations for commodities monitored by the Minerals Information Team of the USGS.

Date of Government Version: 04/14/2011
Date Data Arrived at EDR: 06/08/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 97

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 11/30/2018
Next Scheduled EDR Contact: 03/11/2019
Data Release Frequency: Varies

US MINES 2: Active Mines & Mineral Plants Database Listing

Active Mines and Mineral Processing Plant operations for commodities monitored by the Minerals Information Team of the USGS.

Date of Government Version: 04/14/2011
Date Data Arrived at EDR: 06/08/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 97

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 11/30/2018
Next Scheduled EDR Contact: 03/11/2019
Data Release Frequency: Varies

US MINES 3: Active Mines & Mineral Plants Database Listing

Active Mines and Mineral Processing Plant operations for commodities monitored by the Minerals Information Team of the USGS.

Date of Government Version: 04/14/2011
Date Data Arrived at EDR: 06/08/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 97

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 11/30/2018
Next Scheduled EDR Contact: 03/11/2019
Data Release Frequency: Varies

ABANDONED MINES: Abandoned Mines

An inventory of land and water impacted by past mining (primarily coal mining) is maintained by OSMRE to provide information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). The inventory contains information on the location, type, and extent of AML impacts, as well as, information on the cost associated with the reclamation of those problems. The inventory is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed.

Date of Government Version: 09/10/2018
Date Data Arrived at EDR: 09/11/2018
Date Made Active in Reports: 09/14/2018
Number of Days to Update: 3

Source: Department of Interior
Telephone: 202-208-2609
Last EDR Contact: 12/19/2018
Next Scheduled EDR Contact: 03/25/2019
Data Release Frequency: Quarterly

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 08/07/2018
Date Data Arrived at EDR: 09/05/2018
Date Made Active in Reports: 10/05/2018
Number of Days to Update: 30

Source: EPA
Telephone: (212) 637-3000
Last EDR Contact: 01/08/2019
Next Scheduled EDR Contact: 03/18/2019
Data Release Frequency: Quarterly

UXO: Unexploded Ordnance Sites
A listing of unexploded ordnance site locations

Date of Government Version: 09/30/2017
Date Data Arrived at EDR: 06/19/2018
Date Made Active in Reports: 09/14/2018
Number of Days to Update: 87

Source: Department of Defense
Telephone: 703-704-1564
Last EDR Contact: 10/15/2018
Next Scheduled EDR Contact: 01/28/2019
Data Release Frequency: Varies

DOCKET HWC: Hazardous Waste Compliance Docket Listing
A complete list of the Federal Agency Hazardous Waste Compliance Docket Facilities.

Date of Government Version: 05/31/2018
Date Data Arrived at EDR: 07/26/2018
Date Made Active in Reports: 10/05/2018
Number of Days to Update: 71

Source: Environmental Protection Agency
Telephone: 202-564-0527
Last EDR Contact: 11/30/2018
Next Scheduled EDR Contact: 03/11/2019
Data Release Frequency: Varies

ECHO: Enforcement & Compliance History Information
ECHO provides integrated compliance and enforcement information for about 800,000 regulated facilities nationwide.

Date of Government Version: 09/02/2018
Date Data Arrived at EDR: 09/05/2018
Date Made Active in Reports: 09/14/2018
Number of Days to Update: 9

Source: Environmental Protection Agency
Telephone: 202-564-2280
Last EDR Contact: 01/07/2019
Next Scheduled EDR Contact: 03/18/2019
Data Release Frequency: Quarterly

FUELS PROGRAM: EPA Fuels Program Registered Listing
This listing includes facilities that are registered under the Part 80 (Code of Federal Regulations) EPA Fuels Programs. All companies now are required to submit new and updated registrations.

Date of Government Version: 08/22/2018
Date Data Arrived at EDR: 08/22/2018
Date Made Active in Reports: 10/05/2018
Number of Days to Update: 44

Source: EPA
Telephone: 800-385-6164
Last EDR Contact: 11/19/2018
Next Scheduled EDR Contact: 03/04/2019
Data Release Frequency: Quarterly

Other Ascertainable Records

NY AIRS: Air Emissions Data
Point source emissions inventory data.

Date of Government Version: 11/06/2018
Date Data Arrived at EDR: 11/08/2018
Date Made Active in Reports: 12/18/2018
Number of Days to Update: 40

Source: Department of Environmental Conservation
Telephone: 518-402-8452
Last EDR Contact: 11/22/2018
Next Scheduled EDR Contact: 02/04/2019
Data Release Frequency: Annually

NY COAL ASH: Coal Ash Disposal Site Listing
A listing of coal ash disposal site locations.

Date of Government Version: 06/29/2018
Date Data Arrived at EDR: 07/03/2018
Date Made Active in Reports: 08/07/2018
Number of Days to Update: 35

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 12/27/2018
Next Scheduled EDR Contact: 04/15/2019
Data Release Frequency: Quarterly

NY DRYCLEANERS: Registered Drycleaners

A listing of all registered drycleaning facilities.

Date of Government Version: 03/07/2018
Date Data Arrived at EDR: 03/30/2018
Date Made Active in Reports: 06/05/2018
Number of Days to Update: 67

Source: Department of Environmental Conservation
Telephone: 518-402-8403
Last EDR Contact: 12/07/2018
Next Scheduled EDR Contact: 03/25/2019
Data Release Frequency: Annually

NY E DESIGNATION: E DESIGNATION SITE LISTING

The (E (Environmental)) designation would ensure that sampling and remediation take place on the subject properties, and would avoid any significant impacts related to hazardous materials at these locations. The (E) designations would require that the fee owner of the sites conduct a testing and sampling protocol, and remediation where appropriate, to the satisfaction of the NYCDEP before the issuance of a building permit by the Department of Buildings pursuant to the provisions of Section 11-15 of the Zoning Resolution (Environmental Requirements). The (E) designations also include a mandatory construction-related health and safety plan which must be approved by NYCDEP.

Date of Government Version: 08/21/2018
Date Data Arrived at EDR: 09/20/2018
Date Made Active in Reports: 10/12/2018
Number of Days to Update: 22

Source: New York City Department of City Planning
Telephone: 718-595-6658
Last EDR Contact: 12/17/2018
Next Scheduled EDR Contact: 04/01/2019
Data Release Frequency: Semi-Annually

NY Financial Assurance 1: Financial Assurance Information Listing

Financial assurance information.

Date of Government Version: 12/01/2017
Date Data Arrived at EDR: 01/02/2018
Date Made Active in Reports: 01/31/2018
Number of Days to Update: 29

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 12/27/2018
Next Scheduled EDR Contact: 04/15/2019
Data Release Frequency: Quarterly

NY Financial Assurance 2: Financial Assurance Information Listing

A listing of financial assurance information for hazardous waste facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 12/29/2017
Date Data Arrived at EDR: 04/06/2018
Date Made Active in Reports: 06/05/2018
Number of Days to Update: 60

Source: Department of Environmental Conservation
Telephone: 518-402-8712
Last EDR Contact: 12/07/2018
Next Scheduled EDR Contact: 03/25/2019
Data Release Frequency: Varies

NY HSWDS: Hazardous Substance Waste Disposal Site Inventory

The list includes any known or suspected hazardous substance waste disposal sites. Also included are sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites and non-Registry sites that U.S. EPA Preliminary Assessment (PA) reports or Site Investigation (SI) reports were prepared. Hazardous Substance Waste Disposal Sites are eligible to be Superfund sites now that the New York State Superfund has been refinanced and changed. This means that the study inventory has served its purpose and will no longer be maintained as a separate entity. The last version of the study inventory is frozen in time. The sites on the study will not automatically be made Superfund sites, rather each site will be further evaluated for listing on the Registry. So overtime they will be added to the registry or not.

Date of Government Version: 01/01/2003
Date Data Arrived at EDR: 10/20/2006
Date Made Active in Reports: 11/30/2006
Number of Days to Update: 41

Source: Department of Environmental Conservation
Telephone: 518-402-9564
Last EDR Contact: 05/26/2009
Next Scheduled EDR Contact: 08/24/2009
Data Release Frequency: No Update Planned

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 10/01/2018
Date Data Arrived at EDR: 10/31/2018
Date Made Active in Reports: 12/20/2018
Number of Days to Update: 50

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 10/31/2018
Next Scheduled EDR Contact: 02/11/2019
Data Release Frequency: Quarterly

PA MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 12/31/2017
Date Data Arrived at EDR: 10/23/2018
Date Made Active in Reports: 11/27/2018
Number of Days to Update: 35

Source: Department of Environmental Protection
Telephone: 717-783-8990
Last EDR Contact: 10/15/2018
Next Scheduled EDR Contact: 01/28/2019
Data Release Frequency: Annually

WI MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 12/31/2017
Date Data Arrived at EDR: 06/15/2018
Date Made Active in Reports: 07/09/2018
Number of Days to Update: 24

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 12/07/2018
Next Scheduled EDR Contact: 03/25/2019
Data Release Frequency: Annually

NY SPDES: State Pollutant Discharge Elimination System

New York State has a state program which has been approved by the United States Environmental Protection Agency for the control of wastewater and stormwater discharges in accordance with the Clean Water Act. Under New York State law the program is known as the State Pollutant Discharge Elimination System (SPDES) and is broader in scope than that required by the Clean Water Act in that it controls point source discharges to groundwaters as well as surface waters.

Date of Government Version: 07/18/2018
Date Data Arrived at EDR: 07/31/2018
Date Made Active in Reports: 08/07/2018
Number of Days to Update: 7

Source: Department of Environmental Conservation
Telephone: 518-402-8233
Last EDR Contact: 10/22/2018
Next Scheduled EDR Contact: 02/04/2019
Data Release Frequency: No Update Planned

NY VAPOR REOPENED: Vapor Intrusion Legacy Site List

New York is currently re-evaluating previous assumptions and decisions regarding the potential for soil vapor intrusion exposures at sites. As a result, all past, current, and future contaminated sites will be evaluated to determine whether these sites have the potential for exposures related to soil vapor intrusion.

Date of Government Version: 01/01/2018
Date Data Arrived at EDR: 02/15/2018
Date Made Active in Reports: 03/27/2018
Number of Days to Update: 40

Source: Department of Environmenal Conservation
Telephone: 518-402-9814
Last EDR Contact: 11/16/2018
Next Scheduled EDR Contact: 02/25/2019
Data Release Frequency: Varies

NY UIC: Underground Injection Control Wells

A listing of enhanced oil recovery underground injection wells.

Date of Government Version: 12/03/2018
Date Data Arrived at EDR: 12/06/2018
Date Made Active in Reports: 12/20/2018
Number of Days to Update: 14

Source: Department of Environmental Conservation
Telephone: 518-402-8056
Last EDR Contact: 12/06/2018
Next Scheduled EDR Contact: 03/18/2019
Data Release Frequency: Quarterly

NY COOLING TOWERS: Registered Cooling Towers

This data includes the location of cooling towers registered with New York State. The data is self-reported by owners/property managers of cooling towers in service in New York State. In August 2015, the New York State Department of Health released emergency regulations requiring the owners of cooling towers to register them with New York State.

Date of Government Version: 10/16/2018
Date Data Arrived at EDR: 10/17/2018
Date Made Active in Reports: 11/09/2018
Number of Days to Update: 23

Source: Department of Health
Telephone: 518-402-7650
Last EDR Contact: 10/17/2018
Next Scheduled EDR Contact: 01/28/2019
Data Release Frequency: Varies

EDR MGP: EDR Proprietary Manufactured Gas Plants

The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

EDR Hist Auto: EDR Exclusive Historical Auto Stations

EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR Hist Cleaner: EDR Exclusive Historical Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

NY RGA HWS: Recovered Government Archive State Hazardous Waste Facilities List

The EDR Recovered Government Archive State Hazardous Waste database provides a list of SHWS incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 12/30/2013
Number of Days to Update: 182

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

NY RGA LF: Recovered Government Archive Solid Waste Facilities List

The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/10/2014
Number of Days to Update: 193

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

COUNTY RECORDS

CORTLAND COUNTY:

Cortland County Storage Tank Listing

A listing of aboveground storage tank sites located in Cortland County.

Date of Government Version: 11/16/2018
Date Data Arrived at EDR: 11/16/2018
Date Made Active in Reports: 12/18/2018
Number of Days to Update: 32

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 10/29/2018
Next Scheduled EDR Contact: 02/11/2019
Data Release Frequency: Quarterly

Cortland County Storage Tank Listing

A listing of underground storage tank sites located in Cortland County.

Date of Government Version: 11/16/2018
Date Data Arrived at EDR: 11/16/2018
Date Made Active in Reports: 12/18/2018
Number of Days to Update: 32

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 10/29/2018
Next Scheduled EDR Contact: 02/11/2019
Data Release Frequency: Quarterly

NASSAU COUNTY:

Registered Tank Database

A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 10/29/2018
Next Scheduled EDR Contact: 02/11/2019
Data Release Frequency: No Update Planned

Storage Tank Database
A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34
Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 10/25/2018
Next Scheduled EDR Contact: 02/11/2019
Data Release Frequency: Varies

Registered Tank Database in Nassau County
A listing of facilities in Nassau County with storage tanks.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35
Source: Nassau County Department of Health
Telephone: 516-227-9691
Last EDR Contact: 10/29/2018
Next Scheduled EDR Contact: 02/11/2019
Data Release Frequency: Varies

Registered Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35
Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 10/29/2018
Next Scheduled EDR Contact: 02/11/2019
Data Release Frequency: No Update Planned

Storage Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34
Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 10/25/2018
Next Scheduled EDR Contact: 02/11/2019
Data Release Frequency: Varies

ROCKLAND COUNTY:

Petroleum Bulk Storage Database
A listing of aboveground storage tank sites located in Rockland County. Rockland County?s Petroleum Bulk Storage (PBS) program is no longer in service. All related operations/duties are now wholly overseen by the New York State Dept. of Environmental Conservation (NYSDEC).

Date of Government Version: 02/02/2017
Date Data Arrived at EDR: 03/17/2017
Date Made Active in Reports: 09/22/2017
Number of Days to Update: 189
Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 12/03/2018
Next Scheduled EDR Contact: 03/18/2019
Data Release Frequency: No Update Planned

Petroleum Bulk Storage Database
A listing of underground storage tank sites located in Rockland County. Rockland County?s Petroleum Bulk Storage (PBS) program is no longer in service. All related operations/duties are now wholly overseen by the New York State Dept. of Environmental Conservation (NYSDEC).

Date of Government Version: 02/02/2017
Date Data Arrived at EDR: 03/17/2017
Date Made Active in Reports: 09/22/2017
Number of Days to Update: 189
Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 12/03/2018
Next Scheduled EDR Contact: 03/18/2019
Data Release Frequency: No Update Planned

SUFFOLK COUNTY:

Storage Tank Database
A listing of aboveground storage tank sites located in Suffolk County.

Date of Government Version: 03/03/2015
Date Data Arrived at EDR: 03/10/2015
Date Made Active in Reports: 03/23/2015
Number of Days to Update: 13

Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 10/29/2018
Next Scheduled EDR Contact: 02/11/2019
Data Release Frequency: No Update Planned

Storage Tank Database
A listing of underground storage tank sites located in Suffolk County.

Date of Government Version: 03/03/2015
Date Data Arrived at EDR: 03/10/2015
Date Made Active in Reports: 03/23/2015
Number of Days to Update: 13

Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 10/29/2018
Next Scheduled EDR Contact: 02/11/2019
Data Release Frequency: No Update Planned

WESTCHESTER COUNTY:

Listing of Storage Tanks
A listing of aboveground storage tank sites located in Westchester County.

Date of Government Version: 10/01/2018
Date Data Arrived at EDR: 11/08/2018
Date Made Active in Reports: 12/18/2018
Number of Days to Update: 40

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 10/29/2018
Next Scheduled EDR Contact: 02/11/2019
Data Release Frequency: Semi-Annually

Listing of Storage Tanks
A listing of underground storage tank sites located in Westchester County.

Date of Government Version: 10/01/2018
Date Data Arrived at EDR: 11/08/2018
Date Made Active in Reports: 12/18/2018
Number of Days to Update: 40

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 10/29/2018
Next Scheduled EDR Contact: 02/11/2019
Data Release Frequency: Semi-Annually

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

Oil/Gas Pipelines
Source: PennWell Corporation
Petroleum Bundle (Crude Oil, Refined Products, Petrochemicals, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)) N = Natural Gas Bundle (Natural Gas, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)). This map includes information copyrighted by PennWell Corporation. This information is provided on a best effort basis and PennWell Corporation does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of PennWell.

Electric Power Transmission Line Data
Source: PennWell Corporation
This map includes information copyrighted by PennWell Corporation. This information is provided on a best effort basis and PennWell Corporation does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of PennWell.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

AHA Hospitals:
Source: American Hospital Association, Inc.
Telephone: 312-280-5991
The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing
Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000
A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes
Source: National Institutes of Health
Telephone: 301-594-6248
Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Private Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on private school locations in the United States.

Daycare Centers: Day Care Providers
Source: Department of Health
Telephone: 212-676-2444

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

Historic Topographic Maps

Metro Rail Expansion Corridor

City of Buffalo, Towns of Tonawanda and Amherst

Buffalo, NY 14228

Inquiry Number: 5531774.5

January 11, 2019

EDR Historical Topo Map Report

with QuadMatch™

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Historical Topo Map Report

01/11/19

Site Name:

Metro Rail Expansion Corridor
City of Buffalo, Towns of Tonav
Buffalo, NY 14228
EDR Inquiry # 5531774.5

Client Name:

Watts Architecture & Engineering
95 Perry St Suite 300
Buffalo, NY 14203-0000
Contact: Lisa Connors

EDR Topographic Map Library has been searched by EDR and maps covering the target property location as provided by Watts Architecture & Engineering were identified for the years listed below. EDR's Historical Topo Map Report is designed to assist professionals in evaluating potential liability on a target property resulting from past activities. EDRs Historical Topo Map Report includes a search of a collection of public and private color historical topographic maps, dating back to the late 1800s.

Search Results:

P.O.# 1082

Project: Niagara Frontier Transport.

Coordinates:

Latitude:	43.027411 43° 1' 39" North
Longitude:	-78.783 -78° 46' 59" West
UTM Zone:	Zone 17 North
UTM X Meters:	680626.85
UTM Y Meters:	4766243.89
Elevation:	573.08' above sea level

Maps Provided:

2013	1900
1980	1899
1965	1894
1950	1894, 1897
1948	
1946	
1913	
1901	

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2019 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

2013 Source Sheets

Buffalo NE
2013
7.5-minute, 24000

Tonawanda East
2013
7.5-minute, 24000

1980 Source Sheets



Tonawanda East
1980
7.5-minute, 24000
Aerial Photo Revised 1972

1965 Source Sheets

Buffalo NE
1965
7.5-minute, 24000
Aerial Photo Revised 1942



Tonawanda East
1965
7.5-minute, 24000
Aerial Photo Revised 1942

1950 Source Sheets



BUFFALO VICINITY 1 OF 2
1950
7.5-minute, 24000

Buffalo NE
1950
7.5-minute, 24000
Aerial Photo Revised 1942

Tonawanda East
1950
7.5-minute, 24000
Aerial Photo Revised 1942

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

1948 Source Sheets

Buffalo NE
1948
7.5-minute, 24000
Aerial Photo Revised 1942

1946 Source Sheets

BUFFALO NE
1946
7.5-minute, 25000

1913 Source Sheets

Niagara
1913
30-minute, 125000

1901 Source Sheets

Tonawanda
1901
15-minute, 62500

Buffalo
1901
15-minute, 62500

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

1900 Source Sheets

Tonawanda
1900
15-minute, 62500

1899 Source Sheets

Niagara
1899
30-minute, 125000

1894 Source Sheets

Buffalo
1894
15-minute, 62500

1894, 1897 Source Sheets

Tonawanda
1897
15-minute, 62500



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Buffalo NE, 2013, 7.5-minute

SITE NAME: Metro Rail Expansion Corridor
ADDRESS: City of Buffalo, Towns of Tonawanda and Buffalo, NY 14228
CLIENT: Watts Architecture & Engineering

N

Historical Topo Map

2013



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Tonawanda East, 2013, 7.5-minute
S, Buffalo NE, 2013, 7.5-minute

SITE NAME: Metro Rail Expansion Corridor
ADDRESS: City of Buffalo, Towns of Tonawanda and Buffalo, NY 14228
CLIENT: Watts Architecture & Engineering

N



UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED
UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED
UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED

This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Tonawanda East, 1980, 7.5-minute

SITE NAME: Metro Rail Expansion Corridor
ADDRESS: City of Buffalo, Towns of Tonawanda and Buffalo, NY 14228
CLIENT: Watts Architecture & Engineering

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Tonawanda East, 1965, 7.5-minute
S, Buffalo NE, 1965, 7.5-minute

SITE NAME: Metro Rail Expansion Corridor
ADDRESS: City of Buffalo, Towns of Tonawanda and Buffalo, NY 14228
CLIENT: Watts Architecture & Engineering

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Buffalo NE, 1965, 7.5-minute

SITE NAME: Metro Rail Expansion Corridor
ADDRESS: City of Buffalo, Towns of Tonawanda and Buffalo, NY 14228
CLIENT: Watts Architecture & Engineering

N

Historical Topo Map

1950



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, BUFFALO VICINITY 1 OF 2, 1950, 7.5-minute
TP, Buffalo NE, 1950, 7.5-minute

SITE NAME: Metro Rail Expansion Corridor
ADDRESS: City of Buffalo, Towns of Tonawanda and Buffalo, NY 14228
CLIENT: Watts Architecture & Engineering

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Tonawanda East, 1950, 7.5-minute
S, BUFFALO VICINITY 1 OF 2, 1950, 7.5-minute
S, Buffalo NE, 1950, 7.5-minute

SITE NAME: Metro Rail Expansion Corridor
ADDRESS: City of Buffalo, Towns of Tonawanda and Buffalo, NY 14228
CLIENT: Watts Architecture & Engineering

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Buffalo NE, 1948, 7.5-minute

SITE NAME: Metro Rail Expansion Corridor
ADDRESS: City of Buffalo, Towns of Tonawanda and Buffalo, NY 14228
CLIENT: Watts Architecture & Engineering

N

Historical Topo Map

1946



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, BUFFALO NE, 1946, 7.5-minute

SITE NAME: Metro Rail Expansion Corridor
ADDRESS: City of Buffalo, Towns of Tonawanda and Buffalo, NY 14228
CLIENT: Watts Architecture & Engineering

N



UNMAPPED

This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Niagara, 1913, 30-minute

SITE NAME: Metro Rail Expansion Corridor
ADDRESS: City of Buffalo, Towns of Tonawanda and Buffalo, NY 14228
CLIENT: Watts Architecture & Engineering

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Tonawanda, 1901, 15-minute
S, Buffalo, 1901, 15-minute

SITE NAME: Metro Rail Expansion Corridor
ADDRESS: City of Buffalo, Towns of Tonawanda and Buffalo, NY 14228
CLIENT: Watts Architecture & Engineering

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Buffalo, 1901, 15-minute

SITE NAME: Metro Rail Expansion Corridor
ADDRESS: City of Buffalo, Towns of Tonawanda and Buffalo, NY 14228
CLIENT: Watts Architecture & Engineering

N



UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED
UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED
UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED

This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Tonawanda, 1900, 15-minute

SITE NAME: Metro Rail Expansion Corridor
ADDRESS: City of Buffalo, Towns of Tonawanda and Buffalo, NY 14228
CLIENT: Watts Architecture & Engineering

N



UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED
UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED
UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED

This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Niagara, 1899, 30-minute

SITE NAME: Metro Rail Expansion Corridor
ADDRESS: City of Buffalo, Towns of Tonawanda and Buffalo, NY 14228
CLIENT: Watts Architecture & Engineering

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Buffalo, 1894, 15-minute

SITE NAME: Metro Rail Expansion Corridor
ADDRESS: City of Buffalo, Towns of Tonawanda and Buffalo, NY 14228
CLIENT: Watts Architecture & Engineering

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Tonawanda, 1897, 15-minute
S, Buffalo, 1894, 15-minute

SITE NAME: Metro Rail Expansion Corridor
ADDRESS: City of Buffalo, Towns of Tonawanda and Buffalo, NY 14228
CLIENT: Watts Architecture & Engineering

N

Aerial Photographs

Metro Rail Expansion Corridor

City of Buffalo, Towns of Tonawanda and Amherst

Buffalo, NY 14228

Inquiry Number: 5531774.8

January 11, 2019

The EDR Aerial Photo Decade Package

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

Date EDR Searched Historical Sources:

Aerial Photography January 15, 2019

Target Property:

City of Buffalo, Towns of Tonawanda and Amherst

Buffalo, NY 14228

Year	***Scale***	***Details***	***Source***
1927	Aerial Photograph. Scale: 1"=1100'	Flight Year: 1927	Fairchild
1938	Aerial Photograph. Scale: 1"=1100'	Flight Year: 1938	USDA
1951	Aerial Photograph. Scale: 1"=1100'	Flight Year: 1951	USDA
1958	Aerial Photograph. Scale: 1"=1100'	Flight Year: 1958	USGS
1966	Aerial Photograph. Scale: 1"=1100'	Flight Year: 1966	USDA
1978	Aerial Photograph. Scale: 1"=1100'	Flight Year: 1978	USDA
1985	Aerial Photograph. Scale: 1"=1100'	Flight Year: 1985	USDA
1995	Aerial Photograph. Scale: 1"=1100'	Flight Year: 1995	DOQQ_USGS
2006	Aerial Photograph. Scale: 1"=1100'	Flight Year: 2006	NAIP_USGS
2009	Aerial Photograph. Scale: 1"=1100'	Flight Year: 2009	NAIP_USGS
2013	Aerial Photograph. Scale: 1"=1100'	Flight Year: 2013	NAIP_USGS
2017	Aerial Photograph. Scale: 1"=1100'	Flight Year: 2017	NAIP_USGS



INQUIRY #: 5531774.8
YEAR: INDEX



INQUIRY #: 5531774.8
YEAR: 1927
SCALE: 1"=1100'

INQUIRY #: 5531774.8
YEAR: 1927
SCALE: 1"=1100'



INQUIRY #: 5531774.8
YEAR: 1927
SCALE: 1"=1100'

INQUIRY #: 5531774.8
YEAR: 1938
SCALE: 1"=1100'

INQUIRY #: 5531774.8
YEAR: 1938
SCALE: 1"=1100'



INQUIRY #: 5531774.8
YEAR: 1938
SCALE: 1"=1100'

INQUIRY #: 5531774.8
YEAR: 1951
SCALE: 1"=1100'

INQUIRY #: 5531774.8
YEAR: 1951
SCALE: 1"=1100'



INQUIRY #: 5531774.8
YEAR: 1951
SCALE: 1"=1100'


INQUIRY #: 5531774.8
YEAR: 1958
SCALE: 1"=1100'

INQUIRY #: 5531774.8
YEAR: 1958
SCALE: 1"=1100'



INQUIRY #: 5531774.8
YEAR: 1958
SCALE: 1"=1100'

INQUIRY #: 5531774.8
YEAR: 1966
SCALE: 1"=1100'

INQUIRY #: 5531774.8
YEAR: 1966
SCALE: 1"=1100'



INQUIRY #: 5531774.8
YEAR: 1966
SCALE: 1"=1100'

INQUIRY #: 5531774.8
YEAR: 1978
SCALE: 1"=1100'

INQUIRY #: 5531774.8
YEAR: 1978
SCALE: 1"=1100'


INQUIRY #: 5531774.8
YEAR: 1978
SCALE: 1"=1100'

INQUIRY #: 5531774.8
YEAR: 1985
SCALE: 1"=1100'

INQUIRY #: 5531774.8
YEAR: 1985
SCALE: 1"=1100'

INQUIRY #: 5531774.8
YEAR: 1985
SCALE: 1"=1100'

INQUIRY #: 5531774.8
YEAR: 1995
SCALE: 1"=1100'

INQUIRY #: 5531774.8
YEAR: 1995
SCALE: 1"=1100'

INQUIRY #: 5531774.8
YEAR: 1995
SCALE: 1"=1100'

INQUIRY #: 5531774.8
YEAR: 2006
SCALE: 1"=1100'

INQUIRY #: 5531774.8
YEAR: 2006
SCALE: 1"=1100'

INQUIRY #: 5531774.8
YEAR: 2006
SCALE: 1"=1100'

INQUIRY #: 5531774.8
YEAR: 2009
SCALE: 1"=1100'

INQUIRY #: 5531774.8
YEAR: 2009
SCALE: 1"=1100'

INQUIRY #: 5531774.8
YEAR: 2009
SCALE: 1"=1100'

INQUIRY #: 5531774.8
YEAR: 2013
SCALE: 1"=1100'


INQUIRY #: 5531774.8
YEAR: 2013
SCALE: 1"=1100'

INQUIRY #: 5531774.8
YEAR: 2013
SCALE: 1"=1100'


INQUIRY #: 5531774.8
YEAR: 2017
SCALE: 1"=1100'


INQUIRY #: 5531774.8
YEAR: 2017
SCALE: 1"=1100'

INQUIRY #: 5531774.8
YEAR: 2017
SCALE: 1"=1100'

Sanborn Fire Insurance Maps

Metro Rail Expansion Corridor

City of Buffalo, Towns of Tonawanda and Amherst

Buffalo, NY 14228

Inquiry Number: 5531774.11

January 14, 2019

Certified Sanborn® Map Report

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

Certified Sanborn® Map Report

01/14/19

Site Name:

Metro Rail Expansion Corridor
City of Buffalo, Towns of Tonav
Buffalo, NY 14228
EDR Inquiry # 5531774.11

Client Name:

Watts Architecture & Engineering
95 Perry St Suite 300
Buffalo, NY 14203-0000
Contact: Lisa Connors

The Sanborn Library has been searched by EDR and maps covering the target property location as provided by Watts Architecture & Engineering were identified for the years listed below (selected maps only*). The Sanborn Library is the largest, most complete collection of fire insurance maps. The collection includes maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow, and others. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by the Sanborn Library LLC, the copyright holder for the collection. Results can be authenticated by visiting www.edrnet.com/sanborn.

The Sanborn Library is continually enhanced with newly identified map archives. This report accesses all maps in the collection as of the day this report was generated.

Certified Sanborn Results:

Certification # 45AC-4807-B8E1

PO # 1082

Project Niagara Frontier Transport.

* Environmental Data Resources, Inc. has been instructed by Watts Architecture & Engineering to print ONLY the Sanborn Maps for the years listed below:

1986 (5)	1900 (1)
1964 (5)	
1957 (3)	
1950 (9)	
1935 (2)	
1932 (1)	
1928 (4)	
1916 (1)	

Total Maps: 31

Sanborn® Library search results

Certification #: 45AC-4807-B8E1

The Sanborn Library includes more than 1.2 million fire insurance maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow and others which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

- ☑ Library of Congress
- ☑ University Publications of America
- ☑ EDR Private Collection

The Sanborn Library LLC Since 1866™

Limited Permission To Make Copies

Watts Architecture & Engineering (the client) is permitted to make up to FIVE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2019 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #45AC-4807-B8E1

Site Name:	Metro Rail Expansion Corridor
Address:	City of Buffalo, Towns of Tonawanda and Amherst
City, ST, ZIP:	Buffalo, NY 14228
Client:	Watts Architecture & Engineering
EDR Inquiry:	5531774.11
Order Date:	01/14/2019
Certification #:	45AC-4807-B8E1
Copyright	1986

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #45AC-4807-B8E1

Site Name:	Metro Rail Expansion Corridor
Address:	City of Buffalo, Towns of Tonawanda and Amherst
City, ST, ZIP:	Buffalo, NY 14228
Client:	Watts Architecture & Engineering
EDR Inquiry:	5531774.11
Order Date:	01/14/2019
Certification #:	45AC-4807-B8E1
Copyright	1986



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name: Metro Rail Expansion Corridor
Address: City of Buffalo, Towns of Tonawanda and Amherst
City, ST, ZIP: Buffalo, NY 14228
Client: Watts Architecture & Engineering
EDR Inquiry: 5531774.11
Order Date: 01/14/2019
Certification #: 45AC-4807-B8E1
Copyright 1986



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #45AC-4807-B8E1

Site Name:	Metro Rail Expansion Corridor
Address:	City of Buffalo, Towns of Tonawanda and Amherst
City, ST, ZIP:	Buffalo, NY 14228
Client:	Watts Architecture & Engineering
EDR Inquiry:	5531774.11
Order Date:	01/14/2019
Certification #:	45AC-4807-B8E1
Copyright	1986



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #45AC-4807-B8E1

Site Name:	Metro Rail Expansion Corridor
Address:	City of Buffalo, Towns of Tonawanda and Amherst
City, ST, ZIP:	Buffalo, NY 14228
Client:	Watts Architecture & Engineering
EDR Inquiry:	5531774.11
Order Date:	01/14/2019
Certification #:	45AC-4807-B8E1
Copyright	1986



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #45AC-4807-B8E1

Site Name: Metro Rail Expansion Corridor
Address: City of Buffalo, Towns of Tonawanda and Amherst
City, ST, ZIP: Buffalo, NY 14228
Client: Watts Architecture & Engineering
EDR Inquiry: 5531774.11
Order Date: 01/14/2019
Certification #: 45AC-4807-B8E1
Copyright 1964



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #45AC-4807-B8E1

Site Name:	Metro Rail Expansion Corridor
Address:	City of Buffalo, Towns of Tonawanda and Amherst
City, ST, ZIP:	Buffalo, NY 14228
Client:	Watts Architecture & Engineering
EDR Inquiry:	5531774.11
Order Date:	01/14/2019
Certification #:	45AC-4807-B8E1
Copyright	1964



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #45AC-4807-B8E1

Site Name: Metro Rail Expansion Corridor
Address: City of Buffalo, Towns of Tonawanda and Amherst
City, ST, ZIP: Buffalo, NY 14228
Client: Watts Architecture & Engineering
EDR Inquiry: 5531774.11
Order Date: 01/14/2019
Certification #: 45AC-4807-B8E1
Copyright 1964



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #45AC-4807-B8E1

Site Name: Metro Rail Expansion Corridor
Address: City of Buffalo, Towns of Tonawanda and Amherst
City, ST, ZIP: Buffalo, NY 14228
Client: Watts Architecture & Engineering
EDR Inquiry: 5531774.11
Order Date: 01/14/2019
Certification #: 45AC-4807-B8E1
Copyright 1964

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #45AC-4807-B8E1

Site Name: Metro Rail Expansion Corridor
Address: City of Buffalo, Towns of Tonawanda and Amherst
City, ST, ZIP: Buffalo, NY 14228
Client: Watts Architecture & Engineering
EDR Inquiry: 5531774.11
Order Date: 01/14/2019
Certification #: 45AC-4807-B8E1
Copyright 1964



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #45AC-4807-B8E1

Site Name:	Metro Rail Expansion Corridor
Address:	City of Buffalo, Towns of Tonawanda and Amherst
City, ST, ZIP:	Buffalo, NY 14228
Client:	Watts Architecture & Engineering
EDR Inquiry:	5531774.11
Order Date:	01/14/2019
Certification #	45AC-4807-B8E1
Copyright	1957

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #45AC-4807-B8E1

Site Name:	Metro Rail Expansion Corridor
Address:	City of Buffalo, Towns of Tonawanda and Amherst
City, ST, ZIP:	Buffalo, NY 14228
Client:	Watts Architecture & Engineering
EDR Inquiry:	5531774.11
Order Date:	01/14/2019
Certification #:	45AC-4807-B8E1
Copyright	1957



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #45AC-4807-B8E1

Site Name:	Metro Rail Expansion Corridor
Address:	City of Buffalo, Towns of Tonawanda and Amherst
City, ST, ZIP:	Buffalo, NY 14228
Client:	Watts Architecture & Engineering
EDR Inquiry:	5531774.11
Order Date:	01/14/2019
Certification #:	45AC-4807-B8E1
Copyright	1957



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #45AC-4807-B8E1

Site Name: Metro Rail Expansion Corridor
Address: City of Buffalo, Towns of Tonawanda and Amherst
City, ST, ZIP: Buffalo, NY 14228
Client: Watts Architecture & Engineering
EDR Inquiry: 5531774.11
Order Date: 01/14/2019
Certification #: 45AC-4807-B8E1
Copyright 1950



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #45AC-4807-B8E1

Site Name: Metro Rail Expansion Corridor
Address: City of Buffalo, Towns of Tonawanda and Amherst
City, ST, ZIP: Buffalo, NY 14228
Client: Watts Architecture & Engineering
EDR Inquiry: 5531774.11
Order Date: 01/14/2019
Certification #: 45AC-4807-B8E1
Copyright 1950



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #45AC-4807-B8E1

Site Name:	Metro Rail Expansion Corridor
Address:	City of Buffalo, Towns of Tonawanda and Amherst
City, ST, ZIP:	Buffalo, NY 14228
Client:	Watts Architecture & Engineering
EDR Inquiry:	5531774.11
Order Date:	01/14/2019
Certification #:	45AC-4807-B8E1
Copyright	1950



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #45AC-4807-B8E1

Site Name:	Metro Rail Expansion Corridor
Address:	City of Buffalo, Towns of Tonawanda and Amherst
City, ST, ZIP:	Buffalo, NY 14228
Client:	Watts Architecture & Engineering
EDR Inquiry:	5531774.11
Order Date:	01/14/2019
Certification #:	45AC-4807-B8E1
Copyright	1950



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #45AC-4807-B8E1

Site Name:	Metro Rail Expansion Corridor
Address:	City of Buffalo, Towns of Tonawanda and Amherst
City, ST, ZIP:	Buffalo, NY 14228
Client:	Watts Architecture & Engineering
EDR Inquiry:	5531774.11
Order Date:	01/14/2019
Certification #:	45AC-4807-B8E1
Copyright	1950



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #45AC-4807-B8E1

Site Name: Metro Rail Expansion Corridor
Address: City of Buffalo, Towns of Tonawanda and Amherst
City, ST, ZIP: Buffalo, NY 14228
Client: Watts Architecture & Engineering
EDR Inquiry: 5531774.11
Order Date: 01/14/2019
Certification #: 45AC-4807-B8E1
Copyright 1950



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #45AC-4807-B8E1



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #45AC-4807-B8E1

Site Name: Metro Rail Expansion Corridor
Address: City of Buffalo, Towns of Tonawanda and Amherst
City, ST, ZIP: Buffalo, NY 14228
Client: Watts Architecture & Engineering
EDR Inquiry: 5531774.11
Order Date: 01/14/2019
Certification #: 45AC-4807-B8E1
Copyright 1950



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #45AC-4807-B8E1

Site Name: Metro Rail Expansion Corridor
Address: City of Buffalo, Towns of Tonawanda and Amherst
City, ST, ZIP: Buffalo, NY 14228
Client: Watts Architecture & Engineering
EDR Inquiry: 5531774.11
Order Date: 01/14/2019
Certification #: 45AC-4807-B8E1
Copyright 1950



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #45AC-4807-B8E1

Site Name:	Metro Rail Expansion Corridor
Address:	City of Buffalo, Towns of Tonawanda and Amherst
City, ST, ZIP:	Buffalo, NY 14228
Client:	Watts Architecture & Engineering
EDR Inquiry:	5531774.11
Order Date:	01/14/2019
Certification #:	45AC-4807-B8E1
Copyright	1935



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #45AC-4807-B8E1

Site Name:	Metro Rail Expansion Corridor
Address:	City of Buffalo, Towns of Tonawanda and Amherst
City, ST, ZIP:	Buffalo, NY 14228
Client:	Watts Architecture & Engineering
EDR Inquiry:	5531774.11
Order Date:	01/14/2019
Certification #:	45AC-4807-B8E1
Copyright	1935



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #45AC-4807-B8E1

Site Name:	Metro Rail Expansion Corridor
Address:	City of Buffalo, Towns of Tonawanda and Amherst
City, ST, ZIP:	Buffalo, NY 14228
Client:	Watts Architecture & Engineering
EDR Inquiry:	5531774.11
Order Date:	01/14/2019
Certification #:	45AC-4807-B8E1
Copyright	1932



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #45AC-4807-B8E1

Site Name:	Metro Rail Expansion Corridor
Address:	City of Buffalo, Towns of Tonawanda and Amherst
City, ST, ZIP:	Buffalo, NY 14228
Client:	Watts Architecture & Engineering
EDR Inquiry:	5531774.11
Order Date:	01/14/2019
Certification #:	45AC-4807-B8E1
Copyright	1928



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #45AC-4807-B8E1

Site Name: Metro Rail Expansion Corridor
Address: City of Buffalo, Towns of Tonawanda and Amherst
City, ST, ZIP: Buffalo, NY 14228
Client: Watts Architecture & Engineering
EDR Inquiry: 5531774.11
Order Date: 01/14/2019
Certification #: 45AC-4807-B8E1
Copyright 1928



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #45AC-4807-B8E1

Site Name: Metro Rail Expansion Corridor
Address: City of Buffalo, Towns of Tonawanda and Amherst
City, ST, ZIP: Buffalo, NY 14228
Client: Watts Architecture & Engineering
EDR Inquiry: 5531774.11
Order Date: 01/14/2019
Certification #: 45AC-4807-B8E1
Copyright 1928



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #45AC-4807-B8E1

Site Name: Metro Rail Expansion Corridor
Address: City of Buffalo, Towns of Tonawanda and Amherst
City, ST, ZIP: Buffalo, NY 14228
Client: Watts Architecture & Engineering
EDR Inquiry: 5531774.11
Order Date: 01/14/2019
Certification #: 45AC-4807-B8E1
Copyright 1928



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #45AC-4807-B8E1

Site Name: Metro Rail Expansion Corridor
Address: City of Buffalo, Towns of Tonawanda and Amherst
City, ST, ZIP: Buffalo, NY 14228
Client: Watts Architecture & Engineering
EDR Inquiry: 5531774.11
Order Date: 01/14/2019
Certification #: 45AC-4807-B8E1
Copyright 1916



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #45AC-4807-B8E1

Site Name: Metro Rail Expansion Corridor
Address: City of Buffalo, Towns of Tonawanda and Amherst
City, ST, ZIP: Buffalo, NY 14228
Client: Watts Architecture & Engineering
EDR Inquiry: 5531774.11
Order Date: 01/14/2019
Certification #: 45AC-4807-B8E1
Copyright 1900

City Directory Review

Metro Rail Expansion Corridor
City of Buffalo, Towns of Tonawanda and Amherst
Buffalo, NY 14228

Inquiry Number: 5531774.10
January 18, 2019

The EDR-City Directory Image Report

Environmental Data Resources Inc

6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION

Executive Summary

Findings

City Directory Images

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction orforecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2017 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc. or its affiliates is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

DESCRIPTION

Environmental Data Resources, Inc.'s (EDR) City Directory Report is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's City Directory Report includes a search of available city directory data at 5 year intervals.

RECORD SOURCES

EDR's Digital Archive combines historical directory listings from sources such as Cole Information and Dun & Bradstreet. These standard sources of property information complement and enhance each other to provide a more comprehensive report.

EDR is licensed to reproduce certain City Directory works by the copyright holders of those works. The purchaser of this EDR City Directory Report may include it in report(s) delivered to a customer. Reproduction of City Directories without permission of the publisher or licensed vendor may be a violation of copyright.

Data by infoUSA®

Copyright©2008
All Rights Reserved

RESEARCH SUMMARY

The following research sources were consulted in the preparation of this report. A check mark indicates where information was identified in the source and provided in this report.

Year	Target Street	Cross Street	Source
2018	☐	☑	Polk's City Directory
2014	☐	☑	Polk's City Directory
2008	☐	☑	Polk's City Directory
2004	☐	☑	Polk's City Directory
1999	☐	☑	Polk's City Directory
1998	☐	☑	Polk's City Directory
1993	☐	☑	Polk's City Directory
1992	☐	☑	Polk's City Directory
1987	☐	☑	Polk's City Directory
1983	☐	☑	Polk's City Directory
1982	☐	☑	Polk's City Directory
1977	☐	☑	Polk's City Directory
1973	☐	☑	Polk's City Directory
1968	☐	☑	Polk's City Directory
1964	☐	☑	Polk's City Directory

EXECUTIVE SUMMARY

Year	***Target Street***	***Cross Street***	***Source***

FINDINGS

TARGET PROPERTY STREET

City of Buffalo, Towns of Tonawanda and Amherst
Buffalo, NY 14228

No Addresses Found

FINDINGS

CROSS STREETS

Year	*CD Image*	*Source*
KENMORE AVE		
2018	pg. A1	Polk's City Directory
2018	pg. A2	Polk's City Directory
2018	pg. A3	Polk's City Directory
2014	pg. A15	Polk's City Directory
2014	pg. A16	Polk's City Directory
2008	pg. A28	Polk's City Directory
2008	pg. A29	Polk's City Directory
2004	pg. A42	Polk's City Directory
2004	pg. A43	Polk's City Directory
1999	pg. A53	Polk's City Directory
1999	pg. A54	Polk's City Directory
1999	pg. A55	Polk's City Directory
1999	pg. A56	Polk's City Directory
1992	pg. A71	Polk's City Directory
1992	pg. A72	Polk's City Directory
1987	pg. A78	Polk's City Directory
1987	pg. A79	Polk's City Directory
1987	pg. A80	Polk's City Directory
1983	pg. A93	Polk's City Directory
1983	pg. A94	Polk's City Directory
1977	pg. A106	Polk's City Directory
1977	pg. A107	Polk's City Directory
1973	pg. A112	Polk's City Directory
1968	pg. A118	Polk's City Directory
1964	pg. A126	Polk's City Directory
1964	pg. A127	Polk's City Directory
MAIN ST		
2018	pg. A4	Polk's City Directory
2018	pg. A5	Polk's City Directory
2018	pg. A6	Polk's City Directory
2018	pg. A7	Polk's City Directory

FINDINGS

Year	***CD Image***	***Source***
2014	pg. A17	Polk's City Directory
2014	pg. A18	Polk's City Directory
2014	pg. A19	Polk's City Directory
2014	pg. A20	Polk's City Directory
2008	pg. A30	Polk's City Directory
2008	pg. A31	Polk's City Directory
2008	pg. A32	Polk's City Directory
2004	pg. A44	Polk's City Directory
2004	pg. A45	Polk's City Directory
2004	pg. A46	Polk's City Directory
1998	pg. A63	Polk's City Directory
1998	pg. A64	Polk's City Directory
1992	pg. A73	Polk's City Directory
1992	pg. A74	Polk's City Directory
1992	pg. A75	Polk's City Directory
1987	pg. A81	Polk's City Directory
1987	pg. A82	Polk's City Directory
1987	pg. A83	Polk's City Directory
1987	pg. A84	Polk's City Directory
1987	pg. A85	Polk's City Directory
1983	pg. A95	Polk's City Directory
1982	pg. A104	Polk's City Directory
1982	pg. A105	Polk's City Directory
1977	pg. A108	Polk's City Directory
1977	pg. A109	Polk's City Directory
1973	pg. A113	Polk's City Directory
1973	pg. A114	Polk's City Directory
1973	pg. A115	Polk's City Directory
1968	pg. A119	Polk's City Directory
1968	pg. A120	Polk's City Directory
1968	pg. A121	Polk's City Directory
1968	pg. A122	Polk's City Directory
1968	pg. A123	Polk's City Directory
1964	pg. A128	Polk's City Directory
1964	pg. A129	Polk's City Directory
1964	pg. A130	Polk's City Directory

FINDINGS

Year	*CD Image*	*Source*
NIAGARA FALLS BLVD		
2018	pg. A10	Polk's City Directory
2018	pg. A11	Polk's City Directory
2018	pg. A12	Polk's City Directory
2018	pg. A13	Polk's City Directory
2018	pg. A14	Polk's City Directory
2018	pg. A8	Polk's City Directory
2018	pg. A9	Polk's City Directory
2014	pg. A21	Polk's City Directory
2014	pg. A22	Polk's City Directory
2014	pg. A23	Polk's City Directory
2014	pg. A24	Polk's City Directory
2014	pg. A25	Polk's City Directory
2014	pg. A26	Polk's City Directory
2014	pg. A27	Polk's City Directory
2008	pg. A33	Polk's City Directory
2008	pg. A34	Polk's City Directory
2008	pg. A35	Polk's City Directory
2008	pg. A36	Polk's City Directory
2008	pg. A37	Polk's City Directory
2008	pg. A38	Polk's City Directory
2008	pg. A39	Polk's City Directory
2008	pg. A40	Polk's City Directory
2008	pg. A41	Polk's City Directory
2004	pg. A47	Polk's City Directory
2004	pg. A48	Polk's City Directory
2004	pg. A49	Polk's City Directory
2004	pg. A50	Polk's City Directory
2004	pg. A51	Polk's City Directory
2004	pg. A52	Polk's City Directory
1999	pg. A57	Polk's City Directory
1999	pg. A58	Polk's City Directory
1999	pg. A59	Polk's City Directory
1999	pg. A60	Polk's City Directory
1999	pg. A61	Polk's City Directory
1999	pg. A62	Polk's City Directory
1998	pg. A65	Polk's City Directory

FINDINGS

Year	***CD Image***	***Source***
1998	pg. A66	Polk's City Directory
1993	pg. A67	Polk's City Directory
1993	pg. A68	Polk's City Directory
1993	pg. A69	Polk's City Directory
1993	pg. A70	Polk's City Directory
1992	pg. A76	Polk's City Directory
1992	pg. A77	Polk's City Directory
1987	pg. A86	Polk's City Directory
1987	pg. A87	Polk's City Directory
1987	pg. A88	Polk's City Directory
1987	pg. A89	Polk's City Directory
1987	pg. A90	Polk's City Directory
1987	pg. A91	Polk's City Directory
1987	pg. A92	Polk's City Directory
1983	pg. A100	Polk's City Directory
1983	pg. A101	Polk's City Directory
1983	pg. A102	Polk's City Directory
1983	pg. A103	Polk's City Directory
1983	pg. A96	Polk's City Directory
1983	pg. A97	Polk's City Directory
1983	pg. A98	Polk's City Directory
1983	pg. A99	Polk's City Directory
1977	pg. A110	Polk's City Directory
1977	pg. A111	Polk's City Directory
1973	pg. A116	Polk's City Directory
1973	pg. A117	Polk's City Directory
1968	pg. A124	Polk's City Directory
1968	pg. A125	Polk's City Directory
1964	pg. A131	Polk's City Directory
1964	pg. A132	Polk's City Directory

City Directory Images

Target Street	Cross Street	Source
-	✓	Polk's City Directory

KENMORE AVE 2018

(1996) 716-741-3354
+ WOLCOTT RD INTERSECTS
HOUSEHOLDS 3

KENMORE AVE (BUFFALO)-FROM 3500 MAIN ST NORTHWEST
• ZIP CODE 14226 CAR-RT C001

39 GRACE POINT ALLIANCE churches ✓
.....716-834-4345

43 MICHAEL WILSON REALTY INC real estate ✓
.....716-912-8770

STUDIO J dancing instruction ✓
.....716-833-2623

47 MAY JEN CHINESE RESTAURANT
restaurants ✓ 716-832-5162
+ WINDERMERE BLVD INTERSECTS
+ WINDERMERE BLVD INTERSECTS

63 1 HUGHES & WRAY attorneys ✓
.....716-856-0400
+ WINDERMERE BLVD INTERSECTS

95 No Current Listing
+ CAPEN BLVD INTERSECTS

99 Ⓝ Bauers John ✓
Ⓝ Nyvltova Alena ✓
Shah Umesh 2 ♦ (1956)
+ ALLENHURST RD INTERSECTS

135 Napier Kandie N ✓ 22 ♦ (1952)
.....716-836-9377
Stevens Michael G ✓ 22 ♦ (1952)

140 FRANCAVILLA VINCENT J DDS dentists ✓
.....716-835-6966
IMDENTUS INC nonclassified establishments ✓ 716-835-6966

143 No Current Listing
+ ALLENHURST RD INTERSECTS

BUSINESSES 7 HOUSEHOLDS 7

Target Street	Cross Street	Source
-	✓	Polk's City Directory

KENMORE AVE 2018



Target Street	Cross Street	Source
-	✓	Polk's City Directory

KENMORE AVE 2018

KENMORE AVE

KENMORE AVE Cont'd

189 WILLIAM L LONG & ASSOC architects ✓ @ 716-833-1873
191 Brenner George ✓ 56 ♠ (1925)
193 Rozek Ken P & Jane M ✓ @ 40 ♠ (1925) 716-834-2169
197 Magyar Susan L ✓ 29 ♠ (1925) 716-833-2696
Magyar Renee 716-833-2696
199 No Current Listing
205 EMPORIUM HAIR DESIGN beauty salons ✓ 716-832-6558
210 Labruna Sharon R ✓ 39 ♠ (1957) 716-833-9606
214 Mahoney Thomas E ✓ 28 ♠ (1939) 716-831-0930
217 Leavens Deborah J ✓ @ 10 ♠ (1952)
Porter Eleanor ✓ @ 9 ♠ (1952) 716-895-1484
Porter Tabatha 716-895-1484
Sun-Palozzi Sherry F ✓ 15 ♠ (1952)
1 No Current Listing
218 Sudduth Destiny S ✓ @ 7 ♠ (1939)
225 1 No Current Listing
229 Bitterman James W & Constance M ✓ @ 22 ♠ (1920) 716-837-0094
233 Mehrotra Raj M ✓ 8

KEN
381
392
396
400
401
416
417
447
487
500

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAIN ST 2018


3164 GINSENG UNLIMITED health & diet foods-retail ✓ 716-838-0707
3165 LAKE EFFECT DINER restaurants ✓ 716-833-1952
3168 ICONZ HAIR DESIGN beauty salons ✓ 716-834-1559
3171 2 No Current Listing
3172 JUST PIZZA pizza ✓ 716-831-9979
3176 Noreck John ✓ 5
3180 Wilson Ulysses ✓ 11 • (1939)
3182 Krasopoulos Anna M ✓ 8
3191 Good Jennifer
Sapodin Julia ✓ 2
3193 Ortega Alexandra D ✓ 6
2 No Current Listing
3198 FRANKS MOBIL serv stations- gasoline & oil ✓ 716-836-5337
TIM HORTONS doughnuts ✓ 716-836-5337
ZIP CODE 14214 CAR-RT C022
3208 1 PARKSIDE CANDY CO candy & confectionery-mfrs ✓ ..716-833-7540
3210 1 Goodfellow Katherine ✓ 16
3211 7-ELEVEN convenience stores ✓ 716-834-4018
3214 2 No Current Listing
3216 Depetrillo Makenzie ✓ ..716-833-0915
Li Guoming ✓ 10 716-837-0256
UNIVERSAL WIRELESS cellular telephones ✓ 716-768-5086
3218 Parlato Joseph ✓
Weinert Christopher T ✓ 4
3223 RENAISSANCE CUSTOM TATTOO LLC tattooing ✓ 716-831-0588
Rutski Joshua M 6
3225 Wells Stephen ✓
3230 GREEKS & SNEAKS book dlrs-retail ✓ 716-833-4913
Maldonado John Jr 22
3233 McRae Latoya 7
Patricia Sister M 31 • (1939)
3234 AMYS PLACE restaurants ✓ 716-832-6666
PAVILION INTERNATIONAL gift shops 716-834-8310
3236 Mastrantonio Vincent J 30
MUSIC CITY musical instruments-dlrs ✓ 716-838-4547
3240 DAVID LANE DESIGN LLC nonclassified establishments ✓ 716-836-4140
O'CONNELL LUCAS CHELF INC women's apparel- retail ✓ 716-836-4140
OPERA FOUNDATION OF BUFFALO foundation ✓ 716-832-6355
3242 GLORIA J PARKS COMMUINUTY CTR social serv & welfare org ✓ 716-832-1010
UNIVERSITY DISTRICT CMNTY junior-community college ✓ 716-832-1010
3258 AMAK HEALTH CARE AGENCY home health serv ✓ 716-832-0875
3260 1 - 3 No Current Listing (3 Apts)
3260 4 Pollinger Stacy L 6
5 No Current Listing
6 Guarino James D ✓ 12
A SHANGO BISTRO & WINE BAR restaurants ✓ 716-837-2326
3264 1/2 No Current Listing
3268 MING CAFE restaurants ✓ 716-833-6988
SATO RAMEN restaurants ✓ 716-835-7286
3269 CATHOLIC DIOCES OF BUFFALO religious org ✓ 716-833-0298
Hayes Mike • (1956)
KALEIDA HEALTH health serv ✓ 716-833-0298
Ledwon Jacob C 28 • (1956)
NEWMAN CENTER SUNY/AB SOUTH churches ✓ 716-833-6649
NORTH BUFFALO CATHOLIC YOUTH church org 716-862-9801
ST JOSEPH UNIVERSITY CHURCH churches ✓ 716-833-0298
3275 1 ST JOSEPH UNIVERSITY SCHOOL schools ✓ 716-836-7395
3288 Toone Corey D ✓
Zemaitis Kevin
3296 A1 Epstein Daniel M ✓ 24
A1 Gogate Nikhil ✓ 7
A1 Rajamani Keerthi ✓
A1 Thirtamara Keerthi ✓
A2 Nayak Satya C ✓ 11
A3 Sandlesh Nupur ✓ 8
A3 Sandlesh Poorva
A4 No Current Listing
B1 Garapati Nagasree ✓ 3

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAIN ST 2018

MAIN ST Cont'd

B2 Pal Shailendra
B2 Ra Geraldine
B3 No Current Listing
B4 Scandale Nathaniel ✓
C1 Sarkar Mimi
C2 - C4 No Current Listing (3 Apts)
• ZIP CODE 14214 CAR-RT C006
3330 Herman E V
UNIVERSITY PRESBYTERIAN CHURCH churches ✓ 716-836-7660
3350 BIONDOLILLO AMANDA NOEL RN nurses & nurses' registries 716-835-4011
CHILD & ADOLESCENT TREATMENT non-profit org ✓ 716-835-4011
ERDMANN LINDY JEAN counselors 716-819-3420
FELDMEYER BRITTANY social workers ✓ 716-835-4011
FREY HOLLY counselors ✓ 716-819-3420
HODIL KAROLINA counselors 716-819-3420
KENNELL MORGAN E social workers ✓ 716-835-4011
KNIGHT JR MICHAEL J counselors 716-819-3420
LESNIEWSKI MARK W counselors 716-819-3420
LUNAU ADRIANNE counselors ✓ 716-819-3420
MATHIS AMANI counselors ✓ 716-819-3420
O'KEEFFE KAITLIN social workers ✓ 716-819-3420
POLICELLA MEGHAN social workers ✓ 716-835-4011
POLINSKI JILLIAN counselors 716-819-3420
RUSIN SANDRA T counselors ✓ 716-819-3420
STRAKER MARY E nurses & nurses' registries ✓ 716-819-3420
TYLER EMILY social workers 716-835-4011
3362 WENDY'S restaurants 716-862-3511
3382 SUBWAY restaurants ✓ 716-834-6879
3400 BARBER LOUNGE barbers ✓ 716-424-2647
1 No Current Listing
2 Heinl Richard C Jr
3 - 4 No Current Listing (2 Apts)
3404 Anderson Shawn D
Anderson Shania
NORTH BUFFALO CHIROPRACTIC chiropractors dc ✓ 716-835-0066
3410 BACK TO NATURE health & diet foods-retail ✓ 716-835-4779
Horosh Millie • (1939)
3435 Abraham Maria
AL-JEWAIR THIKRIAT DDS dentists ✓ 716-829-6190
ALATOVIC IRIS MD physicians & surgeons ✓
ALKUDMANI HANIA DDS dentists ✓ 716-829-2442
Amaranto Nicole
ARANY HEMA P DDS dentists ✓
ARMY NATIONAL GUARD state government 716-829-2781
ARYA TENZIN DAWA nonclassified establishments 718-898-4806
Bashar Ishral
BRAUNSTEIN BLAIR DDS dentists ✓ 716-829-3847
Burroughs Tiffany
CINQUINO JORDAN DO physicians & surgeons ✓
Cornar Beatriz
COSTA MITCHEL DDS dentists ✓
CRONYN ROBERT L DDS dentists 706-787-6927
DHANANI DILI MD physicians & surgeons
DONLEY MAUREEN P DDS dentists
DUFFY BRIAN M MD physicians & surgeons ✓ 716-829-6103
Dunford A M
GONZALEZ-STUCK YOLY M DDS dentists ✓ 716-829-3551
Green Lynda
GUFRAN MUZAMIL DDS dentists ✓
HAMANN HAROLD C MD physicians & surgeons ✓
HUTCHINS JEFFREY M NP nurses-practitioners ✓ 716-645-2000
KALEIDA HEALTH membership org ✓ 716-829-3364
Kapur Nisha
KATSAVOCHRISTO ANASTASIA DDS dentists ✓ 716-829-0663
KAUR LOVEJIT MD physicians & surgeons ✓
KIM-PUSATERI SEUNGYEE DDS dentists ✓ 716-829-2862
KRUSZKA ANDREW R DDS dentists
KUMAR SEAN MD physicians & surgeons
Lee Yuanjian
Leger Jan
Lewis Akilah H
Lynne Tay
MANOHAR LESLIE M MD physicians & surgeons ✓
Mengalle Dione
Milisauskas Vita
Monica Meghan
MULLOY MARGARET R NP nurses-practitioners ✓
NETWORK IN AGING OF WNY INC nonclassified establishments ✓ 716-829-3712

MAIN ST Cont'd

Novich Lillian
Omphroy Keri
Ortiz Mariely A
PARK & RIDE park & ride
POKU JUDE MD physicians & surgeons ✓
RADICK ERIK JOHN MD physicians & surgeons ✓
Rosa Eng
Rosario Jean ✓
Sade T#
SBSE nonclassified establishments ✓ 716-829-5214
SEFIDROU DARIUS MD physicians & surgeons ✓
Shanke Rohan
SHIN SARAH nonclassified establishments
Silverman Rob
Smith Maggie
Song Yin S
SOPARKAR MIHIR MD physicians & surgeons
SUNY BUFFALO DENTAL MEDICINE dentists ✓ 716-829-2824
THERAPYX INC laboratories ✓ 502-305-4552
UNIVERSITY AT BUFFALO PTHLGSTS physicians & surgeons ✓ 716-626-7927
UNIVERSITY DENTAL ASSOC dentists ✓
UNIVERSITY NUCLEAR MEDICINE physicians & surgeons ✓ 716-838-5889
VALENTE NICOLA A DDS dentists ✓ 716-939-5979
VARGHESE SHANE S MD physicians & surgeons ✓
WEBER NICOLE M speech pathologists ✓ 716-829-3980
Yencer Dick
1 Scarisbrick Laura
3 STATE UNIVERSITY OF NEW YORK university ✓ 716-829-2537
4 UNIVERSITY ORTHOPAEDIC CTR physicians & surgeons ✓
7 Sharma Sonia
G96 Willer Barry & Shaelagh
M Trosin Ciara
10 MILLARD FILLMORE COLLEGE university ✓ 716-829-3131
16 I SUB-BOARD INC laboratories-medical ✓ 716-829-2367
23 HOEFLER EDWARD C nonclassified establishments
23-117 SINGH TEGBEER MD physicians & surgeons ✓ 716-829-5076
32 ST MARIE BRYAN DDS dentists ✓ 716-662-7183
32-215J GUHA UPOMA DDS dentists ✓ 716-829-6261
33 WBFO radio stations/broadcasting co ✓ 716-829-6000
34 Litwin Cindy R
36 UNIVERSITY-BUFFALO STUDENT special interest libraries ✓ 716-829-3316
41 Keller Katelyn
41 Lam Steven
42 Han Boon L
42 Liang Gary
114 HASHAM ZOHRA DDS dentists ✓
116 LAB ANIMAL FACILITIES laboratories 716-829-2919
117 NANI CHRISTOPHER DO physicians & surgeons ✓ 716-829-6130
117 WIERCHOWSKI SHANA A MD physicians & surgeons ✓ 716-829-2012
119 UB ORAL & MAXIOFACIAL SURGERY dentists ✓ 716-829-2722
139 Lampasso Judith ✓
214 Onike Ndidi E ✓
222 UNIVERSITY DENTAL ASSOC dentists ✓ 716-829-3940
245 KNIGHT III PAUL R MD physicians & surgeons ✓ 716-204-3200
252 AIKEN JOANNA MD physicians & surgeons ✓
252 MATHIAS SHALINI MD physicians & surgeons ✓
252 PIVARUNAS GREGORY A nonclassified establishments
406 Nyamsuren Davaadseren
604-BIOM DIETZ DAVID PHD nonclassified establishments
SQUIRE UB DENTAL SCHOOL dental schools 716-829-2821
3442 Paradiso Alaina ✓
A1 Smith Cindy
A10 No Current Listing
A11 Wolf Tiffany M ✓ 716-768-2051
A12 No Current Listing
A14 Pacheco Emmanuel
A15 No Current Listing
A16 Masterman Dennis A ✓
A2 Hoover Laura E ✓
A2 Vettaikkorum A ✓
A3 Mogro Karen
A4 No Current Listing
A5 Shapiro Graly ✓
A6 Sundar Ajay
A6 Motlekar Anu ✓
A6 Sundareswaran Nikhila ✓
A7 Valentine Erika ✓
A8 Moses Timothy J
A9 Sujama Adi ✓
A9 Tian Kianwee ✓
B1 Kemp Joseph ✓
B10 - B11 No Current Listing (2 Apts)
B12 Damawan Thomas
B14 Dunford Robert G ✓
B15 - B4 No Current Listing (4 Apts)
B5 Clark Latoya M ✓

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAIN ST 2018

MAIN ST Cont'd

B6 - B7 No Current Listing (2 Apts)
B8 Lee Jong W 15
B8 Perese Kerry ✓ 716-835-8022
B9 Nazeer Aliya ✓ 6
C1 Gontha Pamela E ✓ 22
C10 - C11 No Current Listing (2 Apts)
C12 Scott Lataevea N ✓ 18
C14 - C16 No Current Listing (3 Apts)
C2 Nair Jyothsna R 9
C3 - C4 No Current Listing (2 Apts)
C5 Cassaday Margaret E 6
C5 Johnson Alaina ✓
C6 No Current Listing
C7 Dolan Cherise 2
C8 - C9 No Current Listing (2 Apts)

3470 TIM HORTONS doughnuts ✓
.....716-831-3211

3476 FALAFEL BAR restaurants ✓
T-MOBILE cellular telephones ✓
.....716-831-1300

3488 ANDRZEJEWSKI JENNA MAE
pharmacists ✓ 716-834-7223
BERENT MELANIE M pharmacists ✓
.....716-834-7223
WALGREENS pharmacies ✓
.....716-834-7223

BUSINESSES 1221 HOUSEHOLDS 1853

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAIN ST 2018

233

MAIN ST Cont'd

3500 SOUTH INDIAN restaurants ✓ 716-834-3672
TOPS FRIENDLY MARKET PHARMACY pharmacies ✓ 716-515-3250
UNIVERSITY PLAZA shopping centers & malls 877-300-2128
VENUS GREEK restaurants ✓ 716-831-8100
WESTERN UNION money transfer serv ✓ 716-515-3240
2 AMHERST THEATRE theatres-movie ✓ 716-834-7655
5 CITIZENS BANK banks ✓ 716-862-0525
6A VILLA shoes-retail ✓ ..716-834-0491
7 RECORD THEATRE records tapes & compact discs ✓ 716-837-2090
8 HAIR PEOPLE beauty salons ✓ 716-834-9090
8 M&T BANK banks ✓ ..716-832-9523
8 Salon Nella P [4]
24 CRICKET WIRELESS AUTH RETAILER cellular telephones ✓ 716-563-1404
130 Black Sylvia ✓ [6]
130 BUFFALO EXECUTIVES ASSN associations ✓ 716-852-6916
130 Gerrish Robert S ✓ [8]
130 (N) Lamb Carolyn
130 UPS STORE mailing & shipping serv ✓ 716-332-2323
130-213 BOUJI BUNDLES nonclassified establishments ✓ 800-549-9013
150 SLICE OF ITALY restaurants ✓ 716-768-2462
270 RADIOSHACK electronic equip/supl-retail ✓ 716-832-8311
270 SPRINT cellular telephones ✓ 716-954-8951
280 DOLLAR TREE variety stores ✓ 716-837-6680
310 SALLY BEAUTY SUPPLY cosmetics & perfumes-retail ✓ 716-831-3286
320 H&R BLOCK tax return preparation/ filing ✓ 716-874-4199
330 ANDY NU INC restaurants ✓ 716-837-6863
340 GNC vitamin & food supplements ✓ 716-835-9340
360 FOREVER NAILS manicuring ✓ 716-833-5424
500 GAMESTOP games & game supl ✓ 716-836-3748
3540 MC DONALD'S restaurants ✓ 716-832-6221
3586 KEY BANK banks ✓ 716-871-4260
3604 DYNAMIC ELECTRO ACOUSTICS acoustical contractors ✓ ..716-836-2625
SPEAKER SHOP INC home theatre sys ✓ 716-837-1557

MAIN ST

1A 1B 1C 1D 2A 2B 2B 2B 2C 2D 3A 3D 3D 4A 4D 5A 5C 5D 6A 6B 6C 6D 6D 7A 7B 7D 8A 8B 8D 9A 9C 9D 10A 10E 10C 10E 11A 11E 12A 12E 12C 12D 3911 Ho MI RC 3 N 4 3921 BL BL

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 2018



2939 Kerr William ✓
+ RIVER RD INTERSECTS
BUSINESSES 340 HOUSEHOLDS 1304

NIAGARA FALLS BLVD (BUFFALO)-FROM 2 PELHAM DR NORTH
• ZIP CODE 14214 CAR-RT C006
2 Stewart Charles ✓ 716-836-7595
Szemraj James E ✓ 21 (1939)
22 No Current Listing
37 Frempong Hayford ✓
38 Qutubuddin M ✓ 7 (1939) 716-834-2934
40 Dewald Jonathan M ✓ 17 (1939)
41 Newman John C ✓ 14 (1925) 716-837-3036
42 Proacia Joseph D ✓ 9 (1939)
43 No Current Listing
45 Lawson Cecelia M ✓ 14 (1939)
Muldrow Mattie M ✓ 46 (1925) 716-832-6625
46 Kassman Anthony J Sr & Helen K ✓ 37 (1925)
50 Dulanski David S 28 (1925)
54 Metzger Michael M & Erika A ✓ 53 (1922)
58 Brace Frederick E Jr & Kathleen L ✓ 35 (1940)
62 Kowsky Francis R & Helene D ✓ 42 (1930) 716-836-6069
65 McCraty Elner J ✓ 32 (1900) 716-832-2274
66 Klein Rose M ✓ 52 (1940) 716-837-9007
Pedone David L ✓ 9 (1939)
69 Jarosz Michael S & Susan S ✓ 21 (1900) 716-832-1882
70 Kogler Susan M & James F ✓ 45 (1930) 716-836-5436
73 Conti Joan N ✓ 24 (1939)
74 No Current Listing
77 Walls Gerald W Sr & Dalonda M ✓ 24 (1931)
78 Poepsel K ✓ 9 (1939) 716-834-0560
Privateer Christoph A & Karen D ✓ 24 (1930)
81 No Current Listing
82 Reade Dorothy R ✓ 21 (1948) 716-837-7520
Reade Catherine P 716-837-7520
85 Cruz Ruth M ✓ (1939)
Cruz Augustin Jr
Vazquez Ruth ✓
Vazquez Lysette
86 Leising Peter C & Jeanne M ✓ 27 (1931)
89 Helfer Lauren E ✓ 9 (1925)
90 Mendolera Joseph P ✓ 17 (1931)
Rottger John P ✓ 9 (1939)
95 No Current Listing
96 Uebbing Mary C ✓ 13 (1920)
Uebbing Matthew B
97 Simmons Lorayne D ✓ 30 (1932)
100 Owusu Mary 2
Sharma Prateek ✓ 3
101 Morris Farzana R ✓ 26 (1939)
Patel Samina & Wasim ✓ 40 (1939) 716-833-0638
Shirazi Bina P ✓ 22 (1939)
104 Coppola Joseph A & Ruth A ✓ 21 (1938)
105 Maze Scott M & Leanne M ✓ 9 (1930)
+ BELLEVUE AVE INTERSECTS
109 Palmieri Matthew R & Pamela L ✓ 6 (1928) 716-931-5881
112 No Current Listing
115 Arditi Olivia L ✓ 19 (1925)
116 Collins Sarah C ✓
Scarlett Kellyann ✓ (1939)
119 Cooper Blake A ✓
Youhess David A ✓ (1939)
120 Capalbo Marcello ✓
123 Msuku-Purks Gudiya R ✓ 13 (1930)
124 Wells Monica M ✓ 13 (1926)
127 Bryan Jodi M ✓ 13 (1939)
128 EDNA LOUISE ESTATE SALES estates ✓ 716-812-1018
Klemp Brian M ✓ (1939) 716-837-1965

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 2018

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 2018

NEWBERRY LN - NIAGARA FALLS BLVD

NEWHOUSE RD Cont'd
6065 Leman Michael C & Donna M ✓ (2000)
+ CLARENCE CENTER RD INTERSECTS
+ CLARENCE LN N ENDS
6075 Rogers Joseph W ✓ (1989)
Rogers Jessica
BUSINESSES 2 HOUSEHOLDS 39

NEWMARKET AVE (CLARENCE)
+ KINGSTHORPE TER CONTINUES
+ KINGSTHORPE TER INTERSECTS
• ZIP CODE 14031 CAR-RT C001
9839 Kelkenberg Eleanor L ✓ (2004)
Kelkenberg Orin
9842 No Current Listing
9845 Sprankle Thomas C & Helen C ✓ (2004) 716-759-7849
9851 Gibson Frank C ✓ (2004)
Gibson Patrick
9862 Kalinski Dennis W & Jean ✓ (2003)
9857 Ruhland Katherine A ✓ (2003)
9858 Barth Andrew C ✓ (2000)
Martin Joel ✓ (1994)
Martin Susan
9863 Ferm Gordon T & Sandra S ✓ (2003)
9864 Juergens Pamela R ✓ (2002)
9869 Wohlfeil Dale E & Kathleen E ✓ (2004)
9870 Hoehman Debra L ✓ (1994)
Moore Shirley J ✓ (2004)
9875 Vannuys Violet M ✓ (2003)
9876 Grove James K & Gail A ✓ (2005) 716-759-8304
9891 Benfanti Doreen G ✓ (1994)
Singiser Robert B ✓ (2005)
9892 Hollis Ann ✓ (2006) 716-759-1338
9897 Drees M L ✓ (1994) 716-759-8151
Georger Jacque H ✓ (2008)
9898 Sabers Dolores A ✓ (2006) 716-759-6287
+ ROCK OAK PKWY INTERSECTS
9903 No Current Listing
9904 Love John F & Dorothy ✓ (2005) 716-759-8868
9909 Beaumont Marie M ✓ (2005) 716-759-7923
9910 Sekuterski David J ✓ (2003)
9917 Krasinski Patricia P ✓ (2005)
9923 Skingley Charlene J ✓ (1994)
9927 Cian Gary B & Becky B ✓ (2005)
9933 Martin Marlann R ✓ (2003)
+ TOBERMORY AVE ENDS
9943 Hassell Patrick M & Patricia M ✓ (2008) 716-759-7049
9949 Hansen Gregory J ✓ (2004)
Hansen Alicia
9955 No Current Listing
+ WHITWICK TER INTERSECTS
HOUSEHOLDS 32

NEWPORT AVE (BUFFALO)-FROM 627 SAINT LAWRENCE AVE NORTH
+ FARMINGDALE RD CONTINUES
• ZIP CODE 14225 CAR-RT C024
91 Maciejewski Ronald A & Mary E ✓ (1981)
+ KENMORE AVE INTERSECTS
HOUSEHOLDS 1

NFA PARK (BUFFALO)
• ZIP CODE 14228 CAR-RT C061
1 RONALD J PAPA FIRE ADJUSTER
Insurance adjusters ✓
BUSINESSES 1

NIAGARA FALLS BLVD (BUFFALO)
• ZIP CODE 14226 CAR-RT C001
165 No Current Listing
171 Balgobind Mohini D ✓ (1952)
Singhal Darpan ✓
177 McNerney Dennis J ✓ (1952) 716-835-5400
179 No Current Listing
189 Feuerstein Robert S (1950)
195 Puehn George E & Georgia E ✓ (1932) 716-833-6533
199 Gross Kenneth J & Shelly K ✓ (1930)
Melia David ✓ (1952)
207 No Current Listing
213 Aronica Justin (1952)
Chethil Salman ✓
Khalafalla Abubaker ✓
Reilly Kaitlynn ✓
219 Flaitz Heather M ✓ (1952)
225 Phillips Robert J ✓
LEFT Fiorella Robert V ✓ (1952) 716-833-4579
231 Lesniowski Kenneth ✓ (1952)
237 Watson Sarah J ✓ (1952)
249 Ki Brenda P ✓ (1952)
255 Johnson Ashley ✓ 716-862-4209
261 Jankowski Jennifer ✓
Sherwood Jennifer A ✓ (1952)
Sherwood Stacy L
267 Johnson David P Sr & Sherry R ✓ (1944) 716-837-0751
Pease Sherry R ✓ (1952)
Pease Megan
273 Horner A ✓ (1952) 716-837-2439
Leary Adrienne J ✓ (1952)
Leary Jennifer A
Vaughan Kristin R ✓ (1952)
Weisbrodt Sarah L ✓ (1952)
Williams Carolyn M ✓ (1952)
279 No Current Listing
285 Cooper Paula A ✓ (1952)
Meinkes Nan B ✓ (1952)
291 Mattina Rita F ✓ (1952) 716-833-4049
297 Lex Kevin A & Svetlana V ✓ (1952)

NIAGARA FALLS BLVD Cont'd
Schewtchuk Dominka ✓ (1952) 716-824-1495
303 No Current Listing
309 Kyse Terrie K & Willie A ✓ (1952) 716-835-0527
Reed Shenara D ✓ (1952)
315 Huang Josie ✓
Jin Shengxi ✓
321 No Current Listing
327 Schaeffer Lucille J ✓ (1952)
333 Chazen Alana B ✓ (1952)
Chazen Jeremy
McKinnon Sally A ✓ (1952)
339 Cascilano Margo ✓
Okyere Docket
Rahman Abdul ✓
345 Jenney Jessica L ✓ (1952)
Talarico Mike ✓
• ZIP CODE 14226 CAR-RT C043
363 Cox Bruce H & Linda E ✓ (1947)
369 Konovitz Susan A (1947)
Konovitz S D
373 Gordon Loretta L ✓ (1947) 716-833-4927
Gordon Lorrie 716-833-4927
383 Banks Selina D ✓ (1952)
Powers Tyrone ✓ (1947) 716-835-2717
389 Cook Nicholas J & April L ✓ (1946)
395 No Current Listing
399 Adame Vanessa C & Bennie ✓ (1947) 716-836-0192
405 Flint Wildrena ✓ (1952)
Flint Robert D
409 No Current Listing
415 Myers Gregory W & Christine A ✓ (1947) 716-833-4606
423 D'Amico Salvatore J ✓ (1947)
Strade Roger J & Kelly A ✓ (1952)
429 Trinh Hong M ✓
435 Bousamra Chuck ✓
Bousamra Marion
O'Connor Sandra L ✓ (1947)
716-838-4351
SEARS AUTO CTR auto rpr & serv ✓
716-836-7626
443 Difrancescofields Lisa A ✓ (1947)
Fields Lisa D & James M ✓ (1947)
453 Haider Syed J Jr ✓ (1952)
Jaffri Shams A & Rafia S ✓ (1947) 716-838-1035
459 Thelvendiran Niranjan ✓ (1952)
465 No Current Listing
+ OXFORD AVE INTERSECTS
• ZIP CODE 14226 CAR-RT C034
479 FARRELL PHOTOGRAPHY
photographers- portrait ✓
716-836-1447
483 Tucker Ronnie E ✓ (1947)
716-833-0147
489 Spasezska Irena M ✓ (1948)
495 Wong Dennise ✓ (1948)
716-832-8347
505 Wong Manuel G ✓ (1948)
716-837-4918
Wong Marshall 716-837-4919
513 Leach Mary L ✓ (1946)
716-838-1771
519 Saxena Suresh B ✓ (1949)
Saxena Bela R
523 Chen Bin (1958)
Deschamps Yennifer ✓
Pittman Scott ✓
529 Lewis Dion C ✓ (1958)
Rodriguez Alida R ✓ (1958)
535 Favors Iesha ✓
Hill Pamela K ✓ (1958)
543 Vadivel Colin ✓ (1948)
716-783-8947
549 Bookhagen Susan M ✓ (1948)
553 - 559 No Current Listing (2 Hses)
563 Singh Arthur & Asha W ✓ (1948)
716-834-5695
569 Kuberski Jacob F ✓ 716-862-4317
579 Didomizio Joseph C & Annetta S ✓ (1948) 716-838-3412
+ YALE AVE INTERSECTS
593 Seland Keith A ✓ (1958)
599 No Current Listing
605 Heim James A & Jennifer G ✓ (1939)
613 Crane David C & Kim M ✓ (1952)
Gaughan Robert M & Alice B ✓ (1952)
Redenbach Kim M ✓ (1958)
619 Gladwyn Jacob ✓
Jacob Gladwin A & Sunita ✓ (1948)
625 Patterson Robert A & Roberta ✓ (1958) 716-837-4687
633 Relan Sanjeev D Jr & Aureeta ✓ (1947) 716-834-0716
639 Houze Sonja A ✓ (1947)
716-464-1110
Houze Sa 716-464-1110
643 Alexander Seema R ✓ (1948)
716-834-1711
649 Southwick Dianne L ✓ (1948)
716-832-3802
Troicke-Green Dorathea E ✓
653 Johnson Mary L ✓ (1948)
Ridgeway Anthony ✓ (1958)
659 Merner Lillian L & Darrell ✓ (1958)
663 Menchetti Peter P II ✓ (1947)
716-832-3418
665 Loveland Joseph K & Brandy D ✓ (1948)
669 No Current Listing
673 Platt Robert W ✓ (1958)
Platt Pamela D
+ LONGMEADOW RD INTERSECTS
+ LONGMEADOW RD INTERSECTS
677 STAR INK INC grocers-retail ✓
Continued next page

STREET GUIDE

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 2018

NIAGARA FALLS BLVD

NARDIN DR (DEPEW)-FROM 31 PRINCETON AVE NORTH Continued from prior page
NIAGARA FALLS BLVD Cont'd
.....716-833-2666
679 SHAWARM CITY restaurants ✓
.....716-862-8000
681 CHINA MAX restaurants ✓ ..716-833-8885
711 JAZZYOBICS BY SUZY dancing instruction ✓ 716-836-2999
TRINITY UNITED METHODIST CHR churches ✓ 716-835-7711
733 AMERICAN AUTO WORLD armatures ✓
.....716-832-3838
+ RUTH AVE INTERSECTS
751 HECTOR'S HARDWARE & PAINT CO hardware-retail ✓ 716-832-9310
765 CHRISTIAN FELLOWSHIP BAPT CHR churches ✓ 716-835-2899
771 MASTER PHONE INC telephone equip/ supl ⊛ 716-777-8899
773 ALADDIN'S EATERY & BAKERY restaurants ✓ 716-322-1046
Chainani Ramesh L 11 ● (1958)
CHAINS ENTERPRISES INC tailors ✓
.....716-837-8344
785 BOULEVARD INN hotels & motels ✓
.....716-837-7400
Ⓓ Qu Hong ✓
Reibmann Michael R ✓ 14 ● (1958)
789 Branch Eugene M & Maureen B ✓ 38 ● (1958)
Ricchiazzi Matthew J ✓ 9
Ricchiazzi Roslyn R
803 FUNDING GROUP MORGAN INC financing ✓ 855-864-5697
SOKOLSKI SUTHERLAND & LYONS accountants ✓ 716-834-2117
Sutherland D W ✓ 38 ● (1958)
+ BETINA AVE INTERSECTS
839 839 BOULEVARD CTR shopping centers & malls
Gorino Charles 10 ● (1957)
MASTER GORINO'S TAE KWON-DO martial arts instruction ✓ ..716-836-5425
NORTHTOWN ANIMAL HOSPITAL veterinarians ✓ 716-834-8387
843 Downey Timothy P & Maripat P ✓⊛ 11 ● (1957)
MAINTENANCE & MANAGEMENT ASSOC cleaning serv- industrial ✓
.....716-836-2111
Ⓓ Melvin Kevin ✓ 716-834-2368
845 Abbarno Michele ✓ 2
Moran James P Jr & Chandra L ✓⊛ 4
SENTRY APPLIANCE SVC CO appliances- household-major-rpr ⊛
.....716-835-2991
Ⓓ Willett Joshua ✓
847 Malik Sardar ✓ 24 ● (1957)
MALIK TAILORS tailors ⊛ ..716-862-0122
Ⓓ Malik Sardar ✓ ● (1957)
853 FANCY FLORISTS INTL INC florists-retail ✓⊛ 716-836-0844
861 Wahl Philip J & Cheryl J ✓ 38 ● (1940)
.....716-834-4312
865 Ⓓ Balestera Dara ✓ 716-768-3429
Ⓓ Layne Robert ✓
Smith David J ✓ 9 716-836-1046
871 A CAREER RESUME publishing consultants ✓⊛ 716-837-2798
Romanow Brenda T 33
2 HERO DATA SVC info technology serv ✓
.....716-833-1685
5 DESIRED IMAGE skin treatments ✓
.....716-834-1123
200 VCMS INC business mgmt consultants ✓⊛ 716-837-4140
885 MACOFF ELECTRIC LTD caskets ✓
.....716-837-7100
899 NICASTRO ACCOUNTING SVC pest control ✓ 716-831-8690
925 U-HAUL AT NIAGARA FALLS BLVD truck renting & lease ✓ 716-832-1778
+ EGGERT RD INTERSECTS
+ EGGERT RD CONTINUES
• ZIP CODE 14226 CAR-RT C041
951 EL PALENQUE MEXICAN GRILL restaurants ✓ 716-446-9206
+ SHERIDAN DR INTERSECTS
995 BRIDGESTONE MASTERCARE SVC CTR auto rpr & serv 716-837-9700
FIRESTONE COMPLETE AUTO CARE auto rpr & serv ✓ 716-261-3945
1009 Watcharanantakul Sutam ✓ 10
Watcharanantakul Sunari
1025 PEP BOYS auto parts & supl- retail-new ✓
.....716-831-0370
1061 Chimera Joann E & John E ✓ 18 ● (1965)
PLANT PLACE & FLOWER BASKETS florists-retail ✓⊛ 716-838-3400
1101 AQUAJET & ROBERT'S PLUMBING plumbing contractors ✓ ..716-877-1534
CUSTOM CUTS HAIR DESIGN beauty salons ✓ 716-836-4247

NIAGARA FALLS BLVD Cont'd
ROBERT'S HEATING CO plumbing contractors ✓ 716-877-1534
3 LIBERTY TAX SVC tax return preparation/filing ✓ 716-835-1100
3 NATIONWIDE INSURANCE insurance ✓
.....716-833-1900
4 SOUNDWAVE DJ & PHOTO music & live entertainment ✓ 716-639-9283
A Linton Alexander F ✓ 7
• ZIP CODE 14226 CAR-RT C032
1145 CHILI'S GRILL & BAR restaurants ✓
.....716-832-3730
1167 AUDIOMOTIVE CREATIONS auto radio & stereo sys ✓ 716-783-7480
1171 PREMIER CAR CARE auto rpr & serv ✓
.....716-837-4000
1205 M&T BANK banks ✓⊛ 716-835-5118
1207 POSTER ART BLVD MALL sportswear-retail ✓ 716-834-1428
1209 TGI FRIDAY'S restaurants ✓⊛
.....716-835-6000
1211 629 CHILDREN'S PLACE childrens & infants wear ✓ 716-831-3201
1215 BANANA REPUBLIC clothing-retail ✓
.....716-838-0671
FYE video tapes discs & cassettes ✓
.....716-834-9097
1227 VICTORIA'S SECRET lingerie ✓
.....716-833-0385
1235 AMERICAN EAGLE OUTFITTERS clothing-retail ✓ 716-832-1100
1237 A-11 HOT TOPIC clothing-retail ✓
.....716-446-0400
1247 BONEFISH GRILL restaurants ✓⊛
.....716-833-6106
1253 LITTMAN JEWELERS jewelers-retail ✓
.....716-835-4799
1255 FINISH LINE AT MACY'S shoes-retail ✓
.....716-837-9400
LENSCRAFTERS optical goods- retail ✓
.....716-446-1306
SUNGLASS HUT sunglasses & sun goggles ✓ 716-837-1065
1257 E GYMBOREE childrens & infants wear ✓
.....716-836-0622
1259 C CRAZY 8 childrens & infants wear ✓
.....716-834-4754
1259 A/2 317 TEAVANA coffee & tea ✓
.....716-833-3234
1259 C/2 201 PAYLESS SHOE SOURCE shoes-retail ✓ 716-838-0701
1261 DESTINATION MATERNITY maternity apparel
H&R BLOCK tax return preparation/filing ✓
.....716-833-4879
PICTURE PEOPLE photographers-portrait ✓ 716-837-1381
1 BUYBUY BABY baby accessories ✓
.....716-833-3714
2 MICHAELS craft supl ✓ ..716-834-3322
2 MIRACLE-EAR HEARING AID CTR hearing aids ✓ 716-836-6228
1265 GNC vitamin & food supplements ✓
.....716-832-0360
KAY JEWELERS jewelers-retail ✓
.....716-837-8895
TEE SHIRT clothing-retail ✓
1267 Fisher Jake ✓⊛ 9
701 MEN'S WEARHOUSE men's clothing & furnishings ✓ 716-837-1966
1269 GENERAL NUTRITION CTR health & diet foods-retail ✓
1273 SPENCER'S gift shops ✓ ..716-835-8157
1277 725 AERIE lingerie ✓ 716-835-4213
1281 CHRISTOPHER & BANKS-MPW clothing-retail ✓ 716-831-0013
1285 EXPRESS clothing-retail ✓
.....716-834-5864
1287 No Current Listing
1291 DISCOUNT PERFUME cosmetics & perfumes-retail ✓ 716-833-5459
T T NEW YORK women's apparel- retail ✓
.....716-831-8831
1293 CHAMPS SPORTS sporting goods- retail ✓ 716-836-6456
1303 JC PENNEY department stores ✓
.....716-837-2100
JC PENNEY OPTICAL optical goods-retail ✓ 716-833-1166
JC PENNEY SALON beauty salons ✓
.....716-837-1408
SEPHORA INSIDE J C PENNEY beauty supl & equip-rpr ✓ 716-837-2100
• ZIP CODE 14226 CAR-RT C030
1355 DELTA SONIC CAR WASH car washing & polishing ✓ 716-832-4050
1385 MC DONALD'S restaurants ✓
.....716-833-2159
1395 ARBY'S restaurants ✓ 716-832-5231
1405 Fischer Joseph ✓ 3
SCHUELE PAINT CO paint-retail ✓
.....716-836-3871
• ZIP CODE 14228 CAR-RT C057

Grow Your Business with E-MAIL Marketing

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 2018

WASHINGTON MILLS TONAWANDA
INC abrasive products ✓ ..716-693-45
BUSINESSES 10 HOUSEHOLDS

NIAGARA FALLS BLVD (BUFFALO)
• ZIP CODE 14223 CAR-RT C077

154 (N) Guigui Erick
158 (N) Clayton Lori ✓ 716-835-05
(N) Lehane Denise ✓
170 Lang Michelle ✓ [2]
1 Mitchell Mercedez D ✓ @ [5]
2 Torres Ricardo ✓ [9]
3 Ilardo Laurence R ✓ [16] ..716-832-48
174 Zheng Shu ✓ [7]
180 Corbin Jesse ✓ [3] 716-877-06
1 No Current Listing
2 Agustiady Andry K @ [23]
3 Croft Juanita ✓ [3]
4 Joe Benjamin S [9]
186 (N) Ujoatu Chinedu
192 Green Marilyn E ✓ [23] 716-832-50
Lewandowski William R ✓ [7]
Lewandowski Mary E
1 No Current Listing
2 Heary John F ✓ @ [23]
198 (N) Saelee Prontip
(N) Simmons Kylene ✓
1 No Current Listing
2 Jeon Hyewon ✓ [7]
200 Kim Min ✓ [8]
(N) Scott Soni ✓ 716-833-351
2 (N) Scott David I & Alice D ✓ @
202 Dwight Wallace F II ✓ [9] ♦ (1952)
1 No Current Listing
204 Kazinski Brian D ✓ @ [22] ..716-832-529
Lelito Kevin K ✓ [34] 716-833-167
206 Mishra Riya @ [2]
2 No Current Listing
208 BOND VIRGINIA K MD physicians & surgeons ✓ 716-264-419
218 Orrange Scott F ✓ [3]
Strawbvridgre Cassie ✓ @ [23] ♦ (1952)
Strawbvridgre Justina L
2 No Current Listing
222 Gisel John C & Barbara E ✓ [39] ♦ (1952)
.....716-259-910
228 Clark Rodney ✓ [11] ♦ (1952)
.....716-833-036
232 (N) Molle Lisa M ✓ @
240 AFTERMATH TATTOO STUDIO tattooing
✓ 716-832-362
McVaugh Judith M [22]
1 Chomjandr Wassana ✓ [6]
1N No Current Listing
2 Moore John J ✓ [21]
3 Gonzalez Ann ✓ [4]
A BOULEVARD HAIR CARE beauty salons
✓ 716-832-106
244 Channergordon Lorna ✓ [2]
248 Jones Jarren ✓ @ [5]
Jones Brianna
Walker Alyssa M @ [2]
1 Cramer Geoffrey A @ [2]
2 - 3 No Current Listing (2 Apts)
252 Dussault Wayne A ✓ [37] ♦ (1951)
.....716-838-1810
Dussault Anjuli S 716-838-1810
254 Bell Ronald ✓ [4] ♦ (1940)
258 Ringler Mark J ✓ @ [5]

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 2018

NEW NEIGHBOR

165

NIAGARA FALLS BLVD Cont'd

Wilson Mercedes E & James E ✓
716-883-0629
262 Fisher Amanda C ✓ (1940)
Noltee Cassondra ✓
268 Hodur Darrell L ✓ (1916)
270 Henry Ruthann M & David C ✓ ◆ (1953)
716-836-2050
274 Johnson Laquita E ✓ ◆ (1920)
276 Fanara Antonio ✓ ◆ (1953)
Vella Josephine M ✓ ◆ (1953)
280 Muscato Joseph P & Pauline P ✓ ◆ (1916)
286 Daher Joseph J ✓ ◆ (1928)
290 Bishop Gabrielle C ✓ ◆ (1953)
Sumter Nathaniel ✓
716-835-1093
292 Miller Shawn W & Beth M ✓ ◆ (1927)
298 Han Zhonghan ✓
300 Lambert David E ✓ ◆ (1945)
304 No Current Listing
308 Cierno Brian J ✓ ◆ (1930)
716-834-6041
Cierno Michelle M
716-834-6041
310 Godleske Thomas J ✓ ◆ (1930)
716-835-5693
316 Demers Michael J II ✓ ◆ (1922)
320 No Current Listing
324 Manzella Heather ✓
716-834-1539
328 Kindron David J ✓ ◆ (1995)
716-837-8313
330 Allen Janette
Allen D J
334 No Current Listing
338 Soika Alfreda T & Anthony ✓ ◆ (1920)
716-832-1444
342 Fildes Lynn M & Robert M ✓ ◆ (1916)
716-836-6282
344 Hewson Robert A ✓ ◆ (1944)
ROBERT A HEWSON DPM physicians & surgeons ✓
716-833-8094
• ZIP CODE 14223 CAR-RT C049
354 Shamman Ahmed ✓ ◆ (1953)
716-832-0160
• CAMBRIDGE BLVD INTERSECTS
358 Wheeler Mary A & Micky ✓ ◆ (1900)
716-832-0989
362 Ruffino Robert J & Joan E ✓ ◆ (1937)
716-832-7435
370 Bartlett Joshua M ✓
Lam Shek S ✓ ◆ (1953)
Lam Vicki W
378 Hatcher Richard J Jr ◆ (1922)
382 No Current Listing
386 Larson Casey
Tiwari A ✓
1 Sepulveda Edwin L
390 Beach Cris ✓ ◆ (1953)
394 Kelleher Thomas M & Theresa Y ✓ ◆ (1929)
396 Markkandu Pathmarajа ✓
716-436-2111
398 Barnes Timothy D ✓ ◆ (1927)
406 Czarnecki Renay ✓
Grabowski Hank ✓
Grabowski Erica
Rodems Lisa ✓
410 Yager William T ✓ ◆ (1997)
Yager Robert D
414 Stringfellow Ray P ✓ ◆ (1935)
418 Evans Joseph P ✓
• PAIGE AVE BEGINS
422 SCHWARTZ MICHAEL DDS dentists ✓
716-835-3906
4 - 5 No Current Listing (2 Apts)
6 Renda Anthony ✓
424 SWEENEY'S GARAGE auto rpr & serv ✓
716-832-0648
442 DANCE STUDIO dancing instruction ✓
716-335-8652
S&E JEWELERS jewelers-retail ✓
716-832-1595
446 Ippolito Ramon J ✓
716-876-7595
KISLOSKI CONSTRUCTION GROUP construction companies ✓
716-835-5706
1 Kisloski David D Jr & Brenda J ✓
2 Smith Marcus T ✓
462 DARCY'S GROOMING pet washing & grooming ✓
716-836-0456
466 Eddy Pesirterme M ✓ ◆ (1953)
716-262-0225
Eddy Amy L
716-262-0225
474 4 Haq Eajaz S ✓
716-833-3697
4 HAQ SYED E MD physicians & surgeons ✓
716-312-4170
7 ATTAULLAH A SYED MD physicians & surgeons ✓
716-832-1050
• CHALMERS AVE INTERSECTS
480 REEM SALON & SPA LLC beauty salons ✓
716-393-7413
500 DIP & DIVE divers equip/supl ✓
716-837-3483
512 SAIGON BANGKOK RESTAURANT restaurants ✓
716-837-2115
528 NIAGRA FALLS INTL TRADING CORP international trade serv ✓
716-833-7200
536 LAKELAND SUPPLY INC auto body- rpr & painting ✓
716-834-2776
540 Chauhan Rajender S & Sujata ◆ (1953)
NIAGARA FALLS DAILY GROCERS grocers-retail
716-833-3712
US POST OFFICE post offices ✓
716-833-3712
546 K CAFE restaurants
716-836-9888
• DECATUR RD INTERSECTS
564 Bocchino Jonni E ✓ ◆ (1950)
716-835-1793
Bocchino Elizabeth M
716-835-1793
570 McKeone Gerald J ✓ ◆ (1946)
580 Fix Joan W ✓ ◆ (1946)
716-931-5899

NIAGARA FALLS BLVD Cont'd

588 Lunney Dennis M & Melissa A ✓ ◆ (1950)
716-833-8971
594 Diamond Anthony J ◆ (1947)
Michael Ronnie C ✓ ◆ (1950)
600 Villanueva Ester S ✓ ◆ (1946)
608 Harrison Rosemary L ✓ ◆ (1946)
616 Penfield Anne M ✓ ◆ (1946)
Penfield Amber L
624 No Current Listing
628 Melchiorre Christine G ✓ ◆ (1946)
Melchiorre Maria C
634 Barnes Thomas ✓
Drake Zerena N ✓ ◆ (1950)
640 No Current Listing
644 Liscavage William K ✓ ◆ (1946)
716-835-9609
650 Huffman Stephen L & Tammy L ✓ ◆ (1947)
654 Horbowicz Jeffrey J & Denise ✓ ◆ (1946)
716-835-7255
• LINCOLN PARK DR INTERSECTS
664 Israel Chad R & Danielle M ✓ ◆ (1953)
716-835-1720
668 Backey Perique T ◆ (1953)
670 Sahail Shahzad ✓ ◆ (1947)
674 Ranney Gary L ✓ ◆ (1949)
716-835-1198
678 Zimmerman Richard H & Bree A ✓ ◆ (1949)
684 Pray Donald P & Carole J ✓ ◆ (1949)
716-832-7793
688 Bonillas Angelica ◆ (1949)
694 Bisher Douglas M ◆ (1953)
Bisher Julie
698 Giambrone Andrew E Sr & Dianna M ✓ ◆ (1949)
704 Riley Colleen ✓
Weldy Jason Jr
710 Blom Carol D ✓ ◆ (1950)
716-835-6447
716 Francken Timothy M & Kathleen I ✓ ◆ (1947)
716-833-3098
722 Green Joslyn A ✓ ◆ (1953)
728 No Current Listing
738 Dickey Ronald G & Robin L ✓ ◆ (1949)
716-446-1833
• HIGHLAND AVE INTERSECTS
748 Powell Arlene P ✓ ◆ (1949)
716-837-1397
758 No Current Listing
770 AMERICAN FREIGHT FURN-MATTRESS furniture-dlrs- retail ✓
716-695-2500
GARDEN OF HEALTH FAMILY CHIRO chiropractors dc ✓
716-462-4093
1 MOSS ERIN M counselors ✓
716-507-1124
• HARRISON AVE INTERSECTS
782 DAIRY QUEEN ice cream parlors ✓
716-834-2447
798 STURNIOLO FRANK M PHD psychologists ✓
716-832-1434
TEAM Q EMPLOYEE ASSISTANCE psychologists ✓
716-832-0010
800 Mardini Amal ◆ (1955)
• MOORE AVE INTERSECTS
804 Tran Henry & Vivian ✓ ◆ (1955)
820 NOCO ENERGY convenience stores ✓
716-833-3217
850 Choi Sang S ◆ (1958)
860 Schober Robert W ◆ (1955)
1 KENILWORTH ELECTRONICS CO radio communication equip/sys ✓
716-837-6666
874 Klaskala Valerie J ✓ ◆ (1955)
Klaskala Jeremy J
1 CORSI A FIRST KLASS COLLISION auto body- rpr & painting ✓
716-835-2455
900 BUFFALO COMPUTING SOLUTIONS computers- networking ✓
716-852-0523
Bull Amy ✓ ◆ (1955)
ST CLAIR CONSTRUCTION CORP construction companies
910 AMHERST SECURITY PRO INC security guard & patrol serv ✓
716-833-4700
DAVID PHOTO SVC INC photo finishing-retail ✓
716-835-4620
DPS VIDEO video production & taping serv ✓
716-835-4635
920 Battista Raymond ✓ ◆ (1955)
716-837-0201
OASIS DANCE CTR sports info ✓
716-668-0288
926 SUN CITY MATTRESS mattresses ✓
716-834-7400
• EGGERT RD INTERSECTS
934 PARTNERS PIZZERIA pizza ✓
716-834-3434
• SHERIDAN DR INTERSECTS

BUSINESSES 37 HOUSEHOLDS 149

NIAGARA FALLS BLVD (NORTH TONAWANDA)

• ZIP CODE 14120 CAR-RT C043
628 Collis Robert K ✓ ◆ (1958)
Mc Phaden Cynthia M ✓ ◆ (1939)
642 De Mart Michael A Jr & Marcia A ✓ ◆ (1957)
648 Dreier Eugene & Laurie L ✓
Haynes Gene ✓
716-248-1177
Rupp Emily ✓
654 Saunders Nathan L ◆ (1954)
664 FARMERS INSURANCE insurance
716-260-1076
FARMERS INSURANCE-LARRY ACKER insurance ✓
716-260-1076
HEALTH RESOURCES INSURANCE insurance ✓
716-693-6800
672 Aponchuk Rayisa ✓
716-694-1405

NIAGARA FALLS BLVD Cont'd

Aponchuk Nataliya
716-694-1405
682 Daniels John ◆ (1954)
686 Schmidt Ryan T & Tracy L ✓ ◆ (1954)
692 Granto Anne N ✓ ◆ (1890)
716-380-2272
696 Granto Gerald C Jr ✓ ◆ (1953)
700 Pena Felip ✓
716-260-2782
1 Sentz Arthur J Jr ✓
716-695-6027
2 Fortuna Angelina ✓
706 Sniadecki John E Jr & Danielle R ✓ ◆ (1954)
711 JERRY GRADL MOTORS pumps-rpr ✓
716-743-4001
712 HAICK ACCOUNTING financial advisory serv ✓
716-694-7728
Haick Christopher W ◆ (1910)
716 HAICK ACCOUNTING SVC acctng & bkpg genl serv ✓
716-695-9542
748 TIM HORTONS doughnuts ✓
716-692-8630
800 ST JUDE THE APOSTLE PARISH clergy ✓
716-694-0540
886 SUBWAY restaurants ✓
716-695-3110
WALMART BAKERY bakers-retail ✓
716-243-4158
WALMART GROCERY PICKUP grocery pickup- curbside ✓
716-853-9328
WALMART PHARMACY pharmacies ✓
716-243-4162
WALMART PHOTO PRINTING photo finishing- retail ✓
716-243-4161
WALMART SUPERCENTER department stores ✓
716-243-4138
WALMART VISION & GLASSES optical goods- retail ✓
716-243-4159
900 ALLAN VAILLANCOURT nonclassified establishments ✓
AN-COR INDUSTRIAL PLASTICS fiber glass fabricators ✓
716-695-3141
Dicky Joann ✓ ◆ (1958)
908 COMMERCIAL FABRICS boiler tubes ✓
716-694-0641
DOC'S ARCHERY SALES & SVC archery equip/supl ✓
716-693-2703
NLTC INC radioactive materials ✓
716-693-0550
PAWS AT PLAY INC pet boarding sitting & kennels ✓
716-260-1605
Piasecki Kresses ✓
Senecal James ✓
SUNSHINE MAY GAIL social workers ✓
716-238-3161
100 WURLITZER INDUSTRIAL PARK INC industrial parks ✓
716-694-4799
101 BUFKOR INC display designers & producers
716-693-3223
103 VISIONARY BATHS & MORE plumbing fixtures & supl-whol ✓
716-692-3200
104 NICASTRO ACCOUNTING SVC acctng & bkpg genl serv ✓
716-264-4438
106 Urban Roger L
107 PLATTERS CHOCOLATES candy & confectionery-retail ✓
716-693-5391
108 JACOBS LADDER EXERCISE mfrs ✓
716-692-1455
109 TRADESHOW DISPLAY CO signs ✓
716-743-1379
120 JAECE INDUSTRIES laboratory equip/supl-mfrs ✓
716-694-2811
122 TSK ELECTRONICS INC communications equip ✓
716-693-3916
125 IRR SUPPLY CTR INC plumbing fixtures & supl-whol
716-692-1600
125 JORDAN SUPPLY CO INC air conditioning supl/parts ✓
716-692-1600
134 ALL DAWGS ACADEMY pet training ✓
716-743-0988
138 BLACK LABS INC electronic research/development ✓
716-695-6455
206 EXPRESS EMPLOYMENT PRO employment agencies/opportunit ✓
716-389-2901
208 ELDER WEDNESDAY NP nurses-practitioners ✓
814-726-7665
208 MASYGA MARCY ANN DO physicians & surgeons ✓
716-592-3600
208 PARIKH PARAG P MD physicians & surgeons ✓
716-692-3302
208 PRACTICE MANAGEMENT CTR insurance
716-692-3302
208 WEPPNER DENNIS M MD physicians & surgeons
716-634-1702
230 GENERAL PHYSICIAN PC acctng & bkpg genl serv ✓
716-264-4195
252 KRESSES & PIASECKI LEGA real estate ✓
716-693-4792
254 NIAGARA GUTTER gutters & downspouts ✓
716-695-3500
259 EGW ASSOCIATES INC employment agencies/opportunit ✓
716-525-1132
261 AIR TRAC CORP engineers- industrial ✓
716-696-6111
• ZIP CODE 14120 CAR-RT C026
1008 PETER KAY AUTO SALES auto dlrs-used cars ✓
716-695-7910
1014 White David D & Cathleen ✓
716-260-2008
1026 Aldridge Karen F ✓ ◆ (1900)
716-694-8790
1034 Duff William J & Jessica L ✓ ◆ (1958)
1038 Heffernan Janet A ✓ ◆ (1958)
716-694-6315
Heffernan Kerrie A
716-694-6315
1042 Sakharchuk Vikki ✓ ◆ (1958)
Werth Maria T ✓ ◆ (1919)
716-957-3093
1048 Senko Julie L ✓ ◆ (1921)
716-957-3501

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 2018

NIAGARA FALLS BLVD Cont'd

405 Senko Karen G 716-957-3501

1054 Wagner Robert E & Phyllis J ✓ 26 ♦ (1920) 716-695-2157

1086 1 Krull Roger W ✓ 18 ♦ (1958)

272 2 No Current Listing

3 Markovitz Nicole V ✓ 8

782 1102 Strzyz Ronald E & Barbara H ✓ 39 ♦

027 (1920) 716-693-0619

1106 McDonough Jon ✓ ♦ (1958)

1110 Davis Gary A & Victoria E ✓ 24 ♦ (1942)

1124 Miles Barbara A ✓ 45 ♦ (1920) 716-694-5838

001 Miles Kathryn E 716-694-5838

1128 Rowles Joanne M ✓ 40 ♦ (1952)

728 716-694-3857

1134 Werth Mark R & Kathy A ✓ 40 ♦ (1952)

.....716-692-6183

542 1144 Doherty John R & Mary E ✓ 12 ♦ (1955)

• ZIP CODE 14120 CAR-RT C043

630 1166 Giammusso Charles B ✓ 26 ♦ (1958)

✓ 716-695-5799

540 Giammusso Clalogerro 716-695-5799

110 1182 HAYAT MOTEL hotels & motels 716-694-0360

158 Zepp Justin ✓ 3 ♦ (1958)

1200 B-COZY MOTEL hotels & motels ✓

328 716-695-3437

Kabalan Bernard ✓ 16 ♦ (1958)

162 Shingledecker Lisa 7 ♦ (1958)

+ MAPLE DR ENDS

161 **• ZIP CODE 14120 CAR-RT C010**

2880 ALDERCREEK MUSIC INC musical

138 instruments-dlrs ✓ 716-693-5456

2884 Failing M ✓ 2 716-743-2392

159 NOVA DANCENTER dancing instruction ✓ 716-939-0855

RE VIVE SALON & SPA beauty salons ✓ 716-692-0671

141 2888 1 Porter Edrema ✓ 15

1 Simmons Dwayne & Edrema ✓ 10

2890 GUERRA DOMINIQUE nurses-

641 practitioners ✓ 716-807-7337

y HURLEY COLLEEN A NP nurses-

703 practitioners ✓ 716-807-7337

SEAGER TIFFANY PA physicians

550 assistants 716-807-7337

& WHEATFIELD PEDIATRICS physicians &

605 surgeons ✓ 716-807-7337

+ WARD RD INTERSECTS

2910 THRUWAY FASTENERS INC screws ✓ 716-694-1434

Target Street	Cross Street	Source
-	✓	Polk's City Directory

KENMORE AVE 2014

218 HOUSEHOLDS 3

KENMORE AVE (BUFFALO)-FROM 3500 MAIN ST NORTHWEST
227 • ZIP CODE 14226 CAR-RT C001
39 GRACE POINT ALLIANCE churches ✓ @ 716-834-4345
148 43 MICHAEL WILSON REALTY INC real estate ✓@ 716-912-8770
554 QUEEN CITY TATTO CO tattooing ✓ @ 716-862-3808
STUDIO J nonclassified establishments ✓@ ..716-833-2623
Wilson Michael S ✓ 5
982 47 J & S ORIENTAL ENTERPRISES INC restaurants ✓@ 716-832-5162
717 MAY JEN CHINESE RESTAURANT restaurants ✓@ 716-832-5162
+ WINDERMERE BLVD INTERSECTS
+ WINDERMERE BLVD INTERSECTS
092 63 1 HUGHES & WRAY attorneys ✓@ 716-856-0400
180 71 2 CRUZ LOURDES F MD physicians & surgeons ✓ 716-832-3111
985 + WINDERMERE BLVD INTERSECTS
95 Szczepanski Carol A ✓ 18 ♠ (1945)
161 + CAPEN BLVD INTERSECTS
99 Krestos Mary ✓@ 26 ♠ (1956) 716-832-9971
Krestos Thomas M 716-832-9971
612 + ALLENHURST RD INTERSECTS
135 Napier Kandie K ✓@ 18 ♠ (1945) 716-836-9377
548 140 FRANCAVILLA VINCENT J DDS dentists ✓@ 716-835-6966
242 143 No Current Listing
+ ALLENHURST RD INTERSECTS
BUSINESSES 9 HOUSEHOLDS 5

KENNEDY CT (LANCASTER)-FROM 2

Target Street	Cross Street	Source
-	✓	Polk's City Directory

KENMORE AVE 2014



251 Plummer Jeannine C ✓ 5 ● (1950) 716-833-3046 500

+ HIGHLAND AVE INTERSECTS

BUSINESSES 2 HOUSEHOLDS 93 501

535

KENMORE AVE (BUFFALO)

• ZIP CODE 14223 CAR-RT C062

181 No Current Listing

187 Ⓝ Qian Qi 559

189 WILLIAM L LONG & ASSOC architects ✓@ 716-833-1873

191 Brenner Robert J ✓ 52 ● (1925) 716-833-4968

Brenner George 716-833-4968

193 Rozek Ken P & Jane M ✓@ 36 ● (1925) 716-834-2169 563

197 Magyar Susan L ✓ 25 ● (1925) 716-833-2696 567

Magyar Renee 716-833-2696 571

199 Brown Allensia A ✓@ 5 583

Brown Arleemah R 589

205 EMPORIUM HAIR DESIGN beauty salons ✓ 716-832-6558 593

210 Labruna Sharon R ✓ 35 ● (1957) 716-833-9606

214 Mahoney Thomas E ✓ 24 ● (1939) 716-831-0930 597

• ZIP CODE 14223 CAR-RT C069

217 Ⓝ Porter Bruce R Jr ✓@ 601

Porter Eleanor 619

218 Orologio Gioacchino L Jr ✓ 10 ● (1939) 716-885-1830

225 Ⓝ Braun Rebecca ✓

Schuster David C ✓ 4 .....716-834-0860 623

229 Bitterman James W & Constance M ✓ 18 ● (1920)

.....716-837-0094 627

233 Bell J ✓ 3 631

ds, and Business Credit Reports on-line and other Polk City Directorie

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAIN ST 2014

retail ✓@ 716-837-8554
3162 200 Lee Cheng Y ✓ [2]
600 (N) Martinez Steven B ✓
3164 GINSENG UNLIMITED health & diet foods-retail ✓@ ..716-838-0707
3165 LAKE EFFECT DINER restaurants ✓@ 716-833-1952
3168 ICONZ HAIR DESIGN beauty salons ✓@ 716-834-1559
3171 SAL'S PIZZERIA pizza ✓@ 716-835-4718
SLICE OF ITALY restaurants ✓@ 716-837-0200
3172 JUST PIZZA pizza ✓@ 716-831-9979
3178 Seybert Ian D [3]
3180 LOVE IS LOVE barbers ✓@ 716-835-6838
Wilson Ulysses ✓ [6]
3182 Krasopoulos Anna M [3]
3184 QUEEN CITY BOOK STORE comic books ✓@ 716-833-6220
3189 No Current Listing
3191 Hariton Debbie [3]
3193 (N) Brookbank Kaitlyn ✓
(N) Dwyer Jessica ✓
(N) Ortega Alexandra D ✓
3198 FRANKS CONVENIENCE serv stations- gasoline & oil ✓ 716-836-5337
TIM HORTONS doughnuts ✓@ 716-836-5337
3208 PARKSIDE CANDY CO INC candy & confectionery-mfrs ✓@ 716-833-7540
3210 BUFFALO PREGNANCY CARE CTR pregnancy counseling serv/ info ✓@ 716-833-7100
1 Francis Kevin M [14]
2 (N) Sevene Joseph R ✓
3211 7-ELEVEN convenience stores ✓@ 716-834-4018
3214 MAURICE TAILORS tailors ✓@ 716-833-5049
2 (N) Pham Quynhnhu ✓
3216 Li Guoming ✓ [5] 716-837-0256
PARLATO-O'BRIEN REALTY INC real estate ✓@ 716-835-1020
UNIVERSAL WIRELESS cellular telephones ✓@ 716-768-5086
3218 COLLEGE LAUNDRY SHOPPE laundries-self serv ✓ 716-833-0060
(N) Rosso Rocco ✓ ..716-783-9057
3223 716 INKWELL LLC tattooing ✓@ 716-831-0588
3225 (N) Martin Kerrie
UNIVERSITY HOTS restaurants ✓ @ 716-204-2372
3229 HOW'S IT GROWING HYDROPONICS hydroponics equip/ supl ✓@ 716-240-9075
3230 GREEKS & SNEAKS book dlrs-retail ✓ 716-833-4913
3233 CANTALICIAN CENTER-LEARNING schools ✓@ 716-833-5353
Tomasik Patricia M ✓ [31] • (1939)

3270 3275 • ZIP (3290 3296 3334 3350 3362 3382 3400 3404 3410

This directory is property of Poll

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAIN ST 2014

236

MAIN ST Cont'd

3234 AMY'S PLACE restaurants ✓@ 716-832-6666
PAVILION INTERNATIONAL gift shops ✓ 716-834-8310
Uschold Rebecca ✓ [11] 716-833-0265
3236 MUSIC CITY musical instruments-dlrs ✓@ 716-838-4547
3240 Huber Ethan A ✓ [41]
O'CONNELL LUCAS CHELF INC women's apparel- retail ✓@ 716-836-4140
OPERA FOUNDATION OF BUFFALO foundation ✓@ 716-832-6355
3242 GLORIA J PARKS COMMUNITY CTR social serv & welfare org ✓@ 716-832-1010
(N) Harp Ronald L ✓
KIDS & PLAY child care serv ✓ 716-835-5437
KIDS R US DAYCARE child care serv ✓@ 716-768-4744
3258 AMAK HEALTH CARE AGENCY home health serv ✓@ 716-832-0875
3260 1 Luter David G [2]
6 Guarino James D [7]
6 Guarino Marla J
A SHANGO restaurants ✓@ 716-837-2326
3264 (N) Lopez Charlotte G ✓
3268 Deshpande Anil ✓ [12]
KUNG FOOD LLC restaurants ✓@ 716-836-3268
MING CAFE restaurants ✓ 716-833-6988
Qiu Lam Z ✓ [9]
3269 Keleher James P ✓ [4]
Ledwon Jacob C ✓ [23]
Midura Jeremy M ✓ [4]
NEWMAN CENTER SUNY/AB SOUTH churches ✓@ 716-833-6649
NORTH BUFFALO CATHOLIC YOUTH church org ✓@ 716-862-9801
ST JOSEPH'S RC CHURCH religious schools ✓@ 716-835-7395
ST JOSEPH UNIVERSITY PARISH clergy ✓@ 716-833-0298
3270 P J BOTTOMS restaurants ✓@ 716-833-3270
3275 ST JOSEPH SCHOOL schools ✓@ 716-835-7395

• ZIP CODE 14214 CAR-RT C006

3290 KEY BANK banks @ 716-838-7200
3296 A1 (N) Agrawal Abhijeet
A1 Gogate Nikhil [2]
B1 (N) Sharma Prateek ✓
B2 (N) Ra Geraldine ✓
B4 Scandale Nathaniel [21]
C1 (N) Jandhyam Sirisha ✓
3334 GREATER BUFFALO COUNSELING CTR social serv & welfare org ✓@ 716-833-5993
UNIVERSITY PRESBYTERIAN CHURCH churches ✓@ 716-836-7660
3350 CHILD & ADOLESCENT TREATMENT non-profit org ✓@ 716-835-4011
CROWLEY DANIELLE social workers ✓@ 716-935-4011
HEIMBECK MURDI CATHERINE M counselors ✓ 716-835-7807
Rook Antoinette ✓ [6]
STEFEN REBECCA S counselors ✓ @ 716-835-7807
TORRES VANESSA counselors ✓ @ 716-835-7807
VAUGHAN TABITHA social workers ✓@ 716-835-7807
WIECZOREK ALICIA M social workers ✓@ 716-835-7807
3362 WENDY'S restaurants ✓@ 716-862-3511
3382 SUBWAY restaurants ✓@ 716-834-6878
3400 MILITELLO'S LUGGAGE luggage-retail ✓@ 716-833-1600
1 (N) Bush Wayne
4 Bush Joann L ✓ [19]
A SALON TAH TAR beauty salons ✓@ 716-837-3400
3404 UDAGAWA SALVADOR M MD physicians & surgeons @ 716-835-0641
UDAGAWA SAVALDORE M MD physicians & surgeons ✓@ 716-833-1484
3410 BACK TO NATURE vitamin & food supplements ✓@ 716-835-4779
Horosh Millie [9] • (1939)
Horosh William

MAIN ST Cont'd

NUTRITIONAL CENTER-BUILDING genl merchandise- retail @ 716-835-4779
PURE HERBS PRODUCTS herbs ✓ @ 716-835-4779

• ZIP CODE 14214 CAR-RT C020

3435 AGUIRRE ALFREDO DDS dentists ✓@ 716-829-3553
(N) Amaranto Nicole ✓
AMERICAN INSTITUTE-ARCHITECT S architects ✓@ 716-829-2008
ARMY NATIONAL GUARD state government ✓@ 716-829-2761
(N) Banker Christopher M ✓
BARONE DEBORAH J nurses-practitioners ✓@ 716-829-3335
BRAUER DAVID J MD physicians & surgeons ✓@ 716-829-3316
(N) Burroughs Tiffany ✓
CENTER FOR URBAN STUDIES/ UNIV schools ✓@ 716-829-2133
COHEN ROBERT E DDS dentists ✓ @ 716-829-3845
CONTINUING ED UNIV OF BUF schools @ 716-829-2320
ERIE NIAGARA REGIONAL PRTNRSHP nonclassified establishments ✓@ 716-829-3777
GONZALEZ-STUCK YOLY M DDS dentists ✓@ 716-829-3551
(N) Halbreich Judith ✓
HEALTH SCIENCES LIBRARY dentists ✓@ 716-829-3335
I SUB-BOARD INC laboratories-medical ✓ 716-829-2367
LAB ANIMAL FACILITIES laboratories ✓@ 716-829-2919
(N) Lam Giselle ✓
LI CARL K MD physicians & surgeons ✓@ 716-829-2975
(N) Monica Meghan ✓
NEW YORK UNIVERSITY schools @ 716-829-2845
NUTRITION & HEALTH RESEARCH nutritionists ✓@ 716-829-5593
OHRBACH RICHARD psychologists ✓@ 716-829-3590
PDRC dentists ✓@ 716-829-2853
Rosario Jean ✓ [2]
RUSSO THOMAS A MD physicians & surgeons ✓@ 716-829-2674
STATE UNIVERSITY OF NEW YORK physicians & surgeons ✓@ 716-829-2012
SUDANO LINDA M nurses-practitioners ✓@ 716-645-2000
SUNY BUFFALO DENTAL MEDICINE dentists ✓@ 716-829-2824
SUNY UNIVERSITY AT BUFFALO schools ✓@ 716-645-2829
(N) Sze Ching W ✓
THOMAS SHEILLA nurses-practitioners ✓@ 716-829-3316
TOSHIBA STROKE RESEARCH CTR laboratories ✓ 716-829-3594
TOXICOLOGY RESEARCH CTR research serv ✓@ 716-829-2125
U B DENTAL SCHOOL dental schools ✓@ 716-829-2821
U OF BUFFALO nurses-practitioners ✓ 716-829-3316
UB ORAL & MAXIOFACIAL SURGERY dentists ✓@ 716-829-6637
UNIVERSITY DENTAL ASSOC dentists ✓@ 716-829-2013
UNIVERSITY PEDIATRIC DENTISTRY dentists ✓@ 716-836-5595
(N) Waitt Adam ✓
Willer Barry ✓ [2]
2 (N) Yencer Architectur ✓
4 FOUT ALLISON nurses-practitioners ✓@
4 UNIVERSITY NUCLEAR MEDICINE physicians & surgeons ✓@ 716-838-5889
3435 5 McEachern Crystsal R [2]
7 Sharma Sonia [2]
9 Tay Benjamin [2]
M Trosin Ciara [2]
M (N) Wang Jianxin ✓
10 MILLARD FILLMORE COLLEGE schools ✓@ 716-829-3131
33 WBFO radio stations/ broadcasting co ✓@ 716-829-6000
34 Gonzalez Abnenes [3]
35 Baum Ashley M [9]
37A SCHOOL PUBLIC HEALTH physicians & surgeons ✓@ 716-829-3434
41 Lam Steven [14]
41 Lam Kenneth

MAIN ST

42 (N)
EB6(
101F
230 (
509S
616E
928B

• ZIP CODE

3442 1 (N)
A12 (
A12 (
A12 (
A2 H
A2 (N)
A5 (N)
A5 (N)
A6 S
A8 L
A9 (N)
A9 T
B11 (
B14 (
B4 (N)
B5 C
B9 (N)
C1 (N)
C10 (
...
C14 (
C14 (
C15 (
C2 (N)
C2 M
C2 N
C4 K
✓@
C5 (N)
C7 N
3470 TIM (
...
3476 CELL
telep
...
CKP
comp
(N) G
JACK
@
SON
resta
3488 WAL
...

BUSINESSE

MAIN PLAC

• ZIP CODE

300 BUFF
PAR
serv
350 AMIG
LLC
1100 RICC
1300 AMIC
attor
CAV
attor
ISAA
Matth
(N) M
OLIV
SANI
1400 Cans
1600 CAN
atto
EAR
...
LIBE
...
1800 DUK
PHC
Hea
1900 KIR
atto
UND
atto
2100 PER
atto
2150 BUF
atto
2200 CHA
...
2405 JAM
atto
2500 CEL
atto
2600 FAL
...

BUSINESSI

MALSCH S
AVE NORT

• ZIP CODE

10 Kissel
• (1
12 - 14 Nc
15 Dubuq
Dubuq

roperty of Polk City Directories. It is leased for the personal use of the subscriber. Use of
itle page of this directory. This information changes by 60% each year. For an updated dir

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAIN ST 2014

MAIN ST Cont'd

42 Ⓝ Murtanti Aditia
EB606 Ⓝ Smith Adonijah ✓
101F Grinslade Susan [2]
230 Ⓝ Filosi William D ✓
509SB Ⓝ Featherstone Robert M ✓
616EA Ⓝ Shannon Robert M ✓
928B Ⓝ Smith Ian P ✓

• ZIP CODE 14214 CAR-RT C006

3442 1 Ⓝ Oquin Karen E
A12 Ⓝ Godre Atishay ✓
A12 Ⓝ Koirala Supriti ✓
A12 Ⓝ Tan Hui Y ✓
A2 Hoover Laura E [5]
A2 Ⓝ Scott Laura ✓
A5 Ⓝ Sharp Kirsten ✓
A5 Ⓝ Sundar Ajay ✓
A6 Sundareswaran Nikhila [3]
A8 Lim Vun S ✓ [2]
A9 Ⓝ Kadish Marc A ✓
A9 Tian Kianwee ✓ [4]
B11 Kugler Carolyn F @ [5]
B14 Dunford Robert G [18]
B4 Ⓝ Redeiman Meridith ✓
B5 Clark Latoya M [2]
B9 Ⓝ Nazeer Aliya
C1 Ⓝ Kaplan Sarah ✓
C10 Chow Catherine ✓ [10]
.....716-834-7627
C14 Ⓝ Chua Lauren ✓
C14 Ⓝ Genovese Garrett C ✓
C15 Nagel Raymond M ✓ [4]
C2 Ⓝ Mohatt Lisa ✓
C2 Mohatt Dennis S
C2 Nair Jyothsna R ✓ [4]
C4 Kamery Christopher J & Rae C ✓@ [3]
C5 Ⓝ Cassaday Margaret E
C7 Neidl Phoebe F [15]

3470 TIM HORTONS doughnuts ✓@
.....716-831-3211

3476 CELL PHONE STORE cellular telephones-equip/supl ✓@
.....716-831-1300
CKP HOLDINGS LLC holding companies ✓@ 716-862-8226
Ⓝ Gangarossa Tony L ✓
JACK'S HOT DOGS restaurants ✓@ 716-831-8800
SONORA'S EXPRESS MEXICAN restaurants ✓@ 716-218-1564

3488 WALGREENS pharmacies ✓@
.....716-834-7011

BUSINESSES 1287 HOUSEHOLDS 1024

MAIN PLACE TOWER (BUFFALO)
• ZIP CODE 14202 CAR-RT C026

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAIN ST 2014

54 No Current Listing
+ GENESEE ST INTERSECTS
BUSINESSES 10 HOUSEHOLDS 21

MAIN ST (BUFFALO)
• ZIP CODE 14226 CAR-RT C010

3500 Black Sylvia ✓ 2
DMMP PRODUCTIONS LLC promotions & fund raising ✓ 716-834-1080
MEDIDERRANEA INC restaurants ✓@ 716-831-8100
Smith Mylo B ✓ 2
TOPS FRIENDLY MARKET grocers-retail ✓@ 716-515-3260
UNIVERSITY PLAZA shopping centers & malls @ ..877-300-2128
WESTERN UNION money transfer serv 716-515-3240
2 AMHERST THEATRE theatres-movie ✓@ 716-834-7655
5 CITIZENS BANK banks ✓@ 716-862-0525
5A VILLA shoes-retail ✓@ 716-834-0491
7 RECORD THEATRE records tapes & compact discs ✓@ 716-837-2090
HAIR PEOPLE beauty salons ✓@ 716-834-9090
8 M&T BANK banks ✓@ 716-832-9523
110 (N) Jones Barbara J ✓@
120 JIMMY JOHN'S restaurants ✓@ 716-836-3501
130 BUFFALO EXECUTIVES ASSN associations ✓@ 716-852-6916
130 Land Pamela J ✓ 5
130 UPS STORE mailing & shipping serv ✓@ 716-332-2323
150 ZETTI'S PIZZA & PASTA pizza ✓@ 716-931-9571
220 DOTS clothing-retail ✓@ 716-834-4903
270 RADIOSHACK electronic equip/supl-retail ✓@ 716-832-8311
280 DOLLAR TREE variety stores ✓@ 716-837-6680
310 SALLY BEAUTY SUPPLY cosmetics & perfumes-retail ✓@ 716-831-3286
330 CHINA KING RESTAURANT restaurants ✓@ 716-837-6863
340 GNC vitamin & food supplements ✓@ 716-835-9340
350 GLIDDEN paint-retail ✓@ 716-835-7346
360 FOREVER NAILS manicuring ✓@ 716-833-5424
500 GAMESTOP games & game supl ✓@ 716-836-3748
3510 A J WRIGHT department stores ✓@ 716-833-2988
3540 MC DONALD'S restaurants ✓@ 716-832-6221
3582 TUXEDO JUNCTION formal wear-rental @ 716-833-8812
3586 KEY BANK banks ✓@ 716-871-4260
3604 DYNAMIC ELECTRO ACOUSTICS acoustical contractors ✓@ 716-836-2625
SPEAKER SHOP INC home theatre sys ✓@ 716-837-1557
3610 UNIVERSITY MEDICAL BOOKSTORE book dlrs-retail ✓@ 716-833-7131
3612 Crosby Patricia D ✓ 3
(N) Handy Dwayne L Sr
UNIVERSITY MANOR INN hotels & motels ✓@ 716-837-3344
3640 DUNKIN' DONUTS doughnuts ✓@ 716-446-9210

rty of Polk City Directories. It is leased for the pers
age of this directory. This information changes by

3760 HART @ -
3770 Powe ....
Powe
3772 FLUR ....
(N) Sn
3781 ERIE golf c
GROV
REST ....
3782 Lalli V (1950
3790 Ortma Ortma
3800 ORTM estab
3810 Cudne ▲ (19
LEO M
SIDIN ....
+ MAYNARD
3860 BUFF SACF ....
Mahor
Nelso
Perry
SACR
religio ....
Stuhle
• ZIP CODE 1
3901 (N) Ch
(N) Erb
1B Flo
1C Ma
2A Sc ....
2B Ha (1948
2B Mu
2C Ch (1948
2D (N)
3A Ga (1948
3B Vir
3D Ho
4A Jar
4B Bro
4D Du
5A (N)
5C Ku (1949
6A Ga (1942
6C Me ▲ (19
6D Mc
7A (N)
7B An
7C Ha
7D Su ....
8A (N)
8A Ric
8D Pc
9A Bu
9A Hig
9B Ho
9C Sc
9D De
10B (
10C T (1942
10D (
11A B
11C K
12A S (1948

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 2014



NIAGARA ST - NORFOLK AVE

NIAGARA ST Cont'd

2949 Ⓝ Santiago Aaron C ✓

+ RIVER RD INTERSECTS

BUSINESSES 315 HOUSEHOLDS 742

NIAGARA FALLS BLVD (BUFFALO)-FROM 2 PELHAM DR NORTH

• ZIP CODE 14214 CAR-RT C006

2 Fletcher Irving L [9] ♠ (1939)

22 - 37 No Current Listing (2 Hses)

38 Qutubuddin M ✓ [3] 716-834-2934

40 Dewald Jonathan M ✓ [13] ♠ (1939)

41 Newman John ✓ [10] ♠ (1925) 716-837-3036

42 Ⓝ Boyd Damien S ✓

Ⓝ Shute Wesley S

43 No Current Listing

45 Lawson Cecelia M ✓ @ [10] ♠ (1939)

Muldrow Mattie M ✓ [43] ♠ (1925) 716-832-6625

Muldrow Veronica D 716-832-6625

46 Kassman Anthony J Sr & Helen K ✓ [33] ♠ (1925)

50 Newberry Wilma J ✓ [39] ♠ (1925) 716-835-0474

54 Metzger Michael M & Erika A ✓ [49] ♠ (1922)

58 Brace Frederick E Jr & Kathleen L ✓ [29] ♠ (1940)

62 Kowsky Francis R & Helene D ✓ [36] ♠ (1930) 716-836-6069

65 McCraty Elmer J ✓ [28] ♠ (1900) 716-832-2274

66 Klein Rose M ✓ [48] ♠ (1940)

Ⓝ Pedone David L ✓

69 Jarosz Michael S & Susan S ✓ [17] ♠ (1900) 716-832-1882

70 Kogler Susan M ✓ [41] ♠ (1930)

Kogler James E

73 Conti Joan N [22] ♠ (1939)

74 Onorato Victoria A ✓ [46] ♠ (1930) 716-833-9426

77 Walls Gerald W Sr & Dalonda M ✓ [20] ♠ (1931)

78 Privateer Christoph A & Karen D ✓ [20] ♠ (1930)

81 No Current Listing

82 Reade Dorothy R ✓ [17] ♠ (1948) 716-837-7520

Reade Catherine P 716-837-7520

85 Wilson Joseph J ✓ [7] ♠ (1920)

86 Leising Peter C & Jeanne M ✓ [23] ♠ (1931) 716-833-7884

89 Reese Kelly A ✓ [19] ♠ (1925) 716-833-4447

Reese Loreda 716-833-4447

90 Rottger John P ✓ [5] ♠ (1939)

95 Guerin Marissa ✓ [5] ♠ (1939)

Marino Steve [5] ♠ (1939)

Marino Marissa

Ⓝ Salih Sabba ✓

96 Uebbing Mary C ✓ [5] ♠ (1920)

Uebbing Matthew B

97 Simmons Lorayne D ✓ [28] ♠ (1932)

100 Ossei-Anto Mary [7] ♠ (1948)

Ossei-Anto Josephine

101 Patel Samina & Wasim ✓ [30] ♠ (1939) 716-833-0638

104 Coppola Joseph A & Ruth A ✓ [17] ♠ (1938) 716-833-9275

105 Alexander Pamela ✓ [37] ♠ (1939)

Collins Lavarn A ✓ [36] ♠ (1930)

Collins Kim

+ BELLEVUE AVE INTERSECTS

109 McMahon Joseph P Jr & Christina C ✓ [10] ♠ (1928)

112 Ⓝ Mernan Dave ✓ ..716-833-2396

115 Forbach David J ✓ [5] ♠ (1925)

116 Laulette Anthony J ✓ [10] ♠ (1939)

119 Thurston Brandon H ✓ [4]

120 No Current Listing

123 Purks Cortland M & Gudiya R ✓ [9] ♠ (1930) 716-837-9046

124 Cirrito Frank A ✓ [23] ♠ (1926) 716-835-3677

127 Claeys Jonathan M ✓ [9] ♠ (1950)

Claeys Anne

128 EDNA LOUISE ESTATE SALES estates ✓ @ 716-812-1018

Then Philip J & Charmaine L ✓ [30] ♠ (1925)

131 Fish Katherine A [5] ♠ (1920)

132 Curtis Florence H ✓ [29] ♠ (1925) 716-835-1747

136 Ⓝ Dykstra Jeanette ✓

139 WILSON REALTY real estate ✓ @ 716-270-4990

WNY4RENT real estate ✓ @ 716-929-7368

142 ENCOMPASS AGENCY INC nonclassified establishments ✓ @ 716-835-6790

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 2014

288

NIAGARA FALLS BLVD Cont'd

Schewtchuk Dominka ✓ 6 ♦ (1945) 716-824-1495
303 Canavos Sophia ✓ 2
Frank Thomas @ 3
309 Kyse Terrie L & Willie A ✓ 22 716-835-0527
Street Barbara J ✓@ 2 716-834-1908
315 Lee Allen 2
321 Delles Lisa A ✓ 44 716-939-2283
Lawson Jack S Jr ✓ 20 716-837-2962
327 No Current Listing
333 McKinnon Sally A ✓ 10 ♦ (1945) 716-832-0208
339 Poloncarz Robert A & Julie A ✓ 46 ♦ (1945) 716-836-6030
Stilwell Ann P ✓ 25 ♦ (1944)
345 Renzi Gabriele ✓ 4 ♦ (1945)
• ZIP CODE 14226 CAR-RT C043
363 Cox Bruce H & Linda E ✓@ 36 ♦ (1947) 716-833-8629
369 Bulsara Melody R ✓ 10 ♦ (1947)
373 Gordon Loretta L ✓ 16 ♦ (1947) 716-833-4927
Gordon Lorrie 716-833-4927
383 Banks Selina D ✓ 18 ♦ (1945)
Powers Tyrone ✓@ 21 ♦ (1947)
389 Cook Nicholas J ✓ 6 ♦ (1946)
Wise Misao ✓ 14 ♦ (1945)
Wise Todd G
395 No Current Listing
399 Glovack Kristi M & Kevin S ✓@ 17 ♦ (1947)
405 Flint Wildrena @ 6 ♦ (1945)
Flint Robert D
409 Kabala Courtney A ✓@ 2 716-833-2561
415 Myers Gregory W ✓ 23 ♦ (1947) 716-833-4606
Myers Gloria J 716-833-4606
423 (N) Hein Connie
429 Truong Kinh V ✓ 3 ♦ (1945)
Truong Tommy
435 O'Connor Peter J & Sandra L ✓ 43 ♦ (1947) 716-838-4351
443 Fields Lisa D & James M ✓ 18 ♦ (1947)
453 Jaffri Syed Z & Rafia S ✓ 24 ♦ (1947) 716-838-1035
459 Garhartt Barbara ✓ 3
465 No Current Listing
• OXFORD AVE INTERSECTS
• ZIP CODE 14226 CAR-RT C034
479 FARRELL PHOTOGRAPHY photographers- portrait ✓@ 716-838-1447
483 Tucker Jennifer R ✓@ 4 ♦ (1947)
Tucker Ronnie E
489 (N) Przydrozny Matthew ✓
Spasezska Irena M 13 ♦ (1948)
495 Wong Soo K ✓ 48 ♦ (1948) 716-832-8347
505 Wong Sue K & Manuel G ✓@ 48 ♦ (1948) 716-837-4918
513 Leach Mary L ✓ 36 ♦ (1946) 716-838-1771
519 Saxena Suresh B ✓ 24 ♦ (1949) 716-240-9761
Saxena Bela R 716-240-9761
(N) Sion Imsta ✓
523 Drexinger Keith F ✓@ 9 ♦ (1948) 716-837-0191
Drexinger Jennifer 716-837-0191
(N) Livingston Jennifer A ✓
RNG CO INC nonclassified establishments ✓@ ..716-834-2606
529 Lewis Dion C ✓@ 17 716-833-1905
535 Pizetzky Kevin F ✓@ 7 ♦ (1947) 716-835-7106
Pizetzky Pamela 716-835-7106
543 No Current Listing
549 Bookhagen Glenn A Jr & Susan M 18 ♦ (1948)
553 Mezban Kilod ✓@ 2
Mezban Mohammad
559 (N) Rivera Jose ✓ 716-837-0471
563 Singh Arthur & Asha W ✓ 16 ♦ (1948) 716-834-5695
569 No Current Listing
579 Didomizio Joseph C & Annette S ✓ 27 ♦ (1948) 716-838-3412
• YALE AVE INTERSECTS
593 Seland Keith A ✓ 28 ♦ (1956)
599 (N) Anderson Michelle M & Michael J ✓ 716-768-1890
(N) Dougherty X
605 Heim James A & Jennifer G ✓ 8 ♦ (1939)
613 Crane David C & Kim M ✓ 20 ♦ (1952)
619 Jacob Gladwin A & Sunita ✓ 26 ♦ (1948) 716-836-1271
625 Patterson Robert A & Debra M ✓ 32 ♦ (1950)

NIAGARA FALLS BLVD Cont'd

633 Relan Sushil D & Aureeta ✓@ 26 ♦ (1947) 716-832-0223
639 No Current Listing
643 CITYWIDE LOCK & KEY locks & locksmiths ✓ 716-912-7182
Goff James Jr ✓ 7 ♦ (1948)
PRIME PROPERTY HOME INSPECTION real estate inspection @ 716-345-7147
Reppenhagen'Goff James & Kelly M ✓ 19 ♦ (1948) 716-835-0150
649 Guzinski Pati A ✓@ 10
653 Johnson Willard E Sr & Mary L ✓ 43 ♦ (1948) 716-862-0307
(N) Williams Griselda D ✓
659 (N) Merner Darrell ✓@
663 Menchetti Peter P ✓ 40 ♦ (1947) 716-832-3418
Menchetti Rebecca M 716-832-3418
665 Loveland Joseph K & Brandy D ✓ 5 ♦ (1948)
669 Perez Angelita A ✓ 17
673 Piatt Robert W ✓ 25 ♦ (1956)
Piatt Pamala D
• LONGMEADOW RD INTERSECTS
• LONGMEADOW RD INTERSECTS
677 STAR INK INC grocers-retail ✓@ 716-833-2866
679 FERA'S BOULEVARD SUB SHOP restaurants ✓@ 716-838-4545
711 JAZZYOBICS BY SUZY dancing instruction ✓@ 716-836-2999
TRINITY UNITED METHODIST CHR churches ✓ 716-835-7711
733 AMERICAN AUTO WORLD auto parts & supl- retail-new ✓@ 716-832-3838
• RUTH AVE INTERSECTS
751 HECTOR'S HARDWARE & PAINT CO hardware-retail ✓@ 716-832-9310
765 CHRISTIAN FELLOWSHIP BAPT CHR churches ✓@ ..716-835-2899
771 MC CARTY ALLAN P attorneys ✓@ 716-446-0022
773 Chainani Ramesh L 17 ♦ (1956)
CHAINS ENTERPRISES INC tailors ✓@ 716-837-8344
785 BOULEVARD INN hotels & motels ✓ @ 716-837-7400
Rebmann Michael R ✓ 10
789 Branch Eugene M & Maureen B ✓ 34 ♦ (1956)
797 JOLLY JUG bars ✓@ ..716-834-3778
803 SOKOLSKI SUTHERLAND & LYONS accountants ✓@ 716-834-2337
Sutherland David W ✓ 18 ♦ (1956)
• BETINA AVE INTERSECTS
839 839 BOULEVARD CTR shopping centers & malls @
MASTER GORING'S PIL-SUNG TAE martial arts instruction ✓@ 716-836-5425
NORTHTOWN ANIMAL HOSPITAL animal hospitals ✓@ 716-834-8387
SCHAEDLER JEAN M DVM veterinarians ✓@ 716-834-4387
843 EASTERN ENERGY CONTROL WINDOW glass coating & tinting ✓ @ 716-836-2110
MAINTENANCE & MANAGEMENT ASSOC cleaning serv- industrial ✓ 716-836-2110
845 SENTRY APPLIANCE SVC CO appliances- household-major-rpr ✓ @ 716-835-2991
Wilson B ✓ 14 716-832-4824
847 Hultin Antoinette ✓ 9 716-832-1874
Malik Sardar ✓ 20 ♦ (1957)
MALIK TAILORS tailors ✓@ 716-862-0122
853 JAX CONTRACTING INC lawn & grounds maintenance ✓@ 716-674-1070
MR PIZZA pizza ✓@ ..716-837-6500
861 Wahl Philip J Jr & Cheryl J 30 ♦ (1940)
865 Balesteri Dara ✓ 23 ♦ (1957)
Bradl Randy R Jr ✓ 17
869 WOEPPEL EDWARD J CPA accountants ✓@ 716-836-3822
871 A CAREER RESUME resume serv ✓ @ 716-837-2798
Armesto Christine G 13
DESIRED IMAGE cosmetics & perfumes-retail ✓@ ..716-834-1123
GORDON JAMES IMAGE MAKERS INC photographers- portrait ✓@ 716-837-5665
VCMS INC business mgmt consultants ✓@ 716-837-4140

sed for the personal use of the subscriber. Use of this directory is subject to the Terr
tion changes by 60% each year. For an updated directory call 1-800-275-7655 or www.

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 2014

• HOMEOWNE

NIAGARA FALLS BLVD Cont'd

885 JOSEPH SPANO & SONS FUNERAL HM funeral directors ✓@ 716-854-299
LOMBARDO FUNERAL HOME funeral directors ✓@ 716-637-710
899 Glovack Kristi [2]
NICASTRO ACCOUNTING SVC accountants ✓@ 716-831-869
925 U-HAUL MOVING & STORAGE truck renting & lease ✓@ 716-832-177
+ EGGERT RD INTERSECTS
+ EGGERT RD CONTINUES
• ZIP CODE 14226 CAR-RT C041
951 EL PALENQUE MEXICAN GRILL restaurants ✓@ 716-446-920
+ SHERIDAN DR INTERSECTS
995 BRIDGESTONE MASTERCARE SVC CTR auto rpr & serv ✓@ 716-837-970
FIRESTONE COMPLETE AUTO CARE auto rpr & serv ✓@ 716-261-394
Kracker Steven M [18]
1021 PEP BOYS auto parts & supl- retail-new ✓ 716-831-037
1061 Chimera Joann E ✓@ [11] • (1968)
Chimera Lucy
PLANT PLACE & FLOWER BASKETS florists-retail ✓@ 716-838-340
1101 AQUAJET & ROBERT'S PLUMBING plumbing contractors ✓@ 716-877-153
AQUAJET SEWER SVC CORP plumbing contractors ✓@ 716-877-153
CUSTOM CUTS HAIR DESIGN beauty salons ✓@ ..716-836-424
DEBRA R HAMSHER-NATIONWIDE insurance ✓@ 716-833-190
ES-WIRELESS telecommunications contractors ✓@ 716-834-340
Fletcher John W [38]
JAZZY SHOE shoes-retail ✓@ 716-835-769
NATIONWIDE INSURANCE insurance ✓@ 716-833-190
Rich James P ✓ [16]
ROBERT'S HEATING CO plumbing contractors ✓@ 716-877-153
S Allen Michele ✓
• ZIP CODE 14226 CAR-RT C032
1145 CHILI'S GRILL & BAR restaurants ✓@ 716-832-373
1167 AUDIOMOTIVE CREATIONS auto remote starters ✓@ ..716-783-748
CRICKET shopping centers & malls ✓@ 716-803-180
1171 NAPA AUTOMOBILE CARE auto parts & supl- retail-new ✓@ 716-837-400
PREMIER CAR CARE auto rpr & serv ✓@ 716-837-400
1185 BUFFALO ATHLETIC CLUB INC health clubs studios/gymnasium ✓ 716-833-522
1201 5-7-9 women's apparel- retail ✓ 716-835-073
1203 FOOT LOCKER shoes-retail ✓@ 716-837-144
1205 M&T BANK banks ✓@ 716-835-511
1207 POSTER ART BLVD MALL sportswear-retail ✓@ 716-834-142
1209 TGI FRIDAY'S restaurants ✓@ 716-835-600
1211 CHILDREN'S PLACE childrens & infants wear ✓@ 716-831-320
1213 HOLLISTER CO clothing-retail ✓@ 716-833-126
1215 BANANA REPUBLIC clothing-retail ✓@ 716-838-067
1219 BOULEVARD CONVENIENCE convenience stores ✓@ 716-834-126
1221 4 SEASONS GIFTS gift shops ✓@ 716-832-300
LIMITED clothing-retail ✓@ 716-833-248
1225 ABERCROMBIE & FITCH clothing-retail ✓@ 716-832-657
FYE records tapes & compact discs ✓@ 716-834-909
1231 AEROPOSTALE clothing-retail ✓@ 716-836-750
1233 GAP clothing-retail ✓@ 716-828-115
GAP KIDS childrens & infants wear ✓@ 716-836-148
1247 BONEFISH GRILL restaurants ✓@ 716-833-610

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 2014

N NEW NEIGHBOR

NIAGARA FALLS BLVD Cont'd

1251 BOULEVARD MALL BOOTERY shopping centers & malls ✓@ 716-832-4903
1253 LITTMAN JEWELERS jewelers-retail ✓@ 716-835-4799
1255 MACY'S department stores ✓@ 716-837-9400
MINI MATERNITY AT MACEY'S maternity apparel ✓@ 716-835-4650
1257 BROOKSTONE gift shops ✓@ 716-833-4956
GYMBOREE childrens & infants wear ✓@ 716-836-0622
MRS FIELD'S COOKIES cookies & crackers ✓@ 716-833-1077
YANKEE CANDLE CO candles ✓@ 716-832-3700
1259 CRAZY EIGHT childrens & infants wear ✓@ 716-834-4754
NATURALIZER SHOES shoes-retail ✓@ 716-836-4188
TEAVANA coffee & tea ✓@ 716-833-3234
TUTU GIRLS BOUTIK boutique items- retail ✓ 716-836-4569
1261 BOUNCE MAGIC events-special ✓@ 716-834-5867
BUYBUY BABY baby accessories ✓@ 716-833-3714
MICHAELS craft supl ✓@ 716-834-3322
SEARS department stores ✓@ 716-446-5100
SEARS HEARING AID CTR hearing aids ✓@ 716-832-7203
1265 AMERICAN EAGLE OUTFITTERS clothing-retail ✓@ ..716-832-1100
DAKOTA WATCH CO watches-dlrs ✓@ 716-833-1618
ELECTRONIC CIGARETTES cigar cigarette & tobacco dlrs ✓@ 716-837-0385
HOT TOPIC clothing-retail ✓@ 716-446-0400
KAY JEWELERS jewelers-retail ✓@ 716-837-8895
KIDS FOOT LOCKER shoes-retail ✓@ 716-862-9175
MORE WIRELESS cellular telephones-equip/supl ✓@ 716-833-3400
PAYLESS restaurants ✓@ 716-838-0701
TACO BELL restaurants @ 716-835-9448
THINGS REMEMBERED gift shops ✓@ 716-835-0340
1267 Fisher Jake @ D
MEN'S WEARHOUSE men's clothing & furnishings ✓@ 716-837-1966
1269 GENERAL NUTRITION CTR health & diet foods-retail ✓@ 716-832-0350
GNC vitamin & food supplements ✓@ 716-832-0350
1275 JOURNEYS shoes-retail ✓@ 716-837-4635
1281 CHRISTOPHER & BANKS clothing-retail ✓@ 716-831-0013
1285 EXPRESS clothing-retail ✓@ 716-834-5864
1287 LAUX SPORTING GOODS INC sporting goods- retail ✓@ 716-832-2774
1287 A/2 CARLTON CARDS greeting cards- retail ✓@ 716-446-1505
1289 NEW YORK & CO clothing-retail ✓@ 716-836-0814
1293 CHAMPS SPORTS sporting goods-retail ✓@ 716-836-6456
1303 J C PENNEY CO department stores ✓@ 716-837-2100
J C PENNEY OPTICAL optical goods- retail ✓@ 716-833-1166
SEPHORA INSIDE JCPENNEY cosmetics & perfumes-retail ✓@ 716-837-2100

ZIP CODE 14226 CAR-RT C030

1355 DELTA SONIC CAR WASH car washing & polishing ✓@ 716-832-4050
1385 MC DONALD'S restaurants ✓@ 716-833-2159
1395 ARBY'S restaurants ✓@ 716-832-5231
1401 DIVAL SAFETY OUTLET safety consultants ✓@ 716-832-0021
GAME CRAZE INC games & game supl ✓@ 716-831-3747
1405 SCHUELE PAINT CO paint-retail ✓@ 716-836-3871

ZIP CODE 14226 CAR-RT C057

1435 SEARS AUTO CTR tire-dlrs-retail ✓@ 716-836-7049
1445 WEST MARINE marine equip/supl ✓@ 716-803-1357

Get Mailing Lists

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 2014



WASHINGTON MILLS TONAWANDA INC abrasive products ✓@ S
.....716-693-4550

BUSINESSES 16 **HOUSEHOLDS 24**

NIAGARA FALLS BLVD (BUFFALO)
• ZIP CODE 14223 CAR-RT C062
154 - 158 No Current Listing (2 Hses)
166 HALT GRAPHIC DESIGN graphic designers ✓@ ..716-836-4439
Halt Shannon M ✓ [18] ● (1940)
170 (N) Mangun Lamont ✓
2 Torres Ricardo ✓@ [3]
3 Ilardo Laurence R ✓ [12] 716-832-4815
174 Piparo Chris M ✓ [19] ● (1946)
Piparo Joseph A
180 4 (N) Joe Benjamin S
186 - 190 No Current Listing (2 Hses)
192 Green Marilyn E ✓ [19] ● (1946) 716-832-5016
198 1 (N) Linstonburgh Jason W
200 Kim Min [4]
202 Dwight Wallace F II ✓ [3]
Tanzini Katie J ✓ [5]
Wallace Dwight ✓ [2]

446 I
K
2
462 D
466 A
474 A
F
H
S
V
4
4
+ CHA
500 D
512 S

This directory is property of Polk City Directories. It is le
on the title page of this directory. This informa

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 2014

204 ▲ HOMEOWNER

NIAGARA FALLS BLVD Cont'd

1 Brown George A [5]
204 Kazinski Brian D ✓ [18] 716-832-5296
Lelito Kevin K ✓@ [30] 716-833-1671
4563 206 Ali Hasan A @ [5]
4563 (N) Oweis H ✓ 716-835-0171
208 No Current Listing
218 Strawbridge Justina L ✓ [19]▲ (1946)
Strawbridge Cassie
1925 222 Gisel Barbara E & John C ✓@ [26]▲ (1946) 716-832-8647
1466 228 Clark Rodney ✓ [7]▲ (1946) 716-833-0365
232 Poppleton Brian E ✓ [15]▲ (1900)
0737 240 BOULEVARD HAIR CARE beauty salons ✓@ 716-832-1060
(N) Gonzalez Angel M & Ann ✓
1 Chornjandr Wassana [2]
0918 3 (N) Marlett Kathleen I
3731 244 NEGRIL ONE STOP restaurants ✓@ 716-803-1844
248 (N) Alcantara Jason A ✓ 716-837-1305
(N) Jones Jarren ✓@
9098 252 Dussault Anjuli S ✓ [33]▲ (1951) 716-838-1810
254 Parker Candace ✓ [4]
258 (N) Ringler Mark J ✓
3269 (N) Santorio Scott C ✓@
1896 262 Fisher Amanda C ✓ [4]▲ (1940)
268 Hodur Darrell L ✓ [36]▲ (1916)
270 Henry Ruthann M & David C ✓@ [10]▲ (1953) 716-836-2050
0949 274 Johnson Laquita E ✓ [11]▲ (1920)
9232 276 Fanara Antonio ✓ [24]▲ (1948)
Vella Peter ✓ [18]▲ (1948)
6843 Vella Josephine
8223 280 Muscato Joseph P & Pauline P ✓ [18]▲ (1916)
286 Daher Joseph J ✓ [2]▲ (1928)
8222 290 (N) Bishop Gabrielle C ✓
5205 292 Miller Shawn W & Beth M ✓ [18]▲ (1927)
(N) Piewa Wendy ✓
S 122 298 Dombrowskas Brian A ✓ [21]▲ (1906) 716-831-1402
Dombrowskas Noel M 716-831-1402
300 No Current Listing
304 WALSH GEORGE E clergy ✓@ 716-835-2943
8189 308 Clemo Brian J ✓@ [22]▲ (1930) 716-834-6041
Clemo Jeffrey D Jr 716-834-6041
5334 310 Godleske Thomas J & Cheryle A ✓@ [36]▲ (1930) ..716-835-5693
3584 316 Demars Michael J II ✓ [20]▲ (1922)
320 No Current Listing
1952 324 (N) Donovan Derek ✓ 716-837-2612
3327 328 Kindron David J ✓ [28]▲ (1995) 716-837-8313
Kindron Jonathan J 716-837-8313
330 No Current Listing
334 O'Brocta Louis J & Marylou L ✓ [54]▲ (1948) 716-835-0740
338 Soika Alfrieda T ✓ [13]▲ (1920) 716-832-1444
0715 342 (N) Fildes Ralph & Lynn ✓@ 716-836-6282
5288 344 HEWSON ROBERT A DPM podiatrists ✓@ 716-833-8094
6060 WRIGHT SUSAN M DPM podiatrists ✓@ 716-833-2680
• ZIP CODE 14223 CAR-RT C049
4798 354 CAR LOCKSMITH locks & locksmiths ✓@ 716-796-0306
UNLIMITED MINIMART convenience stores ✓ 716-832-0197
+ CAMBRIDGE BLVD INTERSECTS
2832 358 Wheeler Micky & Mary A ✓@ [36]▲ (1900) 716-832-0989
362 Ruffino Robert J & Joan E ✓ [22]▲ (1937) 716-832-7435
9700 370 Lam Shek S ✓ [18]▲ (1948) 716-835-0380
2525 Lam Vicki W 716-835-0380
(N) Roberts Elizabeth ✓@
378 Marter Gerald ✓ [46]▲ (1922) 716-834-2058
382 Stabl Josef W ✓ [40]▲ (1948) 716-835-4031
Stabl Hildegunde 716-835-4031
386 Dreyer Elizabeth ✓ [4]
3825 (N) Febus Benjamin ✓ 716-836-3136
0498 Larson Casey ✓ [3]
1432 Padua Juan ✓@ [3] 716-834-4254
0123 Padua Elizabeth 716-834-4254
Ramirez Jacqueline ✓ [19]
390 Burgos Maleaha A ✓ [2] 716-837-2572
Mack George G ✓ [5]
1044 394 Kelleher Thomas M & Theresa Y ✓ [26]▲ (1929)
396 No Current Listing
0247 398 Barnes Timothy D ✓@ [29]▲ (1927) 716-836-0337
406 (N) Grabowski Henry ✓ 716-695-3093
410 Yager William T ✓ [18]▲ (1997) 716-836-8494
0949 Yager Robert D 716-836-8494
414 Stringfellow Ray P & Jennifer M ✓ [14]▲ (1935)
8068 418 (N) Burns Kevin M ✓
422 JENEANES HAIR CTR hair replacement ✓@ 716-834-0051
0813 ***+ PAIGE AVE BEGINS***
0600 SCHWARTZ MICHAEL DDS dentists ✓@ 716-835-3906
1890 5 (N) Renda Anthony
6 (N) Hughes Sean E ✓
4550 424 SWEENEY'S GARAGE auto rpr & serv ✓ 716-832-0648
✓@ 442 S & E JEWELERS jewelers-retail ✓@ 716-832-1595
4550 S & E TV & ELECTRONICS television & radio-serv/rpr ✓@
DS 24 716-832-1597
446 Ippolito Ramon J ✓ [10] 716-876-7595
KISLOSKI CONSTRUCTION GROUP general contractors ✓@
.....716-835-5706
2 (N) Smith Marcus T @
4439 462 DARCY'S GROOMING pet washing & grooming ✓@
.....716-836-0456
466 Alston James ✓ [6]
474 AFTER 50 newspapers ✓@ 716-832-9300
4815 FROHE ADELE N attorneys ✓ 716-834-5322
HAQ SYED EAJAZ MD physicians & surgeons ✓@
.....716-833-3697
SYED ATTAULLAH MD physicians & surgeons ✓@
.....716-832-1050
5016 VITELLO FRANCINE physicians assistants ✓@ 716-832-1050
4 Haq Syed E ✓ [9]
4 Haq Eajaz S
+ CHALMERS AVE INTERSECTS
500 DIP & DIVE divers equip/supl ✓@ 716-837-3483
512 SAIGON BANGKOK RESTAURANT restaurants ✓@
Continued Next Column

+ ROBINSON ST INTERSECTS Continued from prior column
NIAGARA FALLS BLVD Cont'd
.....716-837-2115
528 No Current Listing
530 LAKELAND SUPPLY INC auto parts & supl- retail-new ✓@
.....716-834-2777
536 LAKELAND SUPPLY INC auto parts & supl- whol ✓@
.....716-834-2776
540 Chauhan Sujata @ [14]▲ (1954)
LINCOLN PARK MARKET grocers-retail ✓@ 716-833-3712
US POST OFFICE post offices ✓@ 716-833-3712
546 K CAFE restaurants ✓@ 716-836-8888
+ DECATUR RD INTERSECTS
564 Bova Velinda J [8]
570 McKeone Gerald J & Nicole M ✓ [8]▲ (1946)
580 Fix Joan W ✓ [48]▲ (1946) 716-931-5899
Fix Francis R 716-931-5899
588 Lunney Dennis M & Melissa A ✓ [20]▲ (1951) 716-833-8971
594 Diamond Anthony A ✓ [32]▲ (1947) 716-836-5462
594 Diamond Anthony J 716-836-5462
600 Villanueva Roberto S ✓ [20]▲ (1946)
Villanueva Ester S
608 Luzak Ruth A [21]▲ (1946)
616 Penfield Anne M ✓ [19]▲ (1946)
Penfield Amber L
624 No Current Listing
628 McPhaden Cynthia M ✓ [20] 716-693-3735
Melchiorre Christine G ✓ [21]▲ (1946)
Melchiorre Maria
634 - 640 No Current Listing (2 Hses)
644 Liscavage William K ✓@ [31]▲ (1946) 716-835-9609
650 (N) Notaro Tammy L ✓
654 Horbowicz Jeffrey J & Denise [23]▲ (1946)
+ LINCOLN PARK DR INTERSECTS
664 Israel Chad R & Danielle M ✓@ [18]▲ (1951) 716-835-1720
668 Frazier Melvin J ✓@ [18]▲ (1948)
Frazier Jennifer M
670 (N) Sahail Shahzad ✓@
674 Ranney Gary L ✓ [36]▲ (1949) 716-835-1198
678 Zimmerman Richard H & Bree A ✓ [24]▲ (1949)
684 Pray Donald P & Carole J ✓ [46]▲ (1949) 716-832-7793
688 Bonillas-Thompson Angelica B ✓ [8]▲ (1949) 716-939-3869
694 No Current Listing
696 Glambrone Andrew E Sr & Dianna M ✓@ [2]▲ (1949)
704 Chamberlin Grant L [2]
(N) Smith Patrick A ✓
710 Blom Carol D ✓ [50]▲ (1950) 716-835-8447
716 Francken Timothy M & Kathleen I ✓ [20]▲ (1947)
722 Zanelottie Richard J & Wendy M ✓ [11]▲ (1948) 716-833-1731
728 Janus Lutz J & Margaret G ✓ [36]▲ (1947) 716-836-8212
738 Dickey Ronald G & Robin L ✓ [28]▲ (1949) 716-446-1833
+ HIGHLAND AVE INTERSECTS
748 Powell Arlene P ✓ [33]▲ (1949) 716-837-1397
758 No Current Listing
770 Battista Ellen B [9]▲ (1954)
GILCHRIST RHONN marriage & family counselors ✓
.....716-833-8314
PAIN TREATMENT CONSLNTS-W NY physicians & surgeons ✓@
.....716-833-8184
+ HARRISON AVE INTERSECTS
782 DAIRY QUEEN ice cream parlors ✓ 716-834-2447
796 BERRYMAN KATHLEEN career & vocational counseling @
.....716-832-1434
STURNIOLO FRANK M PHD psychologists ✓ 716-832-1434
TEAM Q EMPLOYEE ASSISTANCE psychologists ✓@
.....716-832-0010
800 DR AMAL MARDINI PLLC chiropractors dc ✓@ 716-817-6729
Mardini Amal ✓ [4]▲ (1954)
+ MOORE AVE INTERSECTS
804 TRAN BEAUTY SUPPLY beauty salons- equip/supl ✓@
.....716-836-4336
Tran Henry ✓ [3]
820 NOCO EXPRESS serv stations- gasoline & oil ✓@ ..716-832-0810
NOCO SEVENTY FOUR TONAWANDA serv stations- gasoline & oil ✓@ 716-833-3217
828 Kujawa Alicia [5]▲ (1954)
850 Choi Sang S [4]▲ (1954)
SUNG'S ORIENTAL GROCERY & GIFT oriental goods ✓@
.....716-836-3611
860 KENILWORTH ELECTRONICS CO radio communication equip/sys ✓ 716-837-6666
Schober Robert W [6]▲ (1954)
874 CORSI A FIRST KLASS COLLISION auto body- rpr & painting ✓@
.....716-835-2455
Klaskala Valerie J [18]▲ (1954)
Klaskala Val
900 PEARCE & PEARCE CO INC real estate ✓@ 716-833-6600
910 AMHERST SECURITY PRO INC security guard & patrol serv ✓@
.....716-833-4700
DAVID PHOTO SVC INC photo finishing- retail ✓@
.....716-835-4620
DPS VIDEO video production & taping serv ✓ 716-835-4635
920 (N) Battista Raymond ✓ 716-837-0201
FOUR PAWS PET CTR pet shops ✓@ 716-836-0365
OASIS DANCE CTR sports info ✓@ 716-698-0288
926 SUN CITY MATTRESS mattresses ✓@ 716-834-7400
+ EGGERT RD INTERSECTS
+ SHERIDAN DR INTERSECTS
BUSINESSES 47 **HOUSEHOLDS 128**

NIAGARA FALLS BLVD (NORTH TONAWANDA)
• ZIP CODE 14120 CAR-RT C013
628 (N) Collis Robert K ✓▲ (1958)
Collis Nancy L
642 De Mart Michael A Jr & Marcia A ✓ [22]▲ (1957)
648 Heller Joanne M & Richard J ✓ [21]▲ (1951)
654 Verdibello Gregory D [2]
664 No Current Listing

ies. It is leased for the personal use of the subscriber. Use of this directory is subject to the Terms of Use appearing

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 2014



205

NIAGARA FALLS BLVD Cont'd

1134 Werth Mark R & Kathy A ✓ 36 ● (1952) 716-692-6183

1144 Doherty John R & Mary E ✓ 8 ● (1955)

• ZIP CODE 14120 CAR-RT C031

1166 BON'CHAZ beauty salons ✓@ 716-694-1166

Giammusso Charles B ✓ 22 ● (1958) 716-695-5799

Giammusso Calogero 716-695-5799

1182 HAYAT MOTEL hotels & motels ✓@ 716-694-0360

Patel Mahendra J & Kala M 12 ● (1958)

1200 B-COZY MOTEL hotels & motels ✓@ 716-695-3437

(N) Davis Christine @ ● (1958)

Davis Alicia

+ MAPLE DR ENDS

• ZIP CODE 14120 CAR-RT C010

2880 ALDERCREEK MUSIC INC musical instruments-dlrs ✓@ 716-693-5456

2884 No Current Listing

2888 Alexander Katherine A ✓@ 3 716-260-1465

Alexander Kevin 716-260-1465

1 Simmons Dwayne & Edrema @ 6

2890 PINZEL MARK D nurses- practitioners @ 716-807-7337

STEAD SUSAN M nurses- practitioners @ 716-807-7337

WHEATFIELD PEDIATRICS physicians & surgeons ✓@ 716-807-7337

Wittmann Joseph C Jr 2

Target Street	Cross Street	Source
-	✓	Polk's City Directory

KENMORE AVE 2008

HOUSEHOLDS 3

KENMORE AVE (BUFFALO)-FROM 35
WINDERMERE BLVD
+ *MAIN ST CONTINUES*
• ZIP CODE 14226 CAR-RT C002
43 MICHAEL WILSON REALTY LLC real estate consultants ..716-250-5400
47 MAY JEN CHINESE RESTAURANT restaurants 716-832-5162
+ *WINDERMERE BLVD INTERSECTS*
63 No Current Listing
71 WEHRLE DIAGNOSTIC LAB INC laboratories- medical 716-837-6947
2 CRUZ LOURDES F MD physicians & surgeons 716-832-3111
+ *WINDERMERE BLVD INTERSECTS*
95 Martin Ann [20] ♠ 716-833-1479
Szczepanski Carol A [13] ♠
+ *CAPEN BLVD BEGINS*
99 Krestos Michael A [21] ♠ 716-835-3882
Krestos Thomas M 716-835-3882
+ *ALLENHURST RD INTERSECTS*
135 Napier Kandie K [13] ♠ 716-836-9377
140 FRANCAVILLA VINCENT J DDS dentists 716-835-6966
143 No Current Listing
+ *NIAGARA FALLS BLVD INTERSECTS*

BUSINESSES 5 HOUSEHOLDS 6

KENNEDY CT (LANCASTER)-FROM 2

Target Street	Cross Street	Source
-	✓	Polk's City Directory

KENMORE AVE 2008



+ HIGHLAND AVE INTERSECTS

HOUSEHOLDS 88

KENMORE AVE (BUFFALO)-FROM 2 ORSON PL WEST
+ NIAGARA FALLS BLVD CONTINUES
• ZIP CODE 14223 CAR-RT C069

187 Ⓝ Kotla Varsha
Stiles Kelleen J [10] 716-835-5549
189 WILLIAM L LONG & ASSOC architects 716-833-1873
191 Brenner George [46] ▲ 716-833-4968
193 Rozek Kenneth P & Jane M [30] ▲ 716-834-2169
197 Catalano Susan M [20] ▲
199 No Current Listing
205 EMPORIUM HAIR DESIGN beauty salons 716-832-6558
Ⓝ Rockey Shane
210 Labruna Anthony S & Sharon R [29] ▲ 716-833-9606
214 Mahoney Thomas E [18] ▲ 716-831-0930
217 Weiser Matthew J [11] ▲
Weiser Florence K
218 No Current Listing
225 Guidice Michael A [4]
NETEX SERVICES LLC serv 716-819-4400
229 Bitterman James W & Constance M [12] ▲ 716-837-0094
233 No Current Listing
237 Nesselbeck Norman B & Betty R [48] ▲ 716-834-8552
241 Ⓝ James Shaniqua E
245 - 251 No Current Listing (3 Hses)
252 DOUG-AL AUTOMOTIVE INC auto dlrs-used cars ..716-837-2370
253 ADRIAN SALES mfrs- agents & representatives 716-833-2636
Ⓝ Jones Amos Z
+ UNIVERSITY AVE INTERSECTS
257 RAMM OPTICAL opticians 716-834-9500
Suszynski Amy M [2]
261 Baker Lawrence [4] 716-833-2834
265 J J'S CAFE restaurants 716-837-2310
Ⓝ Philip Maya
267 EXCLUSIVE DESIGNS nonclassified establishments
.....716-833-0833
271 CITY A1 DRIVING SCHOOL INC driving instruction
.....716-875-4662
285 ALL COPY USA INC copying/duplicating mach/supl
.....716-831-9906
CENTRAL COPIER SVC INC copying/duplicating mach/supl
.....716-873-9010
+ MONTROSE AVE CONTINUES
299 A-1 PAINTING CO painters 716-833-6943
Kotzambasis Nikolaos E [17] ▲
Kotzambasis Elias N
PETE'S PIZZA pizza 716-834-0254

593 597 601 619 623 627 631 647 651 659 665 • ZI 685 695 707 725 727 • ZI 747 761 765 771 775 791 797 801

This directory is property of Polk City Directories. It is l
on the title page of this directory. This inform

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAIN ST 2008

MAIN ST - MANHASSET ST

MAIN ST Cont'd

3173 V W SPLASH convenience stores 716-832-8050
3178 No Current Listing
3180 LOVE IS LOVE barbers 716-835-6838
Wilson Ulysses
3182 No Current Listing
3184 QUEEN CITY BOOK STORE comic books 716-833-6220
3189 CATHEDRAL OF PRAISE churches 716-803-1187
ST JAMES MISSIONARY BAPT CHR churches 716-446-0948
3191 Good Jennifer
3193 No Current Listing
3198 FRANK'S MOBIL ON THE RUN serv stations- gasoline & oil 716-836-5337
TIM HORTONS doughnuts 716-836-5337
3208 CANDY CO PARKSIDE candy & confectionery-retail ..716-833-7540
PARKSIDE CANDY CO INC candy & confectionery-mfrs 716-833-7540
3210 BUFFALO PREGNANCY CARE CTR abortion alternatives org 716-833-7100
CRISIS PREGNANCY CTR pregnancy counseling servinfo 716-833-7100
Francis Kevin M [9] ..716-833-3441
3214 MAURICE TAILORS cleaners 716-833-5049
3216 Nichols Alyssa
PARLATO-O'BRIEN REALTY INC real estate 716-835-1020
3218 COLLEGE LAUNDRY SHOPPE laundries-self serv ..716-833-0060
3223 Harrelson Charles 716-836-2826
Noreck John 716-835-6056
RENAISSANCE STUDIOS tattooing 716-831-0588
3225 UNIVERSITY HOTS restaurants 716-204-2372
3229 BUFFALO PICTURE FRAME & MIRROR picture frames-mfrs 716-838-3800
3230 GREEKS & SNEAKS book dlrs-retail 716-833-4913
3233 CANTALICIAN CENTER-LEARNING schools ..716-833-5353
Machnica Fran M [17]
+ SUTTON LN BEGINS
3234 AMY'S PLACE restaurants 716-832-6666
PAVILION INTERNATIONAL gift shops 716-834-8310
3236 MUSIC CITY musical instruments-dlrs 716-838-4547
3240 Huber Bernhard J [30]
O'CONNELL LUCAS CHELF INC clothing-retail 716-836-4140
3242 UNIVERSITY HEIGHTS CMNTY CTR social serv & welfare org 716-832-1010
3258 AMAK HEALTH CARE AGENCY home health serv 716-832-0875
3260 Guarino James D [2]
Guarino Marla-Jim
SHANGO restaurants 716-837-2326
6 Glenn Anna M [7]
3264 THIRD BASE bars ..716-833-1284
3264 1/2 No Current Listing
3268 MING CAFE restaurants 716-833-6988
MONDO VIDEO video tapes & discs 716-881-1953
3269 Ledwon Jacob C [18]
NEWMAN CENTER SUNY/AB SOUTH churches 716-833-6649
ST JOSEPH'S RC CHURCH churches 716-833-0298
ST JOSEPH UNIVERSITY PARISH clergy 716-837-2971
3270 P J BOTTOMS restaurants 716-833-3270
3275 ST JOSEPH churches 716-835-7395
+ ZIP CODE 14214 CAR-RT C006
3288 CHABAD HOUSE OF BUFFALO synagogues 716-833-8334
3290 KEY BANK banks 716-838-7600
3292 Ziad Abdulwahab A [9]
3296 GALLIVAN RICHARD S F attorneys 716-831-2727
A2 Nayak Satya C
B1 Chinnam Meenalaksh [3]
B3 Gugliuzza Joseph A & Geraldine I [14] 716-836-7864
B4 Scandale Nathaniel [16]
3334 UNIVERSITY PRESBYTERIAN CHURCH churches ..716-836-7660

MAIN ST Cont'd

3350 CHILD & ADOLESCENT TREATMENT child guidance 716-835-4011
Rook Antoinette
3362 WENDY'S restaurants 716-862-3511
3382 SUBWAY restaurants 716-834-6878
3400 MILITELLO'S LUGGAGE luggage-retail 716-833-1600
MOM & POPS NATURAL FOOD convenience stores ..716-836-8800
3404 UDAGAWA SALVADOR M MD physicians & surgeons 716-835-0641
Vidal-Mohammed Liliana E [3]
3410 BACK TO NATURE BUFFALO INC vitamins 716-835-4779
Horosh Millie [4]
Horosh William
NUTRITIONAL CENTER-BUILDING genl merchandise- retail 716-835-4779
PURE HERBS PRODUCTS herbs 716-835-4779
+ ZIP CODE 14214 CAR-RT C099
3435 AMERICAN INSTITUTE-ARCHITECT S architects 716-829-2008
ARMY NATIONAL GUARD state government 716-829-2761
Barker John M
BETHEL HEAD START PROGRAM social serv 716-829-3161
CONNY DANIEL JAME DDS dentists 716-829-2862
Cosme Jason [9]
GENCO ROBERT J DDS dentists 716-829-2883
HEALTH SCIENCES LIBRARY special interest libraries 716-829-3335
HOFFMAN MARTIN T MD physicians & surgeons 716-829-2244
LAMPASSO JUDITH DDS dentists 716-829-2972
LEVINE MING SHIH DDS dentists 716-829-3847
LI CARL K MD physicians & surgeons 716-829-2975
MILLARD FILLMORE COLLEGE schools 716-829-3131
NABI HANI A MD physicians & surgeons 716-834-5578
NEW YORK STATE UNIVERSITY physicians & surgeons 716-829-2845
NISENGARD RUSSELL J DDS dentists 716-829-2836
RUSSO THOMAS A MD physicians & surgeons 716-829-2674
STATE UNIVERSITY OF NEW YORK physicians & surgeons 716-829-2012
STERLING MEDICAL CTR physicians & surgeons 716-829-3670
SUMMIT EDUCATIONAL RESOURCES schools 716-829-2525
SUNY BUFFALO DENTAL MEDICINE dentists ..716-829-2733
UNIVERSITY DENTAL ASSOC dentists 716-829-2013
UNIVERSITY OF BUFFALO physicians & surgeons 716-829-3092
UNIVERSITY ORAL SURGERY dentists 716-829-6637
UNIVERSITY ORTHOPAEDIC SVC INC physicians & surgeons 716-829-3670
UNIVERSITY PEDIATRIC DENTISTRY dentists 716-836-5595
VILLAGE PARK ORTHODONTICS dentists 716-829-2872
WOLF MERWIN DDS dentists 716-829-2722
33 WBFO radio stations/broadcasting co 716-829-6000
34 Powell Michelle [6]
34 Powell Dominique
41 Sapozhnikova Olga
42 Lee Christopher [6]
42 Lee Grace J
801SB Heinemen Cynthia L
905 Calle Grace L
+ ZIP CODE 14214 CAR-RT C006
3442 Kaplan Eric [2] 716-833-1358
Osterhoudt Amanda [2] 716-834-1303
Sorrell Nick 716-844-8938
9 Perez Paul A & Aymara
B11 Zona Kelly L
B14 Dunford Robert G [13]

MAIN S

B
C
C
C
C
3470 T
3488 W
+ WINDE
+ KENM
+ SPRIN
+ CALLC
BUSINES
MAIN PL
• ZIP CO
20 MCI
90 WAL
BUSINES
MAIN PL
• ZIP CO
300 BUI
P
se
600 ALL
no
1000 LE
te
1110 FL
co
1300 AM
at
Ga
IS
OL
SA
1400
1600 CA
att
Re
1800 Bll
DU
Ph
Su
1900 UN
bu
2150 Bu
BL
att
2200 CL
LL
2300 CH
2400 AN
El
MI
IN
BUSINES
MALSCH
AVE NOR
• ZIP CO
10 Kisse
12 Rodr
14 No C
15 Dubu
16 No C
17 Lach
Lach
18 Leep
20 Soos
Soos
22 Jask
Jask
24 Wrig
Wrig
28 Brow
Brow
29 Ba
Cass
1 He
30 Torn
+ ECKHI
MALTA
ST WES
+ W TUP
• ZIP CO
9 Koma
22 Garc
24 Zam

This directory is property of Polk City Directories. It is leased for the p on the title page of this directory. This information changes

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAIN ST 2008



214

MAIN ST Cont'd

B2 Zhong Dan X [2]

C10 Chow Catherine [5]

011 716-834-7627

C12 Burke Liam P [2]

.....716-834-0405

511 C16 Richardson Claudia D [2]

C9 Ⓝ Bowden Darrell L

878 3470 TIM HORTONS doughnuts

.....716-831-3211

600 3488 WALGREENS pharmacies

.....716-834-7223

800 + WINDERMERE BLVD INTERSECTS

+ KENMORE AVE INTERSECTS

+ SPRINGVILLE AVE BEGINS

641 + CALLODINE AVE BEGINS

BUSINESSES 1280 HOUSEHOLDS 716

C

779 MAIN PLACE MALL (BUFFALO)

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAIN ST 2008

54 No Current Listing
+ GENESEE ST INTERSECTS
BUSINESSES 6 HOUSEHOLDS 19

MAIN ST (BUFFALO)-FROM 2 TENNYSON TER EAST
• ZIP CODE 14226 CAR-RT C002

3500 CHINA KING RESTAURANT restaurants 716-837-6863
DOTS FASHIONS women's apparel- retail 716-834-4903
Milkie Mike
SALLY BEAUTY SUPPLY cosmetics & perfumes-retail 716-831-3286
TOPS FRIENDLY MARKET grocers-retail 716-515-3260
WESTERN UNION money transfer serv 716-515-3240
ZETTI'S PIZZA & PASTA pizza 716-831-8000
2 AMHERST THEATRE theatres-movie 716-834-7655
3 BOBBY MCGEES restaurants 716-837-8338
5 CITIZENS BANK banks 716-862-0525
7 RECORD THEATRE records tapes & compact discs 716-837-2090
8 HAIR PEOPLE beauty salons 716-834-9090
8 M & T BANK banks 716-832-9523
99B Spinder Daniel R T5 716-681-6054
110 STARBUCKS coffee shops 716-834-8069
120 CRICKET cellular telephones 716-446-9313
128 QUIZZNOS SUB nonclassified establishments 716-446-5080
130 Broder Timothy D 3
130 BUFFALO EXECUTIVES ASSN associations ..716-852-6916
130 Dombrowski Susan C
130 Gadley Roslyn D
130 Land Pamela J
130 Lewis Ronald
130 UPS STORE mailing & shipping serv 716-332-2323
130 Young Thelma
130 Young Loretta
130-110 Carmona Dorena
130-119 Swash Ray
130-171 Lidgett William
230 LARUSSA FASHION clothing-retail 716-834-6254
270 RADIO SHACK electronic equip/supl-retail 716-832-8311
280 DOLLAR TREE variety stores 716-837-6680
320 H & R BLOCK TAX SVC tax return preparation/filing 716-838-9641
340 GNC health & diet foods-retail 716-835-9340
360 FOREVER NAILS manicuring 716-833-5424
370 PAYLESS SHOE SOURCE shoes-retail 716-832-3610
500 GAMESTOP games & game supl 716-836-3748
3510 A J WRIGHT department stores 716-833-3083
3540 ILS WAYPORT INC nonclassified establishments 716-833-7886
MC DONALD'S restaurants 716-832-6221
3586 No Current Listing
• ZIP CODE 14226 CAR-RT C007
3604 DYNAMIC ELECTRO ACOUSTICS acoustical contractors 716-836-2625
SPEAKER SHOP INC stereophonic & high fidelity 716-837-1557
3610 UNIVERSITY MEDICAL BOOKSTORE book dlrs-retail 716-833-7131
3612 BOULEVARD INN & SUITES hotels & motels 716-837-3344
BOULEVARD TAXI taxicabs & transportation serv ..716-861-1269
Kvaratskheliya Shorena
3640 KAINOS MAIN BAILEY LLC doughnuts 716-446-9210
3666 Evans Dawn J 8

3710 GERC thera Resid
3714 Delmc Delmc
3742 No Cu
3750 Logan
3760 HART
3770 POWI
3772 Fluren
3781 GROV COUF
3782 Lalli V
3790 No Cu
3800 Ortma
3810 Cudne
LEO N SIDIN
3824 GREG
3826 WATT PC en
3860 BUFF SACR Perry SACR religio
3900 GOLD estabi
3901 Flora Frend Sung 1B Flo 2A Sc 2B Ha 2C Ch 3A Lud 3D Hoc 4C Ide 4D Par 5D Sup 6A Wri 6C Mer 7A Frin 7A M 8A Rict 8B Erb 8C Cos 8C Cos 8D Por 9A H 10B Ha 10C Te 11A Be 11A Be 11B Fit 11D Be 12A Si 12C C 12D 3911 LA MA physic ROBE physic 3921 BLUE veterin BLUE veterin

erty of Polk City Directories. It is leased for the persc

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 2008



BUSINESSES 295 HOUSEHOLDS 689

NIAGARA FALLS BLVD (BUFFALO)
• ZIP CODE 14214 CAR-RT C006

2 - 38 No Current Listing (4 Hses)
40 Nyrop Jessica E [2]
41 Newman John C [5] ▲
42 No Current Listing
43 Ⓝ Rodriguez Michael ▲
45 Lawson Cecelia M [5] ▲
46 No Current Listing
50 Newberry Wilma J [34] ▲
.....716-835-0474
54 Metzger Michael M [44] ▲
58 Brace Frederick E Jr & Kathleen L [24]
▲ 716-833-2272
62 Kowsky Francis R & Helene D [33] ▲
.....716-836-6069
65 McCraty Elner J [23] ▲
.....716-832-2274
66 Klein Peter M Sr & Rose M [43] ▲
.....716-837-9007
69 Jarosz Michael S & Susan S [12] ▲
.....716-832-1882
70 Kogler Susan M & James F [36] ▲
73 Conti Joan N [17] ▲
74 Onorato Victoria A [41] ▲
.....716-833-9426
77 No Current Listing
78 Privateer Christoph A & Karen D [15] ▲
81 Thomas Johnny M [13] ▲
82 Reade Dorothy R [12] ▲
.....716-837-7520
Reade Catherine P 716-837-7520
85 Wilson Joseph J [2] ▲
86 Leising Peter C & Jeanne [18] ▲

Get Mailing Lis

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 2008



Polk City Directories N

NIAGARA FALLS BLVD Cont'd

89 Reese Kelly A [11] ▲ 716-833-4447
90 Nieman Donald H & Elaine D [16] ▲
.....716-837-0585
95 - 96 No Current Listing (2 Hses)
97 Simmons Lorayne D [23] ▲
100 Beggs Donald W [44] ▲
101 Patel Saleem [31] ▲
Patel Samina
104 Coppola Joseph A & Ruth A [12] ▲
.....716-833-9275
105 Alexander Pamela & Derald [32] ▲
.....716-833-3523
109 McMahon Joseph P Jr & Christina C
[5] ▲ 716-876-9140
112 No Current Listing
115 Arditi Olivia L [10] ▲
Arditi Chloe
116 Ⓓ Cantaffa David T ▲
Ⓓ Laulette Anthony J
119 Ⓓ Dunlap Vincent K & Tonya M ▲
.....716-876-5575
120 No Current Listing
123 Ⓓ Groetz Rita M
Woodrow Benjamin F & Colleen F
[21] ▲ 716-837-9395
124 Cirrito Frank A [18] ▲ ..716-835-3677
Cirrito Roseann 716-835-3677
127 Ⓓ Bryan Jodi M
Ⓓ Claeys Jonathan M ▲
128 EDNA LOUISE ESTATE SALES
estates 716-812-1018
Then Philip J & Charmaine L [25] ▲
131 Herod Michael J & Bridget B [20] ▲
132 Curtis Florence H [24] ▲
.....716-835-1747
136 Daum James E & Fay A [46] ▲
.....716-833-2234
142 HULICKA IRENE M PHD
psychologists 716-836-9441

BUSINESSES 2 HOUSEHOLDS 51

NIAGARA FRONTIER FOOD TERMIN
(BUFFALO)-FROM 1480 CLINTON ST

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 2008

512 716-632-5394
166 HOUSEHOLDS 1
310
079
318
690
244
011
011
280
287
621
006
006
266
107
S 37
99
654
438
909
311
003
123
806
685
685
188
304
745
874
287
642
923
662
529
619
475
475

NIAGARA FALLS BLVD (BUFFALO)-FROM 3000 SHERIDAN DR NORTH
• ZIP CODE 14226 CAR-RT C001

165 No Current Listing
171 Smith Bill
Smith Natasha
177 KAM JOSEPH J DC chiropractors dc 716-835-5400
179 Cody Ruth C [8] 716-446-9230
189 Feuerstein Marvin E [45]
Feuerstein Michael S
195 Puehn George E & Georgia E [44] 716-833-6533
199 Gross Kenneth J [8]
Gross Kimberly J
207 Tudor Sorin [8] 716-838-2915
213 Larson David I & Beth E [7]
219 Flaitz Heather M [5]
225 Fiorella Robert V [30] 716-833-4579
Fiorella Susan L 716-833-4579
231 No Current Listing
237 Watson Chris M [5]
249 Lawson Andrea J [7]
255 McNeill Leeann [6] 716-833-1954
261 Sherwood Jennifer A [4]
Sherwood Stacy L
267 Jo Tasha [18] 716-837-0751
Johnson David P Sr [18] 716-837-0751
Johnson Florence M ..716-837-0751
273 No Current Listing
279 Gianiodis Andrew A [16] 716-862-0036
285 Cooper Paula A [12] 716-834-9480
291 Mattina Rita F [23] ..716-833-4049
297 Lex Kevin A [8]
Schewtchuk Dominka [5] 716-824-1495
303 No Current Listing
309 Lindsay Katie [2]
315 No Current Listing
321 Delles Joan M [39] 716-833-6759
Delles Lisa A 716-833-6759
Lawson Jack S Jr [17] 716-837-2962
327 No Current Listing
DARCY'S GROOMING pet washing & grooming 716-836-0456
333 Warren Jeremy J
Warren Alara B
339 Poloncarz Robert A & Julie A [41] 716-836-6030
345 No Current Listing
363 Cox Bruce H & Linda E [30] 716-833-8629
369 Davern Susan A [20] 716-838-9917
373 Gordon Loretta L [11] 716-833-4927
Gordon Lorrie 716-833-4927
383 Powers Tyrone [16]
389 Wise Todd G [9] 716-835-4531
Wise April L 716-835-4531
395 No Current Listing
399 Glavack Kevin S [4]
Glavack Kristi M
405 Wong Michael T & Betty S [15]
409 No Current Listing
415 Myers Gloria J & Gregory W [18] 716-833-4606
423 Snyder Howard G [2]
Snyder Ashley
429 - 435 No Current Listing (2 Hses)
443 Difrancesco-Fields Lisa A [13]
453 Jaffri Shams A & Rafia S [19]
459 No Current Listing
465 Burnis Alice B [41] 716-833-2555
Burnis John J 716-833-2555
+ OXFORD AVE INTERSECTS
479 Farrell Patricia A [18] ..716-838-1447
Farrell Danne W 716-838-1447
FARRELL PHOTOGRAPHY photographers- portrait 716-838-1447
483 No Current Listing
489 Karovski Jason M [8] ..716-833-5276
Karovski Irena 716-833-5276
Spasezska Irena M [5] 716-832-4266
495 Wong Soo K [41] 716-832-8347
Wong Mary 716-832-8347
505 Wong Manuel G [43] 716-837-4918
513 Leach Mary L [31] 716-838-1771

STREET GUIDE

vdirectory.com

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 2008

NIAGARA FALLS BLVD

NIAGARA FALLS BLVD Cont'd

519 Saxena Suresh B Sr & Bala [19] ♠ 716-446-0455
523 Drexinger Keith F [9] ♠
529 BOULEVARD ELECTRIC electric contractors 716-646-4950
Rodriguez Alida R [11] 716-833-0870
535 Pizetzky Paul [9] ♠ 716-835-7106
Pizetzky Kevin F 716-835-7106
543 Paeplow Charles E [38] ♠ 716-836-9572
549 No Current Listing
553 Johnson Alberta J [11]
559 Flint Wildrena [5] 716-837-2507
563 Singh Arthur & Asha W [11] ♠ 716-834-5695
569 Fry Nancy [2]
579 Didomizio Joseph C & Annette S [20] ♠ 716-838-3412
• YALE AVE INTERSECTS
593 Seland Keith A [23] ♠ ..716-833-4334
599 No Current Listing
605 Daniels Craig A & Cheryl L [16] ♠
613 Redenbach Maria L [15] ♠ 716-833-1754
Redenbach Kim M 716-833-1754
619 Jacob Gladwin A & Sunita [20] ♠ 716-836-1271
625 Patterson Brittany N [27] ♠ 716-837-4687
Patterson Debra M 716-837-4687
633 Relan Sushil D & Aureeta [21] ♠ 716-832-0223
639 No Current Listing
643 CITYWIDE LOCK & KEY locks & locksmiths 716-912-7182
Reppenhagen-Goff James & Kelly M [14] ♠ 716-836-0984
649 Southwick Lawrence A III [18] ♠ 716-832-5094
Southwick Lawrence II 716-832-5094
653 Johnson Willard E Sr & Mary L [36] ♠ 716-862-0307
659 Elkins Kevin A & Linda E [22] ♠
663 - 665 No Current Listing (2 Hses)
669 Perez Angelita A & Alberto [12] ♠ 716-838-5671
673 Platt Robert W [20] ♠
Platt Pamala D
• LONGMEADOW RD INTERSECTS
• ZIP CODE 14226 CAR-RT C034
677 CORNER MART convenience stores 716-833-2866
• LONGMEADOW RD INTERSECTS
679 FERA'S BOULEVARD SUB SHOP restaurants 716-838-4545
681 NEW CHINA MAX WOK restaurants 716-833-8889
711 JAZZYOBICS BY SUZY dancing instruction 716-836-2999
KOREAN UNITED MTHDST CHR BFFL churches 716-835-6354
TRINITY UNITED METHODIST CHR churches 716-835-7711
733 A F AUTOMOTIVE auto inspection stations 716-833-0228
AMERICAN AUTO WORLD auto parts & supl- retail-new 716-832-3636
• RUTH AVE BEGINS
765 CHRISTIAN FELLOWSHIP BAPT CHR churches 716-835-2899
773 CHAIN'S INDIA BOUTIQUE tailors 716-837-8344
Chainani Ramesh L [12] ♠
HONG KONG CUSTOM TAILORS tailors 716-837-8344
785 Rebmann Michael R [5] ♠
Rebmann Marc R
UNIVERSITY MANOR hotels & motels 716-837-7400
789 No Current Listing
803 Lyons John M [8] 716-834-2337
SOKOLSKI SUTHERLAND & LYONS accountants 716-834-2337
Sutherland David W [13] ♠ 716-834-2337
• BETINA AVE INTERSECTS
839 ✪ Gorino Charles ♠
MASTER GORINO'S PIL-SUNG TAE martial arts instruction 716-836-5425
NORTHTOWN ANIMAL HOSPITAL veterinarians 716-834-8387
✪ Schaedler Jean M ..716-834-8387
843 EASTERN ENERGY CONTROL WINDOW glass coating & tinting 716-836-2110
MAINTENANCE & MANAGEMENT ASSOC janitor serv ..716-836-2111
Steigauf George P [3]
Steigauf Kathleen M
845 ✪ Martinek Shawn

NIAGARA FALLS BLVD Cont'd

SENTRY NORTH APPLIANCE SVC ranges & ovens- serv & rpr 716-835-2991
Wilson B [3] ♠ 716-832-4824
847 ✪ Falcone Frank & Kathleen L
MALIK TAILORS tailors 716-862-0122
853 MR PIZZA pizza 716-837-6500
861 Wahl Philip J Jr & Cheryl J [27] ♠ 716-834-4312
865 Barker Thomas J [10] ♠ 716-835-4323
869 WOEPPEL EDWARD J CPA accountants 716-836-3822
871 A CAREER RESUME resume serv 716-837-2798
DESIRED IMAGE skin treatments 716-834-1123
GORDON JAMES IMAGE MAKERS photographers- portrait 716-837-5665
885 AAA LOMBARDO CREMATION SVC funeral directors 716-837-7100
JOSEPH SPANO & SONS FUNERAL HM funeral directors 716-854-2994
LOMBARDO FUNERAL HOME funeral directors 716-837-7100
899 EVERYWOMAN OPPORTUNITY CTR INC career & vocational counseling 716-837-2260
NOTARO IRENE E insurance 716-834-4818
SCHEFF & ASSOC INC insurance 716-834-4818
925 U-HAUL CO truck renting & lease 716-832-1778
• EGGERT RD INTERSECTS
• EGGERT RD INTERSECTS
951 EL PALENQUE MEXICAN GRILL restaurants 716-446-9206
• SHERIDAN DR INTERSECTS
995 FIRESTONE COMPLETE AUTO CARE tire-dlrs-retail ..716-837-9700
1021 PEP BOYS auto parts & supl- retail-new 716-831-0370
1061 Chimera Joanne [6]
Chimera Josie
ESTHER GULYAS TAX SVC tax return preparation/filing 716-446-9831
PLANT PLACE & FLOWER BASKET fruit baskets-gift 716-838-3400
1065 FIRST N'GOAL SPORTSCARDS baseball sports cards/memorabi 716-835-1553
1089 SALVATION ARMY social serv & welfare org 716-836-9023
1101 DEBRA RICH HAMSHER INSURANCE insurance 716-833-1900
GEORGE A KEENE INC building restrtn/presrvtn 716-832-0180
Keene Carmen H [49] 716-837-7880
MARLIES Y HENDRICKS & ASSOC business serv 716-837-1400
• ALMEDA AVE BEGINS
• ZIP CODE 14226 CAR-RT C032
1145 CHILI'S GRILL & BAR restaurants 716-832-3730
1171 MIDAS AUTO SVC EXPERTS auto rpr & serv 716-837-4100
1185 Bac Boulevard [3] 716-833-5226
BUFFALO ATHLETIC CLUB health clubs studios/gymnasium 716-833-5226
FITNESS TEST health clubs studios/gymnasium ..716-204-5978
1201 SIZE 5-7-9 SHOPS clothing-retail 716-835-0732
1203 KIDS FOOT LOCKER shoes-retail 716-862-9175
1205 M & T BANK banks ..716-835-5118
1209 TGI FRIDAY'S restaurants 716-835-6000
1211 CHILDREN'S PLACE childrens & infants wear 716-831-3201
1213 ABERCROMBIE & FITCH clothing-retail 716-837-3412
1219 BERRYMOORE CONVENIENCE convenience stores ..716-836-2507
MOTHERHOOD MATERNITY maternity apparel- whol 716-831-0196
1221 STERLING OPTICAL optical goods- retail 716-833-7766
1227 DISNEY STORE gift shops 716-446-0108
FYE records tapes & compact discs 716-834-9097
1231 AEROPOSTALE clothing-retail 716-836-7503
1233 GAP clothing-retail ..716-836-8080

NIAG
1235
1237
1247
1251
1253
1255
1257
1259
1261
1265
1269
1271
1275
1279
1281
1285
1285
1285
1287
1289
1303
• MAP
1355
1385
1395
1401

This directory is property of Polk City Directories. It is leased for the
on the title page of this directory. This information cha

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 2008

266

NIAGARA FALLS BLVD Cont'd

GAP KIDS childrens & infants wear 716-836-1486
1235 AMERICAN EAGLE OUTFITTERS clothing-retail 716-832-1100
1237 HOT TOPIC clothing-retail 716-446-0400
1247 BONEFISH GRILL restaurants 716-833-6106
1251 BOULEVARD MALL BOOTERY shoes-retail 716-832-4903
1253 LITTMAN JEWELERS jewelers-retail 716-835-4799
1255 MACY'S department stores 716-837-9400
1257 GYMBOREE childrens & infants wear 716-836-0622
MRS FIELD'S COOKIES cookies & crackers 716-833-1077
ORIENTAL ENTERPRISES gift shops 716-446-9888
YANKEE CANDLE CO candles 716-832-3700
1259 BODY SHOP cosmetics & perfumes-retail 716-838-2799
DISCOUNT PERFUME HUT INC cosmetics & perfumes-retail 716-833-5459
NATURALIZER shoes-retail 716-836-4155
PAYLESS restaurants 716-838-0701
SELECT COMFORT mattresses 716-833-2576
URBAN BEHAVIOR clothing-retail 716-835-4095
1261 FCE MANAGEMENT CO mgmt serv 716-834-4028
MICHAELS STORES crafts 716-834-3322
MIRACLE EAR CTR hearing aids 716-832-7203
SEARS department stores 716-446-5100
1265 CARLTON CARDS greeting cards-retail 716-446-1505
DAKOTA WATCH CO watches-dlrs 716-833-1618
EXPRESSIONS STUDIO nonclassified establishments 716-836-4381
ISLAND INK-NET OF WESTERN NY printer cartridges 716-835-4042
JAM COMMUNICATIONS communications 716-836-5400
KAY JEWELERS jewelers-retail 716-837-8895
MONSTER WIRELESS cellular telephones-equip/supl 716-836-7923
SIMPLY CERTIFICATES nonclassified establishments 716-837-2941
T-MOBILE cellular telephones 716-833-0915
1267 MEN'S WEARHOUSE men's clothing & furnishings 716-837-1966
1269 GNC health & diet foods-retail 716-832-0350
1271 HATS WORLD INC hats-retail 716-832-6914
1275 JOURNEYS shoes-retail 716-837-4635
1279 ANN TAYLOR LOFT clothing-retail 716-834-1404
1281 CHRISTOPHER & BANKS clothing-retail 716-831-0013
1285 EXPRESS clothing-retail 716-837-3175
1285 A/2 STRUCTURE clothing-retail
1285 B/2 BATH & BODY WORKS cosmetics & perfumes-retail 716-838-9033
1287 MEMORIES IN WOOD wood products 716-835-9127
1289 NEW YORK & CO clothing-retail 716-836-0814
1303 J C PENNEY CO department stores 716-837-2100
J C PENNEY OPTICAL CTR optical goods- retail

+ MAPLE RD INTERSECTS

1355 DELTA SONIC CAR WASH car washing & polishing ..716-834-0964
DELTA SONIC DETAIL SHOP auto detail & clean-up serv 716-834-0433
DUNKIN' DONUTS doughnuts 716-446-9878
1385 MC DONALD'S restaurants 716-833-2159
PERSECO nonclassified establishments 716-834-7754
1395 ARBY'S restaurants ..716-832-5231
1401 Friedman Rebecca

ed for the personal use of the subscriber. Use of th
ion changes by 60% each year. For an updated direc

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 2008

NIAGARA FALLS BLVD Cont'd

ar 1405 SCHUELE PAINT CO paint-retail
486 716-836-3871
S **+ MEYER RD INTERSECTS**
100 **• ZIP CODE 14228 CAR-RT C057**
1435 SEARS AUTO & TIRE CTR auto rpr
400 & serv 716-836-7049
1445 BOAT/US MARINE CTR marine
106 equip/supl 716-803-1357
1459 HARBOR FREIGHT TOOLS USA
903 INC tools 716-835-6435
PARTS AMERICA auto parts &
799 supl- retail-new 716-446-0200
PETCO pet supl & foods- retail
400 716-832-5142
RAYMOUR & FLANIGAN
622 FURNITURE furniture-dlrs- retail
& 716-834-7171
077 TULLY'S GOOD TIMES restaurants
.....716-446-0007
888 1531 FIRST NIAGARA BANK banks
.....716-625-7600
700 1551 APPLE ONE EMPLOYMENT SVC
employment agencies/opportunit
799 716-835-4005
BLOCKBUSTER VIDEO video

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 2008

City Directories Now on the Internet @ www.citydirectory.com

E NIAGARA ST Cont'd

4 ACME GRINDING SVC INC mach shops 716-694-6060
154 GASTOWN SPORTSMENS CLUB INC clubs 716-693-2525
158 Long Diana J [6] 716-743-8564
160 Ⓓ Dooley Sara J
164 Pielecha Joseph H & Dianne M [34]▲ 716-695-3825
168 Gaiser John F [24]▲ 716-695-0498
174 Schleifer Eric W & Penny C [12]▲ 716-743-1432
180 Doll Thomas A & Brenda A [27]▲ 716-692-0123
186 No Current Listing
188 Suter Janet C & Walter G [17]▲ 716-695-2432
194 Faith Ronald A & Roberta C [11]▲
206 No Current Listing
214 Bodkin Brendan F [12]▲ 716-695-8862
220 Kasprzak William M [6]▲ 716-807-0247
222 Abbott William L & Jessica A [11]▲
296 TONAWANDA FOOTBALL CLINIC athletic org 716-692-0949
• ZIP CODE 14150 CAR-RT C046
298 Dibartolomeo Karen L & Benedict N [4] 716-695-8068
Ⓓ Ksaptsa Mary A
300 GREAT LAKES METAL TREATING heat treating metal 716-695-6600
330 COLE AUTOMATIC TOOL & DESIGN tools-new & used 716-213-0813
E B TROTTNOW MACH SPEC mach shops 716-694-0600
796 ISLE VIEW PARK OFFICE parks 716-692-1890
1000 EXOLON CO abrasive products 716-693-4550

BUSINESSES 15 **HOUSEHOLDS 19**

NIAGARA FALLS BLVD (BUFFALO)
• ZIP CODE 14223 CAR-RT C062
154 No Current Listing
• KENMORE AVE CONTINUES
158 Braun Donald G [5] 716-834-6060
WEISS NORMAN J OD optometrists od 716-464-1721
166 HALT GRAPHIC DESIGN graphic designers 716-836-4439
170 Ilardo Laurence R [6] 716-832-4815
174 Piparo Joseph A [13] 716-834-6189
Piparo Chris M 716-834-6189
180 Ⓓ Singh Indrajeet
Singh Anuroop
186 - 190 No Current Listing (2 Hses)
192 Ⓓ Heary John F
198 No Current Listing
200 GET NOTICED PROMOTIONS promotions & fund raising 716-668-8152
Miller Breckglyn R [7]
202 Ⓓ Buckman Christopher C
Rogers-Wilson James H [14]▲ 716-836-6710
204 Lelito Kevin K [34]▲
206 - 218 No Current Listing (3 Hses)
222 Gisel Barbara E & John C [29]▲ 716-832-8647
228 No Current Listing
232 Molle-Poppleton Lisa M [10]▲
240 BOULEVARD HAIR CARE beauty salons 716-832-1060
Wallace Bret A [10] 716-836-0688
2 Moore John J [11] 716-838-6509
242 NATURAL HEALTH CONNECTION health serv 716-837-0702
248 Fowler Zachery L [6]▲ 716-440-8736
252 Dussault Wayne A [27]▲ 716-838-1810
Dussault Anjuli S 716-838-1810
254 Ⓓ Hicks Yvette
258 McDermott Kathleen A [3]
262 Ⓓ Marlett Kathleen I
268 No Current Listing
270 Henry Ruthann M & David C [4]▲ 716-836-2050
274 Rucker Laquita E [26]▲
Rucker Ashley
276 Fanara Jennifer B [18]▲
280 Muscato Joseph P & Pauline P [12]▲
286 Macaluso Linda A [15]▲
290 Brabson William E Jr [13]▲
292 Miller Beth M & Shawn W [11]▲ 716-836-1211
298 Dombrowskas Brian A [15]▲ 716-831-1402
Dombrowskas Noel M 716-831-1402
300 No Current Listing
304 WALSH GEORGE E clergy 716-835-2943
308 Clemo Brian J & Denise A [20]▲ 716-834-6041
310 Godleske Thomas J & Cheryle A [30]▲ 716-835-5693
316 Demars Michael J II [14]▲ 716-833-7101
320 Richardson Mark R [21]▲ 716-838-1658
Richardson Dawn M 716-838-1658
324 Girard Clement J [10]▲
328 Kindron David J & Linda J [22]▲
330 No Current Listing
334 O'Brocta Louis J [48]▲ 716-835-0740
338 Solka Alfrieda T [7]▲ 716-832-1444
342 Lundquist Robert D [45]▲ 716-836-2130
Lundquist Thomas K 716-836-2130
344 HEWSON ROBERT A DPM podiatrists 716-833-8094
WRIGHT SUSAN M DPM podiatrists 716-833-2680
354 DAIRY STORE dairy products- retail 716-836-8690
• CAMBRIDGE BLVD INTERSECTS
358 Wheeler Micky [20]▲ 716-832-0989
Wheeler Mary A 716-832-0989
362 Ruffino Robert J & Joan E [16]▲ 716-832-7435
370 Lam Shek S [12]▲
Lam Vicki W
378 Marter Gerald [40]▲ 716-834-2058
382 Crist Georgina M [28] 716-835-3181
386 Franklin Clarence D & Susan B [30]▲ 716-832-7766
390 Ⓓ Hart J 716-836-9484
Hart Gladys J 716-836-9484
394 Kelleher Thomas M & Theresa Y [20]▲ 716-835-3486
396 No Current Listing
398 Barnes Timothy D [23]▲ 716-836-0337
Barnes Thomas L 716-836-0337
406 Gantz Karen E [4]
410 Yager Gail E & William T [17]▲ 716-836-8494

NIAGARA FALLS BLVD Cont'd

414 Stringfellow Ray P [8]▲
Stringfellow Jenniler
418 Garner Joseph A [13]▲ 716-831-0037
422 BOYD JACKLIN VIOLINS musical instruments-dlrs 716-837-1684
JENEANES HAIR CTR hair replacement 716-834-0051
• PAIGE AVE BEGINS
SCHWARTZ MICHAEL DDS dentists 716-835-3906
424 Bashski Phillip [2]▲
SWEENEY'S GARAGE auto rpr & serv 716-832-0648
442 S & E JEWELERS jewelers-retail 716-832-1595
S & E TV & ELECTRONICS television & radio-serv/rpr 716-832-1597
446 Lee Carrie M [2]▲
450 MULTI PLAYS website design serv 716-835-5446
462 NELSON'S PLUMBING plumbing contractors 716-833-4153
RENTAL CITY INC rental serv- stores & yards 716-833-4818
466 Ⓓ Alston James 716-834-4541
FERNANDO SANTHI MD physicians & surgeons 716-835-0460
474 AFTER 50 newspapers 716-832-9300
Ataullah Syed [2] 716-832-1050
FROHE ADELE N attorneys 716-834-5322
HAQ SYED EAJAZ MD physicians & surgeons 716-833-3697
SYED ATTAULLAH MD physicians & surgeons 716-832-1050
• CHALMERS AVE INTERSECTS
482 CAMEO'S restaurants 716-832-2790
Wiepert Thomas [10]▲ 716-838-3713
500 DIP & DIVE diving instruction 716-837-3483
512 SAIGON BANGKOK RESTAURANT restaurants 716-837-2115
528 No Current Listing
536 LAKELAND SUPPLY INC auto parts & supl- whol 716-834-2776
540 LINCOLN PARK PHARMACY pharmacies 716-832-7800
R S DAILY GROCERY LLC grocers-retail 716-833-3712
546 BIG JOHN'S SUBMARINE & PIZZA restaurants 716-836-4881
• DECATUR RD INTERSECTS
• ZIP CODE 14223 CAR-RT C046
564 Ⓓ Girard James▲
570 No Current Listing
580 Fix Joan W [42]▲
Fix Kevin W
588 Lunney Dennis M & Melissa A [14]▲ 716-833-8971
594 Diamond Anthony A & Norine D [28]▲
600 Sunga Mitzi P [9]▲
608 Luzak Rosemary L [16]▲
616 No Current Listing
624 Bartley John I [30]▲ 716-832-4645
628 Melchiorre Christine G [15]▲ 716-833-4602
634 Mobley Gladys M [41]▲ 716-832-6433
Mobley Joan 716-832-6433
640 Wolff Marian H & Paul A [40]▲ 716-833-0154
644 Liscavage Robert S [25]▲ 716-835-9609
Liscavage Leona E 716-835-9609
650 Eaton Dolores E [40]▲ 716-832-8987
Eaton Wendell L 716-832-8987
654 Horbowicz Jeffrey J & Denise [17]▲ 716-835-7255
• LINCOLN PARK DR INTERSECTS
664 Israel Danielle M [12]▲ 716-831-1352
Israel Chad R 716-831-1352
668 Frazier Melvin J [12]▲
670 Kirbis Robert W Jr & Mary B [30]▲ 716-835-8819
674 Ranney Gary L [33]▲ 716-835-1198
Ranney Charles L 716-835-1198
678 Zimmerman Richard H [18]▲ 716-803-1395
Zimmerman Bree A 716-803-1395
684 Pray Donald P & Carole J [40]▲ 716-832-7793
688 Ⓓ Bonillas-Thompson Angelica▲
694 Ⓓ Bisher Douglas M
Shadle Tina [2] 716-834-4680
698 Giambrone Andrew E [4]▲ 716-833-5535
Giambrone Dianna 716-833-5535
704 Ⓓ Mack Kristina▲
710 Blom Robert G & Carol D [44]▲ 716-835-8447
716 Francken Timothy M & Kathleen I [14]▲ 716-836-8671
722 Zanelottie Richard J [5]▲ 716-833-1731
Zanelottie Wendy M 716-833-1731
728 Janus Lutz J & Margaret G [33]▲ 716-836-8212
738 Dickey Ronald G & Robin L [22]▲ 716-446-1833
• HIGHLAND AVE INTERSECTS
748 Powell Arlene P [27]▲ 716-837-1397
Powell Jeffrey S 716-837-1397
758 CHAMBERS & CHAMBERS accountants 716-833-3409
Chambers Gary M [24]▲ 716-835-9633
770 Battista Ellen [4] 716-833-8184
GREAT LAKES PHYSICAL THERAPY phys therapists 716-833-8152
PAIN TREATMENT CONSLNTS-W NY nurses- practitioners 716-833-8184
• HARRISON AVE INTERSECTS
782 TANGEN DAIRY PRODUCTS INC ice cream parlors 716-834-2447
796 BERRYMAN KATHLEEN career & vocational counseling 716-832-1434
Stumiola Frank M [12]▲ 716-832-1434
TEAM Q EMPLOYEE ASSISTANCE psychologists 716-832-1434
800 ROSIEK'S VACUUMS vacuum cleaners- household-dlrs 716-837-0442
• MOORE AVE INTERSECTS
804 TRAN NAIL SUPPLY INC manicuring 716-836-4336
820 NOCO INC convenience stores 716-832-0810
828 A FREEDMAN ELECTRICAL CONTR electric contractors 716-833-0940
BARRY'S HAIR CTR hair replacement 716-833-2121
850 SUNG'S ORIENTAL GROCERY & GIFT oriental goods 716-836-3611
860 KENILWORTH ELECTRONICS CO radio communication equip/sys 716-837-6666
874 CORSI AUTO BODY & GLASS INC auto body- rpr & painting 716-835-2455
Klaskala Mark [11]▲

STREET GUIDE

s, and Business Credit Reports on-line and other Polk City Directories @ www.citydirectory.com

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 2008

NIAGARA FALLS BLVD

NIAGARA FALLS BLVD Cont'd

900 PEARCE & PEARCE CO apartments 716-833-6600
910 DAVID PHOTO SVC photo finishing- retail 716-835-4620
DPS VIDEO records tapes & compact discs 716-835-4635
920 STARR HAIR WORKS beauty salons 716-833-1919
926 SUN CITY FURNITURE WAREHOUSE furniture-dlrs- retail 716-834-7400

+ EGGERT RD BEGINS

934 MONRO MUFFLER BRAKE & SVC mufflers & exhaust sys-engine 716-838-6400

+ SHERIDAN DR INTERSECTS

BUSINESSES 50 HOUSEHOLDS 102

NIAGARA FALLS BLVD (NORTH TONAWANDA)

• ZIP CODE 14120 CAR-RT C011

642 De Mart Michael A Jr & Marcia A [16]▲
648 Heller Joanne M & Richard F [15]▲ 716-695-2008
654 Saunders Terry L [9]▲
664 MANFREDI INSURANCE insurance 716-693-2850
672 ASTI ANTIQUES antiques-dlrs 716-694-4661
682 Bracken Phyllis M [30]▲ 716-693-0831
Gibbs Raymond [7]
686 No Current Listing
692 Granto Gerald C [7]▲ 716-693-2817
Granto Anne N 716-693-2817
696 Wiechec Sophie D [9]▲ 716-693-9096
Wiechec John F 716-693-9096
700 Weaver Joyce L [20]▲ 716-693-0684
700 1/2 Sentz Arthur J [10] 716-695-6027
706 Drdul Joseph R Jr & Holly A [12]▲
711 GRAY LINE nonclassified establishments 716-693-0774
712 AQUINO FINANCIAL SVC financial advisory serv ..716-694-7728
716 HAICK ACCOUNTING SVC INC accountants 716-695-9542
730 Zimmerman Lorry F [24]▲ 716-693-4222
Zimmerman Wallace G 716-693-4222
748 TIM HORTONS doughnuts 716-692-8630

• ZIP CODE 14120 CAR-RT C037

770 GILCHRIST RHONN marriage & family counselors ..716-833-8314
778 AMERICAN FREIGHT transportation consultants 716-695-2500
908 A & A INSURANCE SVC insurance 716-692-1696
AAA TRUCK & VAN LETTERING advertising 716-774-0414
ACHIEVEMENT PRODUCTS genl merchandise- retail 716-693-0139
ALL DAWGS ACADEMY pet training 716-743-0988
APTEC NUCLEAR INC nonclassified establishments 203-238-2351
BLACK LABS INC mach 716-695-6455
BOOK OUTLET book dlrs-retail 716-743-2795
BUFKOR INC display designers & producers 716-693-3223
CARDON REHABILITATION PRODUCTS physicians & surgeons equip 716-297-4210
COMMERCIAL FABRICS hot tubs & spas- supl/parts 716-694-0641
DEERWOOD DOOR INC doors-rpr 716-694-3797
DOC'S ARCHERY SALES & SVC archery equip/supl 716-693-2703
ERIE ENGINEERED PRODUCTS INC plastics 716-694-2020
FINANCIAL RECOVERY CTR financial advisory serv 716-213-0914
FOUR SEASONS SUNROOMS sun rooms solariums atriums et 716-694-8492
IRR SUPPLY CENTERS INC heating equip & sys ..716-694-4800
JACOBS LADDER EXERCISE mfrs 716-692-1455
JAECE INDUSTRIES physicians & surgeons equip ..716-694-2811
KRESSES & PIASECKI nonclassified establishments 716-693-4792
NOVA STAR HOME MORTGAGE real estate loans 716-692-7007
OH MY DOG DAY CARE child care serv 716-957-3103
PABST BREWING CO brewers 716-743-0550
PERA REAL ESTATE & INSURANCE real estate ..716-692-5555
PRACTICE MANAGEMENT CTR insurance 716-692-3302
PROLINE SOLUTIONS GROUP LLC nonclassified establishments 716-695-8705
Sherwood Jennifer A [4]
SPORTS CAGE INC amusement & recreation 716-695-3275
TRADESHOW DISPLAY CO graphic designers 716-693-0802
TSK ELECTRONICS INC communications equip 716-693-3916
VISIONARY BATHS & MORE BY IRR plumbing fixtures & supl-whol 716-692-3200
WURCO INC phonographs- coin operated 716-694-6247
WURLITZER INDUSTRIAL PARK INC industrial parks 716-692-1600
WURLITZER PIZZA CO restaurants 716-694-4799
992 MIKE REXFORD TIRE & SVC auto rpr & serv 716-693-1558
1014 Ø Andruszko Andrew L▲
1026 Aldridge Karen F [23]▲ 716-694-8790
1034 Raines Amy E [17]▲ 716-692-4369
1038 Andrzejewski Eugene I & Carol A [3]▲ 716-743-7906
1042 Werth James J [9]▲ 716-692-1046
Werth Mark A 716-692-1046
1048 Brosius Paula D [5]▲
Brosius Dawn A
1054 Wagner Robert E & Phyllis J [16]▲ 716-695-2157
1060 WILSON FARMS convenience stores 716-692-7271
1086 Krull Roger W & Linda L [5]▲ 716-694-8674
1102 Strzyz Ronald E & Barbara H [29]▲ 716-693-0619
1106 Goodrich Thomas S [5]▲ 716-695-0550
1110 Lavalley V [18]▲ 716-694-3977
1124 Miles Barbara A [30]▲ 716-694-5838
Miles Kathryn E 716-694-5838
1128 Rowles James P & Joanne M [30]▲ 716-694-3857
1134 Werth Mark R & Kathy A [30]▲ 716-692-6183
1144 Gassman Amy M [5]▲
1166 BON'CHAZ beauty salons 716-694-1166
Giammusso Charles B [18]▲ 716-695-5799
Giammusso Calogero 716-695-5799
1182 HAYAT MOTEL hotels & motels 716-694-0360

• ZIP C

This directory is property of Polk City Directories. Unforma
on the title page of this directory.

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 2008



188

NIAGARA FALLS BLVD Cont'd NIA

00 Patel Mahendra J & Kala M [6] ▲ 716-695-3391 326
20 1200 B-COZY MOTEL hotels & motels 716-695-3437
35 • ZIP CODE 14120 CAR-RT C010
19 2880 ALDER CREEK MUSIC musical instruments-rpr ..716-693-5456 326
CANNONBALL AUTHORIZED DEALER musical instruments-dlrs
00 .....716-693-5456 327
Mackowski Robert J [4] 327
e 2884 No Current Listing 328
00 2888 Porter Edrema [5]
2890 Douglas Schultz 329
02 Joseph Wittmann Jr
WHEATFIELD PEDIATRICS physicians & surgeons
.....716-807-7337 329
Wittman Joseph C Jr [4] 716-807-7337 329
2904 A SUNRISE LIMOUSINE SVC limousine serv 716-695-1260 330
08 Stepien Renee M [3] 716-990-8675
Topolski Richard S
50 2910 THRUWAY FASTENERS INC screws 716-694-1434
61 2921 Serbert Roy A [15] ▲ 330

Target Street	Cross Street	Source
-	✓	Polk's City Directory

KENMORE AVE 2004

135 KING WAY FASHION ACCES
jewelers-whol 716-836-9377
BUSINESSES 3

KENMORE AVE (BUFFALO)
+ MAIN ST CONTINUES
• ZIP CODE 14226 CAR-RT C007
39 TAYLOR PERSONNEL SVC
employment contractors
.....716-837-8100
+ WINDERMERE BLVD ENDS
63 HUDECKI GREGORY E DDS dentists
.....716-834-2744
SYED ATTAULLAH MD physicians &
surgeons 716-832-1050
+ CAPEN BLVD CONTINUES
95 Martin Ann 16 ▲ 716-833-1479
+ CAPEN BLVD INTERSECTS
99 Krestos Michael A & Mary 17 ▲
.....716-832-9971
+ ALLENHURST RD INTERSECTS
135 Napier Kandie K 9 716-836-9377
Stevens Michael G 9 ▲
.....716-836-9377
140 Francavilla Vincent J & Susan M 20
▲ 716-835-6966
FRANCAVILLA VINCENT J DDS
dentists 716-835-6966
143 No Current Listing
156 MC MAHON AGENCY insurance
.....716-837-3943
+ NIAGARA FALLS BLVD INTERSECTS
BUSINESSES 5 HOUSEHOLDS 6

KENNEDY CT (LANCASTER)
+ CENTRAL AVE ENDS

Target Street	Cross Street	Source
-	✓	Polk's City Directory

KENMORE AVE 2004

251 Kaspar Kent R ▲ 716-833-5773
+ HIGHLAND AVE INTERSECTS
HOUSEHOLDS 84

KENMORE AVE (BUFFALO)-FROM 99 N PARKER AVE
+ NIAGARA FALLS BLVD CONTINUES
• ZIP CODE 14223 CAR-RT C069
187 Jerzewski Aaron 716-833-9751
Stiles Kelleen J [3]
1 - 2 No Current Listing (2 Apts)
189 WILLIAM L LONG & ASSOC architects
.....716-833-1873
191 Brenner Robert J & George [20] ▲
.....716-833-4968
193 Rozek Kenneth P & Jane M [20] ▲
.....716-834-2169
+ LARCHMONT RD ENDS
197 Magyar Susan L [15] ▲
Magyar Renee
1 - 2 No Current Listing (2 Apts)
199 Fortson Michelle 716-837-4607
205 EMPORIUM HAIR DESIGN beauty salons
.....716-832-6558
210 Labruna Anthony S & Sharon R [20] ▲
214 Mahoney Thomas E [14] 716-831-0930
217 Dyson Alicia 716-824-2248
Sun-Palozzi Sherry F ▲
218 No Current Listing
225 Schmidt Laura J [8]
Schmidt Jeremy P
Stutzman Magdaline 716-875-2694
229 Werder Catherine L & Paul K [20] ▲
.....716-835-3452
WERDER CHIROPRACTIC OFFICE
chiropractors dc 716-834-7974
233 Czaplicki Augustina A [8]
Czaplicki Chris A
1 - 2 No Current Listing (2 Apts)
237 Nesselbeck Norman B & Betty R [20] ▲
.....716-834-8552

396
401
410
416
417
465
487
500
501
535
559
563
567
571
583
589
593

lk City Directories. It is leased for the personal use of the

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAIN ST 2004

208

MAIN ST Cont'd

3118 LEEON CHINESE FAST FOOD RSTRNT restaurants 716-837-6776
3122 A KUT ABOVE THE REST beauty salons 716-446-1963
Hamdan Nasrun B [4]
Whiting Lloyd M & Joyce M [20]
.....716-838-4478
3124 HEY SARAI CONSIGNMENT & GIFT consignment shops 716-837-1488
Ⓓ Winfrey Barbara ..716-835-2668
2 Banas Michael D [8]
.....716-835-2668
3 No Current Listing
3125 LEWIS DWIGHT MD physicians & surgeons 716-834-1455
QUEST DIAGNOSTICS INC laboratories- medical 716-835-3826
3126 RAGAMUFFINS clothing-retail 716-833-1987
+ HIGHGATE AVE BEGINS
3130 Ⓓ Zaccagnino Douglas 716-834-1776
3135 REGER FUNERAL HOME INC funeral directors 716-836-9969
+ ZIP CODE 14214 CAR-RT C022
3142 Jatana Navpreet S [6] 716-446-1887
UNIFORMS 4U2 uniforms 716-835-2464
3144 - 3144 No Current Listing (3 Hses)
3151 ATM & E automated teller mach 716-835-3497
STEER-PEANUT GALLERY banquet rooms 716-838-0478
STEER RESTAURANT SALOON restaurants 716-838-0478
3152 201 - 208 No Current Listing (5 Apts)
+ CUSTER ST BEGINS
3158 TALKING LEAVES INC book dlrs-retail 716-837-8554
3160 STIMULANCE coffee shops 716-834-8207
3162 Ⓓ Gallimore S 716-831-0713
100 - 200 No Current Listing (2 Apts)
300 Miki Yukari [4]
400 Rossiello Elizabeth A [3]
.....716-836-5355
500 - 600 No Current Listing (2 Apts)
3164 GINSENG UNLIMITED health & diet foods-retail 716-838-0707
3168 ESCAPE HAIR DESIGNS beauty salons 716-834-1559
3171 SAL'S PIZZERIA restaurants 716-835-4718
2 - No Current Listing (2 Apts)
3172 JUST PIZZA restaurants 716-831-9979
3173 Baron Jason B [7]
V W SPLASH convenience stores 716-832-8050
3178 No Current Listing
+ NORTHRUP PL BEGINS
+ W NORTHRUP PL INTERSECTS
3182 Ⓓ Kent Cory 716-834-8808
3184 QUEEN CITY BOOK STORE comic books 716-833-6220
3189 ST JAMES MISSIONARY BAPT CHR churches 716-446-0948
3191 Metcalf Marc H [6]▲
3193 Case Melissa [3] 716-862-0871
2 No Current Listing
3198 FRANK'S MOBIL-ON THE RUN serv stations- gasoline & oil 716-836-5337
3199 MOLLY'S PUB INC restaurants 716-836-6559
3208 PARKSIDE CANDY CO candy & confectionery-mfrs ..716-833-7540
3210 CRISIS PREGNANCY CTR pregnancy counseling serv/info 716-833-7100
Francis Kevin M [5] ..716-833-3441
POLISH ARTS CLUB OF BUFFALO clubs 716-837-8879
3214 CHAYBAN CUSTOM TAILORING tailors 716-833-5049
3216 Ardmore Obrien [7] ..716-834-1000
MAIN STREET STYLES beauty salons 716-833-4846
PARLATO-O'BRIEN REALTY INC real estate 716-835-1020
+ W WINSPEAR AVE BEGINS
+ WINSPEAR AVE BEGINS
3218 COLLEGE LAUNDRY SHOPPE laundries-self serv ..716-833-0060
1 - 2 No Current Listing (2 Apts)
3223 RENAISSANCE STUDIOS tattooing 716-831-0586
3225 Quaning Felicia [3]
3229 BUFFALO PICTURE FRAME & MIRROR picture frames-mfrs 716-838-3800
3230 GREEKS & SNEAKS book dlrs-retail 716-833-4913
Maldonado John Jr [6]
1 - 4 No Current Listing (4 Apts)
+ MERRIMAC ST INTERSECTS
+ SUTTON LN INTERSECTS
3233 CANTALICIAN CENTER-LEARNING schools ..716-833-5353

MAIN ST Cont'd

Patricia Mary [18]
3234 AMY'S PLACE restaurants 716-832-6668
Ⓓ Danson Ted 716-833-0265
PAVILION INTERNATIONAL gift shops 716-834-8310
3236 MUSIC CITY musical instruments-dlrs 716-838-4547
3240 HUBER B nonclassified establishments 716-832-6355
O'CONNELL LUCAS CHELF INC clothing-retail 716-836-4140
3242 GLORIA J PARKS COMMUNITY CTR social serv & welfare org 716-832-1010
UNIVERSITY HGTS COMMUNITY CTR non-profit org ..716-832-1010
+ HEATH ST INTERSECTS
3258 AMAK HEALTH CARE AGENCY home health serv 716-832-0875
3260 COFFEE BEAN CAFE coffee shops 716-837-2328
1 - 2 No Current Listing (2 Apts)
3 Dejesus Leticia [8]
4 - 5 No Current Listing (2 Apts)
6 Potter Kerry J [3]
6 Ⓓ Rabuffo Alexandria 716-860-4018
3264 THIRD BASE bars ..716-833-1284
3264 1/2 1 - 2 No Current Listing (2 Apts)
3268 Ⓓ Kadam Ninad C
MING CAFE restaurants 716-833-6988
ZIAD MARKET II meat-retail 716-836-7922
1 - 4 No Current Listing (4 Apts)
3269 Ledwon Jacob C [14]
N BUFFALO CATHOLIC YOUTH MNSTR churches 716-862-9801
NEWMAN CENTER SUNY/AB SOUTH churches 716-833-6649
ST JOSEPH'S RC CHURCH churches 716-833-0298
3270 P J BOTTOMS restaurants 716-833-3270
3275 ST JOSEPH SCHOOL churches 716-835-7395
+ ENGLEWOOD AVE INTERSECTS
+ ZIP CODE 14214 CAR-RT C006
3288 CHABAD HOUSE OF BUFFALO synagogues 716-833-8334
3292 Ⓓ Ziad Abdulwahab
3296 GALLIVAN RICHARD S F attorneys 716-831-2727
Verma Anshu [3] 716-833-7875
A1 - A3 No Current Listing (3 Apts)
A4 Mooney Kevin P [3]
B1 - B2 No Current Listing (2 Apts)
B3 Gugliuzza Joseph A [10]
.....716-836-7864
B4 - C2 No Current Listing (3 Apts)
C3 Savage Kathleen J [8]
.....716-833-0921
3334 GREATER BUFFALO COUNSELING CTR marriage & family counselors 716-833-5993
UNIVERSITY PRESBYTERIAN CHURCH churches ..716-836-7660
+ UNIVERSITY AVE BEGINS
3350 CHILD & ADOLESCENT TREATMENT mental health serv 716-835-4011
3362 WENDY'S restaurants 716-862-3511
+ NIAGARA FALLS BLVD INTERSECTS
3382 SUBWAY SANDWICHES & SALADS restaurants 716-834-6878
3400 10TH HOUSE DESIGNS website design serv 716-834-7175
Ⓓ Glamos Victor 716-832-7336
MILITELLO'S LUGGAGE luggage-retail 716-833-1600
1 No Current Listing
2 Bush Jacob C & Alana M [6]
.....716-838-0426
3 - 4 No Current Listing (2 Apts)
3404 Udagawa Salvador M [20]▲
.....716-833-1484
Udagawa Cynthia A ..716-833-1484
UDAGAWA SALVADOR M MD physicians & surgeons 716-835-0641
3410 BACK TO NATURE BUFFALO INC vitamins 716-835-4779
+ ALLENHURST RD INTERSECTS
+ ZIP CODE 14214 CAR-RT C099
3435 ALLERGY CLINIC physicians & surgeons 716-829-3316
AMERICAN INSTITUTE-ARCHITECT S architects 716-829-2008
BETHEL HEAD START PROGRAM schools 716-829-3161
Brown Christopher L [6]
.....716-834-6548
Brown Twanda 716-834-6548
Ⓓ Cook Danielle S
DAVIDSON DAVID M DPM podiatrists 716-829-2070
ORINNAN ALAN MD physicians & surgeons 716-829-3555
Eastbrown Shauna M [1]

MAIN ST
ER
PR
Ⓓ
GR
HE
AS
LA
RU
ST
LO
ST
YC
SU
ME
UN
UN
UN
UN
UN
42
81
+ ZIP COD
3442 Ⓓ
6 4
A1
A1
A1
A1
A1
A5
A6
A7
A8
A9
B1
B1
B1
B1
B2
B3
B7
B8
Ap
C1
C2
C6
C7
C9
+ CAPEN
3470 TH
3480 Ma
+ WINDE
3488 W
+ KENMC
+ SPRIN
+ CALLO
BUSINES
MAIN PL
+ ZIP CO
20 MCI
90 WAL
BUSINES
MAIN PL
+ ZIP CO
350 AM
377 TA
395 RA
1110 FI
1400 M
1550 M
1800 D
2300 C

property of Polk City Directories. It is leased for the personal use of the subscriber. Use of
e page of this directory. This information changes by 60% each year. For an updated directo

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAIN ST 2004

MAIN ST Cont'd

ERIE NIAGARA REGIONAL PRTNRSHP city government 716-829-3777

Ⓓ Fraser Maryann B

GREEN LARRY J DDS dentists 716-829-2872

HEALTH CARE INDUSTRIES ASSN associations ..716-829-3888

LAMPASSO JUDITH DDS dentists 716-829-2872

RUSSO THOMAS A MD physicians & surgeons 716-829-2674

STATE UNIVERSITY-NY/BUFFALO dentists 716-829-2012

STATE UNIVERSITY OF NEW YORK schools 716-829-2204

SUNY BUFFALO DENTAL MEDICINE dentists ..716-829-2733

UNIVERSITY-BUFFALO physicians & surgeons 716-829-3092

UNIVERSITY DENTAL ASSOC dentists 716-829-2853

UNIVERSITY OF BUFFALO physicians & surgeons 716-829-2846

UNIVERSITY ORTHOPAEDIC SVC physicians & surgeons 716-829-3670

UNIVERSITY PEDIATRIC DENTISTRY dentists 716-836-5595

WARUNEK STEPHEN P DDS dentists 716-829-2872

WBFO radio stations/broadcasting co 716-829-6000

WESTERN NY GERIATRIC ED CTR government offices-state 716-829-3176

42 Carter Sharone 5

611A Cajou Sheilla 3

• ZIP CODE 14214 CAR-RT C006

3442 Ⓓ Grasmick Vanessa 716-836-6676

Ⓓ Mehrghorbani Soheilla 716-836-4799

6 Ⓓ Suhr Amy E

A1 - A11 No Current Listing (3 Apts)

A12 Colleman Michael G 6

A14 Mah Rudy S 4

A14 Mah Soungah A

A15 - A4 No Current Listing (5 Apts)

A5 Lugo Adelaida 6

A6 No Current Listing

A7 Ⓓ Sherfey Rachel M 716-837-8331

A8 No Current Listing

A9 Ⓓ Mallu Kutbi 716-536-9533

B1 - B11 No Current Listing (3 Apts)

B12 Ⓓ Johnson Danielle M

B14 Dunford Robert G 9

B15 No Current Listing

B2 Walker Heather E 2 716-832-9822

B3 - B6 No Current Listing (4 Apts)

B7 Deslandes Schelly 5 716-836-2265

B8 - C15 No Current Listing (8 Apts)

C16 Warden Richard D & Renee M 10

C2 - C5 No Current Listing (4 Apts)

C6 Mao Loan S 2

C7 - C8 No Current Listing (2 Apts)

C9 Lombardi Giuseppin 5

+ CAPEN BLVD BEGINS

3470 TIM HORTONS doughnuts 716-831-3211

3480 Malolepszy Niki 7

+ WINDERMERE BLVD BEGINS

3488 WALGREENS pharmacies 716-834-7011

+ KENMORE AVE INTERSECTS

+ SPRINGVILLE AVE BEGINS

+ CALLODINE AVE BEGINS

BUSINESSES 1134 **HOUSEHOLDS 909**

MAIN PLACE MALL (BUFFALO)

• ZIP CODE 14202 CAR-RT C019

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAIN ST 2004

electric motors- controls-whol
.....716-689-3838

BUSINESSES 2

MAIN ST (AMHERST)
• ZIP CODE 14226 CAR-RT C007

3500 BUFFALO ONE-STOP nonclassified establishments 716-837-6984

CHINA KING RESTAURANT restaurants 716-837-6863

RECORD THEATRE records tapes & compact discs 716-837-2090

SALLY BEAUTY SUPPLY beauty salons- equip/supl ..716-831-3286

STARBUCKS coffee shops 716-834-8069

TOPS FRIENDLY MARKET grocers-retail 716-515-3260

WESTERN UNION money transfer serv 716-515-3240

8 HAIR PEOPLE beauty salons 716-834-9090

230 FASHION BUG women's apparel- retail 716-803-1271

280 DOLLAR TREE variety stores 716-837-6680

3540 MC DONALD'S restaurants 716-832-6221

3604 DYNAMIC ELECTRO ACOUSTICS acoustical contractors 716-836-2625

3610 UNIVERSITY MEDICAL BOOKSTORE book dlrs-retail 716-833-7131

3640 BURGER KING restaurants 716-836-2288

3781 GROVER CLEVELAND RESTAURANT golf courses-public 716-836-9919

3810 LEO M CUDNEY ROOFING SIDING roofing contractors 716-835-1433

3911 LA MANTIA ROBERT S MD physicians & surgeons 716-833-3366

3931 X-CEL AUTO & TRUCK REPAIR auto rpr & serv 716-838-2751

3947 BILVI FOOD SVCES INC restaurants 716-837-1630

3951 EDGERTON MIRA DDS dentists 716-836-7250

HABERMAN PATRICIA A DDS dentists 716-836-5252

3955 VISUALEYES opticians 716-832-3452

3957 VIDEO RESOURCE ASSOC video production & taping serv 716-833-5150

3961 WORKSHOP beauty salons 716-836-8203

3963 BEAD GALLERY beads 716-836-6775

3980 ST BENEDICT'S EXTENDED DAYCARE schools ..716-838-3439

• ZIP CODE 14226 CAR-RT C014

4100 BOULEVARD ELECTRIC electric contractors 716-646-4950

4178 STATE FARM INSURANCE insurance 716-832-0003

4209 KATHLEEN'S ON MAIN beauty salons 716-837-1169

4301 AMHERST CENTRAL HIGH SCHOOL schools 716-362-8100

4363 HUNT REAL ESTATE CORP real estate 716-832-4838

• ZIP CODE 14226 CAR-RT C024

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 2004



+ RIVER RD INTERSECTS
BUSINESSES 263 HOUSEHOLDS 1
NIAGARA FALLS BLVD (BUFFALO)
+ MAIN ST CONTINUES
• ZIP CODE 14214 CAR-RT C006
2 Bandyopadhyay Sauraz [2]
.....716-835-2
1 - 6 No Current Listing (6 Apts)
22 Patton Alfonia L [10] ♠ ..716-446-6
37 Ⓓ Cutolo Mark 716-833-2
38 Gaglione Mariano C [20] ♠
.....716-835-7
Gaglione Anna R 716-835-7
40 Sansone Christopher J & Julie E [8] ♠
.....716-837-7
41 Ⓓ Newman John C ♠
42 Sangwan Karma V [8] ♠
43 Dugan John T III [8] ♠ 716-833-8
45 Muldrow Mattie M [20] ♠
.....716-832-6
46 No Current Listing
47 Pachla Mary R [8] ♠
Pachla Michael R
50 Newberry Wilma J [20] ♠
.....716-835-0
54 Metzger Michael M & Erika A [20] ♠
+ PELHAM DR INTERSECTS
58 Brace Frederick E Jr & Kathleen L [20]
♠ 716-833-2
62 Kowsky Francis R [20] ♠
.....716-836-6
Kowsky Helen 716-836-6
65 McCraty Elner J [19] ♠ ..716-832-2
66 Klein Peter M Sr & Rose M [20] ♠
.....716-837-9
69 Ⓓ Madeja Emily J
70 Kogler Susan M [20] ♠
Kogler Alexandra C
73 Conti Joan N [13] ♠
74 Onorato Victoria A [20] ♠
.....716-833-9
77 Walls Gerald W Sr & Dalonda M [11] ♠
78 Privateer Christoph A & Karen D [11] ♠
81 Thomas Johnny M [9] ♠
82 Davis Betty F [8] ♠ 716-837-7
85 Maguire Sylvia J [20] ♠ ..716-832-4
86 Leising Peter C & Jeanne [14] ♠
89 Tabone Thomas P & Diane L [20] ♠
.....716-838-5
90 Ⓓ Nieman Donald H & Elaine D ♠
.....716-837-0
95 Dunn Richard [8] ♠
96 Rissel Dorothy A [15] ♠ ..716-835-8
97 Simmons Lorayne D [19] ♠
100 Beggs Donald W & Lillian R [20] ♠
.....716-833-7
101 1 - 2 No Current Listing (2 Apts)
104 Coppola Joseph A & Ruth A [8] ♠
.....716-833-9
105 Alexander Pamela [20] ♠
.....716-833-3
+ BELLEVUE AVE BEGINS
109 Black Kenneth H [10] ♠
112 Burgin Ernst K & Patricia I [20] ♠
.....716-832-1
115 No Current Listing
116 Kuehn Kristin S [3] ♠ ..716-835-0
119 Gerstein Justin H [3] ..716-837-5
Gerstein Robert H 716-837-5
120 Davis Aubrey F [20] ♠
123 Woodrow Benjamin F & Colleen F
[17] ♠
124 Cirrito Frank A [14] ♠ ..716-835-3
Cirrito Roseann 716-835-3
o the Terms of Use appearing

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 2004

@ NEW NEIGHBOR

NIAGARA FALLS BLVD Cont'd

127 Lamm Steve H & Amy 2 ♠
.....716-832-9519

128 Then Philip J & Charmaine L 20 ♠
.....716-836-8140

131 Herod Michael J & Bridget B 16 ♠

132 Curtis Florence H 20 ♠
.....716-835-1747

136 Comell James R 2 716-838-1678

142 HULICKA IRENE M PHD
psychologists 716-836-9441

• KENMORE AVE INTERSECTS

BUSINESSES 1 HOUSEHOLDS 56

NIAGARA FRONTIER FOOD TERMIN
(BUFFALO)

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 2004

3421 WHEATFIELD MINI-STORAGE
storage- household & commercial
.....716-693-0463

BUSINESSES 202

NIAGARA FALLS BLVD (BUFFALO)
+ KENMORE AVE INTERSECTS
• ZIP CODE 14226 CAR-RT C001
165 - 171 No Current Listing (2 Hses)
177 KAM JOSEPH J DC chiropractors dc
.....716-835-5400
179 Cody Ruth A [4] ▲ 716-834-3082
189 Feuerstein Marvin E [20] ▲
.....716-837-6586
Feuerstein Michael S ..716-837-6586
195 - 199 No Current Listing (2 Hses)
207 Tudor Sorin [4] 716-838-2915
213 Larson David I & Beth E [3]
.....716-836-9704
219 Ⓓ Beideck Joshua E ▲ 716-835-1525
225 Fiorella Robert V [20] ▲
.....716-833-4579
231 Samulski Paul A & Judy L [17] ▲
.....716-838-1155
237 Ⓓ Poras Richa 716-833-3243
Ⓓ Watson Chris M
249 Kij Brenda P [12] ▲
255 McNeill Leeann [2] 716-833-1954
261 Schmidt Martha C [20] ▲
267 Johnson David Sr [14] ▲
.....716-836-2643
Johnson E 716-836-2643
273 Ⓓ Steffan A 716-833-3078
279 Gianiodis Andrew A [12] ▲
.....716-862-0036
285 Cooper Paula A [8] ▲ ..716-834-9480
291 Mattina Rita F [19] ▲ ..716-833-4049
297 Monkhouse John J [8] ▲
.....716-832-7720
303 Pezzino Rose P [9] 716-803-1799
Pezzino Anthony 716-803-1799
309 Ⓓ Balogun Olakunle ..716-837-6255
315 Yang Patricia R [4]
321 Delles Joan M [20] 716-833-2164
Delles Lisa A 716-833-2164
327 No Current Listing
333 Caparco Joseph M Sr & Stefie [6]
.....716-831-8872
339 Poloncarz Robert A & Julie A [20] ▲
.....716-836-6030
Stilwell Ann P [16] ▲
345 Perry Bryan [2] ▲ 716-833-7277
+ CAMBRIDGE BLVD BEGINS
363 Cox Bruce H & Linda E [20] ▲
.....716-832-5633
369 Davern Susan A [16] ▲
.....716-838-9917

Get Mailing Lists, Sales Leads, and Business Cred

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 2004

245

NIAGARA FALLS BLVD Cont'd

373 Gordon Loretta L ..716-833-4927
383 Powers Tyrone
389 Stehlin Victor F ..716-832-9590
Stehlin Richard A ..716-832-9590
395 Stanley George Q & Nancy M ..716-834-0390
399 Stanley Kurt A
405 Wong Michael T
Wong Deborah C
409 No Current Listing
415 Myers Gloria J ..716-833-4606
+ PAIGE AVE INTERSECTS
423 Strade Roger J & Kelly A
429 Barnes Katherine I
435 O'Connor Peter J & Sandra L ..716-838-4351
443 Difrancesco Lisa A
453 - 459 No Current Listing (2 Hses)
465 Burnis Alice B ..716-833-2555
Burnis John J ..716-833-2555
+ OXFORD AVE INTERSECTS
479 Farrell Patricia A ..716-838-1447
Farrell Danne W ..716-838-1447
+ CHALMERS AVE INTERSECTS
489 Spasezska Irena M ..716-832-4266
495 No Current Listing
505 Wong Manuel G ..716-837-4918
513 Lesch Darrell C & Mary L ..716-838-1771
519 Saxena Bala R
Saxena Suresh B Sr
523 No Current Listing
529 Majdandzic Dragan
535 Laughlin John M ..716-836-1345
543 Paeplow Charles E ..716-836-9572
Paeplow Vivian E ..716-836-9572
549 Ashley Betty M ..716-832-0520
553 Osborne Thomasina C ..716-893-7019
Osborne Lance Sr ..716-893-7019
+ DECATUR RD INTERSECTS
559 Flint Wildrena ..716-834-4143
Flint Drena ..716-834-4143
563 - 569 No Current Listing (2 Hses)
579 Didomizio Joseph C & Annette S ..716-838-3412
+ YALE AVE BEGINS
593 Seland Keith A ..716-833-4334
599 No Current Listing
605 Daniels Craig A & Cheryl L
613 Gaughan Robert M & Alice B
619 Jacob Gladwin A & Sunita ..716-836-1271
625 Patterson Robert A & Debra M ..716-837-4687
633 Relan Sushil D & Veena D ..716-832-0223
639 Meli Raymond C ..716-837-0624
643 No Current Listing
649 Southwick Lawrence A III
653 Johnson Willard E Sr & Mary L ..716-862-0307
+ LINCOLN PARK DR INTERSECTS
659 Schall David D
663 Menchetti Joanne E ..716-832-3418
665 - 669 No Current Listing (2 Hses)
673 Platt Robert W
Platt Pamela D
+ LONGMEADOW RD INTERSECTS
+ ZIP CODE 14226 CAR-RT C034
681 CHINA MAX WOK restaurants ..716-833-8885
NEW CHINA MAX WOK restaurants ..716-833-8889
711 TRINITY UNITED METHODIST CHR churches ..716-835-7711
+ HIGHLAND AVE INTERSECTS
+ RUTH AVE INTERSECTS
771 ALLAN P MC CARTY LAW OFFICE attorneys ..716-446-0022
+ HARRISON AVE INTERSECTS
789 Imbasciati Raymond N ..716-836-1448
803 Sutherland David W
+ MOORE AVE INTERSECTS
+ BETINA AVE BEGINS
+ BETINA AVE BEGINS
843 1 - 2 No Current Listing (2 Apts)
845 Wilson B ..716-832-4824
847 Doak Douglas P ..716-833-3493
853 DREAM WERKS AUDIO & ACCESS auto radio & stereo sys ..716-836-5600
861 Wahl Philip J Jr & Cheryl J ..716-834-4312
865 Balesteri Dara
1 - 2 No Current Listing (2 Apts)
869 WOEPPEL EDWARD J CPA accountants ..716-836-3822
871 A CAREER RESUME SVC resume serv ..716-837-2798
E A SOFTWARE computer software ..716-835-2914
885 LOMBARDO FUNERAL HOMES funeral directors ..716-837-7100

NIAGARA FALLS BLVD Cont'd

899 EVERYWOMAN OPPORTUNITY CTR INC career & vocational counseling ..716-837-2260
+ EGGERT RD INTERSECTS
+ EGGERT RD INTERSECTS
+ SHERIDAN DR BEGINS
+ SHERIDAN DR INTERSECTS
+ SHERIDAN DR INTERSECTS
1009 THAI BISTRO restaurants ..716-832-2361
1101 JAMES P RICH INSURANCE insurance ..716-833-1900
Keane Carmen H ..716-837-7880
STREAKERS INC shoes-orthopedic ..716-446-5598
+ ALMEDA AVE BEGINS
+ ZIP CODE 14226 CAR-RT C032
1201 RAINBOW clothing-mfrs ..716-835-0732
1257 No Current Listing
+ ZIP CODE 14228 CAR-RT C057
1415 EVERLASTING MEMORIES music & live entertainment ..716-833-1111
1459 HARBOR FREIGHT TOOLS tools-new & used ..716-835-6435
PETCO pet shops ..716-832-2373
RAYMOUR & FLANIGAN FURNITURE furniture-dlrs- retail ..716-834-7171
+ MEYER RD INTERSECTS
1551 APPLE ONE EMPLOYMENT SVC employment agencies/opportunit ..716-835-4005
BLOCKBUSTER VIDEO video tapes & discs ..716-835-6600
BUFFALO BEACH HOUSE swimwear & accessories-retail ..716-832-9002
BURLINGTON COAT FACTORY department stores ..716-833-0554
CREATIVE SEWING CTR sewing mach- household ..716-831-1233
DOLLAR TREE variety stores ..716-837-6816
HOLCOMB'S KNOWPLACE school supl-retail ..716-838-0186
JO-ANN ETC fabric shops ..716-836-8586
LIFE RESOURCES church supl ..716-836-4001
NAIL STOP manicuring ..716-835-4631
OUTBACK STEAKHOUSE restaurants ..716-833-6067
PRICELESS KIDS clothing-retail ..716-834-6381
SUN CAPSULE PLUS tanning salons ..716-835-5178
SVS VISION optical goods- retail ..716-832-6172
SWISS CHALET ROTISSERIE restaurants ..716-837-4300
1565 LANE BRYANT department stores ..716-837-2500
1583 BED BATH & BEYOND linens-retail ..716-835-0286
1593 PAYLESS SHOE SOURCE shoes-retail ..716-835-2163
SUPERCUTS beauty salons ..716-834-7104
1645 CARRABBAS ITALIAN GRILL restaurants ..716-833-5003
1701 KMART department stores ..716-837-8080
LITTLE CAESARS PIZZA restaurants ..716-836-8362
1715 DEXTER SHOE FACTORY OUTLET shoes-retail 716-836-8575
1881 HART HOTELS HOLIDAY INN hotels & motels ..716-564-1103
+ INN KEEPERS LN INTERSECTS
1951 Hamilton Jonathan & Mimi ..716-691-6884
TRAVEL LODGE 11966 motels & hotels reservations ..716-691-9392
2001 Schiff Lawrence M ..716-564-1300
Spara David J ..716-564-3210
TXMQ computer serv 716-564-1700
WESTERN NEW YORK ASSN-PLBG associations ..716-564-8575
WILD JOSEPH CPA accountants ..716-568-1155
6 Berman Eugene S ..716-564-1300
2005 ABCO LEASING & FUNDING lease serv ..716-691-2653
2075 ORIGINAL PANCAKE HOUSE restaurants ..716-694-8219
2113 VIDEO LIQUIDATORS video tapes & discs ..716-691-3970
2153 LA NAIL SALON manicuring ..716-691-7427
LITTLE PEOPLES PARK child care serv ..716-691-5956
2185 CARMEN'S BARBER SHOP barbers ..716-691-8168
2277 Davis Donald L
Davis Esther P
2303 GARY POOLS & LEISURE swimming pool contra dlrs/desi ..716-564-4279

Business Credit Reports on-line and other Polk City Directories © www.citydirectory.com

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 2004

the Internet @ www.citydirectory.com

169 NIAGARA ST - NIAGARA FALLS BLVD

E NIAGARA ST Cont'd

1363 194 Faith Roberta C & Ronald A [7] ..716-743-1044
1363 + DOUGLAS ST BEGINS
206 OMI'S MARKET grocers-retail ..716-694-1361
214 Saj David D [5]
1817 1 - No Current Listing (5 Apts)
222 Abbott William L & Richard T [7]♠
3434 ..716-695-1640
296 TONAWANDA FOOTBALL CLINIC athletic org ..716-692-0949
2546 298 Ⓓ Dibartolomeo Benedict N & Karen L
or ..716-695-8068
1900 + STARK ST BEGINS
• ZIP CODE 14150 CAR-RT C046
5450 330 E B TROTTNOW MACH SPEC mach shops
s/ ..716-694-0600
5333 + WALES AVE INTERSECTS
1000 EXOLON-ESK CO abrasive products
8775 ..716-693-4550
+ CREEKSIDE DR INTERSECTS
BUSINESSES 13 HOUSEHOLDS 26
9539

NIAGARA FALLS BLVD (BUFFALO)
4381 • ZIP CODE 14223 CAR-RT C062
2022 154 MARACLE ENTERPRISES jewelry-rpr ..716-836-8002
166 HALT GRAPHIC DESIGN graphic designers ..716-836-4439
8547 Halt James G [8]♠
8547 Halt Shannon M
170 Ⓓ Yaeger Jeffrey ..716-833-9577
8733 3 Ilardo Laurence R [9]
4563 174 Koch Keith M & Christine M [6] ..716-832-9232
1 - 2 No Current Listing (2 Apts)
5343 3025 Piparo Joseph A [9] ..716-834-6189
3025 Piparo Chris M ..716-834-6189
9125 180 Ⓓ Ronhovdee Danielle ..716-834-8074
1 Liu Shumin [6]
1 Liu Xiao
1466 2 Agustiady Donny A [8] ..716-833-9014
2 Agustiady Dicky A ..716-833-9014
3 No Current Listing
0737 4 Yang Fang [4] ..716-831-8186
4915 186 Lebar Marie H [20]♠ ..716-833-7357
4915 1 - No Current Listing (4 Apts)
198 Ⓓ Bedin Silvia ..716-834-9331
2 Lovett-Torrence Marquetta M [8]
2530 ..716-803-1788
9098 200 Daddario Paul C [6]♠
200 Ⓓ Bryant Roslyn C
8657 202 Wilson James H Jr & Catherine P [8]
1 Rogers-Wilson James H [10] ..716-836-6710
204 Kazinski Brian D [9]♠ ..716-832-5296
1896 Lalito Kevin K [20]♠
206 Grant Rita A [18] ..716-836-5694
7015 208 No Current Listing
218 Strawbridge Justina L [9]
s 2 No Current Listing
9232 222 Ciolczak Helen K [26] ..716-833-6595
3629 Ciolczak Henry J ..716-833-6595
1 Gisel Barbara E & John C [20]♠
0949 ..716-832-8647
0949 2 - No Current Listing (2 Apts)
232 Poppleton Brian E [5]♠
Poppleton Lisa M
5843 240 BOULEVARD HAIR CARE beauty salons
1256 ..716-832-1060
Moore J [8] ..716-838-6509
8223 1-N - 2 No Current Listing (2 Apts)
3 Wallace Bret A [8] ..716-836-0688
167 242 CLASS ACT CLEANING SVC janitor serv ..716-803-1801
244 CLC INTL TRADING CO oriental goods ..716-862-9988
248 Ⓓ Harris Adia
2 Schummer David J [9]
3 No Current Listing
252 Dussault Wayne A [20]♠ ..716-836-1810
5334 Dussault Eva ..716-836-1810
254 Merchant Juanita F [3] ..716-837-4096
3584 258 Colby Jason M [5]
Colby Jill
5 Mitschang Jill M [4] ..716-834-2276
1952 262 Pragel Bernard W [20]♠ ..716-832-4352
Pragel Sheila K ..716-832-4352
268 Hodur Darrell L [20]♠
270 Ⓓ Boyle Christine L
274 Ⓓ Johnson Laquita E ♠
276 - 280 No Current Listing (2 Hses)
286 Macaluso Linda A [19]♠ ..716-836-9657
5060 290 Brabson William E Sr [6]♠
Brabson William E Jr
8099 292 Miller Beth & Shawn W [6]♠ ..716-836-1211
tting 298 Dombrowskas Brian A [11]♠ ..716-831-1402
2715 Dombrowskas Robert J ..716-831-1402
300 No Current Listing
3067 304 Walsh George E Jr & M G [20]♠
308 Ciemo Brian J & Denise A [15]♠ ..716-834-6041
4798 310 Godleske Thomas J [20]♠ ..716-835-5693
Godleske Paul M ..716-835-5693
5288 316 Demars Michael J II [19]♠ ..716-833-7101
320 Richardson Mark R [17]♠ ..716-836-1658
s 324 Ⓓ Girard James J & Clement ♠
2525 328 Kindron David J & Linda J [18]♠ ..716-837-8313
0584 330 No Current Listing
334 O'Brocta Louis J & Marylou L [20]♠
..716-835-0740
336 Solka Freida [9] ..716-832-1444
342 Lundquist Robert D & Marion H [20]♠
..716-836-2130
344 HEWSON ROBERT A DPM podiatrists
..716-833-8094
Wassinger Kathleen E [15]♠ ..716-833-7832

NIAGARA FALLS BLVD Cont'd

354 DAIRY STORE dairy products- retail
..716-836-8690
Salem Fadhel N [6]♠ ..716-832-0807
Salem Abdulnasser ..716-832-0807
358 Wheeler William J Jr & Mary A [20]♠
..716-832-0989
362 Ruffino Robert J [12]♠ ..716-832-7435
370 Chan Kenneth [8] ..716-836-1673
Chan Shuk F ..716-836-1673
378 Marter Gerald [20]♠ ..716-834-2058
382 Crist Georgina M [20] ..716-835-3181
1 - 2 No Current Listing (2 Apts)
386 Franklin Clarence D & Susan B [20]
..716-832-7766
Ⓓ Shinde Ameya ..716-836-5895
390 Barnes James D [11]♠ ..716-837-8442
Barnes Cherie ..716-837-8442
394 Kelleher Thomas M & Theresa Y [16]♠
..716-835-3486
396 Birkby John M Jr & Barbara J [12]♠
398 No Current Listing
406 Ⓓ Redenbach Brad D
410 Yager Gail E & William T [8]♠ ..716-836-8494
414 Ⓓ Stringfellow Ray P♠ ..716-832-8509
Stringfellow Jennifer ..716-832-8509
418 Gamer Joseph A [8]♠ ..716-831-0037
422 Martinez Luis [2] ..716-446-1653
SCHWARTZ MICHAEL DDS dentists
..716-835-3906
3 JENEANES HAIR CTR hair replacement
..716-834-0051
6 BOYD JACKLIN VIOLINS musical instruments-dlrs ..716-837-1684
424 Basinski Philip [20]♠
SWEENEY'S GARAGE auto rpr & serv
..716-832-0648
442 FULL GOSPEL BUSINESS MEN'S religious org ..716-832-1595
S & E TELEVISION SVC television & radio-serv/rpr ..716-832-1597
S & E WHOLESALE CORP jewelers-retail
..716-832-1595
446 Kisloski David O Jr [11] ..716-835-3886
Kisloski Linda ..716-835-3886
1 - 3 No Current Listing (2 Apts)
450 MULTI PLAYS nonclassified establishments
..716-835-4200
466 No Current Listing
474 HAQ SYED E MD physicians & surgeons
..716-833-3697
Ⓓ Petock Joseph ..716-834-9448
4 HAQ EAJAZ SYED MD physicians & surgeons ..716-833-3697
482 CAMEO'S restaurants ..716-832-2790
Wiepert Thomas [15]♠ ..716-838-3713
500 DIP & DIVE divers equip/supl ..716-837-3483
512 SAIGON BANGKOK RESTAURANT restaurants ..716-837-2115
528 No Current Listing
536 LAKELAND SUPPLY INC auto parts & supl-whol ..716-834-2776
540 LINCOLN PARK PHARMACY pharmacies
..716-832-7800
546 BIG JOHN'S SUBMARINE & PIZZA restaurants ..716-836-4881
• ZIP CODE 14223 CAR-RT C063
564 Adamczyk Jason M & Jamie [5] ..716-836-7639
570 Alvarez Rick J [8]♠ ..716-837-6416
580 Fix Joan W [20]♠
Fix Francis R
588 Lunney Dennis M [10]♠ ..716-833-8971
594 Diamond Norine D [20]♠
Diamond Aa
600 Villanueva Ester S [12]♠ ..716-862-9495
Villanueva Roberto S ..716-862-9495
608 Harrison Charles J & Rosemary L [11]♠
..716-837-4962
616 Penfield Allen J [9]♠
Penfield Anne M
624 Bartley John I & Goldie A [20]♠ ..716-832-4645
628 Melchiorre Christine G [11]♠ ..716-833-4602
Melchiorre Bart R ..716-833-4602
634 Mobley John E Jr & Gladys [20]♠
..716-832-6433
640 Wolff Marian H & Paul A [20]♠ ..716-833-0154
644 Liscavage Leona E [18]♠ ..716-835-9609
Liscavage William K ..716-835-9609
648 Heller Richard F & Joanne M [11]♠
..716-695-2008
650 Eaton Dolores E [20]♠ ..716-832-8987
Eaton Wendell L ..716-832-8987
654 Horbowicz Jeffrey J & Denise [13]♠
..716-835-7255
• ZIP CODE 14223 CAR-RT C046
664 Israel Danielle M [8] ..716-831-1352
Israel Chad R ..716-831-1352
668 Ⓓ Frazier Melvin J♠
670 Kirbis Robert W Jr & Mary B [20]♠
..716-835-8819
674 Ranney Gary L [20]♠ ..716-835-1198
Ranney Charles L ..716-835-1198
678 Zimmerman Richard H [14]♠ ..716-803-1395
684 Pray Donald P & Carole J [20]♠ ..716-832-7793
688 No Current Listing
694 Fuentes Roberto F Sr [3]
696 Wiechec John F [8] ..716-693-9096
Wiechec Sophia D ..716-693-9096
698 Griswold Jennifer B [8]♠ ..716-832-1668
700 1/2 Weaver Joyce L [16]♠ ..716-693-0684
700 1/2 Sentz Arthur J [8] ..716-695-6027
704 Janeczko William W [20]♠ ..716-834-8551
Janeczko Josephine P ..716-834-8551

orts on-line and other Polk City Directories @ www.citydirectory.com

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 2004

NIAGARA FALLS BLVD 170

NIAGARA FALLS BLVD Cont'd

710 Biom Robert G & Carol D ..716-835-8447
716 Francken Timothy M & Kathleen I ..716-836-8671
722 Zanelotti Richard J
728 Janus Lutz J & Margaret G ..716-836-8212
730 Zimmerman Wallace G ..716-693-4222
Zimmerman Lorry F ..716-693-4222
738 Dickay Ronald G & Robin L ..716-446-1833
748 Powell Arlene P ..716-837-1397
Powell Jeffrey S ..716-837-1397
758 CHAMBERS & CHAMBERS accountants ..716-833-3409
Chambers Gary M ..716-835-9633
Chambers Laurel ..716-835-9633
770 GREAT LAKES PHYSICAL THERAPY phys therapists ..716-833-8152
REHABLITATION NY physicians & surgeons ..716-833-0824
782 TANGEN DAIRY PRODUCTS INC ice cream parlors ..716-834-2447
796 BERRYMAN KATHLEEN career & vocational counseling ..716-832-1434
Sturniolo Frank M Jr
TEAM Q EMPLOYEE ASSISTANCE psychologists ..716-832-1434
800 ROSIEK'S VACUUM vacuum cleaners-household-dlrs ..716-837-0442
804 TRAN NAIL SUPPLY INC manicuring ..716-836-4336
820 NOCO INC convenience stores ..716-832-0810
828 A FREEDMAN ELECTRICAL CONTR electric contractors ..716-833-0940
BARRY'S HAIR CTR hair replacement ..716-833-2121
850 SUNG'S ORIENTAL GROCERY & GIFT oriental goods ..716-836-3611
860 KENILWORTH ELECTRONICS CO radio communication equip/sys ..716-837-6666
874 CORSI AUTO BODY & GLASS INC glass ..716-835-2455
900 PEARCE & PEARCE CO apartments ..716-833-6600
910 DAVID PHOTO SVC photo finishing- retail ..716-835-4620
DPS VIDEO video tape duplication serv ..716-835-4635
920 ACTION REALTY real estate ..716-836-9650
AMERICAN DANCE STUDIO schools ..716-834-3350
FOUR PAWS PET CTR pet washing & grooming ..716-836-0365
STARR HAIR WORKS beauty salons ..716-833-1919
926 MARTINO'S TELEVISION television & radio-serv/rpr ..716-836-7000
934 MONRO MUFFLER BRAKE & SVC auto rpr & serv ..716-838-6400

BUSINESSES 46 HOUSEHOLDS 133

NIAGARA FALLS BLVD (NORTH TONAWANDA)-FROM 1399 PIERCE AVE
• ZIP CODE 14120 CAR-RT C011
642 No Current Listing
648 Moscoe Maria ..716-743-1689
1 - No Current Listing (3 Apts)
664 MANFREDI INSURANCE insurance ..716-693-2850
672 Fatta Joseph J Jr
Fatta Phyllis J
682 Daniels John ..716-692-6774
686 Gandt Marjorie
692 Granto Gerald C
Granto Anne N
696 No Current Listing
700 Weaver Robert
Weaver Joyce L
706 Drdul Joseph R Jr & Kathleen M
711 GRAY LINE nonclassified establishments ..716-693-0774
712 No Current Listing
716 HAICK ACCOUNTING SVC INC acctng & bkpg genl serv ..716-695-9542
730 No Current Listing
+ CONNECTING BLVD INTERSECTS
+ CONNECTING BLVD CONTINUES
• ZIP CODE 14120 CAR-RT C037
770 GILCHRIST RHONN marriage & family counselors ..716-833-8314
778 AMERICAN FREIGHT furniture-dlrs- retail ..716-695-2500
+ BAISCH DR INTERSECTS
+ BAISCH DR INTERSECTS
908 AEU INC book dlrs-retail ..716-743-2795
ALL DAWGS ACADEMY pet training ..716-743-0988
BLACK LABS INC mach ..716-695-6455
COMMERCIAL FABRICS hot tubs & spas-supl/parts ..716-694-0641
DOC'S ARCHERY SALES & SVC archery equip/supl ..716-693-2703
EASTERN APPLIED RESEARCH INC research serv ..716-694-1426
ERIE ENGINEERED PRODUCTS INC metal shpng barrels drum keg/p ..716-694-2020
FIRST NATIONAL BANK-ARIZONA banks ..716-807-0228
HOPEVALE THERAPEUTIC FOSTER CR foster care ..716-695-1644
MEDICAN GROUP pharmaceutical mach ..716-692-2020

NIAGARA FALLS BLVD Cont'd

MULTI-HEALTH SYSTEMS INC nonclassified establishments ..716-842-0308
PABST BREWING CO brewers ..716-743-0550
PRACTICE MANAGEMENT CTR insurance ..716-692-3302
VISIONARY BATHS & MORE BY IRR plumbing fixtures & supl-whol ..716-692-3200
WURCO INC amusement devices ..716-694-6247
WURLITZER PIZZA CO restaurants ..716-694-4799
101 BUFKOR INC display designers & producers ..716-693-3223
105 SPORTS CAGE INC amusement & recreation ..716-695-3275
122 TSK ELECTRONICS INC communications equip ..716-693-3916
125 IRR SUPPLY CENTERS INC heating equip & sys ..716-694-4800
201 JAECE INDUSTRIES laboratory equip/supl-mfrs ..716-694-2811
203 AAA TRUCK & VAN LETTERING truck-painting & lettering ..716-774-0414
203 GRAFIX IV OF NEW YORK INC graphic designers ..716-693-0802
203 IMPRESSIVE IMPRINTS screen printing ..716-692-0905
203 TRADESHOW DISPLAY CO signs ..716-743-1379
244 FOUR SEASONS SUNROOMS nonclassified establishments ..716-694-8492
250 ACTION SERVICES process servers ..716-692-5032
256 PERA REAL ESTATE & INSURANCE real estate ..716-692-5555
262 A & A INSURANCE SVC insurance ..716-692-1696
992 MIKE REXFORD TIRE & SVC serv stations-gasoline & oil ..716-693-1558
1008 NICKEL CITY AUTO SALES auto dlrs-used cars ..716-695-7910
1014 McKnight Vantross
1026 - 1034 No Current Listing (2 Hses)
+ ARNOLD DR BEGINS
1038 Husami Elizabeth D
Husami Nizar D
1042 Werth James J & Maria T ..716-692-1046
1048 Schultz Mildred C
Schultz Mcarol C
1054 No Current Listing
1060 WILSON FARMS convenience stores ..716-692-7271
1086 No Current Listing
1102 Strzyz Ronald E
Strzyz Barbara H
1106 Goodrich Thomas ..716-695-0550
1110 No Current Listing
1124 Miles Glen A ..716-694-5838
Miles Barbara A ..716-694-5838
1128 Rowles James P & Joanne M ..716-694-3857
1134 No Current Listing
1144 Siegmann Randy
1166 BON'CHAZ beauty salons ..716-694-1166
1182 HAYAT MOTEL hotels & motels ..716-694-0360
+ MAPLE DR BEGINS
• ZIP CODE 14120 CAR-RT C010
2880 ALDER CREEK MUSIC musical instruments-rpr ..716-693-5456
2884 Boyd Thomas P
Boyd Karen A
Failing Mark ..716-694-4091
NEWBURRY ST HAIR DESIGNS beauty salons ..716-694-4528
2888 Porter Edrema
1 No Current Listing
+ WARD RD INTERSECTS
2904 Colavecchia Angela
2910 THRUWAY FASTENERS INC screws ..716-694-1434
2920 Bradt Clara E
2928 ABD ENTERPRISES INC auto body- rpr & painting ..716-692-0647
Rowles Tammy & Craig P ..716-692-4032
2934 Mallone Fred P ..716-692-1946
2942 Lamm Richard D & Susan M
2946 McGowan John F
2950 Roetzer Dana R
2956 EXECUTIVE LANDSCAPING landscape contractors ..716-693-5262
GANTZER'S GARAGE auto rpr & serv ..716-807-7777
2962 No Current Listing
2968 WOLFE'S RUN RV recreational vehicles ..716-692-2208
2972 BOULEVARD AUTO GLASS glass ..716-694-1226
Harrington Brian K ..716-695-8849
2974 - 2990 No Current Listing (4 Hses)
+ ERRICK RD ENDS
2994 - 2998 No Current Listing (2 Hses)
3005 KENDALL'S EXPRESS INC trucking ..716-691-7162
KNOLL'S MOBIL NORTH serv stations-gasoline & oil ..716-691-6447
3008 No Current Listing
3010 PIZZA HUT restaurants ..716-692-7771
3012 No Current Listing
3016 JACKIE'S PET PLACE pet shops ..716-692-3878

NIAGAR
3020 Pri
3024 ST
3030 CL
3038 - 3
3046 BR
ST
3049 FE
3050 NA
ne
3052 - 3
3060 DA
att
RC
co
+ MAVIS
+ MAVIS
3082 CA
sh
3086 Ari
3090 No
3100 R
est
3104 No
3113 WI
co
3114 No
3122 CC
vet
3125 No
3137
3145 Pal
ST
3158 Wo
3165 DY
KE
3176 LA
+ KRUE
+ KRUE
3200 E J
EL
G
TH
fin
+ NASH
• ZIP CO
3264 SA
3265 GR
no
3269 No
3270
3276 RC
3280 No
3287 CA
bt
3290 NC
ut
NU
3296 - 3
3302 DA
&
3305 EL
GL
GL
gy
3308 No
3312 OL
ne
+ KNOL
3325 IM
3328 JIM
NC
3329 Fic
Fic
3332 No
3333
Pa
RC
3338 No
3342 Ba
3349 BC
bc
Sc
3354 - 3
3376 SC
3385 HC
su
SC
er
W
et

This directory is property of Polk City Directories. It is leased for the personal use of the su
on the title page of this directory. This information changes by 60% each year. For a

Target Street	Cross Street	Source
-	✓	Polk's City Directory

KENMORE AVE 1999



HOUSEHOLDS 1

KENMORE AVE (BUFFALO)-FROM 3542 MAIN ST WEST

ZIP CODE 14226 CAR-RT C002

8 cⓃRyan Sharon 446-9603
18 Cook Diane [3] 873-7944
21 Renaldo Darlene C [2]
43 TAYLOR TEMPORARY SERVICES employment agencies..... 837-8100
47 LEONG JAMES Y E & SUSAN S eating places 837-0224
MAY JEN RESTAURANT eating places 832-5162
+WINDERMERE BLVD BEGINS
59 Not Verified
63 SYED ATTAULLAH phys..... 832-1050
HUDECKI GREGORY E dentist 834-2744
QUEST ENERGY oil gas fld svc 831-9106
71 CRUZ LOURDES F phys..... 832-3111
YU CHI-TEH phys..... 832-9888
74 Sheehan Michael J [9]+ ☗
Sheehan Adrianne M
+CAPEN BLVD BEGINS
95ⓃMartin A..... 833-1479
99 Krestos Michael A [9]+ ☗..... 832-9971
Krestos Mary..... 832-9971
113 Schohn Karen [7] ☗
117ⓃMartin M I..... 694-0954
+ALLENHURST RD BEGINS
135 GOODARE-ROSENTHAL NANCY dntst..... 862-0500
KINGWAY jewelry prec metal 836-9377
Napier Kandie G [4] ☗.... 832-4983
ⓃStevens Michael..... 836-9377
140 FRANCAVILLA VINCENT J dntst 835-6966
KAIROS INFORMATION TECHNOLOGY comp rltd svcs 729-0529
143 DOHN FUNERAL HOME funerl svc crmtrie..... 834-8128
Roberts Martin G [9]+ ☗. 832-8704
156ⓃHoock Donald L..... 837-3943

Target Street	Cross Street	Source
-	✓	Polk's City Directory

KENMORE AVE 1999



KENMORE AVE (B)

Ⓝ Hoock Raymond D 837-3943
Ⓝ Hoock William N Jr 837-3943
HOOCK INSURANCE ins agts'svcs
..... 837-3947
Ⓝ Lachut Wayne J 837-3943
2 MC MAHON AGENCY ins
agts'svcs 837-3943
163 Leong Jeffery E ♠
164 Ⓝ Macmillan C 873-8039
+ NIAGARA FALLS BLVD BEGINS
175 RALPH APPLE FOOD MARTS
grocery stores 832-8080
BUSINESSES 16 HOUSEHOLDS 18

KENNEDY CT (LANCASTER)-FROM 2

Target Street	Cross Street	Source
-	✓	Polk's City Directory

KENMORE AVE 1999

BUSINESSES 2 HOUSEHOLDS 88

KENMORE AVE (BUFFALO)-

· ZIP CODE 14223 CAR-RT C069

187 Clark M M 837-1482

189 Long William [5] ♠

LONG WILLIAM L & ASSOCS

architectural svcs

..... 833-1873

191 Brenner Jack [2]+ ♠ 833-4968

Brenner Robert J 833-4968

193 Rozek Kenneth P & Jane [2]+

♠ 834-2169

199 Illardo Laurence R 832-4815

Target Street	Cross Street	Source
-	✓	Polk's City Directory

KENMORE AVE 1999



KENMORE AVE (B)

Ricardo Laurence R [2]

1 Edelman Benjamin J [2]

862-9825

203 GATES ELECTRIC CO elec work 837-5311

205 EMPORIUM HAIR DESIGN beauty shops 832-6558

210 Labruna Anthony S [9]+

Labruna Sharon R

214 Mahoney Thomas E [9]+

831-0930

Yee Yu S [9]+ 835-0404

217 Foegen Mary J [6] 862-0815

Gerrity Michael W & Elizabeth [9]+ 837-5322

218 Willax Carol L [9]+ 833-1827

225 (N) Bordonaro S 837-2518

229 Werder Catherine L [9]+

835-3452

233 Not Verified

237 Nesselbeck Norman G [9]+

834-8552

Nesselbeck Betty R 834-8552

241 Fricano Beth A [2] 834-9125

Polley Jocelyn L [2] 834-9362

Teresi Rachelle A [3]

Whiteside Gregory L [2]

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 1999



nphys rsrch 689-3311
BUSINESSES 4

NIAGARA FALLS BLVD (BUFFALO)-
FROM 175 CREEKSIDE DR
NORTH
- ZIP CODE 14226 CAR-RT C001

165 ALMON ASSOC COMMUNICATIONS
advertisng agencies 833-3031
171 Nikolic Milos [2]
177 Not Verified
179 Hagen Eleanore V [9]+ 834-6821
189 DENTURE CENTERS OF BUFFALO
dentist 834-1133
Fuerstein Robert S [9]+
195 Puehn David [9]+ 833-6533
199(N)Melia Judy G
Melia David J
207 Nice William P & Romayne [9]+
..... 837-4457
A Epstein Ceaton C [3] ... 836-6558
207 a(N)Bonn Polina
213 A Moeser Anthony G [8] 836-3718
B Ladds Joanne S & Anthony [9]+
..... 832-6735
219 Amoroso Albert M [9]+ 835-2115
Amoroso Bert 835-2115
225(N)Felschow Paul 832-2680
Fiorella Louise F [9]+ 832-6857
Fiorella Robert 832-6857
231 Samulski Paul A & Judy [9]+
..... 838-1155
237 Tisby Ronald E & Deborah [7]
..... 838-6550
245(N)McCormick Robert
249(N)Halliman Steven A
Kij Brenda P [7]
255(N)Erway Kimberly 838-4358
261(N)Morcos F 832-0051
267 Bilbo Elson Jr [8] 834-3010
(N)Friedman Danny A
Johnson David [8] 836-2643
(N)Pease Sherry R
273(N)Vaughan K 862-0506
279(N)Gianiodis Andrew 862-0036
285 Meinkes Nan B [9]+ 833-4904
Meinkes Irving 833-4904
291 Mattina Rita F [9]+ 833-4049
1 Not Verified
297 Cooney Tina M [8] 835-9223
Cooney Michael C 835-9223
303 Pezzino Anthony [9]+
(N)Seba Joseph G
309(N)Housel David A 833-6857
315 Trautman Peter D [9]+ 832-5161
321 Delles Joan M [9]+ 833-2164
Delles Lisa A 833-2164
Lawson Jack S Jr [8] 837-2962
327 Zekas Michael J & Darcy [9]+
..... 836-0456
333 Ley Judith E [5] 834-8139
339(N)Poloncarz Robert A 836-6030
Stilwell Ann P [9]+
345(N)Wilburn Donald L
Wilburn Charles
363 Cox Bruce H & Lynda [9]+
..... 832-5633
369(N)Davern Susan 838-9917
373 Pecoraro Antonio [9]+ 833-4927
Pecoraro Loretta L 833-4927
383 Powers Tyrone [6]
389 Stehlin Kathleen A [9]+ 832-9590
395 Stanley George O & Nancy [6]
..... 834-0390

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 1999

S NEWSTEAD RD to NIAGARA FALLS BLVD

NIAGARA FALLS BLVD (B)

399 Stanley Kurt A & Lorie 832-5957
405 Wong Michael T
409 Fuentes William
415 Myers Todd M 833-4606
423 Jok Richard J 835-6358
429 John Terry A
435 Oconnor Peter J 838-4351
443 Difrancesco Lisa A
453 Jaffri Syed R 838-1035
Jaffri Rafia S 838-1035
459 Not Verified
465 Burnis Alice 833-2555
479 Farrell Danne W 838-1447
FARRELL PHOTOGRAPHY photo stdios prtrt 838-1447
483 Gagliardi Frederick J 833-5295
489 Schlager Joseph D
495 Wong Mun F & Soo 832-8347
505 Wong Allen G 837-4918
513 Leach Jon I 838-1771
Leach Mary L 838-1771
519 Saxena Suresh B & Bala
Goshtasb Nehzat
529 Bentkowski Michael E & Cynthia 835-3281
Pierrot Jaclyn S
Pierrot Jaelyn S
535 Merrill Amy S
543 Peeplow Charles E 836-9572
549 Ashley Heber 832-0520
553 Bell Russell 838-3963
559 Meyer Raymond H 832-0583
563 Pulpatt Thomas H & Katherine
569 ABBOTT PHILLIP D flr laying work 832-0949
Hylkema Kenneth R
Hylkema Donna M
579 Didomizio Joseph C & Annette 838-3412
599 Parker James A 837-5620
Wheeler Deborah P
605 Daniels Craig A & Cheryl
613 Gaughan Alice M 835-5658
619 Jacob Gladwin A & Sunita 836-1271
625 Patterson Robert A & Debra 837-4687
633 A 1 COMPUTERS comptr softwre str 834-1992
Relan Sushil D 834-1992
639 Meli Raymond C 837-0624
643 Clark Thomas R
649 Not Verified
653 Ridgeway Carmelita M
659 Elkins Kevin A & Linda 833-2586
663 Menchetti Elizabeth A 832-3418
665 Minick Howard E & Victoria
669 Not Verified
673 Platt Pamela D
Platt Robert W

- ZIP CODE 14226 CAR-RT C034

677 KORNER MART grocery stores 838-2235
Shapiro Bruce M
679 FERA'S BOULEVARD SUBS eating places 838-4545
711 JAZZYOBICS BY SUZY dance stdios'schs 836-2999
TRINITY UNITED METHODIST CHURCH religious orgs 835-7711
733 A F AUTOMOTIVE auto rpr 833-0228
Fabry Alvin H
751 HECTOR'S HARDWARE & PAINT CO hardware 832-9310
765 CHRISTIAN FELLOWSHIP BAPTIST CHURCH religious orgs 835-2899
771 MC CARTY ALLAN P atty 446-0022
773 Chainani Bonnie R
CHAINS INDIA BOUTIQUE misc apprl accy st 837-8344
775 FLASHY TOPPERS misc apprl accy st 838-3613
785 Clark J 838-6008
LINCOLN PARK MOTEL hotels & motels 837-7400
789 Branch Eugene M & Maureen
797 JOLLY JUG drinking places 836-9552
803 Sokolski Edward R 834-2337
839 SZECHUAN HOUSE OF BUFFALO eating places 838-9914
843 Caprino Maricatherine 838-9234
MAINTENANCE & MANAGEMENT ASSOC bldng maint svc 836-2111
845 Burgard Thomas G
Schultz Julia 832-0309
SENTRY APPLIANCE SERVICE elec rpr 835-2991
B Not Verified
847 Lone Shawn A 832-5964
MALIK TAILORS misc apprl accy st 862-0122
Yuhnke Linette 835-7965
861 Wahl Philip J Jr & Cheryl
865 Trabucco Michael 834-0504
869 WOEPPEL EDWARD J acct 836-3822
871 DESIRED IMAGE svc estblshmnt eqpt 834-1123
Fitzgerald Gordon C
FU MEILEE ins agts'svcs 835-7036
GORDON JAMES IMAGE MAKERS photo stdios prtrt 837-5665
LOVE LETTERS BY CYRANO scrtrl crt rpting 837-2798
899 Fox Jerome
SCHEFF & LYNETT ASSOC ins agts'svcs 832-5394
SCHEFF INSURANCE AGENCY ins agts'svcs 834-4818
SULLIVAN JAMES W legal svcs 835-2910

NIAGARA FALLS BLVD

606 Scheff Sandra 834-4818
925 U-HAUL CENTER utility trlr rntl 832-1778
951 DENNY'S RESTAURANT eating places 837-5657
995 BRIDGESTONE/FIRESTONE auto home appl str 837-9700
1009 DOC AND DENS BUFFALO TAPROOM eating places 832-6054
1021 PEP BOYS auto svcs 831-0370
1061 FLOWER BASKET flwrs frsts sppls 838-3400
1065 FIRST GOAL SPORTSCARDS gift shop 835-1553
FLOWER BASKET florists 838-3401
1089 BARNES & NOBLE book stores 834-0626
1101 RICH JAMES INSURANCE AGENCY ins agts'svcs 833-1900
Keene Carmen H 837-7880
NAIL HUT beauty shops 832-4822
Rich James P 833-1900
1145 COMPUSA comptr softwre str 831-8776
1167 Carubba Joseph P
CARUBBA COLLISION CORP auto home appl str 834-0468
1171 MIDAS MUFFLER auto exhaust rpr 837-4100
1185 BUFFALO ATHLETIC CLUB SUBURBAN mbrshp club 833-5226
Schiffhauer Robert J

- ZIP CODE 14226 CAR-RT C032

1201 SIZE 5-7-9 SHOPS womens clothng strs 835-0732
1203 FOOTLOCKER shoe stores 837-1444
1205 CITIBANK (NEW YORK STATE) state commrcl banks 837-1900
CITICORP INVESTMENT SERVICES security brkrs dlr 834-9715
1209 KOSTAS SOULAKI eating places 838-2505
T G I FRIDAYS eating places 835-6000
1213 LANE BRYANT womens clothng strs 837-2500
1215 RECORD TOWN rcd prrcrded tp st 838-1102
1217 STUARTS womens clothng strs 835-0833
1221 THIS END UP FURNITURE furniture stores 833-7375
1223 DISNEY STORE INC ctlg rtl-order hses 446-0108
1225 CARROLL M J womens clothng strs 832-6177
1225 a DRESS BARN womens clothng strs 837-4171
1229 Fentzke Pamela J
1233 GAP family clothng strs 836-8080
GAP KIDS chdrns infnt wear 836-1488
1235 AMERICAN EAGLE OUTFITTERS family clothng strs 832-1100
1239 THOM MCCANN shoe stores 836-9928
1243 CLAIRE'S BOUTIQUES wmns accy spcty st 835-4430
1247 ADVANTAGE SMARTLINK electronics 838-2158
LAUX SPORTING GOODS sptg gds'bike shp 832-2774
1251 BOULEVARD MALL BOOTERY shoe stores 832-4903
1253 DUKE SERVICES wtch clck jwlry rpr 834-4850
LITTMAN JEWELERS jewelry stores 835-4799
1255 KAUFMANNS JEWELRY DEPT jewelry stores 837-9400
RINGS & THINGS jewelry stores 837-2140
1257 NATURAL WONDERS STORE gift shop 836-4866
1259 d BODY SHOP 838-2799
1265 KAY JEWELERS jewelry stores 837-8895
1271 FLETCHER DISTRIBUTING CO ENCHANTMANTS gift shop 836-0840
1273 SPENCER GIFTS gift shop 835-8157
1275 BOMBAY COMPANY misc hsehld rtl stores 836-1331
1277 AUGUST MAX WOMAN womens clothng strs 836-2910
1279 KRASNER M womens clothng strs 674-4336
1285 EXPRESS womens clothng strs 834-5864
1289 PAYLESS SHOESOURCE shoe stores 838-1870
1291 RUBYS RESTAURANT eating places 836-4004
1293 VENATOR GROUP RETAIL CHAMPS misc apprl accy st 836-6456
1295 JENSS DEPARTMENT STORES department stores 837-1100
1303 J C PENNEY department stores 837-2100
1355 DELTA SONIC CAR WASH SYSTEMS gas stations 832-4050
DELTA SONIC DETAIL SHOP elec work 834-0897
1385 MC DONALD'S eating places 837-9255
1395 ARBYS ROAST BEEF eating places 832-5231
1401 HOME SAFETY STORE misc rtl strs 832-7233
1405 SCHUELE PAINT CO pnt gls wlpr strs 836-3871

- ZIP CODE 14228 CAR-RT C057

1459 BUFFALO FAMILY PRACTICE nrsng prsnl care 834-8820
LONE STAR STEAKHOUSE & SALOON eating places 832-7677

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 1999



+CREEKSIDE DR ENDS
BUSINESSES 13 HOUSEHOLDS 37

NIAGARA FALLS BLVD
(BUFFALO)-FROM 3379 MAIN ST NORTH
+PELHAM DR BEGINS
+KENMORE AVE BEGINS
· ZIP CODE 14223 CAR-RT C062

154 MARACLE ENTERPRISES
jewelry stores 836-8002
B Not Verified

158 WESTERN NEW YORK CENTER FOR VISUALLY IMPAIRED optmtrst 836-3250

166 Halt James G +

HALT JAMES GRAPHIC DESIGN commrcl art gr dsg 836-4439

MERRELL MIKOLS & ASSOCIATES commrcl art gr dsg 831-0869

170 Garba Fareh 831-0184

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 1999

GARA ST to NIAGARA FALLS BLVD

NIAGARA FALLS BLVD (B)

Sobieraj B D 834-8155
Sperrazza Eric J
..... 835-4701
Sperrazza Benita D ... 835-4701
2 Lee Angela T
174 Borgese Angelo & Chris
..... 446-0524
Piparo Chris M ... 834-6189
Piparo Joseph A ... 834-6189
180 Natalia Chintia ... 833-2312
Wang Jun ... 837-2893
Wang Yei L ... 832-5637
1 Not Verified
2 Agustiady Donny ... 833-9014
2 Agustiady Dicky A ... 833-9014
3 Utomo Seno ... 833-4101
4 Li Aihong
4 Zhang Yuan L
186 Lebar Marie H ... 833-7357
Polder Isabelle M ... 835-5227
Polder Cecilia A ... 835-5227
190 190 Haldankar Nitin L
192 Balaji Venkatesan
Schoenberg James ... 833-2860
L Chambers Robert
198 Chavez Felipa T
Chavez Gray F
Daddario Diane
Duncan Andrew J ... 836-9565
Gray Kevin A
Gray Felipa T
200 Hauber Andrea S
Midlam J ... 838-4865
219 Not Verified
L Homsi Gregory C
202 Donegan Kip W ... 835-4299
Halizak Kari I
Hansome Darryl ... 838-2922
Rogers Wilson James H
..... 836-6710
Wilson James H
204 Kazinski Brian D ... 832-5296
206 M & M DESIGNS busn svcs
..... 835-7256
A1 Grant Rita A
..... 836-5694
218 Cortellucci Mary
222 Barbara Gisel
Ciolczak Henry J & Helen
..... 833-6595
Gisel John C ... 832-8647
228 Bellanti Susan R
232 AMERICAN DREAM CRUISES
travel agcy ... 862-9590
Vanetten Ronald A ... 834-7851
240 Aduri Pavankumar ... 832-8165
BOULEVARD HAIR CARE
beauty shops ... 832-1060
McVaugh Judith M
1 Liu Hsin L
2-A2 Not Verified (2 Apts)
244 FASTRONICS comptr softwre
str ... 446-1245
248 Alm Rebekah ... 837-5245
Bensink Thomas P
Miller Glenn P & Harriet
..... 832-2099
1 Not Verified
3 Keegan Christopher
252 Dussault Wayne A
..... 838-1810
254 Merchant Taher ... 833-7945
258 Bald Joseph F ... 832-9909
262 Pragel Gary P ... 832-4352
Pragel Sheila K ... 832-4352
268 Hodur Darrell L
270 Greiner Keith M ... 835-1374
Greiner Kelly A ... 835-1374
274 Isenberg Edward I
..... 838-6044
KINGSBURY LEATHER
WORKS busn svcs
..... 838-6044
276 Fanara Antonio
280 Lemley Clifford F
..... 837-6029
Lemley Agnes ... 837-6029
286 Macaluso Linda A
..... 838-9657
290 Brabson William E
Brabson Sylvia A
292 Fickhesen Adrienne M
..... 837-4027
Fickhesen Richard W ... 837-4027
298 Lasky Formato Jane ... 837-6833
300 Lambert David E
304 Walsh George E Jr
..... 835-2943
Walsh M G ... 835-2943
308 Clemo Brian J & Denise
..... 834-6041
310 Godleske Thomas J & Cheryle
... 835-5693
316 De Mars Michael ... 833-7101
320 Richardson Mark R
..... 838-1658
Richardson Dawn M ... 838-1658
324 Zimpfer Helen V
..... 836-4394
328 Kindron David J & Linda
L Not Verified
334 Obrocta Louis J Jr & Marylou
... 835-0740
338 Wackowski Frieda F
..... 832-1444
Wackowski Alfrieda T 832-1444
342 Lundquist Robert D & Marion
... 836-2130
344 HEWSON ROBERT podiatrists
..... 833-8095
HEWSON ROBERT A
podiatrists ... 833-8094
Wassinger Kathleen E
..... 833-7832
354 DAIRY STORE dairy prdts
stores ... 836-8690
Salem Fadhle N

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 1999

NIAGARA FALLS BLVD 126

NIAGARA FALLS BLVD
358 Wheeler Mary A ⊡+ ♠ 832-0989
362 Ruffino Richard J ⊡ ♠832-7435
370 Ⓓ Chan Bonnie 836-2102
Ⓓ Chan Kenneth 836-1673
Lamm Shekshun S ⊡
+CAMBRIDGE BLVD BEGINS
378 Not Verified
382 Crist Georgina M ⊡+ 835-3181
Stabl Joseph ⊡+ ♠ 835-4031
Stabl Hildegunde 835-4031
386 Franklin Margaret G ⊡832-7106
Franklin Clarence D 832-7106
Ⓓ Griffo Nicholas 836-4820
390 Barnes James D & Cherie ⊡ ♠ 837-8442
Czop Linda J ⊡ ♠
394 Kelleher Thomas M & Theresa ⊡+ ♠ 835-3486
396 Birkby John M Jr & Barbara ⊡+ ♠
398 Barnes Timothy D ⊡+ ♠ 836-0337
410 Yager Robert D ⊡ ♠ 836-8494
414 Barber Edward J & Helen ⊡+ ♠ 834-3615
418 Ⓓ Garner Joseph A 831-0037
422 Berg Donald K ⊡
BOULEVARD BARBER SHOP barber shops 834-4999
BOYD JACKLIN VIOLINS musical instrmt str 837-1684
Ⓓ Lay Richard V 835-3906
LINCOLN CAB & LIMO 836-9000
SCHWARTZ MICHAEL L dentist 835-3906
TOMY TILE trz tile mrbl 831-8202
5 Holloway William A ⊡ 831-3119
424 SWEENEYS GARAGE auto rpr 832-0648
+PAIGE AVE BEGINS
442 S & E JEWELERS jewelry stores 832-1595
S & E JEWLERS jewelry stores 832-1596
S & E TELEVISION SERVICE radio tv rpr 832-1597
Starr John I ⊡+ ♠
446 James Janice ⊡+ ♠
Ⓓ Levin A D 831-1557
Ⓓ Nowicki C 836-4417
462 Mauro Salvatore V ⊡+ ♠
Mauro Ellinor A
RENTAL CITY truck rntl 833-4818
466 BOULEVARD GRAPHICS 833-2588
Ⓓ Connor A M 834-9744
474 FROHE ADELE N legal svcs 834-5322
HAQ SYED phys 773-6650
INTERNATIONAL MEDICAL RELIEF WESTERN NEW YORK mgmt cnsltng svcs 836-6092
ROYAL HOMES OF WESTERN NEW YORK BUYERS DIRECT real est agts'mgrs 838-3000
Ⓓ Syed Eajazul H ♠
+OXFORD AVE BEGINS
482 CAMEOS RESTAURANT eating places 832-2790
Wiepert Thomas ⊡ 838-3713
+CHALMERS AVE BEGINS
500 DIP-N-DIVE aptg gds'bike shp 837-3483
512 SAIGON BANGKOK RESTAURANT eating places 837-2115
528 Bolea Anthony ⊡ ♠
BOLEA V & SON reupholstry furn rpr 835-3932
536 CAR PARTS CENTER mtr vhcl spls prts 834-2776
540 LINCOLN PARK PHARMACY drug store 832-7800
546 BIG JOHN'S RESTAURANT eating places 836-4881
Ⓓ Busch Cheryl J
- ZIP CODE 14223 CAR-RT C063
564 Pazik Cynthia M ⊡
570 Alvarez Rick J ⊡ ♠ 837-6416
Alvarez Rita J 837-6416
580 Fix Joan W ⊡+ ♠ 835-1651
Fix Francis R 835-1651
586 Ⓓ Lunney D 833-8971
+YALE AVE BEGINS
594 Diamond Norine D ⊡+ ♠
Diamond Mark A
600 Villanueva Elnore ⊡ ♠862-9495
608 Ⓓ Harrison Charles 837-4962
616 Penfield Allen J ⊡ ♠
Penfield Anne M
624 Bartley Goldie A ⊡+ ♠ 832-4645
628 Melchiorre Bart R ⊡ ♠ 833-4602
Melchiorre Christine G 833-4602
634 Mobley John E Jr & Gladys ⊡+ ♠ 832-6433
640 Not Verified
644 Liscavage William K ⊡+ ♠
Liscavage Robert S
650 Eaton Wendell L ⊡+ ♠ 832-8987
Eaton Dolores E 832-8987
654 Horbowicz Jeffrey J & Denise ⊡ ♠ 835-7255
- ZIP CODE 14223 CAR-RT C046
664 Gil Lourdes E ⊡+ ♠
Gil Laura
668 Hoyt Nancy J ⊡+ ♠ 832-1204
Hoyt Carolyn 832-1204
670 Kirbis Robert W Jr & Mary Beth ⊡+ ♠ 835-8519
674 Ranney Gary L ⊡+ ♠ 835-1198
678 Poplawski Gordon S ⊡+ ♠ 832-5347
Poplawski Lorraine K 832-5347
+LONGMEADOW RD BEGINS
684 Pray Donald P & Carole ⊡+ ♠ 832-7793
688 Ⓓ Edmister Jacquelyn
694 Marino Gary ⊡
Urich Joe ⊡ 838-3177
Urich Steven 838-3177
698 Not Verified
704 Janeczko William W & Josephine ⊡+ ♠ 834-8551
710 ALUMA-WAY CONSTRUCTION CO rfng sdng sht mtl 832-2291
Blom Robert G & Carol ⊡+ ♠ 835-8447
716 Ⓓ Francken Timothy M 836-8671
Ⓓ Francklen Timothy M
Francklen Lathleen I
B Not Verified
722 Ⓓ McHugh-Ellis M 832-2855
728 Janus Lutz J & Margaret ⊡+ ♠ 836-8212
738 Not Verified
+HIGHLAND AVE ENDS
748 Powell Jeffery S ⊡+ ♠ 837-1397
Powell Arlene P 837-1397
758 CHAMBERS GARY M acctng audtng bkp 833-3409
+RUTH AVE BEGINS
770 Salinardo Nicholas E ⊡ 837-2244
SALINARDO FUNERAL HOME funerl svc crmtrie 837-2244
782 DAIRY QUEEN eating places 834-2447
796 PINO CHRISTOPHER J indvdl family svcs 832-1434
800 Ⓓ Portale Sebastian
ROSIEK'S VACUUM hshold applnce strs 837-0442
804 Not Verified
820 UNI-MARTS grocery stores 832-0810
828 BARRY'S HAIR CENTER misc apprl accy st 833-2121
FREEDMAN A ELECTRIC CONTRACTOR elec work 833-0940
+BETINA AVE BEGINS
+MOORE AVE ENDS
850 Singh Baljinder ⊡ 862-0183
Singh Tarsem 862-0183
TAJ MAHAL RESTAURANT eating places 838-5555
860 KENILWORTH ELECTRONICS CO radio tv rpr 837-6666
NIGHT LIFE MAGAZINE misc publishing 834-3348
874 CORSI AUTO BODY & GLASS auto glass rpr 835-2455
Dabb Scott ⊡
Klaskala Valerie ⊡ ♠
Klaskala Anna M
KRESSE PETER AUTO SALES used car dealers 834-0600
Mings Robert ⊡
900 PEARCE & PEARCE CO real est agts'mgrs 833-6600
908 TECH BITE INTERNATIONAL U S A prepackaged sftware 692-2745
910 D P S VIDEO svcs alld mtn pict 835-4620
920 ACTION REALTY real est agts'mgrs 836-9650
A S O D dance stdios'schs 834-3350
CENTURY 21 ACTION REALTY real est agts'mgrs 836-9650
HAIR PZAZZ beauty shops 833-1919
926 MARTINOS ELECTRONICS electronics 836-7000
+EGGERT RD ENDS
+SHERIDAN DR BEGINS
BUSINESSES 56 HOUSEHOLDS 152

NIAGARA FALLS BLVD (NORTH TONAWANDA)-FROM 3975 LOCKPORT AVE
- ZIP CODE 14120 CAR-RT C039
642 Demart Michael A Jr & Marcia ⊡+ ♠
643 Clark Thomas R ⊡+ ♠
Clark Jean S
648 Heller Richard F ⊡ ♠ 695-2008
Heller Joanne 695-2008
Snell Joanne M ⊡+ ♠
654 Ⓓ Ewald Brian 693-3446
Helmer John E ⊡
Ⓓ Ohar Megan M
664 Manfredi Ralph ⊡ ♠
MANFREDI INSURANCE AGENCY INC ins agts'svcs 693-2850
682 VILLA MOTEL hotels & motels 693-0831
686 Dahl Le V ⊡ ♠ 693-3871
692 Nantka Josephine ⊡+ ♠ 693-1441
696 Sukiennik Eugene J & Irene ⊡+ ♠ 694-7065
700 Sentz Arthur J ⊡ 695-6027
Tomak Darlene M ⊡+ ♠
Weaver Joyce L ⊡+ ♠ 693-0684
+BAISCH DR BEGINS
+CONNECTING BLVD ENDS

NIAGARA FALLS BLVD (N T)
706 Ⓓ Ordul Holly A 695-9885
711 ARTS HOUSE OF OMLETS eating places 692-4684
OVER FALLS TOURS travel agcy 692-5018
712 Ⓓ Haick Christopher W ♠ 694-7726
716 HAICK ACCOUNTING SERVICES acctng audtng bkp 695-9542
730 Zimmerman Wallace ⊡+ ♠ 693-4222
748 VICKIES DONUT SHOP retail bakeries 692-8264
- ZIP CODE 14120 CAR-RT C037
908 A A A TRUCK & VAN LETTERING pnt & bdy rpr 774-0414
ALLIED PLUMBING PRODUCTS plumb-htg sup 694-2959
APTEC NUCLEAR elec appratus equip 754-7401
BLACK LAKE gnrl indus mach 695-6455
BRANMAG elec componients 693-5994
COMMERCIAL FABRICS mfg industries 694-0641
Ⓓ Dandrea David T
DEERWOOD DOOR lumbr plywd millw 694-3797
DOC'S ARCHERY SALES sptg gds'bike shp 693-2703
DREAM POOLS busn svcs 694-1651
ERIE ENGINEERED PRODUCTS plstcs products 694-2020
GASTRO TARGET CORP phrmctcl preprtns 695-7667
GRAFIX IV OF NEW YORK advertisng agencies 693-0802
HERITAGE PIPE ORGANS musical instrmt str 743-1444
IMPRESSIVE IMPRINTS commrcl printng 692-0905
JAECE INDUSTRIES professnl equip 694-2811
M B MICROTEC U S A jwlry prcious stns 694-2605
NATIONAL INDUSTRIAL PARK nrsdntl bldg oprtrs 695-6165
NATIONAL LEAK TEST CENTER testing labs 693-0550
NIAGRA COMPUTER MARKETPLACE cmptrs periph sftw 855-6172
NORTHRUP SUPPLY plumb-htg sup 692-1600
OFFICE SPECIALTY offc furn exc wood 836-7676
REINHOLD-CHRISTIAN-FERSTER INTERNATIONAL advertising agencies 693-2580
RORES RESTAURANT eating places 694-4446
SUTHERLAND-SCHULTZ MULTI-TRADE plumb-htg-a'c 385-0534
T-S-K ELECTRONICS elec components 693-3916
TECHBYTE INTERNATIONAL prepackaged sftware 743-8052
TIDDLEDYBINKS CATERING eating places 743-9113
TRADE SHOW DISPLAY CO busn svcs 743-1379
VISIONARY BATHS & MORE BY IRR plumb-htg sup 692-3200
WARREN SOLARIUMS lmbr bldng mtrls 694-8492
WOODEN COUNTRY PLEASURE nondurable gds 695-0269
WURCO elec appl tel rad 694-6247
CANTESCO CORPORATION USA chem alld prdts 693-8206
- ZIP CODE 14120 CAR-RT C039
992 REXFORD'S MIKE TIRE & SERVICE new used car dlrs 693-1558
1014 McKnight George R ⊡+ ♠
McKnight Vantross
1026 Ⓓ Aldridge K F 694-8790
1034 Dicarlo David A ⊡+ ♠
Raines Amy E ⊡+ ♠
1038 Husami Bachar D ⊡+ ♠ 695-0570
Husami Elizabeth M 695-0570
1042 Morgan Kenneth W ⊡+ ♠
1048 Schultz Matthew M ⊡+ ♠ 692-7864
Schultz Carol 692-7864
1054 Ⓓ Wagner Robert 695-2157
1060 B S QUICK MART grocery stores 692-7271
1086 Catalano Karrie L ⊡ 694-0060
Phillips Daniel E ⊡ ♠743-8667
Phillips Donna M 743-8667
Ⓓ Weed Charles 693-3742

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 1999

NIAGARA FALLS BLVD

B Not Verified

1102 Strzyz Ronald E & Barbara [9]+ ♠ 693-0619

1106 (N) Toffalla Richard B Jr

+BELLING PL ENDS

1110 (N) Lavalley V 694-3977

SAWYER CREEK ANTIQUES used merch stores 693-0035

1124 Miles Glen A & Barbara [9]+ ♠ 694-5838

1128 (N) Rowles James P 694-3857

1134 Werth Mark R & Kathy [9]+ ♠ 692-6183

1144 Scholz Erma [9]+ ♠ ... 692-1877

+SHAWNEE RD ENDS

1166 FAMILY HAIR AFFAIR beauty shops 694-1166

(N) Giammusso C 695-5799

+PIERCE AVE ENDS

1182 Elmasarani Sami S [9]+ ♠ 695-3391

Elmasarani Souad N .. 695-3391

Saba Hiayat N [5]

1200 Zgolak Mark A [9]+ ♠

+ERIE AVE ENDS

+RAILROAD CROSSES

+KINGSTON AVE ENDS

+MELODY LN ENDS

+RAILROAD CROSSES

+OHIO ST ENDS

N

30

30

30

30

30

30

30

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAIN ST 1998

300

MAIN ST

3198 FRANKS MOBIL gas stations 836-5337
3199 MOLLYS PUB drinking places 836-6559
3208 CAMPUS ADVERTISING advertising agencies 838-2324
PARKSIDE CANDY chclte cocoa prdcts 833-7540
3210 CRISIS PREGNANCY CENTER WESTERN NEW YORK indvdl family svcs 833-7100
Hasner A 836-1255
1 Not Verified
3211 WILSON FARMS grocery stores 834-4018
3212 PARLATO-OBRIEN REALTY real est agts/mgrs 835-1020
3214 CHAYBAN CUSTOM TAILORING misc apprl accy st 833-5049
Ross Alison 837-3986
3216 A ADAM FAIRMOUNT ANTIQUES used merch stores 834-1000
Kamiet A 833-4563
Okeefe M 835-8141
Reiner Frederick 836-6683
3218 COLLEGE LAUNDRY SHOPPE cn-oprtd lndrs cln 833-0060
Rotundo Benjamin 831-3172
3225 Diebold N 446-6865
PINZONE PIZZA RESTAURANT eating places 834-3810
3229 BUFFALO FRAME & MIRROR CORP wood prods 838-3800
3230 Bloom Craig 838-8123
Goldman Paul 836-3676
SAN-BOR GREEKS & SNEAKS gift shop 833-4913
3233 CANTALICIAN CENTER FOR LEARNING elmntry scndry sch 833-5353
Wagner Rev Harold 836-5276
3234 AMYS PLACE eating places 832-6666
Farber Michael 835-8114
3236 MUSIC CITY musical instrmt str 838-4547
3240 Huber Bernhard J 832-6355
O'CONNELL LUCAS & CHELF mens/boys clothing 836-4140
3242 GLORIA J PARKS COMMUNITY CENTER schs edctl svcs 833-9874
UNIVERSITY HTS COMMUNITY DEVELOPMENT civic social assns 832-1010
3258 AMAK HEALTH CARE AGENCY home hlth care svcs 832-0875
3260 Bolton Jennifer 836-5323
Usvenes Michael 836-5323
Nambiar Sriram 834-6480
Pena Clara E 836-3428
Spiess Jason 833-3690
4-6 Not Verified (4 Apts)
3264 THIRD BASE drinking places 833-1284
3268 COFFEE BEAN CAFE eating places 837-2326
3269 Ledwon Rev Jacob C 833-0298
ST JOSEPHS ROMAN CATHOLIC CHURCH religious orgs 833-0298
3270 Monte Michael
3275 ST JOSEPH SCHOOL elmntry scndry sch 835-7395
3288 CHABAD HOUSE OF BUFFALO religious orgs 833-8334
Crowley Leo T Jr
CROWLEY L T JR ofcs clns of dntst 833-1350
3296 Clody H 834-0126
Jaeger H 833-3067
Kraig Michael 832-3745
McKenna Sean 836-4870
Tambay Pallavi Y 834-1916
A1 Epstein Daniel M 833-1751
A2-A3 Not Verified (2 Apts)
A4 Brandt Catherine M 834-9451
B1 Dworkin Norman G 832-5861
B2 Shepard Carrie W
B3 Gugliuzza Joseph A & Geraldine 836-7864
B4-C3 Not Verified (4 Apts)
- ZIP CODE 14214 CAR-RT C006
3330 UNIVERSITY PRESBYTERIAN CHURCH religious orgs 836-7660
3334 GREATER BUFFALO COUNSELING CENTER indvdl family svcs 833-5993
KIDSWORK UNIVERSITY CHILD CARE child day care svcs 836-5863
3350 CHILD & ADOLESCENT TREATMENT SERVICES spty otpnt clns 835-4011
3362 Not Verified
3400 LIFE UNIFORM & SHOE SHOP misc apprl accy st 833-2909
MILITELLOS LUGGAGE lggage lthr gds st 833-1600
Tsopelas Panagiota 836-5924
1-3 Not Verified (4 Apts)
4 Bush Mark R 832-0417
3404 Udegawa C 833-1484
3410 Horosh Mildred R 835-4779
NUTRITIONAL CENTER misc food stores
- ZIP CODE 14214 CAR-RT C099
3435 CENTRAL RDOPHARMACEUTICAL SERVICES dgnostic substances 836-5686
CUNAT-GREEN LWIS ORTHODONTISTS ofcs clns of dntst 829-2872
HART PATRICK M ofcs clns of dntst 836-1680
JURELLER PAUL D ofcs clns of dntst 829-2251

MAIN ST

MARGARONE JOSEPH JR ofcs clns of dntst 829-2733
NABI HANI A medical clinic 834-5578
NEW YORK STATE OF BUFFALO MATERIALS RESEARCH CTR nomrcl rsch orgnztn 829-2626
NEW YORK STATE OF SUNY BUFFALO colleges/univ 831-3300
NEW YORK STATE OF UNIV BUFFALO/HEALTH AND HSING colleges/univ 645-2000
NEW YORK STATE OF UNIVERSITY AT BUFFALLO rgltn admn trnsprt 829-2886
NISENGARD RUSSEL J ofcs clns of dntst 829-3845
PRIMARY CARE RESOURCE CENTER drgs prprtrs sndr 829-3176
RUSSO THOMAS A medical clinic 829-2674
SCANNAPIECO FRANK ofcs clns of dntst 829-2013
SUB-BOARD CLINICAL LAB medical labs 829-2367
SUNY AT BUFFALO SCHOOL OF MEDICINE vocational sch 829-2775
WESTERN NEW YORK HEALTH SCIENCE CNSRTIUM urbn comnty dvlpmn 829-2766
35 Not Verified
111 NEW YORK STATE exec ofcs 829-2125
140-204 Not Verified (2 Apts)
205 W B F O 887 FM radio brdcstg stns 829-2555
301 Wishardt Maria
512 Not Verified
- ZIP CODE 14214 CAR-RT C006
3442 Abouzied Mohel 836-5419
Alleyne Menelik R 835-8262
Beggio H 832-2520
Bradley M E 837-1354
Chang Yachen 835-8113
Chong Miau K 836-2381
Coleman Michael 836-2051
Crugeiras Juan 836-7089
Dambrosio Ralph M 831-0621
Dicioccio J 837-4164
Goodale Amy R 834-1900
Graham Juanita 837-3156
Kim Jin H 837-4773
Kirk Ed 836-6743
Kwasnewski Heidi L 833-8471
Lotempio Andrew 836-4279
Lukin Joshua B 838-8053
San Henry 834-4951
Shalaby Kamal 834-1669
Singh S 837-6814
Trabold Peter A 836-6176
Warden Renee 838-5117
Warden Richard 838-5117
Yeung Wing 832-0107
b-122 Not Verified (2 Apts)
A1 Smith Angela B
A1 Smith Cleo
A2 Doherty Sean M 833-6895
A3 Not Verified
A5 Crugeiras Juan
A8 Not Verified
A14 Dolan Dawn M
A16 Graham Juanita A
B1 Not Verified
B1 Quinlivan Lara E 832-9127
B2 Benders David L
B4 Not Verified
B6 Kardum Karmen A
B8 Liao Hsiang 446-1521
B10-B14 Not Verified (2 Apts)
B15 Howard Erica P 832-1841
C1 Damaso Aimee E
C4-C14 Not Verified (4 Apts)
C15 Messito Carol 836-9776
C16 Not Verified
3484 Not Verified
3488 WALGREEN COMPANY drug store 834-7011
- ZIP CODE 14226 CAR-RT C007
3500 AMHERST THEATER movie theater 834-7655
BOOK EXPRESS book stores 446-1241
BUFFALO ONE STOP rcd prrcrded tp st 837-2090
FAMILY SAVINGS CENTER used merch stores 835-0153
FANTASTIC SAMS HAIR CARE SALON beauty shops 836-3156
MANUFACTURERS & TRUSTADERS COMPANY M & T BANK state commrcl banks 832-9523
MARC JEWELERS jewelry prec metal 836-8236
PERFECT TIME COMPANY jewelry stores 837-9410
ROYAL BEAUTY SUPPLIES svc estblshmnt eqpt 836-8806
TOPS FRIENDLY MARKETS grocery stores 837-8470
WESTERN NEW YORK THEATERS movie theater 834-7730

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAIN ST 1998



■ HOMEOWNER

MAIN ST

350 (N) Milke Mike

+KENMORE AVE BEGINS

3582 TUXEDO JUNCTION misc prsnl svcs 833-8812

3584 UNIVERSITY MBL COMMUNICATIONS misc rtl strs 835-5486

3586 (N) Hassett Keith 836-1342

JAMISON CONTRACTING sngl-fam hsng cnstr 836-1342

OTIS BEDDING MANUFACTURING COMPANY misc hmfrnshngs str 833-6712

ROWAN TREEFUTON & FURNISHING furniture stores 446-0202

+SPRINGVILLE AVE BEGINS

3604 SPEAKER SHOP electronics 837-1557

3610 FOLLETT COLLEGE STORE book stores 833-7131

3612 Smith T [3] 838-6013

UNIVERSITY MANOR hotels & motels 837-3344

+CALLODINE AVE BEGINS

3640 BURGER KING eating places 836-2288

+BAILEY AVE BEGINS

+CROSBY CIR ENDS

3666 Bronstein Richard W [9]+ ■

Bronstein Lucille J

BRONSTEIN APPRAISAL SERVICE real est agts/mgrs 835-7400

3690 ENTERTAINMENT SERVICES thtrcl prdcrs svcs 835-3500

3696 (N) Moore Latasha M

3700 Lefcourt Yvonne C [9]+ ■ 833-0743

Lefcourt Charles R 833-0743

3710 (N) Gerow Richard J 835-5708

GEROW R J ofcs clns chrprctr 835-1600

3714 Delmont Michael J [9]+ ■

+PARK CIR BEGINS

3742 Tarbell Laura C [9]+ ■

3750 (N) Butts Caprice ■

3760 (N) Hart Patrick M 838-3348

3770 Robinson Girard E [9]+ ■ 834-0212

Robinson John G 834-0212

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 1998



885-1080

BUSINESSES 259 HOUSEHOLDS 579

NIAGARA FALLS BLVD (BUFFALO)-
FROM 166 KENMORE AVE
NORTH
+KENMORE AVE BEGINS

· ZIP CODE 14223 CAR-RT C062

154 MARACLE ENTERPRISES jewelry stores 836-8002
158 WESTERN N Y CENTER FOR VSL IMPRD optmtrst 836-3250
166 HALT JAMES GRAPHIC DESIGN commrcl art gr dsg 836-4439
MARRYL MICHAEL & ASSOCS drct ml advrtsg svc 831-0869
170 ATOMIC AUDIO electronics 835-4701
(N)Lawrence Ann 831-1505
(N)Sobieraj B D 834-8155
Sperrazza Eric J [7] 835-4701
174(N)Borgese Angelo 446-0524
(N)Borgese C 446-0524
180(N)Agustiady Donny 833-9014
(N)Millias Paul 832-4682
Utomo Seno [5] 833-4101
186(N)Lebar M 833-7357
Polder Cecilia A [4] 835-5227
190 Daniels Michael C [4] 832-9664
192(N)Golpi Kerri 837-6710
198(N)Duncan Andrew 836-9565
200(N)Buchholz Charles W 832-1461
(N)Walker James W 852-8217
202(N)Donegan Kip 835-4299
(N)Rogerswilson James H 836-6710
206 M & M DESIGNS busn svcs 835-7256
(N)Masman Michael 835-7256
L-1 Grant Rita A [9]+ 836-5694
218 Ryan Jean E [3] 831-0365
222 Ciolczak Henry J & Helen [9]+ 833-6595
(N)Gisel B 832-8647
(N)Gisel M 838-0684
232 AMERICAN DREAM CRUISES travel agcy 862-9590
Vanetten Ronald A [9]+ 834-7851
240(N)Aduri P 832-8165
BOULEVARD HAIR CARE beauty shops 832-1060
(N)Giaramito James 837-4024
(N)Zastrow M L 834-2800
244 JUST PIZZA eating places. 832-7582
248(N)Miller Glenn 832-2099
(N)Miller Jode 832-2099
(N)Zaibert Leonard A 838-8057
252 Dussault Wayne A [9]+ 838-1810
254(N)Merchant Taher Z 833-7945
258 Baldi Joseph F [9]+ 832-9909
260(N)Viruet F 852-8262
262 Pragel Gary P [9]+ 832-4352
270 Greiner Keith M [2] 835-1374
274 Isenberg Edward I [9]+ 838-6044
WATER TECHNOLOGY CORP busn svcs 838-6044
280 Lorig Clara [1]+ 837-6029
286 Macaluso Linda A [6] 838-9657
290(N)Konkle A 837-5743
292 Fickhesen Adrienne M [7] 837-4027
298(N)Laskyformato Jane 837-6833

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 1998

NIAGARA ST to NIAGARA FALLS BLVD

NIAGARA FALLS BLVD

304 Walsh Mgeraldn G 835-2943
308 Clemo Brian J 834-6041
310 Godleske Thomas J 835-5693
316 Demars Michael J 833-7101
320 Richardson Mark R 838-1658
324 Zimpfer Helen V 836-4394
330 Ebert Cecelia 837-9234
334 Obrocta Louis J & Marylou 835-0740
338 Wackowski Frieda F 832-1444
342 Lundquist Robert D & Marion 836-2130
344 HEWSON ROBERT otcs clncs podtrst 833-8095
HEWSON ROBERT A otcs clncs podtrst 833-6094
Wassinger Kathleen E 833-7832
354 DAIRY STORE dairy prdts stores 836-8690
358 Wheeler Mary A 832-0969
362 Ruffino Joan E 832-7435
370 Chan Kenneth 836-1673
Sene Timothy 832-2084

+CAMBRIDGE BLVD BEGINS

378 Marter Gerald 834-2058
382 Crist Georgina M 835-3181
Stabl Josef 835-4031
386 Franklin Clarence D 832-7106
Griffo Nicholas 836-8594
390 Barnes James D & Cherie 837-8442
394 Kelleher Thomas M & Theresa 835-3486
398 Barnes Timothy D 836-0337
414 Barber Helen M & Edward 834-3615
418 Garner Joseph A 831-0037
422 BOULEVARD BARBER SHOP barber shops 834-4999
Holloway Will 831-3119
JACKLIN BOYD VIOLINS musical instrmt str 837-1684
SCHWARTZ MICHAEL L otcs clns of dntst 835-3906
TOMY TILE trz tile mrbl 831-8202
424 SWEENEYS GARAGE auto rpr 832-0648

+PAIGE AVE BEGINS

442 S & E JEWELERS jewelry stores 832-1595
S & E JEWLERS jewelry stores 832-1596
S & E TELEVISION SERVICE radio tv rpr 832-1597
446 Baldi Linda 835-3886
Dougan John D 836-8304
A Kisloski David D Jr 835-5706
462 RENTAL CITY truck rntl 833-4818
466 BOULEVARD GRAPHICS commrcl art gr dsg 833-2588
Connor A M 834-9744
474 BUYERS DIRECT real est agts/mgrs 838-3000
FROHE ADELE N legal svcs 834-5322
HAQ SYED medical clinic 773-6650
WESTERN NEW YORK mgmt cnsltng svcs 836-6092

+OXFORD AVE BEGINS

482 CAMEOS RESTAURANT eating places 832-2790
Wiepert Thomas 838-3713

+CHALMERS AVE BEGINS

500 DIP-N-DIVE sptg gds/bike shp 837-3483
512 SAIGON BANGKOK RESTAURANT eating places 837-2115
528 BLONDIES ON BOULEVARD beauty shops 834-5727
BOLEA V & SON reupholstry furn rpr 835-3932
LEONARD'S BARBER SHOP barber shops 834-0036
536 CAR PARTS CENTER mtr vhcl spls prts 834-2776
540 LINCOLN PARK PHARMACY drug store 832-7800
546 BIG JOHNS RESTURANT eating places 836-4881

ZIP CODE 14223 CAR-RT C063

570 Alvarez Rick 837-6416
580 Fix Joan W 835-1651

+YALE AVE BEGINS

600 Villanueva Elnore 862-9495
608 Harrison Charles 837-4962
624 Bartlay Goldie A 832-4645
628 Malchiorre Christine 833-4602
634 Mobley John E Jr & Gladys 832-6433
640 Wolff Paul A 833-0154
648 Snell J M 695-2008
650 Eaton Wendell L 832-6987
654 Ewald Gary 693-3446
Horbowicz Jeffrey J & Denise 835-7255

ZIP CODE 14223 CAR-RT C046

668 Hoyt Nancy J 832-1204
670 Kirbis Robert W & Mary 835-8619
674 Ranney Gary L 835-1198
678 Pioplawski Gordon S 832-5347

+LONGMEADOW RD BEGINS

684 Pray Donald P & Carole 832-7793
694 Roberts Theodore 838-6309
698 Tag James 838-3280
704 Janeczko William W & Josephine 834-8551
710 ALUMA-WAY CONSTRUCTION COMPANY rfng sdng sht mtl 832-2291
Blom Roberts G & Carol 835-8447
716 Francken Timothy M & Kathleen 836-8671
728 Jenus Lutz J & Margaret 836-8212
738 Hampe Helen M 833-3451

+HIGHLAND AVE ENDS

748 Powell Jeffery S 837-1397
758 Chambers Gary M 835-9633

NIAGARA FALLS BLVD

CHAMBERS GARY M acctng audtng bkp 833-3409

+RUTH AVE BEGINS

782 DAIRY QUEEN eating places 834-2447
796 PINO CHRISTOPHER J indvdl family svcs 832-1434
800 ROSIEKS VACUUM hshold applnce strs 837-0442
820 UNI-MARTS grocery stores 832-0810
828 BARRY'S HAIR CENTER misc apprl accy st 833-2121
FREEDMAN A ELECTRIC CONTRACTOR elec work 833-0940

+BETINA AVE BEGINS

+MOORE AVE ENDS

860 KENILWORTH ELECTRONICS COMPANY radio tv rpr 837-6666
NIGHT LIFE MAGAZINE misc publishing 834-3348
874 CORSI AUTO BODY & GLASS pnt & body rpr 835-2455
KRESSE PETER AUTO SALES used car dealers 834-0600
900 PEARCE & PEARCE COMPANY real est agts/mgrs 833-6600
908 TECH BITE INTERNATIONAL U S A prepackaged sftware 692-2745
910 DPS VIDEO photofnshng lbrtrs 835-4620
920 A AMERICAN DANCE STUDIO dance stdios/schs 834-3350
ACTION REALTY real est agts/mgrs 836-9650
CENTURY 21 ACTION REALTY real est agts/mgrs 836-9660
HAIR PZAZZ beauty shops 833-1919
926 MARTINOS ELECTRONIC CENTER busn svcs 836-7000
MARTINOS ELECTRONICS electronics 836-7000

+EGGERT RD ENDS

+SHERIDAN DR BEGINS

ZIP CODE 14228 CAR-RT C057

1459 LONE STAR STEAKHOUSE & SALOON eating places 832-7877
RAYMOURS & FLANIGAN furniture stores 834-7171
RIVERFRONT MEDICAL SERVICES PC medical clinic 832-9600
1551 BUFFALO BEACH HOUSE misc apprl accy st 832-9002
BURLINGTON COAT FACTORY STORE wmns accy spcty st 833-0554
HOMEPLACE misc hmfrnshngs str 833-0300
JIM & CHUCKS BOOT SHOP shoe stores 837-1210
JO ANN FABRICS sewing ndlwk 836-5548
KIDS CUTS-R-FUN beauty shops 838-0300
LIFE RESOURCES misc rtl strs 836-4001
NAIL STOP beauty shops 835-4631
PIER 1 IMPORTS OF TONAWANDA gift shop 836-7210
RED WING SHOE STORE shoe stores 836-5424
SUN CAPSULE PLUS misc rtl strs 835-5178
SWISS CHALET BAR-B-Q eating places 852-0008
SWISS CHALET INC eating places 837-4300
1561 SUPER SAVING CENTER electronics 833-3131
1565 PETSTUFF misc rtl strs 838-5009
1641 APPLEBEES NEIGHBORHOOD BAR GRILL eating places 831-8062
1701 KMART department stores 837-8080
PENSKE AUTO CENTERS auto rpr 837-9131
1705 HORTON TIM DONUTS retail bakeries 833-4233
1681 HOLIDAY INN HOTEL OF BUFFALO eating places 691-8181
1925 BOB EVANS RESTAURANT eating places 691-0778
1931 Wichlacz J 871-1006
1951 BLUE DOLPHIN MOTOR LODGE hotels & motels 691-9392
2001 ANSELL BUFFINGTON & COMPANY acctng audtng bkp 691-3111
DATAWAVE COMPUTING cstm cmptr prgmg srv 691-9964
HAYDEN ELECTRICAL SYSTEMS swtchgr brd apprtus 564-2302
HEALTH MANAGEMENT GROUP social svcs 691-9700
HORIZON MAINTENANCE UNIT indvdl family svcs 691-7900
LMM PROPERTIES ENTERPRISES real est agts/mgrs 564-0002
SCHIFF & BURMAN acctng audtng bkp 564-1300
2005 ABCO LEASING hvy const eqpt rntl 691-2653
PEPE ANTHONY F acctng audtng bkp 691-7243
VISION CARE CENTER optical gds stores 691-4221
2055 WAL-MART STORE department stores 691-0195
2065 HOME DEPOT lmbr bldng mtrls 639-9600
2139 MIKE REXFORD TIRE & SERVICE gas stations 691-4243

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 1993



38 BUSINESSES

245

NIAGARA FALLS BLVD (TOWN OF TONAWANDA)–FROM 181 KENMORE AV NORTH

- **ZIP CODE 14226**
- KENMORE AV INTERSECTS
- (FOR LOWER NUMBERS
- SEE BUFFALO CITY DIRECTORY)
- EVEN NUMBERS ZIP CODE 14223

158 WESTERN NEW YORK CENTER FOR VISUALLY IMPAIRED 836-3250
WEISS NORMAN J optom 836-3250
165 SHASTRI SUBRAMANYA R phys 836-3411
ALMON ASSOCIATES consultants 833-3031
Almon Susan M [7] 833-3845
166 HALT JAMES G GRAPHIC DESIGN 836-4439
Design) Halt Jas G & Diane K [9]+
170 Lux Julia [3] ◉ 835-3653
Dark Mary J [9]+ 834-2133
Szczepanek Mary [9]+ 838-2628
171-171 Not Verified (2 Hses)
174 Ricotta Josephine C [9]+ ◉ 834-9634
Wood Stella B [9]+ 837-3134
177 Kam Joseph Jr & Muriel J chiropractor ◉ 835-5400
179 Hagen Eleanore V [9]+ ◉ 834-6821
180 STUDENT RES
186 Le Bar George [9]+ ◉ 834-5929
Le Bar Marie H 834-5929
Kelleher Mary [2] 833-7357
189 Feuerstein Marvin E [9]+ ◉ 837-6586
Feurstein Michl S 837-6586
DENTURE CENTER OF BUFFALO 834-1133
190 STUDENT RES
192 STUDENT RES
195 Puehn Geo E & Georgia R [9]+ ◉ 833-6533
198 STUDENT RES
199 Mc Call N Churchill & Lucille E [9]+ ◉ 833-5939
200 Not Verified
202 Hahn Douglas & Stacie [2] 837-3129
204 Wollsoncroft David A & Susan K [7]
Billups Randall & Kimberley [2]
206 Masman Jean S [9]+ 835-7256
Grant Rita A [2] 836-5694
207 Nice Wm R [9]+
★Selinsky Michele
208 Not Verified
213★Moeser Anthony G ◉
Vacant
218 Cortellucci Mary L [9]+ ◉ 834-3674
Burnett Janet [6]
87 219 Amoroso Albert R & Marilyn [9]+ ◉ 837-7187

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 1993

NIAGARA FALLS BLVD (TT) –Contd

Amoroso Albert M & Ageline 9+ 835-2115
Amoroso Sally 835-2115
222 Gisel John C & Barbara 9+ ● 832-8647
Ciolczak Henry J & Helen 9+ 833-6595
225 Fiorella Robt & Louise 5 ● 833-4579
Fiorella Susan L 833-4579
Fiorella David J 833-4579
228 O'Shaughnessey Terrence J & Melissa A 9+ ● 837-6153
Miller Edw J & Floydette S 2 836-8674
231 Samulski Paul A & Judy L 4 ● 838-1155
★Mark Jennifer 833-1778
232 Not Verified
• KENILWORTH AV INTERSECTS
237 Puerner Lawrence W 9+ ● 838-3200
240 Campbell Denise A 2
Vacant
BOULEVARD HAIR CARE 832-1060
242 SCUBA DIVING SCHOOL
244 GREAT LAKES DIVERS INC 836-6900
248 Vacant
252 Not Verified
254 Seth Jogath & Archna 3 ●
Seth Jaj Raj & Sushma 3 ● 834-4001
• PRINCETON AV INTERSECTS
255 Not Verified
Weitzel Robt C & Deborah A 4 ● 832-5538
258 Baldi Joseph F 9+ ● 832-9909
261 Schmidt Martha C 9+ ● 834-4655
262 Pragel Sheila 9+ ● 832-4362
267 STUDENT RES
268 Hodur Darrel L 9+ ●
270 Then Irene C 9+ ● 832-9555
273 Lum Gregory R & Deborah R 2 ●
274 Isenberg Edw 6 ● 838-6044
276 Fanara Antonio & Josephine 6 ●
279 Not Verified
280 Lorig Clara 9+ ● 837-6029
Lemley Clifford F & Agnes 837-6029
285 Meinkes Irving & Rhoda 9+ ● 833-4136
Vacant
286 Strychalski Michl M & Susan L 4 ● 834-0883
290-290 Not Verified (2 Hses)
291 Mattina Rita F 9+ ● 833-4049
★Baumlur Jon
292★Faulks Chrisopher ●
297 Vacant
298 Laskyformato Salvatore C & Jane A 3 ●
300 Lambert David 2 ●
303 Not Verified
304 Walsh George E Jr & M Geraldine 9+ ● 835-2943
308 Fimbel Richd P & Jerri 5 ● 834-2495
309 Wilson John T Jr & Jutilia M 5
Olszewski Karen A 2
310 Godleske Thos J & Cheryle A 9+ ● 835-5693
315 STUDENT RES
316 Carducci Anthony J 6 ● 837-2469
320 Richardson Mark R 5 ● 838-1658
321 Delles Joan M 9+ ● 833-2164
324 Zimpfer Helen V 9+ ● 836-4394
327 Zekas Michl J & Darcy A 2 ● 831-9229
328 Kindron David J & Linda J 5 ●
330 Ebert Jack C & Cecelia R 9+ ● 837-9234
333 Fawcett Kimberly A 3 837-8385
Catalano Sharon L 2 834-0896
334 O'Brocta Louis J & Mary Lou 9+ ● 835-0740
338 Wackowski Frieda F 9+ ● 832-1444
339 Poloncarz Robt A & Julie A 9+ ● 836-6030
Stilwell Ann P 4
342 Lundquist Robt D & Marion H 9+ ● 836-2130
344 HEWSON ROBT A PODIATRIST 833-8094
• FORD AV INTERSECTS

245-A

345 Not Verified
354 DAIRY STORE THE groc 836-8690
• CAMBRIDGE BLVD INTERSECTS
358 Wheeler Wm J & Mary A truck driver ● 832-0989
White Christina M 832-0989
362★Ruffino Robt J ● 832-7435
363 Cox Bruce H & Linda E 9+ ● 832-5633
Cox Bruce M 832-5633
369-370 Not Verified (2 Hses)
Yayathi Tejeswini 2 ● 836-5989
373 Gibbs Gerald & Carol 2
378 Marter Gerald 9+ ● 834-2058
382 Crist Georgina M 9+ 835-3181
Stabl Josef & Hilde 9+ ● 835-4031
383 Proulx Jacques J & Jeanine 3 ● 834-1250
Proulx Kimberly 834-1250
386 Not Verified
Not Verified
389 Stehlin Victor F 9+ ● 832-9590
Stehlin Diane M 832-9590
Stehlin Richd A 832-9590
390 Gross Michl J & Sherry C 3 ● 837-5783
Jones Jean M 9+ 837-4149
394 Kelleher Thos M & Theresa Y constn wkr ● 835-3486
395 Hunter Rose R 2 ●
396 Dunn Roy G 9+ ● 836-8696
398 Barnes Timothy B 6 ● 836-0337
399 Stanley Kurt A 3 ●
405 Wong Michl 2 ● 831-0578
406 Not Verified
409 Montz Leon R 4 832-1384
Montz Chas G 832-1384
410 Davies Bernice F 9+ ● 836-4768
414 Barber Edw J & Helen M 9+ ● 834-3615
415 Meyer Gloria 2 ●
418 Krupa Karen A 3 ● 835-2582
422 BUFFALO STRING SHOP sls-rents-repr instruments 837-8900
CLASSIC CUTS 834-4999
THERMAL TECHNOLOGY LABORATORY INC research & development 836-6680
WILLIAMS EAMIGH & ASSOCIATES INC ins 833-5351
LAY RICHD V dentist 835-3906
KOLSTAD ASSOCIATES INC mfg rep 834-1445
423 Jok Greg 2 ● 835-6358
• PAIGE AV INTERSECTS
424 Vacant
SWEENEY'S GARAGE auto repr 832-0648
Basinski Philip 2 ● 832-0648
429 Barnes Kath I 9+ ● 832-3856
435 O'Connor Peter J & Sandra L 9+ ● 838-4351
442 S & E WHOLESALE INC appl sls 832-1595
FULL GOSPEL FELLOWSHIP religious org 832-1595
S & E JEWELRY WHOLESALE whol jwlry
443 Nutefall Dani L & Kath L 9+ ● 836-5334
446-446 Not Verified (2 Hses)
Rear Mycek Clara 9+ 836-7074
450 CHECK LIQUOR STORE 835-6300
453 Jaffri Sham S 2 ● 838-1035
Jaffri Raza 838-1035
Jaffri Zia 838-1035
Jaffri Ali 838-1035
Jaffri Abida 838-1035
Jaffri Sarwat 838-1035
459 Bousamra Chas L & Marion B 9+ ● 836-5506
462 RENTAL CITY trucks trailers power tools 833-4818
Mauro Salvatore B 9+
465 Burnis John & Alice B 9+ ● 833-2555
466 BOULEVARD GRAPHICS design 833-2588
Boyle James 4
• OXFORD AV INTERSECTS
474 TOWNE PROFESSIONAL BLDG Rooms
1 Not Verified
2 BECHTEL COMPUTER CO comp sls & serv 833-6815
3 Vacant
4-474 Vacant (2 Businesses)
6 FROHE ADELE N lwyr 834-5322
7 MATTELIANO JAMES C dentist 832-1678
8 BECHTEL COMPUTER CO (ADDL SP)
479 Vacant
Vacant
482 CAMEO'S RESTAURANT 832-2790
483 Gagliardi Fredk J 9+ ● 833-5295
489 Not Verified
495 Wong Mun F & Soo K 9+ ● 832-8347
Wong Betty 832-8347
Wong Mary Inmng 832-8347
500 DIP-N-DIVE INC scuba cntr 837-3483
505 Wong Sue K 9+ ●
512 CATHAY GARDENS INC chinese restr 837-3444
513 Leach Jon I 9+ ● 838-1771
519 Saxena Suresh B & Bala B R 6 ● 837-6235
523 Janese Carolyn F 9+ ● 832-9353
528 BOLEA V & SON UPHOLSTERING & FURNITURE SHOP 835-3932
Vacant
LEONARD'S BARBER SHOP 834-0036
529 Blair Donald J & Patricia M 9+ ● 832-4152
535 Woloszyn Steven & Rita L 9+ ● 837-6475
536 LAKELAND AUTO SUPPLY INC 834-2776

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 1993



165

★ NEW NEIGHBOR

540 LINCOLN PARK PHARMACY INC 832-7800
U S P O (LINCOLN PARK BR) 832-7800
543 V & C IMPRINTING printers 836-9672
Paeplow Charles E & Vivian E 9+ ● 836-9572
546 BIG JOHN'S SUBMARINES & PIZZA 836-4881
549 Ashley Heber & Betty M 9+ ● 832-0520
553 Not Verified
• DECATUR RD INTERSECTS

244-A

• DECTUR AV INTERSECTS
559 Meyer Raymond H 9+ ● 832-0583
563 Pufpaff Kath L 9+ ● 834-3800
Jordan Michl D 834-3890
Jordon Lisa D 834-3890
564 Not Verified
569 Hylkema Ken R & Donna M 2 ● 837-4420
570 Diederich Ralph B & Lila M 5 ● 837-3131
579 Didomizio Joseph C & Annette S 4 ● 838-3412
580 Fix Joan W 9+ ● 835-1651
• YALE AV INTERSECTS
588 De Priest Jay A & Darlene R 9+ ● 833-5167
593 Kielich Ronald J dentist ● 834-3568
594 Diamond Anthony A & Norine D 9+ ●
599 AUTO DRIVEAWAY CO (ADDL SP)
AUTO DRIVEAWAY CO auto forwarding 833-8500
Parker Bernice 4 837-5620
600 Not Verified
605 Daniels Craig A & Cheryl L 2 ● 835-3633
608★Milbrand R 832-0889
613 Gaughan Robt M & Alice M 3 ● 835-5658
616 Szymanski Edw J 9+ ●
619 Jacob Gladwin & Sunita 2 ● 836-1271
624 Bartley John I & Goldie Ann 9+ ● 832-4645
625 Patterson Robt A & Debra 4 ● 837-4687
628 Vacant
633 Tobin Robt & Sylvia 9+ ● 835-4140
634 Mobley John & Gladys 9+ ● 832-6433
639 Not Verified
640 Wolff Marian H 9+ ● 833-0154
643-644 Not Verified (2 Hses)
649 Southwick Larry III & Marcia 2 ● 832-5094
650 Eaton Delores E 9+ ● 832-8987
653 Johnson Willard E & Mary L 9+ ● 862-0307
654 Horbowicz Jeffrey J & Denise 2 ● 835-7256
• LINCOLN PARK DR INTERSECTS
659 Elkins Kevin & Linda 3 ● 833-2586
663 Menchetti John J 9+ ● 832-3418
Menchetti Eliz A 832-3418
Menchetti Joanne 832-3418
664 Gil Andrew O & Lourdes 2 ● 836-1440
665 Minick Howard E & Victoria A 9+ ●
668 Hoyt Dale J & Nancy J 5 ● 832-1204
669 Braun Donald & Patricia 3
670 Kirbis Robt W & Mary B 9+ ● 835-8819
673 Vacant
674 Ranney Mildred A 9+ ● 835-1198
Ranney Gary L 835-1198
• LONGMEADOW RD INTERSECTS
677 KORNER MART groceries-ret 838-2235
678 Poplawski Gordon S 9+ ● 832-5347
679 FERA'S BOULEVARD SUB SHOP 838-4545
681 FEEL-RITE HEALTH FOOD SHOPPE INC 834-3385
684 Pray Donald P & Carole J 9+ ● 832-7793
Pray Donald P Jr 832-7793
688 Thomas Kevin P & Kath L 2
694 Kirbis John J & Theresa M 7 ● 836-7639
698 Tag James & Elaine landscaper 838-3280
704 Janeczko Wm W & Jos P 9+ ● 834-8551
710 ALUMA-WAY CONSTRUCTION CO INC alum constn 832-2291
Blom Robt G & D Carol 9+ ● 835-8447
711 TRINITY UNITED METHODIST CHURCH 835-7711
WESLEY FOUNDATION 835-0632
716 Bingel Wm E & Marian S 9+ ● 832-5003
722 Priamo Gerald A & Susan M 9+ ● 832-2407
728 Janus Lutz J & Margt 9+ ● 836-8212
733 A F AUTOMOTIVE 833-0228
738 Dickey Ronald G & Robin L 5 ● 836-8254
• RUTH AV INTERSECTS

243

• HIHGLAND AV INTERSECTS
748 Powell Arlene P 9+ ● 837-1397
751 HECTOR'S HARDWARE & PAINT CO INC 832-9310
758 Chambers Gary 2 ● 835-9635
765 CHRISTIAN FELLOWSHIP BAPTIST CHURCH 837-1664
770 LINK FOX CO INC 832-6588
LORD ROBERT F FUNERAL HOME 832-6588
Lord Isabelle C 2 832-5178
• HARRISON AV INTERSECTS
771 TONY'S BARBER SHOP barber shop 834-4130
773 CHAIN'S ENTERPRISES INC import clo 837-8344
CHAIN'S HONG KONG CUSTOM TAILORS 837-8344
CHAIN'S INDIA BOUTIQUE tailor made clo jwlry & gifts 832-2075
775 Vacant
782 DAIRY QUEEN custard stand 834-2447
785 LINCOLN PARK MOTEL INC 837-7400
★Kumm Jeoff
Blvd Kumm Sheila
789 Branch Eugene M & Maureen B 2
796 Vacant
STURNIOLO FRANK psychologist 832-1434
BRUMLEY CHARLENE K MRS legal socl wkr 832-1775
GUNTHER COLETTE CARSE massage therapist 832-1434
PINO CHRISTOPHER J clinical psychologist 832-1434
797 JOLLY JUG tavern 836-9552
800-802 Vacant (2 Businesses)
803 EMPIRE AUTO ELECTRIC LTD electrical sys 835-2424
BURGIO & CAMPOFELICE INC genl contrs 833-5171
• BETINA AV BEGINS
804 A A FURNITURE CO sls 833-1977
• MOORE AV INTERSECTS

243-B

820 UNI-MART convenience store 832-0810
828 Vacant
839 SZECHUAN HOUSE restr
GIANNI'S HAIR SALON 834-5993
VIDEO FACTORY video rental 834-8340
VIDEO FACTORY (ADDL SP)
VIDEO FACTORY (ADDL SP)
843 MAINTENANCE & MANAGEMENT ASSOCIATES INC jan serv 836-2111
Rankin Kelly 2
Nugent Brian 2
845 SENTRY NORTH APPLIANCE SERVICE CO 835-2991
★Urich John & Jane
Urich Kathy
847★Chew Huan 838-6118
★Gui Naseem 862-0122
850 BARRY'S HAIR CENTER beauty salon 833-2121
RAJMAMAL restr 834-6433
853 APEX ORIENTAL FOOD INC oriental foods ret 834-2966
860 KENILWORTH ELECTRONICS CO 837-6666
Vacant
TELEMATION busn mktg & consltg
CAM GROUP THE sys dsgn & integration 862-9559
861 Wahl Philip J & Cheryl J 9+ ● 832-5413
Wahl Danielle 832-5413
865 STUDENT RESIDENCE
Not Verified
869★Nasiri Mohsen 835-6926
Building
WOEPPEL EDW J cpa 836-3822
GELLMAN SIGMUND acct 838-1962
871 Building
GORDON JAMES IMAGE MAKERS INC photo 837-5665
DESIRED IMAGE INC fashion consultants 834-1123
DESIRED IMAGE INC (SKIN CARE DIV) skin care salon 834-1123
CAREER PRO INC pro resume & wrtg serv 833-1194
A PROFESSIONAL RESUME & WRITING SERV 833-2612
874 CORSI AUTO BODY & GLASS INC auto body repr 835-2455
ACTION AUTO GLASS auto glass tinting 874-2766
899 SCHEFF INSURANCE AGENCY INC ins agcy 834-4818
D A S BUSINESS SERVICES INC ins co adjstrs 835-6666
MANHARDT COLLISION SURVEY INC antique auto appraisals 835-2851

693-7444

1241 OLIVER STREET

NORTH TONAWANDA, NEW YORK 14120

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 1993

● HOMEOWNER 166

NIAGARA FALLS BLVD (TT) –Contd
SCHEFF & LYNETT ASSOCS INC ins 835-3284
SULLIVAN JAMES W lwyr 835-2910
900 PEARCE & PEARCE CO INC real est 833-6600
910 DAVID PHOTO SERVICE INC 835-4620
920 HAIR PZAZZ beauty shop 833-1919
AMERICAN DANCE STUDIO 834-3350
925 BOULEVARD MOVING & STORAGE (DIV U-HAUL INC) 832-1778
928 MARTINO'S ELECTRONICS CENTER electrical appl sls 836-7000
934 SPEEDY MUFFLER KING 838-6400
• EGGERT RD INTERSECTS
951 DENNY'S RESTAURANT INC 837-5657
• SHERIDAN DR INTERSECTS

241-A
• AMHERST TOWN LINE
• ZIP CODE 14226
• SHERIDAN DR INTERSECTS
995 FIRESTONE TIRE & RUBBER CO 837-9700
1009 BARNABY'S restr 832-6064
• TONAWANDA PO
• ZIP CODE 14150
1016 CAMPOS PHOTOGRAPHY CENTER film processing 837-1016
Vacant
1021-1030 Vacant (2 Businesses)
1060 BOULEVARD SQUARE PLAZA shopping cntr
BRASS BEDROOM THE ret furn & linens 838-2222
BIG L DISTRIBUTORS INC (BR OFC) window door sls 832-8484
CARPET SHOPPE INC THE carpet sls 832-3811
MOVIES PLUS SUPER VIDEO CENTER movie rntls 834-7144
BOULEVARD COFFEE SHOP restr 837-9622
EMPEROR WOK 835-7878
1061 PLANT PLACE & FLOWER BASKET ret florists 838-3400
HEWITT JACKSON TAX SERVICE tax serv 832-7628
Vacant
1090 ROSA'S HOME APPLIANCES ret appl sls 835-6155
BLOCK H & R tax prep 834-3449
1094 MEDICAL BUILDING 883-7012
VOELKER FRANK phys 833-7012
HEALY WM M phys 833-7012
• ROCHELLE PL INTERSECTS
1101 KEENE BUILDING ofc bldg
MATERNITY WEARHOUSE OUTLET ret clo 836-5183
Vacant
RICH JAMES P INSURANCE SERV 833-1900
NEAT REPEATS used clo 838-5624
Keene Carmen H 5 832-0180
KEENE GEO A INC genl contrs 832-0180
• ROCHELLE PL INTERSECTS
1120 CAVALIER MOTOR LODGE 835-5916
De Luca Nicholas & Loretta i 2 ● 833-9730
1130 Vacant
1140 Klein Harold N & Pearl H 9+ ● 834-2996
1154 BRAND NAMES SALES INC genl mdse 834-5094
• BRIARHURST INTERSECTS
1155 FACTORY SLEEP SHOP WHSE bedding mattress sls 833-8112
1167 CARUBBA COLLISION CORP auto body repr 834-0466
1171 MIDAS MUFFLER 837-4100
1172-1185 Vacant (2 Businesses)
1188 CHEMICAL BANK 837-0760
• TREADWELL RD INTERSECTS
1202 WILSON FARMS convenience store 836-4566
1205 CITIBANK 837-1900
• ZIP CODE 14226
1207 BOULEVARD MALL
• (FOR OCCUPANTS SEE BOULEVARD MALL)
1208 DINETTES & MORE furn ret 836-8070
1228 CASUAL MALE BIG & TALL THE ret clo 837-3644
1230 CASUAL MALE BIG & TALL THE (ADDL SP)
1234 Vacant
1242 BISON PLUMBING CITY INC fixtures & sups 837-3117
1244 PETERSON M J real estate 833-3433
1246 ADDED DIMENSIONS womens large-size clo 836-5955
1248 ASIAN ORIENTAL RUGS ret oriental hand-made rugs 833-2127
1250 WATCH WORLD INC watch & repr 835-2241
1252 VAN SCOY DIAMOND MINE 836-2210
1254 Vacant
1258 YOUR HOST RESTAURANT INC 836-9579
1270 EASTERN MOUNTAIN SPORTS INC sport gds 838-4200
1280 GOODYEAR SERVICE STORES tires & auto accessories 837-8730
1304 Vacant
1312 PEARLE VISION CENTER optn 833-8338
1330 Building Floors
1st Fl Vacant
1st Fl SENSATIONAL HAIR unisex hair stylist 837-0019
1st Fl BOTTICELLI INC 837-1122
1st Fl AVCO FINANCIAL SERVICES INC (BR OFC) fin co 832-0372
1st Fl ENTERTAINMENT INC (BR OFC) fund raising 833-8886
1st Fl KWIK KOPY PRINTING 837-4453
1st Fl M & W CAMERA CENTER camera equip sls 833-6110
2d Fl Vacant
2d Fl ACTION AUTO RENTAL INC (BR OFC) auto rntl ins 837-6976
2d Fl ALLSTATE INSURANCE CO 835-5202
1330 HYATT LEGAL SERVICES lwyrs 832-7777
1346 BAUER RADIATOR car radiator sls & serv 834-8822
• BRIGHTON AV INTERSECTS
• MAPLE AV INTERSECTS

240-A
• MAPLE RD INTERSECTS
1355 DELTA SONIC CAR WASH 832-4050
DELTA SONIC DETAIL SHOP car detailing 834-3897
1370 HORIZON BOULEVARD DAY TREATMENT (ADDL SP)
BOULEVARD COUNSELING CENTER-CO 2 833-3708
HORIZON BOULEVARD DAY TREATMENT 833-3792
ALCOHOLIC TREATMENT CENTER org 833-3713
1376 NEW YORK N Y CHINESE RESTAURANT 832-4491
1378 HORSELESS CARRIAGE THE motel 836-2940
Kunvarji Robt & Nalinia 3 ●
1385 MC DONALDS RESTAURANT 837-9255
1395 ARBY'S ROAST BEEF 832-5231
1400 PIZZA HUT 835-3636
1401 CENTURY TWENTY ONE GLASS real est 838-5300
1405 FOSTER THAYER CO INC kitchens sls cabts 838-5106
• ZIP CODE 14150
1420 BURGER KING restr 836-0117
• BRAXMAR RD INTERSECTS
• MEYER RD INTERSCTS
1435 S T S CAR SERVICE CENTER 833-3400
1436 Vacant
JOHN'S PIZZA & SUB SHOP 832-4343
1450 Building Rooms
1st Fl CIVO HAIR 836-2632
1st Fl FACTORY BLINDS LIMITED venetian blind dlrs 838-2330
102-1450 Vacant (2 Businesses)
202 WEINSTEIN KENNETH M c p a's 837-2525
206 STATUS THIMBLE TAILOR SHOP 834-5567
208 L G M DATA data entry prog 862-9888
210 Vacant
1456 SANTANGELO'S HAIR DESIGNERS 834-3995
1459 RAYMOUR & FLANIGAN FURNITURE 834-7171
NATIONAL AUTO SUPPLY 836-2751
RIVERFRONT MEDICAL SERVICE P C 832-9600
FIRST CARE MEDICAL P C med servs 833-2222
1500 DELIA VOLKSWAGON INC 836-4600
1508 STEPHENSONS RENTAL & BEECHERS PARTY TIME INC equip rental 837-6361
1520 KNOLL'S SUNOCO auto repr 832-0921
• YORKSHIRE RD INTERSECTS

240-D
1550 BERTS BIKES & SPORT 837-4882
1551 BURLINGTON VALU SHOPPING PLAZA
SWISS CHALET BAR B Q 837-4300
RED WING SHOES shoe sls 836-5424
WEIGHT WATCHERS 838-0040
VALU HOME IMPROVEMENT CENTER 836-0499
MAJOR MAGIC ALL STAR PIZZA REVIEW 832-0979
PIER ONE IMPORTS variety store 836-7210
JOANN'S FABRICS fabric sls 836-5546
BURLINGTON COAT FACTORY coat sls 833-0554
Vacant
HOMESTYLE FAMILY BUFFET retr 836-8544
LIFE RESOURCES religious book store 836-4001
JIM & CHUCK'S BOOT SHOP 837-1210
Vacant
CAPS FISHING & HUNTING EQUIPMENT INC 833-0112
JOEY'S HAIR DESIGN 834-5738

Target Street	Cross Street	Source
-	✓	Polk's City Directory

KENMORE AVE 1992

194

127-A

KENMORE AV –FROM 3488 MAIN ST WEST TO VULCAN ST

ZIP CODE 14226

38 Vacant

39 Video Connection the 836-1222

41 Becker Jewelers 833-5415

43 Taylor Services temporary employment 837-8100

47 Plaza Shoe Repair 836-4041

May Jen Chinese Restaurant 832-5162

WINDERMERE BLVD INTERSECTS

59 Da Vinci Jewelers ret 836-4700

Ben & Jerrys Ice Cream 834-8566

63 Hudecki Gregory E dentist 834-2744

Hudecki Steph E dentist 834-2744

Syed Attuallah A phys 832-1050

Vacant

Sullivan Jas R phys 832-8044

71 University Medical Building

Hadsaitong Damrong phys 837-2767

Prabharasuth C phys 837-7762

Bregman Allan M dentist 836-1101

Reynhout Jonathan C phys 835-0130

Miller Raymond G dentist 836-1101

Carlo Gerald T dentist 836-1101

Cruz Lourdes Forales phys 832-3111

CAPEN BLVD INTERSECTS

95 Martin Ann ◎ 833-1479

Vacant

99 Krestos Michl A ◎ 835-3882

ALLENHURST RD INTERSECTS

135 Goodare-Rosenthal Nancy dentist 862-0500

Sauer Hazel E Mrs ◎ 836-4553

140 Francavilla Vincent J dentist ◎ 835-7511

143 Austin Warren B Funeral Home 833-6876

Dohn Funeral Home Inc 834-8128

Ashley Heber Jr 832-0520

156 Mc Mahon Agency Inc ins 837-3943

175 Stop-N-Go gro & gasoline 832-8080

NIAGARA FALLS BLVD INTERSECTS

181 Puehn Geo E meat mkt 833-4411

★Mc Donald Timothy

187★Bapst Danl 832-9147

★Landon Christopher 862-9573

189 Words & Graphics Inc graphic design 835-5587

191 Brenner Robt J ◎ 833-4968

193 Rozek Kenneth P ◎ 834-2169

197★Catalano Susan L ◎

199 Ilardo Lawrence R 832-4815

★Li Xu

203 Gates Electric Co Inc appl sls & serv 837-5311

205 Nineteen Ten Hair Emporium beauty shop 832-6558

GRANDVIEW AV BEGINS

299 Ep
300 St
St
MON
311 Ev
Va
Pr
8
Tc
Va
319 Sa
Cc
323 Ke
WEN
326 Cc
8
328 Lc
I
330-33
336 Ai
Sl
8
337 Pe
338 Gl
340 Cc
346 N
2
350 Cl
8
353 M
V
K
359 P
CLA
366 A
369 V
375 N
EN
380 C
382 E
384 J
390 (
396 V
EN
401 E

Target Street	Cross Street	Source
-	✓	Polk's City Directory

KENMORE AVE 1992



19 HOUSEHOLDS 447
50 BUSINESSES 465
487
245

KENMORE AV (TOWN OF TONAWANDA & KENMORE) FROM 154 NIAGARA FALLS BLVD WEST 501

• ZIP CODE 14223
• NIAGARA FALL BLVD INTERSECTS
181 PUEHN'S MEAT MARKET meat mkt 535
833-4411
★Puehn Geo C 836-1814
Mc Donald Tim 836-1814
187 Bapst Danl J & Colleen M [2] 559
832-9147
Landon Christopher [2] 862-9573
189 Not Verified 563
191 Brenner Jack [9]+ ◉ 833-4968
193 Rozek Kenneth P & Jane M [9]+ ◉ 567
834-2169
• LARCHMONT RD INTERSECTS 571
197 Not Verified
199 Ilardo Laurence R [9]+ 832-4815
★Xu Li 833-4591
203 GATES ELECTRIC CO INC contrs 583
837-5311
TAILORMADE mens clo 589
205 EMPORIUM HAIR DESIGN 832-6558
• GRANDVIEW AV INTERSECTS 593
• HAWTHORNE AV INTERSECTS
217 Saemenes Timothy G & Kathy [2] 597
862-9119
Potts Kevin M & Barbara R [6] ◉ 601
838-3625
225 Fanoro Fredk J & Karen M [2] ◉
Le Baron Gertrude [6] ◉ 833-1219 619
229 Werder Paul K & Cath L
chiropractor ◉ 834-7974 623
233 Oberer David [2]
• RADCLIFFE RD INTERSECTS 627
237 Nesselbeck Norman G & Betty R [9]+
◉ 834-8552 631
241 Walter Albert E Jr [9]+ ◉ 834-3761
Walter Gudrun S [9]+ 834-2888
245 Ayer Judd C & Barbara K [9]+ ◉ 647
832-7510
Kaczmarek Mary T 832-7510 651
★Kelly Dave

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAIN ST 1992



235 ★ NEW NEIGHBOR

3162 Apartments
100 Flihan Donald A 838-2046
200★Mc Elligott Marcy
300★Foster Susan M
400 Apap Michl 836-4014
500★Mac Carger Robt D
600★Hedges Rob
3164 Herzog's Drug Store Inc (Addl Sp)
Luterek Frank photographer
3165 Miranda Real Estate 836-6600
3167 Four-M Sales used car sls 836-6600
3168 Herzog's Drug Store 834-1970
Stein Vern Galleries
3171 Latko Printing & Copy Center 835-0100
Vacant
★Joseph Rick
Rear★Balcom A
Rear★Formanek Carrie
W NORTHRUP PL BEGINS
NORTHRUP PL BEGINS
3172 Westworld Video Games 835-0077
3173 Copier & Duplicator Services Instrument dlrs 832-2255
3176 Vacant
3178★Esteseling Paul
3180 Catch Sportcards sports collectibles 833-8442
3182 Vacant
3184 Queen City Book Store 833-6220
Queen City Book Store (Addl Sp)
3191★Berts Scott 832-5160
3193 Dohring Kevin A
★Turgeon Brian
3198 Frank's Mobil Gas Station 836-5337
3199 Molly's Pub tavern 836-6559
3211 Wilson Farms Convenience Food Store 834-4081
WINSPEAR AV BEGINS
W WINSPEAR AV BEGINS

179-B

WINSPEAR AV BEGINS
3208 Parkside Candy Co Inc 833-7540
3210 Resume Center 836-2969
Professional Apprentice Program 838-4509
★Carson Hugh
Crisis Pregnancy Center of Western New York birth control info cntr 833-7100
Parkside Candy (Admn Ofc)
3212 Greeks & Sneaks 833-4913
Vacant
3214 Chayban Custom Tailoring & Dry Cln 833-5049
3216 Hair People the 832-8032
Parlato-O'Brien Realty Inc 835-1020
★Akiki Norman
3218 College Laundry Shop the 833-0060
Bruno Sean
★Capelelatro Matt
WINSPEAR AV BEGINS
3223 North Main Liquor 834-7727
3225 Pinzone's Pizzeria (Addl Sp)
Pinzone's Pizzeria 834-3810
★Delmarco Steven
3229 Buffalo Picture Frame & Mirror Corp 838-3800
MERRIMAC ST BEGINS
SUTTON LA BEGINS
3230 Jimmy Mac's Main Stop sportswear 837-8410
Vacant
★Young Steven
3233 Cantalician Center for Learning sch 833-5353
Dondajewski Lorita Sister
Wagner Harold Rev 836-5276
3234 Fabdoom Video 832-7041
Amy's Place restr 832-6666
3236 Greenhouse the plants 833-5600
3240 O'Connell Lucas Chelf Inc ret clo 836-4140
3242 Vacant
Vacant
3248 Vacant
HEATH BEGINS
3258 Rifco Building
Sable Contracting Co Inc constn
Valco Sales Inc telemktg 832-9343
3260 University Heights Community Development Assn Inc org 832-1010
University Heights Business Association Inc org 832-1010
Apartments
1★Huber Cheryl Lynn
2★Conrad Kimberly
3 Vacant
4★Hietzefthimiou John
5★Clark Kath A
6★Price Sally
3262 Vacant
3264 Third Base tavern 833-1284
3268 Exotic Dance Studio 833-0098
★Mc Namee Karen 831-0789
3269 Saint Joseph's Roman Catholic Church 833-0298
★Bigelow Wm R Rev 833-0298
3270 P J Bottoms Tavern restr & bar 833-3270
3275 Saint Joseph's Roman Catholic School 835-7305
Saint Joseph's Convent 833-7333
ENGLEWOOD AV BEGINS
3292 Chabad House of Buffalo synagogue 833-8334
3296 Chancellor Court Apartments
A1★Herman W
A2 Schottin D
A3 Lee Ju-Hee
A4 Brandt Cath M Mrs 834-9451
B1★Dworkin Norm 832-5861
B2 Shah Ashish 835-9395
B3 Soggi Denise
B4★Hartman Jay
C1 Radice Michl D
C2★Margolis Michl J
C3 Kumar Deepaak
C4 Jaeger Hattie Mrs 833-3067
3300 Vacant
UNIVERSITY AV BEGINS

179-C

UNIVERSITY AV BEGINS
NIAGARA FALLS BLVD BEGINS
3330 University Presbyterian Church 836-7660
3334 Kids Work Child Development day care 835-5863
3350 Child & Adolescent Treatment Services clinic 835-4011
3362 Wendy's Hamburgers restr 838-3684
3382 Subway 834-6878
3400 Militello's Luggage leather gds 833-1600
Life Uniform & Shoe Shop 833-2909
Apartments
1 Axaris Vassilios 833-0671
2★Pelekasis Nikolaos 838-6289
3★Keratsa Katy 833-8859
4 Habakis Manos F 836-9148
3404 Roehl Robt H phys 832-1250
Udagawa Salvatore M phys 835-0641
ALLENHURST RD BEGINS
3435 S U N Y A B Main St Library (medical) 831-2165
S U N Y A B college 831-9000
S U N Y A B (Farber Hall)
S U N Y A B-Anatomical Sciences 831-2912
Animal Diagnostic Laby 831-2832
S U N Y A B Western New York (geriatric educ cntr) 831-3176
Continuing Dental Education 831-2320
Children Dentistry Clinic 831-2723
Emergency Dental Clinic 831-2732
Endodontics Clinic 831-3847
Health Sciences Library 831-3335
Fixed Prosthodontics Clinic 831-2862
General Dental Clinic 831-2821
Operating Dentistry Clinic 831-2866
Oral Medicine Clinic 831-2241
Oral & Maxillofacial Surgery Clinic 831-2722
Orthodontics Clinic 831-2845
Patient Evaluation & Management Ofc 831-2720
Periodontal Disease Clinical Research Center 831-2853
Periodontics Clinic 831-3845
Post-Graduate Clinic 831-2755
Preventive Denistry Clinic 831-2860
Radiology Clinic 831-3930
Comprehensive Dental Care Program 831-2734
S U N Y A B Div of Diagnostic Serv 831-2842
Removable Prosthodontics Clinic 831-2862
Dental Materials Dept (Div Restorative Denistry) 831-2862
S U N Y A B School of Dentistry 831-2836
General Clinical Dentistry 831-2836
Hospital Dental Servs Div 831-2241
Restorative Dentistry 831-2862
S U N Y A B Dept of Endodontics 831-3847
S U N Y A B (Pritchard Hall)
Studt Residence
S U N Y A B (Mac Donald Hall)
S U N Y A B (Clement Hall) 831-3145
General Housing Custodial Information 831-3334
S U N Y A B (Schoellkopk Hall)
S U N Y A B (Hlth Sciences Lib) 831-2165
Center for Media Study 831-3436
S U N Y A B (Wende Hall)
Educational Communications Center 831-2304
Educational Television & Engineering Servs 831-3761
Instructional Development Center 831-2304
Visual Design & Production Center 831-2945
S U N Y A B (Michael Hall)
Environmental Health & Safety 831-3301
University Health Service 831-3316
S U N Y A B (Parker Hall)
S U N Y A B of Continuing Educ 831-2202
Financial Aid To Studts 831-3724
University Book Store 831-2444
S U N Y A B (Hayes Hall)
Admissions & Records 831-2333
Center for the Study of Aging 831-3834
Architecture & Environmental Design 831-3485
Library of Architecture & Environmental Design 831-3505
Office of Studt Accounts 831-2186
S U N Y A B (Goodyear Hall) 831-3145
Goodyear Food Serv 831-3306
Goodyear X Dining Room 831-3224
S U N Y A B (Foster Hall)
Diagnostic Services (Sch of Dentistry) 831-2842
Behavioral & Related Sciences 831-2056

477 Elmwood Ave. Fax 886-9007 Buffalo, N.Y. 14222

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAIN ST 1992

● HOMEOWNER

MAIN ST–Contd
S U N Y A B Dept of Oral Biology 831-2854
SQUIRE HALL
S U N Y A B Dept of Operative Dentistry 831-2862
S U N Y A B Dept of Oral Medicine 831-2241
Oral Surgery Dept 831-2722
S U N Y A B Dept of Orthodontics 831-2845
S U N Y A B Dept of Pediatric Dentistry 831-2724
S U N Y A B Dept of Periodontics 831-3848
Pharmacology & Therapeutics Ofc 831-2802
S U N Y A B Dept of Removable Prosthodontics 831-2862
S U N Y A B Div of Restorative Dentistry 831-2862
S U N Y A B Sch of Medicine 831-2811
S U N Y A B (Sherman Hall)
Medical Admissions Committee 831-3465
S U N Y A B Dept of Physiology 831-2738
Blood Group Research Unit 831-2901
Center for Immunology 831-2848
Microbiology Dept 831-2907
Virology Laboratory 831-2921
S U N Y A B (Harriman Hall) 831-3541
S U N Y A B Dept of Theater & Dance 831-3742
S U N Y A B (Acheson Hall)
Library of Chemistry 831-3278
S U N Y A B (Pediatrics Dept) 831-2351
Chemistry Dept 831-3014
S U N Y A B (Stockton Kimball Tower)
S U N Y A B School of Nursing 831-2734
S U N Y A B (Graduate Sch of Nursing)
Nuclear Research Center
Nuclear Science & Technology Facility 831-2826
S U N Y A B Dept of Physical Ther Exercise Sci 831-2941
S U N Y A B Sch of Health Related Professions 831-3434
S U N Y A B (Medical Technology) 831-2731
S U N Y A B Dept of Occupational Therapy 831-3141
S U N Y A B (Bethune Hall)
Art Dept 831-3479
W B F O F M 88 831-2555
S U N Y A B (Stockton Kimball Tower)
S U N Y A B Dept of Health Behavioral Sciences 831-2941
S U N Y A B (Diefendorf Hall)
S U N Y A B Dept of Mathematics 831-2144
S U N Y A B (Cary Hall)
Animal Facilities 831-2919
Biochemistry Department 831-2725
Biophysical Sciences Department 831-2324
Continuing Medical Education 831-2766
Bioinorganic Graduate Research Group 831-3258
Health Instrument & Device Institute 831-2446
Medical Alumni Ofc (Med Sch Annex)
S U N Y A B (Crosby Hall)
S U N Y A B (Goodyear Hall)
Emeritus Center 831-2271
S U N Y A B Dept of Pharmacy
S U N Y A B Dept of Sociology
S U N Y A B Dept of Statistics
S U N Y A B Dept of Stomatology
S U N Y A B Dept of Urology
S U N Y A B Dept of Political Science
S U N Y A B School of Architecture
S U N Y A B School of Otolaryngology
S U N Y A B School of Pathology
3435 S U N Y A B School of Pharmaceutics
S U N Y A B School of Philosophy
S U N Y A B Sch of Social & Preventive Medicine
S U N Y A B School of Social Work
S U N Y A B School of Surgery
3442 University Court Apartments 835-1161
1b Studt Res
2b Studt Res
A1 Studt Res
A2 Studt Res
A3 Van Verth Jas M Mrs
A4 Studt Res
A5 Studt Res
A6 Student Res
A7 Roberti Pauline 836-5862
A8 Studt Res
A9 Studt Res
A10 Davis Richd L 838-3663
A11 No Return
A12 Studt Res
A14 Studt Res
A15 Denzel J Jordan 836-0314
B1 Dalton John J Jr 832-0501
B2 Studt Res
B3 Adams Dorothy J Mrs
B4 Domres Hazel H 834-9412

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAIN ST 1992



236

B5 No Return 18
B6 Studt Res 20
B7 Breslin Jas M 836-5076 Re
B8 Studt Res 21
B9 Studt Res
B10 Studt Res 23
B11 Studt Res
B12 Studt Res 24
B13 Studt Res 26
B14 Studt Res
B15 No Return 27
C1 Studt Res 28
C2 Studt Res
C3 Studt Res 31
C4 Studt Res 33
C5 Hedman Linda E 832-3879
C6 Studt Res 34
C7 Kurumizawa Tomoko 836-8293 36
C8★Tameta Jocelyn 836-4811 37
C9 Studt Res
C10 Studt Res
C11 Studt Res 40
C12 Sostre Samary 838-2243
C13 Studt Res 41
C14 Studt Res
C15 Mantharam Mythili 836-7088 44
Bsmt Studt Res
CAPEN BLVD BEGINS 45
3484 Basil Ford Inc autos 833-8140
WINDERMERE BLVD BEGINS 46
3488 Seven-Eleven Food Store 836-9633
KENMORE AV BEGINS 47
BAILEY AV INTERSECTS
50

192

MAJESTIC TER (LACKAWANNA) 51
FROM 1944 ABBOTT RD EAST TO

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 1992



CITY LIMITS

127-A

NIAGARA FALLS BLVD –FROM 3310 MAIN NORTH TO KENMORE AV

ZIP CODE 14214

2 Brown John 834-7817
22★Kohrman Michl H ◎ 835-7425
37 Terry Bart S 837-7209
38 Gaglione Mariano C ◎ 835-7050
40 Paulus Kristen
41 Johnson John A ◎ 836-6197
42 Vacant
43 Lewis Lonny B ◎ 838-2503
45 Muldrow Leroy ◎ 832-6625

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 1992



46 Kassman Anthony J ●
50 Newberry Wilma J ● 835-0474
54 Metzger Michl M ●
PELHAM DR BEGINS
58 Brace Frederick ● 833-2272
62 Kowsky Francis R ● 836-6069
65 Mc Craty Edw J ● 832-2274
66 Klein Peter M ● 837-9007
69 No Return
70 Kogler Susan M Mrs ● 836-5436
73 Whitney Stewart B ● 835-0536
74 Onorato Victoria A Mrs ● 833-9426
77 Kendrick Willie J ● 833-1798
78 Mc Namara Emmet J Jr ● 834-6177
81 Koren David C ● 836-3271
82 La Plante Jerry ● 837-5830
85★Mc Guire S J 832-4303
86 Leising
89 Tabone Thos P ● 838-5668
90 Vozga Frank J ● 834-7941
95 Miller Donald E ●
96 Rissel Dorothy A ●
97 Sarikas Theo ● 832-0388
100 Beggs Donald W ● 833-7923
101 Patel Hazel Mrs ●
104 Montana Joseph A ● 836-2165
105 Collins Lavarn A ● 832-6375
109 Grayson Philip ● 837-3040
BELLEVUE ENDS
112 Burgin E Karl ● 832-1891
115 Taliaferro Stella M Mrs ● 833-0157
116 Toepfer Regina F Mrs ● 833-5868
119 Chmiola Chester S ● 832-4110
120 Davis Aubrey ● 837-6009
123 Bollman Eliz ● 838-6366
124★Cirrito Frank A ● 835-3677
127 Miller
128 Then Philip ● 836-8140
131★Herod Michl A ● 836-2601
132 Curtis Henry W ● 835-1747
136 Daum Fay A Mrs ● 833-2234
Daum James E real est broker
833-2234
139 Vacant
142 Lesser Geo V dentist 832-9337
KENMORE AV INTERSECTS

60

NIANTIC ST –FROM 68

Target Street	Cross Street	Source
-	✓	Polk's City Directory

KENMORE AVE 1987

ALLENDALE RD INTERSECTS

416

KENMORE AV (AMHERST)—FROM 3514 MAIN WEST

ZIP CODE 14226
FOR EVEN NUMBERS SEE BUFFALO
39 Neighborhood Card Shop 834-6115
41 Frisch Gustav A Inc optn & jwlr 833-5415
43 Taylor Services employment agcy 837-8100
47 Plaza Shoe Repair-Laundry & Dry Cleaning 836-4041
May Jen Chinese Restr 832-5162

417

WINDERMERE BLVD INTERSECTS
59 Da Vinci Jewelry Inc ret jwlry 836-4700
63 Hudecki Gregory E dentist 834-2744
Hudecki Stephen E dentist 834-2744
Hewson Robert A podiatrist 833-8094
Schaus James P Jr phys 832-1050
Sullivan James R phys 832-8044
71 Kenmore Avenue Medical Building
Buckley Richard J phys 835-4400
Gauchat Joseph C dentist 835-0155
Reynhout Jonathan phys 835-0130
Gage Andrew M phys
Carlo Gerald T dentist 836-1101
CAPEN BLVD INTERSECTS
95★Neffke Aug T ◎ 834-6612
99★Meyers Harold ◎ 838-4399
ALLENHURST RD INTERSECTS
135 Kenrick James C dentist 838-1286
★Sauer Hazel E Mrs ◎ 836-4553
143 Dohn Funeral Home Inc 834-8128
★Roberts Geo J 836-7551
175 Stop-N-Go Food Inc 832-8080

561-B

KENNEDY CT (TOWN OF

Target Street	Cross Street	Source
-	✓	Polk's City Directory

KENMORE AVE 1987



245

KENMORE AV (TOWN OF TONAWANDA & KENMORE) FROM 154 NIAGARA FALLS BLVD WEST

ZIP CODE 14223

181 Puehn Geo E meat mkt 833-4411
187 Lazarus Paul 834-5586
189 Words & Graphics Inc 835-5587
191 Brenner Geo 833-4968
193 Rozek Kenneth P © 834-2169
LARCHMONT RD ENDS
197 Magyar Susan L ©
199 Globnick Donald J 833-4532
Ilardo Laurence R 832-4815

Target Street	Cross Street	Source
-	✓	Polk's City Directory

KENMORE AVE 1987



203 Gates Electric Co Inc appl sls & serv
837-5311
T B I Credit Union
J M A Federal Credit Union
205 Nineteen Ten Hair Emporium 832-6558
GRANDVIEW AV BEGINS
HAWTHORNE AV BEGINS
217 Murphy Peter F 833-0068
Potts Kevin M ◎ 838-3625
225 Fanaro Fredk ◎
Le Baron Gertrude Mrs ◎ 833-1219
229 Werder Paul K chiropractor ◎
834-7974
Werder Brian F chiropractor
233★Hagerty Christopher 834-1239
★Gerwitz Tim 834-3648
RADCLIFFE RD ENDS
237 Nesselbeck Norman G ◎ 834-8552
241 Walter Albert E Jr ◎ 834-3761

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAIN ST 1987

600 Vacant
3164 Herzog's Drug Store Inc (Addl Sp)
3165 Miranda Real Estate 836-6600
University Taxi 832-3000
Northgate Auto Sales Inc used cars
3168 Herzog's Drug Store Inc 834-1970
3171 Latko Printing & Copy Center
31 835-0100
Vacant
Rear★Endo Mayumi
Rear★Sunadome Janko
W NORTHRUP PL BEGINS
NORTHRUP PL BEGINS
3172 Westworld Video Games 835-0077
3173 Copier & Duplicator Services
instrument dlrs 832-2255
3176 Universtiy Heights Teen Cntr
3178★Jainzhwong Chi
3180 Designed With Imagination balloons
& unique gifts 835-2068
3182 Foster Norine
3184 Queen City Book Store 833-6220
Queen City Book Store (Addl Sp)
3191★Wopperer James
3193 Turgeon Frank ◉
Jay Roslyn 837-9041
3198 Frank's Mobil Gas Station 836-5337
3199 Molly's Pub tavern 836-6559
3211 Wilson Farms Convenience Food
Store 834-4081
WINSPEAR AV INTERSECTS

179-B

WINSPEAR AV BEGINS
3208 Parkside Candy Co Inc 833-7540

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAIN ST 1987

240

3210★Kuhn Kenneth 832-0799
★Ernst Mark R
Crisis Pregnancy Center Of Western New York birth control info cntr 833-7100
Parkside Candy (Admn Ofc)
181 3212 Parlato-O'Brien Realty Inc 835-1020
3214 Chayban Custom Tailoring 833-5049
3216 Hair People The 832-8032
★Glinski Susan 836-7355
3218 College Laundry Shop The 833-0060
★Bankarung Kim 834-9350
3223 North Main Liquor 834-7727
3225 Pinzone's Pizzeria (Addl Sp)
Pinzone's Pizzeria 834-3810
3229 Buffalo Picture Frame & Mirror Corp 836-3800
MERRIMAC ST BEGINS
SUTTON LA BEGINS
3230 Goodwill Industries Store 835-0153
★Karans Peter
3233 Cantalician Center For Learning sch 833-5353
Dondajewski Lorita Sister
Wagner Harold Rev 836-5276
3234 Top Shelf Music Inc musical instr sls 832-1045
Amy's Place restr 832-6666
Meadows Sherrie
3236 Greenhouse The plants 833-5600
3240 O'Connell Lucas Chelf Inc ret clo 836-4140
3242 University Heights Community Development Assoc Inc 832-1010
University Heights Business Association Inc 832-1010
Buffalo & Erie County Public Library (Univ Hts Br) 832-7762
3248 World News books & magazines 834-0888
HEATH BEGINS
3258 Rifco Building
Suicide Prevention & Crisis Service Inc counseling serv 834-3131
3260 Affirms Inc automated fin reporting 837-4660
★Ferguson Eliz J
3262★Sauvageau Jeffrey J 836-9098
3264 Third Base tavern 833-1284
3268★Choudhukt Jftekka
Needle & Thread Tailor Shop 833-0789
Big Bob's University Bikes & Games 837-1121
3269 Saint Joseph's Roman Catholic Church 833-0298
Werth Chas M Rev 833-0298
3270 P J Bottoms Tavern restr & bar 833-3270
3275 Saint Joseph's Roman Catholic School 835-7395
Saint Joseph's Convent 833-7333
Costello Agnes M Sister
ENGLEWOOD AV BEGINS
3292 Chabad House jewish culture center 833-8334
3296 Chancellor Court Apartments
A1★Katz Margt 837-4194
A2 Schottin Dorothy B Mrs 835-2360
A3 Chuasid Steve 837-7447
A4 Brandt Cath M Mrs 834-9451
B1★Fassman Donna
B2★Mesolella Christopher
B3★Giardino Vincent
B4★Petkunas Donna
C1★Green Richd J
C2★Williams Donna C
C3★Rajan Dajanard
C3★Dobes Zuzana
C4★Hosein Zareeb Mrs

179

UNIVERSITY AV BEGINS
NIAGARA FALLS BLVD BEGINS
3334 University Presbyterian Church 836-7660
3350 Child & Adolescent Psychiatric Clinic Inc 835-4011
3362 Wendy's Restaurant 832-9594
3382 Sorentino's Two Restaurant 838-1644
3400 Militello's Luggage leather gds 833-1600
Life Uniform Shop 833-2909
Apartments
1 Vacant
2 Bellos John 838-6289
3 Karagounis John K 834-8405
4 Anayiotou Maria S 836-5508
3404 Dodd Michl H 838-2573
Udagawa Salvatore M phys 835-0641
ALLENHURST RD BEGINS
3435 Main Street Library (medical) 831-2165
S U N Y A B college 831-9000
S U N Y A B (Farber Hall)
Anatomical Sciences 831-2912
Animal Diagnostic Laby 831-2932
Continuing Dental Education 831-2320
Children Dentistry Clinic 831-2723
Emergency Dental Clinic 831-2732
Endodontics Clinic 831-3847
Health Sciences Library 831-3336
Fixed Prosthodontics Clinic 831-2862
General Dental Clinic 831-2821
Operating Dentistry Clinic 831-2866
Oral Medicine Clinic 831-2241
Oral Surgery Clinic 831-2722
Orthodontics Clinic 831-2845
Patient Evaluation & Management Ofc 831-2720
79-B Periodontal Disease Clinical Research Center 831-3853
Periodontics Clinic 831-3845
Post-Graduate Clinic 831-2755
Preventive Dentistry Clinic 831-2860
Radiology Clinic 831-3930
Comprehensive Dental Care Program 831-2734
Division Of Diagnostic Services 831-2842
Removable Prosthodontics Clinic 831-2862
Dental Materials Dept (Div Restorative Dentstry) 831-2862
School Of Dentistry 831-2836
General Clinical Dentistry 831-2836
Hospital Dental Servs 831-2241
Restorative Dentistry 831-2862
Dept Of Endodontics 831-3847
S U N Y A B (Pritchard Hall)
Studt Residence
S U N Y A B (Mac Donald Hall)
S U N Y A B (Clement Hall) 831-3145
General Housing Custodial Information 831-3334
S U N Y A B (Schoellkopk Hall)
S U N Y A B (Hlth Sciences Lib) 831-2165
Center For Media Study 831-2426
S U N Y A B (Wende Hall)
Educational Communications Center 831-2304
Educational Television & Engineering Servs 831-3761
Instructional Development Center 831-2304
Visual Design & Production Center 831-2945
S U N Y A B (Michael Hall)
Environmental Health & Safety 831-3301
University Health Service 831-3316
S U N Y A B (Parker Hall)
Division Of Continuing Education 831-2202
Financial Aid To Studts 831-3724
Financial Aid Systems 831-3724
University Book Store 831-2444
Office Of Urban Affairs 831-3474
S U N Y A B (Hayes Hall)
Admissions & Records 831-2333
Center For The Study Of Aging 831-3834
Architecture & Environmental Design 831-3485
Career Planning Ofc 831-3515
Library Of Architecture & Environmental Design 831-3505
Office Of Studt Accounts 831-2186
S U N Y A B (Goodyear Hall) 831-3145
Goodyear Food Serv 831-3306
Goodyear K Dining Room 831-3224
Inter-Residence Council Business Inc
S U N Y A B (Foster Hall)
Diagnostic Services (Sch Of Dentistry) 831-2842
Biological & Behavioral Sciences 831-2854
Dept Of Oral Biology 831-2854
Dept Of Oral Pathology 831-2051
Medical Faculty Council 831-3467
Medical Mail Room 831-2779
Microbiology Graduate Studies Ofc 831-2176
Dept Of Operative Dentistry 831-2862
Dept Of Oral Medicine 831-2243
Oral Surgery Dept 831-2722
Dept Of Orthodontics 831-2845
Dept Of Pedodontics 831-2724
Dept Of Periodontics 831-3848
Pharmacology & Therapeutics Ofc 831-2802
Dept Of Removable Prosthodontics 831-2862
Division Of Restorative Dentistry 831-2862
School Of Medicine 831-2811
Medical Business Ofc 831-2771
Medical Admissions Ofc 831-3466
S U N Y A B (Sherman Hall)
Medical Admissions Committee 831-3465
Dept Of Physiology 831-2738
Blood Group Research Unit
Center For Immunology 831-2848
Microbiology Dept 831-2907
Virology Laboratory 831-2921
S U N Y A B (Harriman Hall) 831-3541
Dept Of Theater & Dance 831-3742
Dept Of Theater & Dance (Technica Theater Shop) 831-3745
S U N Y A B (Acheson Hall)
Library Of Chemistry 831-3278
S U N Y A B (Pediatrics Dept) 831-2351
Chemistry Dept 831-3014
S U N Y A B (Stockton Kimball Tower)
School Of Nursing 831-2734
School Of Nursing (Graduate) 831-2210
Nuclear Research Center 831-2826
Nuclear Science & Technology Facility 831-2826
Dept Of Phyiscal Therapy & Exercise Science 831-2941
School Of Health Related Professions 831-3434
Undergraduate Medical Technology Admissions 831-2731
Dept Of Occupational Therapy 831-3141
S U N Y A B (Bethune Hall)

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAIN ST 1987



MAIN ST–Contd 99
Art Dept 831-3479
S U N Y A B (Allen Hall) 11
American Association Of University Professors 831-2424 11
Graduate School Of Social Work 831-2526 11
W B F O F M 88 831-2555 12
S U N Y A B (Stockton Kimball Tower) 12
Faculty Of Health Sciences
S U N Y A B (Diefendorf Hall) 13
Dept Of Mathematics 831-2144
S U N Y A B (Cary Hall) —
Animal Facilities 831-2919
Biochemistry Department 831-2725 M
Biophysical Sciences Department 831-2324 1
Continuing Medical Education 831-2766 10
Bioinorganic Graduate Research Group 831-3258 12
Health Instrument & Device Institute 831-2446 14 15 16
Medical Alumni Ofc (Med Sch Annex) 17 18
S U N Y A B (Crosby Hall) 20
S U N Y A B (Townsend Hall) (med sch annex) 22 24
Emeritus Center 831-2271
3442 University Court Apartments 835-1930 28
1b Studt Res
2b Studt Res 29
A1 Nau L
2a Studt Res 30
A3 Studt Res
A4 Miyaji Masamichi 837-0338 1
A5 Studt Res —
A6 Burmaster
A7 Pados Chas 837-8969 M
A8★Boyd John 1
A9 Chamberlin Linda 836-4148
A10★Headley Diane 2
A11 Dempsey Donovan V 838-6051 9
A12★Roletta Michl 22
A14★Singh Om 838-5699
A15 Mahl John F 832-1363
B1 Dalton John J Jr 832-0501 —
B2 Tucker D
B3 Adams Dorothy J Mrs M
B4 Domres Hazel H 834-9412 1
B5 Holtham Robt 837-4649
B6 Vacant 2
B7★Breaslin Lilien Mrs 14
B8 Vacant 15
B9 Liu Kenneth
B10 Mayfield Mary L Mrs 836-6843 17
B11★Maloney Margt
B12 Bradley Margt E 837-1354 18
B14★Rozak Mohamed M 20
B15 Doerr Jean 832-0332 Re
C1★Haney Stewart 21
C2 Vacant
C3 Mc Vorran Irene M Mrs 23
C4★Shamram Saiedeh
C5★Hedman Linda 832-3879 24
C6★Mira Mirjanda 26
C7★Quaze Shafat
C8★Lin Kim Soo 27
C9★Sus Kenneth P
C10★Tseng Ching C 28
C11★Phillips Lisa
C12★Tripodi Karen 31
C14 Kwitchoff Marion Mrs 33
C15★Mantharan Myrtile 836-7088
Basemnt★Wesley Michl 836-8076 34
CAPEN BLVD BEGINS
3484 Basil Ford Inc autos 833-8140 36
WINDERMERE BLVD BEGINS 37
3488 Seven-Eleven Food Store 836-9633
KENMORE AV BEGINS 40
BAILEY AV ENDS
3940 Illos Piano Rebuilders & Music Cntr 832-0013 41
44

192

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAIN ST 1987

106 Vizzini Sami @ 689-9395
RED OAK DR INTERSECTS

416

MAIN ST (AMHERST
WILLIAMSVILLE)-A CONTINUATION
FROM BUFFALO CITY LIMITS EAST

ZIP CODE 14226

3500 Manufacturers & Traders Trust Co (Br) 832-9523
Carol's Apparel Coat Co clo retail 833-0533
Two Thousand One V I P Club Of Buffalo night club 837-2001
Grandma Lee's Bakery & Eating Place restr 838-1391
Amherst Theatre 834-7655
Tops Market supermkt 837-8470
3582 Tux Ego Inc tuxedo rental 833-8812
3584 Delaware Camera Mart Inc 836-0715

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAIN ST 1987



MAIN ST (A)—Contd

Zobrest Edw

3586 Waterbeds & Stuff 834-3955

★Po-Chedley Robt

3588 Vacant

SPRINGVILLE AV BEGINS

3604 Speaker Shop Inc stereo equip sls 837-1557

3606 Vacant

3608 East River Savings Bank (Western Div) 834-2323

3610 Laco Book Stores 833-7131

3612 University Manor Motel Inc 837-3344

CALLODINE AV BEGINS

3640 Burger King (Resser Management Corp) 836-2288

N BAILEY AV INTERSECTS

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 1987

VULCAN BEGINS
CITY LIMITS

127-A

NIAGARA FALLS BLVD –FROM 3310 MAIN NORTH TO KENMORE AV

ZIP CODE 14214
2★Avdenko Michl 834-7812
22 Ferguson Charles E ◎ 833-8422
37 Caster John W 835-8727
38 Gaglione Mariano C ◎ 835-7050
40 Chi Omega Sorority House 832-1149
41 Johnson John A ◎ 836-6197
42★Toelsin Wm C ◎ 834-5413
43 Krystaf Maney M Mrs ◎ 833-7799
45 Ebony Construction genl contr 832-4420
Muldrow Leroy J ◎ 832-6625
46 Kassman Anthony J ◎
50 Newberry Wilma J ◎ 835-0474
54 Metzger Michl M ◎
PELHAM DR BEGINS
58 Brace Frederick ◎ 833-2272
62 Kowsky Francis R ◎ 836-6069
65★Mc Craty Edw J ◎ 832-2274
66 Klein Peter M ◎ 837-9007
69 Steele Clara H ◎ 834-4107
70 Kogler James F ◎ 836-5436
73★Kubala Chas A 835-4249
74 Onorato Victoria A Mrs ◎ 833-9426
77 Stegner Bruce E ◎ 833-9387
78 Mc Namara Emmet J Jr ◎ 834-6177
81★Koren David C ◎ 836-3271
82★La Plante Jerome C ◎ 837-5830
85 Maguire Sylvia J Mrs ◎ 832-4303
86 Murphy Danl C ◎ 837-3058
89 Tabone Thos P ◎ 838-5668
90 Vozga Frank J ◎ 834-7941
95 Ansell Danl J ◎ 833-3279
96 Kean Odelia C Mrs ◎ 834-4774
97★Sarikos Theo ◎ 832-0388
100 Beggs Donald W ◎ 833-7923
101 Patel Hazel Mrs ◎
104★Montana Jas P ◎ 836-2165
105 Collins Lavarn A ◎ 832-6375
109 Grayson Philip ◎ 837-3040
BELLEVUE ENDS
112 Burgin E Karl ◎ 832-1891
115 Taliaferro Stella M Mrs ◎ 833-0157
116 Toepfer Regina F Mrs ◎ 833-5868
119 Chmiola Chester S ◎ 832-4110
120 Davis Aubrey ◎ 837-6009
123★Lostaunau Michl J ◎ 838-6366
124★Hall David ◎ 838-4029
127 Sanders Virginia E Mrs ◎ 838-5976
128 Thew Philip ◎ 836-8140
131★Audel Michl W ◎ 837-3969
132 Curtis Henry W ◎ 835-1747
136 Daum Fay A Mrs ◎ 833-2234
Daum James E real est broker 833-2234
139 Vacant
142 Lesser Geo V dentist 832-9337
KENMORE AV INTERSECTS
154 Salemi's Pizza And Subs 837-2424

60

NIANTIC ST –FROM 68 SHENANDOAH RD NORTHEAST TO POTTERS RD

3518 SOUTHWESTERN BLVD. • BUFF

USE ZIP CODE

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 1987



CITY LIMITS

245

NIAGARA FALLS BLVD (TOWN OF TONAWANDA)–FROM 181 KENMORE AV NORTH

ZIP CODE 14226
38 (FOR LOWER NUMBERS SEE BUFFALO CITY DIRECTORY)
EVEN NUMBERS ZIP CODE 14223
154 Salemi's Pizza 837-2424
Bradley David
158 Weiss Norman J optom 836-3250
165 Shastri Subramanya R phys 836-3411
Almon & Associates consultants 833-3031
Almon Susan M 833-3845
166 Halt James G Graphic Design 836-4439
170 Lux Charles N ◎ 835-3653
Dark Mary J 834-2133
Szczepanek Mary 838-2628
171 Bozek Donald A ◎ 837-5277
★Boghofian Leslie 837-0866
174 Ricotta Josephine C Mrs ◎ 834-9634
Wood Stella B Mrs 837-3134
177 Kam Joseph Jr chiropractor ◎ 835-5400
179 Hagen Wm R ◎ 834-6821
180 Apartments
1 Roussi Helen C Mrs 832-3078
2★Hamric Kevin
3 Smith Matthew J 838-3069
4 Rust Gregory 833-6419
186 Le Bar George ◎ 834-5929
189 Feuerstein Marvin E ◎ 837-6586
Denture Center Of Buffalo 834-1133
190 Odea John J 833-3542
★Kalen Cindy 838-6873
192 Cocchi Andrea 837-6195
195 Puehn Geo E ◎ 833-6533
198 Vacant
★Bates Ned 832-5724
199 Mc Call N Churchill ◎ 833-5939
200 Lee Judy
Wagner Joyce A
202 Varga Eliz M Mrs 836-7579
Vidler Richd J 832-6760
204 Wollsoncroft David A 836-1564
Galnes Stacy
206 Masman Jean S Mrs 835-7256
Totaro Angeline J Mrs 837-5796
207 Nice Wm ◎ 837-4457
208 Bock Anna Mrs 835-2898
★Anderson Alice 834-1966
213 Hoolihan Eleanor R Mrs ◎ 834-2950

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 1987

NIAGARA FALLS BLVD (TT)–Contd

O'Neil Gertrude M Mrs 832-7507 373
218 Cortellucci Mary L Mrs ● 834-3674 378
Burnett Janet 382
219 Amoroso Albert R ● 837-7187
Amoroso Albert M 835-2115 383
222 Gisel John C ● 832-8647 386
Ciolczak Henry B 833-6595
225★Fiorella Robt 833-4579 389
Mc Knight Callie
228 O'Shaughnessey Terrence J ● 837-6153 390
Kemp Sharon Mrs 834-5087
231 Haines Judy 838-1155 394
Mc Kenna Kathleen E 836-7018 395
232 Van Etten Ronald W ● 834-7851 396
KENILWORTH AV BEGINS 398
237 Haarmeyer David A 838-4944 399
Puerner Lawrence W ● 838-3200
240 Hills Robt M 834-6273 405
Shisler M 838-3260 406
Student Residence 409
Pippin For Hair beauty salon 832-1060 410
244 Anthony's Barber Shop 836-7883 414
Great Lakes Divers Inc 836-6900 415
248★Weinbaum Cheryl 838-6929 418
249 Ruffino Robt J ● 832-7435 422
Kerney Victor V 834-2775
252 Dussault Wayne A ● 838-1810
254 Becker Barbara Mrs ● 833-4644
PRINCETON AV BEGINS
255 Dzimian Paul J 834-2372
Ryan T J ●
258 Baldi Joseph F ● 832-9909
261 Schmidt Martha C ● 834-4655
Voltura Grace J
262 Pragel Sheila ● 832-4352 42
267 Piazza Joe
Friedman Dani A ● 832-1034 42
268 Hodur Darrel L ●
270 Then Irene M Mrs ● 832-9555
273★Hare David R 832-7933 42
274 Isenberg Edw 836-6044 42
276 Fanara Antonio ● 43
279 Rindfleisch Ronald 836-5948 44
280 Lorig Clara Mrs ● 837-6029
285 Meinkes Irving ● 833-4136
286 Cleary John T ● 834-7552
290 Connell Anna 833-5895 44
291 Mattina Rita F Mrs ● 833-4049 44
Sal's Electrical Maintenance Service Inc
elec contr 894-0577 Re
292 Plumsteel Charles C ● 832-2144 45
297 Niroomand Shahin A phys ● 834-9390 45
298 Formato Salvatore C ● 837-6833 45
300 Lambert David E ● 834-6976 46
303 Michotek Michl J 837-6767
304 Walsh Geo E Jr ● 835-2943 46
308★Fimbel Richd P ● 834-2495 46
309★Wilson John T Jr 838-1229
310 Godleske Thos J ● 835-5693
315 Dimascio John 832-2810 47
316 Carducci Anthony J ● 837-2469
320★Richard Mark
Rear Vacant
321 Delles Joan M Mrs ● 833-2164
324 Zimpfer Helen V Mrs ● 836-4394
327 Sommer John G Jr ● 837-7145
328★Kindron David 837-6845
330 Ebert Jack C ● 837-9234
333 Sheldon L M 838-5727
334 O'Brocta Louis J ● 835-0740
338 Wackowski Henry W ● 832-1444
339 Poloncarz Robt A ● 836-6030
Hayden Cheryl
342 Lundquist Robt D ● 836-2130
344★Masterson Jim ● 836-3030
FORD AV BEGINS

245-A

345 Still Wm G 836-4797
Vacant
354 Mesmer Dairy (Stge)
Mesmer Dairy Stores Inc 836-8690
CAMBRIDGE BLVD BEGINS
358 Wheeler Wm J ● 837-5880
362 Imler Lilias Mrs ● 836-4906
363 Fixers The home improvement contr
832-6604 47
Princess House Crystal 832-6604
Cox Bruce H ●
369 Schurkus Mark J ● 838-1969
370 Cuccaro Paula 837-5742
Yayathi Tejaswin ● 836-5989

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 1987

Mahajan Anil 834-6365
373 Vacant
378 Marter Adoph J ● 834-2058
382 Crist Georgina M Mrs 835-3181
Stabl Josef ● 835-4031
383 Onacko Andrew ● 836-0666
386 Franklin Clarence D 832-7106
Heavern Richd 837-2831
389 Stehlin Victor F ● 832-9590
Stehlin Richd
390 Barth Florence M Mrs ● 833-2010
Jones Jean M 837-4149
394★Kelleher Thos ●
395 Hawks Edgar J ● 832-9848
396 Dunn Roy G ● 836-8695
398 Barnes Timothy B ● 836-0337
399 Meyer's Real Estate 838-5966
★Myers Robt ● 838-5966
405★Habermehl Chas E Jr ● 833-8322
406 Vacant
409 Beach Carl A
410 Davies Bernice F Mrs ● 836-4768
414 Barber Edw J ● 834-3615
415 Buttino Michl E ● 836-3515
418 Vacant
422 Buffalo String Shop sls-rents-repr instruments 837-8900
Boulevard Barber Shop 834-4999
Thermal Technology Laboratory research & development 836-6680
Williams Eamigh & Associates ins 833-5351
Lay Richd V dentist 835-3906
Vacant
Kolstad Associates mfg rep 834-1445
423 Heverley Larry H ●
PAIGE AV BEGINS
424 Cadet Cleaners (Br)
Sweeney's Garage auto repr 832-0648
Sweeney John H ● 832-0648
428★Kramer R 835-0781
429 Barnes Kath I Mrs ● 832-3856
435 O'Connor Peter J ● 838-4351
442 S & E Wholesale Inc jwlry-genl appls 832-1595
Full Gospel Fellowship religious org 832-1595
443 Nutefall Danl L ● 836-5334
446 Diebold Gerald 838-6975
Coale Marjorie P 835-8953
Rear Mycek Clara Mrs 836-7074
450 Check Liquor Store 835-6300
453 Carlino Francis P ● 832-0491
459 Bousamra Chas L ● 836-5506
462 Rental City trucks trailers power tools 833-4818
465 Burnis John ● 833-2555
466 Boulevard Graphics design 833-2588
Vacant
OXFORD AV BEGINS
474 Towne Professional Bldg
Rooms
1 M M L Enterprises accts 834-8100
1 A B C Tax Service Inc acct 834-8100
2 Bechtel Computer Co comp sls & serv 833-6815
3 Western New York Institute For The Psychotherapies sch 837-6660
3 Anchin Jack psychologist 837-6660
3 Crum Houston L psychologist 837-6660
3 Laing Margaret psychologist 837-6660
3 Newman Morris psychologist 837-6660
3 Osberg Timothy psychologist 837-6660
3 Robinson Milton psychologist 837-6660
3 Shefrin Russell psychologist 837-6660
3 Zannoni Joseph psychologist 837-6660
3 Zannoni Ralph psychologist 837-6660
3 Zeidenberg Phillip psychologist 837-6660
4 W N Y Institute For The Psychotherapies (Addl Sp)
5 All State Mechanical Inc
6 Frohe Adele N lwyr 834-5372
7 Matteliano James C dentist 832-1678
8 Yassa Fayek G phys 838-3306
CHALMERS AV BEGINS
479 Krieger Wm A chiropractor ● 832-7233
Care Chair Wheelchair Van Service Inc 835-9072
Penke Christopher chiropractor 832-7233
482 Hello Dolly's Lounge restr 836-9357
Di Natale Vita M ● 837-2092
483 Gagliardi Fredk J ● 833-5295
489 Schlagher Joseph D ●
495 Wong Mun F ● 832-8347
500 Dip-N-Dive Inc scuba center 837-3483
505 Wong Sue K Mrs ● 837-4918
512 Cathay Gardens Inc chinese restr 837-3444
513 Leach Jon I ● 838-1771
519 Saxena Suresh ●
523 Janese Carolyn Mrs ● 837-6936
528 Bolea V & Son Upholstering & Furniture Shop 835-3932
Pietrocalo Coiffure beauty shop 834-5727
Leonard's Barber Shop 834-0036
529 Blair Donald J ● 832-4152
535 Woloszyn Steph ● 837-6475
536 Lakeland Auto Supply 834-2776
540 Lincoln Park Pharmacy Inc 832-7800
U S Post Office (Lincoln Park Br) 832-7800
543 Paeplow Charles E ●
546 Big John's Pizza & Subs 836-4881
549 Ashley Heber ● 832-0520
553 Vacant
DECATUR RD BEGINS
244-A
559 Meyer Raymond H ● 832-0583
563 Pufpaff Lisa D
564 Heiman Herbert ● 832-7989
569 Studt Residence
570★Diederich Ralph B real est broker 837-3131
579 Peifer Carl A ● 832-0910
580 Fix Joan W Mrs ● 835-1651
YALE AV BEGINS
588 De Priest Florence T Mrs ●
593 Kielich Ronald J dentist ● 834-3568
594 Diamond Anthony A ●
599 Mason Robt D Agency ins 832-1484
Auto Driveaway Co auto forwarding 833-8500
599½ Parker Bernice
600 Vacant
605 Loudy Dorothy M Mrs ● 835-3633
608★Giles Greg ●
613 Davis Allen 833-7396
616 Szymanski Edw J ●
619 Haq Muhammed F ● 834-0547
624 Bartley John I ● 832-4645
625 Dudkowski Edw ●
628 Kelsey Anthony N ● 833-8977
633 Tobin Robt ● 835-4140
634 Mobley John ● 832-6433
639★Meli Raymond ●
640 Wolff Paul A ● 833-0154
643 Clark Thos R ● 836-0205
644 Liscavage Leona E Mrs ●
649 Youngman Morris L music tchr ● 836-4158
650 Eaton Wendell L ● 832-8987
653 Johnson Willard E ● 838-4479
654 Blue Eva J Mrs ● 835-7255
LINCOLN PARK DR ENDS
659 Nowocien Richd W ●
663 Menchetti Carl H ● 832-3418
664 Morrow Jane Mrs ●
665 Minick Howard E ● 834-8061
668★Hoyt Dale J ● 832-1204
669 No Return
670 Kirbis Robt W ● 835-8819
673 Vacant
674 Ranney Mildred A Mrs ● 835-1198
LONGMEADOW RD BEGINS
677 Silverstein's Kosher Poultry kosher chicken sls 836-0762
678 Poplawski Gordon S ● 832-5347
679 Boulevard Pizza Submarine Take Out 838-4545
681 Feel-Rite Health Food Shoppe Inc 834-3385
684 Pray Donald P ● 832-7793
688★Dugan Thos 835-1414
694 Kirbis John J ● 836-7639
698★Tag Elaine 838-3280
704 Janeczko Wm W ● 834-8551
710 Aluma-Way Construction Co Inc alum constn 832-2291
Blom Robt G ● 835-8447

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 1987

174

NIAGARA FALLS BLVD (TT)--Contd
711 Trinity United Methodist Church 835-7711
716 Bingel Wm E ● 832-5003
722 Priamo Gerald A ● 832-2407
728 Janus Lutz J ● 836-8212
733 A F Automotive 833-0228
RUTH AV BEGINS
738★Dickey Ron G 836-8254

243

HIGHLAND AV ENDS
748 Powell A Mrs ● 837-1397
751 Hector's Hardware & Paint Co Inc 832-9310
754 Vacant
758★Geraci Joseph T Jr ● 835-9633
765 Christian Fellowship Baptist Church 837-1664
Christian Fellowship Baptist Church (Office) 835-2899
Christian Fellowship Baptist Church (Parsonage) 836-6628
770 Link Fox & Lord Funeral Home 832-6588
Lord Isabella C Mrs 832-5178
HARRISON AV ENDS
771 Buffalo Bronze (bronzing shoes & etc)
773 Chain's Enterprises Inc import clo 837-8344
Chain's India Boutique & Hong Kong Tailors tailor made clo jwlry & gifts 832-2075
782 Tangen Dairy Products custard stand 834-2447
785 Lincoln Park Motel Inc 837-7400
Lewecki Donald 835-7216
789 No Return
796 Aquarian Book Center 835-7888
797 Jolly Jug tavern 836-9552
800 Boulevard Beauty Salon The 836-5280
802 Lincoln Park Barber Shop 836-9402
803 Empire Auto Electric Ltd electrical sys 835-2424
Burgio & Campofelice Inc genl contrs 833-5171
BETINA AV BEGINS
804 A A Furniture Co sls 833-1977
MOORE AV ENDS

243-B

826 Wood's Jim Tire & Battery 833-7744
828 Freedman A Electrical Contractor Inc 833-0940
832 Vacant
839 M M I S marine sup ret 838-5200
Gianni's Hair Salon 834-5993
G & W World News Distributors 839-3900
Radio Shack Computer Store comp sys & equip
Bender's Christian Supplies ch gds 835-2909
843 Schifferle Steven K 837-0046
★Schifferle Michl
Maintenance & Management Associates Inc jan serv 836-2111
845 Sentry North Appliance Service Co 835-2991
847 Jean's Tailor Shop 834-5567
850 Vacant
Ichi Hana restr 832-1585
853 Vacant
860 Kenilworth Electronics Co 837-6666
Shaw-Barton Inc splty adv 833-4193
Night Life Enterprises Inc publ
861 Wahl Philip J ● 837-6293
865★Confino Linda
869 Building
Smolen Anthony B & Co cpa 834-6111
Freeman Joseph consulting eng 837-4800
Sung John J cpa 833-3422
Gellman Sigmund acct 838-1921
Goodman Steven J acct 835-3645
871 Building
Gordon James Image Makers Inc photo 837-5665
Desired Image fashion consultants 834-1123
Desired Image International cosmetologist 834-1123
Vacant
Weinstein Kenneth cpa
Tonkonagy Mordecai cpa
Hawes Herbert cpa
874 Corsi Auto Body & Glass Inc auto body repr 835-2455
899 Vacant
900 Pearce & Pearce Co Inc real est 833-6600
910 David Photo Service Inc 835-4620
920 General Accident Insurance
Kim's Oriental Food & Gift gro 832-1188
A S Of Dance 834-3350
925 Boulevard Moving & Storage (Div U-Haul Inc) 832-3799
926 U L Auto Body Shop auto body reprs 838-2200
934 Speedy Muffler King 838-6400
EGGERT RD INTERSECTS
951 Denny's Restaurant Inc 837-5657

241-A

AMHERST BEGINS
ZIP CODE 14226
SHERIDAN DR INTERSECTS
995 Firestone Tire & Rubber Co 837-9700
1009 Barnaby's restr 832-6054
TONAWANDA PO
ZIP CODE 14150
1016 Campos Photography Center film processing 837-1016
Vacant
1021 Vacant
1030 Santora's Cafe Pasta Inc 833-4255
1055 Vacant(3 Busn 1055-1059)
1060 Boulevard Square Plaza
Brass Bedroom The ret furn 838-2222
Naked Furniture ret
Movies Plus Super Video Center movie rntls 834-7144
Stereo Plus 838-3790
O'Hare's hair stylists 835-1388
Bright Ideas Science Center sci laby dlr 836-1690
Discovery Shoppes science & hobby shop 836-1690
Mei Yuan Restaurant
1061 Plant Place & Flower Basket ret florists 838-3400
August Boutique 833-4335
1065 Vacant
1089 Village Green The bookstore 836-8960
1090 Rosa's Home Appliances ret appl sls 835-6155
1094 First Care Physician P C med cntr 832-8355
ROCHELLE PL BEGINS
1101 Maternity Warehouse Outlet 836-5183
H & R Block income tax servs 838-3343
Rich James P Insurance Serv 833-1900
Neat Repeats used clo 838-5624
★Keene Geo A 832-0180
Keene Geo A Inc genl contrs 832-0180
ALMEDA AV BEGINS
1120 Cavalier Motor Lodge (addl sp)
1139 Cavalier Motor Lodge 835-5916
De Luca Nicholas
Cavalier Restaurant & Lounge Inc 837-8270
1140 Klein Harold N ● 834-2996
1154 Brand Names Sales Inc genl mdse 834-5094
1155 Eaton Office Supply Co Inc 837-6800
BRIARHURST DR BEGINS
1167 Carubba Collison auto body repr 834-0466
1171 Midas Muffler 837-4100
1172 Vacant
1185 Boulevard Mall Racquetball Club 833-6276
1188 Manufacturers Hanover Trust Co 837-0760
TREADWELL RD BEGINS
1200 Knapp Shoes 832-6530
1201 Suburban Lanes Inc bowling 836-0222
Suburban Lanes Pro Shop sporting gds 836-0222
Suburban Lanes Coffee Shop restr 836-0222
ZIP CODE 14226

(716) 874-1511 2760 Kenmore Avenue, Tonawanda, NY 14150

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 1987

1203 Boulevard Mall shopping center 834-8600
Frontier Fruit & Nut Co ret
Piercing Pagoda jwlry sls 837-6632
Silver & Gold Connection jwlry 835-0720
Fashion Island Jewlery & Gifts ret 833-4184
Tees 'n Tops iron on decals 835-5053
1203 Limited Express clo 834-5864
1205 Citibank (addl sp)
1207a Merry Go Round clo ret 837-6209
1207b Foxmoor Casuals clo ret 836-9181
1208 Dinettes & More ret furn 836-8070
1209 Spencer Gifts gift shop 835-8157
1210 Vacant
1211 Kinney Shoes 834-1552
1213 Lane Bryant (Br) clothing retail 837-2500
1219 Wicks & Sticks candle 838-1103
1221 Hanover Shoes 837-7471
1-A 1225 Pleasures & Pastimes craft shop 833-8775
1227 Mc Donald's restr 833-9525
1229 Stuarts Plus wm clo ret 835-0833
Carroll M J ladies clo 832-6177
1228 Casual Male Big & Tall mens clo ret 836-9317
1229 Stuarts womens clo 836-6910
1231 Gutman's Inc womens apparel 837-3100
1233 York's Choices restr 832-7030
Gap The clothing store 836-8080
1234 P K Discount Drugs Inc 835-2100
P O Sub Sta No 4 835-2100
1235 Sample Inc dept store 833-6717
2 1237 Claire's Boutique 835-4430
1239 Thom Mc An Shoe Store 836-9928
1241 His Place men's clo 836-8740
1242 Bison Plumbing City 837-3117
1244 Century Twenty-One M J Peterson real estate 833-3433
1245 Certified Finance Company Inc 832-2281
1246 Answer The womens clo 836-5955
1247 Laux Sporting Goods Inc 832-2774
1248 Six Months To Sixteen Years Shoes Inc 837-9632
1249 White Shoe Store 692-8847
1250 Watch World jwlry 835-2241
1251 Boulevard Mall Bootery 832-4903
0 1252 Van Scoy Diamond Mine 836-2210
1253 Flagg Brothers Shoes retail 832-5566
1253a Vacant
1253b Orange Julius 834-1324
1254 Asian Oriental Rugs ret 833-2127
1255 Sibley's dept store 837-9400
Glenby Beauty Salon 837-9400
1257 Building
Suites
301 Eastern Arts gift shop 835-8315
305 Original Cookie Co The ret bkry 833-1077
309 Mothercare ladies clo ret 836-3492
30 313 Wild Pair ret shoes 837-1476
317 Delaware Camera Mart ret cameras 836-4011
329 Altiers Naturalizer ret shoes 837-0885
333 Petite Sophisticates ladies clo ret 836-1979
337 Chess King mens clo ret 836-8883
341 Artworks ret pictures 836-0900
345 Scandia Down Shop ret bedding 834-0937
1258 Your Host Restaurant Inc 836-9579
1267 Manufacturers & Traders Trust Co (Blvd Mall Ofc) 832-0343
1269 A A Paradise pet shop 694-7450
1270 Eastern Mountain Sports Inc sport gds 838-4200
1271a Ups & Downs clo 836-9113
1271b Eve's cards & gifts 836-6976
1273 Fanny Farmer Candy Shops Inc 833-0203
1275 Vacant
1277 Next Step Shoes retail 837-4406
2 1279 Krasner's womens clothing 834-4084
1280 Goodyear Service Stores tires & auto accessories 837-8720
1281 Consumer Value Stores pharm 836-1857
1283 Reed's Jewelers 837-3934

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 1987



NIAGARA FALLS BLVD (TT)–Contd

1285 Kleinhans men's clo 837-9280
1287 Fanci-Pans kitchen utensils 836-7608
1289 Goldman's Shoes (br) 835-3414
1291 Ruby's restr 836-4004
1293 David's Specialty Shop women's apparel 836-6682
1295 Jenss dept store 837-1100
Jenss Beauty Salon 834-6434
Jenss Decor gift shop 837-1100
Jenss Card Shop stationery 837-1100
1303 Penney J C Co Inc (Br) 837-2100
1304 Sizzler Family Steak House 693-2318
1312 Pearle Vision Center optn 833-8338
1330 Building
Floors
1st Fl Classy Formal Wear tuxedo rntls 837-4700
1st Fl Fantastic Sam's unisex hair stylist 837-0019
1st Fl Botticelli Inc ret clo 837-1122
1st Fl Kwik Kopy Printing 837-4453
1st Fl M & W Camera Center camera equip sls 833-6110
2d Fl Kaplan Stanley H Educational Center Ltd test prep splst 837-8022
2d Fl Liggett & Myers whol tobacco prods 836-7000
2d Fl Allstate Insurance Co 835-5202
Hyatt Legal Services lwyrs 832-7777
1346 Bauer Radiator car radiator sls & serv 834-8822

240-A

MAPLE RD BEGINS
1355 Delta Sonic Car Wash 832-4050
1370 Arthritis Foundation (W N Y Chapter) 837-8600
Boulevard Counseling Center-Co 2 833-3708
Vana Josef consulting psychiatrist 833-3708
Pristach Cynthia consulting psychiatrist 833-3708
Vacant
Multiple Disabilities Continuing Treatment Program 837-0365
Corporation II Boulevard Day Treatment 837-6822
Alcoholic Treatment Center org
1376 Tin Lizzie Restaurant & Lounge The 836-1717
Horseless Carriage The motel 836-2940
1385 Mc Donalds Restaurant 837-9255
1395 Arby's Roast Beef 832-5231
1400 Pizza Hut drive in restr 835-3636
1401 Century Twenty One Glass real est 838-5300
1405 Foster Thayer Co Inc kitchen sls cabts 838-5106
ZIP CODE 14150
1420 Burger King restr 836-0117
BRAXMAR RD BEGINS
MEYER RD BEGINS
1435 S T S Car Service Center 833-3400
1436 Country Treasures & Tole craft shop 834-8653
Tony's Of The Blvd Barber Shop 836-8962
John's Pizza & Sub Shop 832-4343
1450 Building
Rooms
100 Vacant
101 Conveyors & Drives Inc 837-6165
102 Vacant
1456 Santangelo's Hair Designers 834-3995
1459 Flanigan's Furniture 834-7171
National Auto Supply 836-2751
Sounds Great Inc stereo equip sls & serv 838-4600
Vacant
Burnham's J Inc ret appliance 834-2720
1500 Delia Volkswagon 836-4600
1508 Stephensons Rental And Beechers Party Time Inc equip rental 837-6361
1520 Truck 'n' Stuff auto repr 834-1700
YORKSHIRE RD BEGINS

240-D

1550
1551
1561
1570
GLE
1590
1592
1594
1596
1598
1600
1602
1604
1606
1608
1610
1612
1616
1620
1621
1660
GRE
1676
1694
1701
1705
1715
1730
1750
NEW
OVE
1868

Target Street	Cross Street	Source
-	✓	Polk's City Directory

KENMORE AVE 1983



ALLENDALE RD INTERSECTS

416

KENMORE AV (AMHERST)—FROM 3514 MAIN WEST

FOR EVEN NUMBERS SEE BUFFALO ZIP CODE 14226

39 Foremost Wine & Liquor 835-5477
41 Frisch Gustav A Inc optn 833-5415
43 Taylor Services 837-8100
47 Plaza Shoe Repair-Laundry & Dry Cleaning 836-4041
May Jen Chinese Restr 832-5162

417

WINDERMERE BLVD INTERSECTS

59 Behringer Earl Diamonds Inc retail jwlry 836-4700
Haircuts Underground barber shop 836-1781
63 Hudecki Gregory E dentist 834-2744
Hudecki Steph E dentist 834-2744
Schaus James P phys 832-1050
Silvert Allen G podiatrist 833-8094
Sullivan James R phys 832-8044

Target Street	Cross Street	Source
-	✓	Polk's City Directory

KENMORE AVE 1983



71 Kenmore Avenue Medical Building 18
Central Park Clinical Laboratory 833-8166 18
Buckley Richd J phys 835-4400
Gauchat Joseph C dentist 835-0155 18
Kenmore X-Ray Center 833-2223 18
Reynhout Jonathan phys 835-0130
Weber Carl F dentist 836-1101 19
Roche Bertrand P phys 836-0470 19
CAPEN BLVD INTERSECTS
95 Neffke Aug F © 834-6612 19
99 Wolf Sarah Mrs © 832-2395
ALLENHURST RD INTERSECTS 20
135 Kenrick James C dentist 838-1286
Sauer Emile C © 836-4553
143 Dohn Funeral Home Inc 834-8128
Ashley Heber Jr © 832-0520
175 Stop-N-Go Food Inc 832-8080

561 40

KENNEDY CT (TOWN—OF LANCASTER)-

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAIN ST 1983

RED OAK DR INTERSECTS

416

MAIN ST (AMHERST—WILLIAMSVILLE)-A CONTINUATION FROM BUFFALO CITY LIMITS EAST

ZIP CODE 14226

3582 Tux Ego Inc tuxedo rental 833-8812
3584 Delaware Camera Mart Inc 836-0715
Dickinson Wm
3586 Waterbeds & Stuff waterbeds & stereos 834-3955
★Kutrybala Michl 834-3961
3588 Deli-Place bar-restr 832-1456
SPRINGVILLE AV BEGINS
3604 Tagg's Music (Div Of Bflo Piano Sales Tuning Inc) music instrument sls 835-1314
3606 Leukemia Society Of America Inc 833-5400
3608 East River Savings Bank (Western Div) 834-2323
3610 Laco Book Stores Inc 833-7131
3612 University Manor Motel Inc motel 837-3344
CALLODINE AV BEGINS

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 1983

VULCAN BEGINS
CITY LIMITS

127

NIAGARA FALLS BLVD —FROM 3310 MAIN NORTH

ZIP CODE 14214
2 Studt Res
22★Ferguson Charles E ◎ 833-8422
37★Caster John W 835-8727
38 Gaglione Mariano C ◎ 835-7050
40 Chi Omega Sorority House 832-1149
41 Schatz Marshal Z ◎ 847-1820
42 Payne Saml T ◎ 834-5413
43 Krystaf Maney M Mrs ◎ 833-7799
45 Ebony Construction genl contr 832-4420
Muldrow Leroy J ◎ 832-6625
46 Nowak Steph F ◎
50 Newberry Wilma J ◎ 835-0474
54 Metzger Michl M ◎
PELHAM DR BEGINS
58 Caldarone Thos J ◎ 834-9232
62 Kowsky Francis R ◎ 836-6069
65 Koren David ◎
66 Klein Peter M ◎ 837-9007
69 Steele Clara H ◎ 834-4107
70 Kogler James F ◎ 836-5436
73 Rogers Kenneth 837-0409
74 Onorato Victoria A Mrs ◎ 833-9426
77★Stegner Bruce E 833-9387
78 Mc Namara Emmet J Jr 834-6177
81 Momjian Margt Mrs ◎ 833-4816
82★Menichino Anthony J ◎ 834-6608
85 Maguire Sylvia Mrs ◎ 838-3843
86 Marinaccio Anthony ◎ 836-5005
89 Krupp Robt C ◎
90 Breadon Margt V Mrs ◎ 834-7941
95★Parwulski James J ◎ 833-3279
96 Kean Odelia C Mrs ◎ 834-4774
97 Sarikas Theo ◎ 832-0388
100 No Return
101★Patel Hazel Mrs ◎
104 Coca-Cola Vending Equipment Co
834-9231
Dallas James ◎ 834-9231
105★Collins Lavarn A ◎
109 Grayson Philip ◎ 837-3040
BELLEVUE ENDS
112 Burgin E Karl 832-1891
115 Taliaferro Stella M Mrs ◎ 833-0157
116 Toepfer Regina F Mrs ◎ 833-5868
119 Chmiola Chester S ◎ 832-4110
120 Davis Aubrey 837-6009
123 Griffa Arth J 833-4459
124 Rath Ruth G Mrs ◎ 832-9240
127 Newcomb Mary P ◎ 837-4780
128 Hudack Florence M Mrs ◎ 834-8976
131 No Return

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 1983

NIAGARA FALLS BLVD—Contd
132★Doran J G 836-6450
136 Gideons International distr of bibles
832-4330
Daum Earle B real est © 833-2234
139 No Return
142 Lesser Geo V dentist 832-9337
KENMORE AV INTERSECTS

60

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 1983



Zgolak Victor ◎ 692-9424
CITY LIMITS

245

NIAGARA FALLS BLVD (TOWN OF TONAWANDA)—FROM 181 KENMORE AV NORTH

(FOR LOWER NUMBERS SEE BUFFALO CITY DIRECTORY)
EVEN NUMBERS ZIP CODE 14223
ZIP CODE 14226

154 Curtis Imported Foods 832-6900
★Falk Wendy 836-3458
158 Weiss Norman J optom 836-3250
165 Stop-N-Go Inc gas sta restr 834-4343
Vacant
166 Halt James G Graphic Design 836-4439
170 Lux Charles N ◎ 835-3653
Dark Maryann
★Szczepanek Mary 838-2628
171 Bozek Donald A ◎ 837-5277
Student Res
174 Ricotta Josephine C Mrs ◎ 834-9634
Wood Stella B Mrs 837-3134
177 Kam Joseph Jr chiropractor ◎ 835-5400
179 Hagen Wm R ◎ 834-6821
180 Apartments

ML Service
Tel. 837-0330

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 1983



Tonawanda, New York 14150

NIAGARA FALLS BLVD (TT)—Contd
1 Roussi Helen C 832-3078
3★Beckmann R P
4 Kellner Janet L 833-8238
186 Le Bar George @ 834-5929
Kelleher Mary M 833-7357
189 Feuerstein Marvin E @ 837-6586
Denture Center Of Buffalo
190★Odea John J 833-3542
Krause Kurt L 837-5866
192★Ahrens B W
195 Puehn Geo E @ 833-6533
198★Lombard Carl J 832-5053
★Pasternak Mark J 837-1637
199 Mc Call N Churchill @ 833-5939
200★Lee Judy
★Wagner Joyce A 835-5673
202 Varga Eliz M Mrs 836-7579
Vidler Richd J 832-6760
204 Huff James M 837-5415
Vacant
206 Masman Jean S Mrs 835-7256
Totaro Angeline J Mrs 837-5796
207 Nice Wm @ 837-4457
208 Bock Anna Mrs 835-2898
Golden Paul J 833-6430
213 Hoolihan Eleanor R Mrs @ 834-2950
O'Neil Gertrude M 832-7507
218 Cortellucci Mary L Mrs @ 834-3674
★Eaton Raymond G
219 Amoroso Albert R @ 837-7187
Amoroso Albert M 835-2115
222 Gisel John C @ 832-8647
Ciolczak Henry B 833-6595
225 Fiorella Robt V @ 836-3252
★Vircintano Wendy
228★O'Shaughnessey Terrence J @ 856-7780
★Marranca Palma
231 Toth John A 834-9134
232 Van Etten Ronald W @
KENILWORTH AV BEGINS
237★Stromberg G D 832-8460
★Haarmeyer David A
Puerner Lawrence W 838-3200
240★Bradley David K
No Return
Klymenko Victor 838-5675
★Stevens Kath N
Pippin beauty salon 832-1060
244 Anthony's Barber Shop 836-9938
Great Lakes Divers Inc 836-6900
248 Breen
Rosenberg
★Sundarajan Chedlur R
249 Ruffino Robt J @ 832-7435
Ruffino Michl P 836-4834
252 Dussault Wayne A @ 838-1810
254 Becker Don E @ 833-4644
PRINCETON AV BEGINS
255★Dzimian J 834-2372
★Ryan T J @
258 Baldi Joseph F @ 832-9909
261 Schmidt Martha C @ 834-4655
Voltura Grace J
262 Pragel Bernard W @ 832-4352
267 Sambor David H 835-9045
Macvitte Martin H @ 838-3658
268 Hodur Darrel L @ 837-1560
Vacant
270 Then Irene M Mrs @ 832-9555
273★Litwin Edw Q @ 838-4467
★Colletti Serena
274★Jachter Kath G @
276 Greico Mildred A Mrs @ 832-0452
Dickey John A 837-2066
(B)★Czamara Frances C
279★Hare David A @ 832-7933
280 Lorig Clara @ 837-6029
285 Meinkes Irving @ 833-4136
Meinkes Nan B 833-4248
286 Cleary John T @ 834-7552
290★Connell Ann
★Brabson Wm @
291 Mattina Rita F Mrs @
Gullo Daisy Mrs 832-2532
292 Plumsteel Charles C @ 832-2144
297★Miroomand Shahin @ 837-2536
Vacant
298 Schuchardt Arth F @ 832-4733
300 Lambert Ann B Mrs @ 834-6976
303 No Return
★Michotek Michl J
304 Walsh Geo E Jr @ 835-2943
308 Graesser Wm C @ 837-5864
309★Becker Donald M Jr 837-4677
310 Godleske Thos J @ 835-5693
315 Wadosky
Dimascio
316 Flottman Edw @ 836-6261
320★Bing Wm
Rear Vacant
321 Delles Joan M Mrs @ 833-2164
Vacant
324 Zimpfer Helen V Mrs @ 836-4394
327★Sommers John J Jr @ 837-7145
328 Anzalaco Angelo M @ 834-4382
330 Ebert Jack C @ 837-9234
333 No Return
334 Vacant
O'Brocta Louis J @ 835-0740
338 Wackowski Henry W @ 832-1444
339 Poloncarz Robt A @ 836-6030
No Return
342 Lundquist Robt D @ 836-2130
344 Battaglia Louis N @ 834-0112
FORD AV BEGINS
345 Still Wm 836-4797
Vacant
354 Mesmer Dairy (Stge)
Mesmer Dairy Stores Inc 836-8690
CAMBRIDGE BLVD BEGINS
358 Wheeler Wm J @ 837-5880
362 Imler Lilias Mrs @ 836-4906
363 Cox Bruce H @
369 No Return
370★Avanzato John
★Bekkowitz Paul
373 Winkler Ruth M Mrs @ 834-3941
378 Marter Adoph J @ 834-2058
382 Crist Georgina M 835-3181
Stabl Josef @ 835-4031
383 Onacko Andrew @ 836-0666
386 No Return
Vacant
389 Stehlin Victor F @ 832-9590
Stehlin Michl P
390 Barth Florence M Mrs @ 833-2010
★Jones Harold A 832-7438
394 White Christina M Mrs @
395 Hawks Edgar J @ 832-9848
396 Dunn Roy G @ 836-8695
398 Mead Arth K @ 836-0337
399 Vacant
405★Nemeti Nicholas J @
406 Student Res
409 Beach Carl A 836-4336
410 Davies Bernice F Mrs @ 836-4768
414 Barber Edw J @ 834-3615
415 Buttino Michl E 832-2839
418 Bunce Hilton G @ 836-6569
422 Anderson Marie V Iwyr 836-2241
Boulevard Barber Shop 845-4999
Thermal Technology Laboratory research & development 836-6680
Todd Insurance 837-3164
Lay Richd V dentist 835-3906
Vacant
Kolstad Associates 834-1445
423 Heverley Larry H @
PAIGE AV BEGINS
424 Cadet Cleaners (Br)
Sweeney's Garage auto repr 832-0648
Sweeney John H @ 832-0648
428 Joseph's House Of Beauty 835-0034
Guggemos Richd 832-2261
429 Barnes Kath I Mrs @ 837-1766
435 O'Connor Peter J @ 838-4351
442 S & E Wholesale Inc jwlry-genl appls 832-1595
443 Nutefall Danl L @ 836-5334
446★Diebold Gerald
Morgan Hilary J 835-8953
Rear Mycek Clara Mrs 836-7074
450 Check Liquor Store 835-6300
453 Carlino Francis P @ 832-0491
459 Bousamra Charles L @ 836-5506
462 Rental City 833-4818
465 Burnis John @ 833-2555
466★Wright Timothy D 834-7760
★Boyle James Jr
OXFORD AV BEGINS
474 Towne Professional Bldg
Rooms
1 Boles & Boles Accounting Inc phys 834-8100

479
482
483
489
495
500
505
512
513
519
523
528
529
535
536
540
543
546
549★
553
559
563
564★
569
570
579
580
588
593
594
599
599½
600
605
608★
613
616
619★
624
625★
628
633
634
639
640
643
644
649
650
653
654
659★
663
664
665
668★
669★
670
673★
674
677
678
679

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 1983



1 A B C Tax Service Inc 834-8100
3 Vacant
4 Vacant
5 Phelps Robert D phys 833-6171
6 Barney Kenneth R phys 835-5777
7 Matteliano James C dentist 832-1678
8 Vacant
CHALMERS AV BEGINS
479 Krieger Wm A chiropractor ◎ 832-7233
482 Hello Dolly's Lounge restr 836-9357
★Di Natale Vita M ◎ 837-2092
483 Gagliardi Fredk J ◎ 833-5295
489 Schlagher Joseph D ◎
495 Wong Mun F ◎ 832-8347
500 Dip-N-Dive Inc scuba center 837-3483
505 Wong Sue K Mrs ◎ 837-4918
512 Cathay Gardens Inc chinese restr 837-3444
513 Leach Jon I ◎ 838-1771
519 Weinberg's Tailor Shop 837-8181
Weinberg Sol I 837-8181
523 Janese Carolyn Mrs
528 Bolea V & Son Upholstering & Furniture Shop 835-3932
Looking Good beauty salon 833-2333
Leonard's Barber Shop 834-0036
529 Blair Donald J ◎ 832-4152
535 Woloszyn Steph ◎ 837-6475
536 B Kwik gro 834-1300
540 Lincoln Park Pharmacy Inc 832-7800
U S Post Office (Lincoln Park Br) 832-7800
543 Paeplow Charles E ◎
546 Big John's Pizza & Subs 836-4881
549★Ashley Heber ◎ 832-0520
553 Abbarno Perry J ◎ 832-7635
DECATUR RD BEGINS

244

DECATUR RD INTERSECTS
559 Meyer Raymond H ◎ 832-0583
563 Pufpaff Thos H ◎ 834-3890
564★Simon Clara Mrs ◎
569 Fontaine Marc M ◎ 832-5437
570 Taylor Robt J Jr ◎ 837-6843
579 Peifer Carl A ◎ 832-0910
580 Fix Joan W Mrs ◎ 835-1651
YALE AV BEGINS
588 De Priest Florence T Mrs ◎
593 Kielich Ronald J dentist ◎ 834-3568
594 Diamond Anthony A ◎
599 Mason Robt D Agency ins 832-1484
Auto Driveway Co auto forwarding 833-8500
599½★Glose Mary Beth
600 Thamm Virginia F ◎ 832-8711
605 Loudy Dorothy M Mrs ◎ 835-3633
608★Hutten John J ◎ 834-9126
613 No Return
616 Szymanski Edw J
619★Glaister Ernest ◎ 833-4829
624 Bartley John I ◎ 832-4645
625★Dudkowski Edw ◎
628 Kelsey Anthony N ◎ 833-8977
633 Tobin Robt optom ◎ 835-4140
634 Mobley John ◎ 832-6433
639 Mc Gee Howard W ◎ 833-4944
640 Wolff Paul A ◎ 833-0154
643 Clark Thos R ◎ 836-5824
644 Liscavage Robt S ◎
649 Youngman Morris L music tchr ◎ 836-4158
650 Eaton Wendell L ◎ 832-8987
653 Johnson Willard E ◎ 838-4479
654 Blue Howard P ◎ 835-7255
LINCOLN PARK DR ENDS
659★Nowocien Julius H ◎
663 Menchetti John J ◎ 832-3418
664 Morrow Jane Mrs ◎
665 Minick Howard E ◎ 834-8061
668★Kelley Robt W 832-7966
669★Chase Marilyn M Mrs ◎ 837-5607
670 Kirbis Robt W ◎ 835-8819
673★Stratton E G 833-0948
Rear Parkside Management Corporation
674 Ranney Mildred A Mrs ◎ 835-1198
LONGMEADOW RD BEGINS
677 Silverstein's kosher chicken sls
678 Poplawski Gordon S ◎ 832-5347
679 Boulevard Pizza Submarine Take Out 838-4545

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 1983



NIAGARA FALLS BLVD (TT)—Contd
681 Feel-Rite Health Food Shoppe Inc 834-3385
684 Pray Donald P ◎ 832-7793
688 Vacant
694★Kirbs John J ◎ 836-7639
698★Rathburn Melvin ◎
704 Janeczko Wm W ◎ 834-8551
710 Alum-A-Way Construction Co Inc alum constn 832-2791
Blom Robt G ◎ 835-8447
711 Trinity United Methodist Church 835-7711
716 Bingel Wm E 832-5003
722 Priamo Gerald A ◎ 832-2407
728 Janus Lutz J ◎ 836-8212
733 Heron Auto Service auto repair shop 836-9162
RUTH BEGINS
738 Leith June C ◎ 834-0457

243

HIGHLAND AV ENDS
748★Powell A 837-1397
751 Hector's Hardware & Paint Co Inc 832-9310
758 Chambers Gary ◎ 837-8385
765 Christian Fellowship Baptist Church 837-1664
770 Lord Robt F Funeral Home 832-6588
Lord Isabella C Mrs 832-5178
HARRISON AV ENDS
773 Transcendental Audio Ltd radio equip 834-3100
782 Vacant
785 Lincoln Park Motel Inc 837-7400
Johnson James R 834-9645
789 Vacant
796 Aquarian Book Center 835-7888
797 Jolly Jug tavern 836-9552
800 Boulevard Beauty Salon The 836-5280
802 Lincoln Park Barber Shop 836-9402
803 Empire Auto Electric Ltd electrical sys 835-2424
Burgio & Campofelice Inc bldg contrs 833-5171
BETINA AV BEGINS
804 Orville's Appliance Inc sls 832-2700
MOORE AV ENDS
820 Jim Wood's Tire & Battery 836-9732
828 Robert's Rent-A-Tool 836-6464
832 Vacant
Vacant
839 G & W World Newspaper 838-3900
Radio Shack Computer Store
Poppenberg's Inc piano & organ dlr 837-1010
843★Coughlin M
Nugent Brian
Maintenance & Management Associates Inc jan serv 836-2111
845 Vacant
847 Jean's Tailor Shop 834-5567
Vacant
Yellow House Of Beauty 835-5260
850 Hair Forum The beauty shop 837-5007
Ichi Hana Chinese Restaurant
Vacant
Vacant
853 Lakeland Automotive Supply Inc whol auto parts 834-2776
860 Durham Temporaries Inc employment agcy 838-4261
Kenilworth Electronics 837-6666
861 Wahl Alice E Mrs ◎
865 Vacant
Vacant
869 James Building
Tonkology & Gellman acct 838-1921
Freeman Joseph consulting eng 837-4800
871 James Building
Gordon James Image Makers Inc photo 837-5665

Int
ex
Sm
Sur
We
874 Bou
83
899 Art
900 Pea
83
910 Da
920 Am
Vac
Vac
Cho
83
925 Bou
Hi
926 Lav
934 Spe
EGGE
951 Den

AMHI
ZIP C
SHER
995 Fire
1009 Ba
TONA
1016 Ca
pi
Bo
8
Pa
8
Ni
8
1021 Mi
1030 Sa
re
1060 Bo
Su
1065 Su
1089 Me
1090 Wi
8
ROCH
1101 Ne
Ri
8
Ke
8
Ke
Va
Ma
cl
ALME
1120 Ca
8
1139 Ca
Ca
8
1140 Kl
1154 Br
8
1155 Ea
BRIA
1167 Ca
8
1171 Mi
1172 Du
1185 Bo
8
1188 Ma
W
TREA
1200 Kr
1201 Su
Su
g
ZIP C
1203 Bo
8
Ta

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 1983

171

td
Interex Trade Center barter & trade exchanges 836-0550
Smolen Wolstoncroft & Head 834-6111
Sung John J cpa 833-3422
Weinstein Kenneth acct 838-1921
874 Boulevard Collision Inc auto body repr 837-2449
899 Arthur's restr 822-4427
900 Pearce & Pearce Co Inc real est 833-6600
910 David Photo Service Inc 835-4620
920 American Dance Studio 834-3350
Vacant
Vacant
Chopping Block The beauty salon 838-2427
hop
925 Boulevard Moving & Storage (Div U-Haul Inc) 832-1778
926 Lawrence Jesse Collision 838-2200
934 Speedy Muffler King 838-6400
EGGERT RD INTERSECTS
243
951 Denny's Restaurant Inc 837-5657

241

c
AMHERST BEGINS
ZIP CODE 14226
SHERIDAN DR INTERSECTS
ch
995 Firestone Tire & Rubber Co 837-9700
1009 Barnaby's restr 832-6054
588
TONAWANDA PO
1016 Campos Photography Center film processing 837-1016
quip
Boulevard Plumbing Supply Co 834-5049
Parisi Edward Plumbing Co Inc contr 834-5664
Niagara Concessions Associates 834-5664
1021 Mighty Taco The (Admn Ofc) 832-8566
1030 Santora's La Stanza Ristorante Inc restr 833-4255
5280
2
l sys
1060 Boulevard Square Plaza
Super Chips barber 835-1388
1065 Sundown Motel Inc
ntrs
1089 Mean Guys East Inc restr 836-2992
1090 Wil-Pac Packing Co Inc whol meats 832-0511
ROCHELLE PL BEGINS
0
1101 Neat Repeats used clo
'32
Rich James P Insurance Service 833-1900
Keene George A Inc genl contrs 832-0180
Keene Geo A @ 832-0180
0
Vacant
Maternity Warehouse Outlet womens clo 835-5187
llr
ALMEDA BEGINS
1120 Cavalier Motor Lodge (addl sp) 835-5916
ciates
1139 Cavalier Motor Lodge 833-9730
Cavalier Restaurant & Lounge Inc 837-8270
1140 Klein Harold N @ 834-2996
1154 Brand Names Sales Inc genl mdse 834-5094
5007
1155 Eaton Office Supply Co Inc 837-6800
BRIARHURST DR BEGINS
1167 Caruba Collision auto body repr 834-0466
whol
1171 Midas Muffler car mufflers 837-4100
1172 Dunkin Donuts 833-9116
ient
1185 Boulevard Mall Racquetball Club 833-6276
1188 Manufacturers Hanover Trust Co Western 837-0760
TREADWELL RD BEGINS
1200 Knapp Shoes 832-6530
1201 Suburban Lanes Inc bowling 836-0222
21
Suburban Lanes Pro Shop sporting gds 836-0222
ZIP CODE 14226
1203 Boulevard Mall shopping center 834-8600
photo
Tadora Leather Goods 835-3050

1204 American Health & Fitness (Overflow)
1205 Goldome Bank For Savings 847-5800
1207 Foxmoor Casuals clo ret 836-9181
1207b Merry Go Round clo 836-8900
1208 Holiday Health Fitness Center 837-7733
1209 Spencer Gift genl merchandise 835-8157
1210 Dinette's & More furn 836-8070
1211 Kinney Shoes 834-1552
1213 Lane Bryant (Br) clothing retail 837-2500
1219 Bresler's Thirty-Three Flavors ice cream store 837-8330
1221 Hanover Shoes 837-7471
1223 Proving Ground clo 836-8560
1225 Jo Ann Fabrics 836-5546
Stuarts wm clo 837-4381
Eastern Arts oriental art works 835-8315
Jean Nicole women's clo 836-6910
Pleasures & Pastimes craft shop 833-8777
Delaware Camera Mart ret cameras 836-4011
Art Works The art sup 836-0900
Chess King men's clo 836-8883
Micro Center computer sls 833-0908
1227 Mothercare maternity shop 836-3492
Vacant
1229 Wild Pair The shoe retail 837-1476
Yogurt Bar The dairy bar
Vacant
1230 Purchase Radio Electronics Corp wholesale 837-5900
1231 Gutman's Inc womens apparel 837-3100
1233 York Steak House Inc 832-7030
Gap The clothing store 836-8080
1234 P K Discount Drugs Inc 835-2100
P O Sub Sta No 4 835-2100
1235 Sample Inc dept store 833-6717
1237 Claire's Boutique 835-4430
1239 Thom Mc An Shoe Store 836-5111
1241 Martin Limited Men's Wear 832-4252
1242 Bison Plumbing City 837-3117
1244 Century Twenty-One M J Peterson real estate 833-3433
1245 Altiers Naturalizer Shoes ret shoes 837-0885
1246 Sleep Well Waterbeds 834-1131
1247 Laux Sporting Goods Inc 832-2774
1248 Six Months To Sixteen Years Shoes Inc 837-9632
1249 White Shoe Store 692-8847
1250 Boulevard Seafood & Meats Co 832-5898
Vacant
1251 Boulevard Mall Bootery 832-4903
1252 Vacant
1253 Flagg Brothers Shoes retail 832-5566
1254 Watch World 835-2241
Vacant
1255 Vacant
1258 Your Host Restaurant Inc 836-9579
1267 Manufacturers & Traders Trust Co (Blvd Mall Ofc) 832-0343
1269 A A Paradise Inc pet shop 694-7450
1270 Eastern Mountain Sports Inc sport gds 838-4200
1271 Eve's cards & gifts 836-6976
Ups & Downs clo 836-9113
1273 Fanny Farmer Candy Shops Inc 833-0203
1275 House Of Spirits liquor 836-2240
1277 Next Step Shoes retail shoes 837-4406
1279 Krasner's womens clothing 834-4084
1280 Goodyear Service Stores tires & auto accessores 837-8720
1281 Consumer Value Stores pharm 836-1857
1283 Reed's Jewelers 837-3934
1285 Kleinhans Co Inc men's clo 856-5544
1289 Goldman's Shoes (br) 835-3414

Main St., Buffalo, N.Y. 14203 856-3450
7764 Nash Rd. North Tonawanda, N.Y. 14120

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 1983

NIAGARA FALLS BLVD (TT)—Contd
1291 Jaines Youth Center Inc children's clo (br) 837-4177
1293 David's Specialty Shop women's apparel 836-7780
1295 Jenss dept store 837-1100
Jenss Beauty Salon 834-6434
Jenss Decor gift shop 837-1100
Jenss Card Shop stationery 837-1100
1303 Penney J C Co Inc (Br) 837-2100
Firestone Automotive Center 837-7721
1304 Sizzler Family Steak House 693-2318
1312 Pearle Vision Center optn 833-8338
1330 Fantastic Sam's unisex hair stylist
Kaplan Stanley H Educational Center Limited test preparation splst 837-8022
Ford Motor (Credit Div) 833-8231
Liggett & Myers tobacco products whol 836-7000
Hyatt Legal Services 832-7777
Fugazy International Travel Inc travel bus 838-5705
Second Sole athletic shoes 834-3371
Botticelli Inc ret clo 837-1122
Kwik-Kopy Printing 837-4453
M & W Camera Center camera equip sls 833-6110
1341 Vacant
1346 Bauer Radiator car radiator sls & serv 834-8822
240
MAPLE RD BEGINS
1350 Vacant
1355 Delta Sonic Car Wash 832-4050
Amoco Gas 837-4050
SUITES IRREGULAR
1360-70 Vacant
Boulevard Counseling Center-Co 2 833-3708
Union Central Life Ins Co The 837-1217
Bornstein Morton atty 835-4100
Recruiter Communications Network 836-2601
Vacant
1372 Vacant
1376 Tin Lizzie Restaurant & Lounge 836-1717
Horseless Carriage Motor Inn 836-2940
1385 Mc Donalds Restaurant 837-9255
1395 Arby's Roast Beef 832-5231
1400 Pizza Hut drive in restr 835-3636
1401 Century Twenty One Glass Inc real est 838-5300
1405 Foster Thayer Co Inc 838-5106
ZIP CODE 14150
1420 Burger King 836-0117
BRAXMAR RD BEGINS
MEYER RD BEGINS
1435 Tire Man Of Buffalo 833-3400
1436 Paramount Music 835-1500
Tony's Of The Blvd Barber Shop 836-8962
John's Pizza & Sub Shop 832-4343
Rooms
100 Life Resources 836-4001
101 Conveyors & Drives Inc 837-6165
102 Counter Parts dating serv
104 Bluestein Paul S phys 838-4429
200 Gerico Don Sports Sales 832-2153
202 Vacant
204 Di-Ton Co computer sls & trng 832-1450
206 C M R & Ceiling Master Of N Y home improvement contrs
208 Vacant
210 Guaranteed Adjustment Inc 837-6022
1456 Santangelo's Hair Designers 834-3995
1459 Flanigan's Furniture & Carpeting 834-7171
National Auto Supply 836-2751
Sounds Great Inc 838-4602
Flanigan's Eclectic Water Beds 836-5066
Burnams ret furn 834-2720
1500 Kramer Volkswagen Inc 836-4600
1508 Vacant
1520 Truck 'n' Stuff gas sta 834-1700
YORKSHIRE RD BEGINS
1550 Ber
1551 Swi
Sun
U S
Val
83
Sho
Pier
83
Kas
Ste
Hea
1561 Kit
1570 Firs
83
Chr
GLENA
1590 Kad
1592 Hai
1594 Gre
833
1596 Fow
1598 May
1600 Gre
1602 Kim
1606 Sch
1608 Yan
835
1610 Mos
836
1612 Com
836
1614 Vac
1616 Holi
Migl
837
1620 Map
Thre
1621 Gros
lun
1660 Bod
GREEN
1676 Latk
834
Nels
Ser
Trea
688
1694 Oett
1701 K-M
K-M
K-M
ladi
K-M
Cen
K-M
Inc
Mel
KOENI
RIDGE
1705 Copi
Insti
wei
1715 Mist
1730 Ray'
1750 Colo
★Fr
ZIP CO
NEW Y
OVERP
1868 Buil
Kre
693
Nuw
693
Fox
Roo
302
303
304
305
307
310
311
1870 Apa
105

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAIN ST 1982

253

3105 Saint Andrew's Parish House (Ofc) 834-9337
★Sonseca Luis A
3106 Vacant
3107 Saint Andrew's Episcopal Church 834-9337
3108 Western New York Independent Living Project Inc 836-0822
Studt Res
Felton Dean 837-1439
3108½★Totaro Joseph S 834-3171
3112 Vacant
Studt Res
3114 Pinnacle Peaks Apparel & Bootery Shop clo & shoe store 833-6565
Studt Res
3116★Ntumba Tulumba
3118 Fichtel Fredk C Jr 833-5024
Chinese Fast Food restr 837-6776
Le Mok Leong
3122 Cabinet Pak Kitchens By Moehof Bldg Inc 836-6560
Whiting Morris L
3124 Old English Book Shop Apartments
1★Shilling Kinne
2★Wong Kelly
3★Stephens K 838-1344
4★Johnson L
3125 Main Medical Building Neuroscience Associates 838-5346
Bahuleyan Kumar phys
HIGHGATE AV BEGINS
3126 Simulations 836-8666
3130 Sullivan Self Service Laundry 836-9572
CUSTER BEGINS
3135 Reger Funeral Home Inc 834-3600
Vacant
3142 Grabowski Helen Mrs sewing sch 835-4434
Joey's Cleaners dry cln
3144 Talking Leaves Inc books sls 837-8554
North Buffalo Food Corp (food store) 836-8938
★Luban Nina B
Grogan Betsy 835-3279
3151 Sign Of The Steer Restaurant 836-6800
3152 Marine Midland Bank (Univ Br) 838-5865
University Heights apts 837-8153
201 Peters Janet T Mrs 833-6844
202★Tesfaye Kifle 834-2758
203 No Return
204 Fahey Jerry P 837-8153
205 Whitehorne Victoria A
206 Studt Res
207 Orsolits Joanne K 832-5054
208 No Return
3158 Guildcraft Co Of Buffalo Inc The craft sup 837-9346
3160 North Main Hardware 834-5878
★West James 834-7177
3162 Wolff
★Shanahan Mark D 836-5208
★Mauro Geo
★Friedland T 838-4280
3164 Best Florian E optn
3165 Miranda Real Estate 836-6600
3168 Herzog's Drug Store Inc 834-1970
3171 Latke Printing & Copy Center 835-0101
Gerson Stuart
Chinowsky Lary
3171½ Henna Albert 836-4933
Hausman Jeffrie
W NORTHRUP PL BEGINS
NORTHRUP PL BEGINS
3172 Westworld Video Games
3173 Top Shelf Music music store 832-1045
3176 Vacant
3178★Shenquan Xie
★Wong Jeffrey Y 835-2230
3180 La Mia Via Pizzeria 834-3810
3182 Foster John A 838-4854
3184 Hong Kong-Chains Tailors
3191 Turgeon Restaurants Ltd 838-4100
Turgeon Frank @
3193★Strong Sharon
3198 Frank's Mobil Gas Station 836-9809
3199 Bagatelle The restr 836-8803
3211 Wilson Farms Convenience Food Store 834-4081

179

WINSPEAR AV BEGINS
3208 Parkside Candy Co Inc 833-7540
3210 Lewis Paul G 832-7005
Ryan R H Mrs 833-8394
Vacant
Vacant
3212 Parlato-O'Brien Realty Inc 835-1202
3214 Suburban Office Supply 835-8025
Student Residence
3216 Hair People The beauty salon 832-8032
Student Residents
★Beyer Blaine W 838-2983
3218 College Laundry Shop The 833-0060
Student Res
3223 North Main Liquor Store 834-7727
3225 Branch Bookstore The 832-0909
Vacant
★Thill Richd 833-1295
3229 Buffalo Picture Frame & Mirror Corp 838-3800
MERRIMAC ST BEGINS
SUTTON LA BEGINS
3230 Goodwill Industry Store
Studt Residence
3233 Cantalician Center For Learning sch 833-5353
Dondajewski Lorita Sister
Wagner Harold Rev 836-5276
3234 Palmer's Beauty Salon 836-0777
University Donut 832-6666
Studt Res
3236 Plant Parlour plants 833-8111
3240 O'Connell Lucas Chelf Inc men's col 836-4140
O'Connell Lucas Chelf Inc women clo
★Barnett Thos S 833-7584
Rear O'Connell Lucas Chelf (Parking Lot)
3242 University Heights Community Development Assoc Inc 832-1010
University Heights Community Service Center 832-1010
University Heights Business Association Inc 832-1010
University Heights Center Library 832-7762
3248 Chicken Wing King Inc restr take out
HEATH BEGINS
3258 Rifco Building
Crisis Service counseling serv 834-3131
3260 Buffalo's Child ret clo 835-1800
3262 Furnished Rooms
★Boatright Robt 833-1026
3264 Third Base tavern 833-1284
3264½ Studt Residents
3268 Needle & Thread Shop The tailors 833-0789
Half & Half Trading Co trading shop clo 838-4744
Studt Res
3269 Saint Joseph's Roman Catholic Church 833-0296
Maloney Thos 833-0296
3270 P J Bottoms Tavern 833-3270
3275 Saint Joseph's Roman Catholic School 835-7395
Saint Joseph's Convent 833-7333
3276 Buffalo Outlet Inc ret clo 832-1900
ENGLEWOOD AV BEGINS
3288 Vacant
3292 Chabad House jewish culture center 833-8334
3296 Chancellor Court Apartments
A1 Vacant
A2 Schottin Dorothy B Mrs 837-3861
A3 Walker Danl H 836-1639
A4 Brandt Cath M Mrs 834-9451
B1 Balog M
B2 No Return
B3★Minekime James 837-5891
B4★Hamburg N
C1 Studt Res
C2 Studt Res
C3 De Georges Joyce C 836-0946
C4 Foltin Geo
UNIVERSITY AV BEGINS
NIAGARA FALLS BLVD BEGINS
3334 University Presbyterian Church 836-7660
Vacant
3350 Child & Adolescent Psychiatric Clinic 835-4011
3362 Vacant
3380 Vacant
3382 Winnes Restaurant 838-4009
3400 Militello's Luggage leather gds 833-1600
Vacant
Life Uniform Shop 833-2909
Apartments
1 Vacant
2 Licastro Emanuele G 836-1649
3 Sheinberg Donna S 832-8296
4★Livio Emanuels
3404 Vacant
Vacant
ALLENHURST RD BEGINS
3435 Main Street Library 831-2165
S U N Y A B 831-9000
S U N Y A B Book Store 831-2444
Nuclear Research & Technology 831-2826
S U N Y A B (Univ Libraries) 636-2965
S U N Y A B Health Sciences Library 831-3402
3442 University Court Apartments 835-1930
1b★Doyle Kevin 835-1930
2b Vacant
A1★Meyer Elis
A2 Levitt Pauline D 835-3130
A3 Cundal Doria A Mrs 834-5373
A4 Vacant
A5★Robbins Susan 833-9388
A6 Vacant
A7 Hawkins Ruth J Mrs 834-1964
A8★Rose Steven 837-1968
A9 Hall
A10 Chamberlin L
A11 Dempsey D V 838-6051
A12★Veraggi Joann
A14 Mikuls Ruta
A15 Smith Cath J 835-3991
B1 Gianadda Alfonso A 832-6982
B2 Argus Jane M Mrs 837-5766
B3 Adams Dorothy J Mrs
B4 Domres Hazel H 834-9412
B5 Ratigan Helen M Mrs
B6★Letwin Edwin
B7★Howard Molly
B8★Vollaro Linda
B9 Cook Dorothy M 832-3505
B10★Fuerst Vincent
B11 Maloney Molly 835-4057
B12★Bradley Margt
B14 Franz Pauline C Mrs 834-3880

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAIN ST 1982



B15 Fallen Clara 832-3446
1c Vacant
C2★Mc Eleney Brian
C3★Hughes Michl
C4★Ciminelli Danl
C5★Taylor John
C6 Vacant
C7★Fischer Gail A 833-6315
C8★Lupiano John
C9★Menoff Jeff
C10★Snyder Michele W 836-8365
C11 Gern Bertha H Mrs 834-8910
C12 Wieber Katya 832-1438
C14 Johnson Helen M Mrs 834-6751
C15 Misura Sue
Basemnt Vacant

CAPEN BLVD BEGINS

3484 Stephens J C Motor Corp autos
833-8140

WINDERMERE BEGINS

3488 Seven-Eleven Food Store 836-9633

KENMORE AV BEGINS
BAILEY AV ENDS
CITY LIMITS

192

Target Street	Cross Street	Source
-	✓	Polk's City Directory

KENMORE AVE 1977



2547 UNIVERSITY AV INTERSECTS 319

434

KENMORE AV (AMHERST TOWN OF TONAWANDA KENMORE)—FROM 3514 MAIN WEST 323 337

FOR EVEN NUMBERS SEE BUFFALO ZIP CODE 14226 353

39 Amherst Bootery Inc 833-6974 359

41 Frisch Gustav A Inc optn 833-5415

43 Amherst Clothes Tree Inc women's 836-6711 369 375

47 Plaza Shoe Repair-Laundry & Dry Cleaning 836-4041 381

It's Greek To Me 838-4500

436

WINDERMERE BLVD INTERSECTS

59 Behringer Earl Diamonds Inc retail jwlry 836-4700 401

★Behringer Earl ◎ 417

Haircuts Underground barber shop 836-1781

63 Hudecki Gregory dentist 834-2744 421

Hudecki Steph E dentist 834-2744 429

Schaus James P phys 832-1050 435

Silvert Allen G podiatrist 833-8094

Sullivan James R phys 832-8044 447

71 University Medical Building 487

Central Park Clinical Laboratory 833-8166

Buckley Richd J Jr phys 835-4400

Gauchat Joseph C dentist 835-0155

Safran Nathl radiologist 833-2223 501

Reynhout John phys 833-1626

Weber Carl F dentist 836-1101

Wittkugel Herbert W phys 836-5191

Young Mark H phys 836-0470

CAPEN BLVD INTERSECTS

95 Neffke Aug F ◎ 834-6612 559

99 Wolf Joseph ◎ 832-2395

Target Street	Cross Street	Source
-	✓	Polk's City Directory

KENMORE AVE 1977



ALLENHURST RD INTERSECTS
135 Kenrick James C dentist 838-1286
Sauer Emile C ◎ 836-4553
143 Dohn Funeral Home Inc 834-8128
Ashley Heber Jr ◎ 832-0520
175 Vacant

485

ZIP CODE 14223
TOWN OF TONAWANDA BEGINS
181 Puehn Geo E meat market 833-4411
187★Keefe Pauline J 833-7549
★Gawronski Joseph M ◎ 834-5586
189 Lazarski Henry Jr ◎ 834-5877
191 Brenner Matilda A Mrs ◎ 833-4968
LARCHMONT ENDS
193 Rozek Kenneth ◎
197★Baran Jeffrey L ◎ 836-1678
199★Mc Elheney Wallace
★Weigert Donna
203 Gates Electric Co Inc appls sls & serv
837-5311
Schuster J Tailor 833-6096
205 Hair Fashions By Audrey 832-6558
GRANDVIEW AV BEGINS
HAWTHORNE AV BEGINS
217★Carr Greg
★Johnson Bruce
225★Hinton Martin E ◎

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAIN ST 1977

252

MAIN ST—Contd
3180 Red Giant Rental Service rental serv 838-6983
Red Giant Realtors real estate 838-6983
3182 Foster John A 838-4854
3184 Waterbrothers Inc retail sls furn-accessories 833-2100
3191★Johnson Carol @ 833-3097
3193★Phoong Hang Do 836-7560
★Schmidt Gertrude
Heider R
Wrzesien Pauline T Mrs 837-8045
★Hatt Penny
3198 Frank's Mobil Gas Station gas sta 836-9809
3199 Vacant
3201 Vacant
3203 Joe's Shoe Service repr
3205 Vacant

198

WINSPEAR AV BEGINS
3208 Kaiser Candy Co Inc 833-7540
Parkside Candy Co Inc 833-7540
3210 Lewis Paul G 832-7005
Ryan Rose H Mrs 833-8394
Dewitz Charles F phys 832-6262
Doll Raymond J dentist 833-8035
Parkside Beauty Shop 834-8640
3212 Main-Spear Delicatessen 836-0936
3214 Branch Book Store The 838-5935
No Return
3216 Parlato-O'Brien Realty Inc 835-1020
★Fogel U
★Resmovits M
★Mac Kay M C
★O'Day J
3218 College Laundry Shop The 833-0060
No Return
3223 North Main Liquor Store 834-7727
3225 North Buffalo Food Co-Op Inc 836-8938
Mc Carthy Anne M 837-6780
3229 Buffalo Picture Frame & Mirror Corp 838-3800
3230 Studt Res
MERRIMAC ST BEGINS
Center For Exploratory And Perceptual Arts Inc non-profit organization 835-6257
SUTTON LA BEGINS
3233 Cantalician Center For Learning sch 833-5353
Wagner Harold Rev 836-5276
3234 Sol's Esquire Laundry & Cleaners 834-2225
Mr Donut (Br) 832-6666
Studt Res
3236 Plant Parlour plants 833-3945
Plant Parlour (Stge)
3240 O'Connell Lucas Chelf Inc men's col 836-4140
Rear Parking Lot
Stitch Niche sewing designs
Pearman Robt E
3242 University Hts Community Development Assoc Inc 832-1010
University Heights Community Service Center 832-1010
University Heights Business Association Inc 832-1010
3248 John & Mary's Sub Shop restr take out 834-3500
HEATH BEGINS
3258 Rifco Building
Crisis Service counseling serv 838-5980
3260 Nord Alp Inc mountaineering 837-3355
Hike & Bike sls & serv 837-0240
3262 Apartments
1★Snedding James
5 Rahill Dion 834-0562
7★Root Donald
8 Vacant
9 Kremp Birtram A 834-1176
10★Binger Alphons
11 Shaw John
3264 Wurst Place The Inc bar & restr 836-8800
3264½ Studt Residents
3268 Needle & Thread Shop The tailors 833-0789
Half & Half Trading Co trading shop cloths 838-4744
Studt Res
3269 Saint Joseph's Roman Catholic Church 833-0298
Beasley Thos Rev
3270 Bitterman's Restaurant Inc 838-4224
3275 Saint Joseph's Roman Catholic School 835-7395
Saint Joseph's Convent 833-7333
3276 Buffalo Outlet Inc ret clo 832-1900
ENGLEWOOD AV BEGINS
3288 Crowley Leo T Jr dentist 833-1350
3292 Chabad House jewish culture center 833-8334
3296 Chancellor Court Apartments
A1 Lazerson David B 837-5506
A2 Schottin Dorothy B Mrs 837-3861
A3★Magid Norman
A4 Brandt Cath M Mrs 834-9451
B1 Narasimhan V Tupil 832-3677
B2★Barker R
B3 Hamblin Danl M 838-2403
B4 Harrison David
C1 No Return
C2 Robbins Mark S 838-6511
C3★Bazelon David T
C4★Gehami N
UNIVERSITY AV BEGINS
NIAGARA FALLS BLVD BEGINS
3334 University Presbyterian Church 836-7660
Council Churches Bflo Erie Cnty (College Wk Dept) 834-4250
Phase One Mental Health Services Corp 838-6146
3362 Your Host Restaurant Inc 836-9436
3380 Red Barn The restr 836-8789
3382 Arthur Treachers Fish & Chips 838-4009
3400 Militello's Luggage leather gds 833-1600
A M I Co Inc gifts adv 832-3149
Life Uniform Shop 833-2909
Apartments
1 Conjeski Raymond T 838-4542
2★Licastro Emanuele G
3★Hylton Denise
4 Nazzaro Angela 837-7865
3404 Downing Harold S Jr 832-0408
Amigone Helen K Mrs @ 834-5890
ALLENHURST RD BEGINS
3435 New York State Univ At Bflo Lockwood Mem Lib 831-2428
State University Of N Y At Buffalo 831-9000
State University Of N Y At Bflo Book Store 833-8090
Nuclear Research & Technology 831-2826
S U N Y A B (Univ Libraries) 831-2428
State University Health Sciences Library 831-5465
3442 University Court Apartments 852-4700
A Freeman Lee
A1 Murray Elsie Mrs 832-5196
A2 Levitt Pauline L 835-3130
A3 Cundal Doris A Mrs 834-5373
A4 No Return
A5 Vine Kath A Mrs 833-9388
A6 Baker Wm
A7 Hawkins Ruth J Mrs 834-1964
A8 Finn Mary E Mrs 834-2783
A9 Conway Patk J 834-6771
A10 Sholman Laura
A11 Mack
A12 Ziewacz Stanley 836-5424
A14 Thomas Albert E 836-8304
A15 Smith Cath J 835-3991
B1 Gianadda Alfonso A 832-8982
B2 Argus Jane Mrs 837-5786
B3 Adams Dorothy J Mrs 838-3298
B4 Domres Hazel H 834-9412
B5 Ratigan Helen Mrs
B6 Rohe Louise M Mrs 833-9684
B7 Brown F
B8 Farah Albert E 835-1389
B9 Cook D M 832-3505
B10 Heining John 837-6153
B11 Feldman Grace Mrs 835-4057
B12 Hennrich Lena
B14 Franz Pauline C Mrs 834-3880
B15 Quellos Helen
1c Knoll A P
C2 Bierbauer Lois Mrs
C3 Muck Karl 832-7916
C4 Eisenstein Joel A 837-4659
C5 Collins Barbara A 835-7882
C6 Kennedy Eliz S Mrs 834-2551
C7 No Return
C8 Vacant
C9 Garneau Isabelle Mrs 832-2316
C10 Rohe Edna E
C11 Gern Bertha H Mrs 834-8910
C12★Tracy Jill
C14 Johnson Helen M Mrs 834-6751
C15 Vacant
CAPEN BLVD BEGINS
3484 Stephens J C Motor Corp autos 833-8140
WINDERMERE BEGINS
3488 Amoco Serv Sta 836-8805
3500 Manufacturers & Traders Trust Co 832-9523
3514 Blackwell Plaza Service gas sta 836-9390
KENMORE AV BEGINS
BAILEY AV ENDS
CITY LIMITS

85

MALSCH ST —FROM 174 ESSER AV NORTH THEN EAST

ZIP CODE 14207
10 Ferro Michl @
12 Loomis Frank H @ 875-5345
14 Skees Richd D @ 874-6342
15 Ruffino Gerald @ 874-1411
16 Sapienza Anthony @
17 No Return
18 Mackie Leota R Mrs @ 876-2946
20 Soos Gaza J @ 873-9207
22 Horvath Geo F @ 877-4035
24 Tillie's Beauty Nook 876-1510
Klimczak Chester @ 876-1510
28 Morrison Joe
Lysche Victoria 877-1037
29 Rathborne
★Cunningham Mary 875-6024
30 Giaraffa Frank @ 875-5012
Massaro John V @ 875-5012
ECKHERT ST INTERSECTS

15

MALTA PL —FROM 309 MARYLAND NORTHWEST

ZIP CODE 14201
9 Gardner Clarence R
★Kettle Cecil B
22 Koehler Frances R Mrs @ 882-2932

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAIN ST 1977

RED OAK DR INTERSECTS

434

MAIN ST (AMHERST WILLIAMSVILLE)
A CONTINUATION FROM BUFFALO
CITY LIMITS EAST

ZIP CODE 14226

3584 Charlie's Barber Shop 837-3111
Mt Major Corp beauty supplies wholesale 391
837-3111
3586 Cavages Incorporated records 836-0041
3588 Deli-Place 832-1456
SPRINGVILLE AV BEGINS 392
3604 Vacant
Vacant 392
3606 Leukemia Society Of American Inc
833-5400 393
3608 Erie Federal Savings & Loan Assn E
(University Br) 834-2323
3610 Laco Book Stores Inc 833-7131
3612 University Manor Inc 837-3344 394
Straubinger Victor Development Corp
3666 Bronstein Appraisal Service 835-7408
CALLODINE AV BEGINS
N BAILEY AV INTERSECTS 395

432

CROSBY CIR BEGINS 395
3690 Flaherty Harold C photog © 835-1093
3700 Lefcourt Charles R © 833-0743
3710 Gerow Richd J chiropractor © 835-5708

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 1977



Riverside Senior Citizens Center
VULCAN BEGINS
CITY LIMITS

127
NIAGARA FALLS BLVD —FROM 3310
MAIN NORTH

ZIP CODE 14214
2 Sunyab Student Residence
22 Sceusa Frank J ◎ 836-7654
37 Vacant
38 Gaglione Mariano C ◎ 835-7050
40 Chi Omega Sorority House 832-1149
41 Gay Kenneth ◎ 837-9009
42 Payne Saml T ◎ 834-5413
43 Krystaf Joseph G ◎ 833-7799
45 Ebony Construction genl contr
Muldrow Leroy ◎ 832-6625
46 Nowak Steph F ◎
PELHAM DR BEGINS
50★Newberry Wilma J ◎ 835-0474
54 Metzger Michl M ◎
58 Caldarone Thos J ◎ 834-9232
62 Kowsky Francis R ◎ 836-6069
65 Vacant
66 Klein Peter M ◎ 837-9007
69 Steele Clara H ◎ 834-4107
70 Kogler James F ◎ 836-5436
73 Curtis Louis N ◎ 834-7507
74 Onorato Victoria A Mrs ◎ 833-9426
77 Gurary Noson Rabbi ◎ 833-7662
78 Mc Namara Eliz C Mrs ◎ 834-6177
81 Momjian Saml ◎ 833-4816
82 Szakaly Wm ◎ 834-6608
85 Maguire Sylvia Mrs ◎
86 Marinaccio Concetta Mrs ◎ 836-5005
89 Tirado Cruz Jr ◎ 838-5465
90 Breadon Margt V Mrs ◎ 834-7941
95 Vacant
96 Susemihl Ida F Mrs ◎ 832-8750
97 Sarikas Theo ◎ 832-0388
100 Beggs Donald W ◎ 833-7923
101 Snitzer Arthene M Mrs ◎ 837-6496
104 Coca-Cola Vending Equipment Co
834-9231
Dallas James ◎ 834-9231
105 Collins Lavern ◎
109★Thompson Michl 832-0216
BELLEVUE ENDS
115 Taliaferro Stella M Mrs ◎ 833-0157
116 Toepfer Carl E ◎ 833-5868
119 Chmiola Chester S ◎ 832-4110
120 Burkard Christine Mrs ◎ 834-8687
123 Marotta Russell J
124 Rath Ruth G Mrs ◎ 832-9240
127 Newcomb Mary P ◎ 837-4780
128 Hudack Andrew ◎ 834-8976
131 Feron Edw J ◎ 833-1335
132 Rich-Mart Draperies carpets 836-2794
Sochet Lester D ◎ 836-8278
136 Daum Earle B real est ◎ 832-4330

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 1977



284

139 Studt Res
142 Lesser Geo V dentist 832-9337
KENMORE AV INTERSECTS

-3033
3-7317 NIANTIC ST —FROM 68
SHENANDOAH RD NORTHEAST

60

NORFO
DELA

ZIP C
301 Che
304 Pun

Target Street	Cross Street	Source
-	✓	Polk's City Directory

KENMORE AVE 1973



LYNDALE AV INTERSECTS
UNIVERSITY AV INTERSECTS

434

KENMORE AV (AMHERST TOWN OF TONAWANDA KENMORE)—FROM 3514 MAIN WEST

FOR EVEN NUMBERS SEE BUFFALO
ZIP CODE 14226
39 Amherst Bootery Inc 833-6974
41 Frisch Gustav A Inc optn 833-5415
43 Amherst Clothes Tree Inc women's 836-6711
47 Plaza Shoe Repair-Laundry & Dry Cleaning shoe repr 836-4041
Mike's Giant Submarines 838-3340

436

WINDERMERE BLVD INTERSECTS
59★Behringer Earl
Behringer Earl Diamonds Inc retail jwlry
Haircuts Underground barber shop 836-8869
63 Hudecki Steph E dentist 834-2744
Schaus James P phys 832-1050
Silvert Allen G podiatrist 833-8094
Sullivan James R phys 832-8044
71 University Medical Building
Central Park Clinical Laboratory 833-8166
Buckley Richd J phys 835-4400
Gauchat Joseph C dentist 835-0155
Safran Nathl radiologist 833-2223
Swierat John V Jr phys 833-1626
Weber Carl F dentist 836-1101
Wittkugel Herbert W phys 836-5191
Young Mark H phys 836-0470
CAPEN BLVD INTERSECTS
95 Neffke Aug F ◎ 834-6612
99 Wolf Joseph ◎ 832-2395
ALLENHURST RD INTERSECTS
135 Kenrick James C dentist 838-1286
★Sauer Emile C ◎ 836-4553
143 Dohn Funeral Home Inc 834-8128
175 Gas For Less

485

ZIP CODE 14223
181 Puehn Geo E meat market 833-4411
187 Alexander David L ◎ 836-7869
Keefe Pauline J 833-7549
189 Lazarski Henry Jr ◎ 835-5788
191 Brenner Matilda A Mrs ◎ 833-4968
LARCHMONT ENDS
193 Moritz Helene Mrs ◎ 833-9424
197 Wakefield Arth E ◎ 833-9211
199 Sylvester Wm M
★Fliederbaum Alysa 832-4815
203 Gates Electric Co Inc 837-5311
205 Imperial Hair Fashions 832-6558
GRANDVIEW AV BEGINS
HAWTHORNE AV BEGINS
217★Nice Wm 833-2871
Keily James C 838-3942
225★Crombie Paul T 832-3085

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAIN ST 1973

835-0101
Wallace Paul C 835-4393 32
Rooney Margt 832-5321
3171½ ★Smolanoff Joel 837-0753
Miranda Anthony M 837-3006 32
3172 Positively Main Street gifts 836-6100 32
3173 Guildcraft Co Of Buffalo Inc hobby shop 837-9346
W NORTHRUP PL BEGINS 32
3176 Granada Theatre 833-1300
Country Wide Theatre Inc 833-1300
York View Theatre Corp theatre 32
833-1300 32
3178 Wrzesien Pauline T Mrs 837-8045
Walder Linda B 835-0299 32
3180 Prakosh Product Of India pkg food products 837-8344
3182 Quackenbush John J Jr 837-0586
3184 Manufacturers & Traders Trust Co
Co (Br) 834-9272
3191 Taylor Charles B ◎ 833-3097
3193 ★Milligan Wes P 835-5425
Brody Edw Jr 837-2085
Co Ranus Kath Mrs 833-6614
Szymula Norbert J 837-4427
3198 Frank's Independent Service gas sta 836-9809
3199 Beef & Ale House No 1 837-9144
54 3201 Chez Beaute Boutique cosmetic shop 33
838-4784
★Stone Kenneth 832-0615
★Vinal Kath 838-5474

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAIN ST 1973

271

3203 Joe's Shoe Service repr
3205★Coyne Brian P
★Mac Arthur Lisa 832-3680
3211 Drago Petro Service gas sta 836-8973

198

WINSPEAR AV BEGINS
3208 Kaiser Candy Co Inc 833-7540
3210 Lewis Paul G 833-5188
★Ryan Rose H Mrs 833-8394
Dewitz Charles F phys 832-6262
Doll Raymond J dentist 833-8035
Parkside Beauty Shop 834-8640
3211 Vacant
3212 Main-Spear Delicatessen 836-0936
3214 Fairmont Antiques 837-0777
★Fishowak Jay
3216 Vacant
★Fry Gary
3218 College Laundry Shop The 833-0060
★Krasnow Richd 832-8778
MERRIMAC BEGINS
3223 North Main Liquor Store 834-7727
3225 North Buffalo Community Food Co-Op gros 836-8832
3229 Cantalician Center Workshop 833-5355
3230 Thompson Eug 838-3584
SUTTON LA BEGINS
3233 Cantalician Center For Learning sch 833-5353
Wagner Harold Rev 836-5276
3234 Metropolitan Laundry (Pick Up Sta) 834-2225
★Goldstein Denese
Vacant
3236 Plant Parlor plants 833-3945
Southall David 833-3945
3240 Vacant
O'Connell Lucas Chelf Inc men's col 836-4140
Rear Vacant
Vacant
★March Cheryl E 837-5831
Roetter Joseph J 837-2731
3242 Vacant
3248 Dog House The restr 834-7322
HEATH BEGINS
3258 Rifco Building
State Univ Ny At Bflo (Ofc Of Facilities Planning) constn div 831-4542
S U N Y A B Equip Div (Ofc Of Facilities Planning) 831-4421
Maloney John T lwyr 836-4574
Petrison Geo C ins agt 836-4575
3262 Hike & Bike als & serv 837-3300
Apartments
1★Barstis John
3★Wienitzer Mark
4★Duggan James
5 Buscimi Mario
6★Gall Cathy
7 Marnon Vincent C 837-9710
8★Keenan Frank
9★Bikremp Burt
10 Lehman Ronald
3264 Bitterman's Restaurant 838-4224
3266 Cricket Ticket Service 835-2828
3268 Needle & Thread Shop The tailors 833-0789
Pants A Plenty 836-9238
★Munshi Mechboob 838-4180
Guariglin Robt 833-2196
3269 Saint Joseph's Roman Catholic Church 833-0290
Larush Alton Rev 833-0290
3270 Vacant (3270-3274)
3275 Saint Joseph's Roman Catholic School 835-7395
Saint Joseph's Convent 833-7333
3276 Vacant
Vacant
ENGLEWOOD AV BEGINS
3288 Crowley Leo T Jr dentist 833-1350
3292 Chabad House jewish culture center 833-8334
3296 Chancellor Court Apartments
A1★Copeland Leslie 832-5880
A2 Schottin Dorothy B Mrs 837-3861
A3 Toepfer Mary
A4 Brandt Cath M Mrs 834-9451
B1★Sankarasubramanian R 832-3677
B2 Stengel Paul L 837-4741
B3★Miklun John H 832-5888
B4 Menn Richd T 832-4206
C1 Ranov Theo 834-1594
C2 Newberry Wilma J 835-0474
C3 Niedziela Ronald L 835-5251
C4 Griffin Michl
UNIVERSITY AV BEGINS
3330 Council Of Churches Of Bflo & Erie County campus ministry dept 834-4250
NIAGARA FALLS BLVD BEGINS
3334 University Presbyterian Church 836-7660
Council Churches Bflo Erie Cnty (College Wk Dept) 834-4250
S U N Y A B (Nursery Sch) 831-2248
3362 Your Host Restaurant Inc 836-9436
3380 Red Barn The restr 836-8789
3382 Arthur Treachers Fish & Chips 837-1998
3400 Militello's Luggage leather gds 833-1600
Ami Co Inc gifts & advertising splst 832-3149
Life Uniform Shop 833-2909
Apartments
1 Conjeski Raymond T 838-4542
2 Licastro Manuela G
3★Taraki Lisa 837-3788
4★Burns Larry 834-8130
3404 Downing Harold S Jr 832-0408
Amigone Helen K Mrs @ 834-5890
ALLENHURST RD BEGINS
3435 State University Of N Y At Buffalo 837-2000
State Univ Of New York At Bflo (Alumni Relations) 831-4121
State University Of N Y At Bflo Book Store 833-8090
Nuclear Research & Technology 831-2826
S U N Y A B (Univ Libraries) 831-2428
3442 University Court Apartments
Bsmt Smith Norman R 837-9705
A★La Breche Rayburn C Mrs 832-2874
A1 Murray John J 832-5195
A2 Levitt Pauline L 835-3130
A3 Cundal Doris A Mrs 834-5373
A4 Meyer Martin J 836-5867
A5 Vine Kath A Mrs 833-9388
A6 Glasser Esther G Mrs 834-6453
A7 Hawkins Ruth J Mrs 834-1964
A8 Finn Mary E Mrs 834-2783
A9 Conway Patk J 834-6771
A10 Dobmeier Susan 833-7217
A11 Vogt Mabel Mrs
A12★Goss Russell 837-9705
A14 Radder Mabel E Mrs 833-5965
A15 Smith Cath J Mrs 835-3991
B1 Gianadda Alfonso A 832-8982
B2 Argus Jane Mrs 837-5786
B3 Adams Dorothy J Mrs 838-1945
B4 Kober Emma Mrs 834-3413
B5 Ratigan Helen Mrs
B6 Rohe Louise M Mrs 833-9684
B7 Weber Edith Mrs 835-2696
B8 Johnson Edith Mrs 835-1389
B9★Frisch Alf 833-5529
B10 Glenn Vivian E Mrs 835-5770
B11 Feldman Grace Mrs 835-4057
B12 Baumann Mae 833-0292
B14 Franz Pauline Mrs 834-3880
B15★Gallen Clara Mrs 832-3446
1c Siragusa Joanne 837-5135
C2 Loesch Ralph F 833-1819
C3 Lenihan Denis 834-0052
C4 Sheldon Edna H Mrs 832-7213
C5 Collins Cora E Mrs 835-7882
C6 Kennedy Eliz S Mrs 834-2551
C7 Robert Charlotte 834-1442
C8 Neuffer Lyle Mrs 832-1163
C9 Garneau Isabelle Mrs 832-2316
C10 Rohe Edna E
C11 Gern Bertha H Mrs 834-8910
C12 Farrant Jane K Mrs 835-4282
C14 Johnson Helen M Mrs 834-6751
C15 Schnerie Esther 835-7318
CAPEN BLVD BEGINS
3484 Stephens J C Motor Corp autos 833-8140
WINDERMERE BEGINS
3488 Bert's Kendall Service Station 836-9207
Bert's Kendall Used Cars 836-9207
3500 Manufacturers & Traders Trust Co bank 832-9521
3514 Blackwell Plaza Service gas sta 836-9390
KENMORE AV BEGINS
CITY LIMITS

85

MALSCH ST —FROM 174 ESSER AV
NORTH THEN EAST

ZIP CODE 14207
10 Ferro Michl @
12 Loomis Frank H @ 875-5345
14 Skees Richd D @ 874-6242
15 Dudley Victor R @ 877-5915
16 Chapman Reginald A @ 877-3709
17 Cunningham Cath @ 875-6024
18 Mackie Leota R @ 876-2946
20 Soos Gaza J @ 873-9207

501 SIDWAY BLDG., 775 MAIN, BUFFALO, N.Y. 14203 TEL. 85

VENTILATING CONTRACTORS and ENGINEERS

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAIN ST 1973

MAIN ST (AMHERST WILLIAMSVILLE)
A CONTINUATION FROM BUFFALO CITY LIMITS EAST

ZIP CODE 14226

3582 Evans China & Gifts 834-3517
3584 Charlie's Barber Shop 837-3111
Vacant
Vacant
3586 Cavages Incorporated records 836-0041
Vacant
3588 Deli-Place 832-1456
SPRINGVILLE AV BEGINS
3604 Simmons Leo Liquor Store Inc 834-2116
Vacant
3606 I L I Consultants Inc ins consultants 836-3960
Brychta Kurt Violins violin sls 838-3606
Provident Security Inc 836-3960
Vacant
3608 Erie Federal Savings & Loan Assn (University Br) 834-2323
3610 Buffalo Textbook Stores Inc 833-7131
3612 University Manor Motel Inc 837-3344
CALLODINE AV BEGINS
3620 U S Oil Inc 836-9720
3626 Shop The water bed & leather shop 838-4288
3628 Half & Half Trading Co clothing & accessories 838-4744
460 3630 Onetto's Restaurant 836-9563
N BAILEY AV INTERSECTS

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 1973

CITY LIMITS

127

NIAGARA FALLS BLVD —FROM 3310
77 MAIN NORTH

ZIP CODE 14214
2 Sunyab Student Residence
22 Sceusa Frank J ◎ 836-7654
37★Hofer Robt R 837-1729
38 Gaglione Mariano C ◎ 835-7050
40 Chi Omega Sorority House 832-1149
41 Gay Kenneth C ◎ 837-9009
42 Payne Saml T ◎ 834-5413
43 Krystaf Joseph G ◎ 833-7799
45 Muldrow Leroy ◎ 832-6625
46 Nowak Steph F ◎
PELHAM DR BEGINS
50★Katrein Joseph E ◎ 837-2879
54 Metzger Michl M ◎ 837-3488
58 Caldarone Thos J ◎ 834-9232
62 Tremblay Lambert F acct ◎ 832-6082
65 Dorfer Julia L ◎ 832-1573
66 Klein Peter M ◎ 837-9007
69 Steele Clara H ◎ 834-4107
70 Fiedler Bernice J ◎
73 Curtis Louis N ◎ 834-7507
74 Onorato Victoria A Mrs ◎ 833-9426
77★Gurary Noson Rabbi ◎ 833-7662
78 Mc Namara Eliz C Mrs ◎ 834-6177
81 Momjian Saml ◎ 833-4816
82★Szakaly Wm 834-6608
85 Vacant
86 Marinaccio Concetta Mrs ◎ 836-5005
89★Tirado Cruz Jr ◎ 838-5465
90 Breadon Margt V Mrs ◎ 834-7941
95 Mae Phee Scott A ◎ 834-2951
96 Susemihl Ida F Mrs ◎ 832-8750
97 Sarikas Theo ◎ 832-0388
100 Beggs Donald W ◎ 833-7923
101 Snitzer Arthene M Mrs ◎ 837-6496
104 Coca-Cola Vending Co 834-9231
★Dallas James ◎ 834-9231
105 Collins Lavirn ◎
109 Brady Robt T ◎ 834-9580
BELLEVUE ENDS
112 Dadante Anthony F ◎ 832-1891
115 Taliaferro Stella M Mrs ◎ 833-0157
116 Toepfer Carl E ◎ 833-5868
119 Chmiola Chester S ◎ 832-4110
120 Burkard Frank L ◎ 834-8687
123 Marotta Russell J ◎ 836-3882
124 Rath Ruth G Mrs ◎ 832-9240
127 Newcomb Mary P ◎ 837-4780
128 Hudack Andrew ◎ 834-8976
131 Feron Edw J ◎ 833-1335
132 Rich-Mart Draperies carpets 836-2794
Sochet Lester D ◎ 836-8278
136 Daum Earle B real est ◎ 832-4330
139 Krauss Lisbeth Mrs ◎ 835-8259

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 1973



305

142 Lesser Geo V dentist 832-9337 178
KENMORE AV INTERSECTS 179
182
60 186
033 NIANTIC ST —FROM 68
7 SHENANDOAH RD NORTHEAST

Target Street	Cross Street	Source
-	✓	Polk's City Directory

KENMORE AVE 1968



---ALLENDALE RD INTERSECTS

230

KENMORE AV (AMHERST,TOWN OF TONAWANDA,KENMORE)-FROM 3514 MAIN WEST

---FOR EVEN NUMBERS SEE BUFFALO

---ZIP CODE 14226

39 JOHNSON'S AMHERST BOOTERY 833-6974

41 FRISCH GUSTAV A JWLR 833-5415

FRISCH ALF G OPTN 833-5415

43 AMHERST CLOTHES TREE INC WOMEN'S 836-6711

47 E & M FRUIT & VEGETABLE MARKET 834-5710

---WINDERMERE BLVD INTERSECTS

59 STEINHART JACOB M PEDIATRICS PHYS 835-5772

ZAMORA JUAN C 836-2258

63 COPLEY STANFORD S PHYS 832-1022

FISCHMAN EDW H PODIATRIST 833-8094

HUDECKI STEPH E DENTIST 834-2744

SCHAUS JAMES P PHYS 832-1050

SILVERT ALLEN G PODIATRIST 833-8094

SULLIVAN JAMES R PHYS 832-8044

71 UNIVERSITY MEDICAL BUILDING

CENTRAL PARK CLINICAL LABORATORY 833-8166

BUCKLEY RICHD J PHYS 835-4400

SAFRAN NATHL RADIOLOGIST 833-2223

SWIERAT JOHN V JR PHYS 833-1626

YOUNG MARK H PHYS 836-0470

---CAPEN BLVD INTERSECTS

95 NEFFKE AUG F • 834-6612

99 WOLF JOSEPH • 832-2395

---ALLENHURST RD INTERSECTS

135 SAUER EMILE C DENTIST • 836-4553

143 DOHN FUNERAL HOME 834-8128

DOHN CARLTON H • 832-0520

175 VACANT

---NIAGARA FALLS BLVD INTERSECTS

207

181 PUEHN GEO E MEATS 833-4411

187 ALEXANDER DAVID L • 836-7869

KEEFE PAULINE J 833-7549

189 LAZARSKI HENRY JR • 832-7764

191 BRENNER GEO • 833-4968

---LARCHMONT ENDS

193 MORITZ GEO J • 833-9424

197 MC CUTCHEON INK CO PRNTRS SUPS 834-3131

WAKEFIELD ARTH E • 833-9211

199 PLASKIN AARON • 832-7739

BRODY HAROLD B 834-9191

203 VACANT

205 RICHARD'S CLOTHING DISCOUNT CLOTHING

---GRANDVIEW AV BEGINS

---HAWTHORNE AV BEGINS

217 ROY RICHD A • 835-3054

SCHIEFFELIN EDW J 836-1770

225 TREADWAY CHARLES M

REINECKE ISABELLE MRS • 834-8159

PERMANENT SAVINGS & LO

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAIN ST 1968



MINTER MILLARD 837-8240
MINEMIER DIANA L 837-3947
CRZNER B 836-7326
3165 VACANT 326
3168 HERZOG'S DRUG STORE INC
834-1970 326
3171 STELLEY'S OPEN KITCHEN
RESTR 836-9472
GUTNAC BONNIE J 837-9535
3171½ STENGEL PAUL L • 837-4741
3172 CHRISTMAS STUDIO NO 2 INC
GIFTS 836-6100
3173 GUILDCRAFT CO OF BUFFALO
INC HOBBY SHOP 837-9346
---W NORTHRUP PL INTERSECTS
3176 PANTHER GRANADA THEATRE 326
833-7746
3178 BURAKOFF THEO
GRISSOM MARY A MRS 327
835-8608
3180 THORNTON REALTOR 834-2411 327
3182 GREEN BUNNY R MRS 836-6015
3184 MANUFACTURERS & TRADERS
TRUST CO (BR) 834-9272 327
3191 TAYLOR CHARLES B • 327
833-3097
3193 KRAJANOWSKI PAUL • 327
834-1856
ROMANIAK MONIKA I 835-4121
WALKER WM J 837-5584 ---
4 PISQUA HALLINA M 328
3198 AL'S MOBILE SERVICE GAS
STA 836-5989
---W WINSPEAR BEGINS 329
3199 BUFFALO BEEF & ALE HOUSE
INC RESTR 837-9144 329
RUBIN LARRY 836-4748
3201 GIROUX EDW BSM
3203 JOE'S SHOE SERVICE REPR
3205 LUCCI ROCCO A 832-1473
WOLDRUFF MARY 838-1958

YMCA

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAIN ST 1968

3208 PARKSIDE CANDY CO INC
833-7540
3210 LEWIS PAUL G 832-7005
DEWITZ CHARLES F PHYS
832-6262
PARKSIDE BEAUTY SHOP
834-8640
3211 GANDOLPH SINCLAIR SERVICE
GAS STA 837-9176
---WINSPEAR INTERSECTS
3212 DOLL RAYMOND J DENTIST
833-8035
MAIN-SPEAR DELICATESSEN
836-9241
3214 JUDY LYNN SHOP WOMENS CLO
832-9652
3216 DEL PRINCE HAIR FASHIONS
BEAUTY SHOP 836-6663
WOLFF MARGT MRS 835-1336
3218 COLLEGE LAUNDRY SHOP
833-0060
MC KENNA JOHN 837-5483
---MERRIMAC BEGINS
3223 NORTH MAIN LIQUOR STORE
834-7727
3225 VACANT
3229 CUE B BILLIARDS 836-0945
3230 POWRIE CHARLES
---SUTTON LA BEGINS
3233 CANTALICIAN CENTER FOR
CHILDREN SCH 836-4280
REAR LIPCZYNSKI JOSEPH REV
836-5276
3234 SOL'S ESQUIRE SHIRT
LAUNDRY INC 834-2225
WHITING DAVID 836-1975
3236 FLORETTE FLOWER SHOPPE
832-3421
MADDEN DANL A • 832-3421
3240 BOTSFORD DANL R OCULIST
832-8080
HENRICH MARY I OCULIST
832-8080
O'CONNELL LUCAS CHELF INC
MEN'S COL 836-4140
REAR GAS VAC HEATING CORP GAS
HTG 835-9001
REAR PFEFFER ELECTRIC CO
835-9001
CASTILLEN M ISABELINO
837-8728
OAKLEY LILLIAN MRS
3242 FRONTIER ELECTRICAL SUPPLY
INC 835-3714
3248 DOG HOUSE THE 833-3538
---HEATH BEGINS
3258 RIFCO BUILDING
STATE UNIV NY AT BFLO (OFC
OF FACILITIES PLANNING)
831-2109
MALONEY JOHN T LWYR
836-4574
3262 CAMPUS CORNER OF BUFFALO
INC CLO 832-3221
RASSOW ERICH
3264 BITTERMAN'S RESTAURANT
836-9266
BITTERMAN MARY C MRS •
836-9266
3266 CAMPUS BARBER SHOP
852-8109
3268 CHICKEN DELIGHT RESTR
834-6688
NEEDLE & THREAD SHOP THE
TAILORS 833-0789
SAYED SHAMIN AHMAD
837-5738
GHAYASUDDIN MCHAMMAD
837-5738
QURESHI TUFAIL 835-1544
JAVAID JAVAID
3269 SAINT JOSEPH'S ROMAN
CATHOLIC CHURCH 833-0290
RUNG ALBERT REV • 833-0290
3270 LIFE'S BUFFALO UNIFORM
SHOP INC 833-2909
3272 STATE UNIVERSITY OF NEW
YORK AT BFLO FACILITIES
PLANNING DEPT
3274 VACANT
3275 SAINT JOSEPH'S ROMAN
CATHOLIC SCHOOL 833-7333
3276 CADET CLEANERS (BR)
LOBMILLER JOSEPH 834-5135
RYAN ROSE H MRS 833-8394
---ENGLEWOOD AV BEGINS
3288 VACANT
CROWLEY LEO T JR DENTIST
833-1350
3292 GRANT BOOK & STAMP STORE
836-9124
3296 CHANCELLOR COURT
APARTMENTS
BSMT GREAT LAKES ORTHODONTIC
LABORATORY INC ORTHODONIC
APPLIANCE 837-3121

WARE AVE.

BUFFALO, N. Y. 14202

305 NIAGARA ST.

Agent For ALLIED VAN LINES

854

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAIN ST 1968

332

MAIN ST--CONTD
CHANCELLOR COURT
APARTMENTS--CONTD
A1 HOWARD JAMES F 837-6631
A2 SCHOTTIN DOROTHY B MRS 837-3861
A3 DESCARTES RENE M 836-1355
A4 BRANDT CATH MRS
B1 LOEWINGER ROBT J 838-2847
B2 O'SULLIVAN JEREMIAH 836-1025
B3 VANN SARAH K 837-4435
B4 JASSY LILIANA V MRS 837-5751
C1 MC ANERN DONALD M 837-7790
C2 NEWBERRY WILMA J 835-0474
C3 NIEDZIELA RONALD L 835-5251
C4 MUKAMAL SASSON J 837-3646
---UNIVERSITY AV BEGINS
---NIAGARA FALLS BLVD BEGINS
3330 STUDENT CHRISTIAN CENTER 834-4250
3334 UNIVERSITY PRESBYTERIAN CHURCH 836-7660
COUNCIL CHURCHES BFLO ERIE CNTY (COLLEGE WK DEPT) 834-4250
3362 COLONIAL HOUSE RESTAURANT 836-9436
3380 VACANT
3384 COUNTRY CORNER THE WOMEN'S CLO 836-2071
3400 CELEBRITY HOUSE INC MAIL ORDER 832-3149
MISTER COPY INC (BR) PNTG & COPYING 832-6985
MILITELLO P & SON LEATHER GDS 833-1600
AMI CO INC GIFTS & ADVERTISING SPLST 832-3149
APARTMENTS
1 PURSER ROBT J
2 JOYCE LARRY C 832-2428
3 PLANAVSKY RICHD 837-5618
4 BOEX JAMES R 833-9177
3404 WARREN IRENE A MRS 832-0408
AMIGONE JOSEPH N 834-5890
---ALLENHURST RD BEGINS
3435 STATE UNIVERSITY OF NY AT BUFFALO 837-2000
STATE UNIV OF NEW YORK AT BFLO (ALUMNI RELATIONS) 831-4121
STATE UNIVERSITY OF NY AT BFLC BOOK STORE 833-8090
STATE UNIVERSITY OF NY AT BFLO BOOK STORE 833-8990
STATE UNIVERSITY NY AT BFLO (CROSBY HALL) 831-3533
STATE UNIV OF N Y AT BFLO (DEPT OF AIR SCIENCE)
STATE UNIV OF NY AT BFLO (DEPT OF MUSIC) 831-3411
STATE UNIV OF NEW YORK AT BFLO (DEVELOPMENT OFC) 831-2140
STATE UNIV OF NY AT BFLC (FACULTY ARTS & LETTERS)
STATE UNIV OF NY AT BFLC (FACULTY HEALTH SCIENCE) 831-3711
STATE UNIV OF NY AT BFLC (OPERATION & SYS)
STATE UNIV OF NY AT BFLC (PUBLICATIONS)
STATE UNIV OF NEW YORK AT BFLO (DIEFENDORF BLDG) 837-2000
STATE UNIV OF NY AT BFLO (STUDT AFFAIRS)
STATE UNIV NEW YORK AT BFLO (PHYSICAL EDUC DEPT) 831-2935
STATE UNIV OF NEW YORK AT BFLO (RIDGE LEA RD) 831-1252
STATE UNIV OF NY AT BFLC (GOODYEAR HALL) 831-4925
STATE UNIV NY AT BFLO (HAYES HALL B) 831-2100
STATE UNIV OF NY AT BFLO (HAYES HALL) 831-5218
STATE UNIV OF NY AT BFLC (HEALTH SCIENCE LIBRARY) 831-2441
STATE UNIV OF NY AT BFLC (LAW SCH) 852-4372
STATE UNIV NY AT BFLO (MILLARD FILLMORE COLLEGE) 831-2204
STATE UNIV OF NY AT BFLC (NORTON HALL) 831-2511
STATE UNIV OF NY AT BFLC (PLANNING & DEVELOPING) 831-2140
STATE UNIV OF NY AT BFLO (SCH OF BUSINESS ADMN) 831-3533
STATE UNIV OF NY AT BFLC (SCH OF DENTISTRY) 831-2837
STATE UNIV OF NY AT BFLC (SCH OF EDUC) 831-2810
STATE UNIV NY AT BFLO (SCH OF ENG) 831-3104
STATE UNIV OF NY AT BFLO (SCH OF MEDICINE) 831-2811
STATE UNIV OF NY AT BFLC (SCH OF SOCIAL WELFARE) 831-2526
STATE UNIV OF NY AT BFLC (SUMMER SESSION) 831-2411
STATE UNIV OF NY AT BFLO (UNIV COLLEGE) 831-3517
STATE UNIV OF NY AT BFLO (OFC OF FINANCIAL AID) 831-3725
WESTERN NEW YORK NUCLEAR RESEARCH CENTER INC 831-2826
LOCKWOOD MEMORIAL LIBRARY 831-2436
UNIVERSITY OF BFLO FOUNDATION INC 831-4232
HEALTH SCIENCE LIBRARY 831-2441
3442 UNIVERSITY COURT APARTMENTS
BSMT SMITH NORMAN P 837-9705
A1 MURRAY JOHN J 832-5195
A2 LEVITT PAULINE L 835-3130
A3 CUNDALL DORIS A MRS 834-5373
A4 MEYER M J 836-5867
A5 VINE KATH A 833-9388
A6 GLASER E G
A7 ARGUS JANE 837-5786
A8 FINN MARY E MRS 834-2763
A9 MARMOL FANNY R 833-6468
A10 CONWAY PATRICK J 834-6771
A11 BERGWALL NINA M MRS 836-6847
A12 RUBERY MARJORIE MRS 836-8884
A14 RADDER MABEL E MRS 833-5965
A15 SMITH CATH J 835-3991
B1 GIANADDA ALFONSO A 832-8982
B2 KINSLEY KATH M MRS 836-7193
B3 SEDLAK LYNNA J 836-7778
B4 SARGENT INA 838-1488
B5 RATIGAN HELEN
B6 ROHE LOUISE M MRS 833-9684
B7 WEBER EDITH MRS 835-2696
B8 MOTTRAM MABEL J MRS 832-8742
B9 VACANT
B10 GLENN VIVIAN E MRS 835-5770
B11 FELDMAN GEORGE J MRS 835-4057
B12 ROESTER MARTHA MRS 832-2003
B14 FRANZ PAULINE 834-3880
B15 QUELLAS HELEN M MRS 832-3446
1C SIRGUSA JOANNE 837-5135
C2 LOESCH RALPH F 833-1819
C3 LENIHAN DENNIS 834-0052
C4 ALGASE SOL
C5 COLLINS CORA E 835-7882
C6 MURPHY J F
C7 ROBERT CHARLOTTE 834-1442
C8 NEUFFER LYLE MRS 832-1163
C9 GARNEAU ISABELLE 832-2316
C10 ROHE EDNA E 837-8450
C11 GERN BERTHA H MRS 834-8910
C12 FARRANT JANE K 835-4262
C14 JOHNSON HELEN M 834-6751
C15 SCHNERLE EARL P 836-7318
---CAPEN BLVD BEGINS
3484 STEPHENS J C MOTOR CORP AUTOS 833-8140

1300 CHAMBER OF COMMERCE BUILDING BUFFALO, N.Y. 14202

Meehanite — Gray I-

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAIN ST 1968



Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAIN ST 1968

230

MAIN ST (AMHERST, WILLIAMSVILLE)-A
CONTINUATION FROM BUFFALO CITY
LIMITS EAST

---ZIP CODE 14226
3582 EVANS GIFT SHOP 834-3517
3584 CHARLIE'S TONSORIAL CENTER
836-9080
PARKHILL & HART LAUNDRY INC
(BR)
CHAIT ROBT J 834-4129
PELLETIER FRANCIS 833-9767
3586 CRICKET TICKET SERVICE INC
THEATRE TICKET AGCY 835-2828
SCHWARTZ CHARLES
WALKER ARTIE L 837-7596
3588 UNIVERSITY DELICATESSEN
832-1456
TAYLOR TRAVEL SERVICE INC
834-7588
WESTERN NEW YORK HOTEL
RESERVATION SERVICE 834-7588
---SPRINGVILLE AV BEGINS
3604 SIMMONS LEO LIQUOR STORE INC
834-2116
WEBER CARL F DENTIST 836-1101
3606 I L I CONSULTANTS INC INS
CONSULTANTS 836-3960
SIRE ASSOCIATES ACCTS 835-8400
FULSOM E L PHYS
BRUTMAN MALCOLM D LWYR 835-8400
SILVERMAN SAUL S LWYR 835-8400
WRIGHT LONG & CO ACCTS 835-8400
3608 ERIE FEDERAL SAVINGS & LOAN

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 1968



123

NIAGARA FALLS BLVD -FROM 3310
MAIN NORTH

---ZIP CODE 14214
2 THETA CHI FRATERNITY 836-9895
22 SCEUSA FRANK S ● 836-7654
37 VACANT
38 GAGLIONE MARIANO C ●
835-7050
40 CHI OMEGA SORORITY 836-5631
41 GAY KENNETH C ●
42 EVERYBODY'S CLEANING SUPPLY
CO 834-5413

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 1968

NIAGARA FALLS BLVD--CONTD
PAYNE SAML T • 834-5413
43 KRYSTAF JOSEPH G • 833-7799
45 CIMINELLI FRANK L • 836-4372
46 NOWAK STEPH F •
---PELHAM DR ENDS
50 NO RETURN
54 METZGER MICHL M • 837-3488
58 CALDARONE THOS J • 834-9232
62 TREMBLAY LAMBERT F • 832-6082
65 DORFER JULIA L • 832-1573
66 KLEIN PETER M • 837-9007
69 STEELE CLARA H • 834-4107
70 FIEDLER BERNICE J •
73 CURTIS LOUIS N • 834-7507
74 HAENDIGES VICTORIA A MRS • 833-9426
77 FRAWLEY WM J • 832-4461
78 MC NAMARA ELIZ C MRS • 834-6177
81 MOMJIAN SAML • 833-4816
82 CAPIZZI LEONARD S • 834-7423
85 COTTIS HELEN MRS • 833-4784
86 MARINACCIO CONCETTA MRS • 836-5005
89 BIDELL WM E • 835-7251
90 BREADON JOHN A • 834-7941
95 FOERTTER LINCOLN H • 834-2951
96 SUSEMIHL ALF L • 832-8750
97 SARIKAS THEOD • 832-0388
100 BEGGS DONALD W • 833-7923
101 SNITZER WM J • 837-6496
SNITZER MICHL S 835-7885
104 COCA-COLA VENDING CO 834-9231
KANELOS ERNEST G • 834-9231
105 PEACOCK DAVID A • 833-4324
109 BRADY ROBT T • 834-9580
---BELLEVUE ENDS
112 DADANTE ANTHONY F • 832-1891
115 TALIAFERRO STELLA MRS • 833-0157
116 TOEPFER CARL E • 833-5868
119 PAPPAS CLARENCE L •
120 BURKARD FRANK L • 834-8687
123 MAROTTA RUSSELL J
124 RATH RUTH G MRS • 832-9240
127 LENEGHER JAMES T • 837-4780
128 HUDACK ANDREW • 834-8976
131 FERON EDW J • 833-1335
132 RICH-MART DECORATORS CARPETS 836-2794
SOCHET LESTER D • 836-8278
136 DAUM EARLE B REAL EST • 832-4330
139 AMARANTE BRIDGET F MRS • 834-0020
142 LESSER GEO V DENTIST 832-9337
---KENMORE AV INTERSECTS

56

NIANTIC ST -FROM 68 SHENANCCAH RD NORTHEAST

61 62 65 66 69 71 72 75 76 79 80 81 87 88 91 95 100 101 102 105 110 111 115 116 120 121 --- --- 152 155 156 159 160 163 166 167 170 171 174 175 178

Target Street	Cross Street	Source
-	✓	Polk's City Directory

KENMORE AVE 1964

88 Gancarz Jos ◎ TF5-3073
Allendale rd intersects

230
KENMORE AV (Eggertsville)—From 3514 Main west
Zone 26
39 Johnson's Amherst Bootery shoes TF3-6974
41 Frisch Gustav A jwlr TF3-5415
43 Amherst Clothes Tree Inc womens TF6-6711
47 E&M Fruit & Vegetable Mkt TF4-5710
Windermere intersects
59 Hollerman Chas E TF2-9072
63 Schaus Jas P phys TF2-1050
Sullivan Jas R phys TF2-8044
Hudecki Steph E dentist TF4-2744
Early Robt L phys TF2-8044
Silvert Allen G podiatrist TF3-8094
71 Swierat John V jr phys TF3-1626
Siegner Allan W phys TF6-8380
Anllo Victorino phys 835-2252
Wildhack Robt H phys TF6-8380
Central Park Clinical Laby TF3-8166
Safran Nathl radiologist TF3-2223-TF3-2224
Berkson Robt S phys TF4-8161
Young Mark H phys TF6-0470
Capen blvd intersects
95 Neffke Aug F ◎ TF4-6612
99 Wolf Jos ◎ TF2-2395
135 Sauer Emile C ◎ dentist TF3-8444-TF6-4553
Sauer Richd E dentist TF3-8444
Allenhurst rd begins
143 Dohn Funeral Home TF4-8128

624 GENESEE BLDG., BUFFALO, N. Y. 14202

Target Street	Cross Street	Source
-	✓	Polk's City Directory

KENMORE AVE 1964

Dohn Carlton H ◎ TF2-0520
175 Joseph's Ashland Serv gas sta 836-9002
Niagara Falls blvd intersects
207
181 Puehn Geo E ◎ meats TF3-4411
187 Alexander David L ◎ TF6-7869
189 Lohouse Geo F ◎ TF3-5233
191 Brenner Geo ◎ TF3-4968
Larchment rd ends
193 Moritz Geo J ◎ TF3-9424
197 McCutcheon Bros & Quality Inc TF4-3131
Wakefield Arth E ◎ TF3-9211
199 Plaskin Aaron ◎ TF2-7739
Brody Harold B ◎ TF4-9191
203 Conshafter R W Real Estate 832-0021
205 Grandview Tailors & Clns TF2-2910
Grandview av begins
Hawthorne av begins
217 Roy Richd A ◎ TF5-3054
Haag Donald J 833-9125
225 Arbour Herve TF2-3730
Byrnes David C 837-4283
229 Werder Paul K ◎ chiropractor TF4-7974
233 Stieg Louise A Mrs ◎ TF4-1238
Moll Ruth S Mrs TF4-3114
Radcliff rd ends
237 Henry Ottilie D Mrs ◎
Nesselbeck Norman G TF4-8552
241 Pontikos Sam ◎ TF3-5756
Pinkus Allen
245 Ayer Bessie Mrs ◎ TF2-9249
Ayer Judd C TF2-7510
249 Tronolone Evelyn M Mrs ◎ curtains and draperies TF4-2082
Tronolone Michl H TF4-2082
251 Hyland Robt B 837-6426
DiBartolo Jos
253 Parade of Homes Inc real est &

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAIN ST 1964

E-Z Drive Auto Sch TF2-4735
Safe-Way Driving Sch TF4-4300
Northrup pl intersects
3176 Schine's Granada Theatre TF3-7746
3178 Grissom Mary A Mrs TF5-8608
Forsythe Alice
3180 Thornton Realtor TF4-2411
3182 Vacant
3184 Manufacturers & Traders Trust Co (br) TF4-9272
3191 Taylor Chas B © TF3-3097
3193 Updike Kath S 833-7457
Pisqua Helena
W Winspear av begins
3198 Arkeilpane Robt J gas sta TF6-9588
3199 Anderson Rich 836-6248
Upper Level The 836-9490
3201 Brownell Carol 832-5150
Bunner Robt 837-4631
3203 Joe's Shoe Serv shoe repr
3205 Erickson Furniture Co TF3-1937
Grader Helen Mrs TF3-6796
Shah Prabodh TF4-4835
3208 Parkside Candy Co Inc TF3-7540
3210 Parkside Beauty Shop TF4-8640
Doll Raymond J dentist TF3-8035
Dewitz Chas F phys TF2-6262
Schneider Mary
3211 Main Winspear Sinclair gas sta 836-9323
Northrup pl intersects
3212 Main-Spear Delicatessen TF6-9241
3214 Judy Lynn Shop clo TF2-9652
Clift Janis S 832-2439
3216 Del Prince Hair Fashions beauty shop TF6-6663
Wolff Margt Mrs TF5-1336
3218 Vacant
Merrimac begins
3223 North Main Liquor Store TF4-7727

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAIN ST 1964

3225 SUNYAB (storage)
3229 Sheeham's Cue B 836-8921
3230 Launderette TF3-0060
Sutton la begins
3233 Cantalician Center for Children TF6-4280
O'Shea John T Rev ® TF6-5276
3234 Sol's Esquire Laundry & Clnrs shirt TF4-2225
Campus Delicatessen TF6-9686
3236 Madden Danl A ® TF2-3421
3240 Stewart In-Fra Red Commissary caterers TF2-9650
O'Connell Lucas Chelf Inc men's clo TF6-4140
Botsford Danl R oculist TF2-8080
Henrich Mary I oculist TF2-8080
Meyer Val TF2-4718
3242 Frontier Electrical Supply Inc TF5-3714
Heath begins
3258 Riffel J H Co Inc bldg contr TF4-1498
Investors Diversified Service Inc TF6-3935
Clean All Assocs Inc dry cln equip TF5-4747
Maloney John T lwyr TF6-4574
3260 Marnon Vincent C TF3-0188
3262 Campus Corner of Buffalo Inc clo TF2-3221
Redder Adam TF5-3717
Posner David TF4-7232
3264 Bitterman Mary C Mrs ® TF6-9266
Bitterman's Restaurant TF6-9266
3266 Campus Barber Shop
3268 Needle & Thread Shop The tailors TF3-0789
Silk Gladys Mrs
Chicken Delight restr TF4-6688
3269 StJoshph's RC Church TF3-0290
3270 Buffalo Uniform Shop Inc TF3-2909
Angelica Uniform Co TF3-2909
3271 Rung Albert Rev TF3-0290
3274 No Return
3275 StJoseph's RC School TF3-7333
3276 Cadet Cleaners (br)
Lobmiller Jos TF4-5135
Ryan Jacob F TF3-8394
Englewood av begins
3288 Shupe & Co Inc food broker TF5-5411
University Opticians TF6-5721
Dynamatic Division Eaton Manufacturing Co mach mfrs TT6-0850
3292 Deco Restaurants Inc (br) TF6-9561
University av begins
Niagara Falls blvd begins
3330 Student Christian Center TF4-4250
3334 University Presbyterian Church TF6-7660
Council of Churches of Buffalo & Erie Co (College Work Dept) TF4-4250
3362 Colonial House Restaurant (br) TF6-9436
3380 Smith & Clody Inc beverage mfrs TF4-0695
3384 Country Corner The clo TF6-2071
3400 Ami Co Inc gifts TF2-3149
Student Book Shop TF3-7000
Costes Donald
Baranovic Boris I
Buell John
Celebrity House Inc novelties TF2-3149
3404 Amigone Jos N ® TF4-5890
Warren Irene A Mrs TF2-0408
Allenhurst rd begins
3435 **State Univ of NY at Buffalo 831-2001** 831-2001
Book Store 831-2444
School of Engineering 831-3104
University College 831-2011
Goodyear Hall 831-3322
University Relations 831-2928
WBFO Radio Station 831-3405
Veteran Education Services 831-3724
Graduate School of Arts & Sciences 831-3008
School of Dentistry 831-2837
School of Medicine 831-2811
Development Office 831-2121
Planning & Developing 831-2140
Health Science Library 831-2441
School of Business Administration 831-3533
Lockwood Memorial Library 831-2428
Norton Hall 831-2511
Dept of Music 831-3411
School of Pharmacy 831-2546
Liaison Office
Foster Hall 837-2000
Hayes Hall 837-2000
Summer Session 831-2000
Dept of Air Science 831-2945
Health Science Building 831-3513
Crosby Hall 831-3440
Alumni Office 831-3336
School of Education 831-2415
Western NY Nuclear Research Center 831-2826
Millard Fillmore College 831-2204
School of Nursing 831-2533
School of Social Work 831-2526
Diefendorf Bldg 837-2000
3442 **University Court Apartments**
bsmt Caldaria Frank
Apartments
A1 Murray John J TF2-5195
A2 Levitt Pauline L TF5-3130
A3 Cundal Doris A Mrs TF4-5373
A4 Ryan Ruth M Mrs TF4-5770
A5 Baker Wm S TF3-4637
A6 Hall Mildred C
A7 Gibson Alice L Mrs TF6-0389
A8 Finn Mary E Mrs TF4-2783
A9 Volk Margt TF3-7718
A10 Conway Patk J TF4-6771
A11 Bergwall Milton E TF6-6847
A12 Rubery Marjorie Mrs TF6-8884
A14 Radder Mabel E Mrs TF3-5965
A15 Smith Cath J TF5-3991
B1 Glanadda Alphonso A TF2-8982
B2 Kinsley E J 836-7193
B3 Sedlak Lynna J 836-7778
B4 Jones Margt L TF4-5219
B5 Wilson Reuben C
B6 Rohe Louise M Mrs TF3-9864
B7 Weber Edith TF5-2696
B8 Mottram Mabel J Mrs TF6-0204
B9 Frisch Gustan A 834-4603
B10 Glenn Arth C TF5-5770
B11 Ehman Elsie Mrs TF2-3466
B12 Koester Martha Mrs TF2-2003
B14 Fronczak Alice A
B15 Quellos Martin TF2-3446
C1 Keefe Pauline J TF3-7549
C2 Loesch Ralph F TF3-1819
C3 Lenihan Dennis TF4-0052
C4 Algase Sol
C5 Cohen Lawrence TF3-0984
C6 Rhodehouse Mildred M Mrs TF3-3763
C7 Robert Chas
C8 Neuffer Lyle Mrs TF2-1169
C9 Jacobs Louise D
C10 Flynn Edw J TF4-8120
C11 Gern Bertha Mrs TF4-8910
C12 Farrant Jane TT5-4282
C14 Bisk Barbara
C15 Wakefield June D
Capen blvd begins
3484 Stephens J C Motor Corp autos TF3-8140
Stevens Ford Corp TF3-8140
3488 Bert's Kendall Service Station TF6-9207
Zone 26
3514 Blackwell Plaza Service gas sta TF6-9390
3582 Evans Gift Shop TF4-3517

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAIN ST 1964



MAIN—Contd

3584 Charlie's Barber Shop TF6-9084
Rook Violet Mrs
3586 Parkhill & Hart Lndry Inc (br)
3588 University Delicatessen TF2-1456
Taylor Travel Serv Inc TF4-7588
3604 Simmons Liquor Store TF4-2116
Weber Carl F dentist TF6-1101
3606 Silverman Saul S lwyr TF5-8400
Goldfarb Geo dentist TF5-5885
Brutman Malcolm D lwyr TF5-8400
Wright Long & Co accts TF5-8400
Fischman Stuart L dentist TF5-6224
3608 Erie Federal Savings & Loan Assn (br) TF4-2323
3610 Bflo Text Book Store Inc TF3-7131
3620 Gordon's Service gas sta TF5-0242
3624 Vacant
3636 Tai-Wan Restr TF6-9709
3630 Onetto's Restaurant TF6-9563
City limits

83

MALSCH—From 78 Esser av north

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 1964



Vulcan begins
City limits

123

NIAGARA FALLS BLVD—From 3310 Main north

Zone 2

2 Theta Chi fraternity 836-9895
22 Denler Norman A ◎ TF4-7182
37 Laird Robt H Rev TF3-2750
38 Gaglione Mariano C ◎ TF5-7050
40 Race Willfred E osteo TR5-0888 and TF2-9434
41 Hollander Edwin P ◎ TR6-4317
42 Payne Saml T jr ◎ TR4-5413
43 Krystaf Jos G ◎ TF3-7799
45 Ciminelli Frank L ◎ TF6-4372
46 Nowak Steph F ◎ TF3-6264

Pelham dr ends

50 Zembaty Frances Mrs TF5-3463
54 Mix David F ◎ TF6-5388
58 Caldarone Thos J ◎ TF4-9232
62 Tremblay Lambert F ◎ TF2-6082
65 Dorfer Julia L ◎ TF2-1573
66 Rease Geo E ◎ TF5-4592
69 Steele Clara H ◎ TF4-4107
70 Hagberg Anna F Mrs ◎ TF4-9343
73 Curtis Louis N ◎ TF4-7507
74 Haendiges Chas C ◎ TF3-9426
77 Frawley Wm J ◎ 832-4461
78 McNamara Emmet J ◎ TF4-6177
81 Momjian Saml ◎ TF3-4816
82 Capizzi Leonard S ◎ TF4-7423
85 Cottis Nicholas J ◎ TF3-4784

Rooms
101
111-1
112-1
113 D
117-1
121-2
201 M
202 C
203 D
214-1
218 C
219 F

CONTINENTAL INN HO

Target Street	Cross Street	Source
-	✓	Polk's City Directory

NIAGARA FALLS BLVD 1964



86 Marinaccio Concetta Mrs ◎ TF6-5005
89 Lehr Adlaide L ◎ TF3-3921
90 Breadon John A ◎ TF4-7941
95 Foertter Lincoln H ◎ TF4-2951
96 Susemihl Alf L ◎ TF2-8750
97 Sarikas Theo ◎ TF2-0388
100 Beggs Donald W ◎ TF3-7923
101 Cook J Douglas ◎ TF2-9282
104 Kanelos Ernest G ◎ TF4-9231
Coca Cola Vending Co TF4-9231
105 Peacock Bernard R ◎ bldg contr
833-4333
109 Brady Wm T ◎ TF4-9580

Bellevue ends

112 Dadante Anthony F ◎ TF2-1891
115 Taliaferro Stella M Mrs ◎ TF3-0157
116 Toepfer Carl E ◎ TF3-5868
119 Pappas Leon J ◎ TF5-2481
120 Burkard Frank L ◎ TF4-8687
123 Marotta Russell J TF6-8541
124 Rath Ruth G Mrs ◎ TF2-9240
127 Lenegher James T ◎ 837-4780
128 Hudack Andrew ◎ TF4-8976
131 Feron Edw J ◎ TF3-1335
132 Rich-Mart Draperies TF6-2794
Sochet Lester D ◎ TF6-2794
136 Daum Earle B real est ◎ 832-4330
and 833-2234
139 Amarante Albert B ◎ dentist
TF4-7742
142 Lesser Geo V ◎ dentist TF2-9337

Kenmore av intersects

1B5

NIAGARA SQ—At junction of Niagara

1040 Kensington Ave.
Buffalo, N. Y. 14215
Tels. 833-3701

Metro Rail Expansion Corridor
City of Buffalo, Towns of Tonawanda and Amherst
Buffalo, NY 14228

Inquiry Number: 5532017.2
January 16, 2019

The EDR-City Directory Image Report

Environmental Data Resources Inc

6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION

Executive Summary

Findings

City Directory Images

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction orforecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2017 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc. or its affiliates is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

DESCRIPTION

Environmental Data Resources, Inc.'s (EDR) City Directory Report is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's City Directory Report includes a search of available city directory data at 5 year intervals.

RECORD SOURCES

EDR's Digital Archive combines historical directory listings from sources such as Cole Information and Dun & Bradstreet. These standard sources of property information complement and enhance each other to provide a more comprehensive report.

EDR is licensed to reproduce certain City Directory works by the copyright holders of those works. The purchaser of this EDR City Directory Report may include it in report(s) delivered to a customer. Reproduction of City Directories without permission of the publisher or licensed vendor may be a violation of copyright.



RESEARCH SUMMARY

The following research sources were consulted in the preparation of this report. A check mark indicates where information was identified in the source and provided in this report.

Year	Target Street	Cross Street	Source
2019	☐	☑	Polk's City Directory
2014	☐	☑	Polk's City Directory
2008	☐	☑	Polk's City Directory
2004	☐	☑	Polk's City Directory
1998	☐	☑	Polk's City Directory
1992	☐	☑	Polk's City Directory
1988	☐	☑	Polk's City Directory
1983	☐	☑	Polk's City Directory
1977	☐	☑	Polk's City Directory
1973	☐	☑	Polk's City Directory
1968	☐	☑	Polk's City Directory
1963	☐	☑	Polk's City Directory

FINDINGS

TARGET PROPERTY STREET

City of Buffalo, Towns of Tonawanda and Amherst
Buffalo, NY 14228

No Addresses Found

FINDINGS

CROSS STREETS

Year	*CD Image*	*Source*	
JOHN J AUDUBON PKWY			
2019	pg. A1	Polk's City Directory	
2019	pg. A2	Polk's City Directory	
2019	pg. A3	Polk's City Directory	
2014	pg. A10	Polk's City Directory	
2014	pg. A7	Polk's City Directory	
2014	pg. A8	Polk's City Directory	
2014	pg. A9	Polk's City Directory	
2008	pg. A16	Polk's City Directory	
2008	pg. A17	Polk's City Directory	
2008	pg. A18	Polk's City Directory	
2008	pg. A19	Polk's City Directory	
2004	pg. A24	Polk's City Directory	
2004	pg. A25	Polk's City Directory	
1998	pg. A28	Polk's City Directory	
1998	pg. A29	Polk's City Directory	
1992	pg. A33	Polk's City Directory	
1988	pg. A36	Polk's City Directory	
1983	pg. A40	Polk's City Directory	
1977	-	Polk's City Directory	Street not listed in Source
1973	-	Polk's City Directory	Street not listed in Source
1968	-	Polk's City Directory	Street not listed in Source
1963	-	Polk's City Directory	Street not listed in Source
MAPLE RD			
2019	pg. A4	Polk's City Directory	
2019	pg. A5	Polk's City Directory	
2014	pg. A11	Polk's City Directory	
2014	pg. A12	Polk's City Directory	
2014	pg. A13	Polk's City Directory	
2008	pg. A20	Polk's City Directory	
2008	pg. A21	Polk's City Directory	
2004	pg. A26	Polk's City Directory	

FINDINGS

Year	CD Image	Source
1998	pg. A30	Polk's City Directory
1998	pg. A31	Polk's City Directory
1992	pg. A34	Polk's City Directory
1988	pg. A37	Polk's City Directory
1988	pg. A38	Polk's City Directory
1983	pg. A41	Polk's City Directory
1983	pg. A42	Polk's City Directory
1977	pg. A44	Polk's City Directory
1977	pg. A45	Polk's City Directory
1973	pg. A47	Polk's City Directory
1973	pg. A48	Polk's City Directory
1968	pg. A50	Polk's City Directory
1968	pg. A51	Polk's City Directory
1963	pg. A54	Polk's City Directory

SWEETHOME RD

2019	pg. A6	Polk's City Directory
2014	pg. A14	Polk's City Directory
2014	pg. A15	Polk's City Directory
2008	pg. A22	Polk's City Directory
2008	pg. A23	Polk's City Directory
2004	pg. A27	Polk's City Directory
1998	pg. A32	Polk's City Directory
1992	pg. A35	Polk's City Directory
1988	pg. A39	Polk's City Directory
1983	pg. A43	Polk's City Directory
1977	pg. A46	Polk's City Directory
1973	pg. A49	Polk's City Directory
1968	pg. A52	Polk's City Directory
1968	pg. A53	Polk's City Directory
1963	pg. A55	Polk's City Directory

City Directory Images

Target Street	Cross Street	Source
-	✓	Polk's City Directory

JOHN J AUDUBON PKWY 2019



+ COMMERCE DR BEGINS

BUSINESSES 23 HOUSEHOLDS 9

JOHN JAMES AUDUBON PKWY (BUFFALO)

• ZIP CODE 14228 CAR-RT C061

)641 1 AMITRANO LORETTA J nurses- practitioners ✓

BELLINGER TRISH M NP nurses-practitioners ✓

)530 BUKHARI SYED W MD physicians & surgeons ✓ @ 716-849-8750

4) CHIMA MARY MD physicians & surgeons ✓

4259 716-849-8750

CUKIERSKI JACOB J DO physicians & surgeons ✓ 716-849-8750

EDDY SUSAN M PA physicians assistants ✓

5432 FERGUSON MICHAEL S MD physicians &

5432 surgeons 716-817-2929

GONCALVES PATRICK J NP nurses-

9602 practitioners ✓ 716-817-1928

Target Street	Cross Street	Source
-	✓	Polk's City Directory

JOHN J AUDUBON PKWY 2019

JOHN JAMES AUDUBON PKWY - JONES RD

JOHN JAMES AUDUBON PKWY Cont'd

KOTHARI NIRMIT D MD physicians & surgeons ✓ 716-817-2929
PATEL MEGHA H nurses- practitioners ✓
PATTON AMY M PA physicians & surgeons ✓
PIETROMICCA CHERYL PA physicians assistants ✓ 716-817-2929
TEAMHEALTH physicians & surgeons ✓ 716-849-8750
USLINOV STEPHEN MD physicians & surgeons 716-874-2273
VASILOFF ALYSSA C physicians assistants
WEHRLE DENISE A NP nurses- practitioners ✓
1 GOLDHABER REASEARCH ASSOC nonclassified establishments ✓ 716-689-3342
2 BELLINGER JEREMY S NP nurses-practitioners ✓
2 ENGLE TAMMY E C NP nurses-practitioners ✓
2 LOVE ELIZABETH M MD physicians & surgeons ✓
2 POMATTO RENEE NP nurses-practitioners ✓
2 WITMAN JODI L NP nurses- practitioners ✓
100 PRUDENTIAL FINANCIAL insurance ✓@ 716-636-1960
200 INTERLICHIA JAMIE C PA physicians assistants ✓
200 SILLIMAN CARRIE nurses- practitioners ✓
210 AHMAD ANEES MD physicians & surgeons ✓

+ N FOREST RD INTERSECTS

10 A MUIR LAKE CONSULTING CORP insurance ✓@ 716-689-1700
A NATIONAL FIRE ADJUSTMENT insurance adjusters ✓ 716-689-7700
B COM DOC copying/duplicating mach/supl 716-689-0202
C GOLDHABER RESEARCH ASSOC LLC educational research ✓ ..716-689-3311
101 AMERICAN CANCER SOCIETY associations ✓@ 716-689-6981
140 Ballard Tonya B
COLUMBUS MC KINNON CORP nonclassified establishments
Dom Cindy R
YALE INDUSTRIAL PRODUCTS INC mfrs distrs & indl products 716-689-5409
200 Duchscherer Wendel 14
151 NATIONAL TRAFFIC SVC INC marketing programs & serv ✓ 716-636-8253
200 BROWN & BROWN OF NEW YORK INC insurance ✓ 716-995-5620
BUFFALO NIAGARA ASSN OF RLTR associations ✓@ 716-636-9000
GIACOMO RICHARD attorneys ✓ 716-688-3800
NESPER FERBER & DI GIACOMO attorneys ✓ 716-688-3800
Peterson Victor L
102 ACTUARIAL CONSULTING SVC INC pension & profit sharing plans 716-691-2181
105 SCHWARTZ GROUP INC marketing programs & serv ✓ 716-635-9650
105 VOCAL TECHNOLOGIES LTD nonclassified establishments ✓ 716-688-4640
107 Couzo Lidia M ✓ 4
107 Pienkowski Kryatyna ✓
203 EMPLOYMENT SCREENING SVC LLC background screening ✓@ 716-332-2274
204 LIAISON INTERNATIONAL computer software ✓ 716-636-7777
206 NORTH AMERICAN MFG CO combustion controls ✓ ..716-689-0671
300 M J PETERSON CORP real estate ✓ 716-688-1234
331 Bruno John A Sr & Carol A ✓ 5
PAYROLL acctng & bkpg genl serv ✓ 716-689-0611
VICTOR LIBERATOR TIME CLOCK time recorders ✓ 716-276-8081
350 AMHERST PUBLIC LIBRARY libraries-public 716-689-4922
AUDUBON PUBLIC LIBRARY libraries-public ✓@ 716-689-4922
370 AMHERST SENIOR CITIZENS FNDTN senior citizens serv ✓ 716-636-3065
AMHERST SENIOR OUTREACH SVC government offices ✓@ ..716-636-3070
AMHERST SENIOR TRNSPRTN SVC government offices ✓@ ..716-636-3075
AMHERST TOWN AMHERST SENIOR senior citizens serv org ✓ 716-636-3050
Lazarz Jennifer
MEALS ON WHEELS social serv & welfare org ✓ 716-636-3065

Continued Next Column

JAMAICA LN (BUFFALO)-FROM 113 ZOERB AVE NORTH Continued from prior column
JOHN JAMES AUDUBON PKWY Cont'd

400 TOWN OF AMHERST COURT city government- courts ✓ 716-689-4200

+ PARTRIDGE RUN INTERSECTS
+ PARTRIDGE RUN INTERSECTS

461 Broadley Donna ✓ 8 716-639-7296
CINQUINO MICHELE dietitians ✓ 716-810-1843
Gormady P ✓ 716-688-8781
MORITZ MICHAEL nurses & nurses' registries ✓ 716-810-1823
Reed John ✓ 8 716-636-0022
Rupert William R ✓ 8 716-688-4205
TOTAL AGING IN PLACE PROGRAM government ✓@ 716-250-3100
YATES CHARLES W MD physicians & surgeons ✓
465 AMHERST GLEN SENIOR APT INC apartments ✓
Anderson Barbara ✓ 716-689-0819
CLOVER CONSTRUCTION genl contractors ✓ 716-636-0494
Keaveny Lorna ✓ 716-639-5960
Mourmoulidis Stamatia ✓ 716-688-3514
Sutliff Mari ✓ 2 716-688-0424
Wright Hattie ✓ 2 716-636-1826
109 Hunt Ann M ✓ 6 716-688-6494
113 Hobson Clara E ✓ 10 ..716-689-0253
114 Lapp Evelyn 6
115 Schmitt Faye S ✓ 8 716-636-0289
116 Sanborn Carol J ✓ 8 ..716-688-5852
116 Sanborn Helen C 716-688-5852
117 No Current Listing
118 Ferrugia Carolyn L 8
119 Bisaonette Carol C ✓ 2 716-688-5762
120 Falcone Santa ✓ 14 ..716-688-5626
120 Falcone Chris 716-688-5626
121 Sampson Nancy T ✓@ 8
122 No Current Listing
123 Johnson J ✓ 8 716-688-5440
124 Heuser Janice L ✓ 8
125 Ogribene Joseph G ✓ 716-276-3950
126 Kulinski Sandra L ✓@ 10 716-580-3980
126 Pieri Genevieve L ✓@ 10
127 Mohammad Wahid ✓ 8
127 Mohammad Pong W
128 Hartwick Mary A ✓ 14 ..716-688-9584
129 Aldridge Edythe ✓ 7 ..716-688-3511
129 Aldridge Christopher 716-688-3511
130 No Current Listing
131 Smith Norma A ✓ 8 716-568-2035
132 - 133 No Current Listing (2 Apts)
134 Jurewicz Jacquelin P ✓ 15 716-688-3006
135 Boron Bonnie L 10
203 Blenman Virginia L ✓@ 8
205 Bauer Geraldine E ✓ 2 716-636-0740
205 Bauer Otha 716-636-0740
209 Gromada Shirley A ✓ 10
213 Insinna Annette M ✓ 10 716-688-5618
214 Gechell Diana J ✓@
215 Sheldon Maryann A ✓ 16
216 No Current Listing
217 O'Neill Patrick J ✓ ..716-688-3016
218 - 219 No Current Listing (2 Apts)
220 Stout Leonard D ✓ 7 ..716-688-3089
222 Noto Margie ✓@ 7 716-691-5267
224 No Current Listing
225 Burgio Roseann M ✓ 8
226 Retter Emily A ✓@
227 Nowak Diane ✓@ 18
228 - 230 No Current Listing (3 Apts)
231 Babbitt Cheryl A ✓ 8
232 No Current Listing
233 McNair Mary C ✓ 8
234 Richey Ronald L 14
467 Kosa Irene ✓ 716-688-5302
Kosa Sabina 716-688-5302
Perez Maria ✓ 716-688-3032
Scott Diane ✓ 716-631-1070
108 Nola Patricia E ✓
109 Nola Louis ✓
110 Grossman Marcia E ✓ 2
112 Lewis Richard ✓
116 Vanghel Dory E
120 Contrino Joan ✓ 716-688-2602
121 Sciandra Peter C ✓
122 Cristiano Phyllis A ✓ 716-636-1505
123 Vishnevetskaya Genya ✓ 716-689-0798
126 Salomon Leslie S ✓@
204 Eisenberg Judith ✓ ..716-276-9164
207 Scott James ✓@ ..716-632-0678
208 Lewis Patricia J ✓
210 Branka Esther S ✓
211 Moore Peter D ✓
212 Bordonaro Samuel M ✓@ 8

Continued Next Column

Grow Your Business with **E-MAIL Marketing**

JAMAICA LN AVE NORTH JOHN JAMES

216 C
220 Rega
227 W
309 F
310 W
314 W
316 Helse
320 Lo
322 M
323 Ja
324 Giglia
326 Powe
471 Alvare
Ann Mary
Bodne
Cali Josep
Goodier C
Griffith
Guido
Gullo J
Leuth Flor
O'Brien As
Pagila S ✓
Potter Gay
101 - 102
103 O
104 No Cu
105 Utz D
106 - 108
109 Pa
110 Go
110 Goodi
111 - 114
115 Stank
116 - 118
119 W
120 Ballan
121 - 122
123 Klend
124 - 125
126 Ru
126 Rutko
127 Horva
128 Kreeg
129 - 130
201 Brow
202 No Cu
203 Co
204 Holli
205 - 207
208 Allen
209 - 210
211 Lewa
212 Maste
213 - 214
215 Diben
216 No Cu
217 Velas
218 Mastr
219 - 223
224 Kube
225 No Cu
226 Fisch
226 Stank
226 Stank
227 - 228
229 Grau
230 No Cu
301 Irelan
302 - 307
308 Heye
309 No Cu
310 Thust
311 Sc
312 - 316
317 Zobri
318 No Cu
319 Ingra
320 No Cu
321 Saky
322 Scott
323 - 326
327 McCa
328 Lacy
329 - 403
404 H
405 No Cu
406 Minic
407 - 408
409 Nicke
410 - 414
415 Aleks
416 - 417
418 Mazu
419 - 424
425 Kuzn
426 - 427

Target Street	Cross Street	Source
-	✓	Polk's City Directory

JOHN J AUDUBON PKWY 2019

196

ERB nn

)-4200
)-7296
)-1643
)-8781
)-1823
)-0022
)-4205
)-3100
)-0819
)-0494
)-5960
)-3514
)-0424
)-1826
)-6494
)-0253
)-0289
)-5852
)-5852
)-5762
)-5626
)-5626
)-5440
)-3950
)-3980
)-9584
)-3511
)-3511
)-2035
)-3006
)-0740
)-0740
)-5618
)-3016
)-3089
)-5267
)-5302
)-5302
)-3032
)-1070
)-2602
)-1505
)-0798
)-9164
)-0678

JAMAICA LN (BUFFALO)-FROM 113 ZOERB AVE NORTH Continued from prior column
JOHN JAMES AUDUBON PKWY Cont'd

716-689-0609
216 Cassaro Maryann E ✓
716-685-6835
220 Regan Maureen & Gerald D ✓ ⊕ [1]
716-688-8137
227 Wilson Roberta J ✓
309 Fose Carole L ✓ 716-636-1815
310 Walz Geraldine M ✓ 716-688-4305
314 Wilka Jeffrey J ✓ ⊕
316 Helsel Beth A ✓ [4] 716-688-6934
320 Lorentz Carol
322 Murtha Elizabeth L ✓ 716-639-7961
323 Jalili Ghodsive ✓
324 Giglia Robert C ✓ [2]
326 Powell Robert L ⊕ [10]
471 Alvarez Maria ✓
Ann Mary [8]
Bodnar Leonora ✓ 716-688-6069
Cali Joseph ✓ [2] 716-688-2702
Goodier Charles ✓ [2] 716-688-5929
Griffiths Sharon ✓ 716-688-5461
Guido Rose ✓
Guillo Joseph ✓ 716-633-4289
Leuth Florence ✓ [4] 716-689-0478
O'Brien Anthony ✓ [3] 716-636-0767
Pagila S ✓ [4] 716-689-0310
Potter Gay-Yvonne ✓ [4] 716-639-7611
101 - 102 No Current Listing (2 Apts)
103 Owens Wallace ✓
104 No Current Listing
105 Utz Deborah [3]
106 - 108 No Current Listing (3 Apts)
109 Papia Geraldine C ✓
110 Goodwin Peter L ✓ ⊕
110 Goodwin Pegie
111 - 114 No Current Listing (4 Apts)
115 Stankowski Judith A ✓ [10]
716-636-7419
116 - 118 No Current Listing (3 Apts)
119 Weiss Maria C ✓
120 Ballaro Janet ✓ [8] 716-688-6475
121 - 122 No Current Listing (2 Apts)
123 Klendathoj John [4]
124 - 125 No Current Listing (2 Apts)
126 Rutkowski Robert J ✓
126 Rutkowski Paul
127 Horvath Michael ✓ [8] ..716-688-8259
128 Kreeger Brian M ✓ [8]
129 - 130 No Current Listing (2 Apts)
201 Brown Bethel M [10]
202 No Current Listing
203 Constantino Rose
204 Holliday Dorothy ✓ [4]
206 - 207 No Current Listing (3 Apts)
208 Allen Carol M ✓ [2] 716-691-5816
209 - 210 No Current Listing (2 Apts)
211 Lewandowski Barthur ✓ [3]
716-688-0178
212 Masters Jean W ✓ [8] ..716-688-1643
213 - 214 No Current Listing (2 Apts)
215 Dibenedetto Alice M ✓ [10]
716-639-7459
216 No Current Listing
217 Velasquez Oscar ✓ [3] ..716-689-0607
218 Mastrantonio E ✓ [6] 716-689-2011
219 - 223 No Current Listing (5 Apts)
224 Kubera Irene A ✓ [6] 716-688-0749
225 No Current Listing
226 Fischer Ora E ✓ [15]
226 Stanton Elizabeth R ✓ [2]
716-688-5793
226 Stanton Lillian 716-688-5793
227 - 228 No Current Listing (2 Apts)
229 Grau Susan M ✓ [2] 716-689-5881
230 No Current Listing
301 Ireland Ann M ✓ ⊕ [10] ..716-688-4113
302 - 307 No Current Listing (6 Apts)
308 Heyer Robert M ✓ [7]
309 No Current Listing
310 Thuston Dorothy E ✓ [18]
311 Scott William D ✓ ..716-688-5071
312 - 316 No Current Listing (5 Apts)
317 Zobrist Annette [2]
318 No Current Listing
319 Ingram Theresa ✓ [10] ..716-689-2353
320 No Current Listing
321 Saky June ✓ [8]
322 Scott Vivian M [21]
323 - 326 No Current Listing (4 Apts)
327 McCarthy Sharon M ✓ [18]
716-636-4909
328 Lacy Louis S Sr ✓ [7] ..716-639-0526
329 - 403 No Current Listing (5 Apts)
404 Hooker Daniel
405 No Current Listing
406 Minich Carl E [14]
407 - 408 No Current Listing (2 Apts)
409 Nickerson Susan J ✓ [2]
716-688-5427
410 - 414 No Current Listing (5 Apts)
415 Aleksandrowicz Jacquelyn A [2]
416 - 417 No Current Listing (2 Apts)
418 Mazurowski Frank R ✓ [4]
419 - 424 No Current Listing (6 Apts)
425 Kuzara Judith B ✓ [21] ..716-688-7017
426 - 427 No Current Listing (2 Apts)
428 Fron Donald A [9]
429 Hohbach Irmgard T ✓ [8]
716-688-3553
430 No Current Listing
• PARTRIDGE RUN INTERSECTS
• PARTRIDGE RUN INTERSECTS
475 Bogdan Carol ✓ 716-688-1873
Buczynski Virginia M ✓ [7] ..716-639-8216
Butticci Patricia ✓ ⊕ 716-689-0127
Hartrich Gary ✓ [2] 716-688-5749
Levatte Annette ✓ [3] 716-688-2059
Tomb Preston ✓ 716-688-5927
115 No Current Listing

JOHN JAMES AUDUBON PKWY Cont'd

116 Tomb Janet M
117 Eisenberg Leonard M ✓ [2]
118 No Current Listing
119 Steszewski Rosemary
120 Lynch Patricia A ✓ ⊕ [6]
716-691-5306
121 No Current Listing
122 Capera Mary O ✓ [10]
122 Depeters Dennis A ✓ ⊕ [14]
123 No Current Listing
127 Boland Susan ✓ ⊕
128 - 129 No Current Listing (2 Apts)
130 Macauley Mary T ✓ [6]
130 Rychnowski Elizabeth A ✓
131 - 140 No Current Listing (2 Apts)
141 Callahan Patricia ✓ 716-689-0540
142 - 143 No Current Listing (2 Apts)
144 Gonzalez Lucila ✓ [6] ..716-688-5159
145 No Current Listing
146 Solazzo Patricia G ✓ [11]
716-689-0475
147 No Current Listing
148 Brown Donna ✓ [20]
148 Fagen Lorraine A ✓ [2]
148 Mundy Elinore M ✓ ⊕ [8]
148 Mundy Eli
149 Szymanski Frances F ✓
716-688-5826
215 Garr Selena J ✓
216 - 217 No Current Listing (2 Apts)
218 Conard Anne K ✓ ⊕ 716-688-0509
219 Loporto Nancy L ✓ [11] ..716-688-6590
220 Pratcher Evelyn T
221 Ruske Shirley A ✓ [6] ..716-688-8647
222 No Current Listing
223 Frey Nancy L ✓
227 Iacuzzo Joseph S Jr ✓ [8]
716-688-1787
228 McCarthy Linda M ✓ [8]
229 Turnwall Jose L ✓ [24] ..716-639-8684
230 Burns Bonnie L [16]
231 O'Shei Mary S ✓ [11] ..716-639-7790
237 No Current Listing
239 Elliott Bonnie J ✓ [14] ..716-689-0657
240 Majchrzycki Gloria ✓ [12]
716-636-1030
241 Obrian Martha ✓ [4]
242 Blatner Richard N ✓ [10]
243 No Current Listing
244 Hansen Jerome H ✓ [8]
716-639-0614
245 - 246 No Current Listing (2 Apts)
247 Krzewicki Danuta ✓ [10]
247 Milazzo Joan Y ✓ [10]
248 No Current Listing
249 Yaw Joan M ✓ [8]
500 AMHERST ANIMAL CONTROL government offices 716-689-1311
AMHERST FIRE DEPT fire departments ✓
716-689-1212
AMHERST POLICE DEPT police departments ✓ 716-689-1322
AMHRST TWN PL DEPT police departments 716-689-1355
Foran Sandra F [7]
501 LUMINATOR CO nonclassified establishments ✓ 972-424-6511
Nesper Jas ⊕
103 TXMQ federal government contractors ✓ 716-998-4665
200 ROBISON & WOESE INC fire protection consultants ✓ ⊕
716-636-1800
201 I EVOLVE info technology serv ✓
716-568-2810
202 GANTRESS THOMAS E CPA accountants ✓ 716-626-0005
400 BLINKOFF & BLINKOFF attorneys ⊕
716-332-6104
400 PLAZA GROUP real estate ✓ ⊕
716-332-6100
400 PLAZA SUITES hotels & motels
716-332-6122
400 PRIORE RADEMAKER accountants ✓
716-332-6162
• BRYANT WOODS N BEGINS
• BRYANT WOODS N BEGINS
• DODGE RD BEGINS
• RAILROAD CROSSES
• DODGE RD ENDS
BUSINESSES 74 HOUSEHOLDS 292

JOHN MUIR DR (BUFFALO)
• SYLVAN PKWY ENDS
• ZIP CODE 14228 CAR-RT C054
61 LOCAL EDGE yellow pages- publishers
716-875-9100
90 MBMS INC computer software ✓
716-636-0914
90 A Jamieson John [6]
90 A/2 MORTGAGE BANKING MGMT SYSTS computers ✓ ⊕ 716-689-2000
90 B/2 104 GEI CONSULTANTS INC engineers- consulting ✓ ..716-204-7154
95 BROWNELL DEBORAH phys therapists ✓
716-631-9515
FRANCIS TURQUESSA phys therapists ✓
716-800-2328
KHADILKAR SUMEDHA M phys therapists ✓
LUCIA KRISTEN PT phys therapists ✓
716-250-4135
MELEEN MICHAELA phys therapists ✓
716-292-6560
SCARBOROUGH SARAH E phys therapists ✓ 716-250-4137
SNYDER LIANA phys therapists ✓
603-998-3677
100 ADAMS SERENA L DPT phys therapists
716-250-4133
100 CALKINS MITCHELL N phys therapists ✓

JOHN

JOLIE DELLV • ZIP C
BUSIN
JORA ELLTC • ZIP C
BUSIN
JONES RANSC • ZIP C

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAPLE RD 2019

241

MAPLE RD Cont'd

333 Sindoni Lois E ✓ ..716-633-9182
334 Bergwall Arlene R ✓ 5
716-458-0730
335 No Current Listing
336 Fell Shirley M ✓ 5A
337 - 339 No Current Listing (3 Apts)
340 Telesco Dominic S & Sarah ✓ 9
716-428-3720
341 - 350 No Current Listing (10 Apts)
351 Greenwald Carol ✓
352 Hill Edward Jr ✓ 8 716-810-9312
352 Hill Anna G 716-810-9312
353 Clark Alice ✓
354 No Current Listing
355 Hamilton Margot P 8
356 Jofre Daniel ✓ 8
356 Sheffer James D & Jeanne T ✓ 8
716-810-9969
357 Mallcan Patricia J & Edward C ✓ 8
716-204-8159
358 Herman Donna M ✓ 10
716-932-7571
359 No Current Listing
360 Huber John ✓ 716-932-7056
361 No Current Listing
362 Rundell Irmgard ✓ 7
363 Shults Janet M ✓ @ 8
716-276-8152
364 Weinstein Sara ✓ 8 ..716-580-7787
365 No Current Listing
366 Haven Alvin ✓
367 Moffett Warren C ✓ 8
367 Moffett Becky
368 No Current Listing
369 Martorana Theresa A ✓
369 Martorana Samuel
370 Day Ja ✓ 716-634-6340
370 Day Carolyn W 716-634-6340
371 - 372 No Current Listing (2 Apts)
373 Zima Aino V 10
374 No Current Listing
375 Buscaglia Fred A ✓ 2
375 Malone Helen A ✓ 716-689-2531
376 - 378 No Current Listing (3 Apts)
379 Keuter Juan R & Vincenette M ✓ 3
380 No Current Listing
381 Palmieri Joseph A & Maria S ✓
382 - 383 No Current Listing (2 Apts)
384 Palme Martha J ✓ 10
716-688-8099
385 No Current Listing
386 Michalowski Edward W ✓ 1
386 Stahl Audrey A ✓ @
387 Herman Bernard B & Jean J
387 Peterson Eric ✓ 10
388 Saunders Kimberly M 4
388 Saunders Kelly A
389 Gerstenmier Roberta ✓
716-580-9409
390 - 391 No Current Listing (2 Apts)
392 Rakowski Daniel & Christine T ✓ 4
392 Schaktman Dorothy ✓
393 No Current Listing
394 Sozanski Anne ✓ 2
395 Steck Audrey C
396 No Current Listing
397 Olszewski Melanie T ✓ @ 14
716-636-0621
397 Whitcomb Marilyn
398 No Current Listing
399 Mecca Giovanna M ✓ 8
399 Mecca Anna
2361 CITIZENS BANK banks ✓ ..716-634-4970
TOPS FRIENDLY MARKET PHARMACY pharmacies ✓ 716-515-3205
2379 LENGTHS beauty salons ..716-626-1181
2383 MARSHALLS department stores
716-810-0980

• TRANSIT RD INTERSECTS
• ZIP CODE 14226 CAR-RT C030

3900 PREMIER WINE & SPIRIT marketing programs & serv ✓ 716-873-6688
PRIME WINES CORP liquors-retail ✓
716-873-6686
WINE DEALS wines-retail ✓
716-873-6688
3904 PREMIER CAFE coffee & tea ✓
716-877-3574
3908 DRAGON SNACK GAMES games & game supl ✓ 716-833-0740
3910 RED PEPPER CHINESE-VIETNAMESE restaurants ✓ @ 716-831-3878
3920 DENNY'S restaurants ✓ ..716-446-1671
3931 FIRESTONE COMPLETE AUTO CARE auto rpr & serv ✓ 716-261-3929
PAC SUN clothing-retail ✓ 716-837-4641

• ALBERTA DR INTERSECTS

3951 OLIVE GARDEN ITALIAN KITCHEN restaurants ✓ 716-837-5211
3980 GOODWILL thrift shops
Hanusin Grace
Hope Deborah J 4
KEY BANK banks ✓ 716-834-4065
TIM HORTONS doughnuts ✓
716-446-9730
TOPS FRIENDLY MARKET PHARMACY pharmacies ✓ 716-515-0080
WESTERN UNION money transfer serv @
716-515-0076
3999 SCOTCH N' SIRLOIN RESTAURANT restaurants ✓ @ 716-837-4900
4001 JENSS DECOR department stores ✓ @
716-837-1100
REEDS JEWELERS jewelers-retail ✓
716-837-3934
4003 IHOP RESTAURANT restaurants ✓ @
716-446-1117
4010 RED LOBSTER restaurants ✓
716-837-0202

Continued Next Column

• HARLEM RD BEGINS Continued from prior column

MAPLE RD Cont'd

4033 IMPAACT GROUP MEETING nonclassified establishments ✓
716-834-0900
200 FRONTIER SCIENCE & TECHNOLOGY foundation ✓ @
4043 NEXT FINANCIAL financial advisory serv ✓ 716-768-1463
100 H J HILL TAX & ACCOUNTING SVC tax return preparation/filing ✓ @
716-832-7853
102 COLOR COMMUNICATIONS INC printers ✓ 716-838-0698
104 MJI CONSULTING business mgmt consultants ✓ 716-837-1033
104B ZEFTEL BRUCE attorneys ✓
716-381-9141
106 ADVANCED STORAGE TECHNOLOGY storage- liquid & bulk ✓
716-833-6212
108 KIRST COMMERCIAL REAL ESTATE real estate ✓ @ ..716-836-8200
203 MARSH PLASTICS INC plastics- raw mtrls/powder/resi ✓ @ 716-834-6500
207 KEY MARK AGT real estate ✓ @
716-603-8649
207 REALTY EDGE real estate ✓
716-864-0777
209 Di Giacomo Tom 4
210B OBANNON & DAVIS INC insurance ✓ @ 716-856-7555
211 E M SYSTEMS INC computer software ✓ @ 716-836-4910
211 TELECARECONNEX nonclassified establishments ✓ @ 716-836-4910
4050 WENDY'S restaurants ✓ ..716-832-0855
4053 BENCHMARK MERCHANT SOLUTIONS financial advisory serv ✓ ..716-506-9250
111 CHILDREN'S GROWTH FOUNDATION org ✓ 716-878-7769
114 Hora Michael Jr 7
122 Hill Charles R & Susan L 2
122 VALPAK advertising- direct mail ✓
716-633-0625
200 BENCHMARK 325 DE ASSOC LP real estate developers 716-833-4986
200 BENCHMARK FINANCIAL GROUP INC real estate developers ✓ @
716-833-4986
200 BENCHMARK MANAGEMENT CORP real estate ✓ 716-833-4986
200 Gellman Gerge I & Susan R 25 • (1971)
200A BENCHMARK GROUP bowling centers ✓ @
4060 KYOTO JAPANESE RESTAURANT restaurants ✓ 716-836-6688
4080 RED ROBIN GOURMET BURGERS restaurants ✓ 716-834-4100
4090 BOUNCE MAGIC kids entertainment ✓
716-646-5867
PLANET FITNESS health clubs studios/ gymnasium ✓ 716-253-7676
4110 ORECK CLEAN HOME CTR vacuum cleaners- household-dlrs ✓
716-833-3444
100 SOLA SALON STUDIOS beauty salons ✓ 716-506-7652
4120 BRICK HOUSE TAVERN + TAP restaurants ✓ 716-834-1490
4150 Commisso Angela ✓ 8
Davis Keri
SWEET HOME MIDDLE SCHOOL schools ✓ @ 716-250-1450
4185 BOSTON MARKET restaurants ✓
716-834-2320
4220 ACCEPTANCE NOW furniture- renting & lease ✓ 716-831-8164
VALUE CITY FURNITURE furniture-dlrs-retail ✓ 716-833-5794
4224 108 SUBWAY restaurants ✓
716-832-4905
112 LENSCRAFTERS optical goods- retail
716-833-1046
116 LEON STUDIO ONE SALON beauty salons ✓ 716-862-0068
124 TEA LEAF CAFE food products ✓
716-831-8202
4225 JOSEPH L MADDI MD PC physicians & surgeons ✓ 716-834-0221
RUTOWSKI JEROME M NP nurses-practitioners ✓
4227 MC CANN FIRM LLC nonclassified establishments ✓ 716-395-2122
Pearson Penny 4
4229 ACUPUNCTURE CHINESE MEDICINE acupuncture ✓ 716-803-8899
4231 AMHERST SURGICAL ASSOC physicians & surgeons ✓ 716-837-9111
Buckley Richard J Jr 14
Buckley Judy
ZIELINSKI CHRISTOPHER PA physicians assistants ✓ ..716-837-9111
4233 Kotob Radwan ✓
UNIVERSITY UROLOGY physicians & surgeons ✓ 716-898-5008
4239 Gentile Joseph D 23 • (1971)
JOSEPH GENTILE MD physicians & surgeons ✓ 716-832-9747
1 LESTER S SIELSKI MD physicians & surgeons ✓ 716-835-2984
4241 AMERIPRISE FINANCIAL financial advisory serv ✓ 716-831-8944
JAMES J PACER-AMERIPRISE FNCL financial advisory serv 716-831-8944
Manchigiah Kamala 7
SCOTT MIRANTO-AMERIPRISE FNCL financial advisory serv ✓ ..716-831-8944

Continued Next Column

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAPLE RD 2019

prior

+ HARLEM RD BEGINS Continued from prior column

MAPLE RD Cont'd

STEPHEN RAGLOW-DEFRANCO investments 716-831-8944

8 PAUL J MIOSI-AMERIPRISE FNCL financial advisory serv ✓

4243 Lamastra Michael S ✓ 23 • (1971) 716-833-4637

MAPLE DENTAL dentists ✓ 716-833-4637

4245 Malik Fauzia F ✓ 17 • (1971)

Malik Farah F

4247 CUKIERMAN & HAQUE MDS physicians & surgeons 716-835-9871

HAQUE & CUKIERMAN MED GROUP physicians & surgeons ✓ 716-835-9871

4249 DALY RICHARD F attorneys ✓ 716-835-2200

4258 Rhorres Adam 8

TACO BELL restaurants ✓ 716-833-8332

4265 TIM HORTONS doughnuts ✓ 716-833-1500

4276 CONOVER CHIROPRACTIC chiropractors dc ✓

(N) Conover Keith

3 AQUINO MICHAEL V DC chiropractors dc ✓ 716-831-0011

3 MARTINEZ DENA VALINE phys therapists ✓ 716-831-0011

C AMC MAPLE RIDGE 8 theatres-movie ✓ 716-833-9545

4291 CROSBY'S STORES convenience stores 716-836-0156

U-HAUL NEIGHBORHOOD DEALER truck renting & lease ✓ ..716-839-1745

• ZIP CODE 14226 CAR-RT C047

4350 (N) Barthel Katharina

FRIENDLY'S restaurants ✓ 716-835-2862

4400 MOTEL 6 hotels & motels ✓ 716-834-2231

+ FLINT RD INTERSECTS

4621 ZETTI'S PIZZA & PASTA pizza ✓ 716-691-8535

BUSINESSES 261 HOUSEHOLDS 825

MAPLE ST (CLARENCE CENTER)-FROM 6001 EASTWOOD RD

MAPLEL

67 Dima

72 Fitzp

73 Roth

78 Vacar

79 Lenk

84 Greel

85 Hissir

90 Murpt

91 Nelsc

96 (N) Ku

97 Occh

102 Beic

Gibb

Mas

103 Den

108 (N) M

109 Tich

114 Tivje

115 Bag

120 Cru

126 Ver

127 Wei

Wei

132 Hoe

Mat

133 Doe

138 Wei

Wei

139 Altn

Rob

Target Street	Cross Street	Source
-	✓	Polk's City Directory

SWEETHOME RD 2019

363

SWANS

SWEET HOME RD Cont'd

828 No Current Listing
830 Hoffman Beverly J ✓ ⓮ ♦ (1968) 716-875-5919
Hoffman Ronald N 716-875-5919
836 March Eureka Y ✓ ⓭ ♦ (1941)
March Taylor A
840 No Current Listing
848 Kazmierczak Nicholas A Ⓔ ♦ (1956)
852 Hash Phillip & Ashley L ✓ ⓮ ♦ (1955)
Princess Edwin E ✓ ⓑⓓ ♦ (1927)
Princess Edwin W
860 No Current Listing
864 Pietrzyk Brian K ✓ ⊛ ⓫ ♦ (1960)
868 No Current Listing
872 Rowley Katrina C ⓯ ♦ (1942)
876 Smith Matthew J ④ ♦ (1936)
884 Neuman Mathew J ✓ ⓯ ♦ (1978) 716-834-4916
Nye Ashley D ✓ Ⓔ ♦ (1955)
885 LITTLE LEARNERS schools ✓ ⊛ 716-832-6340
Smith Michael C ✓ Ⓔ ♦ (1959)
ST LEO PARISH clergy ✓ .. 716-835-8905
ST LEO THE GREAT RC CHURCH churches ✓ ⊛ 716-835-8905
892 Bonati Roy F Jr & Maria A ✓ ⊛ ⓫ ♦ (1978)
903 Ⓓ Kraus Carolyn
922 Dombek Sharon D ✓ ⊛ ⓯ ♦ (1937) 716-931-9621
926 Silvaroli Nicole M ⓭ ♦ (1935)
938 Kerkeslager Jason L ✓ ㉔ ♦ (1937) 716-837-9305
Kerkeslager Mandy R 716-837-9305
945 A S C OF W NY surgical centers ✓ ⊛ AMBULATRY SURGERY CTR MNG-WSTR physicians & surgeons ✓
946 Burkard Keith M ✓ ⊛ ㉞ ♦ (1935) 716-838-1130
Burkard Kathleen A 716-838-1130
948 Abbamo Joseph P ✓ ㉟ ♦ (1961) 716-835-3878
956 No Current Listing
965 Brummer John J Sr & Judith A ✓ ㊳ ♦ (1959) 716-834-3185
966 NORTH BAILEY FIRE CO INC fire departments ✓ ⊛ 716-836-9571
1005 No Current Listing
1011 Aye Than ✓ Ⓔ ♦ (1959) 716-833-3723
Oo Khin M Ⓔ ♦ (1959)
1012 Furman Jason G ㊳ ♦ (1968)
1015 No Current Listing

• MAPLE RD INTERSECTS

1185 AMHERST HEALTH CTR PHARMACY physicians & surgeons ✓ 716-689-3401
LIFETIME HEALTH MEDICAL GROUP physicians & surgeons ✓ 716-689-0040

• ZIP CODE 14228 CAR-RT C060

1260 JOHN SHAFLUCAS ARCHITECTS architects ✓ 716-636-5000
1280 BREAK N EGGS CREPERIE LLC restaurants ✓ 716-688-6068
Ⓓ Marchant Cody ✓ 716-688-6273
Ⓓ McClam Chanel ✓ 716-688-5805
Ⓓ Perun Oleg ✓ 716-688-5984
Ⓓ Smajlaj Joseph ✓ 716-636-0259
105 IN & OUT PASTA restaurants ✓ 716-688-9500
201 Rydzik Tina ✓ ⓑ 716-689-5942
203 Kleinschmidt Aaron ✓ ⊛ Ⓔ
203 Lanzot Alberto ✓ ④ .. 716-688-5170
204 - 206 No Current Listing (2 Apts)
301 Bui Camly ✓ ⓐ
301 Ⓓ Komar Gail ✓
303 Ⓓ Kreuzer Kiel D ✓
305 Ⓓ Mandarino Gianna ✓
306 Best Talethea M ✓ ⓑ 716-688-3925
401 No Current Listing
402 Oloyede Samuel ✓ ⊛ Ⓔ 716-688-9646
402 Oloyede Sarah 716-688-9646
403 Meisel Samuel N Ⓔ
404 Tomczak Richard C ✓ ⊛ Ⓔ
405 - 406 No Current Listing (2 Apts)
1290 Ⓓ Brand Samantha ✓
STAYBRIDGE SUITES hotels & motels ✓ ⊛ 716-276-8750
Tania Paul W & Rachel J ✓ Ⓔ
1300 BONADIO CO LIP accountants ✓ 716-688-0526
Ford Tamica ✓ Ⓔ 716-636-0515
Ⓓ Karlson G ✓ 716-688-2914
Ⓓ Polimeni John ✓ 716-688-3877
101 Bilek Denise R Ⓔ
102 YOTALITY yogurt 716-689-3242
104 JIMMY JOHN'S restaurants ✓ 716-688-3278
106 BUFFALO TRIM beauty salons ✓ 716-639-7527
107 MIGHTY TACO restaurants ✓ ⊛ 716-689-5785
201 - 204 No Current Listing (4 Apts)
206 Adinolfisaggone Angela M ✓ Ⓔ
207 Samuel Natasha ✓ Ⓔ
208 Tarasevich Oksana & Anatoli ✓ Ⓔ 716-688-1467
301 Ⓓ Pressman Elizabeth B ✓
302 - 303 No Current Listing (2 Apts)
304 Uslinov Lauren N ✓ ⊛ Ⓔ
304 Uslinov Stephen
306 Ⓓ Blenias James J ✓ 716-688-8069
307 - 401 No Current Listing (3 Apts)
402 Hodgson Bryan A ✓ Ⓔ 716-689-2403
403 - 408 No Current Listing (6 Apts)
1306 NEPHROLOGY ASSOCIATES physicians & surgeons ✓ 716-838-3188
PENNINGTON JANICE M NP nurses-practitioners ✓ 716-838-3188
Wheat Heather M Ⓔ

Continued Next Column

• RUNNING BROOK DR ENDS *Continued from prior column*

SWEET HOME RD Cont'd

• RENSCH RD ENDS

• RENSCH ENTRANCE INTERSECTS

1400 HNAT FAMILY CHIROPRACTIC chiropractors dc ✓ 716-689-5919

• RENSCH RD ENDS

ROYAL ALLIANCE ASSOC INC financial planning consultants ✓ .. 716-929-6550
1 Bahgat Rosemary Ⓔ
1 LEGACY QUEST ADVISORS financial advisory serv ✓ 716-200-4900
3 HNAT GREGORY J DC chiropractors dc ✓
4 COMPLETE PAYROLL PROCESSING payroll preparation serv ✓ 716-689-2574
5 HOFFMAN MARTIN MD physicians & surgeons 716-932-6064
7 ALIOTTA JOSEPH insurance annuities ⊛ 716-568-2920
7 LEVEL FINANCIAL ADVISORS financial advisory serv ✓ ⊛ 716-634-6113
8 ALDRICH MARK D CPA accountants ✓ 716-932-7674
9 FERON POLEON LLP attorneys ✓ 716-639-1111
10 ADVANCED HAIR SOLUTIONS beauty salons ✓ ⊛ 716-839-4100
33 24 HOUR EMERGENCY SEMI TRUCK truck-rpr & serv .. 518-380-6605
1404 1 ALLTOWN DENTAL dentists ✓ 716-636-1762
2 RICOTTA & ASSOC psychologists ✓ ⊛ 716-634-0566
5 UNIVERSITY PEDIATRIC ASSOC physicians & surgeons ✓ 716-639-9360
8 ORCHESTRAL FINANCIAL GROUP INC financial advisory serv ✓ ⊛ 716-691-4289
10 DIDONATO KNOX & ASSOC accountants ✓ 716-204-4888
11 STEAM KING CARPET CARE carpet & rug cleaners ✓ 716-349-9489
12 UNIVERSITY WEALTH MANAGEMENT financial planning consultants ⊛ 716-213-0080
1408 AMERICAN EDUCATION FOUNDATION foundation ✓ 716-348-3496
3 POSITIVE HEALTH & WELLNESS PC chiropractors dc ✓ 716-689-3629
6 Yeh Steven Ⓔ
8 ENERGY COOPERATIVE OF AMERICA electric companies ✓ 716-580-3506
8 INDUSTRIAL ENERGY BUYERS LLC energy mgmt sys & products ✓ 716-688-2700
8 Ⓓ Lawrence Jamie
9 UB FAMILY MEDICINE & SPECIAL physicians & surgeons ✓ 716-247-5281
1412 1 SARAH SMITH counseling serv 716-689-0593
1 SMITH SARAH A social workers ✓ 716-430-2524
1 Weinstein Bruce Ⓖ
6 BUFFALO PAIN & HEALING pain control 716-688-5088
6 Hsu Bernard Ⓔ
1416 SOUND ANSWERS HEARING & SPEECH speech pathologists ✓ 716-688-3516
3 BROWN NICOLE N social workers ✓ 917-674-6742
3 CH3 BIOSYSTEMS LLC physicists 716-688-5222
3 EXPLORE WHAT'S NEXT physicists ✓ ⊛ 716-308-6683
5 Maraccini Marc ✓ Ⓔ
5 PREMIER CONSULTING ASSOC LLC business mgmt consultants ✓ ⊛ 716-688-5600
9A BENEFIT BROKERS merchandise brokers ✓ 716-524-6740
9A WOJNOWSKI ADAM A audiologists ✓ 716-688-3010
9B QUEEN CITY FUNDING INC financing ✓ 716-799-0846
10B ELLMANN MARK CPA accountants ✓ 716-626-1272
12 Ⓓ Barwell Jennifer ✓
12 SWEET HOME FAMILY MEDICINE PC physicians & surgeons ✓ 716-636-7800
1434 Ⓓ Jacob Barry O ✓
1436 Ⓓ Smart Hayden ✓ 716-688-4340

• RENSCH ENTRANCE INTERSECTS

1544 No Current Listing
1554 Ⓓ Heffle Norm
1576 ACCUTHERANOSTICS laboratories-medical ✓ 716-688-9600
Bloomberg Dale ✓ ⓯ ♦ (1972)
CAPITAL FORMATION INST INC associations ✓ 716-645-5500
EMVIS5 LLC nonclassified establishments ✓ 716-345-8624
Ⓓ Hacikyan Mike
ONY INC physicians & surgeons equip ✓ ⊛ 716-636-9096
TECHNICOR INC nonclassified establishments ✓ 716-564-8888
YOU FIRST SVC INC serv ✓ 716-204-7215

• CHESTNUT RIDGE RD INTERSECTS

1606 Weller Rex Ⓔ
1 Merasa Teuku Ⓔ
1 Tan Sianglau ✓ ⊛ ⓐⓒ
2 Harjanta Devi ✓ ⓑ
2 Ⓓ Turley Tricia ✓
3 - 4 No Current Listing (2 Apts)

Target Street	Cross Street	Source
-	✓	Polk's City Directory

JOHN J AUDUBON PKWY 2014



@ 716-625-8363

+ COMMERCE DR BEGINS

BUSINESSES 23 HOUSEHOLDS 2

JOHN JAMES AUDUBON PKWY (BUFFALO)

• ZIP CODE 14228 CAR-RT C061

1 AMMERMAN CRYSTAL M physicians assistants ✓@ 716-817-2929

BATTISTONI JARED V physicians assistants ✓ 716-817-2929

BLAZIER LINDA - nurses- practitioners ✓@ 716-817-2929

BRADLEY STEVEN P physicians assistants ✓@ 716-817-2929

BUFFALO EMERGENCY ASSOC physicians & surgeons ✓@ 716-626-9525

CARTER JOHN M MD physicians & surgeons ✓ 716-817-2929

CLARK COLEEN M nurses-practitioners ✓@ 716-817-2929

COMSTOCK MELANIE A nurses-practitioners ✓@ 716-817-2929

DOEMLAND HELEN B physicians assistants ✓@ 716-817-2929

DOERR RENATA M physicians assistants ✓@ 716-817-2929

EDMISTON TARA physicians assistants ✓@ 716-817-2929

EXIGENCE GROUP personnel consultants @ 716-204-4500

EXIGENCE LLC physicians & surgeons ✓@ 716-639-3789

FARMER AMY F physicians assistants ✓@ 716-817-2929

FARMER II DAVID E physicians assistants ✓@ 716-817-2929

GOLDHABER REASEARCH ASSOC nonclassified establishments ✓@ 716-689-3342

HILL BRIAN M physicians assistants ✓ @ 716-817-2929

JOHN CHRISTOPHER physicians assistants ✓@ 716-817-2929

KIRCHBERGER LIANE C physicians assistants ✓@ 716-817-2929

KRZYSTEK MARC A physicians assistants ✓@ 716-817-2929

LABI MARIA L MD physicians & surgeons ✓@ 716-817-2929

LAKOMY STEVEN A MD physicians & surgeons ✓@ 716-817-2929

LOUIS GUERLANDE physicians assistants ✓@ 716-817-2929

MACDIARMID JR PATRICK G physicians assistants ✓ 716-817-2929

MCFARLAND SIBLEA F physicians assistants ✓@ 716-817-2929

MCLANAHAN SUSAN G physicians assistants ✓@ 716-817-2929

NASH SARA A physicians assistants ✓ @ 716-817-2929

PATTON AMY M physicians assistants ✓@ 716-817-2929

PRUDENTIAL INSURANCE CO insurance ✓@ 716-636-1960

RANKIE JENNIFER physicians assistants ✓@ 716-817-2929

iness Credit Reports on-line and other Polk City

Target Street	Cross Street	Source
-	✓	Polk's City Directory

JOHN J AUDUBON PKWY 2014

www.citydirectory.com

JOE MCCARTHY DR - JOHN JAMES AUDUBON PKWY

JOHN JAMES AUDUBON PKWY
Cont'd

SHERIF JENIA MD physicians & surgeons ✓@ 716-817-2929
SNYDER DAVID M physicians assistants ✓@ 716-817-2929
WALIA MANDEEP K MD physicians & surgeons ✓@ 716-817-2929
WESTNER THOMAS G MD physicians & surgeons ✓@ 716-817-2929
ZIOMEK PAULETTE C physicians assistants ✓@ 716-817-2929
210 Daniel Gregory F [3]
+ N FOREST RD INTERSECTS
10 BESTRY SHERWOOD L attorneys @ 716-688-1600
COM DOC copying mach- serv & rpr ✓ @ 716-689-0202
MUIR LAKE CONSULTING CORP insurance ✓@ 716-689-1700
Papa Ronald J [18]
Papa Frank R
1 NATIONAL FIRE ADJUSTMENT CO insurance ✓@ ..716-689-7700
108 ATTORNEY AT LAW attorneys ✓ 716-636-9181
101 AMERICAN CANCER SOCIETY associations ✓@ 716-689-6961
Devantier Dorothy [2]
140 ACE INDUSTRIES INC cranes & derricks @ 716-689-5400
AUDUBON EXPORT INC exporters ✓@ 716-689-5400
CM CADY LIFTERS hoists @ 716-689-5400
CM CHAIN hoists ✓@ 716-689-5400
CM INSURANCE CO INC insurance ✓@ 716-689-5400
COLUMBUS MC KINNON CORP crane serv ✓@ 716-689-5400
Pratt Roland C ✓ [17]
WENDEL DUCHSCHERER ARCH & ENGR engineers- consulting ✓@ 716-688-0766
100 Necessary David R [6]
200 Duchscherer Wendel ✓ [9] 716-688-4913
151 NATIONAL TRAFFIC SVC INC marketing programs & serv ✓@ 716-636-8253
200 ACADEMIC SOFTWARE PLUS computer software ✓@ 716-636-7760
ACTUARIAL CONSULTING SVC INC pension & profit sharing plans ✓@ 716-691-2181
AEROTEK STAFFING AGENCY employment agencies/opportunit ✓ @ 716-932-1450
AMN HEALTHCARE medical serv-temporary ✓@ 716-639-7975
BROWN & BROWN OF NEW YORK INC insurance ✓@ ..716-995-5620
BUFFALO NIAGARA ASSN-REALTORS real estate ✓@ 716-636-9000
KIDENEY ARCHITECTS architects ✓ @ 716-636-9700
L F ENGINEERING engineers-consulting ✓@ 716-688-3060
MARVAL & ASSOC nonclassified establishments ✓@ ..716-923-7408
(N) Miller Karen
NC INDUSTRIES INC mfrs ✓@ 716-689-8400
NIAGARA CUTTER LLC cutting tools/ acces/measuring ✓@ 716-689-8400
NORTH AMERICAN MFG CO combustion controls ✓@ 716-689-0671
SCHWARTZ GROUP INC marketing programs & serv 716-635-9650
STEARNS & WHELER engineers-environmental ✓@ ..716-691-8503
SYSTEMS & ENGINEERING PC engineers- consulting ✓@ 716-633-9950
TRUEMAN-MALIN financial planning consultants ✓@ 716-204-3550
251 Dean Connie [11]
SYKES ENTERPRISES INC call centers ✓@ 716-636-2000
331 COMPUTER SEARCH PAYROLL SVC computer related serv ✓@ 716-692-1409
VICTOR LIBERATOR TIME SYSTEMS time recorders ✓@ 716-656-5700
350 AMHERST PUBLIC LIBRARY libraries-public @ 716-688-4919
AUDUBON LIBRARY libraries-public ✓@ 716-689-4922
370 AMHERST ADULT DAY SVC day care centers- adult ✓ 716-689-1403

JOHN JAMES AUDUBON PKWY
Cont'd

AMHERST CENTER-SENIOR SVC senior citizens serv org ✓@ 716-636-3050
AMHERST MEALS ON WHEELS social serv & welfare org ✓@ 716-636-3065
AMHERST SENIOR OUTREACH SVC government offices ✓@ 716-636-3070
AMHERST SENIOR TRNSPRTN SVC government offices ✓@ 716-636-3075
(N) Sommer Cathy ✓
400 TOWN OF AMHERST COURT city government- courts ✓@ 716-689-4200
411 JEWISH HERITAGE DAY SCHOOL religious schools ✓@ 716-568-0226
+ PARTRIDGE RUN INTERSECTS
+ PARTRIDGE RUN INTERSECTS
461 Astridge Anna ✓ [3] 716-689-2538
(N) Broadley Donna ✓ 716-639-7296
D'Agostino Joseph A ✓ [7]
(N) Graham Ora ✓
Howard Kathleen ✓ [5] 716-688-0737
Majkut Nora ✓ [5] 716-636-0405
Morris Thelma ✓ [3] ..716-689-0823
(N) Reed John ✓ 716-636-0022
TOTAL AGING IN PLACE PROGRAM government ✓@ 716-250-3100
465 (N) Babbitt Cheryl ✓ ..716-636-1961
CLOVER CONSTRUCTION construction companies ✓@ 716-636-0494
(N) Elkayam Esther ✓ ..716-639-0342
Galatioto Calogera ✓ [2] 716-688-0801
(N) Hartwick Mary A ✓ 716-688-9584
(N) Johnson J ✓ 716-688-5440
(N) Keele William ✓ ..716-688-0957
(N) Lapp Evelyn ✓ 716-688-0156
(N) Lebowitz S ✓
Noto Margie ✓ [2] 716-691-5267
(N) Shumway Evangeline ✓ 716-636-6178
109 Mayes Lucille ✓ [5] 716-688-1752
113 Hobson Clara E ✓ [3] 716-689-0253
115 Schmitt Faye S ✓ [2] 716-636-0289
116 Sanborn Carol J ✓ [2] 716-688-5852
117 Diem Merva J ✓ [3] 716-688-1061
118 (N) Ferrugia Carolyn L ✓ 716-636-1967
120 Falcone Santa ✓ [3]
121 (N) Osborne Nancy H ✓ 716-639-7516
122 (N) Cipollina John R
127 (N) Mohammad Wahid ✓@
129 Aldridge Edythe ✓ [2] 716-688-3511
131 Huels Dave E & Ellen S ✓ [5] 716-689-2079
132 (N) Odien Grace N ✓ 716-688-3515
134 Jurewicz Jacquelin P ✓ [3] 716-688-3006
134 Jurewicz Arthur ..716-688-3006
135 (N) Boron Bonnie L ✓ 716-639-3942
209 (N) Gromada Shirley A ✓
213 Insinna Annette M ✓ [2] 716-688-5618
214 Sturm Janet D ✓ [2]
215 (N) Demblewski Anne N ✓ 716-636-0576
216 (N) Loeb Karen ✓
217 (N) Hulse Phyllis R ✓ 716-688-4082
218 Thon Aleksandra J ✓ [2]
219 No Current Listing ✓
220 Stout Leonard D ✓ [2] 716-688-3089
224 (N) Hines Imogene ✓ 716-689-5769
225 (N) Overbey Rita ✓
226 Thompson Molly I ✓ [2] 716-688-5023
227 Nowak Diane ✓ [11]
228 (N) Neely Arlene M
230 Brooks Margaret M ✓ [2] 716-688-2358
232 (N) Kappel Rene A
234 (N) Ritchey Ronald L ✓
471 Alessi Rosalie ✓ [5] 716-688-1063
BAGEL NATIONAL bagels ✓@ 716-639-8980
Ballaro Janet ✓ [3] 716-688-6475
(N) Bellanca Richard ✓ 716-568-2035
Bialy Sally ✓ [3] 716-636-0953

STREET GUIDE

her Polk City Directories @ www.citydirectory.com

Target Street	Cross Street	Source
-	✓	Polk's City Directory

JOHN J AUDUBON PKWY 2014

JOHN JAMES AUDUBON PKWY - JOSEPH ST

JOHN JAMES AUDUBON PKWY Cont'd

Brent Gary ✓ [2] 716-636-1659
Burdzy Rose ✓ [2] 716-688-0282
Clark Janet ✓ [2] 716-634-5030
Collins Gloria ✓ [4] 716-639-7491
Edwards Patricia ✓ [4] 716-689-0951
Evege Thomas L ✓ [10]
Fox Lorraine ✓ [4] 716-626-9301
(N) Hall Jory ✓ 716-688-4678
Hausler Donna ✓ [4] ..716-688-4512
(N) Horvath Michael ✓ 716-688-8259
Ingrao M R ✓ [6] 716-639-0867
Landowski Jennie ✓ [3] 716-688-8695
Lankina Galina ✓ [7] ..716-688-7409
(N) Loving L ✓ 716-688-8953
Majewicz Anita ✓ [5]
(N) Masters J ✓ 716-688-1643
Mastrantonio E ✓ [5] ..716-689-2011
Meraglia Colleen ✓ [6] 716-689-3040
(N) Pierro Josephine ✓ 716-688-5408
Polizzi C ✓ [10] 716-636-5737
(N) Rivera-Santiago Milagros ✓ 716-688-6051
Taggart Mary ✓ [4] 716-688-5721
Vogel Barbara ✓ [5] ..716-688-3044
Wagner B ✓ [4] 716-688-0790
Wagner Helen ✓ [5] ..716-688-5795
103 Shaner Richard D & Loryna M ✓ [11] 716-689-6753
107 Schultz Louis E [2]
113 Dreher Marian B ✓ [15] 716-689-6629
115 Stankowski Judith A ✓ [10] 716-639-7419
126 Lang Doreen A ✓ [5] 716-639-7627
129 Schomaker Teresa A ✓ [7] 716-689-6307
202 Maloney Violet E ✓ [3]
204 Robins Jack M ✓ [5] 716-689-0016
206 Post Eleanor M ✓ [5] 716-688-5119
207 (N) Leo Sharon M ✓
208 Derby Valerie H ✓ [16] 716-688-5326
209 Willet Sally W ✓ @ [3] 716-688-4042
212 Damiani Sylvia ✓ [3]
213 Sandman Florence [3]
215 Dibenedetto Alice M ✓ [3] 716-639-7459
216 Lo Vullo Anna M ✓ [20] 716-688-5566
219 Mackay Kathleen A ✓ @ [3] 716-688-0330
222 Maghamez Georgette M ✓ [13]
227 (N) Moritz Alan G ✓
229 Howard Kathleen A ✓ [9]
301 Collins Barbara A ✓ [32] 716-565-2041
303 (N) Dokshutskaya Genya ✓
303 Majkut Nora C ✓ [5]
304 Anger Audrey G ✓ [7] 716-689-5986
305 Sansom Bruce R ✓ @ [10] 716-688-0143
306 Lamacchia Bernadine B ✓ [18] 716-688-1885
307 Prout Wilson C ✓ [13] 716-688-2396
308 Grimaldi Olive M ✓ [3]
310 Groth P A ✓ [13] ..716-639-0602
314 Hogan Mary E ✓ [5] 716-688-4397
314 Hogan E 716-688-4397
318 Gerth Charlotte E ✓ [5]
318 Gerth Donald A
319 Ingram Theresa ✓ [5] 716-689-2353
321 Saky June ✓ [4] ..716-689-2130
324 Salverson Patricia A ✓ [7] 716-688-8479
327 McCarthy Sharon M ✓ [15] 716-636-4909
328 Lacy Louis S Sr ✓ [5] 716-639-0526
401 Lepczyk Robert E ✓ [2] 716-688-0738
402 Sondel Anthony ✓ [4] 716-568-0259
406 Minich Carl E ✓ [9]
410 Kaufman Frank J ✓ [6] 716-636-1609
417 Goldfarb Vivian ✓ [7] 716-688-4117
419 (N) Mazurowski Frank ✓ 716-639-7896
424 (N) Fox Thomas E
425 Kuzara Judith B ✓ [16] 716-688-7017
427 Chatman Edna B ✓ [2] 716-688-1817

JOHN JAMES AUDUBON PKWY Cont'd

428 Fron Donald A ✓ [4]
429 Camparella Rose A ✓ [2]
+ PARTRIDGE RUN INTERSECTS
+ PARTRIDGE RUN INTERSECTS
475 Battaglia Viola ✓ [2] ..716-688-4413
Buczynski Virginia M ✓ [2] 716-639-8218
Francoforte F J ✓ [6] ..716-688-0480
Ledoux Bertrand P ✓ [3] 716-689-0418
Spagna Arlene ✓ [2] ..716-688-0824
(N) Syracuse Peter W ✓ 716-689-5813
115 Madill Dorothy A ✓ [9] 716-688-2279
116 Wells Patricia A ✓ [7] 716-636-4186
117 (N) Tapley Virginia ✓ 716-639-0428
119 Zimmer Jeanne M ✓ [7]
126 Murphy Margaret M ✓ [10]
129 Potter Alicia ✓ [7] 716-639-3758
131 (N) Edwards Ruthie M ✓ 716-688-5060
141 McQueary Alice ✓ [10] 716-689-6202
142 Jay Roslyn ✓ [4] 716-688-5346
143 Euller Betty J ✓ [7] 716-688-2171
144 Terry Lucille F ✓ [15] 716-689-3643
145 Palaszewski Rose J ✓ [13] 716-688-8209
146 Solazzo Patricia G ✓ [6] 716-689-0475
147 Parsons Virginia C ✓ [19]
215 Bordonaro Samuel M ✓ [4] 716-689-0609
217 Cortelli Josephine C ✓ [10]
218 Klopp Barbara A ✓ [4] 716-688-5201
219 Loporto Nancy L ✓ [6] 716-688-6590
221 Warren Charlotte A ✓ [18] 716-636-0023
221 Warren Lorraine ..716-636-0023
222 Gecewicz Betty J ✓ [7] 716-636-1015
223 (N) Westley Richard A ✓ 716-689-0539
228 McCarthy Linda M [6]
229 Andrzejewski Benedict P ✓ [5]
229 Turnwall Jose L ✓ [23] 716-639-8684
230 Burns Bonnie L ✓ [10]
231 O'Shei Mary S ✓ [6] 716-639-7790
240 Majchrzycki Gloria ✓ [7] 716-636-1030
241 Brown Geoff L ✓ [20]
242 (N) Blatner Richard N ✓ 716-688-2124
244 Labedz Michael S [3]
244 Labedz Dee A
247 Milazzo Joan Y ✓ [10]
249 Yaw Joan M ✓ [3] 716-688-3999

500 AMHERST ANIMAL CONTROL government offices ✓ @ 716-689-1311
AMHERST POLICE DEPT police departments ✓ @ 716-689-1322
AMHRST TWN PLC DEPT TRF BUREAU nonclassified establishmerits ✓ @ ..716-689-1355
501 BORELLI & LIPUMA CPA accountants ✓ @ 716-636-9800
(N) Capozzi Tammy ✓
DAYCO PRODUCTS LLC government offices ✓ @ 716-689-4972
I EVOLVE TECHNOLOGY SVC telecommunications consultants ✓ 716-568-2810
IEVOLVE INC info technology serv ✓ @ 716-505-8324
KANICK & CO business mgmt consultants ✓ @ 716-651-0111
LAWLEY VIVACQUA SCHEFF LLC insurance ✓ @ 716-636-5800
M J PETERSON CORP real estate ✓ @ 716-688-1234
M J PETERSON REAL ESTATE real estate mgmt ✓ @ 716-689-7800
MARK IV LLC auto parts & supl- mfrs 716-689-4972
NESPER FERBER & DI GIACOMO attorneys ✓ @ 716-688-3800
OLDE TOWNE VILLAGE APARTMENTS apartments ✓ @ 716-689-6006
PETERSON M J real estate ✓ 716-689-7800

JOHN JAMES Cont'd

PSI data p .....
ROBSON protectic .....
SUNDRID .....
202 Lipum
204 Miami
+ BRYANT WOO
+ BRYANT WOO
+ DODGE RD BU
+ RAILROAD CR
+ DODGE RD EA
BUSINESSES 9

JOHN LORD O E
• ZIP CODE 142
319 SUNY UN schools
BUSINESSES 1

JOHN MUIR DR
+ SYLVAN PKW
• ZIP CODE 142
90 AMEC ENG engine .....
BETHLEHI & steel .....
M B M S th establis
90 A (N) Jamie
90 A/2 MORT SYSTE .....
95 BUFFALO info/tre
RALPH J V bonds- .....
(N) Welch
100 (N) Mo
100 REDL collectic .....
112 Vanne
110 (N) Brohm COMPUT data pr .....
Grisanti M
130 100 JOHI controls .....
106 SES ISRAEL .....
400 UTIC GROUI .....
131 (N) Leiby WESTEF church
1 ADOPT agencie
+ N FOREST R
BUSINESSES 1

JOLIET LN (BU
RD EAST
• ZIP CODE 14
8 Palombo M (1993)
16 Angelako [16] ● (1
17 Pera Dav (2002)
24 Kuczkow ● (199
25 FRANCIS builder
Theeman ● (199
32 Woeppel
33 Stephan (1993)
40 Lewis Dv (1990)
41 Anderso Anderso
48 Wright D (1992)
49 Folga Rc (1992)
57 Andrews [27] ●
64 Costanz (1993)
65 Bonito M [21] ●
72 (N) Colle

This directory is property of Polk City Directories. It is leased for the pers on the title page of this directory. This information changes by

Target Street	Cross Street	Source
-	✓	Polk's City Directory

JOHN J AUDUBON PKWY 2014



212

JOHN JAMES AUDUBON PKWY
Cont'd

PSI data processing serv ✓
.....716-688-0235
ROBSON & WOESE INC fire
protection consultants ✓ @
.....716-636-1800
SUNDRIDGE APTS apartments ✓ @
.....716-689-6006
202 Lipuma Joseph A [2]
204 Mamo Laurie [2]

+ BRYANT WOODS N BEGINS
+ BRYANT WOODS N BEGINS
+ DODGE RD BEGINS
+ RAILROAD CROSSES
+ DODGE RD ENDS

BUSINESSES 98 HOUSEHOLDS 176

JOHN LORD O BRIAN HAL (BUFFALO)

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAPLE RD 2014

34 716-636-3395
397 Olszewski Melanie T ✓ 3
65 716-636-0621
397 Olszewski Paul ..716-636-0621
50 399 Barish Phyllis R ✓ 25
.....716-639-8213
401 SILVER MANE SALON beauty
salons ✓@ 716-636-1700
79 2351 CITIZENS BANK banks ✓@
.....716-634-4970
2379 EVERTHING FOR DOLLAR
STORE USA retail shops ✓@
34 716-565-3055
2383 MARSHALLS department stores ✓
09 @ 716-810-0980
2395 WEAR HOUSE clothing-retail ✓@
76 716-636-8234
+ *TRANSIT RD INTERSECTS*
• **ZIP CODE 14226 CAR-RT C030**
43 3895 J C PENNEY PORTRAIT STUDIO
A shopping centers & malls ✓@
39 716-833-2228
J C PENNEY SALON beauty salons
93 ✓@ 716-837-6098

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAPLE RD 2014

NEW NEIGHBOR

MAPLE RD Cont'd

3900 PRIME WINE & SPIRITS liquors-retail ✓@ 716-877-6589
3902 LIFE RESOURCES LLC book dlrs-retail ✓@ 716-836-4001
3904 PREMIER GOURMET cheese ✓@ 716-877-3574
3910 RED PEPPER CHINESE-VIETNAMESE restaurants ✓@ 716-831-3878
3912 FEEL-RITE FRESH MARKET health & diet foods-retail ✓@ 716-834-3385
3920 DENNY'S restaurants ✓@ 716-446-1671
3931 BRIDGESTONE MASTERCARE SVC CTR auto rpr & serv ✓@ 716-837-7721
FIRESTONE COMPLETE AUTO CARE auto rpr & serv ✓@ 716-261-3929

▲ ALBERTA DR INTERSECTS

3951 OLIVE GARDEN ITALIAN RSTRNT restaurants ✓@ 716-837-5211
Ⓝ Smith Maddie ✓
3980 DI VENCENZO ROBERT F MD physicians & surgeons ✓@
Ⓝ Melewski Colleen
NISSAN'S KOSHER DELI delicatessens ✓@ ..716-515-0075
TIM HORTONS doughnuts ✓@ 716-446-9730
TOPS FRIENDLY MARKET PHARMACY pharmacies ✓@ 716-515-0080
WESTERN UNION money transfer serv ✓@ 716-515-0076
3999 SCOTCH N SIRLOIN restaurants ✓ 716-837-4900
4001 JENSS DECOR department stores ✓@ 716-837-1100
REEDS JEWELERS jewelers-retail ✓@ 716-837-3934
4003 IHOP RESTAURANT restaurants ✓ 716-446-1117
Ⓝ Zeis Michael
4010 RED LOBSTER restaurants ✓@ 716-837-0202
4033 Harrison Danita [5]
200 FRONTIER SCIENCE & TECHNOLOGY foundation ✓@ 716-834-0900
4043 BROWN ENTERPRISES business mgmt consultants ✓@ 716-834-1900
NEXT FINANCIAL financial advisory serv ✓@ 716-768-1463
OBANNON & DAVIS INC insurance ✓@ 716-856-7555
100 H J HILL TAX & ACCOUNTING SVC tax return preparation/filing ✓@
102 COLOR COMMUNICATIONS INC printers ✓@ 716-838-0698
104 MJI CONSULTING business mgmt consultants ✓@ 716-837-1033
104 ZEFTEL BRUCE attorneys ✓@ 716-381-9141
105 LEUKEMIA & LYMPHOMA SOCIETY org ✓@ ..585-263-2440
106 ADVANCED STORAGE TECHNOLOGY storage- liquid & bulk ✓@ 716-833-6212
108 KIRST COMMERCIAL REAL ESTATE real estate ✓@ 716-836-8200
203 MARSH PLASTICS INC plastics- raw mtrls/powder/resi ✓@ 716-834-6500
207 Ⓝ Edwards Ann ✓
207 REALTY EDGE real estate ✓@ 716-834-3343
209 BECK REEDY & ASSOC financial planning consultants ✓@ 716-833-3447
210 Ⓝ Davis William R
211 E M SYSTEMS INC computer software ✓@ 716-836-4910
4050 WENDY'S restaurants ✓@ 716-832-0855
4053 BENCHMARK MERCHANT SOLUTIONS financial planning consultants ✓@ 718-506-9250
Dobbins Terrence L [6]
106 PARK LANE CONSTRUCTION construction companies ✓@ 716-836-6790
106 SOUNDCORE INC concrete products ✓@ 716-833-7651
111 CHILDREN'S GROWTH FOUNDATION org ✓@ 716-878-7769
111 JENSS DEPARTMENT STORES INC nonclassified establishments @ 716-837-4958
200 AMERICAN EQUITY CORP building contractors ✓@ 716-833-4934

MAPLE RD Cont'd

200 BENCHMARK 325 DE ASSOC LP real estate developers ✓@ 716-833-4986
200 BENCHMARK FINANCIAL GROUP INC real estate developers ✓@ 716-833-4986
200 BENCHMARK MANAGEMENT CORP real estate 716-833-4966
200 Gellman Susan R ✓ [20] ▲ (1967)
200 Ⓝ Narins Clarke H ✓
200A BENCHMARK GROUP bowling centers ✓@
4060 KYOTO JAPANESE RESTAURANT restaurants ✓@ 716-836-6688
4080 RED ROBIN GOURMET BURGERS restaurants ✓@ 716-834-4100
4090 PLANET FITNESS health clubs studios/gymnasium ✓@ 716-253-7676
4110 COLD STONE CREAMERY ice cream parlors ✓@ ..716-803-1500
ORECK CLEAN HOME CTR vacuum cleaners- household-dlrs ✓@ 716-833-3444
VISIONWORKS optical goods-retail ✓@ 716-831-8050
4120 BRICK HOUSE TAVERN + TAP bars ✓@ 716-834-1490
4125 JOE'S CRAB SHACK restaurants ✓@ 716-836-4739
4150 Commisso Angela ✓ [4]
SWEET HOME MIDDLE SCHOOL schools ✓@ 716-250-1450
4185 BOSTON MARKET restaurants ✓@ 716-834-2320
4220 RAC ACCEPTANCE furniture-renting & lease ✓@ ..716-831-8164
VALUE CITY FURNITURE furniture-dlrs- retail ✓@ 716-833-5794
4224 EXECUTIVE FOOD GROUP food products- retail ✓@ ..716-836-9241
TEA INNOVATIONS INC food products ✓@ 716-831-8202
100 COPYMAX MAPLE RIDGE CTR copying & duplicating serv ✓@ 716-831-0396
100 OFFICE MAX office supl ✓@ 716-862-6660
108 SUBWAY restaurants ✓@ 716-832-4905
112 LENSCRAFTERS optical goods- retail ✓@ 716-833-0803
116 LEON STUDIO ONE SALON beauty salons ✓@ ..716-862-0068
120 LIBRARY LOCATED IN THE MAPLE restaurants ✓@ 716-831-3271
120 MAPLE ENTERTAINMENT restaurants ✓@ 716-831-3271
4225 JOSEPH MADDI PC physicians & surgeons ✓@ 716-834-0221
THOMAS SUZANNE K nurses-practitioners ✓@ 716-834-0221
4227 PAIN MANAGEMENT & HEADACHE pain control ✓ 716-832-1107
4229 ACUPUNCTURE CHINESE MEDICINE acupuncture ✓@ 716-803-8899
4231 AMHERST SURGICIAL ASSOC physicians & surgeons ✓@ 716-837-9111
ZIELINSKI CHRISTOPHER physicians assistants ✓@ 716-837-9111
4233 DEVANS BETH A nurses-practitioners @ 716-838-3188
GANNON DONNA M nurses-practitioners ✓@ 716-838-3188
HYPERTENSION RESEARCH PROGRAM physicians & surgeons ✓ 716-838-3188
Marinides George N [5]
NEPHROLOGY ASSOCIATES physicians & surgeons ✓@ 716-838-3188
PENNINGTON JANICE M nurses-practitioners ✓@ 716-838-3188
SCIME-CORMIE DOROTHY M nurses- practitioners @ 716-838-3188
4239 GENTILE JOSEPH D MD physicians & surgeons ✓@ 716-832-9747
Gentile Theresa L ✓ [19]
Gentile Joseph D
SIELSKI LESTER S MD physicians & surgeons ✓@ 716-835-2984
4241 AMERIPRISE FINANCIAL financial advisory serv ✓@ 716-831-8944
4243 Lamastra Michael S ✓ [18] ▲ (1967)
MAPLE DENTAL dentists ✓@ 716-833-4637
4245 Malik Fauzia F ✓ [12]

MAP

4247
4249
4258
4265
4276
4291
• ZIP (
4330
4350
4400
• FLI
4621
4641
BUSI
MAPL
EAST
• LON
• ZIP (
9450
• GO
9475
9480
9490
• RAI
9525
9530
9540
9550
• ELA
9560
9565
9570
BUSI
MAP
• ZIP
6 Ba
11 L
12 L
17 M
18 T
23 K
24 (

Get Mailing Lists, Sales Leads, and Business Cr

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAPLE RD 2014



261

MAPLE RD Cont'd

REPORT LEASE LLC lease serv ✓ @ 716-834-0793
TRAVEL HOUSE INTL OF WNY INC airline ticket agencies ✓@ 716-835-2141
4247 CUKIERMAN JACK MD physicians & surgeons ✓@ 716-835-9871
HAQUE SHAHID MD physicians & surgeons ✓@ 716-835-9871
KALEIDA HEALTH LABORATORY laboratories- medical ✓@ 716-836-8359
4249 DALY RICHARD F attorneys ✓@ 716-835-2200
SIEGEL KELLEHER & KAHN attorneys ✓@ 716-834-5800
4258 Rhorres Adam @ 3
TACO BELL restaurants @ 716-833-8332
4265 NOCO EXPRESS serv stations-gasoline & oil ✓@ ..716-837-8479
4276 AMC MAPLE RIDGE 8 theatres-movie ✓@ 716-833-9545
U SPORTS BAR restaurants ✓@ 716-833-8438
4291 ERIN & BILL'S AUTO & TRANSPORT auto rpr & serv ✓@ 716-836-7500
ERIN'S AUTOMOTIVE & TRNSPRTN auto transporters & drive ✓ 716-691-1017
U-HAUL NEIGHBORHOOD DEALER truck renting & lease ✓@ 716-839-1745

• ZIP CODE 14226 CAR-RT C047

4330 XEROX OF UPSTATE NY copying/duplicating mach/supl ✓@ 716-218-3488
103 FINANCIAL PLANNING ADVISORY financial advisory serv ✓@ 716-362-8787
200 INSPIRE DENTAL GROUP dentists ✓@ 716-362-4800
4350 FRIENDLY'S ICE CREAM SHOP ice cream parlors ✓@ 716-835-2862
MAC GREGOR'S GRILL & TAP ROOM restaurants ✓@ 716-725-0720
4400 MOTEL 6 hotels & motels ✓@ 716-834-2231
Smith Cj J 3

+ FLINT RD INTERSECTS

4621 ZETTI'S PIZZA & PASTA pizza ✓@ 716-691-8535
4641 A P MART serv stations- gasoline & oil ✓@ 716-564-1248

BUSINESSES 308 HOUSEHOLDS 511

MAPLE ST (CLARENCE CENTER)-FROM 6001 EASTWOOD RD

Target Street	Cross Street	Source
-	✓	Polk's City Directory

SWEETHOME RD 2014

5-5936
8-9916
8-9916
6-8329
6-8329
14
6-4097
@
6-7351
5
1-6055
sts ✓
3-0850
g ✓@
8-2130
s)
4)
7-4161
7-4161
7-2047
7-2047
HT
6-7556
ON
6-7556
7-1294
943)
5-7665
5-7665

.....716-837-9305
Kerkeslager Mandy 716-837-9305
946 Burkard Keith M & Kathleen A ✓@
29 ♠ (1935) 716-838-1130
948 Abbarno Joseph P ✓@ 23 ♠ (1961)
.....716-835-3878
956 Geib Gloria M ✓ 47 ♠ (1935)
.....716-834-6508
965 Brummer John J Sr & Judith A ✓ 25
♠ (1958) 716-834-3185
966 NORTH BAILEY FIRE CO fire
departments ✓@ 716-836-9571
1005 Harbison Emily ✓ 50 ♠ (1950)
.....716-837-6878
1011 Tibung Jesus D Jr & Zenada C ✓
10 ♠ (1936) 716-834-7861
1012 Furman Jason G ✓ 17 ♠ (1968)
1015 No Current Listing
+ MAPLE RD INTERSECTS
1185 AMHERST MEDICAL GROUP
health maintenance org ✓@
.....716-689-0040
ARCARA MICHELE S nurses-
practitioners ✓@ 716-689-0040
BURTON PAMELA JILL physicians
assistants ✓@ 716-689-0040
CALHOUN CAROL E physicians
assistants ✓@ 716-689-0040
EASTERN NIAGARA RADIOLOGY
physicians & surgeons ✓@
.....716-689-3468
GENCO ANTOINETTE pharmacists
@ 716-689-3471
JOHNSON-CLARK KATELYN E
DO physicians & surgeons ✓@
.....716-689-0040
LIFETIME HEALTH AMHERST
MED physicians & surgeons ✓@
.....716-689-0040
MAKAR JULIE social workers ✓
.....716-689-0040
MC GRATH KIMBERLY A
physicians assistants ✓@
.....716-689-0040
NANNI MICHELE physicians
assistants ✓@ 716-689-0040
ROESSLER LORI A nurses-
practitioners ✓@ 716-689-0040

STREET GUIDE

tydirectory.com

Target Street	Cross Street	Source
-	✓	Polk's City Directory

SWEETHOME RD 2014

SWEET HOME RD

SWEET HOME RD Cont'd

RUBIN BARBARA nurses-practitioners ✓@ 716-689-0040
SAVOY NANCY A nurses-practitioners ✓@ 716-689-0040
• ZIP CODE 14228 CAR-RT C059
1260 JOHN SHAFLUCAS ARCHITECTS architects ✓@ 716-636-5000
• RENSCH RD ENDS
• RENSCH ENTRANCE INTERSECTS
1400 DENNIS CARROLL INVESTMENT financial planning consultants ✓@ 716-688-7708
HNAT FAMILY CHIROPRACTIC chiropractors dc ✓@ 716-689-5919
LEGACYQUEST ADVISORS LLC financial advisory serv ✓@ 716-200-4900
• RENSCH RD ENDS
SCHROEDER BRAXTON VOGT financial advisory serv ✓@ 716-634-6113
2 RITCHIE STRAFFORD D attorneys ✓@ 716-639-4400
4 N Salerno-Kobel Annmarie S ✓
4 W E ARCHITECTURE architectural designers ✓@ 716-626-9966
6 PHOENIX RISING MEDICAL PC physicians & surgeons ✓@ 716-836-1388
7 ALIOTTA JOSEPH insurance annuities @ 716-568-2920
7 CARROLL FINANCIAL SVC INC financial advisory serv ✓@ 716-568-2920
9 THERMOGRAPHY OF WEST NY INC business serv ✓@ 716-688-1828
10 ADVANCED HAIR SOLUTIONS beauty salons ✓@ ..716-839-4100
1404 STARLINE USA INC advertising ✓@ 716-636-1937
1 AFLAC insurance ✓@ 716-213-0659
2 RICOTTA & ASSOC psychologists ✓ 716-634-0566
5 UNIVERSITY PEDIATRIC ASSOC physicians & surgeons ✓@ 716-639-9360
8 ORCHESTRAL FINANCIAL GROUP INC financial planning consultants ✓@ 716-691-4288
10 DIDONATO KNOX & ASSOC accountants ✓ 716-204-4888
12 UNIVERSITY WEALTH MANAGEMENT investments ✓ 716-213-0080
1408 CAMPBELL SR LORNE R MD physicians & surgeons ✓@
FISHER MARK D MD physicians & surgeons ✓@
JAMYA INC computer software ✓@ 716-565-9114
PROPOSAL SOFTWARE computer software ✓ 716-689-4800
1 BENEFIT BROKERS OF WNY insurance ✓@ 716-639-3950
8 ENERGY COOPERATIVE OF AMERICA electric companies ✓@ 716-580-3506
8 INDUSTRIAL ENERGY BUYERS LLC energy mgmt sys & products ✓@ 716-688-2700
9 UBMD FAMILY MEDICINE physicians & surgeons ✓ 716-247-5281
11 LIGHTHOUSE TECHNOLOGY SVC INC payroll preparation serv ✓@ 716-634-0509
12 CONNECT EDU INC internet serv ✓@ 716-204-0464
1412 ELIZABETH A O'NEILL PC physicians & surgeons ✓@ 716-810-9030
HSU R BERNARD pain control ✓@ 716-688-5088
1 MALIK POPIEL PC attorneys ✓@ 716-689-7770
2 BUFFALO GEORGE SCIENCE nonclassified establishments ✓@ 716-688-8226
3 BUFFALO COMPUTING SOLUTIONS computers-networking ✓@ 716-852-0523
BUFFALO MEN'S HEALTH PRACTICE clinics ✓@ 716-688-7777
10 CREDIT MANAGEMENT SOLUTIONS credit reporting agencies ✓@ 716-688-8002
12 NORNEW INC oil/gas exploration/developmen ✓ 716-568-2048
1416 ALTERNATIVES OPTIONS massage therapists ✓@ 716-639-0768

SWEET HOME RD Cont'd

1416 INSTITUTE FOR CLINICAL clinics ✓@ 716-688-8144
ODDO CONSTRUCTION SVC LLC construction companies ✓@ 716-689-7729
RGIS INVENTORY SPECIALISTS inventory serv ✓@ ..716-636-4912
3 CH3 BIOSYSTEMS LLC physicists ✓@ 716-688-5222
3 EXPLORE WHAT'S NEXT counseling- transformation serv ✓@ 716-688-5222
5 PREMIER CONSULTING ASSOC insurance ✓@ 716-688-5600
7 FIRST RELIANCE HOLDINGS holding companies ✓@ 716-691-0829
7 POSITIVE HEALTH & WELLNESS chiropractors dc ✓@ 716-833-1664
12 BARWELL JENNIFER J physicians assistants ✓@ 716-636-7800
12 SWEET HOME FAMILY MEDICINE PC physicians/surgeons info burea ✓@ 716-636-7800
1434 Allen Michele L 16 ● (1977)
N Bennett Ryan ✓
1436 Shunmugasundram Dhana L 9
• RENSCH ENTRANCE INTERSECTS
1544 Jesserer Beth 4
1554 N Envisdnvusn X
1576 ACCUTHERANOSTICS laboratories- medical ✓@ 716-688-9600
AZTECH INC market research & analysis ✓@ 716-833-7870
Bloomberg Dale ✓ 5
GSE COMMUNICATIONS video tape editing @ 716-639-0260
ONY INC physicians & surgeons equip ✓@ 716-636-9096
RANDFORCE ASSOCIATES LLC business mgmt consultants ✓@ 716-639-1047
• CHESTNUT RIDGE RD INTERSECTS
• ZIP CODE 14228 CAR-RT C060
1608 1 Murtanti Aditia 3
2 N Harjanta Devi ✓
5 Tan Kuo S ✓ 2
5 N Widjaja Andrew ✓
7 Vanleuvan Adrian B 2
8 Clarke Janette R 2
1741 SWEET HOME SCHOOL DISTRICT SVC educational serv-business ✓@ 716-250-1445
1772 UNIVERSITY VILLAGE SWEETHOME student housing ✓ 716-689-5880
1880 SWEET HOME SENIOR APARTMENTS apartments ✓@ 716-636-0001
• SKINNERSVILLE RD INTERSECTS
1900 C W A 1168 LOCAL labor org ✓@ 716-688-4317
MJW CORP envrmntl & ecolgcl serv ✓@ 716-631-8291
1901 N Mahmood Syed @
SHIPE BEVERLY ANN nurses-practitioners ✓@ 716-250-1269
SWEET HOME HIGH SCHOOL schools ✓@ 716-250-1200
SWEET HOME SCHOOL DISTRICT educational serv-business ✓@ 716-250-1423
SWEET HOME SPECIAL EDUCATION schools ✓@ 716-250-1236
1950 TIM HORTONS doughnuts ✓@ 716-688-2024
1960 SWEET HOME FEDERAL CU credit unions ✓@ 716-204-8932
1974 Stumm Rodney C & Susan C ✓ 38 ● (1960) 716-688-1371
1984 Anthon Bryan A ✓@ 7 ● (1960) 716-688-5186
Anthon Linda 716-688-5186
1991 Granto Elizabeth M ✓ 5 716-688-5460
2001 N Bevacqua Chris W ✓
N Johnson Feren ✓
2004 Capaccio Joe ✓ 10 ● (1977) 716-689-2922
Capaccio Cody J 716-689-2922
2011 Medwid John G ✓ 10 ● (2005) 716-688-6024
Medwid Wanda H 716-688-6024
2014 No Current Listing
2021 N Buckwalter Esther H ✓
2024 Hanna Judith ✓ 33 ● (1952)
2031 Gallo Martha B ✓ 46 ● (1977) 716-688-9230
Gallo Samuel A 716-688-9230
2034 Bainbridge Larry J & Andrea J ✓ 43 ● (1948) 716-688-8204

SWEET HOM

2038 Harbiso
33 ● (1
2041 Oneill C
2071 No Curr
• WINDHAM W
• ZIP CODE 142
2211 3 Bou-M
3 Bou-M
5 N Ca
7 N De
9 Gjhas
10 Lim
2215 Wyse H
2350 AVERA
2360 N Aguil
N Cola
1 MATT chiropra
1 MISIA chiropra
1 Misiak
2 HARIS PC mas
3 WSP ENERG ✓@
4 BEHA OF WN
4 Cooke
5 PRES @
6 SIMPL chiropra
2365 N Rebb
Spano K
3 N Wi
6 N Mu
9 N Mu
2367 N Blak
N Justi
N Vann
11 N M
14 Kean
14 Kean
2372 1 BUFF ✓@
5 CARR COMM consult
7 SUMM financia
8 BATC return p
8 C D F advisory
8 ROYA planning
2399 Allen Sc GAR AS ✓@
LARKIN
2420 AMERIC collectic CIMINE estate NEW Y title cor Redding 100 Har 110 JNE busines
110 THE ENGNF
130 SU SOLUT agencie 145 AB attorne 145 RE @
145 RE LAW at
2425 MC DO attorne PBM M
PBM S clothing 1 FINA ADVIS consult
2446 N Esa
N Hija
• DODGE RD

This directory is property of Polk City Directories. It is leased for the perso
on the title page of this directory. This information changes by

Target Street	Cross Street	Source
-	✓	Polk's City Directory

JOHN J AUDUBON PKWY 2008



BUSINESSES 21 HOUSEHOLDS 3

259

259 JOHN JAMES AUDUBON PKWY (BUFFALO)

• ZIP CODE 14228 CAR-RT C061

594 1 ALLEN LISA A attorneys

CARLY WILSMAN ATTORNEY

attorneys 716-632-2852 251

d for the personal use of the subscriber. Us

Target Street	Cross Street	Source
-	✓	Polk's City Directory

JOHN J AUDUBON PKWY 2008

♠HOMEOWNER

JOHN JAMES AUDUBON PKWY Cont'd

8602 ENNIS-BUONOCOR COLLEEN attorneys
3475 GOLDHABER REASEARCH ASSOC nonclassified establishments 716-689-3342
HARRIENGER TRACY S attorneys
♠ HOGAN & WILLIG PLLC attorneys
5613 716-434-7600
HOGAN & WILLIG REAL ESTATE CTR
0829 attorneys 716-688-1991
King Hazel
LEONARD G LONDON LAW OFFICES
4704 attorneys 716-634-8600
0307 LICATA JOHN B attorneys
MAHONEY KEVIN S attorneys
7958 PRUDENTIAL INSURANCE CO insurance 716-636-1960
8658 TINNEY CAROLYN L attorneys
TIVERON DIANE R attorneys
5530 WACHOVIA SECURITIES stock & bond brokers 716-689-5935
2913 21 Forcello Kathi
210 Hogan Corey J [9] 716-636-7600
7056 ***+ N FOREST RD INTERSECTS***
7056 10 BESTRY SHERWOOD L attorneys 716-688-1600
COMDOC INC duplicating mach & supl 716-689-0202
8433 LILLIS TARA B attorneys 716-636-9181
8015 MUIR LAKE CONSULTING CORP insurance consultants/advisors 716-689-1700
9732 NATIONAL FIRE ADJUSTMENT CO adjusters-public 716-689-7700
2579 PAPA RONALD J FIRE ADJSTR insurance adjusters ..716-689-7700
9196 1 Papa Ronald J [13]
1 Papa Frank R
4939 101 AMERICAN CANCER SOCIETY associations 716-689-6981
3607 140 AUDUBON EXPORT INC exporters
DS 35 716-689-5400
C M CHAIN hoists 716-689-5400
CADY LIFTERS nonclassified establishments 716-689-5400
CM INSURANCE CO INC insurance 716-689-5400
ing COLUMBUS MC KINNON CORP
8688 hoists-mfrs 716-689-5400
Duchscherer Wendel [4]
0222 716-688-4913
GAFFEY INC hoists-mfrs 716-689-5400
7631 Necessary Dave
SPRECKLES CONSOLIDATED IND
3630 hoists-mfrs 716-689-5400
SPRECKLES DEVELOPMENT CO
2158 INC real estate developers 716-689-5400
SPRECKLES WATER CO INC
7012 engineers- water supply 716-689-5400
7012 WENDEL DUCHSCHERER ARCHITECTS architects 716-688-0766
YALE INDUSTRIAL PRODUCTS
8806 INC mfrs distrs & indl products 716-689-5409
151 NATIONAL TRAFFIC SVC INC
5100 marketing programs & serv 716-636-8253
200 BARTECH GROUP INC employment
3174 contractors 716-689-8960
P BARTON DISTILLERS IMPORT
3511 CORP distillers 716-688-6760
BROWN & BROWN INSURANCE
insurance 716-995-5620
5100 ELLIS HOWARD M attorneys 716-689-8837
3300 GOODYEAR DUNLOP TIRES N AMER tire-dlrs-retail 716-639-5200
7979 KIDENEY ARCHITECTS architects 716-636-9700
0477 L F ENGINEERING PLLC engineers-consulting 716-688-3060
3603 NC INDUSTRIES INC mfrs 716-689-8400
4525 NIAGARA CUTTER INC tools-cutting 716-689-8400
0032 NORTH AMERICAN MFG CO combustion controls ..716-689-0671
1688 PROCTER & GAMBLE
TN DISTRIBUTING distribution serv
3300 716-689-0803
SCHWARTZ GROUP INC marketing
1154 consultants 716-635-9650
SYSTEMS & ENGINEERING PC
DS 3 engineers- consulting 716-633-9950
9 UNITED INSURANCE GROUP insurance 716-636-7277
XL MEDIA GROUP multimedia 716-568-1211
2852 251 Dean Connie [6]

JOHN JAMES AUDUBON PKWY Cont'd

FIDNATIS nonclassified establishments 716-636-7812
ICT GROUP communications consultants 716-636-2000
MR METICULOUS LANDSCAPE landscape contractors 716-636-1130
SMARTLINE MEMBER ICT GROUP telemarketing serv ..716-639-7438
WELLS FARGO FINANCIAL financing 716-689-0484
331 COMPUTER SEARCH PAYROLL SVC computer related serv 716-692-1409
350 AMHERST PUBLIC LIBRARY libraries-public 716-688-4919
AUDUBON LIBRARY libraries-public 716-689-4922
370 AMHERST ADULT DAY SVC government offices ..716-689-1403
AMHERST CENTER-SENIOR SVC government offices ..716-636-3050
AMHERST MEALS ON WHEELS social serv & welfare org 716-636-3065
AMHERST SENIOR TRNSPRTN SVC government offices 716-636-3075
400 TOWN OF AMHERST COURT city government- courts ..716-689-4200
411 JEWISH HERITAGE DAY SCHOOL religious schools 716-568-0226
Schanowitz Rachel C [2]
+ PARTRIDGE RUN INTERSECTS
+ PARTRIDGE RUN INTERSECTS
461 Buczynski Virginia M 716-639-8218
D'Agostino Joseph A [2] 716-689-3832
Hedrich Anna [2] 716-689-5813
McCarthy Sharon M [15]
Santowski E N 716-689-6583
Sokolski B [3]
Staufenberge Edward 716-689-7685
Weber Joan 716-689-1981
471 Alessi Rosalie 716-688-1063
Anderson J [5] 716-688-6660
Buffamanti Fred [3] 716-634-0082
Campbell K 716-688-4714
Campbell Dorothy J ..716-688-4714
Chiaramomte Santina [5] 716-639-1390
Chiarmonte Lucy [4] ..716-639-8717
Cohen Marilyn J [6] 716-636-4935
Collins Barbara A [27] 716-565-2041
Danahy Joan [2] 716-688-5423
Daniels Shirley J [13] ..716-688-5038
Evege Thomas L [5]
Fergen Geraldine [12] ..716-639-0017
Gamble T 716-688-0824
Graesser E [2] 716-688-5722
Hoffman M D [4] 716-636-4117
Ingram Theresa 716-689-2353
Ingrao M R 716-639-0867
Jackson Delores [8] 716-691-8493
Johnson Margaret [4] 716-688-5458
Jordan D I [2] 716-688-3947
Kalinowski Doires ..716-688-8910
Kaufman Frank J ..716-636-1609
Kaukus Frances M [12] 716-639-1538
Kuzara Judith [4] 716-688-7017
Lake S [4] 716-689-1729
Lamacchia Bernadine [4] 716-688-1885
Lankina Galina [2] 716-688-7409
Leone Rose 716-639-0828
Levin Sam 716-568-1768
Long Mary 716-689-6960
Mc Farland James Sr 716-688-0846
Meraglia Colleen 716-689-3040
Mierczewski V
Millett Francis [4] 716-688-0643
O'Connor Fran.....
.....716-636-0778
Peterson Esther [3] 716-636-0106
Pohl Annette [4] 716-688-7305
Radeff Raina 716-636-0055
Reedus G [4] 716-639-7507
Rizzo Richard [2] 716-688-6186
Sansom Bruce 716-688-0143
Sauer Rosemarie [2] ..716-688-7020
Schaffer Nettie L ..716-688-0293
Scharett F 716-636-0397
Schuder Joseph J [3] 716-636-0910
Stadler L M [2] 716-689-9306
Ziff Lilian [3] 716-639-8074
Ziv Yocheved Y 716-625-4161
103 Shaner Richard D & Loryna M [6] 716-689-6753

riber. Use of this directory is subject to the Terms of Use appearing

Target Street	Cross Street	Source
-	✓	Polk's City Directory

JOHN J AUDUBON PKWY 2008

NEW NEIGHBOR

JOHN JAMES AUDUBON PKWY
Cont'd

106 Greco Agnes E [5] 716-689-4079
109 Metz Elvina G
112 King Hazel 716-639-8078
114 Hickey Clara A [5] 716-688-2714
115 Stankowski Judith A [5] 716-639-7419
126 Slootsky Lyudmila V [16] 716-633-5544
129 Barnes Peggy [17]
202 Sullivan Barbara J [11] 716-689-3782
204 Kasimov Samuel L [23] 716-689-4964
207 Shepard Gail M
210 Pulvino Lena E [8] 716-688-4977
211 Carlson Mildred M [4] 716-636-5956
216 Lo Vullo Anna M [15] 716-688-5566
222 Maghamez Georgette M [6] 716-688-2337
223 Bumbalo Jane [16] 716-636-4361
229 Di Gaetano Antonina D
302 Grgurich Ann
303 Walker Donald J [10] 716-688-6213
303 Walker Robert J ..716-688-6213
305 Wells Patricia A [5] 716-636-4186
307 Prout Wilson C [5] 716-688-2396
310 Groth P A [8] 716-639-0602
314 Price Audrey A [5] 716-689-8827
318 Valenti Florence A [5]
323 Alcock Bessie J [24] 716-636-4161
323 Alcock Jean M 716-636-4161
323 Difrancesco Virginia A 716-688-1018
325 No Current Listing
327 Kolis Chester J [5] 716-636-0316
327 McCarthy Sharon M [5] 716-636-4909
328 Inman Iona B [12] 716-688-6743
403 Forman Samuel [5] 716-636-9626
405 Darcy Louis H [26] 716-688-5534
406 Minich Mary ..716-688-4097
408 Mangold Clarita F [5]
411 Mistretta Jennie
416 Ingersoll Barbara A 716-639-8246
417 Goldfarb Vivian [2] 716-688-4117
418 Webber Joan M
422 Coker Carmella L 716-688-1092
426 Prawel Eugene F [5] 716-565-0899
429 Cyranowski Chester C [49] 716-688-5721

+ PARTRIDGE RUN ENDS

475 Ahl Linda D [23]
Euller Betty J [2] 716-688-2171
Francoforte F J 716-688-0480
Gindt Geraldine [2] 716-688-3989
Grzebielucha Sandra 716-689-3638
Hergert Edna P [2] 716-688-3067
Madill Dorothy 716-688-2279
Majchrzycki G [2] 716-636-1030
Majewicz A 716-689-0480
Manzella Agnes D ..716-639-0851
Mazurowski Frank [2] 716-639-7896
Mierczewski C 716-639-8482
Mureck Frances [2] 716-688-3583
Potter A [2] 716-639-3758
Turnwall Jose L 716-639-8684
119 Zimmer Jeanne [2]
120 Heppel Mamie
122 Moritz Alan G [5]
130 Mikula Irene A [5] ..716-688-4221
141 McQueary Alice [5] 716-689-6202
142 Lopresti Victoria L 716-691-6508
145 Lehner Norma J 716-639-8436
147 Parsons Virginia C [5]
148 Brown Geoffrey L [15] 716-688-7467
148 Brown Joan M 716-688-7467
215 Fitzgerald Sandra A [5] 716-689-6861
217 Cortelli Josephine C
219 Loporto Nancy L 716-688-6590

Get Mailing L

Target Street	Cross Street	Source
-	✓	Polk's City Directory

JOHN J AUDUBON PKWY 2008



JOHN JAMES AUDUBON PKWY
Cont'd

221 Ⓓ Warren Charlotte A
-4079 716-636-0023
223 Ⓓ Borman Alice B
-8078 716-688-1320
228 Ⓓ Broeneman Thelma
-2714 716-636-0773
231 Klaich Sylvia A [2]
-7419 716-639-8580
242 Wesp Gertrude M [15]
-5544 716-688-5592
244 Ⓓ Godfrey Helen J
.....716-689-9645
-3782 245 Giglia Joseph [5]
.....716-689-9539
-4964 245 Giglia Angela A ..716-689-9539
246 Ⓓ Picone Josephine D
.....716-688-0586
-4977 247 Milazzo Joan Y [5]
500 AMHERST ANIMAL CONTROL
-5956 government offices ..716-689-1311
AMHERST FIRE DEPT fire
-5566 departments 716-689-1212
AMHERST POLICE DEPT police
-2337 departments 716-689-1322
501 DORN JOHN W attorneys
-4361 716-688-3800
Ferber Gabriel J [11]
JOHNSON WILLIAM P attorneys
.....716-688-3800
-6213 KANICK & CO business mgmt
-6213 consultants 716-651-0111
M J PETERSON CORP apartments
-4186 716-688-1234
M J PETERSON REAL ESTATE real
-2396 estate 716-689-7800
-0602 MARK IV INDUSTRIES INC
marketing programs & serv
-8827 716-689-4972
NESPER FERBER & DI GIACOMO
attorneys 716-688-3800
-4161 O'Connor Timothy W [4]
-4161 716-636-1800
OLDE TOWNE VILLAGE APTS
-1018 apartments 716-689-6006
ROBSON & WOESE INC fire
protection consultants
-0316 716-636-1800
SUNDRIDGE APTS apartments
-4909 716-689-6006
TRUEMAN-MALIN mgmt training
-6743 716-204-3550
+ BRYANT WOODS N BEGINS
-9626 **BUSINESSES 76** **HOUSEHOLDS 143**

-5534 **JOHN MUIR DR (BUFFALO)**
+ SYLVAN PKWY ENDS

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAPLE RD 2008

MAPLE RD Cont'd — *MAPL*

-0820 394 Trzeciak Irene T ..716-688-7158
-7493 398 Weber Frances S [15] 4060
-7493 ..716-634-0311
399 Barish Phyllis R [25]
-1649 ..716-639-8213 4080
2351 CITIZENS BANK banks
-4925 ..716-634-4970
TOPS MARKET LOANS loans 4100
-5223 ..716-634-2768
2383 MARSHALLS department stores
-3936 ..716-810-0980
2391 CLASSIC CLEANERS cleaners 4110
-4097 ..716-631-5720
+ TRANSIT RD INTERSECTS
-9743 *• ZIP CODE 14226 CAR-RT C032*
3908 COLLEGE STORE book dlrs-whol
-0309 ..716-332-3040
3910 RED PEPPER CHINESE- 4125
-0309 VIETNAMESE restaurants
..716-831-3878 4150
-2989 3912 FEEL-RITE FRESH MARKET
health & diet foods-retail 4185
-2989 ..716-834-3385
3920 DENNY'S restaurants 4220
-6649 ..716-446-1671
3931 FIRESTONE COMPLETE AUTO 4224
-6649 CARE tire-dlrs-retail ..716-837-7721
L Fisher Todd [2]
-2959 J C PENNEY OPTICAL optical
arete goods- retail ..716-833-1166
-0187 LAUX SPORTING GOODS INC
tennis equip/supl- retail
-1059 ..716-832-2774
PLUM GOLD jewelers-retail
-8967 ..716-832-5118
+ ALBERTA DR INTERSECTS
-2651 3951 OLIVE GARDEN ITALIAN RSTRNT
restaurants ..716-837-5211
-0381 3980 DI VENCENZO ROBERT F MD
physicians & surgeons
-2951 KEY BANK banks 716-834-4065
MARTIN'S FOOD MARKET grocers- 4229
-0131 retail ..716-515-0077
TIM HORTON coffee shops 4231
-0131 ..716-446-9730
aret TOPS FRIENDLY MARKET
-8447 grocers-retail ..716-515-3215
-2250 TOPS MARKETS grocers-retail
..716-515-0075
-7092 WESTERN UNION money transfer
serv ..716-515-0076 4233
-4389 3999 SCOTCH 'N SIRLOIN
RESTAURANT restaurants
-5858 ..716-837-4900
• ZIP CODE 14226 CAR-RT C047
-2352 4001 JENSS DECOR department stores
..716-837-1100
-0139 REEDS JEWELERS INC jewelers-
retail ..716-837-3934
-9027 4003 IHOP RESTAURANT restaurants
..716-446-1117
-0906 Karvounaris Maureen F
4010 RED LOBSTER restaurants
-4129 ..716-837-0202 4239
4033 FRONTIER SCIENCE &
-8653 TECHNOLOGY medical research
..716-834-0900
-6767 4043 COLOR COMMUNICATIONS INC
printers ..716-838-0698 4241
5959 100 H J HILL TAX & ACCOUNTING
SVC tax return preparation/filing
-1501 106 ADVANCED STORAGE 4243
TECHNOLOGY storage- liquid &
-0910 bulk ..716-833-6212 4245
-0583 107 UNIVERSITY PSYCIATRIC
physicians & surgeons
..716-835-1246
108 KIRST COMMERCIAL REAL 4247
ESTATE real estate ..716-836-8200
7576 203 MARSH PLASTICS INC
plastics- raw mtrls/powder/resi
9415 ..716-834-6500
9415 204 GRAYTON CO INC advertising
..716-835-5041 4249
9420 211 E M SYSTEMS INC computer
software ..716-836-4910
9420 4050 WENDY'S restaurants
..716-832-0855 4258
3829 4053 COMIX CAFE restaurants
..716-833-0838 4276
0904 Dobbins Terrence L
2320 PARK LANE CONSTRUCTION 4291
construction companies
..716-836-6790
8035 SOUNDCORE INC concrete
products ..716-833-7651
2473 105 M ORFI ARCHITECT INC
architects ..716-833-1337 4300
3941 110 LEUKEMIA & LYMPHOMA
SOCIETY social serv & welfare org 4330
7582 ..585-263-2440
200 BENCHMARK FINANCIAL
7582 GROUP INC real estate developers 4350
0004 ..716-833-4986
200 Gellman Bodil K [19]
2198 200 Gellman Arthur M

riber. Use of this directory is subject to the Ter
n updated directory call 1-800-275-7655 or www

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAPLE RD 2008



♠HOMEOWNER

MAPLE RD Cont'd

200A CONBOW CORP bowling centers 716-833-4934

4060 KYOTO JAPANESE RESTAURANT restaurants 716-836-6688

4080 RED ROBIN GOURMET BURGERS restaurants 716-834-4100

4100 DSW SHOE WAREHOUSE shoes-retail 716-835-0497

LINENS 'N THINGS housewares-retail 716-862-4513

4110 COLD STONE CREAMERY ice cream parlors 716-204-5963

EMPIRE VISION CTR INC opticians 716-831-8050

ORECK vacuum cleaners-household-dlrs 716-833-3444

4125 UNO CHICAGO GRILL restaurants 716-834-6200

4150 SWEET HOME MIDDLE SCHOOL schools 716-250-1450

4185 BOSTON MARKET restaurants 716-834-2320

4220 VALUE CITY FURNITURE furniture-dlrs- retail 716-833-5794

4224 EXECUTIVE FOOD GROUP food products- retail 716-836-9241

LEON STUDIO ONE EVOLUTION SLN beauty salons ..716-862-0068

SPOILED SALON & SPA beauty salons 716-803-1122

Weiner Kenneth M [2] 716-833-1047

100 OFFICE MAX office supl 716-862-6660

108 SUBWAY restaurants 716-832-4905

110 ALDO'S UOMO men's clothing & furnishings 716-834-3378

112 LENS CRAFTERS optical goods- retail 716-833-0803

4229 Carrol Clifford [2]

Kaplan Richard D [2]

4231 AMHERST SURGICAL ASSOC physicians & surgeons 716-837-9111

Buckley Richard J Jr [4] 716-837-9111

Rainstein Miguel A [4] 716-837-9111

4233 DEVANS BETH A nurses-practitioners 716-836-3188

HYPERTENSION RESEARCH PROGRAM physicians & surgeons 716-838-3188

NEPHROLOGY ASSOCIATES physicians & surgeons 716-838-3188

RYAN JAMES E MD physicians & surgeons 716-838-3188

SCIME-CORMIE DOROTHY M nurses- practitioners 716-838-3186

4239 GENTILE JOSEPH D MD physicians & surgeons 716-832-9747

SIELSKI LESTER S MD physicians & surgeons 716-835-2984

4241 AMERIPRISE FINANCIAL financial planning consultants 716-831-8944

4243 MAPLE DENTAL dentists 716-833-4637

4245 Malik Tariq S [7]

Malik Farah F

TRAVEL HOUSE INTL INC airline ticket agencies 716-835-2141

4247 CUKIERMAN JACK MD physicians & surgeons 716-835-9871

HAQUE SHAHID MD physicians & surgeons 716-835-9871

KALEIDA HEALTH laboratories-medical 716-836-8359

4249 DALY RICHARD F attorneys 716-835-2200

SIEGEL KELLEHER & KAHN attorneys 716-834-5800

4258 TACO BELL restaurants 716-833-8332

4276 MAPLE RIDGE B video tape editing 716-833-9545

4291 ERIN & BILL'S AUTOMOTIVE auto rpr & serv 716-836-7500

EXPERT AUTO GLASS INC glass coating & tinting 716-831-0074

SUNOCO serv stations- gasoline & oil 716-836-6100

4300 FUDDRUCKERS restaurants 716-832-5360

4330 FPAG FINANCIAL PLANNING financial planning consultants 716-691-6700

4350 FRIENDLY'S RESTAURANT restaurants 716-835-2662

PONDEROSA STEAKHOUSE restaurants 716-838-3182

Target Street	Cross Street	Source
-	✓	Polk's City Directory

SWEETHOME RD 2008



948 Abbarno Joseph P & Leigh A 18 ♠ 716-835-3878
956 No Current Listing
965 Brummer John F & Judith A 20 ♠ 716-834-3185
966 NORTH BAILEY FIRE CO halls & auditoriums 716-836-9571
+ HOMECREST DR BEGINS
+ HOMECREST DR BEGINS
1006 Harbison John J & Emily 45 ♠ 716-837-6878
1011 Tibung Jesus D 5 ♠ 716-834-7861
Tibung Zenaida 716-834-7861
1012 Walsh Kim M 12
1015 No Current Listing
+ MAPLE RD INTERSECTS
• ZIP CODE 14226 CAR-RT C047
1185 ABIOLA ADEBUKOLA O MD physicians & surgeons 716-689-0040
AMHERST MEDICAL GROUP health maintenance org 716-689-0040
BARTELS MATTHEW F MD physicians & surgeons 716-689-0040
HEALTH CARE PLAN physicians & surgeons 716-689-0040
LEILABADI SHAHRIYAR A MD physicians & surgeons 716-689-0040
Lonny Walter
MCGRATH KIMBERLY A physicians assistants 716-689-0040
NOUKLA SHAHERA MD physicians & surgeons 716-689-0040
NYLANDER EMMEKUNLA MD physicians & surgeons 716-689-0040
PACZOS TAMERA A MD physicians & surgeons 716-689-0040
PAULUS IRENE MD physicians & surgeons 716-689-0040
PETERSON JOHN MD physicians & surgeons 716-689-0040
SAVOY NANCY A nurses-practitioners 716-689-0040
STOUTER BARBARA S MD physicians & surgeons 716-689-0040
VIENNE JR RICHARD P DO physicians & surgeons 716-689-0040
WILLIAMS EMILY MD physicians & surgeons 716-689-0040
WU PAUL MD physicians & surgeons 716-689-0040
YOST MURRAY MD physicians & surgeons 716-689-0040
ZIEGLER SHARON L MD physicians & surgeons 716-689-0040
• ZIP CODE 14228 CAR-RT C065
1260 JOHN SHAFLUCAS ARCHITECTS architects 716-636-5000
Shaflucas John W 10 ♠
Shaflucas Sandra
+ RENSCH RD ENDS
+ RENSCH ENTRANCE INTERSECTS
1400 CARROLL FINANCIAL SVC INC financial planning consultants 716-876-0806
HNAT FAMILY CHIROPRACTIC chiropractors dc 716-689-5919
1400 PHOENIX RISING MEDICAL PC psychologists 716-836-1388
+ RENSCH RD CONTINUES
SCHROEDER BRAXTON & VOGT financial advisory serv 716-634-6113
1 LEGACY QUEST LLC financial advisory serv 716-204-9048
2 RITCHIE STRAFFORD D attorneys 716-639-4400
5 SLEEP & WELLNESS CTR psychologists 716-691-6283
8 C D FINANCIAL INC financial advisory serv 716-929-6550

STREET GUIDE

irectory.com

Target Street	Cross Street	Source
-	✓	Polk's City Directory

SWEETHOME RD 2008

SWEET HOME RD - SWEETWOOD DR

SWEET HOME RD Cont'd

10 HEALTHY TRANSFORMATIONS holistic practitioners 716-688-1825
10 MITCHELL MARGARET MD physicians & surgeons 716-688-1825
1404 AFLAC insurance 716-213-0859
HAHN & ASSOC LLC sales promotion serv 716-564-2131
Huber Bernard A [2] 716-634-0566
1 RGIS INVENTORY SPECIALISTS inventory serv 716-636-4912
2 RICOTTA & ASSOC psychologists
2 Ricotta Philip F [4]
5 Obrien Callista
5 UNIVERSITY PEDIATRIC ASSOC physicians & surgeons 716-639-9360
8 SHOWCASE SPORTS MEMORABILIA baseball sports cards/memorabi 716-625-7410
8 Weinstein Bruce [2]
9 LASERTONE computer parts & supl 716-636-5036
11 SANDLER SALES INSTITUTE sales training
12 UNIVERSITY WEALTH MANAGEMENT investments 716-213-0080
1408 JAMYA INC computer software 716-565-9114
NATURAL HARMONY HOLISTIC weight control serv ..716-204-2999
TAYLOR LINDA ANN nurses-practitioners 716-204-9299
7 LAB CORP laboratories- medical 716-636-0174
8 US SIGNS signs ..716-689-7000
9 BUFFALO INFUSION CTR-NORTH physicians & surgeons 716-204-4261
11 PACMA INC marketing consultants 716-626-1030
12 RAJPUT SUNITA M DO physicians & surgeons 716-625-4500
1412 NORNEW INC oil/gas exploration/ developmen 716-568-2048
SWEET HOME FAMILY MEDICINE PC physicians/surgeons info burea 716-636-7800
USEN JOSHUA M MD physicians & surgeons 716-636-7800
5 NARBY GEORGE M MD physicians & surgeons 716-689-2012
6 KARASZEWSKI BRIAN MD physicians & surgeons 716-688-1412
7 Narby George M
1434 Allen Michele L [11]
1436 Robbins Joseph A Jr [4]
+ RENSCH ENTRANCE INTERSECTS
1544 Taylor James A [2]
1554 No Current Listing
1576 ACADEMIC MANAGEMENT SYSTEMS fuel mgmt 716-204-0464
AEROSTAR GROUP computer software 716-636-9620

Target Street	Cross Street	Source
-	✓	Polk's City Directory

JOHN J AUDUBON PKWY 2004

.....716-564-1154
+ COMMERCE DR INTERSECTS
BUSINESSES 6 HOUSEHOLDS 1

JOHN JAMES AUDUBON PKWY (AMHERST)
• ZIP CODE 14228 CAR-RT C061
1 ALLEN LISA A attorneys 716-636-7600
CARDAMONE-SCHU JENNIFER
attorneys 716-636-7600
CIOCCA STEPHEN C attorneys
.....716-636-7600
ENNIS-BUONOCOR COLLEEN
attorneys 716-636-7600
HARRIENGER TRACY S attorneys
.....716-636-7600
HOGAN & WILLIG attorneys
.....716-636-7600
LICATA JOHN B attorneys
.....716-636-7600
MAHONEY KEVIN S attorneys
.....716-636-7600
TINNEY CAROLYN L attorneys
.....716-636-7600
TIVERON DIANE R attorneys
.....716-636-7600
VIRTUAL REALTY USA real estate
.....716-688-1991
10 BESTRY SHERWOOD L attorneys
.....716-688-1600
COMDOC INC duplicating mach & supl
.....716-689-0202
LILLIS TARA B attorneys
.....716-636-9181
NATIONAL FIRE ADJUSTMENT CO
adjusters-public 716-689-7700
C GOLDHABER RESEARCH ASSOC
market research & analysis
.....716-689-3311
101 AMERICAN CANCER SOCIETY
associations 716-689-6981
140 AUDUBON EXPORT INC exporters
.....716-689-5400
CM CHAIN hoists 716-689-5400
CM INDUSTRIAL PRODUCTS
industrial equip/supl-mfrs
.....716-689-5400
CM INSURANCE CO INC insurance
.....716-689-5400
COLUMBUS MC KINNON CORP
hoists-mfrs 716-689-5400
CRANE ENGINEERING & SVC GRP
hoists-mfrs 716-689-5400
GAFFEY INC hoists-mfrs
.....716-689-5400
SPRECKLES CONSOLIDATED IND
hoists-mfrs 716-689-5400
SPRECKLES DEVELOPMENT CO
INC hoists-mfrs 716-689-5400
SPRECKLES LAND CO INC hoists-
mfrs 716-689-5400
SPRECKLES WATER CO INC
hoists-mfrs 716-689-5400
YALE INDUSTRIAL PRODUCTS
INC industrial equip/supl-mfrs
.....716-689-5409
151 NATIONAL TRAFFIC SVC freight-bill
audit 716-636-8253
200 DUNLOP TIRE CORP tire-distributors
.....716-639-5200

ectory.com

Target Street	Cross Street	Source
-	✓	Polk's City Directory

JOHN J AUDUBON PKWY 2004



JOHN JAMES AUDUBON PKWY - JUDITH DR

JOHN JAMES AUDUBON PKWY Cont'd

JAMES MANAGEMENT CO real estate 716-689-3368
KIDENEY ARCHITECTS architects 716-636-9700
NC INDUSTRIES INC mfrs 716-689-8400
NIAGARA CUTTER INC mach tools-mfrs 716-689-8400
VOCAL TECHNOLOGIES LTD engineers- electrical 716-688-4640
251 ICT GROUP INC telemarketing serv 716-636-2000
331 COMPUTER SEARCH CORP payroll preparation serv 716-689-0511
350 AMHERST PUBLIC LIBRARY libraries-public 716-688-4919
370 AMHERST CENTER-SENIOR SVC government offices ..716-636-3050
500 AMHERST ANIMAL CONTROL government offices ..716-689-1311
AMHERST FIRE DEPT fire departments 716-689-1212
AMHERST POLICE DEPT police departments 716-689-1322
501 FIDDLER & CO accountants 716-688-4343
M J PETERSON CORP real estate 716-688-1234
MARK IV aircraft components-mfrs 716-689-4972
MERGLER JOSEPH H accountants 716-688-4343
NESPER FERBER & DI GIACOMO attorneys 716-688-3800
PARK VIEW MANOR apartments 716-689-6006
ROBSON & WOESE INC engineers-consulting 716-636-1800
SUNDRIDGE APTS apartments 716-689-6006

BUSINESSES 51

JOHN JAMES AUDUBON PKWY (BUFFALO)
• ZIP CODE 14228 CAR-RT C061
1 CARLY WILSMAN ATTORNEY
attorneys 716-632-2852

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAPLE RD 2004



3908 COLL 716-332-3040
+ ALBERTA DR INTERSECTS
3980 TOPS FRIENDLY MARKET grocers-retail 716-515-0080
+ N BAILEY AVE INTERSECTS
• ZIP CODE 14226 CAR-RT C047
4001 REEDS JEWELERS INC jewelers-retail 716-837-3934
4043 MUSCO FAMILY OLIVE CO mfrs-agents & representatives 716-832-4770
4053 200 (N) Bohicket Marina
+ HILLCREST DR INTERSECTS
4224 ALDO'S UOMO men's clothing & furnishings 716-834-3378
COPY MAX copying & duplicating serv 716-831-0396
DAKOTA GRILL restaurants 716-834-6600
DE NORE LIMITED clothing-retail 716-832-0288
LEON STUDIO ONE EVOLUTION SLN beauty salons ..716-862-0068
OFFICE MAX office supl 716-862-6660
SPOILED SALON & SPA beauty salons 716-803-1122
SUBWAY SANDWICHES & SALADS restaurants 716-832-4905
112 LENS CRAFTERS optical goods- retail 716-833-0803
4239 No Current Listing
4249 JOHNSTON JR HERBERT R attorneys 716-834-5806
SIEGEL KELLEHER & KAHN attorneys 716-834-5800
4276 No Current Listing
+ SWEET HOME RD CONTINUES
+ SWEET HOME RD INTERSECTS
4300 FUDDRUCKERS restaurants 716-832-5360
+ CORPORATE PKWY INTERSECTS

716 DESSERT DELI wedding supl & serv 716-688-5656
720 BLOCKBUSTER VIDEO video tapes & discs 716-689-2115
727 ROBO SELF-SERVE car washing & polishing 716-689-2225
736 FUJI GRILL restaurants 716-632-2789
777 3 AMHERST RADIOLOGY physicians & surgeons 716-688-619
3 DIAGNOSTIC X-RAY SVC INC physicians & surgeons 716-634-208
781 ALL SAINTS EPISCOPAL CHURCH churches 716-632-07
790 STURBRIDGE VILLAGE APARTMENTS apartments 716-688-2
800 DIVOTS SPORTS GRILL restaurar 716-688-1
FOUR SEASONS nonclassified establishments 716-688-9
• ZIP CODE 14221 CAR-RT C039
811 ADVANCED COSMETIC SURGE CTR physicians & surgeons 716-626-
BUFFALO PLASTIC SURGERY physicians & surgeons 716-626-
821 KVS INFORMATION SYSTEMS computer software ..716-626-
• ZIP CODE 14221 CAR-RT C054
830 CHRISTOPHER'S FAMILY RESTRNT restaurants 716-636
840 7-ELEVEN convenience stores 716-68
• ZIP CODE 14221 CAR-RT C039
851 MAPLE WEST ELEMENTARY SCHOOL schools 716-62
• ZIP CODE 14221 CAR-RT C054
870 TIM HORTONS doughnuts 716-63

Get Mailing Lists, Sales Leads, and E

Target Street	Cross Street	Source
-	✓	Polk's City Directory

SWEETHOME RD 2004

-2510 ♠ 716-835-2054
-2510 868 No Current Listing
872 Rowley Richard S & Katrina [2]♠
-1561 716-862-0683
876 Heimiller Francis L & Lila D [20]♠
♠ 716-832-4345
-0804 884 Wagner Lyn L [14]♠ ..716-862-0720
-4108 885 McDonnell William J [20]♠
[20] 716-835-8905
-0745 892 Bonati Roy F Jr & Maria A [17]♠
.....716-832-1361
+ EMERSON DR ENDS
-4511 922 - 926 No Current Listing (2 Hses)
938 Ⓟ Besant Julia F
-2285 Kerkeslager Jason L & Patrice A [10]
-2285 ♠ 716-837-9305
946 Burkard Keith M & Kathleen A [20]♠
948 Abbamo Joseph P & Leigh A [14]♠
-2285 716-835-3878
956 Gelb Gloria M [20]♠ ..716-834-6508
-1159 965 Brummer Judith A & John F [16]♠
.....716-834-3185
-1937 966 NORTH BAILEY FIRE CO halls &
-1937 auditoriums 716-836-9571
-0114 + HOMECREST DR BEGINS
-9287 + HOMECREST DR BEGINS
-9287 1005 Harbison John J & Emily [20]♠
-7557 716-837-6878
-7557 1011 Tibung Jesus D [2]♠
♠ 716-834-7861
-1762 1012 Furman Jason G [8]♠
Furman Kim W
1015 No Current Listing
-9916 + RENSCH RD ENDS
+ RENSCH ENTRANCE INTERSECTS
• ZIP CODE 14228 CAR-RT C065
-3956 1400 HNAT FAMILY CHIROPRACTIC
-9426 chiropractors dc 716-689-5919
♠ PHOENIX RISING MEDICAL PC
-8329 clinics 716-688-0088
-5689 ST JUDE MEDICAL clinics
-5689 716-688-5400
5 ASSOCIATED SLEEP CTR
♠ psychologists 716-691-6283
-7351 1404 Ⓟ Ricotta Philip F
9 LASERTONE computer parts &
supl 716-636-5036
12 RITCHIE STAFFORD
-5981 ATTORNEY attorneys
.....716-639-4400
-1430 1434 Allen Michele L [7]
[8]♠ 1436 No Current Listing
-4502 1544 Feinstein Lori D [8] 716-691-2651
1554 Wagner April A & Eric L [8]
-4161 716-564-0803
-4161 + RENSCH ENTRANCE INTERSECTS
1576 ACADEMIC MANAGEMENT
-4681 SYSTEMS mgmt serv
-7450 716-204-0464
AZTECH INC market research &
es analysis 716-833-7870
-6565 COUNTERPOINT SYSTEMS
[2]♠ nonclassified establishments
-7766 716-688-2466
GSE COMMUNICATIONS video
-7665 production & taping serv
-7665 716-639-0280
+ BAIRD HALL BEGINS
-8458 + BAIRD HALL CONTINUES
+ CHESTNUT RIDGE RD INTERSECTS
-0429 1608 Manning Charles E [7]
1 See Tung K [3]
-5682 2 - 4 No Current Listing (3 Apts)

2446
+ DOD
+ DOD
2493
+ COM
+ COM
2550
2551
+ SUN
2575
2581
2587
2593
2599
2605
2611
2617
2623
2629
2635
2641
• ZIP C
2661
2671
2685
2690
2695
2705
2710
2712
2715
2725
2735
2745
+ FRE
+ N FR
+ FRE
+ N FR
+ FRE
+ N FR
• ZIP C
2800

her Polk City Directories @ www.citydirectory.com

Target Street	Cross Street	Source
-	✓	Polk's City Directory

JOHN J AUDUBON PKWY 1998



Target Street	Cross Street	Source
-	✓	Polk's City Directory

JOHN J AUDUBON PKWY 1998



■ HOMEOWNER

JOHN JAMES AUDUBON PKWY

Killian Marion B ♠
PRUDENTIAL ins agts/svcs 636-7625

TRANSMRICA FNCL SERVICES
CAL CORP ins agts/svcs 636-8456

+N FOREST RD CONTINUES

10 BESTRY SHERWOOD L legal svcs 688-1600

COMDOC elec parts equip 689-0202

Goldhaber Gerald M [2]+ ♠

LEITER MARK A legal svcs 636-7827

101 AMERICN CANCER SOCEITY NEW YORK STATE DIVISION social svcs 689-6981

+SYLVAN PKWY ENDS

140 ACRES INTERNATIONAL CORP eng svcs 689-3737

C M HOIST DIVISION hsts cranes monor 689-5400

151 NATIONAL TRAFFIC SERVICE busn consltng 636-8253

200 ABACUS COMPUTER TECHNOLOGY data proc schs 689-3100

BUFFALO STRUCTURAL STEEL fbrcted strctrl mtl .. 639-7714

DUNLOP TIRE CORP tires inner tubes 639-5200

ELLIS & JOHNSON ATTYS AT LAW legal svcs 689-8837

FIRST UNION HOME EQUITY BANK loan brokers 689-0655

HANOVER INSURANCE COMPANY THE ins agts/svcs . 564-0020

IMPACT MARKETING SERVICES drgs prprtrs sndr .. 639-9705

JAMES MANAGEMENT COMPANY real est agts/mgrs . 689-3368

METRO PLASTICS plstc mtrl bsc shp 636-1717

N C INDUSTRIES machine tool accs 689-8400

Tanaka Yashushi

251 ICT GROUP commrcl nphys rsrch 636-2000

331 COMPUTERSEARCH CORP data proc 689-0511

+PARTRIDGE RUN BEGINS

350 AMHERST PUBLIC LIBRARY libraries 689-4922

411 PRUDENTIAL INSURANCE OF AMERICAN ins agts/svcs 636-1960
Woomer Warren J [3]

+DODGE RD INTERSECTS

500 AMHERST TOWN OF ANIMAL CONTROL animal specity svcs 689-1352

501 FIDDLER & COMPANY acctng audtng bkp 688-4343

FIDDLER & COMPANY LLP acctng audtng bkp 689-2500

LUMINATOR DIVISION hshld audio vdeo 689-4972

PETERSON JAY real est agts/mgrs 689-7800

ROBSON & WOESE eng svcs 636-1800

Tablie Nabih Y

WESTCHESTER PARK ASSOCIATES apmnt bldg oprtrs 688-1234

WILLIMSVILLE ROTARY FOUNDATION civic social assns 853-5200

BUSINESSES 32 HOUSEHOLDS 5

JOHN MUIR DR (BUFFALO)-FROM 2339 N FOREST RD NORTH

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAPLE RD 1998



636-5973
2375 PETWISE misc rtl strs..... 631-5911
2385 DISCOVERY ZONE amusement rcrtn..... 633-0033
+PALMDALE DR ENDS
+TRANSIT RD INTERSECTS
+GREINER RD BEGINS
+BRIGHTON RD ENDS
- ZIP CODE 14226 CAR-RT C032
3900 Taylor Thomas P
TAYLOR ED LINCOLN MERCURY new used car dlrs 838-2600
3902 PAPER FACTORY THE gift shop 836-5831
3908 REPP BIG & TALL mens/boys clothing..... 837-2753
3912 FEEL RITE misc food stores 834-3385
3920 PERKINS FAMILY RESTAURANT eating places 837-0296
3931 BRIDGESTONE/FIRESTONE auto home sppl str..... 837-7721
3951 OLIVE GARDEN ITALIAN RESTAURANT eating places 837-5211
3980 TOPS FRIENDLY MARKETS grocery stores..... 834-2955
3999 SCOTCH & SIRLOIN RESTAURANT eatng places..... 837-4900
- ZIP CODE 14226 CAR-RT C047
4003 CHI-CHIS eating places.... 834-2281
+N BAILEY AVE INTERSECTS
4010 RED LOBSTER eating places 837-0202
4023 AMERICAN STATES INSURANCE ins agts/svcs..... 837-2950
200 PAYCHEX acctng audtng bkp 838-5702
4033 Not Verified
4033 206 FRONT SCNC/TECH RSCH ncmrcl rsch orgnztn..... 834-0900
4043 EMPIRE BOTTLE COMPANY indus supl..... 832-5555
MARYLAND INSURANCE COMPANY ins agts/svcs 834-4627
TWELVE THREE MARKETING comp rltd svcs 837-5727
111 RODKE AGENCY ins agts/svcs 837-3800
112 SCOTT WILLIAM ARCHITECT PC architectural svcs 835-3327
203 MARSH PLASTICS plstc mtrl bsc shp 834-6500
204 GRAYTON COMPANY mgmt cnsltng svcs 835-5041
4053 CONBOW CORP bowling centers 833-4934
M ORFI ARCHITECTS PC architectural svcs .. 833-1337
Orfi Magued M
WARD NORTH AMERICA ins agts/svcs 834-0752
102 ARBYS ROAST BEEF RESTAURANT eating places 837-1630
106 ADVANCED STORAGE TECHNOLOGY patent owner lessr 833-6212

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAPLE RD 1998



● HOMEOWNER

MAPLE RD

106 PARK LANE CONSTRUCTION & DEVELOPEMENT sngl-fam hsng cnstr 835-9830

200 BENCHMARK DEVELOPMENT CORP mgmt svcs . 832-2174

200 BENCHMARK MANAGEMENT CORP nrsdntl bldg optrs 833-4986

4060 BENNIGANS eating places 838-3550

4100 UNIVERSITY CINEMA movie theater 837-8374

+HILLCREST DR ENDS

4125 UNO RESTAURANTS eating places 834-6200

4150 SWEET HOME MIDDLE SCHOOL elmntry scndry sch 837-3500

4185 BOSTON MARKET eating places 834-2320

4220 SERVICE MERCHANDISE misc gnrl mrch strs 837-7040

4224 ALDOS UOMO mens/boys clothing 834-3378

Capuson Stephen E ⓩ ●

DAKOTA GRILL eating places 834-6600

DENORE womens clothng strs 832-0288

LENSCRAFTERS optical gds stores 833-0803

OFFICEMAX statnry ofc suppl 862-6660

112 WEINER optmtrst 833-1046

4225 HYPERTENSION RESEARCH PROGRAM hlth alld svcs 838-1295

4227 Slepian Barnett A ⓩ

SLEPIAN BARNETT A medical clinic 834-6796

4229 GASTROENTEROLOGY ASSOC OF WESTERN NEW YORK medical clinic 828-3420

4231 AMHERST SURGICAL ASSOCIATES PC medical clinic 837-9111

4233 STOVROFF & POTTER REAL ESTATE real est agts/mgrs 838-6074

4239 GENTILE JOSEPH MD PC medical clinic 832-9747

SIELSKI LESTER S MD PC medical clinic 835-2984

4241 PILGRIM RECYCL & ENVIRONMENTL SERVICE busn consltng 832-2422

4243 LA MASTRA MICHAEL S ofcs clns of dntst 833-4637

Lamastra Zulah S ⓩ ●

MAPLE DENTAL ofcs clns of dntst 833-4639

4245 TRAVEL HOUSE INTERNATIONAL OF WESTERN NEW YORK travel agcy 835-2141

4247 CUKIERMAN JACK medical clinic 835-9871

4249 DALY RCHARD F ATTY AT LAW legal svcs 835-2200

4265 NOCO MOTOR FUELS grocery stores 837-8479

4276 JOHNNY BS SODA BAR & CAFE eating places 838-1950

RE/MAX EXCELLENCE real est agts/mgrs 833-0100

4291 AMHERST AUTOMOTIVE auto rpr 834-7800

HERSHERER SUNOCO gas stations 836-6100

4300 FUDDRUCKERS eating places 836-3683

4350 HOOTERS eating places .. 833-0856

PONDEROSA STEAKHOUSE eating places 838-3182

4400 ⓩ Covert William J

MOTEL 6 hotels & motels 834-2231

+RAILROAD CROSSES

+FLINT RD INTERSECTS

4641 CEDERS SERVICE CENTER gas stations 688-1140

U HAUL COMPANY truck rntl 689-4012

BUSINESSES 172 HOUSEHOLDS 733

MAPLE RD (EAST AURORA)-FROM 243

Target Street	Cross Street	Source
-	✓	Polk's City Directory

SWEETHOME RD 1998



Geib Gloria M 834-6508
965 (N) Brummer John F 834-3185
Shields Paul W [3] 832-2097
966 NORTH BAILEY VOLUNTEER FIRE COMPANY fire protection 836-9571
+ *HOMECREST DR INTERSECTS*
1005 Harbison John J [9]+ ☗ 837-6878
1011 Hastings William P Jr & Deborah [7] ☗ 835-3018
1012 (N) Morin Stephen 834-2402
1015 Trbovich Thomas D [8] ☗ . 837-6915
1101 DELICATE DESIGNS mfg industries 832-7770
1185 AIMHERST medical clinic . 689-0040
HEALTH CARE PLAN COMPANY ins agts/svcs 668-3600
C HMO HEALTH CARE SERVICES medical clinic 689-3488
+ *MAPLE RD INTERSECTS*
+ *RENSCH RD ENDS*
· ZIP CODE 14228 CAR-RT C055
1434 Not Verified
1436 Trombetto Nicholas M & Shelly [7] ☗ 636-4744
1544 Woodward Michael J [2]+ ☗ 636-8408
1554 Rapp Michael J [2] 688-5531
1576 BIOLYNE commrcl phys rsrch 639-7420
BION TECHNOLOGIES refuse systems 639-0448
INTEGRAL INFORMATION SYSTEMS cstm cmptr prgmg sv 636-6007
KANTI TECHNOLOGIES busn consltng 636-8356
LASER PHOTONICS TECHNOLOGY commrcl phys rsrch 688-8251
(N) Murzynski Jennifer L ONY phrmctcl preprtns.... 636-9096
VOCAL TECHNOLOGIES eng svcs 688-4675
WESTERN NEW YORK TECH DEVELOPMENT social svcs 636-3626
214 WHAT SOFTWARE cstm cmptr prgmg sv 639-9428
1608 (N) Butera C A 691-8201
(N) Harris R 636-6046
(N) Montesanti David 639-9020
(N) Montesanti Jackie 639-9020
(N) Soto Leandro 568-9401
(N) Su Liam 636-6880
1 Sterk Linda K [4] 688-7911
3A (N) Rey Jay C
4A Not Verified

Target Street	Cross Street	Source
-	✓	Polk's City Directory

JOHN J AUDUBON PKWY 1992



• COMMERCE DR INTERSECTS
15 BUSINESSES

433

JOHN JAMES AUDUBON PKWY (AMHERST)–FROM 2401 N FOREST RD NORTH

• ZIP CODE 14068
• N FOREST RD INTERSECTS
1 Building
Suites
1 PRUDENTIAL INSURANCE ins 636-0650
2-1 Vacant (2 Businesses)
210 HOGAN COREY J & ASSOCAITES lwyrs 636-7600
• SYLVAN PKWY INTERSECTS
101 AMERICAN CANCER SOCIETY org welfare & relief 689-6981
140 COLUMBUS MC KINNON CORP chain mfrs 689-5400
ACRES INTERNATIONAL CORP civ engs 689-3737
151 Vacant
200 EMPBANQUE CENTER
Suites
• 1ST FL
101 EMPBANQUE CAPITAL CORP mtge 689-2090
102 Vacant
103 JAMES MANAGEMENT COMPANY INC 689-3368
103 J R C REALTY CO real est 689-3368
104 First Union Home Equity Corp 689-0655
2d Floor
201-200 Vacant (2 Businesses)
203 PARTNERSHIP LIMITED THE adv agcy 689-2222
204 FINANCIAL COLLECTION AGENCIES colln agcy 639-0091
205-200 Vacant (2 Businesses)
207 Empbanque Capital (Addl Sp)
3d Floor
302 PROCTER & GAMBLE soap & detergent mfrs 689-2801
303 KIDENEY ARCHITECTS 636-9700
305 Hiross corp ofc 689-4181
307 Empbanque (Addl Sp)
251 HONEYWELL INC (BR OFC) 636-1250
BULL WORLDWIDE INFORMATION SYSTEM comp sls & serv 636-1500
331 COMPUTERSEARCH CORP payroll processing-med billing 689-0511
350 TOWN OF AMHERST PUBLIC LIBRARY (main br) 689-4922
400 TOWN OF AMHERST COURT 689-4200
411 PRUDENTIAL INSURANCE 636-1960
500 TOWN OF AMHERST POLICE HEADQUARTERS 689-1311
AMHERST POLICE CLUB INC
TOWN OF AMHERST FIRE DEPT (DISPATCH OFC) 689-1212
• TOWN CENTRE INTERSECTS
• PARTRIDGE RUN INTERSECTS
• DODGE RD INTERSECTS
22 BUSINESSES

433

JOHN MUIR DR (AMHERST)

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAPLE RD 1992

★Wright Hozmer S 689-6014 84
★Zeckhauser lola 689-6309
★Zeitler Wm F 639-0414
East Building 85
-B 2330 SILVER MANE SALON beauty shop
636-1700 90
Vacant 91
MANUFACTURERS & TRADERS
TRUST CO (BR) 689-7702 96
2375 PET WISE pet sups 631-5911 97
2309 TOPS MARKET 633-1283 10
TOPS PHOTO FINISHING 10
TOPS PHARMACY 633-1287 10
WESTERN UNION 633-1283
MAC INSTANT BANKING CNTR 10
• TRANSIT RD INTERSECTS
11

421-A

• SWEET HOME RD INTERSECTS 11
(SS)
4291 SUNOCO MAPLE gas sta 836-6100 12
4300 FUDDRUCKERS RESTAURANT 12
836-3683 12
4350 PONDEROSA STEAKHOUSE
838-3182 13
• NY STATE THRUWAY 13
UNDERPASSES
• FLINT ENTRANCE BEGINS 13
Flint Rd Begins 13
4400 JOURNEY'S END MOTEL 834-2231
4641 CEDER'S SHELL SERV CNTR auto 14
repair shop 688-1140
• MILLERSPORT HWY INTERSECTS 14
397 HOUSEHOLDS
205 BUSINESSES 15

495-A

MAPLE ST (CLARENCE)–FROM 15
6045 LONG ST EAST
16

Target Street	Cross Street	Source
-	✓	Polk's City Directory

SWEETHOME RD 1992

SWEET HOME RD (A)–Contd
• SHERIDAN DR INTERSECTS
• HARTFORD RD INTERSECTS
641 SWEET HOME MASONIC TEMPLE 838-2130
HIRAM LODGE NO 105 (F & AM)
PARISH LODGE NO 292 (F & AM)
AMARANTH HIGHLAND COURT LODGE CHAPTER NO 132
MODESTIA LODGE NO 340 (F & M)
EGGERTSVILLE LODGE NO 1157 (F & AM)
FOX CHRISTOPHER G FOX LODGE NO 1021 (F & AM)
SUBURBAN LODGE NO 1158
SALOME NAOMI CHAPTER 102 ORDER OF EASTERN STAR
PERSERVERANCE LODGE NO 948 (F & AM)
LEVANT BETSY ROSS CHAPTER 695 org benevolent & fraternal
651★Bogue Charisma
663 Dyckman Ruth L [9]+ ◎ 832-1430
671 Terhaar Jas P & Diane L [5] ◎ 832-4502
683 Gerow Robt & Jayne [2] ◎ 833-6740
687★Torre Andrew & Betty J ◎ 837-4161
Torre Carolyn 837-4161
691★Cockrum Clifford
697 DOUBLE D BOOKKEEPING & TAX SERVICE 833-5396
Dabritz Oscar W & Winifred [9]+ ◎ 833-5396
700 TEMPLE BETH ZION school 836-6565
TEMPLE BETH ZION NURSERY SCHOOL 836-6565
727 Dispenza Vincent G & Sylvia [9]+ ◎ 835-7665
735 Scharf Harvey A & Linda M [9]+ ◎
739 Rowland John L & Dorothy E [9]+ ◎ 835-7421
747 Scime Saml C & Nancy C [9]+ ◎ 833-4150
Scime Linda M 833-4150
751 Gibson Robt B & Gwyneth [9]+ ◎ 833-0429
752★Winkler Harry ◎ 836-2332
Winkler Hayra Libel 836-2332
756★Putnam Danl J ◎
760 Mc Coy F J [4] 837-9430
764 Knab Eug J & Rosemary [7] ◎ 833-5317
765 ANDRONICO VINCENT G dentist 832-7765
• NEWGATE RD INTERSECTS
• HILTON INTERSECTS
782 Mudd Richd D & Jacqueline M [6] ◎ 836-8659
788 Cadille Dave M & Jean M [2] ◎
794 Muhr Saml J & Arlene M [9]+ ◎ 833-5046
800 Lee Janet E [9]+ ◎ 837-1127
803 Sykes Frank R Jr & Ruth E [9]+ ◎ 835-1846
Sykes Kevin J 835-1846
Sykes Todd W 835-1846
Sykes Scott F 835-1846
804 Marcinelli Paul J & Ruth E [9]+ ◎ 834-4743
• WOODCREST INTERSECTS
812 Not Verified
816 Dmochowski Thos F [2] ◎
820 Vivian Richd [9]+ ◎ 832-6394
824 Caruso John A & Jenelle M [5] ◎ 833-0206
828 Caro John P & June M [9]+ ◎
830 Not Verified
836 Humbert David & Jeanne M [7] ◎ 834-1861
840 Maranca Maryanne [2] ◎ 831-0125
848 Holden Margt M [5] ◎ 833-9534
852 Princess Edwin E [9]+ ◎ 834-6767
860 Sykes Robt C & Julie M [7] ◎ 834-8219
864 Pietrzyk Steph A & Dorothy [9]+ ◎ 833-5537
Pietrzyk Brian K 833-5537
868 Caro Salvatore & Angela [2] ◎
872 Zack Lena M [9]+ ◎ 832-7330
876 Vacant
Heimiller Frank L & Lila D [9]+ ◎ 832-4345
884 Wagner Wm F & Lynn A [2] ◎ 862-0720
885 Saint Leo the Great R C Ch Rectory 835-8905
Mc Donnell Wm J Rev Msgr [9]+ 835-8905
Kelly John Rev 835-8905
892 Bonati Roy F Jr & Marie [2] ◎ 832-1361
903 SAINT LEO THE GREAT ROMAN CATHOLIC CHURCH 833-8359
SAINT LEO THE GREAT PAROCHIAL SCHOOL 832-6340
• EMERSON DR INTERSECTS
922★Amend
926 Hollands Wm R [9]+ ◎ 833-5472
938 Witucki Al & Elaine B [9]+ ◎ 837-1056
946 Burkard Keith M & Kathleen [6] ◎
948★Klug Anne ◎
956 Geib Theo W & Gloria M [9]+ ◎ 834-6508
965 Brummer John F & Judith [9]+ ◎ 834-3185
Not Verified
966 NORTH BAILEY EXEMPT FIREMAN'S ASSOCIATION 836-9571
NORTH BAILEY FIRE CO volunteer 836-9571
• HOMECREST DR INTERSECTS
1005 Harbison John J & Emily [9]+ ◎ 837-6878
1011 Horton Scott P & Shelly [2] ◎ 862-0253
1012 Blazysnki Brian & Debra D [5] ◎
1015★Atasoy Seymen ◎ 837-5137
Trbovich Thos 837-5137
• MAPLE RD INTERSECTS
• YOUNGMAN HWY OVERPASSES

434-A
• ZIP CODE 14221
• RENSCH RD INTERSECTS
1434 Pempsell Ray C [9]+ ◎ 688-8251
1436 Smith W K & Martha [2] ◎ 689-8643
1544 Fleisch C M [2]
1576 HANFORD BAY ASSOCIATES comp consits 636-0100
R C S CO INC consits 636-3720
A T T O TECHNOLOGY comp mfg 688-4259
BATTERY COMPANY THE battery sls 695-9482
RADAR TEST LABORATORIES radar instr testing 636-3135
P C ASSISTANCE INC consits 636-0997
PRODUCTIVITY MANAGEMENT GROUP INC consits 689-7724
LASER PHOTONICS CO
RECRA ENVIRONMENTAL 691-2613
Bion Technologies Inc environmental testing-planning
E B ASSOCIATES chem & solvent analysis 636-3644
TREE TECHNOLOGIES communications equip 688-4640
Vacant
O N Y Inc pharm mfg 636-0997
CHODOROW ASSOCIATES adv consult 636-0367
CENTER FOR INDUSTRIAL EFFECTIVENESS THE consults 636-2568
Western New York Technology Dev Cntr 636-3626
• CHESTNUT RIDGE RD INTERSECTS
1608 Erickson Olive M [9]+ ◎ 688-7949
• LOCKPORT EXPRESSWAY INTERSECTS
1741 Sweet Home Central Sch Dist 7 (Trans Servicenter) 689-5250
Sweet Home Central Dist No 7 (Kitchen Dept) 689-5255
Sweet Home Central Sch Dist No 7 (bldg & ground dept) 689-5245
1872 Mitchell Robt A Rev & Margt P [2] 689-9848
1900 SWEET HOME UNITED METHODIST CHURCH 688-8677
1901 SWEET HOME SENIOR HIGH SCHOOL 689-5301
Sweet Home Central Sch Dist 689-5251
Sweet Home Central Sch Dist (Bd of Educ) 689-5201

435-C
• SKINNERSVILLE RD INTERSECTS
• NUMBERS IRREGULAR
1949a★Masters Theo 636-0010
1949b★Hwa Steph 689-3729
Rear★Koepsell Eva M 689-9521
1950 Hughes Claude P Jr [9]+ ◎ 688-8374
1957★Frank David ◎
1974 Stumm Rodney C & Susan C [9]+ ◎ 688-1371
1984 Hupf Gerald & Rosemary [9]+ ◎ 691-7932
1991 Not Verified
2001 Sutherland James E & Barbara S [2] ◎ 688-5724
Sutherland Frank 688-5724
2004 Saia Celestine B [9]+ ◎ 688-7617
2021 Hayden Bruce S [9]+ ◎ 688-4946
2031 Gallo Michl & Martha B [9]+ ◎ 688-9230
2034 Bainbridge Larry & Andrea [9]+ ◎ 688-8204
2038 Harbison Wm J & Eliz [9]+ ◎ 688-8820
2071 Lignos Thos J & Celia M [2] ◎ 689-0455
2150★Marsha John C & Linda ◎ 688-4740
Marsha John C Jr 688-4740
• DURHAM DR INTERSECTS
• WINDHAM WAY INTERSECTS
• PASSGRILLE DR INTERSECTS

436
• **ZIP CODE 14228**
• N ELLICOT CREEK RD INTERSECTS
• ELLICOTT CREEK UNDERPASSES
2350 SWEET HOME CAFE
2430 Smith Beatrice [9]+ ◎
2445 Hill Huron O & Gloria G [9]+ ◎ 691-9120
• DODGE RD INTERSECTS
• COMMERCE DR INTERSECTS
2493 Harbison Robt Y & Rene C [9]+ ◎ 691-7382
2545 HERITAGE HEIGHTS ELEMENTARY SCHOOL 691-6992
2550 SWEET HOME MEDICAL CENTER 691-1414
2551★Badger Brian 691-8032
★Peck Anthony 691-1107
Not Verified
• SUNSHINE DR INTERSECTS
2575 Knoop David C & Lois B [9]+ ◎ 691-9314
Knoop Christine 691-9314

Target Street	Cross Street	Source
-	✓	Polk's City Directory

JOHN J AUDUBON PKWY 1988

COMMERCE DR INTERSECTS

433

JOHN JAMES AUDUBON PKWY (AMHERST)–FROM 2401 N FOREST RD NORTH TO 270 DODGE RD

ZIP CODE 14068
SYLVAN PKWY ENDS
1 Bldg
Suites
A National Fire Adjustment Co Inc ins 689-7700
B Plan Designers Inc financial planning 688-0801
C Goldhaber Research Associates mkt research 689-3311
100 First Union Home Equity 689-0655
104 Plan Designers Inc (Addl Space)
108 American Law Firm Association lwyrs 689-4655
110 Vacant
200 Wiggle Semanchin Wetter & Co cpa's 689-1644
101 American Cancer Society 689-6981
140 Columbus-Mc Kinnon Corp chains & hoists 689-5400
151 Executone Telecom Inc communication sys 689-6000
200 Empbanque Capital Corp mtge 689-2090
Partnership Limited
Procter & Gamble paper prods 689-2865
Procter & Gamble pkg soap 689-2865
Procter & Gamble bar soap & hsehold cln 689-2801
251 Honeywell Inc (Br Ofc) 689-0200
331 Computersearch Corp payroll processing-med billing 689-0511
350 Amherst Main Library 689-4922
400 Amherst Town Court 689-4200
500 Amherst Town Police Headquarters 689-1311
Amherst Police Club Inc
Amherst Town Fire Dept (Dispatch Ofc) 689-1212
TOWN CENTRE BEGINS
PARTRIDGE RUN BEGINS
PARTRIDGE RUN ENDS
DODGE RD INTERSECTS

433

JOHN MUIR DR (AMHERST)–FROM

5255 Genesee, (2 Mile

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAPLE RD 1988

West Building Apartments
Vacant
East Building Apartments
Vacant
2375 Vacant
2385 Tops Market 633-1283
Tops Pharmacy 633-1287
Western Union 633-1283
Instabank
TRANSIT RD INTERSECTS

420

3840 Goldome Bank (Br) 847-5800
Goldome Bank (Br) 847-5800
Goldome Agency Inc (Br Ofc) ins 847-4816
3900 Taylor Ed Lincoln Mercury sls & serv 838-2600
3902 Paper Factory The 836-5831
3908 Harry's Clothing Inc 837-2753
3910 Nutri-System Weight Loss Center 836-5100

427

3912 Urbach Kahn & Werlin P C accts 837-0073
3920 Perkins Restaurant 837-0297
3931 Firestone Tire & Rubber sls & serv auto repr 837-7721
ALBERTA DR ENDS
3950 Toddle House restr 835-5734
3960 Grisanti's restr 837-6190
3980 Gold Circle Discount Store 834-6401
3999 Scotch 'n Sirloin restr 837-4900
N BAILEY AV INTERSECTS
4003 Chi Chi's Restaurant 834-2281
4010 Red Lobster restr 837-0202
4023 Building
Suites
100 Actuarial Consulting Service Inc pension consltg 837-2283
102 American Health & Diet weight loss clinic 837-4776
103 Gates Circle Heart Group 834-3271
4033 Frontier Science & Technology Research 834-0900
4050 Wendy's Old Fashioned Hamburgers restr 837-1190
4053 Building
Suites
100 Accountemps temp employment agcy 833-5322
101 Mutual Of Omaha ins 832-3573
102 Bilvi Food Stores Inc 837-1630
103 N N-C A Inc comp sls
110 Partnership Management Corp hotel mgmt
111 Tabor Agency Inc 837-3800
112 Park Lane Construction bldg dev 833-8786
113 Silverstein & Green Leasing brokers 837-4433
200 Benchmark Group Inc bldg dev 833-4986
200 Con Bow Corp bldg dev 833-4937

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAPLE RD 1988

201 K V S Information Systems comp sls 834-3202
202 Gellman & Cohen lwyr 833-5301
203 Marsh Plastics Inc
204 Tal Inc mtkg 833-4767
4053 Benchmark Development Corporation 833-8782
4050 Wendy's Old Fashioned Hamburgers 837-1190
4060 Bennigan's restr & lounge 838-3550
BO MART PKWY BEGINS
3 4100 University Cinema (Div Of Genl Cinema) 837-8374
HILLCREST DR ENDS
4145 Vacant
4150 Sweet Home Junior High School 837-3500
4155 Vacant (4 Busn 4155-85)
4205 Under Constn
4220 Maple Ridge Centre shopping cntr
Dahlkemper's catalog showroom & sls 837-7040
27-A
4224 Len's Crafters opticians 833-0803
Buffalo Beach House The ret clo 832-9002
Fowler's Chocolates candy store 836-3707
Johnny B's Soda Bar & Cafe 838-1950
4231 Siegel Kelleher & Kahn lwyrs 834-5800
4265 Noco Motor Fuels gas sta 837-8479
4276 Maple Ridge Eight theaters 833-9500

421-A

SWEET HOME RD INTERSECTS (SS)
4291 Sunoco Maple gas sta 836-6100
4300 Fuddruckers Restaurant 836-3683
NY STATE THRUWAY UNDERPASSES
FLINT ENTRANCE BEGINS
Flint Rd Begins
27-B
4400 Continental Journey's End Motel 834-2231
4641 Ceder's Chevron Serv Cntr auto repair shop 688-1140
MILLERSPORT HWY INTERSECTS

427

MAPLELEAF DR (AMHERST)–FROM

Target Street	Cross Street	Source
-	✓	Polk's City Directory

SWEETHOME RD 1988

Saint Leo The Great Parochial School
832-6340
EMERSON DR ENDS
922 Amann Emma Mrs ◉ 833-6550
926 Hollands Wm R ◉ 833-5472
938 Witucki Al ◉ 837-1056
946 Burkard Keith M ◉
948 Dowd Charles S ◉ 837-7098
956 Geib Theo W ◉ 834-6508
965 Brummer John F ◉ 834-3185
966 North Bailey Exempt Fireman's
Association 836-9571
North Bailey Fire Co volunteer 832-2021
HOMECREST DR INTERSECTS
1006 Harbison John J ◉ 837-6878
1011★Dreyer Wm W ◉
1012 Blazysnki Brian ◉
1015 Roetzer Scott ◉ 836-5965
MAPLE RD INTERSECTS
YOUNGMAN HWY OVERPASSES

434-A

ZIP CODE 14221
RENSCH RD ENDS
1434 Pempsell Ray C ◉ 688-8251
1436 Martino Anthony H ◉ 688-2008
1544 Vacant
1554 Grandits Robt J ◉ 688-5764
1576 Vacant
CHESTNUT RIDGE RD ENDS
1608 Erickson Olive M Mrs ◉ 688-7949
I 190 OVERPASSES
1741 Sweet Home Central Sch Dist 7 (Trans
Servicenter) 689-5250
Sweet Home Central Dist No 7 (Kitchen
Dept) 689-5255
Sweet Home Central Sch Dist No 7
(bldg & ground dept) 689-5245
1872 Le Valley Peter W Rev 689-9848
1900 Sweet Home United Methodist Church
688-8677
1901 Sweet Home Senior High School 689-5301
Sweet Home Central Sch Dist (Ofc)
689-5251

Target Street	Cross Street	Source
-	✓	Polk's City Directory

JOHN J AUDUBON PKWY 1983



215 Standard Electronics Inc 691-3061
220 Barry's Factory Discount Carpets 691-3451

542
1025

433

JOHN JAMES AUDUBON PKWY (AMHERST)—FROM 2401 N FOREST RD NORTH TO 300 DODGE RD

ZIP CODE 14068
SYLVAN PKWY ENDS
101 American Cancer Society 689-6981
4 140 Columbus-Mc Kinnon Corp chains & hoists 689-5400
151 Vacant
251 Honeywell Corp (Br Ofc) 689-0200
331 Computer Search Corp payroll processing-med billing 689-0511
500 Amherst Police Headquarters 689-1311
Amherst Police Club Inc
Amherst Fire Dispatch Ofc 689-1212
TOWN CENTRE BEGINS
PARTRIDGE RUN BEGINS
PARTRIDGE RUN ENDS
DODGE RD INTERSECTS

433

JOHN MUIR DR (AMHERST)—FROM 2323 N FOREST RD NORTH TO SYLVAN PKWY

35★At Siri
36 Me
40 He LLO
44 Ros Nu
48 Er Er
49 Fro ★W
52 We Wit
55 Sor Vac
56 Kol ★M NAG
70 Me
74 De
75 Sor ★M
78 Wo LUC
82 Hof
86 Bar
90 Urs
94 Jer BET

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAPLE RD 1983



T 2365 Main at Leroy, Buffalo, N.Y. 14214 Tel. 834

MAPLE RD (A)—Contd
1933 Gentile Mary Mrs ◎ 634-4077
1940 Militello Frank J ◎ 688-4825
1948 Mann Carl A ◎ 688-4762
1955 Grace Norbert B ◎ 634-0473
1959 No Return
COUNTRY PKWY ENDS
1970 Tunney James J ◎ 689-6400
1980 Frantz Bernard C ◎ 688-4729
1985 Kumm Warren E ◎ 632-0641
1990 Smith James E ◎
2000 Agro Salvatore T ◎
2005 Norgren Joseph W ◎ 632-8114
2010 Young Doyle L ◎ 688-4540
2025 Monkelbaan Henry C ◎ 633-1482
BAUMAN RD INTERSECTS
MAPLELEAF RD BEGINS
2046 Setzer Norman C ◎ 688-7766
2085 Mc Dermott Wm H ◎ 633-1297
2105 Galuski Danl F ◎ 634-5763
2115 Rastelli Marino Jr ◎ 634-1382
2120 Martin Ronald R ◎ 688-5627
2121 Miller Norman
2122 Stacy Gerald C ◎ 688-4891
2156 Behr Dennis A ◎ 688-5048
SPRUCEWOOD TER ENDS
2160 Liptak Joseph ◎ 688-4553
SAGEWOOD TER ENDS
2195★Arcuri Faust ◎ 631-9787
2210★Danahon ◎
2230 Rommel Ernest G ◎ 688-6184
2240 Maroney Laveta M ◎
TEAKWOOD DR ENDS
2245 Sapp Richd A ◎ 634-5368
2250 Brandel Betty F ◎ 688-9077
2255 Hughes Sherman J ◎
SHETLAND DR ENDS
2265 Cushing Brian G dentist ◎ 633-4590
2275 Prugel Otto ◎ 634-2536
PATRICE DR ENDS
PALMDALE DR ENDS
2375 Maple-Transit Pharmacy Inc 633-5200
2385 Tops Market 632-7440
TRANSIT RD INTERSECTS

428

MAPLELEAF DR (AMHERST)—FROM 511

96 104 105 112 115 120 125 130 135 140 145 150 160 165 170 175 L 236 244 252 260 B MA 1 Z 44★ 52 54★ 60 62 63 67★ 68 69 70★ 71 73 76★ 78 81★ 82★ 83 84

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAPLE RD 1983



290

560 420
M 42 **MAPLE RD (AMHERST)—FROM 1341 NIAGARA FALLS BLVD EAST**

ALBERTA DR ENDS
3840 Goldome Bank (Br) 847-5800
Goldome (Addl Sp)
3900 Taylor Ed Lincoln Mercury sls & serv 838-2600
3902 Paper Factory The 836-5831
3908 Harry's Clothing Inc 837-2753
3910 Nutri-System Weight Loss Center 836-5100
3912 Seligman Sunshine & Co pub accts 837-0073
3920 Perkins Cake & Steak restr 837-0297
ALBERTA DR ENDS
3950 Citibank (Br) 837-1900
3960 Duff's Famous Smorgasbord
3980 Gold Circle Discount Store
3999 Scotch 'n Sirloin restr 837-4900
N BAILEY INTERSECTS
4000 Red Lobster Restr 837-0202
4003 Chi Chi Restaurante
4050 Wendy's Old Fashioned Hamburgers 837-1190
HILLCREST DR ENDS
4100 University Cinema (Div Of Genl Cinema) 837-8373
4150 Sweet Home Junior High School 831-8200
4265 Dukarm's Ed Mobil Service gas sta & auto repr 836-8902
SWEET HOME RD ENDS

421
SWEET HOME RD INTERSECTS (SS)
RIDGE LEA ENDS
4291 Mike's Service auto repair 836-9765
NY STATE THRUWAY UNDERPASS
CONRAIL CROSSES
SWEET HOME RD INTERSECTS (NS)
FLINT ENTRANCE BEGINS
4641 Ceder's Service Center auto repair shop 689-9865

422

455 Ma
SANI
500 Am
690 No
Fot
705 Top
711 C
FOXC
ELLI
720 K
724 Bra
68
726 Joh
68
736 Rit
740 Ma
62
ZIP C
N FO
770 Stu
1a
1b
2a
2b
3a
3b
4a
4b
5a
5b
6a
6b
7a
7b
8a
8b
9a
9b
10a
10b
11a
11b
12a

Target Street	Cross Street	Source
-	✓	Polk's City Directory

SWEETHOME RD 1983



Church 835-8905
Saint Leo The Great Parochial School 832-6340
EMERSON DR ENDS
922 Amann Andrew ◎ 833-6550
926 Hollands Wm R ◎ 833-5472
938 Witucki Aloysius ◎ 837-1056
946 Vacant
948 Dowd Charles S ◎ 837-7098
956 Geib Theo W ◎ 834-6508
965★Brummer John F ◎ 834-3185
966 North Bailey Exempt Fireman's Association 836-9571
North Bailey Fire Co volunteer 832-2021
HOMECREST DR INTERSECTS
1005 Harbison John J ◎ 837-6878
1011 Vacant
1012 Gibson Raymond J ◎ 832-7051
1015 Wightman Paul H ◎ 834-1250
MAPLE RD INTERSECTS

434

RENSCH RD ENDS
ZIP CODE 14221
1380★Lipp Donna Mrs ◎ 688-1041
1434 Pempsell Raymond C ◎ 688-8251
1436 Martino Anthony H ◎ 688-2008
1544 Hewitt Joseph W ◎ 688-0898
1554 Grandits Robt J ◎ 688-5764
1576 No Return
CHESTNUT RIDGE RD ENDS
1608 Erickson Oleve M Mrs ◎ 688-7949
I990 OVERPASSES
1741 Sweet Home Central Sch Dist 7 (Trans Servicenter) 688-5532
Sweet Home Central Dist No 7 (Kitchen Dept) 688-9255
Sweet Home Central Sch Dist No 7 (bldg & ground dept) 688-6252
1872★Le Valley Peter W Rev 689-9848
1900 Sweet Home United Methodist Church 688-8677
1901 Sweet Home Senior High School 688-8686
Sweet Home Central Sch Dist (Ofc) 688-8686

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAPLE RD 1977

2160 Liptak Joseph mfrs rep ◎ 688-4553
SAGEWOOD TER ENDS
2195 After Hours Maintenance 633-1214
Minnuto Thos M ◎ 633-1214
2210 Kraus Clarence W Jr ◎ 688-9013
2230 Rommel Ernest G ◎ 688-6184
2240★Kontak Thos
TEAKWOOD DR ENDS
2245 Barry David F acct ◎ 634-5256
2250 Brandel Robt H ◎ 688-9077
2255 Hughes Sherman J ◎
SHETLAND DR ENDS
2265 Cushing Brian G dentist ◎ 633-4590
2275 Prugel Otto ◎ 634-2536
PATRICE DR ENDS
PALMDALE DR ENDS
2375 Maple-Transit Pharmacy Inc 633-5200
2385 Tops Mkt 632-7440
TRANSIT RD INTERSECTS

479

MAPLEGROVE AV (TOWN OF

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAPLE RD 1977

3★Mandell H
4 Cotellessa Joseph A 839-5290

442

MAPLE RD (AMHERST)—FROM 1341 NIAGARA FALLS BLVD EAST

ALBERTA DR ENDS
NUMBERS IRREGULAR
3840 Western New York Savings Bank The (Br) 832-5353
Maxilift Facial Salons Inc beauty shop 838-6600
3900 Taylor Ed Lincoln Mercury sls & serv 838-2600
3902 Gepetto's Tale O'The Whale restr 837-2950
3908 Harry's Clothing Inc 837-2753
3910 Burnham's Furniture & Appliances appliance sls 834-2720
3920 Perkins Steak & Cake 837-0297
ALBERTA DR ENDS
3950 Citibank (Br) 837-1900
3980 Twin Fair Discount Store 836-7050
Twin Fair Major Appliance Dept 836-7050
Cinema I (Blvd Mall) (Side Ent)
Cinema II (Blvd Mall) (Side Ent)
Cinema III (Blvd Mall) (Side Ent)
3999 Scotch N Sirloin restr 837-4900
N BAILEY ENDS
HILLCREST DR ENDS
4150 Sweet Home Junior High School 837-4040

444

4265 Dukarm's Ed Mobil Service 836-8902
SWEET HOME RD INTERSECTS (SS)
RIDGE LEA ENDS
4291 Geiger Enterprises sunoco gas serv 837-9742
NY STATE THRUWAY UNDERPASS
CONRAIL CROSSES
SWEET HOME RD INTERSECTS (NS)
FLINT ENTRANCE BEGINS
4641 Ceder's Service Center 688-1140

446

ZIP CODE 14221
41 O'Brien Betty Mrs 631-5377
61 Ryan Alvin H ◎ 632-6887
75 Mowry Donna M ◎ 633-2589

FOX
ELL
720 K-
724 Ar
726 Jo
6
736 Ri
740 M
6
ZIP
N F
770 St
1a
1b
★
2b★
3a
3b★
4a
4b
5a★
5b★
6a
6b★
7a★
7b★
8a★
8b★
9a
9b★
10a
10b
11a
11b
12a
12b
780 A
13a
13b
14a
14b
15a
15b
16a
16b
17a
17b
18a
18b

Target Street	Cross Street	Source
-	✓	Polk's City Directory

SWEETHOME RD 1977

876 Lila's Beauty Shoppe 832-4345
Heimiller Frank L ◎ 832-4345
885 Saint Leo Rectory 835-8905
Dineen Patk J Rev Msgr
EMERSON DR ENDS
903 Saint Leo The Great Roman Catholic Church 835-8905
Saint Leo Parochial School 832-6340
922 Amann Andrew ◎ 833-6550
926 Hollands Wm ◎ 833-5472
938 Witucki Aloysius ◎
946 Leising Michl 838-2554
948 Templeton David P ◎
956 Berndt Selma J Mrs ◎ 834-6508
965 Brummer Henry P ◎ 832-0932
966 North Bailey Exempt Fireman's Association 836-9571
North Bailey Fire Co volunteer 836-9571
HOMECREST DR INTERSECTS
1005 Harbison John J ◎ 837-6878
1011 Waring Mark ◎
1012 Gibson Raymond J ◎ 832-7051
1015 Wightman Paul H ◎ 834-1250
MAPLE RD INTERSECTS

470

RENSCH RD ENDS
ZIP CODE 14221
1434 Pempsell Raymond C ◎ 688-8251
1436 Martino Anthony H ◎ 688-2008
1544★Hewitt Joseph ◎
1554 Grandits Robt J ◎ 688-5764
1576 No Return
CHESTNUT RIDGE RD ENDS
1608 Erickson Olive M Mrs ◎ 688-7949
1741 Sweet Home Transportation Servicenter 688-5532
Sweet Home Central (Kitchen Dept)
444 688-9255
1872 Woike Glenn V Rev 689-9848
1900 Sweet Home United Methodist Church 688-8677
1901 Sweet Home Senior High School 688-8686
ter Sweet Home (Central Sch Dist Ofc) 688-9678

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAPLE RD 1973

2122 Stacy Gerald C ◎ 634-3909
2156 Behr Dennis A ◎ 631-5276
SPRUCEWOOD TER ENDS
2160 Liptak Joseph mfrs rep ◎ 632-7769
2195 After Hours Maintenance 633-1214
Minnuto Thos M ◎ 633-1214
2210 Kraus Clarence W Jr ◎ 632-1046
SAGEWOOD TER ENDS
2230 Rommel Ernest G ◎ 633-7110
2240 Sand Robert J ◎ 632-0389
2245 Barry David F acct ◎ 634-5256
2250 Brandel Robt H ◎ 632-5055
2255 Stanford Joseph R ◎ 632-4128
2265 Cushing Brian G dentist ◎ 633-4590
TEAKWOOD TER ENDS
SHETLAND DR ENDS
PATRICE DR ENDS
PALMDALE ENDS
TRANSIT RD INTERSECTS

479

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAPLE RD 1973



4 Nir Shlomo 839-4392

442

MAPLE RD (AMHERST)—FROM 1341 NIAGARA FALLS BLVD EAST

ALBERTA DR ENDS

3840 Western New York Savings Bank The (Br) 832-5353

3900 Boulevard Mall Lincoln Mercury sls & serv 838-2600

3999 Scotch N Sirloin restr 837-4900

BAILEY ENDS

HILLCREST DR ENDS

4000 Burnham's 834-2720

4150 Sweet Home Junior High School 837-4040

780 Ap

444

4265 Yoh University Mobil Gas Sta 836-8945

SWEET HOME RD INTERSECTS (SS)

RIDGE LEA ENDS

4291 Gleason's Sunoco 836-8865

NY STATE THRUWAY UNDERPASS

LEHIGH VALLEY RR CROSSES

SWEET HOME RD INTERSECTS (NS)

4641 Amherst Service Center gas sta 633-7575

446

ZIP CODE 14221

41★O'Brien Betty Mrs 631-5377

61 Ryan Alvin H @ 632-6887

Target Street	Cross Street	Source
-	✓	Polk's City Directory

SWEETHOME RD 1973



835-8905 271
Saint Leo Parochial School 832-6340 271
922 Amann Andrew ◎ 833-6550
926 Hollands Wm ◎ 833-5472
938★Witucki Aloysius ◎ 837-1056 F
946 Kindt Emil C ◎ 836-6572 280
948 Armstrong Blair ◎ 834-7356 283
956 Berndt Selma J Mrs ◎ 834-6508 284
965 Brummer Henry P ◎ 832-0932 287
966 North Bailey Exempt Fireman's
Association 836-9571 290
North Bailey Fire Co volunteer 836-9571
HOMECREST DR INTERSECTS 290
1005 Harbison John J ◎ 837-6878 290
1011 Allcorn Grace Mrs ◎ 832-2088 291
1012 Gibson Raymond J ◎ 832-7051 292
1015 Wightman Paul H ◎ 834-1250 293
295
470 295
MAPLE RD INTERSECTS F
ZIP CODE 14221 303
1434 Pempsell Raymond C ◎ 688-8251 303
1436 Hoffman Kenneth A ◎
1544 Tuttolomondo Saml ◎ 688-6661 303
1554 Grandits Robt J ◎ 688-8228 304
1576 No Return 305
RENSCH RD BEGINS
CHESTNUT RIDGE RD ENDS
1741 Sweet Home Service Center (Trans Dept) 306
688-5532 (
Sweet Home Central (Kitchen Dept) 307
688-9255 316
1608 Erickson Charles L ◎ 688-7949 316
1872 West Wayne M Rev ◎ 689-9848 317

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAPLE RD 1968



HUGHES JOHN C • 633-6027
2105 DI ROSE J RICHD • 633-8867
2115 FLEMING STEWART E • 633-9680
2120 MARTIN RONALD R • 632-8882
2121 MILLER NORMAN J • 632-0414
2122 STACY GERALD C • 634-3909
2156 BERTA JULES G • 633-6184
---SPRUCEWOOD TER ENDS
2160 LIPTAK JOSEPH • 632-7769
2210 KRAUS CLARENCE W JR • 632-1046
---TEAKWOOD TER ENDS
2230 STANTON FRANK S • 632-6413
2240 VACANT
2245 VACANT
2250 BRANDEL ROBT H • 632-5055
---SHETLAND DR ENDS
---PATRICE DR ENDS
---TRANSIT RD INTERSECTS

233

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAPLE RD 1968



242

MAPLE RD (AMHERST)-FROM 1341 NIAGARA
FALLS BLVD EAST

---ALBERTA DR ENDS
---HILLCREST DR ENDS
4150 SWEET HOME JUNIOR HIGH SCHOOL
837-4040
---SWEET HOME RD INTERSECTS (SS)
---RIDGE LEA ENDS
---NY STATE THRUWAY UNDERPASS
---LEHIGH VALLEY RR CROSSES
---SWEET HOME RD INTERSECTS (NS)
---MILLERSPORT HWY INTERSECTS

244

---ZIP CODE 14121
---FRANKHAUSER RD INTERSECTS
41 VACANT
61 RYAN ALVIN H • 632-6887
116 BENNETT MARTIN S • 632-4157

Target Street	Cross Street	Source
-	✓	Polk's City Directory

SWEETHOME RD 1968

872 ZACK LENA M MRS • 832-7330
876 LILA'S BEAUTY SHOPPE 832-4345
HEIMILLER FRANK L • 832-4345
---EMERSON DR ENDS
903 SAINT LEO THE GREAT CATHOLIC CHURCH
SAINT LEO PAROCHIAL SCHOOL 832-6340
LEO LANES 836-9632
922 AMANN ANDREW • 833-6550
926 HOLLANDS WM • 833-5472
938 SCHMIDT BERNARD W • 832-7772
946 KINDT EMIL C • 836-6572
948 ARMSTRONG BLAIR • 834-7356
956 BERNDT SELMA J MRS • 834-6508
965 BRUMMER HENRY P • 832-0932
966 NORTH BAILEY EXEMPT FIREMAN'S ASSOCIATION 836-9571
NORTH BAILEY FIRE CO VOLUNTEER 836-9571
980 VACANT
995 CLIFT WALTER T H 834-2630
---HOMECREST DR INTERSECTS
1005 HARBISON JOHN J • 837-6878
1011 ALLCORN FREDK C • 832-2088
1012 GIBSON RAYMOND J • 832-7051

Target Street	Cross Street	Source
-	✓	Polk's City Directory

SWEETHOME RD 1968



397

1015 WIGHTMAN MARJORIE I MRS •
834-1250
1025 HOLMES RUTH E MRS • 832-4501

240

---MAPLE RD INTERSECTS
1434 PEMPSELL RAYMOND C • 692-4887
1436 LO BRUTTO JOSEPH R • 693-9592
1544 TUTTOLOMONDO SAML •
1554 GRANDITS ROBT J •

Target Street	Cross Street	Source
-	✓	Polk's City Directory

MAPLE RD 1963



Bauman rd ends
2035 Under Constn
2045 Under Constn
2046 Setzer Norman C ◎ NF3-6047
2055 to 2106 Under Constn
2115 Fleming Stewart E ◎ NF3-9680
2116 Under Constn
2120 Martin Ronald R ◎ NF2-8882
2121 Miller Norman J NF2-0414
2122 Kilbury Ruez E ◎ NF4-2054
2156 Cunningham Edw P ◎
2160 Liptak Joseph ◎ NF2-7769
2210 Kraus Clarence W jr ◎
NF2-1046
2230 Stanton Frank S ◎ NF2-6413
2240 Under Constn
2250 Brandel Robt F ◎ NF2-5055
Transit rd intersects

242

Alberta dr intersects
4150 Sweet Home Jr High Sch
837-4040
Sweet Home rd intersects

Target Street	Cross Street	Source
-	✓	Polk's City Directory

SWEETHOME RD 1963



SWEET HOME RD–Contd
946 Kindt Emil C ◎ TF6-6572
948 Armstrong W Blair ◎ TF4-7356
956 Berndt Selma J Mrs ◎ TF4-6508
965 Brummer Henry P ◎ TF2-0932
966 North Bailey Exempt Firemans Association TF6-9571
North Bailey Fire Co TF6-9571
980 Vacant
Homecrest dr intersects
995 Clift Walter I ◎ TF4-2630
1005 Bunting Wm ◎ TF5-5277
1011 Allcorn Electric contrs TF2-2088
Allcorn Fredk C ◎ TF2-2088
1012 Gibson Raymond J ◎ TF2-7051
1015 Wightman Marjorie I Mrs ◎ TF4-1250
1025 Holmes Ross C ◎ TF2-4501
Maple rd intersects
1063 Lunetta John L ◎ TF2-6059
1071 Schaab Francis J ◎ TF3-4015
1081 Higgins Leonard J ◎ TF3-1083
1091 Zeller John J ◎ TF6-6362
1101 Spina Jos A ◎ TF5-4559
1111 Rutterman Geo N ◎ TF3-6471
1121 Eldridge Donald H ◎ TF2-9931
1128 Maggiore Pasquale F jr ◎ TF4-4854
Schaab Carl A TF6-4620
Martino J J Inc excavating
Meyer rd ends
1131 Shoures Clarenca A ◎ TF6-1940
Zone 21
1181 O'Neill Eug M ◎ NF2-3149
1220 Brenner John F ◎ NF2-4339
1240 Budzynski Henry G NF3-8338
1241 Bealer Mildred E ◎ NF3-9847
1242 Bealer Cletus J ◎ NF2-8251
1247 Bealer Clarence A ◎ NF2-2495
1253 Toth Steph M ◎ NF2-1466
1254 Jakala Robt S ◎ NF4-3679
1268 Garlock Franklin A NF3-8014
Spann Kath M Mrs ◎ NF2-2440
1269 Bainbridge Fredk C ◎ TF2-2467
1275 Epedanick Geo E ◎ NF2-4125
1301 Lalomia Benj trucking ◎ NF2-8198
1303 Kadziolka Edw A ◎ NF2-0825
1313 Roberts Television Service NF2-2308
Cipresso Robt A ◎ NF2-2308
1316 Steinberger John B ◎ NF2-8389
rear Moyer John E NF4-4366
1341 Walsh Robt W ◎ NF4-3264
1349 Daskalakes Angelo ◎ NF3-9203